



BRIDGE NO.00315

73070 - STAMFORD
US ROUTE 1
over
NOROTON RIVER

Routine and Underwater Inspection

4/03/2018

Inspected by: A. DiCesare




TABLE OF CONTENTS

<u>Section</u>	<u>Page Number</u>
Report Title Page	1
Location Map	2
Structure Inventory and Appraisal (BRI-19)	3
Inspection Data (BRI-18)	8
National Bridge Elements	17
Underwater Inspection (BRI-59)	18
Sketches	19
Pictures	29

Bridge No. 00315, US Route 1 over Noroton River, Stamford

Inspected By: A.DiCesare Associates Date: 04/03/2018



Professional Certification: I hereby certify that this report, including all of its contents, has been approved by me, and that I am a duly licensed professional engineer under the laws of the State of Connecticut.

Signature: *Arthur DiCesare*

License No.: 14073

Date: 05/02/2018

Form: Location

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates


Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Location Map # 1

Form: BRI-19, Rev. 2/15
Inspection type: Routine, Underwater
Inspection Date: 4/03/2018
Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD
Carried: US ROUTE 1
Crossed: NOROTON RIVER
Inventory Route: NHS

STRUCTURE INVENTORY & APPRAISAL

INSPECTION

Structurally Deficient Functionally Obsolete
Sufficiency Rating
(90) Inspection Date (91) Frequency
Indepth Insp Proposed next Indepth Year
Deck Survey Date Class
Access Flagman

	Frequency	Date	Type
Fracture	<input type="text"/>	<input type="text"/>	<input type="text"/>
Underwater	<input type="text" value="24"/>	<input type="text" value="04/03/2018"/>	<input type="text" value="A Full Inspection"/>
Special	<input type="text"/>	<input type="text"/>	<input type="text"/>

IDENTIFICATION

Bridge Name
Town Code - Name
(5) Inventory Route
(A) Record Type
(B) Signing Prefix
(C) Level of Service
(D) Route Number
(E) Dir Suffix
(6A) Featured Intersected
(6B) Critical Facility Indicator
(7) Facility Carried
(9) Location
(11) Mile Post Miles
(16) Latitude Deg. Min. Sec.
(17) Longitude Deg. Min. Sec.
(98) Border Bridge
(A) State Code (B) Percent Responsibility %
(C) Border Town Name
(99) Border Bridge Structure No.

STRUCTURE TYPE & MATERIALS

(43) Structure Type, Main
A) Material
B) Design Type
(44) Structure Type, Approach
A) Material
B) Design Type
(45) Number of Spans, Main Unit
(46) Number of Approach Spans
(107) Deck Structure Type
(108) Wearing Surface/Protection Systems
A) Type of Wearing Surface
B) Type of Membrane
C) Type of Deck Protection
Substructure
A) Material
B) Design Type
Paint
Type
Year
Comment

GEOMETRIC DATA

(48) Length of Maximum Span ft.
(49) Structure Length ft.
(50) Curb or Sidewalk Widths
A) Left ft. in. B) Right ft. in.
(51) Bridge Roadway Width Curb to Curb ft. in.
(52) Deck Width, Out to Out ft. in.
(32) Approach Roadway Width ft.

Form: BRI-19, Rev. 2/15
Inspection type: Routine, Underwater
Inspection Date: 4/03/2018
Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD
Carried: US ROUTE 1
Crossed: NOROTON RIVER
Inventory Route: NHS

(33) Bridge Median
Deck Area sq. ft.
(34) Skew Angle deg.
(35) Structure Flared
(10) Inv. Rte. Min. Vert. Clearance ft. in.
(47) Inv. Rte. Total Horiz. Clr. ft. in.
Log Inv. Rte. Total Horiz. Clr. ft. in.
RLog Inv. Rte. Total Horiz. Clr. ft. in.
(53) Min. Vert. Clearance Over Bridge ft. in.
(54) Log-Min. Vert. Underclearance ref. ft. in.
(55) Min. Lat Underclearance on Right ref. ft. in.
(56) Min. Lat Underclearance on Left ft. in.

CONDITION

(58) Deck
(59) Superstructure
(60) Substructure
(61) Channel & Channel Protections
(62) Culverts
(36) Traffic Safety Features
A) Bridge Railings
B) Transitions
C) Approach Guardrail
D) Approach Guardrail Ends

WATERWAY

Drainage Basin Waterway
(38) Navigation Control
(39) Navigation Vertical Clearance ft.
(40) Navigation Horiz. Clr. ft.
(111) Pier/Abutment Navigation
(116) Vert-Lift Brg Nav Min ft. in.

AGE AND SERVICE

Year Built (106) Year Reconstructed
(42) Type of Service
A) On
B) Under
(28) Number of Lanes
A) On B) Under
(29) Average Daily Traffic
Is Above Half ADT?
(109) Percent Truck %
(30) Years of ADT
(19) Bypass, Detour Length Miles

APPRAISALS

(67) Structural Evaluation
(68) Deck Geometry
(69) Underclearances, Vert. & Horiz.
(71) Waterway Adequacy
(72) Approach Roadway Alignment
(113) Scour Critical

COMMENTS

Item 50 - Sidewalk width reduced by Dec 2006 installation of barrier to prevent pedestrian access to broken parapet. RDJ 3/7/07

CLASSIFICATION

(112) NBIS Bridge Length
(104) Highway System
(26) Functional Class
(100) Defense Highway
(101) Parallel Structure
(102) Direction of Traffic

Form: BRI-19, Rev. 2/15
 Inspection type: Routine, Underwater
 Inspection Date: 4/03/2018
 Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD
 Carried: US ROUTE 1
 Crossed: NOROTON RIVER
 Inventory Route: NHS

(103) Temporary Structure
 (110) Designated National Network
 (20) Toll
 (21) Maintain
 (22) Owner
 Report Class
 (37) Historical Significance

POSTED SIGNS

Other Posted Sign 1
 Other Posted Sign 2

	Actual	Recommended	
Posted Load Single Unit Truck	<input type="text"/>	<input type="text"/>	tons
Posted Load Semi-Trailer Truck	<input type="text"/>	<input type="text"/>	tons
Posted Load 4 Axle Truck	<input type="text"/>	<input type="text"/>	tons
Posted Load 3S2 Truck	<input type="text"/>	<input type="text"/>	tons
All Vehicles	<input type="text"/>	<input type="text"/>	tons
Posted Vert. Clearance on Bridge	<input type="text"/> ft.	<input type="text"/> in.	
Posted Vert. Underclearance	<input type="text"/> ft.	<input type="text"/> in.	
Posted Speed Limit on Bridge	<input type="text" value="35"/> m.p.h.		

OTHER FEATURES

Fence Required
 Fence Present
 Fence Type
 Fence Height
 Fence Material
 Fence Top Type
 Barrel Ladders
 Stand Pipes
 Catwalks
 Moveable Inspection System
 Haunches Present over Roadway

PROPOSED IMPROVEMENTS

(75A) Type of Work Proposed
 (75B) Work Done By
 (76) Length of Structure Improvement ft.
 (94) Bridge Improvement Cost \$
 (95) Roadway Improvement Cost \$
 (96) Total Project Cost \$
 (97) Year of Improvement Estimate
 (114) Future ADT
 (115) Year of Future ADT
 DOT Bridge Program List No
 Project No
 Advertised Date

LOAD RATING & POSTING

(31) Design Load
 (63) Operating Rating Type
 (64) Operating Rating
 (65) Inventory Rating Type
 (66) Inventory Rating
 Evaluation Code
 Year of Evaluation
 (70) Bridge Posting
 (41) Structure Status

Form: BRI-19, Rev. 2/15

Inspection type: Routine,Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS

Utilities

1 Gas

2 Water

4 Telephone

Form: BRI-19, Rev. 2/15

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD


Carried: US ROUTE 1

Crossed: NOROTON RIVER


Inventory Route: NHS

INSPECTOR'S SIGNATURES:

1) _____ Date: 04/12/2018



2) _____ Date: 04/12/2018



3) _____ Date: 04/12/2018



4) _____ Date: _____

P.E. SIGNATURE:



Date: 04/12/2018

P.E. #

14073

Reviewed By:



Date: 08/03/2018

Form: BRI-18, Rev. 1/14

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS

FIELD INSPECTION REPORT

Location:	STAMFORD DARIEN TOWN	Year Built:	1913
Main Material:	5 - Prestressed concrete	Year Rebuilt:	1957
Main Design:	01 - Slab		

Snooper Required:

Snooper Used:

Inspectors:

Lead Inspector:	Clay Carlson
Inspector:	Task:
Carlson, Clay	BSE - Inspector Rail - Inspector
Harrington, Peter	BSE - Inspector
Nixdorf, Steven	BSE - Inspector

Visits:

Visit Date:	Temp:	Start Time:	End Time:
04/03/2018	41	07:30 AM	01:00 PM

58. DECK:

The original structure consists of concrete encased steel beams with a reinforced concrete deck. The deck has a bituminous overlay.

Overall Rating:

Rating

Overlay:	<input type="text" value="5"/>	The bituminous concrete overlay has random longitudinal and transverse cracks up to 2" wide , raveling up to 1" deep throughout and random bituminous patches. Longitudinal paving seams are open up to 2" wide. There are full width transverse cracks at the deck ends up to 1-1/2" wide with edge potholes up to 2' long x 1' wide x 2" deep. See Roadway Plan Sheet and Photos 8-10.
Deck - Str. Condition:	<input type="text" value="6"/>	The original structure (east half) consists of concrete encased steel beams with a reinforced concrete deck that supports a bituminous concrete roadway on 2'± of fill. The underside of the reinforced concrete deck has isolated diagonal hairline cracks with efflorescence at the east end, isolated areas of mapcracking and intermittent areas of dampness throughout. In span 2 between girders 6 and 9, the underside has spalls up to 1-1/2" diameter x 2" deep with exposed rebar, dampness, efflorescence and 1-1/2" diameter drill holes. In span 2 between girders 8 and 9 near midspan there is a 6' long x 3' wide damp area with honeycombing.
Curbs:	<input type="text" value="6"/>	The east concrete curb is integral with the sidewalk. See "Sidewalks" below. The west concrete railbase has random transverse hairline to 1/16" cracks, scrapes and spalls up to 1/2" deep. Average Curb Reveal: West Side = 6" East Side = 6"
Median:	<input type="text" value="N"/>	
Sidewalks:	<input type="text" value="4"/>	Access to the damaged east sidewalk is blocked by jersey barrier and chain-link fence. The east sidewalk has light scale, isolated transverse hairline cracks and random bituminous concrete patches.

Form: BRI-18, Rev. 1/14

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS

At the south end of the east sidewalk, there are up to 1" wide cracks and the approach side of the sidewalk has settled up to 1/2".

The east sidewalk in span 1 has a 2-1/2' long x 2' wide section that is settled up to 1" and is loose with a 2" wide crack.

The east sidewalk is undermined up to 2" wide x full length x up to 8" deep.

See Roadway Plan Sheet and Photos 11-13.

Parapet: 1 The full length of the east parapet has fallen into the channel.

A jersey barrier has been attached to the bridge deck along the east fascia.

The concrete jersey barrier exhibits random spalls up to 1' long x 6" high X 3" deep and isolated hairline cracks.

The fallen parapet is rated 1, and the jersey barrier would be rated 6.

See Roadway Plan Sheet and Photos 11-13.

Railing: 6 The west railing consists of 4 channel beams welded to W-flange posts.

The posts and beams have light to moderate corrosion.

The 2nd post base from abutment 1 has 1 missing/sheared-off nut and 1 loose nut.

Paint: N

Fence: 8 There is a chain-link fence attached to the east side of the jersey barrier. There are no notable deficiencies.

Drains: N

Lighting Standard: N

Overall Utility Condition Rating 6 - Fair

Utility Type/Size

1 Gas	There is a 24" diameter utility pipe supported by brackets mounted to the east fascia. The support plates that are bolted to the fascia have areas of moderate to heavy corrosion. 2 of 3 utility supports are broken and the utility pipe is not properly seated.
2 Water	Per the plans there is a 12" diameter water main buried in the fill (over deck units 5 and 6) that is not visible.
4 Telephone	Per the plans there are communication ducts buried in the fill (over deck units 5 and 6) that are not visible.

Construction Joints: N

Expansion Joint: N

Haunches Present over travelway? NO

APPROACH CONDITION:

Bituminous concrete pavement.

Overall Rating: 5

Rating

Approach Slab:	N	
Relief Joints:	N	
Approach Guide Rail:	5	<p>The northwest approach rail is 2-cable guide rail on timber posts.</p> <p>The timber posts are leaning and the cables are loose.</p> <p>Along the east side, there is a continuous jersey barrier across the bridge.</p> <p>The jersey barrier is bolted to the sidewalk.</p> <p>The northeast approach has a jersey barrier placed at a 90° angle to the bridge rail.</p> <p>The southeast approach has a jersey barrier with a single metal beam guide rail attached.</p> <p>The jersey barrier and metal beam guide rail have isolated scrapes, spalls up to 1' long x 6" high x 3" deep and hairline cracks, as well as minor collision damage to one rail at the intersection.</p> <p>The southwest approach has no approach guide rail.</p> <p>See Roadway Plan Sheet and Photo 19.</p>
Approach Pavement:	5	<p>The approach pavements have random transverse and longitudinal cracks up to 1-1/2" wide.</p> <p>Longitudinal paving seams are open up to 2".</p> <p>The southeast approach sidewalk at the east edge has a 3' long x 2' wide section that is missing and the remaining portion is undermined up to 8" deep due to erosion.</p> <p>The area that is undermined is beneath the jersey barrier.</p> <p>See Roadway Plan Sheet and Photos 6 and 7.</p>
Approach Embankment:	6	<p>The southeast approach embankment has a 4' long x 3' wide x 2' deep eroded area that undermines the approach sidewalk/jersey barrier.</p>

Traffic Safety Features

Bridge Railings:	0	Open bridge rail.
Transitions:	0	<p>The 2-cable rail at the northwest approach is not connected to the bridge rail.</p> <p>The metal beam guide rail at the southeast approach does not have blockouts and is not stiffened.</p>
Approach Guardrails:	0	<p>2-cable guide rail on timber posts at the northwest approach.</p> <p>Metal beam guide rail with no blockouts and is not stiffened at the southeast approach.</p> <p>There is no approach rail at the southwest approach.</p> <p>The northeast approach rail (jersey barrier perpendicular to bridge rail) has a blunt end in the clear zone.</p>
Approach Guardrail Ends:	0	The metal beam guide rail and 2-cable guide rail are continuous with adjacent side streets.

59. SUPERSTRUCTURE:

The original structure has concrete encased steel beams (east half). The roadway was widened in 1957 and the newer portion (west half) consists of prestressed concrete deck units. There is a 5' wide masonry arch section at the east fascia and between girder 5 and the prestressed deck units in span 1 and between girders 5 and 6 in span 2.

Overall Rating: 5

Rating

Bearing Devices: 6 Premolded joint filler for the deck units is squeezed out at random locations. Steel girder bearings are not visible.

Stringers: 6 Concrete encased steel beams rated here.
Span 1 has 5 concrete encased beams and span 2 has 9 concrete encased beams.
Span 1 girders 1 and 4 and span 2 girder 2 at the pier have up to 3' long hairline cracks with efflorescence or rust staining.
Span 2 girder 3 at pier, concrete encasement has 2' long x 1' wide hollow area with efflorescence.
Span 2 girder 4 encasement at the pier has a 1' long horizontal hairline crack with rust stains.
Span 2 girder 5 west side encasement has a hollow corner at the bottom flange 10'± long x 4" wide.
Span 2 girder 6 east edge has random areas of scale up to 2" deep.
Span 2 girder 7 concrete encasement has (2) spalls up to 10' long x 1' wide with exposed beam with light corrosion.
Span 2 girder 8 concrete encasement has a 4' long spall with rust staining.
Span 2 girder 9 has spalled concrete encasement up to 85% of the beam length with exposed beam with moderate corrosion and pitting up to 1/16" deep and random horizontal and vertical cracks on the remaining concrete encasement.

Girders: 6 Prestressed concrete deck units rated here.
The prestressed concrete deck units in both spans have isolated areas of efflorescence leakage between units and minor chips at the edges.
In span 1 there is evidence of water leakage between units 9 and 10 at the pier (±10' long).

Floor Beams: 5 Arch sections rated here.
The east arch (arch 1) is concrete.
In both spans, the east fascia has spalls and heavy scaling up to full length x full height x up to 4" deep with exposed reinforcement.
The arch face over the pier has a 5-1/2' long x 2' high x 2" deep spall with exposed reinforcement with up to 100% section loss.
The arch underside has random cracks up to 1/8" with heavy efflorescence.
The west arch (arch 2) between girder 5 and the prestressed deck units in span 1 and between girders 5 and 6 in span 2 is masonry block with a concrete skim coat.
The arch has spalls and scaling in the concrete skim coat, random hairline cracks with heavy efflorescence, random mortar loss up to 20% with up to 18" deep joint penetration, and active leakage.
There are isolated voids in joints between masonry blocks up to 2.1' wide x 1' high x 1-1/2' deep.
At the south elevation of the pier, there is a block with a 2' long vertical crack up to 1/4" wide (located 2.2' above the footing) and a 2' long section of the joint is open up to 3/4" wide (full depth).
See Underside of Deck, Abutments 1 and 2 and Pier 1 North and South Elevation Sheets and Photos

	15-17, 27 and 28.
Trusses - General:	N
Trusses - Portals:	N
Trusses - Bracing:	N
Paint:	N
Rust:	7 The exposed steel beams in span 2 have light to moderate corrosion.
Machinery Movable Span:	N
Rivets & Bolts:	N
Welds - Cracks:	N
Timber Decay:	N
Concrete Cracking:	5 See "Stringers" and "Floor Beams" above.
Collision Damage:	8
Member Alignment:	8
Deflection Under Load:	N (N) Normal (E) Excessive
Vibration Under Load:	N (N) Normal (E) Excessive
Stand Pipes:	N
Catwalks:	N
Movable Inspection System:	N
Barrel Ladders:	N

Are Barrel Ladders OSHA Compliant?

60. SUBSTRUCTURE:

Abutment 1 is reinforced concrete. Abutment 2 is reinforced concrete and stone masonry. The pier central portion is stone masonry and remaining portions are reinforced concrete. The wingwalls are reinforced concrete.

Overall Rating:

Rating

Abutments - Stem: The abutment stems have a band of moderate scale, hairline cracks, mapcracking with efflorescence and delaminations throughout.

There are isolated vertical cracks up to 1/8" wide with efflorescence at both abutments.

The footing is exposed at both abutments.

Abutment 1 exhibits spalls up to 1-1/2' high x 1-1/2' wide x 4" deep.

At the interface with the west arch (arch 2), abutment 1 stem has a 1/2" gap in the construction joint.

Abutment 1 has an area of severe scale 10' long x 3' high x up to 4" deep starting at arch 2 and extending west.

Abutment 2 has spalls up to 3.0' high x 7" wide x 5" deep.

At the east end of abutment 2 stem there is a 3 square foot area of punky concrete with heavy efflorescence.

A central portion of abutment 2 is stone masonry.

The masonry at arch 2 has up to 90% mortar loss and 1' penetration.

The masonry throughout the abutment 2 stem has up to 50% mortar loss and 1' penetration.

	<p>Arch 2 at abutment 2 has a void 2.4' long x 7" high x up to 10" deep.</p> <p>Abutment 2 has an area of severe scale 5.6' long x 6" high x up to 8" deep approximately at the centerline of the bridge.</p> <p>See Abutments 1 and 2 Sheets and Photos 27-29, 32 and 34.</p>
Abutments - Backwall: N	
Abutments - Footings: 6	<p>Abutment 1 footing is exposed extending from the east end 55± long x 2'-3' wide x up to 1.1' high.</p> <p>Abutment 2 footing is exposed extending from the east end 55± long x 2'-3' wide x up to 3.2' high.</p> <p>Exposed footings at both abutments exhibit scale up to 1-1/2" deep.</p> <p>At the east end of abutment 2 footing, there is a 12' long x up to 6" high x 8" deep void.</p> <p>Exposed sheet piling at both abutments have heavy surface corrosion.</p>
Abutments - Settlement: 6	<p>Abutment 1 east end has a 5' long horizontal hairline crack with efflorescence and water infiltration and a hairline to 1/16" wide full height vertical crack near the roadway centerline.</p> <p>Abutment 2 has a 6" long diagonal hairline to 1/8" wide crack at the east end with heavy efflorescence and a full height vertical hairline to 1/16" crack wide at the west end.</p>
Abutments - Wingwalls: 5	<p>The reinforced concrete wingwalls have moderate scale, isolated hollow areas and shallow spalls with light efflorescence.</p> <p>Wingwall 1B has scale up to 1" deep with efflorescence and water infiltration at the southeast end.</p> <p>The top of the Wingwall 1B has a 12' long x 2' high x 4"-9" deep spall/scale with exposed vertical reinforcement.</p> <p>Wingwall 1B has a full length by 2' high hollow area with isolated spalls up to 2" deep.</p> <p>Wingwall 1B has full height cracks up to 1/8" wide with efflorescence, intermittent mapcracking and delaminations.</p> <p>The top of the Wingwall 2B has a 12' long x 2' high x 4"-9" deep spall/scale.</p> <p>Wingwall 2B has vertical and horizontal hairline cracks with efflorescence.</p> <p>See Plan, Abutments 1 and 2 Sheets and Photos 2 and 33.</p>
Piers/Bents - Caps: 5	<p>The concrete portions of the pier have random hairline cracks and moderate scale extending from elevation -7.0' to the mudline with intermittent areas of honeycombing to 1/2" deep.</p> <p>A central portion of the pier is stone masonry.</p> <p>The masonry portions have areas of mortar loss up to 70% with up to 1' penetration.</p> <p>The west nose of the pier has a band of scale with intermittent honeycombing up to 2" deep.</p> <p>The south elevation, east end has an area of mapcracking with hollow areas up to 6-1/2' long x 3-1/2' high and a spall 2' high x 1' wide x 3" deep.</p> <p>The south elevation near the roadway centerline has an area of scale 12' long x 2.0' high x up to 7" deep and a missing stone 1-1/2' high x 4" wide x 1.3' deep.</p> <p>The south pier stemwall has a spall 2' high x 1-1/2' wide x 6" deep adjacent to arch 2 at the top of the wall and two areas of severe scale up to 0.8' wide x 3' high x 3" deep in the tidal zone.</p>

	<p>Arch 2 at the south pier stemwall has a 2' long x 1-1/2' high broken stone 2.2' above the footing.</p> <p>The north elevation east end has random spalls up to 2' long x 0.3' high x 2-1/2" deep with heavy efflorescence.</p> <p>Where arch 2 meets the north elevation of the pier there is a concrete wall/repair; the wall has an area 7' long x 3.7' high with mapcracking up to 1/8" wide, spalls to 1" deep and heavy efflorescence.</p> <p>The two upper corners of the wall have spalls up to 2-1/2' wide x 1-1/2' high x 10" deep.</p> <p>The north pier wall has an area of severe scale 3' long x 1-1/2' high x 3" deep starting approximately at the centerline of the bridge in the tidal zone.</p> <p>See Pier 1 North and South Elevation Sheets and Photos 30, 31 and 35-37.</p>
Piers/Bents - Pile Bent:	N
Piers/Bents - Columns:	N
Piers/Bents - Footings:	6
	<p>The pier footing is exposed 55'± long along both elevations.</p> <p>The exposed footing has up to 3" deep scale.</p> <p>Exposed sheet piling has heavy surface corrosion.</p>
Piers/Bents - Settlement:	7
Erosion - Scour:	5
	<p>The substructure units have isolated cracks up to 1/8" wide with efflorescence.</p> <p>The sounding grid has shown a history of minor fluctuations (less than 2') throughout the channel since the 2001 Inspection.</p> <p>The greatest isolated degradation during the 2018 Inspection was 0.7' at the centerline and west end of abutment 1.</p> <p>The greatest isolated aggradation was 2.7' at the west end of abutment 2.</p> <p>The footings at all substructure units are exposed for 55'± extending from the east end.</p> <p>Footings are exposed up to 1.1' high (2016: 0.9') at abutment 1, up to 3.2' high (2016: 3.0') at abutment 2 and up to 2.3' high (2016: 2.2') at the pier.</p> <p>The exposed footings on all substructure units are not undermined.</p> <p>Sheet piling is exposed at all substructure units.</p> <p>The exposed sheet piling exhibits heavy corrosion.</p> <p>See Plan, Upstream Profile (West Elevation), Downstream Profile (East Elevation), Abutments 1 and 2 and Pier 1 North and South Elevation Sheets</p>
Concrete Crack - Spall:	5
Steel Corrosion:	N
Paint:	N
Timber Decay:	N
Collision Damage:	8
Debris:	6
	There is light timber debris along the west nose of the pier in span 2.

61. CHANNEL AND CHANNEL PROTECTION:

Noroton River is a brackish water body with tidal flow.

Overall Rating: 6

Form: BRI-18, Rev. 1/14

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS

Rating

Channel - Scour:	6	Channel bottom consists of riprap, cobbles and soft silt with up to 1.0' penetration into the mudline. Flow is tidal, 1/4 knot at the time of the inspection. The sounding grid has shown a history of negligible fluctuations (less than 2') throughout the channel since the 2001 Inspection. The greatest isolated degradation during the 2018 Inspection was 0.7' at the centerline and west end of abutment 1. The greatest isolated aggradation was 2.7' at the west end of abutment 2. The exposed footings on all substructure units are not undermined.
Embankment - Erosion:	8	
Debris:	6	There is light timber debris along the west nose of the pier in span 2. There is scattered drift and debris throughout the channel.
Vegetation:	8	The banks are well vegetated.
Channel Change:	8	There are no significant lateral changes to the channel. Channel bottom elevations have not significantly changed since the 2016 Inspection. See "Channel-Scour" above.
Fender - System:	N	
Spur Dikes and Jetties:	N	
Rip Rap:	6	There is scattered riprap up to 4' in diameter.

62. CULVERTS AND RETAINING WALLS:

Overall Rating:

Rating

Barrel:	N	
Concrete:	N	
Steel:	N	
Timber:	N	
Headwall:	N	
Cutoff Wall:	N	
Debris:	N	
Retaining Wall System:	N	
Footings:	N	

LOAD POSTING:

Rating

Single Unit (Tons):	<input type="text"/>
Semi Trailer (Tons):	<input type="text"/>
4 Axle (Tons):	<input type="text"/>
3S2 (Tons):	<input type="text"/>
All Vehicles:	<input type="text"/>
Advanced Warning:	N

Form: BRI-18, Rev. 1/14

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS

Warning At Bridge:		
Legibility:	N	
Visibility:	N	

VERTICAL CLEARANCE POSTING

Min. Vert Under Clearance:		Ft		In	Structure spans a waterway.
Posted Clearance Under Bridge:		Ft		In	
Posted Clearance On Bridge:		Ft		In	
Advanced Warning:	False				
Warning At Bridge:					
Legibility:					
Visibility:					

NOTES / COMMENTS:

Character of Traffic: Light to moderate volume, mixed traffic weights.

Additional Notes:

Bridge ID is on fallen piece of east parapet.
 The bridge is inventoried from south to north with girder 1 at the east fascia. The log direction was changed to match the inventory direction of US Route 1.
 The inspection should be performed at low tide.
 The above water and underwater inspections were performed concurrently.

Additional Comments:

Repair the blunt end of the northeast approach rail.

National Bridge Elements

Inspection type: Routine,Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS

	Environment	Total Quantity	Units	Condition State 1	Condition State 2	Condition State 3	Condition State 4
12 - Reinforced Concrete Deck	Mod.	1223	sq. ft.	1184	28	11	0
1080 - Delamination/Spall/Patched Area		12		0	1	11	0
1130 - Cracking (RC and Other)		23		0	23	0	0
1190 - Abrasion/Wear (PSC/RC)		4		0	4	0	0
104 - Prestressed Concrete Closed Web/Box Girder	Mod.	598	ft.	568	30	0	0
1120 - Efflorescence/Rust Staining		30		0	30	0	0
107 - Steel Open Girder/Beam	Mod.	322	ft.	297	25	0	0
1000 - Corrosion		25		0	25	0	0
144 - Reinforced Concrete Arch	Mod.	41	ft.	0	0	41	0
1080 - Delamination/Spall/Patched Area		15		0	0	15	0
1090 - Exposed Rebar		5		0	0	5	0
1120 - Efflorescence/Rust Staining		0		0	0	0	0
1130 - Cracking (RC and Other)		1		0	0	1	0
1190 - Abrasion/Wear (PSC/RC)		20		0	0	20	0
145 - Masonry Arch	Mod.	41	ft.	9	10	22	0
1120 - Efflorescence/Rust Staining		10		0	0	10	0
1610 - Mortar Breakdown (Masonry)		12		0	0	12	0
1620 - Split/Spall (Masonry)		10		0	10	0	0
210 - Reinforced Concrete Pier Wall	Mod.	93	ft.	0	66	27	0
1080 - Delamination/Spall/Patched Area		21		0	7	14	0
1120 - Efflorescence/Rust Staining		14		0	14	0	0
1130 - Cracking (RC and Other)		26		0	26	0	0
1190 - Abrasion/Wear (PSC/RC)		32		0	19	13	0
215 - Reinforced Concrete Abutment	Mod.	197	ft.	51	120	26	0
1080 - Delamination/Spall/Patched Area		41		0	15	26	0
1120 - Efflorescence/Rust Staining		18		0	18	0	0
1130 - Cracking (RC and Other)		45		0	45	0	0
1190 - Abrasion/Wear (PSC/RC)		42		0	42	0	0
330 - Metal Bridge Railing	Mod.	46	ft.	20	25	1	0
1000 - Corrosion		25		0	25	0	0
1020 - Connection		1		0	0	1	0
331 - Reinforced Concrete Bridge Railing	Mod.	46	ft.	30	15	1	0
1080 - Delamination/Spall/Patched Area		11		0	10	1	0
1130 - Cracking (RC and Other)		5		0	5	0	0

UNDERWATER INSPECTION (BRI-59)



Bridge: 00315 Town: 73070 - STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Total Number of Piers: 1

Piers in the Water: 1

Boat Used? No

Boat Size: N/A

Dive Station Used? No

Access to Bridge: Shore

Access/ Equipment
Comments U/W: N/A

Type of water: Brackish

Marine Growth: Light algae.


Max Water Depth: 4.1'

Max Water Depth at Pier Or
Abutment: 4.1'

Current Strength: 1/4 knot tidal

U/W Visibility: 2.0'

Bottom Composition: Riprap, cobbles and soft silt with up to 1.0' penetration in to the mudline.



CONNECTICUT DEPARTMENT OF TRANSPORTATION			
BRIDGE NO. 00315			
US 1 (EAST MAIN STREET) OVER NOROTON RIVER			
STAMFORD			CONNECTICUT
KEY PLAN			
INSPECTED BY: CC REVISED BY: PR	SCALE: AS SHOWN	DATE OF INSPECTION 04/03/18	DRAWING NO. 00315A

US RTE 1
LOG NORTH

4 CHANNEL RAILS
WELDED TO W-FLANGE
POSTS WITH
LIGHT-MODERATE
CORROSION

RAILBASE WITH SCRAPES
AND EDGE SPALLS UP
TO 1/2" DEEP, LIGHT
SCALE, AND RANDOM
TRANSVERSE HAIRLINE-
TO-1/16"W CRACKS

(1) MISSING/
SHEARED OFF
NUT AND (1)
LOOSE NUT

JOINT SEAL

WINGWALL 2A

JERSEY BARRIER

BROOKSIDE
DRIVE

GUARDRAIL CABLES
(2) LOOSE -
RANDOM
POSTS
LEANING

ROUTE 1
SB

CONCRETE CURB
1-1/2"W CRACK AT
JOINT WITH EDGE
POTHOLES UP TO 2'L x
1'W x 2'D
WHITE TRAFFIC LINE

1/2"W CRACK

40'L OPEN
1" PAVING
SEAM

1-1/2"W OPEN
PAVING
SEAM

3/4"W CRACK

PAVING
SEAM OPEN
UP TO
1-1/2"

8" DIA. POTHOLE
x 1-1/2"D

YELLOW TRAFFIC LINE

1/2"W CRACK

3/4"W CRACK

1"W CRACK

ROUTE 1
NB

3/4"W CRACK

2"W CRACK

1"W CRACK

3/4"W CRACK

2"W OPEN
PAVING SEAM
WITH EDGE UP
TO 5"

WHITE TRAFFIC LINE

1"W OPEN
PAVING SEAM

1"W CRACK

3/4"W CRACK

ASPHALT PATCH

1"W CRACK, APPROACH
SIDEWALK SETTLED UP
TO 1/2"

ASPHALT PATCH

CONCRETE SIDEWALK

ALL JERSEY
BARRIERS RANDOM
SPALLS AT
BOTTOM UP TO
1'L x 6"H x 3'D
AND ISOLATED
HAIRLINE CRACKS

SIDEWALK NOT IN
SERVICE

TEMPORARY JERSEY BARRIER OVER SIDEWALK & CHAIN WIRE FENCE

JERSEY BARRIER

APPROACH SIDEWALK
SPALLED/MISSING 3' LONG
x 2' WIDE AND UNDERMINED
UP TO 8"D x FULL
LENGTH DUE TO EROSION
AND HAS A TEMPORARY
BARRIER PLACED OVER
UNDERMINING.

FULL LENGTH OF PARAPET HAS
FALLEN INTO THE CHANNEL

2"W CRACK IN SIDEWALK &
2-1/2'L x 2'W SECTION IS
SETTLED UP TO 1" AND IS
LOOSE

1'L x 1'H x 2"D SPALL

NOTES

ROADWAY PLAN

N.T.S.

1. THE PAVEMENT AT THE BRIDGE EXHIBITS LONGITUDINAL AND TRANSVERSE CRACKS UP TO 1/2" WIDE, RAVELING UP TO 1" DEEP, AND RANDOM BITUMINOUS PATCHES.
2. APPROACH PAVEMENT HAS RANDOM TRANSVERSE AND LONGITUDINAL CRACKS UP TO 1-1/2" WIDE AND LONGITUDINAL PAVING SEAMS OPEN UP TO 2".
3. EAST SIDEWALK EXHIBITS LIGHT SCALE AND ISOLATED TRANSVERSE CRACKS UP TO 2"W AND UNDERMINING FL x UP TO 8"D.
4. SOUTHEAST APPROACH EMBANKMENT ERODED AREA 4'L x 3'W x 2'D.

CONNECTICUT DEPARTMENT OF TRANSPORTATION

BRIDGE NO. 00315
US 1 (EAST MAIN STREET) OVER NOROTON RIVER

STAMFORD

CONNECTICUT

ROADWAY PLAN

INSPECTED BY: CC
REVISED BY: PR


SCALE:
AS SHOWN

DATE OF INSPECTION
04/03/18

DRAWING NO. 00315B

- ① G6 EAST EDGE WITH RANDOM SCALE TO 2" DEEP.
- ② G7 CONC. ENCASEMENT W/ 10'L x 1'W SPALL EXPOSED BEAM WITH LIGHT RUST.
- ③ G8 4'L CONC. ENCASEMENT SPALL WITH RUST STAINS.
- ④ G9 85% OF ENCASEMENT IS SPALLED EXPOSING BOTTOM FLANGE. BOTTOM FLANGE W/ MOD. RUST AND PITTING UP TO 1/16"D.
- ⑤ ACTIVE LEAKAGE AND EFFLO. +/- 10'L.

- ⑥ 6' x 3' AREA OF DAMPNESS ON G9 ENCASEMENT W/ 4'L x 1'H HONEYCOMBING
- ⑦ G4 AT PIER - BASE OF WEB W/ 1'L HORZ. HLC WITH RUST STAINS.
- ⑧ G5 BOTTOM FLANGE 4" x 3" HOLLOW CORNER WITH HAIRLINE CRACK
- ⑨ UNDERSIDE WITH SPALL UP TO 1-1/2' DIA. x 2"D WITH DAMPNESS AND EFFLO. AND 1-1/2" DIA. DRILL HOLES.
- ⑩ 2'L x 1'W HOLLOW AREA WITH EFFLO.
- ⑪ 2'L HAIRLINE CRACKS WITH RUST
- ⑫ HAIRLINE CRACKS WITH EFFLO.



UNDERSIDE OF DECK

N.T.S.

LEGEND:

- HOLLOW AREA
- SHALLOW REBAR
- SPALL AREA
- SPALL WITH EXPOSED REBAR
- MAPCRACKS OR HAIRLINE MAPCRACKS
- HAIRLINE MAPCRACKS (HLC) OR CRACKS (CR)
- HONEY COMB AREA
- SCALE AREA (HVY, MED, OR LT)
- EFFLORESCENCE
- G* CONCRETE ENCASEMENT BEAM No.

NOTES

1. ARCHES HAVE RANDOM TRANSVERSE CRACKS TO 1/8" WIDE WITH ACTIVE LEAKAGE (SPAN 2 ONLY), HEAVY EFFLO., SCALE UP TO 3"D AND SPALLS IN SKIM COAT.
2. END DIAPHRAGMS BETWEEN CONC. ENCASED BEAMS HAVE EDGE SPALLS ON THE BASE UP TO 1/2" DEEP.
3. SPALLED CONC. ENCASEMENT FOR G6-G9 WITH RANDOM HAIRLINE CRACK.
4. EFFLO. STAINS ALONG JOINT BETWEEN G1-G5 AND PIER.
5. UNDERSIDE OF DECK HAS ISOLATED AREAS OF MAPCRACING (<2%).
6. ARCHES IN SPAN 2 AT PIER HAVE AREAS OF EFFLO.

CONNECTICUT DEPARTMENT OF TRANSPORTATION


BRIDGE NO. 00315
US 1 (EAST MAIN STREET) OVER NOROTON RIVER
STAMFORD CONNECTICUT

UNDERSIDE OF DECK

INSPECTED BY: CC
REVISED BY: PR
SCALE: AS SHOWN
DATE OF INSPECTION: 04/03/18
DRAWING NO. 00315C

US RTE 1
LOG NORTH

9.8' +/- 9.8' +/- 9.8' +/- 9.8' +/- 9.8' +/- 9.8' +/- 9.8' +/- 9.8' +/-



PLAN
N.T.S.

LEGEND FOR SYMBOLS



- ⊕ DATUM ELEV. 0.0 TAKEN FROM THE BOTTOM OF DECK AT THE SOUTHWEST CORNER.
- ▽ W.S. ELEV. -9.0' -9.0'

LEGEND FOR BOTTOM ELEVATIONS

ELEVATION/PENETRATION = -0.0'/0.0'

- APR 2018 → -0.0'/0.0'
- MAY 2016 → -0.0'/0.0'

* INDICATES NO INFORMATION




CONNECTICUT DEPARTMENT OF TRANSPORTATION

BRIDGE NO. 00315
US 1 (EAST MAIN STREET) OVER NOROTON RIVER
STAMFORD CONNECTICUT

PLAN

INSPECTED BY: CC
REVISED BY: PR
SCALE: AS SHOWN
DATE OF INSPECTION: 04/03/18
DRAWING NO. 00315D



UPSTREAM PROFILE (WEST ELEVATION)
N.T.S.

LEGEND FOR SYMBOLS

- ⊕ DATUM ELEV. 0.0 TAKEN FROM THE BOTTOM OF DECK AT THE SOUTHWEST CORNER.
- ▽ W.S. ELEV. -9.0'

NOTES

1. RANDOM VERTICAL HAIRLINE CRACKS.
2. (12) RANDOM POPOUTS UP TO 2" DIAMETER X 1/2" DEEP.
3. RANDOM AREAS OF DELAMINATED GROUT POCKETS.

LEGEND FOR BOTTOM ELEVATIONS

- ELEVATION = -0.0'
- APR 2018 ———▶ -0.0'
- MAY 2016 ———▶ -0.0'

LEGEND FOR MUDLINE ELEVATIONS


- APR 2018
- MAY 2016

CONNECTICUT DEPARTMENT OF TRANSPORTATION

BRIDGE NO. 00315
US 1 (EAST MAIN STREET) OVER NOROTON RIVER
STAMFORD CONNECTICUT

UPSTREAM PROFILE (WEST ELEVATION)

INSPECTED BY: CC	SCALE: AS SHOWN	DATE OF INSPECTION: 04/03/18	DRAWING NO. 00315E
REVISED BY: PR			



NOTES

1. BAND OF UP TO 1.5" D SCALE FROM ELEV. -7.0' TO THE MUDLINE.
2. INTERMITTENT HAIRLINE CRACKS, MAP CRACKING, AND DELAMINATIONS THROUGHOUT.
3. WINGWALLS HAVE UP TO 1" D SCALE AND DELAMINATIONS AND SPALLS, WITH LIGHT EFFLORESCENCE.
4. WINGWALL 1B HAS A FULL HEIGHT 1/8" WIDE CRACK WITH EFFLORESCENCE STARTING 5' SOUTH OF ABUTMENT 1. ADJACENT CONCRETE EXHIBITS A 10' H x 1' W x 1" D AREA OF SPALLING AND DELAMINATION.
5. HORIZONTAL CRACK 7' L x HL TO 1/8" W AT WINGWALL 1B 3' ABOVE MUDLINE WITH LIGHT EFFLORESCENCE.

ABUTMENT 1
N.T.S.

LEGEND FOR SYMBOLS

- ⊕ DATUM ELEV. 0.0 TAKEN FROM THE BOTTOM OF DECK AT THE SOUTHWEST CORNER.
- ▽ W.S. ELEV. -9.0' -9.0'

LEGEND FOR BOTTOM ELEVATIONS


ELEVATION/PENETRATION = -0.0'/0.0'

- APR 2018 → -0.0'/0.0'
- MAY 2016 → -0.0'/0.0'

LEGEND FOR MUDLINE ELEVATIONS

- APR 2018
- - - MAY 2016

CONNECTICUT DEPARTMENT OF TRANSPORTATION			
BRIDGE NO. 00315			
US 1 (EAST MAIN STREET) OVER NOROTON RIVER			
STAMFORD			CONNECTICUT
ABUTMENT 1			
INSPECTED BY: CC	SCALE: AS SHOWN	DATE OF INSPECTION 04/03/18	DRAWING NO. 00315G
REVISED BY: PR			



PIER 1 (SOUTH ELEVATION)
N.T.S.

NOTES


1. SCATTERED HAIRLINE CRACKS THROUGHOUT.
2. BAND OF UP TO 1" D SCALE FROM ELEV. -7.0' TO MUDLINE WITH INTERMITTENT UP TO 1/4" D HONEYCOMBING.
3. SCATTERED DRIFT AND DEBRIS THROUGHOUT CHANNEL.
4. EXPOSED FOOTING HAS SCALE UP TO 3" DEEP.

- LEGEND FOR SYMBOLS**
- ⊕ DATUM ELEV. 0.0 TAKEN FROM THE BOTTOM OF DECK AT THE SOUTHWEST CORNER.
 - ▽ W.S. ELEV. -9.0'

- LEGEND FOR BOTTOM ELEVATIONS**
- ELEVATION/PENETRATION = -0.0'/0.0'
- APR 2018 ———→ -0.0'/0.0'
 - MAY 2016 ———→ -0.0'/0.0'

- LEGEND FOR MUDLINE ELEVATIONS**
- APR 2018
 - MAY 2016


CONNECTICUT DEPARTMENT OF TRANSPORTATION			
BRIDGE NO. 00315			
US 1 (EAST MAIN STREET) OVER NOROTON RIVER			
STAMFORD		CONNECTICUT	
PIER 1 (SOUTH ELEVATION)			
INSPECTED BY: CC	SCALE: AS SHOWN	DATE OF INSPECTION: 04/03/18	DRAWING NO. 00315H
REVISED BY: PR			



NOTES

1. SCATTERED HAIRLINE CRACKS THROUGHOUT.
2. BAND OF UP TO 1/2" D SCALE FROM -7.0' TO THE MUDLINE, WITH INTERMITTENT 1/4" - 1/2" D HONEYCOMBING.

PIER 1 (NORTH ELEVATION)
N.T.S.



LEGEND FOR BOTTOM ELEVATIONS

- ELEVATION/PENETRATION = -0.0'/0.0'
- APR 2018 ———> -0.0'/0.0'
- MAY 2016 ———> -0.0'/0.0'


LEGEND FOR MUDLINE ELEVATIONS

- APR 2018
- MAY 2016

LEGEND FOR SYMBOLS

- ⊕ DATUM ELEV. 0.0 TAKEN FROM THE BOTTOM OF DECK AT THE SOUTHWEST CORNER.
- ▽ W.S. ELEV. -9.0'
- W.S. ELEV. -9.0'

CONNECTICUT DEPARTMENT OF TRANSPORTATION			
BRIDGE NO. 00315			
US 1 (EAST MAIN STREET) OVER NOROTON RIVER			
STAMFORD		CONNECTICUT	
PIER 1 (NORTH ELEVATION)			
INSPECTED BY: CC	SCALE: AS SHOWN	DATE OF INSPECTION 04/03/18	DRAWING NO. 00315I
REVISED BY: PR			



NOTES

1. WINGWALL 2B HAS SEVERE SCALE, SPALLS AND CRACKS WITH EFFLORESCENCE.
2. STEM HAS INTERMITTENT HAIRLINE CRACKS, MAP CRACKING, AND DELAMINATIONS.
3. FOOTING ELEVATIONS WERE FIELD MEASURED.
4. CHAMFER SPALLS UP TO 2" D WITH EFFLORESCENCE ON WINGWALL 2B COLD JOINT.
5. VERTICAL AND HORIZONTAL HAIRLINE CRACKS WITH EFFLORESCENCE ON WINGWALL 2B.

- ⑥ SPALL 3.0' H x 7" W x 5" D.
- ⑦ AREA WITH 90% MORTAR LOSS BETWEEN STONE AND CONCRETE WITH 1.0' PENETRATION.
- ⑧ FROM ELEV. -7.0' DOWN TO MUDLINE, UP TO 1/2" D SCALE AND UP TO 1.5" D HONEYCOMBING.
- ⑨ UP TO 1.5" D SCALE FROM ELEV. -7.0' TO MUDLINE.
- ⑩ 12' WEST OF E. FASCIA HORZ. VOID IN FACE OF STEP 2.0' W x 3" H x 3" D.

LEGEND FOR BOTTOM ELEVATIONS

ELEVATION/PENETRATION = -0.0'/0.0'
 APR 2018 ———→ -0.0'/0.0'
 MAY 2016 ———→ -0.0'/0.0'

LEGEND FOR MUDLINE ELEVATIONS

————— APR 2018
 - - - - - MAY 2016

LEGEND FOR SYMBOLS

- ⊕ DATUM ELEV. 0.0 TAKEN FROM THE BOTTOM OF DECK AT THE SOUTHWEST CORNER.
- ▽ W.S. ELEV. -9.0'
- ▽ W.S. ELEV. -9.0'

CONNECTICUT DEPARTMENT OF TRANSPORTATION			
BRIDGE NO. 00315			
US 1 (EAST MAIN STREET) OVER NOROTON RIVER			
STAMFORD		CONNECTICUT	
ABUTMENT 2			
INSPECTED BY: CC REVISED BY: PR	SCALE: AS SHOWN	DATE OF INSPECTION 04/03/18	DRAWING NO. 00315J

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 1

Photo Taken: 04/03/2018

Bridge identification number on fallen piece of east parapet.



Photo Number: 2

Photo Taken: 04/03/2018

West (upstream) elevation.

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 3

Photo Taken: 04/03/2018

East (downstream) elevation.



Photo Number: 4

Photo Taken: 04/03/2018

Bridge from south approach.

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 5

Photo Taken: 04/03/2018

South approach from bridge.



Photo Number: 6

Photo Taken: 04/03/2018

Bridge from north approach.

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 7

Photo Taken: 04/03/2018

North approach from bridge.



Photo Number: 8

Photo Taken: 04/03/2018

Typical top of deck, looking east.

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 9

Photo Taken: 04/03/2018

Top of deck at abutment joint, looking west. Note potholes and full width cracks.



Photo Number: 10

Photo Taken: 04/03/2018

Top of deck at abutment 2 joint, looking west. Note full width crack.

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 11

Photo Taken: 04/03/2018

Concrete jersey barrier and chain link fence blocks access to deteriorated east sidewalk and fallen east parapet.



Photo Number: 12

Photo Taken: 04/03/2018

East sidewalk is cracked, settled and loose. Note access to east sidewalk is blocked by jersey barrier and chain link fence.

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 13

Photo Taken: 04/03/2018

East fascia, looking north. Note missing parapet and heavy deterioration with undermining of sidewalk.



Photo Number: 14

Photo Taken: 04/03/2018

East fascia utility pipe bracket broken and utility pipe not seated properly.

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 15

Photo Taken: 04/03/2018

Span 1 east fascia arch exhibits heavy deterioration and spalls with exposed rebar.



Photo Number: 16

Photo Taken: 04/03/2018

Underside of span 1 east fascia. revealing spalls and exposed rebar.

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 17

Photo Taken: 04/03/2018

Span 2, east fascia arch exhibiting heavy scale with hollow areas and exposed rebar.



Photo Number: 18

Photo Taken: 04/03/2018

West bridge railing. Note base plate bolt is sheared.

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 19

Photo Taken: 04/03/2018

2 Cable guide rail at northwest approach. Both cables are loose and timber posts leaning.



Photo Number: 20

Photo Taken: 04/03/2018

Typical underside of span 1, west portion (prestressed concrete deck unit).

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 21

Photo Taken: 04/03/2018

Typical underside of span 2, west portion (prestressed concrete deck unit).



Photo Number: 22

Photo Taken: 04/03/2018

Typical underside of concrete deck and concrete encased steel beams at span 1, east portion.

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 23

Photo Taken: 04/03/2018

Joint between deck units 9 and 10 in Span 1 at pier. Note evidence of leakage and efflorescence.



Photo Number: 24

Photo Taken: 04/03/2018

Underside of deck between girders 8 and 9 in span 2 near abutment 2. Note spall with drill hole.

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 25

Photo Taken: 04/03/2018

Span 2, girder 9 at midspan with spall in concrete encasement and exposed flange of steel girder.



Photo Number: 26

Photo Taken: 04/03/2018

Span 2, girder 5 near pier exhibiting a hollow corner and hairline cracks with rust.

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 27

Photo Taken: 04/03/2018

Span 2, arch 2 near abutment 2 with scaling, spalls and efflorescence.



Photo Number: 28

Photo Taken: 04/03/2018

Span 1, arch 2 at abutment 1 exhibiting end spall with penetration.

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 29

Abutment 1.

Photo Taken: 04/03/2018



Photo Number: 30

South elevation of pier.

Photo Taken: 04/03/2018

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 31

North elevation of pier.

Photo Taken: 04/03/2018



Photo Number: 32

Abutment 2.

Photo Taken: 04/03/2018

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 33

Photo Taken: 04/03/2018

Wingwall 1B.



Photo Number: 34

Photo Taken: 04/03/2018

Abutment 1 stem with heavy scale in tidal zone.

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 35

Photo Taken: 04/03/2018

Pier south elevation with heavy scale and spalls in tidal zone.



Photo Number: 36

Photo Taken: 04/03/2018

Pier south elevation with void at interface between concrete and masonry sections.

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 37

Photo Taken: 04/03/2018

Pier north elevation at arch 2 buttress with heavy scale.



Photo Number: 38

Photo Taken: 04/03/2018

Typical exposed step and tremie.

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 39

Photo Taken: 04/03/2018

Span 1 east channel with parapet laying in water.



Photo Number: 40

Photo Taken: 04/03/2018

Channel looking upstream (west).

Form: Asset Photos

Inspection type: Routine, Underwater

Inspection Date: 4/03/2018

Inspected by: A. DiCesare Associates

Bridge No: 00315

Town: STAMFORD

Carried: US ROUTE 1

Crossed: NOROTON RIVER

Inventory Route: NHS



Photo Number: 41

Photo Taken: 04/03/2018

Channel looking downstream (east).