GLOBAL SAFETY FIELD INVESTIGATIONS DCS5799 URGENT - DISTRIBUTE IMMEDIATELY

Date: May 20, 2021

Subject: N212330480 - Service Update

Front Lift System Reservoir Cap Leak

Models: 2020-2021 Chevrolet Corvette

To: All General Motors Dealers

General Motors is releasing Service Update N212330480 today. The total number of U.S. vehicles involved is approximately 13,000. Please see the attached bulletin for details.

Global Warranty Management (GWM)

The Required Field Action section on the Investigate Vehicle History (IVH) screen will be updated May 21, 2021 or sooner. A list of involved vehicles in dealer new inventory is attached to this message. Please hold all warranty transactions until IVH has been updated.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS

Service Update

N212330480 Front Lift System Reservoir Cap Leak



Release Date: May 2021 Revision: 00

Attention: This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

		Model Year			
Make	Model	From	То	RPO	Description
Chevrolet	Corvette	2020	2021		

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	On certain 2020-2021 model year Chevrolet Corvette vehicles, there may be a hydraulic lift fluid leak at			
	the front right hand (passenger) side of the vehicle.			
Correction	Dealers are to replace the front hydraulic lift fluid reservoir vented cap with a non-vented cap.			

Parts

Quantity	Part Name	Part No.	
1	CAP-HYD SUSP FLUID RSVR	85165040	

Reminder: Parts may be removed from Retail Inventory Management (RIM). Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.

Warranty Information

Labor		Labor	Trans.	Net
Operation	Description	Time	Type	Item
9105654	REPLACE HYD SUSP FLUID RSVR CAP	0.3	ZFAT	N/A

Service Procedure

Warning: Refer to Brake Fluid Irritant Warning in SI.

Caution: Refer to Brake Fluid Effects on Paint and Electrical Components Caution in SI.

- Remove the front compartment rear access panel. Refer to Front Compartment Rear Access Cover Replacement in SI.
- 2. Locate the hydraulic suspension fluid reservoir mounted on the passenger side of the compartment.

Note: Clean the filler cap and surrounding area before removing the cap.



5700361

3. Remove the incorrect reservoir cap. Discard the cap.

Service Update

N212330480 Front Lift System Reservoir Cap Leak





- Install the new service reservoir cap.
- Reinstall the front compartment rear access panel. Refer to Front Compartment Rear Access Cover Replacement in SI.

Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin <u>must</u> be held and inspected/repaired per the service procedure of this bulletin <u>before</u> customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

Dealer Reports

The Inventory tab of the Open Vehicle Report will contain Service Update Bulletin VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will not contain Service Update Bulletin VIN data because the intent of a Service Update Bulletin is to not inconvenience a customer with a special trip for service. Service Update Bulletins are to be completed when the customer is in for a regularly scheduled visit.