

MEMORANDUM TO: Tolbert Young, Section Chief, Region V

FROM: Glenn A. Walton, Senior Resident Inspector,
BVPS Unit #2

DATE: October 7, 1983

SUBJECT: TEAM INSPECTION - PALO VERDE UNIT 1

Attached is my feeder report covering inspection activities at Palo Verde, Unit 1. The inspection of concrete expansion anchor bolts and embeded plates was a combined inspection and will be written by Mr. Lou Vorderbrueggen. The radiographs that I reviewed will be included in Harry Kerch's report.

I will be on vacation the week of October 11 - 14, 1983. If any questions arise, please call me at my office on October 17th or thereafter at (412) 728-8886.

Glenn A. Walton
Glenn A. Walton

gab

cc: L. E. Tripp, Region 1, w/attach.
W. Albert, Region V, w/attach.
L. Vorderbrueggen, Region V, w/attach.

8402140038 831220
PDR FOIA
BERNABE83-598 PDR

#26

APPENDIX A

NOTICE OF VIOLATION

Arizona Public Service
Palo Verde, Unit 1

Docket No. 50-528
License No. CPPR-141

10 CFR 50, Appendix B, Criterion IX requires that measures shall be established to assure that special processes including welding are controlled and accomplished in accordance with applicable codes, standards, specifications, criteria, and other special requirements.

Bechtel Drawing Number 13-S-ZAS-536, Revision 3, requires a 5/16 inch fillet weld when attaching structural steel vertical members to horizontal members. Drawing Number 13-C-ZAS-570, Revision 8, requires a 5/16 inch fillet weld when attaching structural steel to embeded plates.

AWS D.1.1 Paragraph 10.17 states that undercut shall be no more than .01 inch deep when its direction is transverse to primary tensile stress in the part that is undercut, not more than 1/32 inch for all other situations.

Contrary to the above, on September 10 and 15, 1983, welds on structural steel were found with fillet sizes less than required by the drawings and welds with undercut were observed which exceeded the requirements of AWS D1.1.

This is a Severity Level IV Violation (Supplement 11).

Pursuant to the provisions of 10 CFR 2.201, Arizona Public Service is hereby required to submit to this office within thirty days of the date of the cover letter to this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending your response time.

APPENDIX A

NOTICE OF VIOLATION

Arizona Public Service
Palo Verde, Unit 1

Docket No. 50-528
License No. CPPR-141

10 CFR 50, Appendix B, Criterion V states "activities affecting quality shall be prescribed by documented instructions, procedures, or drawings . . . and shall be accomplished in accordance with these instructions, procedures, or drawings."

Bechtel specification 13-CM-320, Section 11.0 states, in part "Installation shall be in accordance with AISC Specification for Structural Joints using ASTM-A325 or A490 Bolts."

The specification for Structural Joints using ASTM A325 or A490 Bolts, Paragraph 5(a) requires that A325 bolts, 7/8 inch diameter, be tightened to at least a minimum tension of 39 Kips. An acceptable method of obtaining this tension is described in paragraph 5(e) "Turn-of-Nut Tightening" which requires that bolts be brought to a "snug tight" condition plus an additional 1/3 to 2/3 turn, depending on the bolt length.

Contrary to the above, on September 7 and 13, 1983, four A325 bolts were found finger loose and additional test using a calibrated torque wrench found two A325 bolts with tightness less than the 39 Kips.

This is a Severity Level IV Violation (Supplement 11).

Pursuant to the provisions of 10 CFR 2.201, Arizona Public Service is hereby required to submit to this office within thirty days of the date of the cover letter to this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending your response time.

DETAILS

1. Persons Contacted

R. Forrester, Quality Assurance, Arizona Public Service
C. Collup, Quality Control Engineer, Bechtel
R. Butler, Civil Lead Discipline Engineer, Bechtel
H. Mear, Quality Control Manager, Bechtel
J. Black, Field Engineering Manager, Bechtel
A. Spicer, Records Management, Bechtel

2. Structural Steel

The inspector audited the installed structural steel associated with the High Pressure Safety Injection (HPSI) A train system. The areas inspected are located in the Auxiliary Building and Containment Building. The inspector physically examined welds and bolted connections to ascertain compliance with the below listed applicable documents.

- Specification 13-CM-320 Revision 7 Installation Specification for Erection of Structural and Miscellaneous Steel.
- Structural Welding Code AWD D1.1 1972 with 1973 Revision 1.
- American Institute of Steel Construction AISC - Specification for Structural Joints using ASTM A325 or A490 Bolts.
- Applicable construction drawings.

The matrix below identifies the areas inspected, location, type of inspection and inspection findings.

<u>Inspection Location</u>	<u>Elevation</u>	<u>Amount of Inspection Versus Total Available</u>	<u>Items Inspected</u>	<u>Type Of Inspection</u>	<u>Inspection Findings</u>
Auxiliary Bldg. Pump Room A HPSI	51'6"	15 joints of approx. 30	Bolted Connections	Visual	Four Loose bolts See details below
AD06 Pipe Way Auxiliary Bldg.	51'6"	13 joints of approx. 15	Bolted Connections	Visual	Acceptable
AD06 Pipe Way Auxiliary Bldg.	51'6"	13 joints of approx. 15	Welded Connections	Weld gauge Visual	Six undersize fillet welds See details below
Piping Penetration Area Auxiliary Bldg.	82'-95'	46 joints of approx. 200	Bolted Connections	Visual	Acceptable
Pipe Chase Area Auxiliary Bldg.	88'-	40 joints of approx. 200	Bolted Connections	Visual	Acceptable
Pipe Chase Area Auxiliary Bldg.	88'	50 joints of approx. 200	Welded Connections	Weld gauge Visual	Eight undersize fillet welds, Four welds with undercut. See details below
Containment Bldg.	80'-87'	110 joints of approx. 500	Bolted Connections	Visual	Acceptable
Containment Bldg.	80'-87'	110 joints of approx. 250	Welded Connections	Weld gauge Visual	Acceptable
Auxiliary Bldg. Pump Room A	51'6"	10 bolts of approx. 120	Bolted Connections	Torque Test	Acceptable
AD06 Pipe Way Auxiliary Bldg.	51'6"	28 bolts of approx. 52	Bolted Connections	Torque Test	One bolt turned 60 degree rotation before minimum tightness was achieved. See details below.

<u>Inspection Location</u>	<u>Elevation</u>	<u>Amount of Inspection Versus Total Available</u>	<u>Items Inspected</u>	<u>Type Of Inspection</u>	<u>Inspection Findings</u>
Containment Bldg.	87'	24 bolts of approx. 2500	Bolted Connections	Torque Test	One bolt turned 45 degrees rotation before minimum tightness was achieved. See details below
Containment Bldg.	98'	34 joints of approx. 100	Bolted Connections	Visual	Acceptable
*Containment Bldg.	125'	12 joints	Bolted Connections	Visual	Acceptable
*Containment Bldg.	125'	4 joints	Welded Connections	Weld gauge Visual	Acceptable
*Containment Bldg.	140'	15 joints	Bolted Connections	Visual	Acceptable
*Containment Bldg. Pressurizer Cubicle	-	20 joints	Bolted Connections	Visual	Acceptable
*Auxiliary Bldg. Pump Room B HPSI	51'6"	15 joints	Bolted Connections	Visual	Acceptable

*Items inspected which are not associated with the HPSI Train A system.

Findings:

Bolted Connections

Visual inspections performed in the HPSI Pump Room A found four bolts which were finger loose. The bolts are shown on Drawing 13-C-ZAS-581 Revision 7 and connect the AC-6 platform at the 51'6" elevation. The connections were inspected by Bechtel Quality Control personnel on August 17, 1980, and found acceptable.

Specification 13-CM-320 requires the turn-of-the-nut method be used to obtain a minimum tightness of 39 Kips on an A325, 7/8 inch diameter bolt. To verify whether correct turn-of-the-nut tightness was achieved, the inspector requested the licensee to retorque a sample number of A325 bolts. The contractor used a calibrated torque wrench set at 560 foot pounds. Torque testing of bolted clips to I beams in the Containment Building, AD06 pipe way at AE, 6 foot east of AD, elevation 51'6" found one bolt which required a nut rotation of 60 degrees to achieve the minimum tightness requirements of 39 Kips.

In the Containment Building at 125 degrees azimuth, 10 foot from the liner plate, elevation 88, one bolt is an I beam to I beam connection turned 45 degrees before achieving the minimum tightness.

The loose bolts discussed above were previously inspected and accepted by Bechtel Quality Control personnel.

The installation specification 13-CM-320 Revision 8, for erection of structural and miscellaneous steel, specifies AISC as applicable for structural joints using ASTM-A325 or A490 bolts. Table 3 of this specification requires that 7/8 inch diameter, A325 bolts must be tightened to a minimum tension of 39 Kips.

Failure to achieve the required bolt tightness is a Violation of the installation specification 13-CM-320 and 10 CFR 50, Appendix B, Criterion V. The licensee had commenced corrective actions by issuing a non-conformance report.

All other bolted connections were found acceptable to the applicable acceptance standards.

Welded Connections

In the Auxiliary Building Pipe Chase, elevation 51', the inspector found six fillet welds with undersize leg length and unacceptable undercut. The welds are portions of a W8X31 pipe rack, number 79, fabricated by Marathon Steel Company and shown on Drawing No. 13-S-ZAS-536, Revision 3. In the AD06 pipe way, elevation 51'6", the inspector found six additional fillet welds with undersize leg lengths. The welds are portions of W16X36 I beams clip connections shown on Drawing No. 13-ZAS-500 Revision 10.

The drawings stated above specify a 5/16 inch fillet weld for these connections. The inspector found fillet sizes down to 5/32 inch. The undercut criteria is specified in AWS D1.1 which states, Undercut shall be no more than .01 inch deep when its direction is transverse to primary tensile stress in the part that is undercut, nor more than 1/32 inch for all other situations. Contrary to this requirement, the inspector found undercut of approximately 1/16 inch deep. All other welds inspected were found acceptable to the applicable requirements.

Failure to achieve the required minimum fillet sizes and allowing undercut which exceeds the acceptance standards is a Violation of the applicable drawings, Bechtel Specification 13-CM-320, Revision 8, AWS D1.1 and 10 CFR 50, Appendix B, Criterion IX.

In addition to the inspection associated with the HPSI, Train A system, the inspector randomly selected and inspected 66 bolted and/or welded structural steel connections in the Auxiliary Building and Containment Building. All items were found acceptable to the applicable acceptance standards.

3. Containment Penetrations



Reviews were made of five piping penetrations and one electrical penetration associated with the HPSI Train A system. In addition, one containment pressure, and one spare piping penetration was reviewed.

The review included a walk down of penetrations number 13, 14, 15, 16, 77 (piping), 69 (spare penetration), 62 (containment pressure), and 47 (electrical penetration), to assure the welding was in accordance with ASME, B&PV Code, Section III. In addition, a record review was made to ascertain compliance with the applicable requirements. The inspector verified the below listed attributes were performed in accordance with the requirements. No items of noncompliance were identified.

<u>Penetration Number</u>	<u>Weld Reinforcement</u>	<u>Surface Finish</u>	<u>NDE</u>	<u>Weld Procedure Qualification</u>	<u>Preheat Temp. Maintained</u>	<u>Interpass Temp. Controls</u>	<u>Filler Metal</u>	<u>Weld Checklist</u>	<u>Material Test Report</u>
13	X	X	X	X	X	X		X	X
14	X	X	X	X				X	X
15	X	X	X	X	X	X	X	X	X
16	X	X	X	X	X	X		X	X
77	X	X	X	X	X			X	X
69	X	X	X	X				X	
62	X	X	X	X					
47	X	X	X	X					X

Symbols for Joint Types

- B — butt joint
- C — corner joint
- T — tee joint
- BC — butt or corner joint
- TC — tee or corner joint
- BTC — butt, tee, or corner joint



MAXIMUM SIZE OF FILLET WELD ALONG EDGES

Symbols for Base Metal Thickness and Penetration

- L — limited thickness — complete joint penetration
- U — unlimited thickness — complete joint penetration
- P — partial joint penetration

Symbols for Weld Types

- 1 — square-groove
- 2 — single-Vee-groove
- 3 — double-Vee-groove
- 4 — single-bevel-groove
- 5 — double-bevel-groove
- 6 — single-U-groove
- 7 — double-U-groove
- 8 — single-J-groove
- 9 — double-J-groove

Symbols for Welding Processes, if not Manual Shielded Metal-Arc

- S — Submerged Arc
- G — Gas Metal-Arc
- F — Flux Cored Arc

Fig. 2.6.1—Prequalified joints, method of joint and weld classification

2.7.1.1 The minimum fillet weld size, except for fillet welds used to reinforce groove welds, shall be as shown in the following table:

Base Metal Thickness of Thicker Part Joined, in.	Minimum Size* of Fillet Weld, in.
To $\frac{1}{4}$ inclusive	$\frac{1}{8}^{**}$
Over $\frac{1}{4}$ to $\frac{1}{2}$ inclusive	$\frac{3}{16}$
Over $\frac{1}{2}$ to $\frac{3}{4}$ inclusive	$\frac{1}{4}$
Over $\frac{3}{4}$ to $1\frac{1}{2}$ inclusive	$\frac{5}{16}$
Over $1\frac{1}{2}$ to $2\frac{1}{4}$ inclusive	$\frac{3}{8}$
Over $2\frac{1}{4}$ to 6 inclusive	$\frac{1}{2}$
Over 6	$\frac{5}{8}$



*Except that the weld size need not exceed the thickness of the thinner part joined.

**Minimum size for Bridge applications $\frac{3}{16}$ in.

2.7.1.2 The maximum fillet weld size permitted along edges of material shall be:

(1) the thickness of the base metal, for metal less than $\frac{1}{4}$ in. thick; (See Fig. 2.7.1, Detail A)

(2) $\frac{1}{16}$ in. less than the thickness of base metal, for metal $\frac{1}{4}$ in. or more in thickness, (See Fig. 2.1.1,



SKewed TEE JOINTS

Fig. 2.7.1—Details for fillet welds

Detail B) unless the weld is designated on the drawing to be built out to obtain full throat thickness.

2.7.1.3 Fillet welds in holes or slots in lap joints may be used to transmit shear or to prevent buckling or separation of lapped parts. These fillet welds may overlap, subject to the provisions of 2.3.2.2. Fillet welds in holes or slots are not to be considered as plug or slot welds.

2.7.1.4 Fillet welds may be used in skew joints that have an included angle of not less than 60 degrees. (See Fig. 2.7.1, Details C and D)

2.7.1.5 The minimum length of an intermittent fillet weld shall be $1\frac{1}{2}$ in.

2.8 Plug and Slot Welds⁵

2.8.1 Plug and slot welds in lap joints may be used to transmit shear or to prevent the buckling or separation of lapped parts.

2.8.2 The diameter of the hole for a plug weld shall be not less than the thickness of the part containing it plus $\frac{5}{16}$ in., preferably rounded to the next greater odd $\frac{1}{16}$ in., nor shall it be greater than $2\frac{1}{4}$ times the thickness of the weld.

2.8.3 The minimum center to center spacing of plug welds shall be four times the diameter of the hole.

2.8.4 The length of the slot for a slot weld shall not exceed ten times the thickness of the weld. The

⁵ See Appendix A for the technique of making plug and slot welds.

SI - 008 - 5002

$\frac{1}{16}$ " P.I. Problem

Narbut Note

51

STATUS: AA

VENDOR: HBA

PALO VERDE NUCLEAR GENERATING STATION

NONCONFORMANCE REPORT



1. UNIT	2. MO DAY YR	3. DRAWING/PART NO.	4. ITEM DESCRIPTION	REV.	5. ITEM LOCATION	NO. PA-7138	PAGE 1 OF 2
1	9/9/83	13-A 5/6-201	13 PIPE - 10" SCH 40- GLC	13	AUX BLDG 'A'		
6 Q/C CLASS	7. STARTUP SYSTEM NO.	8. SERIAL NO.	9. SUBCONTRACTOR/SUPPLIER/BECHTEL		10. P.O. OR SPEC NO.	11. ASME AUTHORIZED INSPECTION REQ'D	
M	151-008-5002	151-008-5002	BECHTEL		13-PN-204(12)	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO 9/9/83	
12. DESCRIPTION LIST IN ORDER: NO. PCS., DWG/SPEC REQMT., PRESENT CONDITION			16. FIELD ENGR DECISION	17. <input type="checkbox"/> FIELD RECOMMENDED <input type="checkbox"/> DISPOSITION <input type="checkbox"/> ENGINEER L POSITION REQ'D.	18. ENGINEER CONCURRENCE REQ'D.		
<p>1 A MECHANICAL INDENTATION HAS BEEN DISCOVERED ON LINE 51-008-5-002 (MAP ATTACHED).</p> <p>THE CIRCULAR INDICATION MEASURES: 1/8" DIA. X 0.059" DEPTH.</p> <p>10" SCH/10 INCH WALL = .250</p> <p>INCH. MIN. WALL = .219</p> <p>CALCULATED WALL = .198</p> <p>INSTRUMENT: STARRETT DIAL INDICATOR</p> <p>DEPTH GAUGE - S/N JGA-0683; RANGE .0005-.125"; CAL. 9-23-83 - 9-23-83</p>			<p>A UT exam has been performed around the circular indication and a min. wall thickness of .256" has been found (Note: this is .006" above nom. wall). Per engineering calculation 22.584 a wall thickness of .198" (.257" (.256-.059") will not affect the integrity or function of the pipe.</p> <p>QA #9/63</p>				
<p>13. REPORTED BY: E. POLYCHRONIS</p> <p>14. ASSUMED CAUSE OF DISCREPANCY UNKNOWN</p> <p>INITIATOR: E. Polychronis DATE 9-9-83</p>			<p>15. INSPECTION/VALIDATION/REVIEW DATE 9/9/83</p> <p>16. AUTHOR. INSP. DATE</p> <p>17. PROJ. FIELD ENGR. DATE</p> <p>18. GROUP SUPV DATE</p> <p>19. ACCEPTANCE OF REWORK/REPAIR AUTHOR. INSP. DATE</p> <p>20. QC ENGR DATE</p> <p>21. FIELD ENGR DATE</p> <p>22. GROUP SUPV DATE</p> <p>23. PROJ. ENGR DATE</p> <p>24. QA ENGR DATE</p>			<p>15A. REPORTABILITY EVALUATION: NOT REPORTABLE: <input type="checkbox"/></p> <p>16A. REVIEWERS: R/E (Signature) QA (Signature) DATE</p> <p>17A. DISPOSITION CONCURRENCE NUCLEAR GROUP SUPV DATE</p> <p>18A. (IF REQUIRED) DATE</p> <p>19A. AUTHORIZED INSPECTOR DATE</p>	

Please do not open

GEO

Construction Testing

SJ 01

CERTIFIED REPORT of NONDESTRUCTIVE EXAMINATION

CUSTOMER Bechtel Power Corporation				DATE 9/9/83	
ADDRESS P.O. Box 49, Palo Verde, Arizona 85343				CONTROL NO OR REPORT NO GEO - UT - 1,187	
JOB OR PROJECT LOCATION PVNGS Unit #1		PO NO. 10407-13-MM-501B		PLAN OR DWG NO 13 PSIF 201 REV. N/A	
SURFACE CONDITION <input type="checkbox"/> AS GROUND <input checked="" type="checkbox"/> AS WELDED <input checked="" type="checkbox"/> AS FABRICATED	SPECIFICATION <input checked="" type="checkbox"/> ASME SECTION III <input type="checkbox"/> ANSI B31.1 <input type="checkbox"/> AWS D1.1 <input type="checkbox"/>	ACCEPTANCE STANDARD RECORD ONLY	TYPE OF MATERIAL SS		TEMP OF MATL N/A °F
TYPE OF EXAMINATION UT <input checked="" type="checkbox"/> MT <input type="checkbox"/> PT <input type="checkbox"/>		OTHER	N.D.T. PROCEDURE NO. TM D 1		REV. AMEND
ULTRASONIC EXAMINATION					
EQUIPMENT PANAMETRICS SN JJA 0066	TRANSDUCER 10 MHZ $\frac{1}{4}$ DIA	TEST BLOCK 0301 SS 1	METHOD USED DIGITAL READOUT	SCANNING METHOD CONTACT	SENSITIVITY LEVEL N/A
MAGNETIC PARTICLE EXAMINATION					
EQUIPMENT N/A	DRY <input type="checkbox"/> WET <input type="checkbox"/>	VISIBLE <input type="checkbox"/> FLUORESCENT <input type="checkbox"/>	AC <input type="checkbox"/> RECTIFIED <input type="checkbox"/>	DC <input type="checkbox"/>	AMPERAGE
LIQUID PENETRANT EXAMINATION					
<input type="checkbox"/> Solvent Removable <input type="checkbox"/> Post Emulsifying <input type="checkbox"/> Water Washable N/A	PENETRANT Brand No.	CLEARER Batch No.	EMULSIFIER Brand No.	Batch No.	DEVELOPER Brand No.
AREA EXAMINED SJ 008 5002 10"	AREA EXAMINED SEE REMARKS		TYPE OF WORK NEW <input checked="" type="checkbox"/>	REPAIR <input type="checkbox"/>	BECHTEL NDE PROCEDURE NO. TM D 1 REV. O AMEND N/A
TYPE OF DEFECTS CODE C - Cracks P - Porosity NF - Non-Fusion LI - Linear Indication S - Slag LA - Lamination OTHER - Specify					
SERIAL # OR WELD # 5002	ACC N/A	REJ N/A	DEF. CODE	REMARKS Scanned entire area around indication Min reading obtained = .251 couplant = cellulose gum Nom wall = .250" Min wall = .219" NCR PA 7138	SERIAL # OR WELD # ACC REJ DEF. CODE REMARKS

AREA -

Aux

NPW

NCR # PA 7138
Q. 3 o/p 3

Technician John D Brown II SNT-TC-1A
 Asst Technician N/A
 Customer acceptable / March 9/9/83
 Witnessed by NONE
 ENCLOSURE ADDED Yes No
 SIGNATURE _____
 Page 1 of 1



Walk down bug off Procedure 204

463032

Page 1

PALCO VERDE NUCLEAR GENERATING STATION

JOB NO. 10407

PIPING RELEASE FOR INSULATION UNIT NO. 1

QC FIELD INSPECTION REPORT

DATE

11/11/81

RELEASE NO.

301-398

STARTUP SYSTEM

152091

LINE

SLB008

SPOOLS

5001 THRU 5008

VALVES

V470 Q 55

DATE

NAME OF
INITIATOR

NAME OF
INSPECTOR

CLEANED

11-1-82

RWS



11/14/82

INSPECTED

INSULATED

1-31-83

RWS

Remarks

PALLO VERDE NUCLEAR GENERATING STATION

JOB NO. 10407

PIPLING RELEASE FOR INSULATION UNIT NO. 1QC FIELD INSPECTION REPORTDATE 11/11/81RELEASE NO. 301-398

STARTUP SYSTEM

15209

LINE

SLB08SPOOLS 5001 THRU 5008VALVES V470 Q 55

	<u>DATE</u>	<u>NAME OF INITIATOR</u>	<u>NAME OF INSPECTOR</u>
CLEANED	<u>11-1-82</u>	<u>RWS</u>	<u>11/14/82</u>
INSPECTED			
INSULATED	<u>1-31-83</u>	<u>PWS</u>	

Remarks _____

INSULATION SERVICES, INC. - JOB 1411
PALO VERDE NUCLEAR GENERATING STATION
10407-13-MM-301 (PO) (SC)

RELEASE NO. 398
LINE NO. SI-008

UNIT NO. 1
SHEET 60 of 102
BILLING NO. 21

MULT.	PIPE SIZE X THICKNESS DESCRIPTION	10X2 LF/ea	10X2 E.LF	1X2 LF/ea	1X2 E.LF	1X2 LF/ea	E.LF	LF/ea	E.LF
---	Pipe	59	59						
X 2	Tee, Cross, Wye, Union, Coup., Cap., Red.								
X 3	Elbow & Bend 1.5 Times	4	12						
X 4	Expansion Joints								
X 2	Strainer 1" to 4"								
X 4	" 4" to 10"								
X 8	10" and larger								
	Valve (excludes in line flanges) - All valves except Fl.Bonnet valves								
X 4	1" to 4"								
X 6	4.5" to 10"								
X 8	12" and larger								
	Valves with flanged bonnet								
X 5	1" to 4"								
X 7	4.5" to 10"	1	7						
X 9	12" and larger								
	Flanges								
X 4	In line	2	8						
X 4	Equipment nozzle								
X 2	Uncovered								
X 4	Valve								
	Stub-ins, bosses & butt- weld Tees W/branches 1.5"								
	NPS + smaller and run of								
X 1.5	6" NPS and larger each			2	3				
X 2	Sup. collars and kickbands								
X 1.5	Bevels								
	Other								
	Subtotal ELF	86		3					
	ASME III & H.T. Surcharge	—		—					
	Total ELF	86		3					
	Material unit	7.92		2.75					
	Material price	681.12		8.25					
	Labor unit	8.01		5.22					
	Labor price	688.86		15.66					

CERTIFIED CORRECT:

D.P.C. _____ Date: _____

I.S.I. Schussel Date: 11-23-82

Ref: Dwg. No. SI-201

Insulation: Cal. Sil. ✓ F/G

Complete: Partial: ✓

TOTALS THIS PAGE:


1M-301-PO-Material: 689.37

EM-301-SC-Labor: 704.52

ASME Piping - 1.5

Heat traced - 1.05

Turbine - 1.10

LOS ANGELES
POWER DIVISION

DATA

LARGE PIPE CONTROL CARD

RETENTION TIME 27 YRS RS.
1510085002
SPOOL TAG NUMBER

Code

64

SIZE	LENGTH	P&ID NO.	COORD	REV	PROJ CLASS	AREA
MAT'L CLASS	S/U SYSTEM	MRR NO.			STORAGE LOC	VENDOR
RECEIVED	FPT	DATE	INSTALLED		FOREMAN	DATE

1-51-008-5002

7
REV.NA
FCRNA
DCN

AISK NO.	INSPECTION ITEM	AFE	DATE	QCE	DATE
1.0	SPOOL NUMBER MARKING VERIFIED	QH	10/10/80	BPC 118 QCE	10/13/80
2.0	CONFIGURATION & ORIENTATION PER ENGR DWG	QH	10/10/80	BPC 118 QCE	10/13/80
3.0	ORIENTATION OF FLOW ELEMENTS, ETC.	QH 10/13/80	NA	N/A	
4.0	INTERNAL CLEANLINESS INSPECTION LEVEL:	FB	QH	BPC 118 QCE	10/13/80
5.0	SURFACES FREE OF INJURIOUS DEFECTS	QH	10/10/80	BPC 118 QCE	10/13/80
6.0	RECORD NCR & MCN APPLICABLE TO INSTALLATION	NA		N/A	
7.0	INSTALLATION ACCEPTED	QH.1 0-1 1-51-008-5,002	QH	BPC 118 QCE	10/13/80

MARKS: INFO TRANSFERRED FROM SUPPLEMENTARY SHEET DATED 8/28/78 QC H64
10/13/80

LAO-0478 12/79

PIPE: 10" SCH 20 WELDED SA312 TP304

Q 4-1 C 4 J W

S&D DATA REPORT

FORM NPP-1 DATA REPORT FOR FABRICATED NUCLEAR PIPE ASSEMBLIES
(As Required by the Provisions of the ASME Code Rules)RETENTION TIME "15 yrs.
ASSEMBLIES page 1 of 2
MRR NO. 279641. Fabricated by *Pullman Power Products, Paramount, CA
(Name and Address of Fabricator) Order No. 2810 R40602. Fabricated for Bechtel Power Corp., Norwalk, CA
(Name and Address) Order No. 10407-13-PM-201

3. Owner Arizona Public Service Co. 4. Location of Plant 3 miles south of Wintersburg, AZ

5. Piping System Identification SAFETY INJECTION Serial No. N-5589-R ✓
(Brief description of Intended use, main coolant etc.)

Bechtel Dwg.

(a) Drawing No. 13-P-SIF-201

Prepared by

Bechtel Power Corp., Norwalk, CA

(b) National Board No. N/A

6. The material, design, construction, and workmanship complies with ASME Code Section III, Class 2 ✓
Edition 1974, Addenda Date Summer 1975, Case No. -----

Remarks: Manufacturers' Data Reports properly identified and signed by Commissioned Inspectors have been furnished for the

following items of this report NOT APPLICABLE

(Name of Part — Item number, Manufacturer's name, and identifying stamp)

7. Shop Hydrostatic Test None psi.

1-SI-008-S-002 ✓

8. Description of piping inspected 1-Piping Ass'y. P.C. Mk. (Include—mark no.—material spec.—nom. pipe size—schedule or thickness—Length—fittings—flanges, etc.)
Fabrication Drawing F-136R REVO FOR ORIGINAL FABRICATION SEE DATA REPORT SIGNED BY A.N.I.

ON 10-18-77 ATTACHED!! (SEE ATTACHMENT B)

PIPE: 10" SCH 20 WELDED SA312 TP304

N.D.E.: 100% R.T. GIRTH BUTT WELD

100% L.P. ATTACHMENT WELD

We certify that the statements made in this report are correct and that the fabrication of the described piping conforms with the requirements of SECTION III of the ASME BOILER AND PRESSURE VESSEL CODE

Date 4/13/78 Signed *Pullman Power Products
(Fabricator)

Certificate of Authorization Expires 11-18-80

Certificate of Authorization No. N-1926

CERTIFICATE OF SHOP INSPECTION

I, the undersigned holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and/or the State or Province of _____ and employed by H.S.B.I. & I. Co. of Hartford, Conn., have inspected the piping described in this Data Report on 4/13/1978, and state that to the best of my knowledge and belief, the Manufacturer has constructed this piping in accordance with the applicable Subsections of ASME Code, Section III.

By signing this certificate, neither the Inspector nor his employer make any warranty, expressed or implied concerning the piping in this Data Report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

Date 5/9/1978

(Inspector)

Commission No. Ca 1126

National Board, State, Province and No.

D-1-C-4-13

15-100-00

9. Description of Field Fabrication

24A

CUT ITEM (1A) AT A POINT 0'7 $\frac{3}{4}$ " AT A POINT FIELD WELD W-002.
 (REFERENCE FULLMAN SHOP DRAWING F-136R, REV. 0) WELD A 0'8 $\frac{3}{4}$ "
 10" Dia. SS pipe, Schedule 20, SA-312, TP-304, AT CUT POINT WITH FIELD
 WELD FW#301. THIS IS IN COMPLIANCE WITH NCR-PA-306 016 POSITION.
 REFER TO NCR FOR MATERIAL HEAT NUMBER.

10. Field Hydrostatic Test NA psi.

We certify that the field fabrication of the described piping conforms with the requirements of SECTION III of the ASME BOILER AND PRESSURE VESSEL CODE, Class 2, Edition 1974, Addenda Date Winter 75, Class No. NR

Date 6/25 1979 Signed BECHTEL POWER CORP. By Emil A. Kowalewski
 (Fabricator) (Representative)

Our Certification of Authorization to use the NPT Symbol Expires Sept 1 1981
 Certificate of Authorization No. N-1917-2

CERTIFICATE OF FIELD FABRICATION INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and/or the State or Province of ARIZONA and employed by LMCC of ILLINOIS

have compared the statements in this Manufacturer's Data Report with the described piping and state that the parts referred to as data items No. 9, not included in the certificate of shop inspection have been inspected by me and that to the best of my knowledge and belief the manufacturer has constructed this piping in accordance with the applicable section of the ASME CODE SECTION III.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the piping described in this Manufacturer's Data Report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

Date 6/25 1979

R. J. Wohleben
 Inspector

Commissions Az #86

National Board, State, Province and No.

SEE REVISED DATA REPORT PULLMAN POWER PRODUCTS

RETENTION TIME 10 YRS

FROM KPP-1 DATA REPORT FOR FABRICATED NUCLEAR POWER SYSTEM PIPELINES MRR NO. 2796
(As Required by the Provisions of the ASME Code Rules)

1. Fabricated by Pullman Kellogg, Paramount, CA Order No. 2810 R406①
(Name and Address of Fabricator)

2. Fabricated for Bechtel Power Corp., Norwalk, CA Order No. 10407-13-PH-201
(Name and Address)
3 miles south of

3. Owner Arizona Public Service Co. 4. Location of Plant Wintersburg, AZ

5. Piping System Identification SAFETY INJECTION & SHUTDOWN COOLING Serial No. N-5539
Bechtel Dwg. R-3 (Brief description of intended use, main coolant etc.)
(a) Drawing No. 13-P-SIF-201 Prepared by Bechtel Power Corp., Norwalk, CA
(b) National Board No. N/A

6. The material, design, construction, and workmanship complies with ASME Code Section III, Class 2
Edition 1974, Addenda Date Summer 1975, Case No. -----

Remarks: Manufacturers' Data Reports properly identified and signed by Commissioned Inspectors have been furnished for
the following items of this report - NOT APPLICABLE
(Name of Part - Item number, Manufacturer's name, and identifying stamp)

7. Shop Hydrostatic Test None psi.


8. Description of piping inspected 1-Piping Ass'y. P.C. Mk. 1-SI-008-S-002
(include - mark no. - material spec. - nom. pipe size - schedule or thickness - length
Fabrication Drawing F- 136
- fittings - flanges, etc.)

PIPE: 10" SCH 20 WELDED SA312 TP304

6" SCH 40 SMLS SA376 TP304

PLATE: SA240 TP304 (For Support Attach.)

SA516 Gr. 70 (For Support Attach.)



We certify that the statements made in this report are correct and that the fabrication of the described piping conforms
with the requirements of SECTION III of the ASME BOILER AND PRESSURE VESSEL CODE.

Date 10/13/77 Signed Pullman Kellogg By J.C. Johnson
(Fabricator)

Certificate of Authorization Expires 11/22/77 Certificate of Authorization No. N-776

CERTIFICATE OF SHOP INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors
and/or the State or Province of California and employed by D.I.S. of State of CA
have inspected the piping described in this Data Report on 10/19/77 and state that to the best of my knowledge
and belief, the Manufacturer has constructed this piping in accordance with the applicable Subsections of ASME Code,
Section III.

By signing this certificate, neither the Inspector nor his employer make any warranty, expressed or implied, concerning
the piping in this Data Report. Furthermore, neither the Inspector nor his employer shall be liable in any manner
for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

Date 10/13/77

G. DeKlerk
(Inspector)

Commissioner Ca 857
National Board, State, Province and No.

Q4/C4-3

1-51-100

MRR NO. 2004
ATTENTION TIME 23 YRS.

FORM SPP-1 DATA REPORT FOR FABRICATED NUCLEAR PIPING SUBASSEMBLIES
(As Required by the Provisions of the ASME Code Rules)

R272(I)

1. Fabricated by Pullman Kellogg, Paramount, CA Order No. 2810
(Name and Address of Fabricator)

2. Fabricated for Bechtel Power Corp., Norwalk, CA Order No. 10407-13-PM-201
(Name and Address)

3. Owner Arizona Public Service Co. 4. Location of Plant Wintersburg, AZ
3 miles south of

5. Piping System Identification SAFETY INJECTION & SHUTDOWN COOLING Serial No. N- 5589
Bechtel Dwg. R-3 (Brief description of intended use, main coolant, etc.)
(a) Drawing No. 13-P-SIF-201 Prepared by Bechtel Power Corp., Norwalk, CA
(b) National Board No. N/A

6. The material, design, construction, and workmanship complies with ASME Code Section III, Class 2
Edition 1974, Addenda Date Summer 1975, Case No. -----

Remarks: Manufacturers' Data Reports properly identified and signed by Commissioned Inspectors have been furnished for
the following items of this report NOT APPLICABLE
(Name of Part - Item number, Manufacturer's name, and Identifying stamp)

7. Shop Hydrostatic Test None psi.

8. Description of piping inspected 1-Piping Ass'y. P.C. Mk. 1-SI-008-S-002

(Include - mark no. - material spec. - nom. pipe size - schedule or thickness - length

Fabrication Drawing F- 136
- fittings - flanges, etc.)


PIPE: 10" SCH 20 WELDED SA312 TP304

6" SCH 40 SMLS SA376 TP304

PLATE: SA240 TP304 (For Support Attach.)

SA516 Gr. 70 (For Support Attach.)

N.D.E: 100% L.P. ALL ATTACHMENT WELDS



We certify that the statements made in this report are correct and that the fabrication of the described piping conforms with the requirements of SECTION III of the ASME BOILER AND PRESSURE VESSEL CODE.

Date 10/18/77 Signed Pullman Kellogg By A. E. Olson
(Fabricator)

Certificate of Authorization Expires 11/30/77 Certificate of Authorization No. N-776

CERTIFICATE OF SHOP INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and/or the State or Province of California and employed by D.I.S. of State of CA have inspected the piping described in this Data Report on 10/18/77 and state that to the best of my knowledge and belief, the Manufacturer has constructed this piping in accordance with the applicable Subsections of ASME Code, Section III.

By signing this certificate, neither the Inspector nor his employer make any warranty, expressed or implied, concerning the piping in this Data Report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

Date 10/18/77

J. W. K.
(Inspector)

Commissioner Ca 857
National Board, State, Province and No.

1. Fabricated by Pullman Power Products, Forneynt, CA. Order No. 2810
 (Name and Address of SPT Certificate Holder)
2. Fabricated for Bachtel Power Corp, Norwalk, CA Order No. 10407-13-PM-201
 (Name and Address)
3. Owner Arizona Public Service Co. 4. Location of Plant 3 miles south of Wintersburg AZ.
5. Piping System Identification Safety Injection Serial No. N-5589
 (Brief description of intended use, main coolant etc.)
Bachtel Drawing
 (a) Drawing No. 13-P-SIF-201 Prepared by Bachtel Power Corp, Norwalk, CA
 (b) National Board No. N/A
6. Description of Field Fabrication. 151-008-H003

Weld BB was cut out, C.S. plate item 5 and replaced with, S.S. plate $\frac{3}{4}'' \times 10'' \times 10'$ SA 210 Gr. TP-304 item 31 welded to item 30 with weld #3 (shop sheet drawing F-136) work done in compliance with NCR # PA-252.

7. Field Hydrostatic Test N/A psi.

We certify that the field fabrication of the described piping conforms with the requirements of SECTION III of the ASME BOILER AND PRESSURE VESSEL CODE, Class 2, Edition 1974, Addenda Date W 75 Case No. N/A

Date 8 - 8, 1980 Signed Bachtel Power Corp By Emil A. Kowacewicz
(SPT Certificate of Authorization) (Representative)

Our Certification of Authorization to use the NPT Symbol Expires Sept. 1, 1981
 Certificate of Authorization No. A-1917-2

CERTIFICATE OF FIELD FABRICATION INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and/or the State or Province of Illinois and employed by IMCC of Illinois

have compared the statements in this Data Report with the described piping and state that the parts referred to as data items.

Number 6, not included in the certificate of shop inspection have been inspected

by me and that to the best of my knowledge and belief, the SPT Certificate Holder has constructed this piping in accordance with the applicable section of the ASME CODE SECTION III.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the piping described in this Data Report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

Date Aug 13 1980

Robert C. Kochans
 Inspector

Commissions

Arizona 124
 National Board, State, Province and No.



REV. 7

PALO VERDE NUCLEAR GENERATING STATION UNITS 1, 2 & 3
RECEIVING INSPECTION PLANNING FOR
PERMANENT PLANT ITEMS
JOB NO. 10407

PAGE 2 OF 2

OP/P/QC
NO. 4.0

9. TASK NO.	10. DESCRIPTION	11. INSPECTION METHOD	12. QCE ACCEPT.	13. DATE
5.0	EXCEPTIONS:			
5.1	NO EXCEPTIONS NOTED ITEM(S) RELEASED FOR STORAGE OR INSTALLATION.	VERIFY	N/A	
5.2	INDICATE EXCEPTIONS IN REMARKS SECTION RECORD NCR NO. <u>R-699</u> OR DON NO. <u>R-699</u> ITEM(S) TAGGED AND PLACED ON HOLD PENDING COMPLETION OF RECEIVING INSPECTION.	VERIFY	(P) 6/2/78	6-9-78
5.3	INDICATE EXCEPTIONS IN REMARKS SECTION RECORD NCR NO. _____ ITEMS TAGGED AND CONDITIONALLY RELEASED FOR INSTALLATION.	VERIFY	N/A	

14. REMARKS:

1. DON R-699- DOCUMENTATION.
2. THIS RIP & DOCUMENTATION
IS FOR PIPE SPEL 136-R
MK # 1-SI-008-5-002 ONLY.

EXHIBIT 4.0-1 (back)

15. COMPLETED PACKAGE REVIEWED
AND ACCEPTED

POCE Miles E. Moore DATE 6/5/78

RETENTION TIME 4 YRS

MACH NO. G-1064

P4060

EXHIBIT SA-2

HEAD INSTRUCTIONS BEFORE FILLING IN FORM

This form is used for Quality Verification. It is intended to be used in conjunction with the Quality Assurance Document Requirements and those requirements are made in accordance with the quality assurance program. It is the responsibility of the Quality Assurance Department to ensure that this form is used in accordance with the quality assurance program.

1. Document Category Number	2. Description Reference	3. Date Issued	4. KEEPING DOCUMENTS		QUALITY VERIFICATION DOCUMENTS					12. Remarks
			5. QDQCS	6. QAR	7. Quality Required	8. Date	9. Inspector Name	10. Engineer Name	11. Date	
			Document No.	Date Issued	Code No.	Check No.				
12.0 4.6.	Reproduction			1 b	a	G/T/H				* SEE QAR-3
12.0 5.1	Material			1 b	a	G/T/H				* SEE QAR-5
12.0 4.6.	Reproduction			1 b	a	G/T/H				* SEE QAR-2
12.0 5.3	Material			1 b	a	G/T/H				
13.0 4.6.	Reproduction				N/A	G/T/H				
13.0 3.9	Material			1 b	N/A	G/T/H				
14.0 4.6.	Reproduction			1 b	N/A	G/T/H				
14.0 6.6	Material			1 b	N/A	G/T/H				
14.0 4.4.	Reproduction			1 b	N/A	G/T/H				
14.0 2.3	Material			1 b	N/A	G/T/H				
14.0 4.12.	Reproduction		NOT USED	1 b	1	G/T/H				Verification Reports
15.0 1	Material			N/A	G/T/H					* SEE QAR-1-C
16.0 3d	Material				*	G/T/H				* SEE QAR-1-C
17.1 4.4.	Reproduction			1 b	*	G/T/H				* SEE QAR-1-C
17.1 1.2	Material			1 b	*	G/T/H				
17.1 4.15.	Reproduction			1 b	N/A	G/T/H				
17.1 3c	Material			1 b	N/A	G/T/H				
17.2 4.9.	Reproduction			1 b	N/A	G/T/H				
17.2 2.2	Material			1 b	N/A	G/T/H				
17.2 4.6.	Reproduction			1 b	*	G/T/H				Ferrite Data Report
17.3 3.7	Material			1	1	1				* FOR WELD MATERIAL SEE QAR-2

13. Supplier's Order No.

2810

14. Supplier's Part No.

SEE PAGE 3 OF 3

15. Supplier's Part Name

PIPE SPOOLS

16. Quantity

1

17. Buyer's Part No.

ITEM 2

18. Buyer's Part Name, Tag or Case No.

SEE PAGE 3 OF 3

19. Transaction

RELEASE 39

SEE PAGE 3 OF 3

21. Supplier's Statement

I certify that the listed work and required documents meet the requirements of the producing documents.

Supplier Signature _____ Date _____

22. Inspector's Statement

Work was released based on satisfactory completion of inspection and review of documentation.

Inspector Signature _____

Authorized Examiner YES Release under 12. Remarks CONT

4-13-78 Date

23. Engineer's Statement

The Quality Verification Document is submitted to Engineering with this form have been reviewed to conform to the specified reference standards acceptable.

Eng. No. _____

Signature _____

FILED

5-9-78 Date

24. Quality Control's Statement

Quality and the Quality Verification Document reported herein have been reviewed and found to be acceptable.

QC No. _____

Signature _____

10407 Date

RT SPEC NUMBER

13-111-201 Date

5-13-78 Date

1 of 3 Page

PALO VERDE NUCLEAR GENERATING STATION

UNITS 1, 2 AND 3

QUALITY VERIFICATION DOCUMENT REQUIREMENTS



QUALITY VERIFICATION DOCUMENT REQUIREMENTS

EXHIBIT 5A-2

RETENTION TIME ~~10~~ yrs.
MR NO. 27964

R406①

READ INSTRUCTIONS BEFORE FILLING IN FORM

This document contains for Quality Verification. Documents are to be furnished in accordance with the Schedule set forth below. Supply's failure to comply with these requirements may result in order cancellation or withholding of payment until compliance is established.

1. Document Category Number	2. Description Paragraph Reference	3. Kind of Item	ENGINEERING DOCUMENTS		QUALITY VERIFICATION DOCUMENTS					12. Remarks
			4. Quantity Required	5. Unit Required	6. Date Required	7. Document Name	8. Inspection Status	9. Engineering Review Status	10. Field DCE Check In	
17.4	4.15. 3E	Reproduction					*	GPA		* SEE QAR-1-C
		Microfilm								
18.0	4.2.4 4.15.	Reproduction			1. b	3	GPA			
		Microfilm			1. b	4	GPA			
19.0	3.8 4.15.	Reproduction			1. b	N/A	GPA			
		Microfilm			1. b	1	GPA			INCLUDES 1 PACKAGE OF FILM
20.0	3h 4.15.	Reproduction			1. b	N/A	GPA			
		Microfilm			1. b	N/A	GPA			
21.0	3a 4.15.	Reproduction			1. b	1	GPA			
		Microfilm			1. b	1	GPA			
22.0	3a 4.9.	Reproduction	NOT USED		1. b	N/A	GPA			
		Microfilm			1. b	N/A	GPA			
24.0	1.1	Reproduction			1. b	2	GPA			
		Microfilm								
25.0	4.11	Reproduction								
		Microfilm								
12. Buyer's Part No.	14. Supplier's Part No.	16. Supplier's Part Name	18. Quantity							
2810	SEE PAGE 3 OF 3	PIPE SPOOLS	1							
17. Buyer's Part Num. Ref.	18. Buyer's Line Item Tag or Code No.	19. Buyer's Part Name	20. Transparency							
ITEM 2	SEE PAGE 3 OF 3	PIPE SPOOLS	RELEASE 39							
21. Supplier's Signature	We certify that the listed work and required documents meet the requirements of the preceding documents.	Sig: <i>J.M. Miller QA ENGINEER 4/13/78</i>	Date: <i>4/13/78</i>							
22. Inspection Review Statement	Work was released based on satisfactory completion of inspection and review of documentation.	Authorizing Person: <i>Assistant FOR G. WADDEP</i>	Date: <i>4-13-78</i>							
23. Engineering Review Statement	The Quality Verification Documents submitted to Engineering with this form have been reviewed for conformance to the specified requirements and are acceptable.	Engineering: <i>Sig: [Signature]</i>	Date: <i>4-13-78</i>							
24. DCE Check In Statement	The form and the Quality Verification Documents referenced herein have been reviewed and then released to the hardware department.	DCE: <i>Lorraine C. H. Hite</i>	Date: <i>5-9-78</i>							
Ansi/ASQC Z1.4-1979 - Purchasing - Production - Quality Control - Material Management - Quality Assurance										
PALO VERDE NUCLEAR GENERATING STATION UNITS 1, 2 AND 3										
QUALITY VERIFICATION DOCUMENT REQUIREMENTS										
JOB NO. 10407 PO SPEC NUMBER 13-TM-201										
SHEET 2 OF 3 1										



G-321-D

RELEASE: 39

JOB NO.: 2810

Pullman Power Products
Supplemental Sheet 3 of 3

Form 1286-321-0

R4DG①

RETENTION TIME ~~4~~ yrs.
MR NO 27964

PULLMAN POWER PRODUCTS
-SHEET NUMBER

BECHTEL PIECE
MARK NUMBER

F- 136R

1-SI-008-S-002

Pullman Power Products Verification

J.M. Palac
Signature
QA ENGINEER
Title

Date 4/13/78

Bechtel Verification

G.Waldrop
Signature

Title SQR

Date 4-13-78

RELEASE: 39

JOB NO.: 2810

Pullman Power Products

DATE: 4/13/78

R4060

MRR NO. 27964

RETENTION TIME 1/4 yrs

INSPECTION VERIFICATION REPORT

All pipe spools inspected in accordance with approved Pullman Power Products procedures and procurement documents. Inspection signed off on shop traveler by Pullman Power Products and Bechtel Inspector. Traveler on file for review.

Verification Inspection by Pullman Power Products Quality Assurance.

J.M. Palac
Signature

QA ENGINEER
Title

Date

4/13/78

Verification Inspection by Bechtel.

C. H. Hunt
Signature

SQR

Title

4-13-78

Date

RETENTION TIME 12 YRS

SEE TRAVELER 2810 F-136 MBR NO 27964

QUALITY VERIFICATION DOCUMENTATION LIST

NUCLEAR PIPING SUB-ASSEMBLIES

Records and/or Reports which apply to this individual piece

ARIZONA PUBLIC SERVICE COMPANY
 PALO VERDE NUCLEAR GENERATING STATION
 BECHTEL P.O. No. 10407-13 3 PM 201

BECHTEL ITEM NO. 2

QUALITY PROGRAM DOCUMENTATION

Front F Sheet Item No.

Material Verification

MATERIALS	DOC CODE	SPEC PARAGRAPH	#	1	1A	*	2							
Certified Chemical and Mechanical Properties	Note A	4.15.3												
Impact Test Report Materials	Note A	4.9.2.2												
Manufacturer's Cert. of Compliance	Note A	4.17												
* Manufacturer's Partial Data Report	Note A	4.15.2												
PT Report Materials	Note A	4.15.3												
MT Report Materials	Note A	4.15.3												
Radiographic Film Materials		4.8.2.1.2												
Ultrasonic Exam. Report - Materials	Note A	4.15.3												
Report of Vendor's MT Repair Weld	Note A	4.15.3												
PT or MT Report - Vendor Repair Weld	Note A	4.15.3												
Radiographic Report - Vendor Repair Weld	Note A	4.15.3												
Stress Relief of Vendor Repair Weld	Note A	4.15.3												
Test Report - Weld MT Repair - Vendor	Note A	4.15.3												
Deviation Requests and Resolution		4.15.2												

Note A: No transmittal - Approved by reference on the "as built" F Sheet

Note B: No transmittal - A QC Form is included in Tool only.

Note C: Approved by reference on the Quality History Record

RELEASED FOR SHIPMENT
Pullman Power Products*J.W. Galae* 4/13/78SHOP INSPECTION
BECHTEL POWER CORPORATIONFACILITY: SOR TEST: *Established* DATE: *4/13/78*

REVISIONS

RETENTION TIME 10 yrs

BECHTEL FOR DOC. SEE TRAVELER 2810 F-136 "

REVISED 1996-11

Q.D.C.

ITEM DOCUMENTATION LIST

PUNG SUB ASSEMBLIES

which apply to an individual piece

ELECTRIC SERVICE COMPANY
CLEAR GENERATING STATION
P.O. No. 10407-13-PM 201

Z

BECHTEL

QUALITY - 47

DOCUMENTATION

From F Sheet Item No.

Material Identification

OPERATOR
CENTRAL
THE MAILDOC
CODESPEC
PARAGRAPH#
1 1A
S/S S/STransfer
IdenticalN.A.9744 R
(a) (3)Pending
ReportNote
B

4.567

Post P.T.
Report

16

4.152

Post Err.
ReportNote
BU.T. Rept.
After Br.

19

48252

P.T. Rept.
After Br.

22

4568

Report of
Pullman E
Material P

14

4423

Gold Dat
Material PNote
C

4423

P.T. or M
Material P

14

4423

Pending
Report P

14

4423

U.S. Std.
of Mater

14

4423

BECHTEL

250

ITEMS ON A PER PIECE BASIS

DOC. CODE

SPEC PARAGRAPH

Full Furn.

Report of

16

4153d

Gold Hist.

X S/S

4647, & 4.9

Delta Furn.

17

4637

Cleaning E

S. 150 Report of

X

15

44438

G.D. Part E

S/S

Note B

G.D. Part P

X

Note B

Repairs

X

Note B

Final S

X

474

Final D

X

417 & 4.11

Final T

X

RETENTION TIME 1 yr

MR&BL 22-964

Pullman Power Products
Division of Pullman Incorporated

P-04 3 of 3

QUALITY VERIFICATION DOCUMENTATION LIST
NUCLEAR PIPING SUB ASSEMBLIES

Records and/or Reports which apply to an individual piece

ARIZONA PUBLIC SERVICE COMPANY
PALO VERDE NUCLEAR GENERATING STATION
BECHTEL P.O.No. 10407-13 PM 201

BECHTEL ITEM NO. 2

QUALITY PROGRAM DOCUMENTATION

From F Street Weld

77-37

REVISED 1/26/78

WELDS	DOC CODE	SPEC. PARA.	A	B	C	D	E	F	G	H
P.T. or M.T. Report Preparation for Weld		Sect. III NB INCL - 5130								
Weld Data Report	Note C									
Local Stress Relieve Chart	16	4.15. 3d								
P.T. or M.T. Report	21 22	4.15. 3e								
Radiographic Report	20	4.15. 3b								
Radiographic Films		4.5 23								
Weld Material Qualification	Note C									
Weld Data Report Weld Repair	Note C									
Local Stress Relieve Chart of Weld Repair	16	4.6.6								
P.T. or M.T. Report of Weld Repair	21 22	4.6.6								
Radiographic Report of Weld Repair	20	4.6.6								
Radiographic Films of Weld Repair		4.6.6								
Deviation Requests And Resolution		4.15.2								

BECHTEL
250

Pulman Forest Products
Division of Pulman Incorporated

RETENTION TIME 2 yrs

MGR NO. 27964

R406①

Liquid Penetrant Inspection Record

Job No. 2810

DATE 4-13-78

Piece No. 1-SI-008-5-C02

ITEM NO. 136

Material S/S

Examination Procedure JS404 REV.O

Acceptance Criteria JS404 REV.O

Brand Name and Type of:
Penetrant SPOT CHECK
Cleaner " "
Developer " "

Batch No. of:
Penetrant 7D073
Cleaner 7K001
Developer 7K054

Chemical Analysis Certification of Test Components Attached.

RECORD OF EXAMINATION RESULTS

Accept (Weld) D

BECHTEL
250

Name of Inspector George Franklin

SNT-TC-1A Level II

RECORD OF RE-EXAMINATION

Name of Inspector _____

SNT-TC-1A Level _____

RETENTION TIME 14 YRS.
MRN NO 27964

77373

REVISED 1/26/78

WELD HISTORY RECORD			
WELD FROM F SHEET	VPS IN QAH 3 (IS NOT)	WAOH NO IN QAH 2	WELDER OR WELDING OPERATOR SYMBOL
C	803 803 805	118-1 118-1 176-1	JS M M
D	803	118-1	B
			BECHTEL 250
Puliman Power Products Division of Puliman Incorporated	QA	JML	JOB NO. 2810
	FILE NAME	1-SI-005-S-002	
	DATE	4-13-78	DWG. NO. F - 3362

RETENTION TIME 15 yrs

MRR NO. 27964

R4060

VISUAL INSPECTION FINAL INSPECTION CHECKLIST			
JOB NO <u>2640</u>	PIECE NO <u>1-SI-CUES-002</u>	WORK NO <u>245</u> <u>2467</u>	COMMENTS
CHECK POINTS	YES	NO	N.A.
ALL PRIOR OPERATIONS HAVE BEEN PERFORMED AND APPROVED AND SIGNED OFF IN THE TRAVELER.	/		
SPECIFIED MATERIALS HAVE BEEN INSTALLED IN THE PIPING SUB-ASSEMBLY.	/		
ALL STAMPING DISPLAYED ON THE PIPING SUB-ASSEMBLY IS ACCURATE AND CORRESPONDS WITH THE INFORMATION PRESENTED ON THE FABRICATION SHEET.	/		
FINAL DIMENSIONAL EXAMINATION HAS BEEN PERFORMED AND THE DIMENSIONAL INFORMATION HAS BEEN RECORDED ON THE FABRICATION SHEET.	/		
LEVELING HAS BEEN PERFORMED IN ACCORDANCE WITH THE REQUIREMENTS OF THE GOVERNING SPECIFICATION.	/		
WELLER SYMBOLS AND RADIOPHGRAPHIC POINT LOCATIONS HAVE BEEN ACCURATELY APPLIED AND ARE COMPLETE.	/		
CONTROL, FINISH, AND HEIGHT OF WELD CRACK COMPLIES WITH THE REQUIREMENTS OF THE GOVERNING SPECIFICATION.	/		
ALL ACCESSIBLE INSIDE WELD BEADS HAVE COMPLETE JOINT PENETRATION AND ARE FREE FROM UNDERRCUTTING.	/		
FIELD WELD END PREPS ARE MACHINED TO THE CONFIGURATION AND TOLERANCES dictated ON THE MACHINING SKETCH.	/		
PIPING SUB-ASSEMBLY IS FREE FROM DAMAGE, EXCESSIVE PITTING, AND UNACCEPTABLE SURFACE DEFECTS.	/		
ASSEMBLY HAS BEEN INSPECTED AND APPROVED BY THE AUTHORIZED INSPECTOR AND OR THE CUSTOMERS SURVEILLANCE REPRESENTATIVE.	/		BECHTEL 250
THE APPROPRIATE CODE STAMP HAS BEEN APPLIED.	/		
ASSEMBLY HAS BEEN CAPPED, PAINTED, AND IDENTIFIED IN ACCORDANCE WITH THE REQUIREMENTS OF THE GOVERNING SPECIFICATION.	/		
PULLMAN POWER PRODUCTS Division of Pullman Incorporated	INSPECTED BY <u>George Pugh</u>	APPROVED <u>John Tolson</u>	DATE <u>4-13-78</u>

REVISED DATA REPORT

FORM NPP1 DATA REPORT FOR FABRICATED NUCLEAR PIPING SUBASSEMBLIES
(As Required by the Provisions of the ASME Code Rules)RETENTION TIME 15

MVR NO. 279

1. Fabricated by Pullman Power Products, Paramount, CA (Name and Address of Fabricator) Order No. 2810 R406C2. Fabricated for Bechtel Power Corp., Norwalk, CA (Name and Address) Order No. 10407 13 PM 2013. Owner Arizona Public Service Co. 4. Location of Plant 3 miles south of Wintersburg, AZ5. Piping System Identification SAFETY INJECTION Serial No. N 5569-R

Bechtel Dwg. (Brief description of intended use, main coolant etc.)

(a) Drawing No. 13-P-SI-F-201 Prepared by Bechtel Power Corp., Norwalk, CA(b) National Board No. N/A6. The material, design, construction, and workmanship complies with ASME Code section III, Class 2Edition 1974, Addenda Date Summer 1975, Case No. _____Remarks: Manufacturers' Data Reports properly identified and signed by Commissioned Inspectors have been furnished for the following items of this report NOT APPLICABLE
(Name of Part - Item number, Manufacturer's name, and identifying stamp)7. Shop Hydrostatic Test None psi.8. Description of piping inspected 1 Piping Ass'y Pd. Mfg. 1-SI-008-S-002(includes part no., material spec., nom. pipe size, schedule or thickness, length, fittings, flanges, etc.)
Fabrication Drawing F-136R REVO FOR ORIGINAL FABRICATION SEE DATA REPORT SIGNED BY A.N.I.

9. ON 10-18-77 ATTACHED" (SEE ATTACHMENT B)

1

PIPE: 10" SCH 20 WELDED SA312 TP304

2

3

4. N.D.E.: 100% R.T. GIRTH BUTT WELD5. 100% L.P. ATTACHMENT WELD

We certify that the statements made in this report are correct and that the fabrication of the described piping conforms with the requirements of SECTION III of the ASME BOILER AND PRESSURE VESSEL CODE.

Date 4/13/78 Signed Pullman Power Products

(Fabricator)

By J.M. PalaeCertificate of Authorization Expires 11-18-80Certificate of Authorization No. N-1926

CERTIFICATE OF SHOP INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and/or the State or Province of _____ and employed by HSBI & I. Co. of Hartford, Conn. have inspected the piping described in this Data Report on 4/13/78, and state that to the best of my knowledge and belief, the Manufacturer has constructed this piping in accordance with the applicable Subsections of ASME Code, Section III.

By signing this certificate, neither the Inspector nor his employer make any warranty, expressed or implied concerning the piping in this Data Report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

Date 5/9/78L.E. Heister

(Inspector)

Commissioner

Ca 1126

National Board, State, Province and No.

SEE REVISED DATA REPORT PULLMAN POWER PRODUCTS

PENTENTION TIME 11 YRS

ASME DATA REPORT FOR FABRICATED NUCLEAR PIPING SUBASSEMBLIES NR NO. 27964
(As Required by the Provisions of the ASME Code Rules)

R4060

1. Purchaser Pullman Kellogg, Para. Junt., CA Order No. 2810
(Name and Address of Purchaser)
2. Manufacturer Bechtel Power Corp., Norwalk, CA Order No. 10407-13-PM-201
(Name and Address)
3. Owner Arizona Public Service Co. 4. Location of Plant 3 miles south of Wintersburg, AZ
5. Piping System Designation SAFETY INJECTION & SHUTDOWN COOLING Serial No. N-522
Bechtel Dwg. 1-3 (Brief description of intended use, main design ref.)
(a) Drawing No. 13-P-SIF-201 Prepared by Bechtel Power Corp., Norwalk, CA
(b) National Board No. N/A

6. The material, design, construction, and workmanship complies with ASME Code Section III, Class 2
Edition 1974, Addenda Date Summer 1975, Case No. *****

Remarks: Manufacturers' Data Reports properly identified and signed by Commissioned Inspectors have been furnished for
the following items of this report: NOT APPLICABLE
(Name of Part - Item number, Manufacturer's name, and identifying stamp)

7. Shop Hydrostatic Test None PSI

8. Description of piping inspected 1-Piping Ass'y., PC, HK, 1-SI-008-S-002
(Include - mark no. - material spec. - nom. pipe size - schedule or thickness - length
Fabrication Drawing F- 136
Engineering - Design, etc.)

PIPE: 10" SCH 20 WELDED SA312 TP304

6" SCH 40 SHLS SA376 TP304

PLATE: SA240 TP304 (For Support Attach.)

SA516 Gr. 70 (For Support Attach.)

E.D.E: 100% L.P. ALL ATTACHMENT WELDS

 Pullman Power Products
Division of Pullman Incorporated

OVR IDENTIFICATION

2810 F-136
PER 13-1001-1

We certify that the statements made in this report are correct and that the fabrication of the described piping conforms
with the requirements of SECTION III of the ASME BOILER AND PRESSURE VESSEL CODE.
Date 10/13/77 Signed Pullman Kellogg By D.L.S. 10/13/77

Certificate of Authorization Expires 11/30/77 Certificate of Authorization N-776

CERTIFICATE OF SHOP INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors
and/or the State of California, and employed by Pullman Kellogg of State of CA,
have inspected the piping described in this Data Report on 10/13/77 and state that to the best of my knowledge
and belief, the manufacturer has constructed this piping in accordance with the applicable Subsections of ASME Code
Section III.
By signing this certificate, I further inspect that the employer make any warranty, expressed or implied, concerning
the quality of the Data Report. I acknowledge, under the direction of his employer shall be liable in
any action for damages resulting from or connected with this inspection.
Date 10/13/77 Inspector 33666 Contractor Ca 857
Contractor National Board, Inc., San Francisco, CA

RETENTION TIME 15 YRS.


PALO VERDE NUCLEAR GENERATING STATION

NONCONFORMANCE REPORT

NO 174-3846 PAGE 1 OF 2

1. UNIT	2. MODAY	3. DRAWING/PART NO.	4. ITEM DESCRIPTION	5. ITEM LOCATION
1	2 20 79	13-P-S1/F-20/	6 Pipe Spool	Aux. Block.
6. CLASS/7. STARTUP SYSTEM NO.			8. SERIAL NO.	9. CONTRACTOR/SUPPLIER
Q	S1		1-S1-008-5006	Bochart & C/Bellman
10. FIELD ENGR. NO. PCS. DWG/SPEC REQ'D. PRESENT CONDITION			11. P.D.O. OR SPEC NO.	11. ASME AUTHORIZED INSPECTION REQ'D.
			13-2007. 20-1-S	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
12. DESCRIPTION			12. FIELD ENGR. DECISION	13. FIELD RECOMMENDED DISPOSITION
1. Dwg. 13-P-S1/F-20/ Rework shows Centrifuge line of HPSI Pump SIA-B2 Suction nozzle located at E. 3002.0". The center line of spool 1-S1-008-5006 is at E. 3001.11". Scales have a 1" misalignment.			1. $\frac{1}{2}$ z.	CUT A $7\frac{3}{4}$ " SECTION FROM SPOOL 1-S1-008-5002 AT POINT INDICATED ON SKETCH & REPLACE WITH AN $8\frac{3}{4}$ " long, 10"Ø, S/20 S.S., SA-312, GR.TP. 304. PUP. REWELD USE W-002 C.
2. Spool 1-S1-008-5002 does not conform to Spec. 13-Pm. 2004 Rev. S Part 8.7, which allows a $\pm \frac{3}{8}$ " dimensional tolerance. The spool measures 18-8 $\frac{1}{2}$ ", it should be 18-9".			2. QC. ENGR. VERIF.	RECORD HT # 36905 <u>6/12/79</u>
13. REPORTED BY:			14. INSPECTION/VALIDATION/REVIEW DATE	15. DISPOSITION/CONCURRENCE DATE
C. Kim			16. PROJ. FLD. ENGR. REVIEW DATE	16. FIELD RECOMMENDATION TO PREVENT RECURRANCE DATE
4/6/79			2/21/79	1. NO ACTION REQUIRED AND 2. FIELD ENGINEER RECOMMENDS THAT THIS NCR BE SET TO FAVORABLE FOR CORRECTIVE ACTION. A COPY OF THIS NCR HAS BEEN SENT TO THE PROJECT PROCUREMENT MANAGER FOR ACTION.
22. ACCEPTANCE OF NEW WORK/REPAIR			17. PROJ. FLD. ENGR. REVIEW DATE	17. PROJ. FLD. ENGR. REVIEW DATE
QC. ENGR. DATA 4/12/79 AUTHOR Blawheller INSP			18. INSPECTOR 2/21/79 QA ENGR. J. E. Blawheller	18. AUTHORIZED BY 2/21/79 NUCLEAR GROUP SUPERVISOR J. E. Blawheller
14. CAUSE OF DISCREPANCY			19. FIELD RECOMMENDATION TO PREVENT RECURRANCE DATE	19. FIELD RECOMMENDATION TO PREVENT RECURRANCE DATE
1. ACCUMULATION OF TOLERANCE Tolerance of vendor error.			1. NO ACTION REQUIRED AND 2. FIELD ENGINEER RECOMMENDS THAT THIS NCR BE SET TO FAVORABLE FOR CORRECTIVE ACTION. A COPY OF THIS NCR HAS BEEN SENT TO THE PROJECT PROCUREMENT MANAGER FOR ACTION.	2. Vendor error
2. Vendor error			INITIATOR A.G. Tomson DATE 2/21/79	INITIATOR A.G. Tomson DATE 2/21/79

RETENTION TIME ~~ft~~ YRS.



Pass 2 of 2
NCR PA-386

RETENTION TIME 65 YRS.

PALO VERDE NUCLEAR GENERATING STATION**NONCONFORMANCE REPORT**

1. UNIT								2. TODAY YR			3. DRAWING/PART NO.		4. ITEM DESCRIPTION		5. ITEM LOCATION			NO. R-169		PAGE 1 OF 1					
1. CLASS 7. STARTUP SYSTEM NO. Q								11 7 77			1-S1-008-5-002		VA PIPE SPEC		SOUTH LAYDOWN AREA										
E. LIST IN ORDER: NO. PCS., DWG/SPEC REQMT., PRESENT CONDITION								N/A			4-N-5589		PULLMAN KELLOGG		13-PM-201			<input checked="" type="checkbox"/> YES		<input type="checkbox"/> NO					
12. DESCRIPTION								ONE PIECE OF PIPE			REJECT		Return to Supplier for repair												
SPEC DAMAGE. MK. #								1-S1-008-5-002.			PIPE IS BEAT AT BOTH ENDS APPROX. 1/4"														
13. REPORTED BY:								J. White			11/24/77		15. INSPECTION/VALIDATION/REVIEW DATE		16. FIELD RECOMMENDATION TO PREVENT RECURRENCE			17. PROJ. FLD. ENGR. REVIEW		18. FIELD ENG. DATE		19. FIELD ENG. DATE			
14. COMPANY								J. Stander for NCL (P)			11/24/77		PROJ. FIELD ENG. DATE		NCL			O.S. & D. report No. 166 in forms.		20. TWX/TELECON REFERENCE		21. DISPOSITION CONCURRENCY		DATE	
15. ACCEPTANCE OF NEW WORK/RETURN OF FAULT								NA			11/24/77		FIELD ENG. DATE		NCL			COMPANY OF FREIGHT		PROJECT NUMBER		DATE			
16. FIELD ENG. DATE								NA			11/24/77		FIELD ENG. DATE		NA			IN COMPANY		11/24/77		J. E. O'Donnell			
17. FIELD ENG. DATE								NA			11/24/77		FIELD ENG. DATE		NA			IN COMPANY		11/24/77		J. E. O'Donnell			

RICHARD J. O'DONNELL DATE

Narbut Notes

Closed Issues :

#106

~~Clamp over Code Plate~~
~~Busch Pro Ram~~
~~SI-100 H003~~
WPP 201.1 ok if you can read it
- Sabot

Procedure:


QCI 26.2 61.2 stains

- removal (if req) for interference
Nothing, states \$ how much
can be covered

Decision is F.E. discretion
if into will be covered

(~~Do~~) Spec search, Code Search

Done No Code Regt
Not an issue



60° - 135°

Ld Hgr QCE
Project Engr
Welding Engr

Jim White
~~Bill Miller~~
Gene Slam

cccccccccccccccccccccccccccccccc

~~Paint allowed on side Plates?~~

SI 106 - H 007

No negt on Paint

No negt on machine surface

Beam already painted

38686666335555555555555555555555
9/7/83

HPSI A 13-P-SIF-201 H005

Notes on 13-SI-008-H005 Rev E
overall ok

H003

H004 See Notes on Dog 13-SI-008 H-004

9/9 Regarding ~~Fit~~ SI 008 - H004
.250 nom wall allowed 12 1/2% on nominal

.219 min wall

.031

P.i .059

- Walkdown for Insulation.

QCI 202

Should have been picked up

- for CIP sign off QCI 200
configuration, etc.

NPT 2

Nameplate N 5587 1977

→ N 5589R 1978

1/2 covered w. pipe clamp

Brian F. Love Startup QC E

Final Walkdown ^{PPM} prior to lagging:

QCI 204

-par 3.1 check for damage
per ED-1

EDI 2.4.1

minor defects = $3/8$ or 10%
of thickness whichever less

S&D Welding, Repair

QCI 101 Welding, Control

516 Arc strikes repaired

shall have NCR

repair per EDI -par 5.0

Vibro etch on pipe

Gil NCR being written Got it

CIP Got it

When ED1 put in effect: (11/81?) NA

Specified	Applicable Procedures
<u>either</u>	202 Pipir, Inst Pa. 5.0
<u>or</u> deleted 4/13/82	202.3 Pipir, System Final Inspection
<u>or</u>	(204)

Resolution

IOPC based on WPPQCI 204

inspection should have identified
NCR PA-7138 resolved user basis

~~Clamps~~
~~Stamps~~

Clearances

Size

~~#101~~
11002

QCI 201.1

~~DER~~ ⁸²⁻⁷³ written 11/82
^ on Grinnells Clamps - due 10/83

Nothing Specific in Spec.

NCR's written 10/82

No resolution licensee identified
problem

~~(08630033331333333311)~~

~~Sabol, Pipe Support Engr. Decklet~~

~~Hot Setting, Cld Setting, not per latest Rev~~

~~SI 008 H-004~~

~~CS varies vendor to vendor~~

~~- 13PM 209 = ITT Grinnel~~

~~- 13PM 209B = Pacific Scientific~~

~~ITP Plate PS in all~~

~~Assy by ITT~~

~~Resolved w. explanation~~

Washers not Installed

Are they required/prohibited

Load Bolt

SI 008 H004

high strength bolt

no washer

Clamp Bolt

no washer req.

could be optional

Per Vendor Dwg's no washers
called out

— Don't know of washer req's in
QCI

13 PM-204

12.3.6

optional use of
Resolved

Allows
flat washers

~~Slide Plates SS vs CS~~

~~Plate thicker than called out - called out in FCR~~

H003

H005

13 PM-204

allows either CS or SS

Resolved

542.c.

~~Nut on Sway Brace
Only One Installed~~

H002

~~Per Corner Lada
Sway Strut Dwg Fig 631
Shows one nut
required
Corner Lada Galvanized
ITI Grinnell Greenish color
Resolved~~

~~List of
Snubber Sizes~~

ie. "No 1" on H004

~~Sway Brace Sizes ie~~

"C" on H002

~~PSA Snubber Should have
P/N # on it~~

~~Look for No 1, 10 etc
on Snubber body~~

Resolved

~~Location Tolerances~~ S1008, H002

in 204 and QCI

Grinnell's LCD (load capacity
data sheet has adjust)

± 2 horiz
 ± 6 axially
Resolved

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16

Beam attachment Pin used vs Bolt.

SI 100 H003

Substitution allowed?

ITT Grinnell Cat shows $\frac{5}{8}$ bolt req (for lgr sizes use pin
 (401))

Corner and Lada Cat. shows pin w. cotter pins

Part 66

Field Stk List Sect 1-16

allows use of C&L 401 for

ITT Pt 66

Rev 3

- Procedure 201.1

9 2.15

allows substitution

Resolved

~~Hot Setting not Right~~

Dwg doesn't match - Plate on Snubber

13 SI - 099 H002

Might be surplus snubber, check
hgr tag # on snubber body

Hot setting checked

Rev 1 had HS = $1\frac{5}{16}$ = 1.31

Resolved

13 PM

~~\$ 204.8~~ Par

12.2.1

allows

Variance on CS

provided 1" reserve not
infringed on (including movement)

~~Location Wrong
What is tolerance~~

$\frac{7}{8}$ is $\frac{15}{16}$

SI 099 H002

QCI 201.1 9.3.12 allow $\pm 2"$ horiz
for misc members

~~Lugs Deleted~~

SI 105

HOOB

HOOC

HOOD

HOGG

QCI 201.1 Per 942. allows deletion

~~Were lugs removed? No/Not installed~~

~~PT records? N/A~~

~~Spool dng applies? Bechtel manfact~~

~~Spools NOOI, C, A~~

Spool 5001 } ~~Not Pullmans, * Look at TDS~~
NOOC } ~~in pkg~~
NOOA }

NOOA record don't show lugs

NOOC " " " "

NOOB had no lugs

Resolved Sat

~~What is max pin to pin dim?~~

~~(See QCI Exh 201.1-17)~~

Resolved 2 #'s for diff "L" length

Undersize Lug Weld

SI 100 H-034 n/dok
H 002 ok DOK
H-015

Dwgs 13 SI-100 H-034 Rev 1

shows diff configuration one lug, $\frac{3}{16}$ fillet
different lower loads

Rev 2 revises lug location changes loads
calls for $\frac{1}{4}$ " fillet

Rev 3 Revised thermal movement

Rev 4 Show $\frac{1}{4}$ " all units

- Pullman power Dwg F-161A Rev 3

Shows $\frac{1}{4}$ " weld -typ lugs to spool
spool 2

OCT 201.1 Par 14.3 requires QC inspect vendor
welds

date added to QCI = 7/20/79 PCM 29

date of QC inspection H034 =

H002 =

Need CIP's for H034, H002, H015

G.1

Will Check DER 79-10? APS
was to do 100% reinspect of vendor
welds.

*Procedure Change Effect. Date

Loose Nut on Sway Strut - (Wagner Ident)

SI 101

H00A1

ITT

SI 107

H025

CIP 201.1 15.4 "IIL" on incomplete item
^{turn in}

QCE Stamps CIP Hanger Control Card
11cm Support per dwg

Also observed ^{single} loose nut on
Sway Strut on SI-107 H025
(not inspected hgr but in area)

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15

Actions

9/12

- ① Inspect Clamp size SI 100 H 003
Right size Should have tightened lower-bolt more
- ② Check w/ Sabot does as built w/b log show NCR's
- ③ Code Search for Clamp over Code Plate

Where does 75% of lug contact wgt come from?

See TCR w.

SI-100 - H009

Originating Engr believed in QCI

Sabot checked PCN's can't find wgt deleted

→ PCN 39 ^{"10/17/73"} 8.8.4

204 12.3.8 A

Revise 201, 15.7

Carry as open item :

What are AWS words on eff throat

SI 100H - 011

- ① - Code applies to 60° to 135°
- Angle was 45° — equal

- ② Does engineering take resp.
or is field to do calc
Sabot

ok

11111111111111111111

Shims welded to pipe clamp

SI 176 +1004

Need to pull CIP

Should be in Grinnell's N5 rpt.

- [-] Grinnel doesn't make a 3" clamp
- [-] Shims out a $3\frac{1}{2}$ clamp.

L C A S S O S S I S S S S S S S S S S S S S S S S S S

Measurement of Weld by QC

H₂S SI 176 - H003

Need NCR on SI 176 H003

NCR WC 812

w. Marini

①

vis. est $\frac{1}{32}$ gouge
orig undercut + grinding
tuc of weld

②

Wraparound

w. Marini

Transverse undercut

$\frac{1}{32}$ " + $\frac{1}{4}$ " long

almost sat w $\frac{1}{32}$ criteria
judgement all either way

Unsat for .01" criteria

No Lockwire on Gunnel Screws
Body Bolts

CIP 201.1-16 for Snubbers

clearly shows PSA Lockwire

ITT signs - wrong verification

Item 3 of Crimnells

PHD 7594-1 Maint & Install Manual

Rev 2 11/28/78 Item 3

$\frac{1}{4}$ kip 22 in lbs (10-24 x 56 SA 320)

1 kip 45 in lbs $\frac{1}{4} \times 20$ Gr L7A
socket head cap screw
SA-354 Gr BD

Washers SA 325 (Hardened)

Sat: Body bolts high strength
procedure excepts high strength

QCI 201

Loose U bolts 16 - $\frac{1}{8}$ gap + 3 nuts.

* PSA $\pm 5^\circ$

Location tolerances (9.0) $> 2\frac{1}{2} \pm 2''$ vert
 ± 6 horiz

QCI Notes

Material Substitution QCI Par 6.1

Material Defects

Install per Dwg 7.2

Locking Device 83

U Bolts 8.6 \pm 9.24

Spring Cans 8.8

Snubbers 8.10 + 9.26

Clamps 8.9

Misc Bolting 813 ($7/8''$ / 325)

Beam Attachments 9.2.7

Lateral Restraint Clearance 9.5

Narbut Notes

Total hgr count

13 P SIF -136

3

13 P SIF 204

20

01 P SIF 105

15

13 D SIF 203

$$6 + 3 + 3 + 11 + 24 + 13 + 3 + 8 =$$

71

5

13 P SIF 201


2

13 P SIF 103

116 hgrs

+3 P SIF 136

Total



ARIZONA PUBLIC SERVICE COMPANY
Organization Diagram
August 1, 1983

APPROVED:

Keith L. Turley,
Chairman, Board of Directors & Chief Executive Officer

APPROVED:

J.K. Wellington, Mgr., Manpower Planning & Development

Page

1 - 1

APS.

OPERATIONS
EXEC. VICE PRESIDENT
CHIEF OPERATING OFFICER
T. G. Woods Jr.

ELECTRIC OPERATIONS
VICE PRESIDENT
G. C. Andognini


NUCLEAR PROJECTS
MANAGEMENT
VICE PRESIDENT
E. E. Van Brunt, Jr.

CORPORATE
QUALITY ASSURANCE
MANAGER
J. A. Roedel

PVNGS
ADMINISTRATIVE &
TECHNICAL SERVICES
MANAGER
E. L. Lewis


REVISION 1
(Through 1985)

NUCLEAR PROJECTS MANAGEMENT




REVISION 1
(Through 1985)

NUCLEAR PROJECTS
NUCLEAR ENGINEERING




REVISION 1
(Through 1985)

NUCLEAR PROJECTS
NUCLEAR ENGINEERING



REVISION 1
(Through 1985)

NUCLEAR PROJECTS
NUCLEAR RECORDS MANAGEMENT





REVISION 1
(Through 1985)


NUCLEAR PROJECTS
NUCLEAR RECORDS MANAGEMENT

NUCLEAR RECORDS
MANAGEMENT
MANAGER
B. F. Godwin


ADMINISTRATIVE
SECRETARY
On-Board (1)







ADMINISTRATIVE
SECRETARY
Audrey Vennell



Vicky Tersini

DESIGN DOC. CNTRL
& VAULT

LEAD DRAWING
& DOCUMENT CONTROL
SPECIALIST (1)

Dave Holmes

3:00-11:30

SENIOR DRAWING &
DOCUMENT CONTROL
PROCESSORS (3)

Tally Priesmeyer
Janet Terry
Armando Salgado

DRAWING &
DOCUMENT CONTROL
PROCESSORS (3)

Sharon Edwards
Ann Hagen
Penny Buckholter

11:00-7:30

DRAWING &
DOCUMENT CONTROL
PROCESSORS (10)

Sandra Pryor
Cathy Jury
Bobbie McDaniel
Debbie Hernandez
Greg Brown
Lois Burns
Blaine Greer
Wanda Mooney
Jean Williams
Jeff Iverson

DRAWING &
DOCUMENT CONTROL
SPECIALIST (1)

Shila Tijerina
11:00-7:30

DRAWING &
DOCUMENT CONTROL
PROCESSOR (2)

Johnny Carson
Kay House

NUCLEAR RECORDS
ANALYST
(1)

Bev Solakiewicz

S/U DDC &
PVNGS-SM CNTRL

LEAD DRAWING
& DOCUMENT CONTROL
SPECIALIST (1)

Debbie Johnson

3:00-11:30

DRAWING &
DOCUMENT CONTROL
SPECIALIST (1)

Margaret Lavoie

DRAWING &
DOCUMENT CONTROL
SPECIALIST (1)

Nancy Jerosi

SENIOR DRAWING &
DOCUMENT CONTROL
PROCESSORS (2)


Sara Wygant
Lorraine Shadwick

DRAWING &
DOCUMENT CONTROL
PROCESSORS (8)

Brenda Owens
Trisha Sherman
Lynn Lockwood
Paul Coronado
Lee Ann Massey
John Knox
Shirley Lucia


REVISION 1
(Through 1985)

NUCLEAR PROJECTS
NUCLEAR CONSTRUCTION




REVISION 1
(Through 1985)

NUCLEAR PROJECTS
NUCLEAR CONSTRUCTION




REVISION 1
(Through 1985)

CORPORATE QUALITY ASSURANCE



REVISION 1
(Through 1985)

CORPORATE QUALITY ASSURANCE



PVNCS ADMINISTRATIVE & TECHNICAL SERVICES

PVNCS ADMINISTRATIVE
& TECHNICAL SERVICES
MANAGER
E. L. Lewis

SECRETARY
On-Board (1)

BUDGETS/COST CONTROL MANAGER	CONTRACTS & PROCUREMENT ADMINISTRATOR J. O'Hara	SCHEDULING SUPERVISOR K. C. Kieselbach	EMERGENCY PLANNING DIRECTOR R. W. Page	NUCLEAR OPERATIONS SUPPORT MANAGER J. Vorees	NUCLEAR FUEL MANAGEMENT MANAGER P. F. Crawley
------------------------------------	--	--	---	---	--


PVNGS ADMINISTRATIVE & TECHNICAL SERVICES
NUCLEAR FUEL MANAGEMENT

NUCLEAR FUEL
MANAGEMENT
MANAGER
P. F. Crawley


SECRETARY
1-1983 (1)

FUEL CYCLE SERVICES SUPERVISOR <u>M. D. Holohan (1)</u>	NUCLEAR ANALYSIS LEAD NUCLEAR ENGINEER 1-1983 (1)	SAFETY ANALYSIS LEAD NUCLEAR ENGINEER 1-1983 (1)	TECHNICAL PROJECT LEAD NUCLEAR ENGINEER On-Board (1)
NUCLEAR ENGINEERS 1-On-Board/1-1984 (2)	NUCLEAR ENGINEERS 3-On-Board/1-1983 12-1984/1-1985 (7)	NUCLEAR ENGINEERS 4-On-Board/2-1983 (6)	TECHNICAL PROJECT NUCLEAR ENGINEERS 1-On-Board/1-1984 1-1985 (3)
FUEL ANALYSTS 1-On-Board/2-1983 (3)	ENGINEERING TECHNICIANS 1-On-Board/1-1984 (2)	ENGINEERING TECHNICIAN 1-1984 (1)	PLANT SUPPORT NUCLEAR ENGINEERS 5-1983 (5)
ENGINEERING AIDE 1-1983 (1)			


PVNGS ADMINISTRATIVE & TECHNICAL SERVICES
PVNGS SCHEDULING



PVNGS ADMINISTRATIVE & TECHNICAL SERVICES
PVNGS CAPITAL BUDGETS/COST CONTROLS



PVNGS ADMINISTRATIVE & TECHNICAL SERVICES
CONTRACT ADMINISTRATION



Narbut

Bio data Sheet

Name

Paul P. Narbut

(as you want it to
appear on report)

Your Current Position

Project Inspector USNRC

(e.g. Project Inspector USNRC,
Private Consultant or
however you wish to
be identified)

Your Principal Qualification

Nuclear Engineer

(e.g. Level III ASNT,
Registered Professional
Engineer, Electrical
Specialist or however
you wish to describe)

Your Experience Supporting

20 years experience

Your Professional Qualifications

in design, construction

(e.g. 40 years electrical

and testing of

design experience, 35
years NDE experience)

nuclear power plants

Burdoin

Bio data Sheet

Name

JOHN F. BURDOIN

(as you want it to
appear on report)

Your Current Position REACTOR INSPECTOR

(e.g. Project Inspector USNRC,
Private Consultant or
however you wish to
be identified)

Your Principal Qualification ELECTRICAL ENGR.

(e.g. Level III ASNT,
Registered Professional CALIF. 3 Lic (EE, ME, NRE)
Engineer, Electrical
Specialist. or however
you wish to describe)

Your Experience Supporting 36 yrs. IN ELEC.

Your Professional Qualifications ENGR'G.

(e.g. 40 years electrical
design experience, 35
years NDE experience)

Young

Bio Data Sheet

Name

(as you want it to
appear on report)

TOLBERT YOUNG JR

Your Current Position SECTION CHIEF, USNRC

(e.g. Project Inspector USNRC,
Private Consultant or
however you wish to
be identified)

Your Principal Qualification

(e.g. Level III ASNT, REGISTERED PROFESSIONAL ENGINEER,
Registered Professional NUCLEAR, STATE OF CALIFORNIA
Engineer, Electrical
Specialist or however
you wish to describe)

Your Experience Supporting 22 YEARS NUCLEAR POWER

your Professional Qualifications ~~██████████~~ PLANTS

(e.g. 40 years electrical
design experience, 35
years NDE experience)

Walton

Bio Data Sheet

Name

(as you want it to
appear on report)

Glenn A. Walton

Your Current Position

Senior Resident Inspector BIV2

(e.g. Project Inspector USNRC,
Private Consultant or
however you wish to
be identified)

Your Principal Qualification

(e.g. Level III ASNT,

Registered Professional

Engineer, Electrical

Specialist or however

you wish to describe)

Welding, NDE & Structural
Steel Specialist

Your Experience Supporting

17 yrs experience Babcock

Your Professional Qualifications

& Wilcox Co. as NDE Mgr.,

(e.g. 40 years electrical

R.E. Mgr. 10 yrs. experience

Design experience, 35

with NRC as Specialist in

years NDE experience)

Mechanical area

Wagner

Bio data Sheet

Name

W. J. Wagner

(as you want it to
appear on report)

Your Current Position

Reactor Inspector

(e.g. Project Inspector USNRC,
Private Consultant or
however you wish to
be identified)

Your Principal Qualification

Professional Engineer
in State of Calif. (Quality)

(e.g. Level III ASNT,
Registered Professional
Engineer, Electrical
Specialist or however
you wish to describe)

American Welding Society
Certified Welding Inspector

Your Experience Supporting

24 yrs experience
in metallurgy, quality

your Professional Qualifications

assurance and
nondestructive examination

(e.g. 40 years electrical
design experience, 35
years NDE experience)

Kerch

Bio Data Sheet

Name

HARRY W KERCH

(as you want it to
appear on report)

Your Current Position

LEAD RENDERER ENGINEER

(e.g. Project Inspector USNRC,
Private Consultant or
however you wish to
be identified)

Your Principal Qualification

ASNT NDE LEVEL III

(e.g. Level III ASNT,
Registered Professional
Engineer, Electrical
Specialist or however
you wish to describe)

STATE OF CAL IN QUALITY.

Your Experience Supporting

35 yrs NDE

Your Professional Qualifications

15 yrs of the above

(e.g. 40 years electrical

nuclear.

Design experience, 35
years NDE experience)

Verdierbrugge

Bio Data Sheet

Name

(as you want it to appear on report)

L E VERDIERBRUGGE

Your Current Position

SENIOR RESIDENT INSPECTOR (INST)

(e.g. Project Inspector USNRC,
Private Consultant or
however you wish to
be identified)

Your Principal Qualification

BS&EE, CONSTRUCTION

(e.g. Level III ASNT,
Registered Professional
Engineer, Electrical
Specialist or however
you wish to describe)

SPECIALIST

Your Experience Supporting

Your Professional Qualifications

(e.g. 40 years electrical
design experience, 35
years NDE experience)

36 years experience in
design of steel, chemical,
and power plants, and in
inspection and operation
of nuclear power plants

Harris

Bio Data Sheet

Name

(as you want it to
appear on report)

Richard H. Harris

Your Current Position Engineering Tech.

(e.g. Project Inspector USNRC,
Private Consultant or
however you wish to
be identified)

Your Principal Qualification LEVEL II ASNT

(e.g. Level III ASNT,
Registered Professional
Engineer, Electrical
Specialist or however
you wish to describe)

CERTIFIED Welding Inspector
(CWI) AWS.

1½ yrs Tech. USNRC RI

Your Experience Supporting (NA) 3 yrs Const. Nuclear power plant (qc)

Your Professional Qualifications (NA) 3 yrs Vendor Surveillance

(e.g. 40 years electrical 3 yrs Inspection Laboratory (NDE)
Design experience, 35 11 yrs Steel Mill (NDE)
years NDE experience)

Campbell

Bio Data Sheet

Name

Randy M. Campbell

(as you want it to
appear on report)

Your Current Position

Engineering Tech

(e.g. Project Inspector USNRC,
Private Consultant or
however you wish to
be identified)

Your Principal Qualification

ASNT LEVEL II

(e.g. Level III ASNT, Certified Welding Insp. (CWI) AWS
Registered Professional
Engineer, Electrical
Specialist or however
you wish to describe)

Your Experience Supporting Your Professional Qualifications

5 yrs test laboratory NDE

4 yrs (TVA) Vendor Surveillance

(e.g. 40 years electrical
design experience, 35
years NDE experience)

Stanley

Bio data Sheet

Name

LOREN STANLEY

(as you want it to
appear on report)

Your Current Position

PRIVATE CONSULTANT

(e.g. Project Inspector USNRC,
Private Consultant or
however you wish to
be identified)

Your Principal Qualification

REGISTERED P.G. (EE) IN CALIF

(e.g. Level III ASNT,
Registered Professional
Engineer, Electrical
Specialist or however
you wish to describe)

SPECIALIZING IN INSTRUMENTATION
AND CONTROL

Your Experience Supporting

ELECTRICAL

15 YEARS DESIGN EXPERIENCE ~~WITH~~

Your Professional Qualifications

OVERALL 27 YEARS ENGINEERING

(e.g. 40 years electrical
design experience, 35
years NDE experience)

EXPERIENCE.

Marini

Bio Data Sheet

Name

(as you want it to
appear on report)

WILLIAM MARINI

Your Current Position

PRIVATE CONSULTANT

(e.g. Project Inspector USNRC,
Private Consultant or
however you wish to
be identified)

Your Principal Qualification

LEVEL III ELECTRICAL + V.T.

(e.g. Level III ASNT,
Registered Professional
Engineer, Electrical
Specialist or however
you wish to describe)

Your Experience Supporting

13 YEARS OF NUCLEAR
ELECTRICAL

Your Professional Qualifications

AND WELDING INSPECTION

(e.g. 40 years electrical
design experience, 35
years NDE experience)

INSPECTION SPECIALIST

Crane

Bio Data Sheet

Name

CYRIL J. CRANE P.E.

(as you want it to
appear on report)

WESTEC SERVICES, INC.

Your Current Position

PRINCIPAL ENGINEER

(e.g. Project Inspector USNRC, Consultant to NRC for
Private Consultant or Palo Verde CAT
however you wish to
be identified)

Your Principal Qualification

Electrical engineer

(e.g. Level III ASNT,
Registered Professional
Engineer, Electrical
Specialist or however
you wish to describe)

Registered Professional
Engineer

Your Experience Supporting

14 years of Reactor Operation,

your Professional Qualifications

Maintenance

(e.g. 40 years electrical
Design experience, 35
years NDE experience)

and engineering experience

8 years of nuclear electrical

design experience.

5 years of Electrical

Engineering Consulting and A/E
electrical engineering

ARIZONA



HAYES 11/16/81.01
ARIZONA PUBLIC SERVICE COMPANY

COMPANY CORRESPONDENCE

PVNCS-SIM-M82-104

Prepared by: J. M. Moyers
S. M. Moyers

Reviewed by: R. Taylor
R. Taylor

Reviewed by: J. Zerucha
J. Zerucha

Approved by: J. Kirby
J. Kirby

Approved by: C. G. Andozzini
C. G. Andozzini

DATE: PVNCS-GCA-M82-257
September 28, 1982

TO: W. Stubblefield
Bechtel Construction Building
FROM: S. M. Moyers X6440
Stn #: 6310
Ext #: 6440

SUBJECT: Construction/APS Operation
Interface on Pump Doweling

File: 001-503

The final alignment and doweling of pumps and motors was originally scoped to be accomplished as part of the pre-op tests because that was expected to be the start of the major runs on the equipment. With the startup activities as now scoped, significant run time on equipment is being experienced through the prerequisite phases of testing and long before the equipment is turned over to APS.

In cases where the equipment will experience significant operation before turnover, the pump-motor final alignment and doweling should be carried out by the Bechtel Millwrights to preclude any equipment damage as a result of slippage. It is requested that APS Maintenance be notified to observe this activity when it is required. Should any assistance in the alignment or vibration analysis be required during this phase, the APS Maintenance Department will provide it as needed, with the Bechtel crafts doing the actual work until such time the equipment is turned to APS.

SMM:jvb

cc: List X
J. Houchen
R. Ozment
A. Priest
J. Zerucha

RECEIVED

CONSTRUCTION
PVNGS

#109



MEMORANDUM

TO Leon Aferk Mech. Discipline LOCATION Main Office
FROM D. CRANMER Mech. Engineer DATE 2-1-83 ID 83
SUB: Equipment Doweling Unit #1, 2, 3 JOB NO PVNGS 10407

FILE

0830 - In APS Stewart Mayer Office

Attendees: D. CRANMER - Bechtel

F. NORRIS - APS

S. MAYER - APS

Per APS letter dated Sept. 28, 1982 # PVNGS GCA - M82 - 257

Discussions were based on type of equipment APS wished to have Bechtel dovel. We discussed types of dovels, material composition, sizes, labor, and all phases of the work.

APS is interested in Bechtel labor force to dovel only the Circulating Water Pumps (13mm 008) on a Po, A/B/c/d and Plant Cooling Water pumps (13mm 082) PWN Po, A/B at the present time. Bechtel will supply "all" materials, tools, labor & supervision. One APS representative will occasionally check progress. Labor charges will be charged against an account number supplied by APS. APS will send a letter via Stabbfield requesting the doveling with pertinent information included.



Concord
Page 2

MEMORANDUM

TO _____ LOCATION _____
FROM _____ DATE 2-1-83
SUBJECT Equipment dewatering Units #1, 2, 3 JOB NO.
FILE _____

Unit #1 equipment is ready to be started since all pumps have been ran. Exception can be the "C" Circulating Water pump which has a vibration problem.

Unit #2 equipment will be dewatered per letter of reference.

#3 Unit - Far down the road - but this dewatering is applicable as in other units.

B. Orammer
Mech Eng.

C.C. Steve Moyers - APS

Rod Rulick - Bechtel

Harold Thoresen - Bechtel

Dave Tanne - Bechtel

Og. Read. Review / file - 4/22 - 5/13/83

Developed Checklists for Design, Procurement,
Work Control, Misc (and test, supplier, Accounting etc.)
Under Work Control - Maint. / Modif.

Topic: Alignment of Equip.

Found Procedure No. assignment
31 MT- 922 03

PURCHASE REQUEST (PR)
PALO VERDE NUCLEAR GENERATING
STATION

APS.

PRIATE TERM
SR = SAFETY RELATED
NSR = NON SAFETY RELATED

P.O. NO.	SHIP TO (MAX 30 CHARACTERS PER LINE)			PROJECT NO.	SUB-PROJ. NO.	PROJECT NAME (MAX 13 LETTERS)	HOME UNIT	PR NO.						
	ARIZONA PUBLIC SERVICE CO				PV-		- SR AX NSR	9571 003821						
DO NOT DELIVER TO BECHTEL			REQUIRED INVOICE APPROVALS AND STA. NO.			PURCHASE \$ LIMIT (BLANKET P.O.)								
APS/PVNGS OPERATIONS STA 4015 6320														
4 MILES S. WINTERSBURG, AZ 85343						BUYER NAME (IF KNOWN) PR DATE DATE NEEDED								
MATERIAL MGT EXT 2426 STA 4015 6320			REQUESTOR LAST NAME STA. NO & EXT. NO. R.E. Shultz 6310x6019			VENDOR NAME AND ADDRESS Power tool & Supply Co. 725 W. Madison Ave. (Harry) Phoenix, Az. 85036 XXXXXXXX								
NOT BEFORE (MM/DD/YY)		REQUIRED BY (MM/DD/YY)		VENDOR NO.	TR DIS	CO NO.	STRM	FOB	SHIP VIA					
50														
P.M. NO.		QUOTE NO.		INTERIM EXPEDITE DATES (MM/DD/YY)		DATE OF P.O.			USEH LAST NAME STA. NO & EXT. NO.					
7														
LINE NO.		ACCT / WORK ORDER NO.		SUB LEDG / JOB ORDER		CHARGE UNIT	TUC	ALLO%	DESCRIPTION (MAXIMUM 60 CHARACTERS PER LINE)		INTENDED USE (THIS LINE NO ONLY)		STH. LVL	HANDEL
8		99-152080				9571	003		TOTAL 180 - INCLUDING SPACING		Special tools, all units		B	N/A
LOAD		CLASS	ITEM	U/I	ORDER QTY.	UNIT PRICE	0'0"0'0"0'E8		73		#650 High speed helical high spiral taper pin reamers.			
9				2					73		Cleveland twist drill part #24236			
10		1 R 2 TAX 3 TERM 4		DESCRIPTION (FOR PURCHASING ONLY - 25 CHAR. MAX.)				53		(Do not substitute)				
LINE NO.		ACCT / WORK ORDER NO.		SUB LEDG / JOB ORDER		CHARGE UNIT	TUC	ALLO%	DESCRIPTION (MAXIMUM 60 CHARACTERS PER LINE)		INTENDED USE (THIS LINE NO ONLY)		STH. LVL	HANDEL
8		1 99-152080				95.71	003		TOTAL 180 - INCLUDING SPACING		Special tools, all units		B	N/A
9		LOAD	CLASS	ITEM	U/I	ORDER QTY.	UNIT PRICE	0'0"0'0"0'E8	73		#650 High speed helical high spiral taper pin reamers.			
10				2					73		Cleveland twist drill part# 24237			
10		1 R 2 TAX 3 TERM 4		DESCRIPTION (FOR PURCHASING ONLY - 25 CHAR. MAX.)				53		(Do not substitute)				
LINE NO.		ACCT / WORK ORDER NO.		SUB LEDG / JOB ORDER		CHARGE UNIT	TUC	ALLO%	DESCRIPTION (MAXIMUM 60 CHARACTERS PER LINE)		INTENDED USE (THIS LINE NO ONLY)		STH. LVL	HANDEL
8		1 99-152080				95.71	003		TOTAL 180 - INCLUDING SPACING		Special tools, all units		B	N/A
9		LOAD	CLASS	ITEM	U/I	ORDER QTY.	UNIT PRICE	0'0"0'0"0'E8	73		#650 High speed helical high spiral taper pin reamers.			
10				2					73		Cleveland twist drill part #24238			
10		1 R 2 TAX 3 TERM 4		DESCRIPTION (FOR PURCHASING ONLY - 25 CHAR. MAX.)				53		(Do not substitute)				
APPROVAL SIGNATURE(S) MUST MEET ALL REQUIREMENTS OF PURCHASING REQUEST AUTHORIZATION AND REVIEW SCHEDULE (SEE OPERATING INSTRUCTIONS 510-09-01 (EXHIBIT E) FOR DETAILS.)										PURCHASING APPROVALS				
PR-E APPROVAL INITIAL(S)										BUYER SIGNATURE				
1 2 3 4 5 6														

OPERATIONS ENGINEERING

DATE

MAINTENANCE ENGINEERING

DATE

OPR QUALITY ASSURANCE DEPT.

DATE

NON SPECIFIED REVIEW

DATE

X. E. Shultz 6-21-83
4522-01G (3/82) REVIEWED BY (IF REQUIRED)/DATE

CONCURRENCE (IF REQUIRED)/DATE

AUTHORIZED BY

DATE

\$450.00

PH COST ESTIMATE

REQUESTOR → MATERIALS MGT. → REQUESTOR (FILE COPY)

APS.

ARIZONA PUBLIC SERVICE CO.
PALO VERDE NUCLEAR GENERATING
STATIONPURCHASE REQUEST (PR)
CONTINUATION PAGE

P.O. NO (SAME AS 1st PAGE)

PR NO (SAME AS 1st PAGE)

003821

PAGE 2 OF 3

* 1	2	3	4	5	6	7	DESCRIPTION (MAXIMUM 60 CHARACTERS PER LINE) TOTAL 180 - INCLUDING SPACING	INTENDED USE (THIS LINE NO ONLY)	STR LVL	HANDLE
LINE NO	ACCT / WORK ORDER NO	SUB LEDG / JOB ORDER	CHARGE UNIT	TOD	ALLO %					
8	1 99-152080		95.71	003			#650 High speed helical high spiral taper pin reamers.	Special tools, all units	B	N/A
9							Cleveland twist drill part #24239			
10							(Do not substitute)			
8	1 990152080		95.71	003			#650 high speed helical high spiral taper pin reamers	Special tools, all units	B	N/A
9							Cleveland twist drill part #24240			
10							(Do not substitute)			
8	1 99-152080		95.71	003			#650 High speed helical high spiral taper pin reamers	Special tools, all units	B	N/A
9							Cleveland twist drill part #24241			
10							(Do not substitute)			
8	1 99-152080		95.71	003			#650 High speed high helical high spiral taper pin reamers	Special tools, all units	B	N/A
9							Cleveland twist drill part #24242			
10							(Do not substitute)			
8	1 99-152080		95.71	003			#650 hgh speed helical hgh spiral taper pin reamers	Special tools, all units	B	N/A
9							Cleveland twist drill part #24243			
10							(Do not substitute)			

PV 522-01H (3/82)

• ARIZONA PUBLIC SERVICE CO.
PALO VERDE NUCLEAR GENERATING
STATION

PURCHASE REQUEST (PR)
CONTINUATION PAGE

P.R. NO (SAME AS 1st PAGE)

P.R. NO (SAME AS 1st PAGE)

PAGE 3 OF 3

1	2	3	4	5	6	7	8	9	10	DESCRIPTION (MAXIMUM 60 CHARACTERS PER LINE) TOTAL 180 - INCLUDING SPACING	INTENDED USE (THIS LINE NO ONLY) Special tools, all units	STR LVL	HANDLE
LINE NO ACCT / WORK ORDER NO				SUB LEDG / JOB ORDER		CHARGE UNIT	LOC	ALLO%				B	N/A
1 99-152080						95.71	003			#650 High speed helical high spiral taper pin reamers			
1 LOAD CLASS				2 ITEM	3 U/I	4 ORDER QTY.	5 UNIT PRICE	6	7 E 8	Cleveland twist drill part #24244			
1 R 2 TAX 3 TERM 4				DESCRIPTION (FOR PURCHASING ONLY - 25 CHAR. MAX.)						(Do not substitute)			
1	2	3	4	5	6	7	8	9	10	DESCRIPTION (MAXIMUM 60 CHARACTERS PER LINE) TOTAL 180 - INCLUDING SPACING	INTENDED USE (THIS LINE NO ONLY) Special tools, all units	STR LVL	HANDLE
LINE NO ACCT / WORK ORDER NO				SUB LEDG / JOB ORDER		CHARGE UNIT	LOC	ALLO%				B	N/A
1 99-152080						95.71	003			#650 High speed helical high spiral taper pin reamers			
1 LOAD CLASS				2 ITEM	3 U/I	4 ORDER QTY.	5 UNIT PRICE	6	7 E 8	Cleveland twist drill part #24245			
1 R 2 TAX 3 TERM 4				DESCRIPTION (FOR PURCHASING ONLY - 25 CHAR. MAX.)						(Do not substitute)			
1	2	3	4	5	6	7	8	9	10	DESCRIPTION (MAXIMUM 60 CHARACTERS PER LINE) TOTAL 180 - INCLUDING SPACING	INTENDED USE (THIS LINE NO ONLY)	STR LVL	HANDLE
LINE NO ACCT / WORK ORDER NO				SUB LEDG / JOB ORDER		CHARGE UNIT	LOC	ALLO%					
1 99-152080													
1 LOAD CLASS				2 ITEM	3 U/I	4 ORDER QTY.	5 UNIT PRICE	6	7 E 8				
1 R 2 TAX 3 TERM 4				DESCRIPTION (FOR PURCHASING ONLY - 25 CHAR. MAX.)									
1	2	3	4	5	6	7	8	9	10	DESCRIPTION (MAXIMUM 60 CHARACTERS PER LINE) TOTAL 180 - INCLUDING SPACING	INTENDED USE (THIS LINE NO ONLY)	STR LVL	HANDLE
LINE NO ACCT / WORK ORDER NO				SUB LEDG / JOB ORDER		CHARGE UNIT	LOC	ALLO%					
1 99-152080													
1 LOAD CLASS				2 ITEM	3 U/I	4 ORDER QTY.	5 UNIT PRICE	6	7 E 8				
1 R 2 TAX 3 TERM 4				DESCRIPTION (FOR PURCHASING ONLY - 25 CHAR. MAX.)									

APDS

PURCHASING DEPARTMENT, STATION 5763
P.O. BOX 21666 • PHOENIX, AZ 85036

PAGE

OF

1

3621

SHIP VIA

PO DATE	NOT BEFORE	DELIVERY REQUIRED BY	FOR	SHIP VIA	TRADE DISC.	NIP	PURCHASE ORDER NO.
06/22/83		07/06/83	DEST	VENDOR	0.0000		53202571

SHIP TO

ARIZONA PUBLIC SERVICE CO.
DO NOT DELIVER TO BELTLINE
APS/PVHS OPERATIONS SIno bldg
4 FILES 5 WINTERBERG DR E5043

SHIP TO

PHOENIX
PHOENIX
PHOENIX
PHOENIX

SHIP TO

AZ 85121

ITEM # 257105 NOR = NON QUALITY RELATED
ITEM # 257104 NOR = NON QUALITY RELATED

ITEM # 257103 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257102 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257101 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257100 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257105 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257104 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257103 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257102 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257101 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257100 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257105 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257104 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257103 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257102 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257101 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257100 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257105 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257104 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257103 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257102 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257101 NOR = NON QUALITY RELATED

OA REQUIREMENT

ITEM # 257100 NOR = NON QUALITY RELATED

OA REQUIREMENT

QUALITY ASSURANCE DEPT REVIEW
THE PURCHASE ORDER INVOLVES VENDOR NO.
PARTICIPANTS-SEB BACK OF FORM
EXPLANATION OF TAX CODES SEE BACK OF FORM

X BUYER SIGNATURE
BUYER NO. 2C
QUOTE NO.

* 2C7 *

THIS ORDER NO 1126 THIS ORDER SHALL BE GOVERNED BY THE ARIZONA PUBLIC SERVICE COMPANY TERMS AND CONDITIONS ATTACHED TO OR REFERENCED IN THIS PURCHASE ORDER II ANY AND THE UNIFORM COMMERCIAL CODE AS ADOPTED BY THE STATE OF ARIZONA EXCEPT TO THE EXTENT MODIFIED BY THE ATTACHED OR REFERENCED APS TERMS. TERMS CONTAINED IN OR A PART OF SELLER'S PROPOSAL THAT CONFLICT WITH SUCH APS TERMS OR UCC SHALL NOT BE APPLIED. IF THERE IS A DISCREPANCY BETWEEN THIS PURCHASE ORDER AND THE ATTACHED PROPOSAL, THAT CONFLICT WITH SUCH APS TERMS OR UCC SHALL NOT BE APPLIED. IF THIS ORDER FARY C, THIS ORDER EXCEPT TO THE EXTENT REPRODUCED IN THIS PURCHASE ORDER

ARIZONA PUBLIC SERVICE COMPANY

VEICOR INSTRUCTIONS

PLEASE SIGN PO NO ON ALL PACKAGES, INVOICES, SHIPPING PAPERS, FREIGHT BILL AND CORRESPONDENCE

2 PLEASE SUBMIT INVOICE ORIGINAL, ONE COPY AND FREIGHT BILL TO ACCOUNTING DEPT., STA. 1840,

P.O. BOX 21232, PHOENIX, AZ 85028

PLEASE SHOW CLASS & ITEM NO. FOR EACH ITEM WHEN APPLICABLE.

EXPLANATION OF TAX CODES SEE BACK OF FORM

APS.

ARIZONA PUBLIC SERVICE COMPANY
PURCHASING DEPARTMENT, STATION 5763
P.O. BOX 21666 • PHOENIX, AZ 85036

PLEASE SUBMIT INVOICE ORIGINAL, ONE COPY
AND FREIGHT BILL TO: ACCOUNTING DEPT.,
STA. 1640, P.O. BOX 21232, PHOENIX, AZ 85036

PAGE OF

PR

3521

PO DATE	DELIVERY REQUIRED NOT BEFORE	REQUIRED BY	FOB	SHIP VIA	TRADE DISC.	NIP	PURCHASE ORDER NO.
06/22/63		07/04/63	BEST		.0000		33202571

SHIP TO ► ARIZONA PUBLIC SERVICE CO
DO NOT DELIVER TO BECHTEL
APS/PVASS OPERATIONS STA. E320
4 MILES S WINTERSEURG AZ 85343
TO ► POWER TOOL & SUPPLY CO
P.O. BOX 23272
PHOENIX AZ 85036

NOR: R.E. SHULTZ 6310X6329
QUESTION: PV-NGS " -NSR
QD/SAFETY:

← OR = QUALITY RELATED NQR = NON QUALITY RELATED

LINE NO.	DESC ALA-TAXATION	CLASS	ITEM	U/I	ORDER QUANTITY	UNIT PRICE	DESCRIPTION	QA REQUIREMENT
--	50	2622	257510	EA	2	\$0.5000	PE52 HIGH SPEED HELICAL HIGH SPIRAL TAPER FIN FLAT FLAT CLEVELAND TWIST DRILL PART #64245-CONFIRMING CHECK TO HARRY DO NOT DUPLICATE	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
							TERMS: NET 30	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
							TERMS: 1/10, 1/30	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
							TERMS: 1/10, 1/30	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
							TERMS: 1/10, 1/30	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
							TERMS: 1/10, 1/30	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
							TERMS: 1/10, 1/30	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
							TERMS: 1/10, 1/30	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
							TERMS: 1/10, 1/30	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
							TERMS: 1/10, 1/30	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

EXECUTIVE ORDER NO. 11246
DATED SEPTEMBER 24, 1965,
ENDED IS INCORPORATED
REFERENCE AND MADE
PART OF THIS ORDER IF PART OF THIS ORDER EXCEPT TO THE EXTENT REPRODUCED IN THIS PURCHASE ORDER

VENDOR INSTRUCTIONS

1. PLEASE SHOW P.O. NO. ON ALL PACKAGES, INVOICES, SHIPPING PAPERS, FREIGHT BILL AND CORRESPONDENCE.
2. PLEASE SUBMIT INVOICE ORIGINAL, ONE COPY AND FREIGHT BILL TO ACCOUNTING DEPT., STA. 1640, P.O. BOX 21232, PHOENIX, AZ 85036.
3. PLEASE SHOW CLASS & ITEM NO. FOR EACH ITEM ON YOUR INVOICE WHEN APPlicable.
FOR EXPLANATION OF TAX CODES SEE BACK OF FORM.

ARIZONA PUBLIC SERVICE COMPANY

QUALITY ASSURANCE DEPT. REVIEW

BUYER SIGNATURE

THIS PURCHASE ORDER INVOLVES
PARTICIPANTS - SEE BACK OF FORM

VENDOR NO. ►

TOTAL COST

\$0.00

BUYER NO. QUOTE NO.

22

PALO VERDE NUCLEAR GENERATING STATION MANUAL	PROCEDURE NO.	
HORIZONTAL ROTATING EQUIPMENT ALIGNMENT	REVISION 0	Page 1 of

Truman
Rejected Jm Wright
- rewrite Jon

This was written in
Draft Form in August 1983.

R.H. Selsor 10/18/83

JD Hager 10/13/83

BY	DATE	SUBJECT	SHEET NO. 1 of
CHECKED BY	DATE	3IMT- 92203	JOB NO.

1.0 PURPOSE

- 1.1 To provide general instructions for alignment of horizontally mounted rotating equipment.
- 1.2 To describe alignment tasks such as:
 - 1.2.1 Foundation plate check
 - 1.2.2 Coupling hub removal and replacement
 - 1.2.3 Soft feet check
 - 1.2.4 Rough alignment
 - 1.2.5 Fine alignment
 - 1.2.6 Doweling.
- 1.3 May be used for routine maintenance or full alignment.
- 1.4 May be supplemented or superseded by manufacturer's Technical Manuals.

BY	DATE	SUBJECT	FILE NO.
CHECKED BY	DATE		2 of JOB NO.

2.0 REFERENCES

2.1 Implementing References

- 2.1.1 30AC-9ZZ01, Work Control
- 2.1.2 40 AC-0ZZ05, Station Tagging and Clearance
- 2.1.3 60AC-0ZZ05, Inspection Programs for Maintenance and Modification of Plant Equipment
- 2.1.4 75RP-9ZZ440, Radiation Exposure Permit

2.2 Developmental References

None

- 3.0 DEFINITIONS AND ABBREVIATIONS
- 3.1 Soft Feet - Those mounting foot at the base of a molar, canine, premolar, furcine, etc. that, due to being cracked, bent, uneven, or otherwise misaligned, could cause misalignment of coupled rotating equipment.
- 3.2 Offset Misalignment - Misalignment that occurs where coupling hub faces one parallel but do not have a common center line.
- 3.3 Angular Misalignment - Misalignment that occurs when coupling hub faces another parallel and may or may not have a common center line.

BY	DATE	SUBJECT	CHECKED BY	DATE	RECORDED
3					

cds.



BY	DATE	SUBJECT	FILED NO.
CHECKED BY	DATE		JOB NO.

3.4 Nomenclature Used


WATER PUMP
LINES

DRILLED


FOR THERMAL
POWER

3.4 Nomenclature Used


MOUNTING FOOT




ALIGNMENT



AXIAL MISALIGNMENT



ANGULAR MISALIGNMENT



BY	DATE	SUBJECT	SHLF. NO.
CHECKED BY	DATE		JOB NO. 5 of

4.0 PRECAUTIONS AND LIMITATIONS

- 4.1 Ensure equipment has been properly tagged out in accordance with 40AC-02205, Station Tagging and Clearance, before starting alignment task.
- 4.2 If safety related or quality related equipment is involved, comply with the independent inspection requirements of 60AC-02205, Inspection Requirements for Maintenance and Modification of Plant Equipment.
- 4.3 If applicable, comply with radiological restrictions as required in 75RP-07744, Radiation Exposure Permit

BY	DATE	SUBJECT	FILE NO.
CHECKED BY	DATE		6 of JOB NO.

5.0 PREREQUISITES/INITIAL CONDITIONS

- 5.1 Work Control Package processed in accordance with 30 AC-92201, Work Control.
- 5.2 Rotating equipment isolated, deenergized, and tagged out in accordance with 40AC-02205.
- 5.3 If applicable, maintenance personnel covered by an active Radiation Exposure Permit (REP).
- 5.4 Measuring and Test Equipment (M&TE) being used is labeled with valid PVNGS M&TE label that is within its due date.
- 5.5 Alignment data from manufacturer's Technical Manuals, or Plant Technical Manual on hand and reviewed for requirements and specifications for the equipment involved.

BY	DATE	SUBJECT	FILE NO.
CHECKED BY	DATE		JOB NO. 7 of

6.0 RESOURCES REQUIRED

6.1 Manpower

Two maintenance personnel, one of whom is qualified to the journeyman level

6.2 Material / Equipment

The following material / equipment, or equivalent, available for use

- | | |
|--|---------------------------------------|
| (1) approved solvent | (21) rat tail file |
| (2) approved lubricants | (22) drill and bits |
| (3) standard dowels and lifting nuts | (23) grinder and wheels |
| (4) tempsticks | (24) mechanics level |
| (5) clean rags | (25) metal straight edge |
| (6) steel strapping, 1/4 inch x 2 inch | (26) torque wrench |
| (7) assorted wedges | (27) strap wrench |
| (8) keystone | (28) reamers |
| (9) shim stock | (29) weld rod oven |
| (10) hardwood blocks | (30) hot oil bath |
| (11) crocus cloth | (31) tin snips |
| (12) soft faced mallet | (32) flash light |
| (13) wire brush | (33) extension mirror |
| (14) mill file | (34) felt tip pen |
| (15) thread taps | (35) taper gages |
| (16) coupling hub puller | (36) metal scribe |
| (17) stubby hydraulic jack, 5 ton cap | (37) combination end wrenches |
| (18) 2 gas heating torches with tanks | (38) dial indicators |
| (19) powdered chemical fire extinguisher | (39) dial indicator mounting hardware |
| (20) fuel gas gages | (40) approved rigging |


APPENDIX D

TAPER DOWEL PIN DATA SHEET


1. Standard taper is $1/4$ inch per foot.
2. Threaded (NF thread) approximately $1-3/8$ inch length at major diameter.
3. Steel _____, Rockwell hardness _____
4. Standard sizes: _____

APPENDIX C


THRUST BRACKET DATA SHEET



SOFT FOOT DATA SHEET

INDICATOR READING (STEP 8.4.2)

NOTE: IF INDICATOR READING IS LESS
THAN 0.002, SHIM REQUIREMENT
IS NOT APPLICABLE

DISTANCE READING (STEP 8.4.3)CALCULATIONS (STEP 8.4.4)

(FOR SHIMS) $a \& b = \frac{\text{DISTANCE B} \times \text{INDICATOR READING FOR THAT FOOT}}{\text{DISTANCE A}}$

(FOR SHIMS) $c \& d = \frac{\text{DISTANCE B} \times \text{INDICATOR READING FOR THAT FOOT}}{\text{DISTANCE C}}$

SHIM THICKNESS NEEDED (STEP 8.4.5)

FOOT a _____
FOOT b _____
FOOT c _____
FOOT d _____


APPENDIX A

ALIGNMENT READINGS DATA SHEET

STEP 8.3.6, MANUFACTURER'S COUPLING GAP _____

STEP 8.3.7.4, SHAFT THRUST _____

STEP 8.3.8, ACTUAL COUPLING GAP _____



STEP 8.5.6.1 A = _____


STEP 8.5.6.2 B = _____

STEP 8.5.6.3 C = _____


STEP 8.5.6.4 FRONT FOOT RATIO $\frac{B}{A} =$ _____

STEP 8.5.6.5 REAR FOOT RATIO $\frac{C}{A} =$ _____

STEP 8.6.11



STEP 8.6.11




STEP 8.6.12 Final Shim Thickness, Number

Foot a. _____, _____

Foot b. _____, _____

Foot c. _____, _____

Foot d. _____, _____



COUPLING HUB

8.7.5 ~~Driver~~ proper seated pins where he is most
likely to pull his hands away from the steering wheel.

8.7.4 Coat proper seated pins with a high quality
of leather and stitching in reinforced holes.

8.7.3 Repair the holes in the footboard found during plate
pins (right push fit). Clean and check.

8.7.2 On diagonally opposite corners of the driver
and driver's side door pins a series of
three feet and two of four positions (4 places) with
to desired depth. Holes must be 1/16 inch
less in diameter than the
of selected proper seated pins. Clean
the holes in the door pins.

8.7.1 Check driver - driver door combination
with signs of vibration being produced
Select proper seated pins at a rate of one per
square inch of surface area.

NOTE

for eight (8) hours. It is also necessary
at design pressures and temperatures
at the maximum of the body is exposed
for the duration of the test.

8.7.0 Drawing

BY	SERIALIZED ON	DATE	CHECKED BY	DATE
28				

cds.



BY	DATE	SUBJECT	SHEET NO.
CHECKED BY	DATE		29 of JOB NO.

9.0 RESTORATION

9.1 Coupling Installation

- 9.1.1 Assemble couplings, fill with prescribed lubricant and torque coupling bolts to manufacturer's specifications
- 9.1.2 Install coupling guard
- 9.1.3 Attach appropriate data sheets to Work Control Package.

BY	DATE	SUBJECT	SPREADING
CHECKED BY	DATE		27 of JOB NO.

8.6.6.2 For the rear feet —

$$\text{Shim thickness} = \text{rear foot ratio (8.5.6.5)} \times \text{TIR face (8.5.8.2)} \\ + \frac{\text{TIR rim (8.5.8.3)}}{2}$$

8.6.7 Fabricate required shims. Use least number of shims possible.

8.6.8 Loosen one (1) driver mounting bolt, add the necessary shims, then tighten the bolt. Repeat the process for the remaining three (3) bolts.

8.6.9 Repeat step 8.6.5. If not within specifications, repeat steps 8.6.4 thru 8.6.8.

8.6.10 Loosen driver mounting bolts one at a time, replace lockwashers, and torque mounting bolts to manufacturer's specifications.

8.6.11 Repeat step 8.6.5 and record readings (face and rim on data sheet of Appendix A).

8.6.12 Record thickness of shims under each foot and the number of shims used under each foot on data sheet of Appendix A.

8.6.13 Remove measuring equipment and associated alignment materials and equipment.

BY	DATE	SUBJECT	SHEET 140
CHECKED BY	DATE		26 of JOB NO.

NOTE

If using a fulcrum attachment (wiggler) for the face measurements, remember that wiggler readings taken directly from the face will give true readings but readings taken from the rear of the coupling hub will give reverse readings.

8.6.4 Rotate driver shaft 360° using strap wrenches and check that dial indicators return to zero. If not at zero examine linkage and adjust as necessary.

8.6.5 Rotate both shafts 360° in 90° increments using strap wrenches. Note the indicator readings and check that indicators return to zero. If not at zero reexamine linkage.

8.6.5.1 To check dial indicator readings, add the 90° and 270° face (or rim) readings with their plus(+) or (−) signs and compare the sum to the 180° face (or rim) reading. They should be equal.

8.6.5.2 If not equal, replace dial indicators.

8.6.6 Calculate the shim thickness required as follows:

8.6.6.1 For the front foot —

$$\begin{aligned} \text{Shim thickness} = & \text{front foot ratio (8.5.6.4)} \times \text{TIR face (8.5.8.2)} \\ & + \frac{\text{TIR rim (8.5.8.3)}}{2} \end{aligned}$$

BY	DATE	SUBJECT	SHEET NO.
CHECKED BY	DATE		JOB NO. <u>25</u>

8.6 Final Alignment

NOTE

Two (2) dial indicators, one for face readings and one for rim readings, are normally used in final alignment. If only one (1) dial indicator is used, take face readings, remount dial indicator and take rim readings.

- 8.6.1 Mark each coupling hub at four (4) places, 90° apart on the rims. Use a felt tip marking pen.
- 8.6.2 Mount dial indicators perpendicular to the face and rim of the driver coupling hub. Ensure clamping devices are solid and clearance exists to allow coupling hubs and dial indicators to rotate 360° . Locate dial indicator buttons as close as possible to the same position on the coupling hub. If space is limited, mount one dial indicator 90° clockwise or counter clockwise from the others.
- 8.6.3 Compress dial indicator buttons to approximately one half the total travel and zero at top center of driver coupling hub.

2

3

4

- 8.5.8.3 Deforrmance vertical rim reading
by setting a mark on top center of the
straight edge on top center of the
driven coupling hub rim parallel
with driver shaft and compare
distance between driver coupling
hub rim top center and the
vertical rim reading
Rear (8.5.8.3)
TIRE of vertical front shaft, multi-layer
for driver rear shaft, multi-layer
8.5.9 To determine shim thickness required
TIRE of vertical front shaft, multi-layer
for driver rear shaft, multi-layer
RIM reading (8.5.8.3)
(8.5.8.2) by rear foot
TIRE of vertical front shaft, multi-layer
for driver rear shaft, multi-layer
8.5.10 To determine shim thickness required
Vertical rim reading (8.5.8.3)
RIM reading (8.5.8.3)
TIRE of vertical front shaft, multi-layer
for driver rear shaft, multi-layer
8.5.11 Fabricate two round shim thicknesses
using this figure of dimension of shims possible
8.5.12 Locsmr size (1) driver shaft mounting with
and add required shims and tighten
foot of the driver shaft 8.5.13

SHEET NO.	SUBJECT	DATE	CHECKED BY
24			BY GAN

WE CAND. HIGH QUALITY

BY	DATE	SUBJECT	SHEET NO.
CHECKED BY	DATE		23 of JOB NO.

8.5.6.4 Divide distance B (step 8.5.6.2) by diameter A (step 8.5.6.1) to get the front foot ratio. Record ratio on data sheet of Appendix A

8.5.6.5 Divide distance C (step 8.5.6.3) by diameter A (step 8.5.6.1) to get the rear foot ratio. Record ratio on data sheet of Appendix A

8.5.7 If visual examination shows coupling hub face and rim vertical alignment is very close proceed to step 8.6

8.5.8 If visual examination shows coupling hub face and rim vertical misalignment perform the following:

8.5.8.1 Use feeler gage and determine vertical face readings at four (4) places 90° apart starting at top center (0°). Note the readings.

8.5.8.2 Calculate the Total Indicator Reading (TIR) by subtracting the top center reading from itself and from each of the other three (3) readings. The top center sum will be zero. Maintain the plus (+) and minus (-) signs of the other three (3) readings. Note the sum.

8.5.6.3 Measure distance from driver
coupling hub face to rear foot of driver
coupling hub face to rear foot of driver

8.5.6.2 Measure distance from driver
coupling hub face to rear foot of driver
coupling hub face to rear foot of driver

8.5.6.1 Measure driver coupling hub flange
distance from driver coupling hub flange
sheet of Appendix A

8.5.6 Find the ratio path from the driver
coupling hub flange to the driver coupling hub flange
calculated from dimensions used later in this procedure for
feet. (This ratio path from the driver coupling hub flange to the
driver coupling hub flange is the ratio of the distance from the driver

8.5.5.4 Using Tightron driver manufacturing bolts.

8.5.5.3 Using a probe, determine the
maximum distance between the two
coupling hubs and the two
pins are the same as the
and each for the rear hub with
3700

8.5.5.2 Using a spacer or gage
to this specified thickness
at step 8.5.8) position this coupling
hub parts parallel and firmly
with the spacer or gage
the spacer or gage

8.5.5.1 Loosen driver manufacturing bolts

BY	DATE	SUBJECT	JOB NO.	CHECKED BY
				DATE
				RECEIVED
22				

BY	DATE	SUBJECT	FILE NO.
CHECKED BY	DATE		21 of JOB NO.

8.5 Rough Alignment

8.5.1 Determine alignment specifications from applicable Technical Manual

8.5.2 Determine coupling gap if not previously determined (step 8.3.8).

8.5.3 From the applicable Technical Manual or from known data, calculate the vertical compensation requirements inherent in the equipment. The expansion of steels is roughly 0.0007 inch per inch per 100°F.

Example: With a known 200°F differential between an operating pump and motor whose cold shaft centerline is 40 inches above the common foundation plate, the correction is $0.0007 \text{ inch} \times 32 \text{ inches} \times 2 = 0.056 \text{ inch}$. This is the offset requirement to allow for expansion to bring shafts into required alignment when equipment is in the operational mode.

8.5.4 Fabricate and mount a thrust bracket on driver and set driver shaft at magnetic center (step 8.3.6). Design of thrust bracket is shown in Appendix C

8.5.5 Proceed with rough horizontal alignment as follows:

BY	DATE	SUBJECT	SHEET NO.
CHECKED BY	DATE		JOB NO. Z0

8.4.3.3 Add dimensions of distances A and B.
This is distance C. Record on data sheet of Appendix B

8.4.4 To determine shim thickness needed to adjust soft feet, use the following calculations:

8.4.4.1 For rear feet shim requirements, the equation is :

$$\text{Shim thickness} = \frac{\text{Distance B} \times \text{Indicator reading for that foot}}{\text{Distance A}}$$

Record results on data sheet of Appendix B

8.4.4.2 For front feet shim requirements, the equation is :

$$\text{Shim thickness} = \frac{\text{Distance B} \times \text{Indicator reading for that foot}}{\text{Distance C}}$$

8.4.5 Fabricate and install needed shims under each foot, one at a time. Use fewest number of shims possible. Record on data sheet of Appendix B.

8.4.6 Tighten driver mounting bolts.

BY	DATE	SUBJECT	SPILL NO.
CHECKED BY	DATE		19 of JOB NO.

8.4.2 Determine soft feet indicator readings as follows:

- 8.4.2.1 Tighten each driver mounting bolt
- 8.4.2.2 Mount a dial indicator perpendicular to the driven coupling hub rim at top center. Ensure clamping device is solid, clearance exists for dial indicators, dial indicator is seated solid, and there is a smooth seat for the dial indicator button
- 8.4.2.3 Zero indicator and loosen one(1) driver mounting bolt. Record indicator reading on data sheet of Appendix B. Tighten bolt
- 8.4.2.4 Repeat step 8.4.2.3 for the other three (3) feet

8.4.3 Determine driver feet mounting bolt centerline distances to dial indicator centerline as follows:

- 8.4.3.1 Measure distance from dial indicator button centerline to bolt hole centerline of driver front foot (foot closest to indicator). This is distance A. Record on data sheet of Appendix B.
- 8.4.3.2 Measure distance from driver front foot bolt hole centerline to bolt hole centerline of driver rear foot on same side of driver. This is distance B. Record on data sheet of Appendix B.

BY	DATE	SUBJECT	SHEET NO.
CHECKED BY	DATE		18 of JOB NO.

8.3.9 For driver that is not a motor, determine shaft running center from the appropriate Technical Manual and then perform step 8.3.7.

8.3.10 Ensure there is enough clearance between driver and driven coupling hubs to set gap determined in step 8.3.8 or 8.3.9.

8.4 Soft Feet Determination and Adjustment

8.4.1 To determine possible soft feet problems:

8.4.1.1 Rock driver on foundation, plate. If there is movement, locate the soft feet. When no movement is noted, proceed to step 8.4.2

8.4.1.2 After locating soft feet, use feeler gages to measure gaps and shim accordingly

8.4.1.3 To determine whether shims are needed on diagonal corners, remove those mounting bolts and tighten the other two mounting bolts. Use feeler gages to determine whether one or both feet need shims. Shim accordingly.

BY	DATE	SUBJECT	SHEET NO.
CHECKED BY	DATE		17 of JOB NO.

- 8.3.6 If not previously determined in step 8.3.2.1, determine manufacturer's coupling gap from appropriate Technical Manual and record on data sheet of Appendix A.
- 8.3.7 Mount a dial indicator perpendicular to the driver coupling hub face at top center.
- 8.3.7.1 Ensure clamping device is solid, clearance exists for dial indicator to function properly, dial indicator is seated solid, and there is a flat smooth seat for the dial indicator button
- 8.3.7.2 Compress button to approximately one half its total travel and zero dial indicator
- 8.3.7.3 Push driver shaft away from dial indicator to limit of shaft travel, zero dial indicator, then push shaft toward dial indicator until manufacturer's magnetic center mark (step 8.3.5.1) or scribe mark (step 8.3.5.2) is even with driver bell housing. Read dial indicator and record reading on data sheet of Appendix A
- 8.3.8 Subtract thrust reading (step 8.3.7.3) from manufacturer's coupling gap dimension (step 8.3.6) and record this on data sheet of Appendix A.

BY	DATE	SUBJECT	FILE NO.
CHECKED BY	DATE		16 of JOB NO.

8.3.4.2 Visually check driver coupling hub rim at top center (0°) relative to driven coupling hub rim at top center. Driver coupling hub rims must be even with or lower than driven coupling hub rim.

8.3.4.2 If a visual check is not sufficient to determine the relative height of the rims, use a machinist's level and feeler gages to determine relative rim positions.

8.3.4.3 When driver coupling hub rim at top center is higher, without shims or with temporary shims used to rough set alignment, than driven coupling hub rim, inform foreman and proceed as instructed.

8.3.5 Determine the magnetic center for a driver that is a motor as follows:

8.3.5.1 Visually locate manufacturer's magnetic center mark, when mark cannot be found, perform step 8.3.5.2

8.3.5.2 Bump motor and scribe the motor shaft where it extends thru the motor bell housing at the coupling hub end.

BY	DATE	SUBJECT	SEE E. NO.
CHECKED BY	DATE		15 st JOB NO.

8.3.3 To correct for too little lateral movement it will be necessary to modify the equipment. Inform foreman of plant to do one or more of the following:

- 8.3.3.1 Slightly file slots in the driver feet mounting holes in the direction needed. Use a rattrailfile.
- 8.3.3.2 Slightly enlarge driver feet-mounting holes. Use drill and bit
- 8.3.3.3 Plug, redrill, and retap foundation plate tapped holes
- 8.3.3.4 File or grind mounting bolt shoulders that are causing interference. Do not remove metal to less than the thread root diameter.
- 8.3.3.5 Modify foundation plate to slotted holes rather than tapped holes

8.3.4 Determine driver up and down (vertical) movement as follows:

- 8.3.4.1 Position driver shaft level and on common center line with driven shaft using machinist's level and temporary shims under driver feet

BY	DATE	SUBJECT	sheet no.
CHECKED BY	DATE		14 of JOB NO. <i>[Handwritten]</i>

8.3.1.2 Check driven shaft for level condition. Use a machinists level. If shaft is not level, inform foreman and proceed as instructed.

8.3.2 Determine driver side-to-side (lateral) movement capability as follows:

8.3.2.1 Set driver shaft level using machinists level and temporary shims under driver feet

8.3.2.1 Set coupling hub faces parallel and separated by a distance equal to the manufacturer's coupling gap as stated in the manufacturer's Technical Manual. Use spacers, keystocks, wedges, feeler gages etc

8.3.2.2 Keeping coupling hub faces parallel, move driver laterally to determine whether driver coupling hub flange will extend past drivers coupling hub flange in each direction (at 90° and 270°)

8.3.2.2.1 If there is enough lateral movement, go to step 8.3.4

8.3.2.2.2 If there is not enough lateral movement, go to step 8.3.3

BY	DATE	SUBJECT	SHEET NO.
CHECKED BY	DATE		13 of JOB NO.

- 8.2.2.4 Quickly move coupling hub to shaft. If it fits, quickly push coupling hub on shaft until metal strap bottoms on shaft end. Allow to cool naturally
- 8.2.2.5 If coupling hub does not fit, check for interference, reheat coupling hub, and repeat step 8.2.2.4

8.3 Preliminary Installation

- 8.3.1 Place driver on foundation plate. Leave mounting bolts loose to allow for driver positioning

NOTE

This procedure assumes the driven unit is fixed or piped into its system and is not mechanically moveable.

CAUTION

DO NOT USE A PIPE WRENCH ON A DRIVER OR DRIVEN SHAFT. TO ROTATE SHAFT USE A STRAP WRENCH

- 8.3.1.1 Rotate driver and driven unit shafts at least two(2) revolutions. This will get oil under the bearings and allow the units to seek thrust position

BY	DATE	SUBJECT	SPILL NO.
CHECKED BY	DATE		JOB NO. 12

8.2.1.3 Continue heating the coupling hub until it pops loose. Quickly remove coupling hub by pulling on coupling puller extension rods

8.2.1.4 Allow coupling hub and shaft to cool naturally to room temperature

8.2.1.5 Clean up coupling hub and shaft mating surfaces by removing nicks, gouges, and foreign material. Remove and clean up key. Lightly lubricate parts using approved lubricants and protect parts for reassembly

8.2.2 Install coupling hub as follows:

8.2.2.1 Construct a 1/4 inch thick by 2 inch wide by the OD of the coupling hub long and bolt the strap to coupling hub face, covering the shaft hole. The bolts (or threaded rods) should extend to be used for carrying handles

8.2.2.2 Degrease coupling hub, shaft, and key. Check key fit in coupling shaft and place key on shaft

8.2.2.3 Place coupling hub in a controlled hot oil bath or in a weld rod oven and heat to 275°F maximum. Monitor temperature

BY	DATE	SUBJECT	SPRING NO.
CHECKED BY	DATE		11 of JOB NO.

8.1.5.2.2 If coupling hubs are interference fits and are not flush, go to step 8.2

8.2 Coupling Hub Removal and Installation

8.2.1 Remove coupling hub as follows:

8.2.1.1 Attach coupling puller to coupling hub and place hydraulic jack under the puller. Apply a reasonable load on the jack. The coupling hub should not move

CAUTION

TAKE CARE WHEN HEATING COUPLING HUBS TO AVOID BURNS AND POSSIBILITY OF FIRE. HAVE POWDERED CHEMICAL FIRE EXTINGUISHER AT HAND

NOTE

Do not overheat coupling hub. Limit temperature to 275°F. Use Tempstik to monitor temperature.

8.2.1.2 Rapidly heat coupling hub by moving two(2) gas heating torches in semicircular arcs around coupling hub outer surface. At the same time keep wet sags wrapped around shaft and close to coupling hub

BY	DATE	SUBJECT	SHEET NO.
CHECKED BY	DATE		10 of JOHNSON

8.1.4 Bolting hardware and foundation plate prepared as follows:

8.1.4.1 No thread damage on mounting bolts.
Replace as necessary

8.1.4.2 Sufficient bolt length. Replace as necessary

8.1.4.3 No burrs on bolts caused by lockwasher action. Remove burrs as necessary

8.1.4.4 Threads in foundation plate clean and free of burrs. Retap as necessary

8.1.4.5 Flatwashers not distorted (capped).
Replace as necessary

8.1.4.6 Lockwashers removed and retained for final assembly

8.1.5 Driver and driven coupling hubs prepared as follows:

8.1.5.1 Grease, rust, burrs, and rolled edges removed

8.1.5.2 Coupling hubs faces set flush with driver and driven shaft's

8.1.5.2.1 If coupling hubs are not interference fits and are not flush, set coupling hub faces flush with shaft's and go to step 8.3

8.1.3.3 Burns and rolled edges removed

8.1.3.2 Rust removed with wire brush

Where removing metal, maintain flatness
surfaces and flat bottoms.
Requirements of foundtion plate mounting

NOTE

8.1.3.1 Gresae required with approved

8.1.3 Foundtion plate and driver foot
prepared as follows:

8.1.2 Coupling square recessed, coupling
removed
drilled (if required) and coupling

8.1.1 Pump (driver) isolated and driver
circuit breaker rocked out
(driver) power switch off with
driver

8.1 Clean up
Before starting this alignment, either perform
or make sure the following tools, have been
performed.

The following instructions apply to hourly
mounting loctite and equal.

NOTE

8.0 INSTRUCTIONS

BY	DATE	SUBJECT	CHECKED BY	DATE	NO. ON
6					



BY	DATE	SUBJECT	SHEET NO.
CHECKED BY	DATE		8 of JOB NO.

7.0 PERSONNEL ORIENTATION

7.1 Since this procedure is a general guide for horizontally mounted rotating equipment alignment, personnel responsibilities, overall time frame, and working environment will vary dependent on the specific work situation.

ROUTING AND TRANSMITTAL SLIP

Date

10/17/83
RECEIVEDTO: (Name, office symbol, room number,
building, Agency/Post)

Initials

Date

1. J. Young / J. Burdoin 1963 OCT 19 PM 12:49

2. _____ R:V

3. _____ READING ROOM

4. _____

5. _____

Action	File	Note and Return
Approval	For Clearance	Per Conversation
As Requested	For Correction	Prepare Reply
Circulate	For Your Information	See Me
Comment	Investigate	Signature
Coordination	Justify	

REMARKS

DO NOT use this form as a RECORD of approvals, concurrences, disposals,
clearances, and similar actions

FROM: (Name, org. symbol, Agency/Post)

Room No.—Bldg.

Bill Albert, WNP-3

Phone No.

5010-202

OPTIONAL FORM 41 (Rev. 7-75)

Prescribed by GSA

FPMR (41 CFR) 101-11.205

* U. S. Government Printing Office: 1979-281-184/8

110



UNITED STATES
NUCLEAR REGULATORY COMMISSION
Office of Inspection & Enforcement
P. O. Box 545
Elma, Washington 98541

October 17, 1983

MEMORANDUM FOR: Al Johnson, Region V
FROM: Bill Albert, WNP-3
SUBJECT: PALO VERDE ENFORCEMENT FOLLOW-UP

A couple of points that you may wish to look into during your enforcement follow-up visit to Palo Verde:

1. Bolting Motor Control Centers

Crane's finding relates chiefly to bolting problems between the base of the MCCs and the surrounding cabinet, as we discussed last week. However, Crane also mentioned that he had a question with regard to the bolting between the MCC and the base itself. Burdoine has Crane's write-up and should be able to shed further light on this. Seems to me the bolting of MCC to base is more critical than the base-to-cabinet bolting.

As I noted, the GE drawings are typically careless in their attention to detail. This should be mentioned in the report itself; perhaps in the citation also.

2. Doweling of Motors

Although our last (10/1) conversation with W. Ide of APS would indicate that the seriousness of this finding has been mitigated by the fact the maintenance organization did (eventually) plan to do something, I believe there is a disconnect between what these people are doing and the startup/operating organization. This item may be another example of that disconnect. For example, how could that work have been accomplished in time for the originally planned startup this fall? One of our other problems was that the tagging system showed maintenance was to do something about the HPSI-A manual operator, but this was simply the observation of the man who hung the tag, and there was no cross reference to the actual maintenance work ordered. (Ordered following CAT observations on 9/7/83.)

Copy to: Young/Burdoine

#110

ARIZONA



PUBLIC SERVICE COMPANY

PVNGS-JGS-M83-264

DATE: September 20, 1983

Prepared by:

William B. GarrettTO: L.G. Papworth
Sta. # 6075

Reviewed by:

Lee ClydeSUBJECT: Special Investigation 83-20:
1PSIAV470 Inoperability

Approved by:

Jerry Self

File: 83-147-419

Swing Shift, September 7, 1983, Operations personnel discovered 1PSIAV470 ("A" HPSI Pump Suction Isolation Valve) inoperable due to disconnection of the operator from the valve. A Special Investigation has been conducted by personnel from the STA/ISF Group. The cause of the valve operator failure has been determined. Details of the determination and recommended corrective actions appear below.

Equipment Description

Valve 1PSIAV470 is a 10" rising stem gate valve manufactured by Borg-Warner Corp. The valve is manually operated with an assembly manufactured by the Roto Hammer Company. This operator allows "hammer blows" to be delivered to a valve by turning a large handwheel (~3 1/2 feet in diameter on 1PSIAV470) which is attached to a bridle and hammer through pipe extensions and universal and slip joint. The hammer contacts the anvil through a set of raised lugs. The anvil is bolted to the handwheel replacement adaptor which slips over the stem nut. The handwheel replacement adaptor is secured to the stem nut with a nut which has been secured with a lock wire or set screw. See Figure 1.

Damage Discovery

Due to an NRC Construction Assessment Team (CAT) request to perform radiography on a section of the "A" HPSI Pump suction piping, a clearance was prepared which would allow isolation and draining of the pipe section. When Operations personnel attempted to close 1PSIAV470 they found the operator (i.e. the bridle/hammer/anvil/handwheel replacement adaptor assembly) disconnected from the stem nut and therefore inoperable. Further investigation revealed that the operator was above, and hung up on, a section of Fire Protection System piping. The valve was closed by using a wrench on the stem nut and tagged in that position so the requested radiographic work could continue as scheduled. In addition, Maintenance was contacted to repair the operator.

During disassembly of the operator, it was noted that the nut utilized to secure the handwheel replacement adaptor to the stem nut was missing. In addition, damage to the valve operator position indicator was noted. Finally, damage was noted on the Fire Protection System piping elbow upon which the operator had been resting and on Fire Protection System piping supports.

It should be noted that valve operator failure occurred with the valve approximately 1 1/2" from the full open position.

Damage Scenario

"Stackup" and location measurements of the Fire Protection System piping and 1PSIAV470 verify that interference between the valve operator and the piping elbow existed. This conclusion is further supported by a wear line on the elbow approximately 1/2" from the bottom of the elbow and by paint removal on the sides and edges of the hammer section of the valve operator.

During the opening of 1PSIAV470 (on 8/1/83) the valve operator was lifted past and above the Fire Protection System piping elbow through action of the rising valve stem. This conclusion is supported by the following evidence:

1. Damage (scratch marks) exists on the piping elbow on the bottom, side and top. These scratch marks form a sort of "trail" from the bottom to the top of the elbow such as would be made by a rotating, climbing device.
2. Paint damage exists on the bottom, edges, side and top of the hammer section known to have interference problems with the piping elbow.
3. Scratch marks exist on the inside of the top of the bridle and damage exists on the top of the valve stem indicating the stem was in contact with the top of the bridle and rotating against it. Without a handwheel replacement adaptor lock nut in place, the rising stem would be able to lift the operator off of the stem nut as the stem continued to rise during valve opening.
4. Hanger damage exists which indicates the Fire Protection System piping was lifted and pushed away from the rising valve operator.

Further opening of the valve was prevented through spring action of the Fire Protection piping lifting the operator off of the stem nut and then supporting it above the stem nut and not allowing stem nut/handwheel replacement adaptor engagement. This conclusion is supported by the following evidence:

1. As stated above, scratch marks exist on the top of the elbow and the bottom of the hammer indicating the hammer (i.e. operator) was turned while the elbow was supporting it.
2. No distress marks exist on the stem nut as would be expected if the rise of the operator was only due to action of the stem in the final

stages of operator removal and the stemnut and handwheel replacement adaptor were locking and unlocking (slipping over one another).

Finally, it is concluded that valve operation had not been attempted from August 1, 1983 to September 7, 1983 because of the condition of the Fire Protection System piping elbow and due to inspection of valve position logs. The elbow raised edges and piping adjacent to the elbow are rusty indicating that the joints had once leaked. This rust includes the main section of damage caused by the elbow/hammer interference indicating the damage is not "fresh".

In addition, the SI system PSE logs major valve movements. The last operation of 1PSIAV470 prior to September 7, 1983 was valve opening on August 1, 1983.

Conclusions and Recommendations

1. The failure mode of this operator indicates the operator was incorrectly assembled. This is apparent by the missing handwheel replacement adaptor nut and by the valve stem being too long to fit inside the operator and allow full valve travel.


Recommendations:

- 1.1 Startup should conduct a study to determine the extent of utilization of Roto Hammer operators of similar design to the one which failed (i.e. operators which enclose the stems of rising stem valves) at PVNGS.
 - 1.2 In addition, Startup should conduct sampling to assure correct installation (i.e. handwheel replacement adaptor nut installation and security and correct stem length).
 - 1.3 Startup should notify construction of problems found in order that problems of a similar nature are avoided in Units 2 and 3 at PVNGS.
 - 1.4 STA/ISEG should contact INPO with complete failure information for dissemination to the industry.
 - 1.5 Failure of this operator and the observed condition of the "B" HPSI Pump suction isolation valve as not fully open despite inability to obtain further valve stem travel indicates that verification of full stem travel capability on all rising stem manual valves should be performed. Startup should add this verification as a generic test for all safety related manually operated rising stem valves.
2. A root cause analysis into the failure of this valve operator was not performed by Maintenance or Startup. Root cause analysis should have been performed when the problem was reported (in accordance with 30AC-9ZZ01, Section 5.2.5) prior to repair in order to determine if maintenance or operating instructions need to be changed, if a design

change is required or if this failure carried any significance for other PVNGS equipment.

Recommendations

- 2.1 Maintenance and startup should assure that timely performance of root cause analysis are performed on safety related equipment in accordance with 30AC-9ZZ01, Work Control. Concern with continuation and completion of startup testing should not preclude the timely and accurate determination of equipment failure cause.
- 2.2 STA/ISEG should be notified as soon as possible of failures of this type(i.e. those which have generic failure indications) in order that it can properly evaluate the failure impact to PVNGS and the industry in a timely fashion.
3. Operators were inattentive to equipment condition during its operation and have been negligent in reporting observed deficiencies such as valve position indication not in agreement with valve position. During the failure of the 1PSIAV470 operator, noise of the operator moving the Fire Protection System sprinkler pipe surely was evident. Further, vibration and operational difficulty followed by free movement of the operator rather than operator security at the valves upper limit surely were felt.

 In addition, the valve in the other loop is known by operators to have what they feel is incorrect position indication (the valve does not indicate full open when no further valve movement is obtainable). In fact, this investigation has revealed that the valves position indication is correct.

Recommendations

- 3.1 Operations should reemphasize the importance of attentiveness to equipment degradation and malfunction during its operation, attentiveness to equipment condition on the operators rounds and prompt reporting of any abnormal operation or indication so that it can be properly evaluated and corrected.
4. As previously stated in this report, it is clear that the HPSI Pumps' suction isolation valves have not been completely open when they were assumed to be so during startup testing. This could also be true of other valves identified by the study recommended earlier in 1.

Recommendations

- 4.1 Operations Engineering should independently review data and determine test results acceptability for testing on systems for which valves are found to be in positions other than that called for in the startup test procedure.

5. During the investigation poor housekeeping and equipment conditions were noted. The HPSI Pump rooms are generally unkempt. In addition, significant leakage of boric acid is in evidence on equipment and includes body to bonnet and packing leaks on valves, leakage by caps on vents and drains, leakage from HPSI Pump seal injection cyclone separators and leakage from HPSI Pump seal injection pipe attachments to the pump case. Some of this leakage is orange in color indicating it is causing oxidation of the material onto which it has leaked.

Recommendations

- 5.1 A general cleanup of the pump rooms and equipment should be conducted by Startup.
- 5.2 Needed repairs to leaking equipment should be identified by Startup and completed as quickly as possible.
- 5.3 Specific attention should be directed to HPSI Pump seal injection piping support by Startup. This piping has screwed connections to the HPSI pumps, some of which show evidence of leakage, and can be shown to vibrate easily in the present configuration.

JS: C/WBG/mr

cc: J.R. Bynum
J.M. Allen
E.W. Gross
J.E. Kirby
R.K. Nelson

Special Investigation 83-20:


~~1PSIWA47D~~ Inoperability

Page 6

Interview Documentation Sheet

Friday, September 16, 1983: Ron Younger (Ops)
Stephen W. Ryan (Ops); prepared statement

Sunday, September 18, 1983: Chris Crane (S/U)
Jim Crews (Maintenance)
Gary McGriff (Ops)




BOTTOM VIEW OF "VALVE"
WITH HAMMER ATTACHED
FROM IRSIAV47D

9/12/83




YOKE & OPERATOR OF
1.PS1B V-102 ("E" 4PSI Pump
Suction Line)

9/12/83



SPRINKLER PIPE WHICH HAD
BEEN IN CONTACT WITH
IRSIAV47D OPERATOR

9/12/83



BENT PIPE HANGER FROM
IRSIAV47D -
(Sprinkler pipe)

9/12/83




FIGURE 1