Western Digital Corporation 5601 Great Oaks Parkway San Jose, California 95119

Tel: +1.408.717.6000

Release Notes

DC SN640™ U.2 Generic & AP OEM

Firmware Version: R1110021



Western Digital Corporation 5601 Great Oaks Parkway San Jose, California 95119

Tel: +1.408.717.6000

Overview

 This document describes the Ultrastar® DC SN640 U.2 NVMe SSD release with FW version R1110021 for Generic and AP OEM SKUs.

Affected Model/Part Numbers:

Model Number	SKU	Product Description	Firmware Code Name
WUS4BB096D7P3E3	0TS1927	Ultrastar® DC SN640 NVMe SSD, 2.5-inch, 960GB, 0.8 DW/D, ISE	R1110021
WUS4BB019D7P3E3	0TS1928	Ultrastar® DC SN640 NVMe SSD, 2.5-inch, 1.92TB, 0.8 DW/D, ISE	R1110021
WUS4BB038D7P3E3	0TS1929	Ultrastar® DC SN640 NVMe SSD, 2.5-inch, 3.84TB, 0.8 DW/D, ISE	R1110021
WUS4BB076D7P3E3	0TS1930	Ultrastar® DC SN640 NVMe SSD, 2.5-inch, 7.68TB, 0.8 DW/D, ISE	R1110021
WUS4CB080D7P3E3	0TS1952	Ultrastar® DC SN640 NVMe SSD, 2.5-inch, 800GB, 2.0 DW/D, ISE	R1110021
WUS4CB016D7P3E3	0TS1953	Ultrastar® DC SN640 NVMe SSD, 2.5-inch, 1.6TB, 2.0 DW/D,ISE	R1110021
WUS4CB032D7P3E3	0TS1954	Ultrastar® DC SN640 NVMe SSD, 2.5-inch, 3.2TB, 2.0 DW/D, ISE	R1110021
WUS4CB064D7P3E3	0TS1955	Ultrastar® DC SN640 NVMe SSD, 2.5-inch, 6.4TB, 2.0 DW/D, ISE	R1110021
WUS4BB096D7P3E1	0TS1960	Ultrastar® DC SN640 NVMe SSD, 2.5-inch, 960GB, 0.8 DW/D, SE	R1110021
WUS4BB019D7P3E1	0TS1961	Ultrastar® DC SN640 NVMe SSD, 2.5-inch, 1.92TB, 0.8 DW/D, SE	R1110021
WUS4BB038D7P3E1	0TS1962	Ultrastar® DC SN640 NVMe SSD, 2.5-inch, 3.84TB, 0.8 DW/D, SE	R1110021
WUS4BB076D7P3E1	0TS1963	Ultrastar® DC SN640 NVMe SSD, 2.5-inch, 7.68TB, 0.8 DW/D, SE	R1110021
WUS4BB096D7P3E3	0TS2162	Ultrastar® DC SN640 NVMe SSD, 2.5-inch, 960GB, 0.8 DW/D, ISE, AP OEM	R1110021
WUS4CB032D7P3E3	0TS2163	Ultrastar® DC SN640 NVMe SSD, 2.5-inch, 3.2TB, 2.0 DW/D, ISE, AP OEM	R1110021
WUS4BB019D7P3E1	0TS2164	Ultrastar® DC SN640 NVMe SSD, 2.5-inch, 1.92TB, 0.8 DW/D, SE, AP OEM	R1110021
WUS4BB038D7P3E1	0TS2165	Ultrastar® DC SN640 NVMe SSD, 2.5-inch, 3.84TB, 0.8 DW/D, SE, AP OEM	R1110021

Western Digital Corporation 5601 Great Oaks Parkway San Jose, California 95119

Tel: +1.408.717.6000

General Disclaimer:

Ultrastar® DC SN640 NVMe SSD with FW version R1110021Qualification Samples are:

- Ultrastar® DC SN640 NVMe SSD Qualification Samples are intended for customer evaluation and performance testing and not authorized for field deployment.
- Ultrastar® DC SN640 NVMe SSD Qualification Samples are delivered as "SAMPLE UNITS" without any express or implied Western Digital warranties.

Changes between R1110012 and R1110021

Category	Severity	Likelihood	Details
Power Cycle Related	Low	Medium	Where found: Customer
			Host Level Behavior:
			In a rare case, drive reported Format Corrupt
			Root Cause:
			PFAIL did not have enough time to save all the required data because of a background task taking too long to complete
			 In case of back to back PFAILs, in a rare case, if SCRAM did not run again, next boot-up assumed a successful SCRAM.
			Change Description:
			 PFAIL and background tasks fine-tuned to make sure PFAIL can start as soon as possible. In case SCRAM did not run, point to the previous
			SCRAM data.
			Drive Recovery: Power-Cycle the drive

Page: 3

Western Digital Corporation 5601 Great Oaks Parkway San Jose, California 95119

Category	Severity	Likelihood	Details	
Performance	Low	Medium	Where found: Internal	
			Host Level Behavior: • Performance drop during Random Read test	
			 Root Cause: Background Garbage Collection was interfering with Random Reads performance. 	
			Change Description: • Amount of data Garbage Collected was fine-tuned to remove the performance drops.	
			Drive Recovery: No Recovery Needed	
New Features	NA	NA	Where found: NA Host Level Behavior: • Do not update SMBus co-processor's boot code with every code download. • New Log Page CAh implemented Root Cause: • NA Change Description: • Versioning system put in place. Only update SMBus co-processor's boot-cold if the version number has changed. • Additional SMART counters implemented in the context of Log Page CAh • Additional debug traces and event to catch any field issues faster. Drive Recovery: No Recovery Needed	
			faster.	

Western Digital Corporation 5601 Great Oaks Parkway San Jose, California 95119

Category	Severity	Likelihood	Details
BMC (SMBUS)	Low	High	Where found: Customer Host Level Behavior: Host read junk/zero temperature via SMBus/BMC at boot-up Some systems did not boot up with Aspen+ plugged in BMC commands returning 0's VendorID in BMC data 0 Errors seen by host on the SMBUS VPD data unexpected Code download through SMBus fails Root Cause:
			 After code download, BMC response could wait for other high priority work to finish. In rare cases, BMC data is responded before VendorID is set in the PCIe registers. If Host sends packet greater than max MTU size, drive just ignored it and did not handle it correctly Transactions between Host processor and SMBus processor were Best effort with no retry mechanism. In case of 12V loss in the middle of BMC data transaction between Host and SMBus processor, handshaking would fail. In a rare corner case scenario, VPD/BMC data was not initialized correctly after a reset/power-cycle Regular temperature updates from Host Processor would sometime overwrite a chunk of firmware image
			 Change Description: 1st BMC response after a code download is handled at higher priority for Atmel to get BMC data quickly. Read VendorID from APIs and not from registers. If the packets size is greater than MCTP MTU size, send NACK from drive. Retry mechanism added between Host processor and SMBus processor in case of any failures. In case of 12V power-loss and return, any pending BMC transactions are reset/aborted. Wait till VPD/BMC data is initialized fully after a power-cycle/reset before responding with data to host Code logic was fixed to make sure that host processor updates do not overwrite code download segments.
			Drive Recovery: Power cycle

Western Digital Corporation 5601 Great Oaks Parkway San Jose, California 95119

Category	Severity	Likelihood	Details
Miscellaneous Low fixes	Low	Medium	Where found: Customer
			Host Level Behavior:
			Double the DDR refresh rate
			 Command Timeouts or random asserts in high I/O traffic
			 Percentage Life used SMART counter value can be > 100
			 After a Format Command FLBAS field may not have correct value
			 Command Abort may take longer than expected during high traffic scenario
			 In a rare scenario, drive may not go RO when available Spares falls below threshold.
			Root Cause:
			 DDR refresh rate is doubled to help DDR work better at higher temperatures.
			 Serializer block sometimes loses a command descriptor leading to missing commands.
			 FW implementation capped the Percentage Life Used SMART counter at 100%.
			 After Format command some reserved bits were set in FLBAS field
			 Command Abort handling did not handle submitting abort
			completion response correctly in CQ, leading to delays.
			 A specific leg of code was found where the drive would not go RO even though number of spares < threshold
			Change Description:
			 The sequence has been corrected as per ASIC/DDR specification.
			 The serializer block was reconfigured to make sure that no commands are missed in high traffic.
			The SMART counter Percentage Life Used can have values up
			to 255 in accordance with NVMe spec.
			 FLBAS field bits were cleaned up. Only those bits are set that
			are not marked reserved in the spec.
			Command Abort handling corrected to make sure responses are quoued correctly.
			are queued correctly.Spares handling was fixed to make sure drive always goes RO
			when spares < threshold.
			Drive Recovery: No Recovery Needed

Western Digital Corporation 5601 Great Oaks Parkway San Jose, California 95119

UEFI Driver related	NA	NA	Where found: NA
related			 Host Level Behavior: Power-state resets to default after a power-cycle. Incorrect FW Revision number returned
			 Root Cause: UEFI driver was resetting the power-state of the drive back to default(0). The UEFI driver was reading FW revision from an incorrect location.
			 Change Description: Modify UEFI driver to not reset the power-state at power-up. Modify UEFI driver to read FW revision from correct location. UEFI Driver was modified and recertified by Microsoft. Drive Recovery: No Recovery Needed

Western Digital Corporation 5601 Great Oaks Parkway San Jose, California 95119

Tel: +1.408.717.6000

Legal Disclaimer

The Western Digital Corporation or its affiliate's general policy does not recommend the use of its products in life support applications wherein a failure or malfunction of the product may directly threaten life or injury. Without limitation to the foregoing, Western Digital Corporation shall not be liable for any loss, injury, or damage caused by use of its products in any of the following applications:

Special applications such as military related equipment, nuclear reactor control, and aerospace.

Control devices for transportation equipment including automotive vehicles, trains, ships, and traffic equipment. Safety systems for disaster prevention and crime prevention.

Medical-related equipment (including medical measurement devices).

Accordingly, in any use of Western Digital Corporation products in life support systems or other applications where failure could cause damage, injury, or loss of life, the products should only be incorporated in systems designed with appropriate redundancy, fault tolerant or back-up features. Per Western Digital Corporation Terms and Conditions of Sale, the user of Western Digital Corporation products in life support or other such applications assumes all risk of such use and agrees to indemnify, defend, and hold harmless Western Digital Corporation or its affiliates against all damages.

Security safeguards, by their nature, are capable of circumvention. Western Digital Corporation cannot, and does not, guarantee that data will not be accessed by unauthorized persons, and Western Digital Corporation disclaims any warranties to that effect to the fullest extent permitted by law.

This document and related material are for information use only and are subject to change without prior notice. Western Digital Corporation or its affiliates assumes no responsibility for any errors that may appear in this document or related material, nor for any damages or claims resulting from the furnishing, performance, or use of this document or related material. absent a written agreement signed by Western Digital Corporation or its affiliates or its authorized representative to the contrary, Western Digital Corporation or its affiliates explicitly disclaims any express and implied warranties and indemnities of any kind that may, or could, be associated with this document and related material, and any user of this document or related material agrees to such disclaimer as a precondition to receipt and usage hereof. Each user of this document expressly waives all guaranties and warranties of any kind associated with this document and/or related materials, whether expressed or implied, including without limitation, any implied warranty of merchantability or fitness for a particular purpose or infringement, together with any liability of Western Digital Corporation or its affiliates and its affiliates under any control, negligence, strict liability of Western Digital Corporation or its affiliates and its affiliates under any contract, profit or other incidental, punitive, indirect, special, or consequential damages, including without limitation physical injury or death, property damage, lost data, or costs of procurement of substitute goods, technology, or services.

This document and its contents, including diagrams, schematics, methodology, work product, and intellectual property rights described in, associated with, or implied by this document, are the sole and exclusive property of Western Digital Corporation or its affiliates and its applicable subsidiaries. No intellectual property license, express or implied, is granted by Western Digital Corporation associated with the document recipient's receipt, access and/or use of this document; Western Digital Corporation retains all rights hereto.

No work for hire, nor any form of joint ownership, is granted or implied by the document recipient's receipt, access and/ or use of this document.

Page: 8

Any work requested (or implied by the document recipient to be requested) to Western Digital Corporation associated with this document and/or its contents, shall be the sole and exclusive property of Western Digital

Western Digital Corporation 5601 Great Oaks Parkway San Jose, California 95119

Tel: +1.408.717.6000

Corporation, except to the extent, if any, expressly agreed otherwise by Western Digital Corporation in writing referencing this document.

This document and Western Digital Corporation communications to the user associated therewith, shall be treated as Western Digital Corporation's proprietary and confidential information, protected by the recipient as such, and used by the recipient only for the purpose authorized in writing by Western Digital Corporation. This document shall be covered as Western Digital Corporation's confidential information under all applicable nondisclosure agreements between the recipient and Western Digital Corporation.

No part of this document may be reproduced, transmitted, transcribed, stored in a retrievable manner, or translated into any language or computer language, in any form or by any means, electronic, mechanical, magnetic, optical, chemical, manual, or otherwise, without the prior written consent of an officer of Western Digital Corporation or its affiliates.

All parts of the Western Digital Corporation documentation are protected by copyright law and all rights are reserved. Western Digital Corporation and the Western Digital Corporation logo are registered trademarks of Western Digital Corporation or its affiliates, registered in the United States and other countries. Other brand names mentioned herein are for identification purposes only and may be the trademarks of their respective holder(s). Copyright 2018 Western Digital Corporation or its affiliates. All rights reserved.

Western Digital Corporation 5601 Great Oaks Parkway San Jose, California 95119

Tel: +1.408.717.6000

Revision History:

FW Revision	Date	Description
R1110021	04/05/2021	Maintenance Release
R1110012	06/24/2020	Maintenance Release
R1110009	02/04/2020	Initial AP OEM SKU FW Release & Generic FW Update
R1110007	11/13/2019	Initial Generic FW Release

Contact information

Address:

5601 Great Oaks Parkway San Jose, California 95119

Phone:

U.S. (Toll-Free): 800.801.4618 International: +1 408.717.6000

Western Digital and Ultrastar are registered trademarks or trademarks of Western Digital Corporation or its affiliates in the U.S. and/or other countries. All other marks are the property of their respective owners. Product specifications subject to change without notice. Pictures shown may vary from actual products. Not all products are available in all regions of the world.

Page: 10

© 2021 Western Digital Corporation or its affiliates. All rights reserved.