

Number	A.1.
Section	General Information
Sheet	1 (of 1)
Date	January, 1960

PRELIMINARY INFORMATION

(Mark 2 Models)

The following is the general data for the above models. It can be assumed that any items of data not listed are the same as for the previous models; in the case of the 3.8 litre Mark 2 the remaining data is the same as that for the 3.4 litre model.

DATA

	2.4 litre Mark 2	3.4 litre Mark 2	3.8 litre Mark 2
<u>ENGINE</u>			
Cylinder head type	'B' type	'B' type	'B' type
Cam lift	5/16"	3/8"	3/8"
Bore	3.2677"(83 mm)	3.2677"(83 mm)	3.425"(87 mm)
Sparking plug type			
7:1 comp. ratio	Champion L.7	Champion L.7	Champion N.5
8:1 comp. ratio	Champion N.5	Champion N.5	Champion N.5
9:1 comp. ratio	-	Champion N.5	Champion N.5
Sparking plug gap	.025"	.025"	.025"
Ignition timing			
7:1 comp. ratio	6° B.T.D.C.	T.D.C.	T.D.C.
8:1 comp. ratio	8° B.T.D.C.	2° B.T.D.C.	4° B.T.D.C.
9:1 comp. ratio	-	T.D.C.	5° B.T.D.C.
Valve seat angle			
Inlet and exhaust	45°	45°	45°
Carburetter needles			
7:1 comp. ratio	-	S.C.	T.X.
8:1 comp. ratio	-	S.C.	S.C.
9:1 comp. ratio	-	S.C.	S.C.

2.4 litre
Mark 2

3.4 litre
Mark 2

3.8 litre
Mark 2

STEERING

Castor angle	$0^{\circ} \pm \frac{1}{4}^{\circ}$	$0^{\circ} \pm \frac{1}{4}^{\circ}$	$0^{\circ} \pm \frac{1}{4}^{\circ}$
Camber angle	$\frac{3}{4}^{\circ} \pm \frac{1}{4}^{\circ}$ pos	$\frac{3}{4}^{\circ} \pm \frac{1}{4}^{\circ}$ pos	$\frac{3}{4}^{\circ} \pm \frac{1}{4}^{\circ}$ pos

TRACK

Disc wheels - front	4' 7"	4' 7"	4' 7"
- rear	4' $5\frac{3}{8}$ "	4' $5\frac{3}{8}$ "	4' $5\frac{3}{8}$ "
Wire wheels - front	4' $7\frac{1}{2}$ "	4' $7\frac{1}{2}$ "	4' $7\frac{1}{2}$ "
- rear	4' $6\frac{1}{8}$ "	4' $6\frac{1}{8}$ "	4' $6\frac{1}{8}$ "



Number	A.2
Section	General Information
Sheet	1 (of 1)
Date	March, 1960

"PERIODIC MAINTENANCE VOUCHER BOOKLET"

(All Models)

A copy of the above booklet is being included in the literature wallet issued with each new car.

The reason for the introduction of this Maintenance Voucher scheme is to provide a record of the maintenance services carried out and to encourage owners to have their cars regularly serviced. The record of service will be of value to a dealer who is undertaking work on a car for the first time in that he will be aware of the services that have been previously carried out. In addition, the completed vouchers will provide proof to a prospective purchaser that the maintenance operations have been carried out as recommended.

The existing form of 500 miles (800 km) Free Service Voucher is discontinued and will instead be included in the Voucher booklet.

Number	A.3
Section	General Information
Sheet	1 (of 1)
Date	March, 1960

SPECIAL SERVICE TOOLS FOR JAGUAR CARS

In order to assist Distributors and Dealers in reducing labour costs and improving efficiency in their service organisations, a range of Special Purpose Tools have been designed and approved. Such tools are to be marketed by Messrs. V.L. Churchill & Co. Ltd., and the following procedure should be adopted.

(1) Home Distributors and Dealers:-

Order direct from V.L. Churchill & Co. Ltd.,
Great South West Road,
Bedfont, Feltham,
Middlesex.

(2) Overseas Distributors:-

Order on Jaguar Cars Ltd.,
(Overseas Dealers order on their Distributors)

The following Special Purpose Tools may now be ordered:

<u>Ref. No.</u>	<u>Description</u>	<u>Price (Trade)</u>		
		£.	s.	d.
J.1 (A)	Hub puller (5 stud hub)	7.	6.	0 (already advised)
J.2	Top timing chain adjusting tool	1.	16.	6
J.3	Overdrive Drain Plug Spanner	1.	3.	9
J.4	Mark VII, VIII, IX Gearbox rear oil seal removing adaptor	1.	14.	0
J.5	2.4/3.4 litre and Mark 2 gearbox rear oil seal removing adaptor	1.	13.	0
<u>Note:</u> Applicable to standard gearbox only and used in conjunction with 7657 oil seal removing tool.				
J.6	Front suspension coil spring compressor	6.	10.	0
J.7	Hub puller (Centre lock wire wheel type)	8.	7.	6
J.8	Engine lifting plate	5.	0.	9
J.6118	Valve spring compressor	2.	9.	3
7657	Oilseal remover (for use with J.4 & J.5)	1.	17.	6

/Cont'd...

Your attention is drawn to the range of Special Purpose tools available for servicing Laycock Overdrive Units and Salisbury Rear Axles already advised in Service Bulletin No.151.

Automatic Transmission Service Tools

The following Special tools for servicing the automatic transmission are also being marketed by Messrs. V.L. Churchill & Co. Ltd.,

<u>Description</u>	<u>Original No.</u>	<u>Churchill No.</u>	<u>Price</u>		
			£.	s.	d.
∅ Pressure gauge rig	J.4270	BW.1	5.	19.	6.
∅ Band Adjuster	J.4285	BWA 2B	1.	16.	9.
∅ Spline Adjustment fixture	J.4283	BW.5	15.	13.	0.
∅ Converter Alignment flange	J.4286	BW.3	5.	1.	0.
Universal puller	HM.925	BW.55	3.	15.	0.
Fuller Plate Rear Bearing	J.12986	BW.55-1	4.	16.	5.
Adaptor rings " "					
Mainshaft end float gauge	-	BW.13	6.	11.	0.
Ring gear retaining clip	-	BW.14		1.	9.
Transmission Pilot Studs	-	BW.4		7.	9.
Mainshaft Bearing replacer	-	BW.7	1.	1.	0.
Spring retainer remover	-	BW.8 (set)		15.	6.
Governor shaft Setscrew wrench	-	BW.9		5.	3.
Piston installing pins	-	BW.10		15.	10.
Clutch Assembly Tool	-	BW.11		16.	3.
Lubrication Valve Test Rod	-	BW.12		6.	5.
Bench cradle	-	BW.15	2.	4.	3.
Drive flange oil seal replacer (use with 550 handle)	-	BW.16		13.	9.
" " Remover (use with 55 puller)	-	BW.55/2	1.	4.	0.
Circlip pliers	-	7065		19.	9.
Oil seal driver handle	-	550		18.	0.

Those marked ∅ are the minimum requirement for diagnosis or removal and refitting of Transmission and converter.

Number A.3 (2nd issue)
Section General Information

Sheet 1 (of 1)
Date February, 1961

SPECIAL SERVICE TOOLS FOR JAGUAR CARS

(This bulletin supersedes A.3 of March, 1960)

In order to assist Distributors and Dealers in reducing labour costs and improving efficiency in their service organisations, a range of Special Purpose Tools have now been designed and approved. Such tools are to be marketed by Messrs. V.L. Churchill & Co. Ltd., and the following procedure should be adopted.

1. Home Distributors and Dealers:-

Order direct from V.L. Churchill & Co. Ltd.,
Great South West Road,
Bedfont, Feltham,
Middlesex.

2. Overseas Distributors:-

Order on Jaguar Cars Ltd.,
(Overseas Dealers order on their Distributors)

The following Special Purpose Tools may now be ordered:

	<u>Description</u>	<u>Ref.No.</u>
ABC	Hub Puller (5 stud hub)	J.1 (A)
ABC	Top timing chain adjusting tool	J.2
ABC	Overdrive Drain Plug Spanner	J.3
AB	Mark VII, VIII, IX Gearbox rear oil seal removing adaptor.	J.4
AB	2.4/3.4 litre and Mark 2 Gearbox rear oil seal removing adaptor	J.5
<u>Note:</u> Applicable to standard gearbox only and used in conjunction with 7657 oil seal removing tool.		
AB	Front suspension coil spring compressor	J.6
ABC	Hub puller (Centre lock wire wheel type)	J.7
AB	Engine lifting plate	J.8
ABC	Valve spring compressor	J.6118
AB	Oil seal remover (for use with J.4 & J.5)	7657

Your attention is drawn to the range of Special Purpose Tools available for servicing Laycock Overdrive Units and Salisbury Rear Axles already advised in Service Bulletin No. 151.

Automatic Transmission Service Tools

The following Special tools for servicing the automatic transmission are also being marketed by Messrs. V.L. Churchill & Co. Ltd.,

	<u>Description</u>	<u>Original No.</u>	<u>Churchill No.</u>
ABC	∅ Pressure gauge rig	J.4270	BW.1
ABC	∅ Band Adjuster	J.4285	BWA 2B
AB	∅ Spline adjustment fixture	J.4283	BW.5
AB	∅ Converter Alignment flange	J.4286	BW.3
A	Universal Pulley Puller	-	6312A
A	Mainshaft bearing adaptors	-	BW.6312A - 1
A	Mainshaft end float gauge	-	BW.13
A	Ring gear retaining clip	-	BW.14
A	Transmission Pilot Studs	-	BW.4
A	Mainshaft Bearing replacer	-	BW.7
A	Spring retainer remover	-	BW.8 (set)
A	Governor shaft setscrew wrench	-	BW.9
A	Piston installing pins	-	BW.10
A	Clutch Assembly Tool	-	BW.11
A	Lubrication Valve Test Rod	-	BW.12
A	Bench Cradle	-	BW.15
A	Drive flange oil seal replacer use (use with 550 handle)	-	BW.16
A	Circlip pliers	-	7065
A	Oil seal driver handle	-	550

Those marked ∅ are the minimum requirement for diagnosis or removal and refitting of Transmission and Converter.

Rear Axle Service Tools

ABC Axle shaft extractor - SL.13A

Overdrive Service Tools

ABC Rig for testing hydraulic pressure - L.188

The notation A, B or C against each tool indicates the minimum requirements for distributors, district distributors, area dealers, retail and sub-retail dealers.

- A - Distributors
- B - District Distributors and area dealers
- C - Retail and sub-retail dealers

Number	A.4
Section	General Information
Sheet	1 (of 1)
Date	May, 1960

"PERIODIC MAINTENANCE VOUCHER BOOKLET"

(All models)

Owing to the demand for the above booklets by owners of cars already in service it should be noted that these booklets can be obtained at a cost of 7/6d. each by placing an order on Jaguar Spares Department.

STEERING COLUMN CONTROLS

(2.4, 3.4 and 3.8 litre Mark 2 models)

<u>Models affected</u>	<u>Commencing chassis numbers</u>	
	R.H. Drive	L.H. Drive
2.4 litre	102242	125520
3.4 litre	151466	175683
3.8 litre	201087	212640

On cars with the above chassis numbers and onwards the overdrive or automatic transmission control and the flashing indicator control are changed over side for side on both right and left hand drive cars. The location and operation of the controls is now as follows:-

Automatic Transmission Selector Control

On the right-hand side of the steering column.

The selector lever must be raised when selecting P, L or R and when moving from P to any other position.

Overdrive Control

On the right-hand side of the steering column.

Operate the lever clockwise to engage overdrive and anti-clockwise to bring the drive into top (4th) gear.

Continued...

Flashing Direction Indicators

On the left-hand side of the steering column.

Move the lever clockwise to operate the flashing direction indicators on the right-hand side of the car and anti-clockwise to operate the left-hand indicators.



Number A.5
Section General Information

Sheet 1 (of 1)

Date September, 1960

MANUFACTURERS WARRANTY

(All models)

To simplify the procedure covering the issue of a new car guarantee to the purchaser of a Jaguar car and eliminate the need for an individual "Owners Identification Card" a new form of "Manufacturers Warranty" card, which replaces the existing guarantee form and owners identification card, will, in the near future, be included in the literature envelope issued with each new car leaving our works.

Distributors and Dealers when handing over a new car to the purchaser must adopt the following procedure or in the case of cars sold through traders who are not Jaguar dealers ensure that this procedure is carried out with the new type Manufacturers Warranty form.

1. Inside Warranty Card and below statement of Warranty

Type the details of chassis number, delivery date, purchaser's name and address. Apply dealers stamp or type in name and address of dealer and append signature on behalf of dealer. Ensure that this section of warranty card which serves as an Owners Identification Card is signed by the purchaser.

2. Registration of Ownership Card attached to Warranty Card

Type in all details called for on "Registration of Ownership" card.

Ensure that this card is signed by the purchaser, detach from warranty card and place in mail.

3. On rear of Warranty Card

Type in details called for under the heading "Details for the Purchaser".

4. Ensure that the completed warranty card is handed to the purchaser. Advise him to keep it in the car and to show it to the Jaguar dealer on whom he may call if warranty service should be required during the warranty period.

Number **A.6.**
Section **General Information**

Sheet **1 (of 1)**

Date **November, 1960**

USE OF OIL ADDITIVES

In view of the large number of anti-friction additives now on the market we would remind you that we do not recommend the use of any oil additives.

It is emphasized that this is particularly important in so far as the rear axle, automatic transmission and gearbox/overdrive units are concerned in view of the special purpose oils used therein.



Number A.7
Section General Information

Sheet 1 (of 1)
Date February, 1961

RECOMMENDED LUBRICANTS - ADDITIONAL BRAND

(All Models)

The following lubricants manufactured by the Regent Oil Co. Ltd., are now added to our list of recommendations.

Engine - Summer	32° - 90° F	Advanced Havoline 30
	Winter Below 32° F	Advanced Havoline 20W
	Tropical Above 90° F	Advanced Havoline 40
U.C.L.		Regent U.C.L.
Gearbox		
Carburettor hydraulic piston dampers		Advanced
Distributor oil can points		Havoline 30
Oil can Lubrication		
Rear Axle		Universal Thuban 90
Steering Box		Universal Thuban 140
Rack and pinion steering		
Prop. shaft		
Wheel bearings		
Steering track rod		Marfak
Steering tie-rods		Multi-purpose 2
Wheel swivels		
Handbrake cable		
Clutch and brake pedals		
Automatic		3528
Transmission		Texamatic
Power-assisted steering		Fluid
Multigrade		Advanced
Engine oil		Havoline Special 10W/30

Number A.9
Section General Information

Sheet 1 (of 1)
Date March, 1961

CONTINENTAL TOURING KITS

With the large volume of Jaguar owners who now make continental tours and the improved service facilities in Continental Europe, we consider it no longer practicable or necessary to issue comprehensive Continental Touring Kits on a sale or return basis.

We are, however, making available small, low priced, First Aid Kits which some owners may wish to purchase to carry in their car when touring abroad or at home.

Note: THESE KITS ARE SUPPLIED ONLY ON AN OUTRIGHT SALE BASIS.

Distributors and Dealers will no doubt be pleased to supply to the owner on a sale or return basis any additional parts they may wish to carry with them on a particular tour.

The First Aid Kits now being made available consist of the following parts:

- 1 Fan Belt
- 2 Fuses (50 amp)
- 1 set Distributor Contacts
- 1 Distributor Condenser
- 1 Distributor Rotor
- 1 Brake Master Cylinder Repair Kit
- 1 Clutch Master Cylinder Repair Kit
- 1 Cylinder Head Gasket
- 1 Inlet Manifold Gasket
- 2 Exhaust Manifold Gaskets
- 2 Camshaft Cover Gaskets
- 4 Oil Pipe Washers

Note: In some of the kits for the earlier models an additional camshaft cover gasket has been included for use where an electric rev-counter is incorporated.

Note that to ensure that the correct kit is obtained for a particular car it is necessary to know the engine number and in some cases whether the car has drum or disc brakes.

Details of the First Aid Kits are given in Spares Bulletin A.48

Number A.11. (4th issue)
Section General Information.

Sheet 1 (of 1)
Date December, 1962.

This Service Bulletin supersedes the 3rd issue of November, 1962 which should be destroyed.

ADDITIONAL SERVICE TOOLS.

The following service tools are now available in addition to those listed in Service Bulletin A.3. which bulletin also gives the procedure for obtaining these tools.

OVERDRIVE TOOLS

<u>Applicable to:</u>		<u>Churchill Tool No.</u>
Mark 1X) Accumulator Piston Housing	L.216
) Remover -- for 1½" piston	
3.8 litre Mark 2) Accumulator Piston (1½" diameter)	L.217
) 'O' Ring Replacer	
3.8 litre XK.150) Accumulator Piston Ring Compressor	L.218
) (1½" diameter)	
Mark 10	Operating Piston Remover	L.300
Mark 10	Hydraulic Pressure Testing Equipment	L.301 ⁺

POWER - ASSISTED STEERING TOOLS

Mark 2 models	Power steering piston assembly sleeve	L.9
Mark 10	Power steering piston assembly sleeve	J.19
Mark 1X) *Hydraulic pressure gauge set	J.10
Mark 10) comprises:-	
Mark 2 models) Gauge	J.10/2
) T. Adaptor	J.10/1
) Pipe	J.10/3

* See Service Bulletin No.II.5

+ Consists of BW 1A and adaptor BW 38.

/cont'd.....

GENERAL TOOLS

5 stud hubs	* Hub Puller	J.1.C.
'E' Type Mark 10	Hydraulic damper/Rear spring dismantling adaptor	J.11.A.(use with SL.14).
'E' Type Mark 10	Servo Vacuum Gauge	J.12
'E' Type Mark 10	Servo Vacuum gauge adaptor	J.12-1(early cars)
'E' Type	Servo Vacuum gauge adaptor	J.12-2
'E' Type	Servo Vacuum gauge adaptor	J.12-3(Later cars)
'E' Type Mark 10	Rear Hub end float gauge (dial indicator)	J.13
'E' Type Mark 10	Rear Wishbone pivot dummy shafts (2 off per set)	J.14
'E' Type Mark 10	Rear Hub Master Spacer and Bearing replacer	J.15
'E' Type Mark 10	Rear Hub outer bearing cone remover and replacer	J.16A (use with SL.14).
Engines with latest rear cover - see Service Bulletin B.13.	Crankshaft rear oil seal sizing tool	J.17
All O.H.C. engines	Valve guide reamer	J.18
'E' Type Mark 10	Rear Hub Inner and Outer Bearing Cup Remover and Replacer	J.20.(use with SL.12).

* Same as J.1.B. except for longer centre
screw (J1C/3) and thread protector (J1C/7)

Note: To the application table of the "Jaguar Service Tools"
pamphlet issued with this bulletin make the following
additions.

Mark 10 Column

Add an asterisk against Tool numbers J6A, J11A, J16A, and SL14.

Mark 1 and 11 3.8 litre Column

Add an asterisk against Tool numbers J6118 and 7657.

'E' Type Column

Add an asterisk against Tool number J6118.

Number A.18.

Section General Information.


Sheet 1 (of 1)

Date June, 1963.

THE S.U. CARBURETTER SERVICE SCHOOL.

Distributors and Dealers are advised that a Service Course dealing with the correct method of assembly, installation and maintenance, repair procedure and practical tuning of S.U. Carburetters is now in full operation for the benefit of personnel dealing with these carburetters in service.

Full details of this course can be obtained from:-



Number A.19.
Section General Information.

Sheet 1 (of 1)

Date September, 1963.

RECONDITIONED EXCHANGE UNITS - OVERSEAS SCHEME.

Many enquiries are being received from overseas distributors concerning the scheme for obtaining reconditioned engine and gearboxes from the factory.

The attention of all Distributors and Dealers is drawn to the letter circulated in January 1963 which gives details and prices of the reconditioned exchange scheme.



Number A.22.
Section General Information.

Sheet 1 (of 1)
Date May, 1964.

LABOUR ALLOWANCE FOR REMOVAL OF REAR HALF-SHAFTS.

Having examined the circumstances surrounding the removal and replacement of rear half-shaft assemblies on Mark 10, 'E' Type and 3.4 'S' and 3.8 'S' Type models, we find that the allowance made in our Repair Labour Schedule Operation H.14 is causing concern amongst a number of distributors and dealers.

A re-assessment has now been made of this operation having regard to all contingencies and we have decided to increase the allowance in this respect to 1½ hours. We would make it quite clear that 1½ hours covers the complete removal and replacement of the half-shaft assembly, but excludes re-adjustment of hub bearings, which would not be disturbed. Will all concerned please ensure that the necessary adjustments are recorded against Operation H.14 of the Repair Labour Schedule and submit guarantee claims in accordance with this revised allowance.

This increased allowance is effective from the 1st June, 1964 and is no way retrospective.

Number A.25.

Section General Information

Sheet 1 (of 1)

Date October, 1964.

NEW SERVICE TOOLS.

The following new service tools are now available.

Please note the new address of Messrs. V.L. Churchill & Co. Limited, - London Road, Daventry, Northants.

<u>Tool No.</u>		<u>Models.</u>	<u>Supplier.</u>
JD.23	Weatherstrip fitting tool (For use when fitting windscreen and backlight rubbers).	All	V.L. Churchill.
JD.24	Ball joint separator. (For "breaking" the taper of track rod and tie-rod ball joints).	All	V.L. Churchill.
10416	Brake piston retraction tool (For pushing back the pistons when fitting new friction pads on Series 3 brakes).	3.4/3.8 'S' 4.2 Mark 10	Jaguar Cars Ltd.

Number A.2826
Section General Information

Sheet Sheet 1 (of 1)
Date November, 1965

PROTECTIVE WAX (HOME MARKET)

(All Models)

With effect from 1st October, 1965, all cars sold on the Home Market will be sprayed with a protective wax finish before leaving the factory, which must be removed before delivery to the customer.

The procedure recommended for de-waxing is as follows:

- (1) Water wash, using "TERGEZ" or similar detergent agent to remove dirt and dust.
- (2) De-wax by hand with S.B.P. white spirit or paraffin, the former being preferable.
- (3) Clean glass and chrome.
- (4) Final hand polish.

Number A.27
Section General Information

Sheet 1 (of 1)
Date April, 1966

De-Waxing of New Cars

If Distributors and Dealers have sufficient movement of new cars, it may be found that manual de-waxing presents something of a problem in regard to the time factor.

We have investigated the claims made for the Kismet Mini Master Steam Jet Cleaner, with particular reference to the de-waxing operation, using a hot spray with addition of 4% detergent (or paraffin) and find this to be entirely satisfactory equipment for this purpose.

Use of the Mini Master Cleaner under these conditions involves consumption of approximately $1\frac{1}{2}$ gallons of paraffin per car. The operation take 12 to 15 minutes, depending on model, and has the most important advantage that **THERE IS NO POSSIBILITY OF PAINTWORK BEING SCRATCHED** as does occur with manual de-waxing.

The equipment costs £265 nett trade and it should be remembered that, in addition to hot water de-waxing, the equipment provides full steam-cleaning facilities.

We recommend this equipment but all enquiries should be made to Kismet Limited, Fenlake Works, Fenlake Road, Bedford, England.

Number A.28
Section General Information

Page 1 of 1
Date September, 1966

RECOMMENDED LUBRICANTS
(All Models)

Following oil specification changes by certain Oil Manufacturers the RECOMMENDED LUBRICANTS listed have been modified as detailed below:-

		<u>New Oil</u>	<u>Replacing</u>
ENGINE	(Castrol (B.P.	Castrol XL20W/50 Super Visco-Static	Castrolite or Castrol XL Visco-Static
STEERING	Mobil	Mobilube C140	Mobilube 9X140

These new oils are recommended for all current Jaguar models.

It should also be noted that ESSO Extra Motor Oil 5W/20 has now been deleted from the recommended Engine oil specification.

Number A.29
Section General Information

Sheet 1 of 1
Date March, 1967

PETROL GRADING - 'STAR' SYSTEM

For attention of all Jaguar HOME Distributors and Dealers

With reference to the introduction of a 'STAR' grading system to indicate the octane rating of petrol supplied to the Home Market, it is important to ensure that only the correct grade of petrol is used to suit the engine compression ratio.

— ALL CARS WITH 8:1 COMPRESSION RATIO REQUIRE '4 STAR' PETROL (97 OCTANE) AND ALL CARS WITH 9:1 RATIO '5 STAR' PETROL (100 OCTANE).

The compression ratio (-8 or -9) is shown as an extension of the engine number stamped on the Commission Plate and on the Engine.

The use of petrol of a lower grading may cause detonation and, in severe cases, resultant piston damage.

Petrol Pump personnel should be notified of these requirements.

Number A.30

Section General Information

Page 1 of 1

Date July, 1968

TO ALL DISTRIBUTORS AND DEALERS

Although the general requirement is laid down in the First (Free) Service at 1,000 miles (1,600 km.) as quoted in the Owner's Handbook and the Service Voucher Booklet, that all bolts, nuts, hydraulic unions, etc., are checked for tightness, it is considered, that in line with the worldwide efforts to achieve greater road safety, more emphasis must be placed on safety-related items.

Will you please instruct all personnel accordingly, and ensure that specific attention is given during the First (Free) Service to such items as:-

- (1) Tightness and freedom from leakage of all brake hydraulic and petrol pipe unions.
- (2) Tightness of road wheel securing nuts and freedom from damage to tyres.
- (3) Tightness of clamp pinch bolts on all steering column universal joints.
- (4) Proper functioning of all door locks.
- (5) Bonnet release returning to position.
- (6) Lights legally required operating correctly.

These remarks apply to any First (Free) Service whether or not you are the vendor of the car and listing of these specific points does not remove the necessity of attention being given as laid down in the Service Schedule.

Number A.32

Section General Information

Page 1 of 1

Date February, 1969

ROUTINE SERVICE VOUCHERS
(Publication No. E.153)
1,000 MILES (1,600 KM.) FREE SERVICE

IMPORTANT: To all Distributors and Dealers

When submitting the FREE Routine Service Voucher for payment, it is essential that the name and address of the SELLING DEALER is quoted in addition to the Servicing Dealer.

This information should be written on the back of the Voucher.

J A G U A R
S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO.211

ADVANCE SERVICING INFORMATION

3.4 Litre Model.

GENERAL DATA

ENGINE.

Cylinder Head	"B" type
Bore	3.2677" (83 mm.)
Compression ratio	8 to 1 (7 to 1 alternative)
Distributor contact breaker gap	.014" - .016" (.36 - .41 mm.)
Sparking Plug Type	
7 to 1 compression ratio	Champion L.10.S.
8 to 1 compression ratio	Champion N.8.B.
Sparking Plug Gap.	.025" (.64 mm.)
Ignition Timing	
8 to 1 compression ratio	2° E.T.D.C.
7 to 1 compression ratio	T.D.C.
Valve Clearances (cold)	
Inlet	.004" (.10 mm.)
Exhaust	.006" (.15 mm.)
Valve Seat Angle	
Inlet	45°
Exhaust	45°
Carburetters	
- type	H.D.6.
- needles	L.D.4. T.L.
- tuning	See Service Bulletin No.200

CLUTCH.

Operation	Hydraulic
Fluid	Genuine Lockheed Hydraulic Brake Fluid No.102 (to S.A.E.Spec 70-R1)

BRAKES

Type	Lockheed-vacuum servo assisted. Self adjusting at both Front and Rear.
Fluid	Genuine Lockheed Hydraulic Brake Fluid No.102 (to S.A.E. Spec.70-R1)

FRONT SUSPENSION AND STEERING

Castor angle	$\frac{1}{2}^{\circ}$ - 1° negative
Camber angle	$\frac{1}{10}^{\circ}$ - 1° positive
Front wheel alignment	Parallel to $\frac{1}{16}$ " (1.59 mm) toe in.

Continued on page 2.

REAR AXLE

Type	4HA
Ratio	Cars fitted with synchro-mesh gear box only 3.54 to 1 Cars fitted with an overdrive 3.77 to 1 (Overall ratio with overdrive engaged 2.93:1) Cars fitted with automatic transmission 3.54 to 1

TYRES

Type	Dunlop 6.00/6.40 x 15 Road Speed	
Pressures	Front	Rear
Normal driving	25 lbs. per sq. in. (1.76 kg/cm ²)	22 lbs per sq. in. (1.55 kg/cm ²)
Fast touring (that is long distances at sustained speeds in region of 100 m.p.h.) with short bursts at maximum speed)	31 lbs per sq. in. (2.18 kg/cm ²)	28 lbs per sq. in. (1.97 kg/cm ²)

For when maximum speed capabilities are likely to be exploited to the full

34 lbs. per sq. in. (2.39 kg/cm ²)	31 lbs. per sq. in. (2.18 kg/cm ²)
---------------------------------------------------	---------------------------------------------------

CAPACITIES.

	Imperial.	U.S.	Litres
Engine - refill	11 pints	13 $\frac{1}{4}$ pints	6 $\frac{1}{4}$
- total	13 pints	15 $\frac{1}{2}$ pints	7 $\frac{1}{2}$
Gearbox (without overdrive)	2 $\frac{1}{2}$ pints	3 pints	1 $\frac{1}{2}$
Gearbox (with overdrive)	4 pints	4 $\frac{3}{4}$ pints	2 $\frac{1}{4}$
Automatic Transmission unit	15 pints	18 pints	8 $\frac{1}{2}$
Rear Axle	3 $\frac{1}{2}$ pints	4 $\frac{1}{4}$ pints	2
Cooling system (including heater)	22 pints	26 $\frac{1}{2}$ pints	12 $\frac{1}{2}$
Petrol tank.	12 galls	14 $\frac{1}{2}$ galls	54 $\frac{1}{2}$

INTERMEDIATE SPEED HOLD.
(fitted to Automatic Transmission Models)

A switch mounted on the facia provides a means for the driver to obtain a downshift from direct to intermediate gear without depressing the accelerator pedal and to retain the drive in the intermediate range. This will be found convenient for overtaking or when hill climbing.

With the switch in the "In" position no automatic upshift will take place between intermediate and direct drive; placing the switch lever in the "Out" position will cause the transmission to shift to direct drive, provided the normal upshift speed has been obtained.

Warning: DO NOT allow the maximum permitted engine revolutions to be exceeded through allowing the "Intermediate Speed Hold" to remain in operation longer than necessary or by switching in the "hold" at speeds in excess of 75 m.p.h. (121 k.p.h.)

February 1957.

J A G U A R
S E R V I C E A N D S P A R E S O R G A N I S A T I O N


SERVICE BULLETIN NO.211 A.

ADVANCE INFORMATION ON SERVICING ITEMS.

<u>Model affected</u>	<u>Commencing</u>	
	<u>Engine No.</u>	<u>Chassis No.</u>
3.4 Litre	KE.1001	970001 R.H.Drive 985001 L.H.Drive

Items which may be required to service 3.4 models are listed below.

The detail parts for the 3.4 litre cylinder head are as for the Mark VIII model (see Service Bulletin No.200A)

<u>Part No.</u>	<u>Description</u>	<u>No per Unit.</u>	<u>Remarks.</u>
			
G.12386	OIL SUMP ASSY.	1	
G.8595	Gasket, between Oil Sump and Cylinder Block.	2 Halves	
G.9166	FILTER BASKET ASSY INSIDE OIL SUMP	1	
G.9171	COVER, AT BOTTOM OF OIL SUMP RETAINING FILTER BASKET.	1	
G.9173	Gasket, at each side of Filter Basket	2	
NS.131/5D	Screw, Set, securing Cover and filter Basket to Oil Sump	8	
FW.105/E	Washer (Copper) on Setscrews	8	
G.12896	DIPSTICK ASSY, FOR OIL SUMP	1	
G.12532	OIL CLEANER ASSY	1	
6144	Filter Head Assy (41032)	1	
6145	Valve Seat (403127)	1	
6146	Circlip retaining Valve Seat (175045)	1	
6147	Clamping Plate (134282)	1	

<u>Part No</u>	<u>Description</u>	<u>No. per Unit.</u>	<u>Remarks.</u>
<u>ENGINE (Continued.)</u>			
6148	Anchor Insert holding, Clamping Plate to Filter Head (103118)	1	
6150	Drain Plug (103181)	1	
6149	Washer on Drain Plug (150382)	1	
2713	Relief Valve (118076)	1	
6462	Spring for Relief Valve (160604)	1	
2698	Union Screw for connection of Flexible Hose to Pressure Gauge (102255)	1	
5243	Washer for Union Screw (4323)	1	
6155	Sealing Ring between Filter Head and Canister (137366)	1	
6157	Canister Assy (61871)	1	
6159	Spring at bottom of Canister (160441)	1	
6160	Plain Washer at top of Spring (174660)	1	
6161	Felt Washer under Pressure Plate (141251)	1	
6162	Pressure Plate at bottom of Canister (134337)	1	
1526	Element (EG.2306)	1	
6156	Bolt, securing Canister to Filter Head (103183)	1	
6158	Rubber Washer under head of Bolt (137367)	1	
6163	Spring Clip on Bolt (174966)	1	
C.12534	Banjo for Connection of Hose to Oil Sump	1	
C.12533	Bolt, securing Banjo to Filter Head	1	
6153	Washer at each side of Banjo	2	
C.12177	Gasket, between Oil Cleaner and Cylinder Block.	2	
NB131/37D	Bolt, securing Oil Cleaner to Cylinder Block.	1	
ND.131/27D	Bolt, securing Oil Cleaner to Cylinder Block	1	
NB.131/11D	Bolt, securing Oil Cleaner to Cylinder Block.	2	
FW.105/E	Washer (Copper) on Bolts, adjacent to Cylinder Block	4	
FW.105T	Washer (Steel) under head of Bolts	4	
C.12382	HOSE, FROM OIL CLEANER TO OIL SUMP	1	
C.2905/2	Clip, securing Hose	2	
C.12381	BLANKING PLATE BETWEEN OIL CLEANER AND CYLINDER BLOCK	1	
C.8068	FLEXIBLE OIL PIPE FROM OIL CLEANER TO COPPER PIPE	1	
C.11628	COPPER OIL PIPE BETWEEN FLEXIBLE PIPES	1	
C.10110	FLEXIBLE OIL PIPE FROM COPPER PIPE TO PRESSURE GAUGE ON INSTRUMENT PANEL	1	

Continued on page 3.

<u>Part No.</u>	<u>Description</u>	<u>No. per Unit.</u>	<u>Remarks.</u>
<u>ENGINE (Continued.)</u>			
G.12114	FLYWHEEL	1	
G.12746	HEATER RETURN PIPE AT REAR OF CYLINDER BLOCK	1	
G.11818	Clip, securing Return Pipe to Exhaust Manifold Stud	1	
G.11742	HOSE FROM REAR RETURN PIPE	1	
G.2905/1	Clip, securing Hose	2	
G.4836	HEATER RETURN PIPE AT SIDE OF CYLINDER BLOCK	1	
G.12742	Clip, securing Front Return Pipe to Inlet Manifold Studs	2	
BD.215/1	ELBOW HOSE FOR HEATER PIPE	1	
G.11730	HOSE FOR HEATER FEED ADAPTOR	1	
G.12391	FAN ASSEMBLY	1	
G.2485/1	FLEXIBLE PIPE FOR BREATHER HOUSING (27" LONG)	1	
G.11480	BRACKET ASSY FOR L.H.FRONT ENGINE MOUNTING	1	
G.11481	BRACKET ASSY FOR R.H.FRONT ENGINE MOUNTING.	1	
G.11757	LOWER BRACKET ASSY FOR MID ENGINE MOUNTING	1	Not required when Automatic Transmission is fitted.
G.10665	REV.COUNTER DRIVE SHAFT ON INLET CAMSHAFT	1	
G.12339	REV.COUNTER ADAPTOR ON INLET CAMSHAFT	1	
G.10666	Screw, securing Rev.Counter Adaptor	2	
G.9914	REV COUNTER GEARBOX	1	
G.10667	Gasket for Rev.Counter Gearbox	1	
G.11777	Screw, securing Gearbox	2	
SD.1054	CYLINDER HEAD ASSY (Complete with Valves, Inserts, Guides, Springs, Tappets, Camshafts, Rev.Counter Gearbox, etc.)	1	

Continued page 4

<u>Part No.</u>	<u>Description</u>	<u>No. per Unit</u>	<u>Remarks.</u>
<u>ENGINE (Continued.)</u>			
C.12012	EXHAUST MANIFOLD, FRONT	1	
C.12013	EXHAUST MANIFOLD, REAR	1	
C.12422	WATER OUTLET ELBOW	1	
C.12867	WATER THERMOSTAT IN OUTLET ELBOW	1	
C.12515	Bracket for anchoring of Throttle Return Spring	1	
C.13097	PETROL FEED PIPE ASSY LINKING CARBURETTORS	1	
C.12481	BRAKE SERVO VALVE (70149)	1	
C.12480	Spring for Servo Valve (70150)	1	
C.12482	Seat for Servo Valve (70332)	1	
C.12695	AIR CLEANER AND SILENCER	1	
C.12705	Stud for fixing of Air Cleaner	2	
C.12691	BRACKET ASSY, SUPPORTING AIR CLEANER OVER CYLINDER HEAD	1	
C.12734	Wing Nut, securing Air Cleaner to Bracket.	2	
C.12694	RUBBER SEAL BETWEEN AIR CLEANER AND INTAKE PIPE	1	
C.12584	AIR INTAKE PIPE FOR AIR CLEANER	1	
C.12648	HOSE BETWEEN AIR CLEANER AND WING VALANCE	1	
C.2905/9	Clip, securing Hose	2	
C.12225	STRAF ASSY FOR FIXING OF STARTER MOTOR	1	
C.12737	PIPE ASSY BETWEEN CLUTCH SLAVE CYLINDER AND FLEXIBLE HOSE	1	R.H.DRIVE CARS ONLY
C.12738	PIPE ASSY BETWEEN CLUTCH SLAVE CYLINDER AND FLEXIBLE HOSE.	1	L.H.DRIVE CARS ONLY.
C.12731	Bracket, securing Clutch Pipe to Cylinder Head	1	
C.12477	OVERDRIVE UNIT, COMPLETE (28/1474)	1	SUPPLIED TO SPECIAL ORDER ONLY.
C.11837	Accumulator Spring (ZN.4972)	1	

Continued on page 5.

<u>Part No.</u>	<u>Description</u>	<u>No.per Unit.</u>	<u>Remarks.</u>
<u>ENGINE (Continued.)</u>			
<u>AUTOMATIC TRANSMISSION UNIT.</u>			
G.12523	AUTOMATIC TRANSMISSION ASSY, COMPLETE.	1	
G.12485	Stop Plate, restricting Reverse Gear Operating Lever	1	
G.125553	CONVERTER HOUSING	1	
G.12888	Support Bracket at R.H.side of Converter Housing	1	
G.12889	Support Bracket at L.H.side of Converter Housing	1	
G.13383	Lockwasher (Converter to Driving Plate.)	3	
G.12577	MOUNTING BRACKET UNDER GEARBOX REAR EXTENSION	1	
G.12578	REAR ENGINE MOUNTING BRACKET ASSY	1	
G.12027	Spacer for Rear Engine Mounting Bracket	4	
G.12677	RUBBER MOUNTING, SUPPORTING ENGINE AT REAR	2	
G.12890	MID ENGINE MOUNTING LINK	1	
<u>ACCELERATOR CONTROLS.</u>			
G.12547	PIVOT STEADY	1	} R.H.DRIVE CARS ONLY
G.12545	CONTROL ROD ASSY. LOWER	1	
G.13395	Spacer for Control Shaft Mounting Bracket	2	
302	CONTROL ROD, UPPER	1	} Fitted to L.H.Drive cars at Chassis No. 985312 and Subs.
G.12286	BELL CRANK ASSY	1	
G.12322	CONTROL ROD ASSY, LOWER	1	
G.13307	ACCELERATOR PEDAL SHAFT ASSY	1	
G.13316	Distance Collar on Pedal Shaft	1	
G.13308	Bearing Housing Assy on R.H. side of Scuttle	1	} Continued on page 6

<u>Part No.</u>	<u>Description.</u>	<u>No.per Unit.</u>	<u>Remarks.</u>
<u>ACCELERATOR CONTROLS (Continued.)</u>			
C.13310	LEVER ON CROSS SHAFT AND FOR RETURN SPRING	2	}
C.13355	Return Spring for Throttle	1	
C.13305	PIVOT STEADY ASSY	1	
C.13387	BRACKET, MOUNTING ACCELERATOR PEDAL TO FLOOR	1	
<u>ACCELERATOR CONTROLS</u> <u>(For use when Automatic Transmission is fitted.)</u>			
C.12413	CONNECTING LINK ASSY	1	}
C.12408	BELL CRANK ASSY	1	
C.12315	PIVOT STEADY	1	
C.12322	CONTROL ROD ASSY, LOWER	1	
C.12288	CONTROL ROD, UPPER	1	
C.12286	BELL CRANK ASSY	1	}
C.13314	KICK-DOWN LEVER ASSY	1	
C.13310	THROTTLE LEVER	1	
C.13305	PIVOT STEADY ASSY	1	
C.12322	CONTROL ROD ASSY, LOWER	1	
302	CONTROL ROD, UPPER	1	
C.12547	PIVOT STEADY	1	
C.12545	CONTROL ROD ASSY, LOWER	1	
C.12413	CONNECTING LINK ASSY	1	
C.12408	BELL CRANK ASSY	1	
C.12060	PROPELLOR SHAFT ASSY	1	For Standard cars only
C.12183	PROPELLER SHAFT ASSY	1	For cars fitted with Overdrive Unit.

Continued on page 7.

<u>Part No.</u>	<u>Description</u>	<u>No. per Unit.</u>	<u>Remarks.</u>
<u>PROPELLER SHAFT (Continued.)</u>			
C.12155	FRONT PROPELLER SHAFT ASSY	1	} For cars fitted with Automatic Transmission Unit.
C.12156	REAR PROPELLER SHAFT ASSY	1	
C.12531	MOUNTING ASSY FOR PROPELLER SHAFT CENTRE BEARING	1	

BRAKE CONTROLS

C.12431	VACUUM PIPE ASSY, FROM BRAKE SERVO UNIT TO INLET MANIFOLD	1
C.12884	HYDRAULIC PIPE ASSY, FROM 3-WAY ADAPTOR TO R.H.REAR WHEEL CYLINDER.	1
C.12885	HYDRAULIC PIPE ASSY, FROM 3-WAY ADAPTOR TO L.H.REAR WHEEL CYLINDER	1



C.12589	HYDRAULIC PIPE ASSY, FROM 4-WAY ADAPTOR TO ANTI-CREEP SOLENOID	1	
C.12591	HYDRAULIC PIPE ASSY FROM ANTI-CREEP SOLENOID TO 3-WAY ADAPTOR	1	
C.13070	Cover Plate, blanking Clutch Pedal hole in Pedal Housing.		
C.8966	Return Spring for Brake Pedal	1	
C.13066	BRAKE PEDAL PLATE ASSY	1	R.H.DRIVE CARS ONLY
C.13062	BRAKE PEDAL PLATE ASSY	1	L.H.DRIVE CARS ONLY
C.6876	RUBBER PAD FOR BRAKE PEDAL	1	
C.11881	BRAKE PEDAL	1	

HANDBRAKE CONTROL

C.12838	HANDBRAKE COMPENSATOR ASSY	1	R.H.DRIVE CARS ONLY
C.13217	HANDBRAKE COMPENSATOR ASSY	1	L.H.DRIVE CARS ONLY
C.12839	Cable from Cross Shaft Lever to Compensator	1	
C.12840	Compensator Lever	4	
C.12841	Compensator Tube	1	
C.12842	Compensator Sleeve	1	

Continued on page 8

<u>Part No.</u>	<u>Description</u>	<u>No.per Unit</u>	<u>Remarks.</u>
<u>HANDBRAKE CONTROL (Continued)</u>			
C.2296/4	Copper Washer, between Levers	3	
C.12843	Compensator Spring	1	
C.12844	Compensator Bracket	1	R.H.DRIVE CARS ONLY
C.12845	Compensator Bracket	1	L.H.DRIVE CARS ONLY
C.12846	Cable, 17.5/8" long, from Compensator to Rear Brake Backplate	1	
C.12847	Cable, 25.11/16" long from Compensator to Rear Brake Backplate	1	
UFB.125/12R	Bolt, securing assembly of Compensator	1	
C.8667/1	Nut, Self-Locking, on Bolt	1	
C.13218	Shim for Compensator	As req'd	
J.105/11.5S	Clevis Pin,securing Cables to Rear Brakes	2	
FW.105/T	Washer, Plain, on Clevis Pins	2	
L.103/7U	Split Pin, retaining Clevis Pins	2	
C.13410	Clip, securing Handorake Clip to Silencer Strap	1	
C.12848	LEVER, FROM HANDBRAKE OPERATING SHAFT TO LINK	1	
C.12849	FORK END FOR HANDBRAKE CABLE	1	
<u>CHASSIS</u>			
C.12585	FRONT SUSPENSION COIL SPRING	2	
C.12186	PANHARD ROD ASSEMBLY	1	
C.12890	STABILISING LINK AT REAR OF CYLINDER BLOCK	1	
C.12111	REAR AXLE ASSEMBLY (4HA-001/26A) (RATIO 3.77:1)	1	For use when Overdrive Unit is fitted
C.11925	REAR AXLE ASSEMBLY (4HA-001/26) (RATIO 3.54:1)	1	For use on Automatic and Standard Transmission cars
6975	REAR AXLE SHAFT (4HA-005/24)	2	
C.12788	R.H.REAR BRAKE ASSY (LOCKHEED)	1	
C.12789	L.H.REAR BRAKE ASSY (LOCKHEED)	1	
C.12566	TYRE FOR ROAD WHEELS (DUNLOP 'ROAD SPEED' 6.40 x 15)	5	
C.12557	TUBE FOR TYRES (6.40 x 15)	5	

Continued on page 9

<u>Part No.</u>	<u>Description</u>	<u>No. per Unit</u>	<u>Remarks.</u>
<u>CHASSIS (Continued)</u>			
J.12672	RADIATOR BLOCK ASSY.	1	
C.12424	TOP WATER HOSE	1	
C.12630	BOTTOM WATER HOSE	1	
J.12883	COWL, ON RADIATOR BLOCK, AROUND WATER PUMP FAN	1	
C.12718	FRONT DOWN PIPE ASSY FOR EXHAUST SYSTEM	1	
C.1759	Flexible Pipe (12" long)	1	
C.12720	REAR DOWN PIPE ASSY FOR EXHAUST SYSTEM	1	
C.1759	Flexible Pipe (12" long)	1	
C.13063	Clip, securing Down Pipes to Silencers	2	
C.12723	INNER TAIL PIPE FOR EXHAUST SYSTEM	1	
C.12724	OUTER TAIL PIPE FOR EXHAUST SYSTEM	1	
C.12717	TWIN SILENCER ASSY	1	
C.13225	Single Silencer, Inner	1	
C.13226	Single Silencer, Outer	1	
C.13227	Strap, securing Silencers	3	
C.13228	Strap Assy, securing Silencers	1	
C.8397	RUBBER MOUNTING FOR SUSPENSION OF TAIL PIPES AND SILENCERS	4	
<u>HAND CONTROL FOR AUTOMATIC TRANSMISSION UNIT</u>			
C.12757	HAND CONTROL ASSY, COMPLETE	1	
C.12758	Support Plate, top	1	
C.12759	Support Plate, Bottom	1	
C.12760	Bearing Collar	1	
C.12761	Spacing Collar	4	
C.12762	Support Bracket Assy	1	
C.12764	Bearing Washer for Control mounting	2	
C.12765	Selector Gate	1	
C.12767	Operating Lever Assy	1	
C.12771	Spring for Operating Lever	1	
R.102/6W	Rivet securing Spring	2	
C.12727	Spacer for Spring	1	
C.12772	Hand Lever	1	
R.102/6W	River, securing Hand Lever	2	

Continued on page 10

<u>Part No.</u>	<u>Description</u>	<u>No.per Unit</u>	<u>Remarks</u>
<u>HAND CONTROL FOR AUTOMATIC TRANSMISSION UNIT (Continued)</u>			
C.12773	Link, operating Starter and Reverse Lights Switch	1	
J.103/3.5S	Clevis Pin, securing Link	1	
C.12706	COVER FOR GEAR SELECTION (INSCRIBED P.N.D.L.R.)	1	
C.13112	Masking Plate under Cover	1	
C.13117	Support Collar on Woodscrews	2	
C.12596	GEAR CONTROL CABLE	1	
C.12586	Abutment Clamp for Gear Control Cable	1	
UGB.131/28R	Bolt, securing Abutment Clamp to Transmission Housing	1	
C.12689	MOUNTING BRACKET FOR GEAR CONTROL CABLE	1	
C.12690	Locknut, securing Cable to Mounting Bracket	2	
C.12587	CONTROL JOINT BODY ATTACHED TO SELECTOR LEVER	1	
C.13075	GEAR CONTROL END FITTING	1	
C.7071	Bush for attachment to End Fitting to Lever on Transmission Unit	1	
<u>AUTOMATIC TRANSMISSION KICK-DOWN CONTROLS</u>			
C.12409	UPPER CONTROL ROD	1	} R.H.DRIVE CARS ONLY.
C.6936	Guide for Control Rod	1	
C.6925	Spring for Kick-Down Control Rod	1	
C.12611	INNER CABLE ASSY FOR KICK-DOWN CONTROL	1	} FOR R.H.DRIVE CARS ONLY
C.12613	Nipple for Inner Cable	1	
C.12614	OUTER CABLE FOR KICK-DOWN CONTROL	1	R.H.DRIVE CARS ONLY
C.12588	Lock-Pin for Inner Cable	1	
C.10701	Jaw, for connection of Inner Cable to Gearbox Lever	1	
J.103/9S	Clevis Pin for Jaw	1	
C.12793	Abutment for attachment of Outer Cable to Gearbox	1	
C.3880	Abutment for attachment of Outer Cable to Carburettor Lever	1	

Continued on page 11

<u>Part No.</u>	<u>Description</u>	<u>No.per Unit.</u>	<u>Remarks.</u>
<u>AUTOMATIC TRANSMISSION</u>			
<u>KICK-DOWN CONTROLS (Continued)</u>			
C.4443	Abutment for attachment of Outer Cable	2)	
C.13315	KICK-DOWN CONTROL ROD ASSY	1)	L.H.DRIVE CARS ONLY
C.13309	Felt Washer on Kick-Down Rod	4)	
C.13356	LOWER CONTROL ROD ASSY	1)	
C.13358	CONTROL LEVER FORK ASSY	1)	
C.6925	Return Spring for Kick-Down	1)	
C.13361	Washer, fixing Spring to Fork	1)	

ELECTRICAL EQUIPMENT

C.12679	STARTER MOTOR (LUCAS 26140-M.45G/GC.70)	1	
C.12700	Adaptor Assy for Starter Solenoid	1	
C.12732	DISTRIBUTOR (LUCAS 40576/A-DMBZ.6)	1	For 8:1 Compression Ratio Engines
C.12733	DISTRIBUTOR	1	For 7:1 Compression Ratio Engines
C.8821	CONTROL BOX (LUCAS 37189/H-RB.310)	1	
C.12365	Bracket Assy, mounting Control Box	1	
C.12366	Cover for Control Box	1	
C.12602	INSTRUMENT PANEL ASSY (LUCAS 30224/A-GC.256)	1	
C.12603	Ammeter (36237/A-3M.A)	1	
C.13236	INSTRUMENT PANEL ASSY	1	Fitted only to cars exported to U.S.A.

Note:- Instrument Panel C.13236 is identical with Panel C.12602 with the following exceptions:-

C.5577	Lighting Switch	1	Replaces C.9117
C.8165	Escutcheon for Lighting Switch	1	Replaces C.9118

ALL other items as for 2.4 litre Instrument Panel C.9634

C.12739	Special Washer for Instrument Mounting	10	
C.12698	CHASSIS HARNESS (794200)	1	
C.4636	Cable, Coil to Distributor (99142)	1	

Continued on page 12

<u>Part No.</u>	<u>Description</u>	<u>No. per Unit.</u>	<u>Remarks.</u>
<u>ELECTRICAL EQUIPMENT (Continued).</u>			
C.4593	Cable, Carburetter Solenoid to Thermostat (860268)	1	
C.12702	Cable, Solenoid to Starter (813728)	1	
C.12699	Cable, Starter Solenoid Connector (864537)	1	Not required when Automatic Transmission is fitted
C.12701	BATTERY CABLE (NEGATIVE) (810811)	1	
C.12425	Grommet, in Bulkhead, for Rev. Counter	1	
C.13036	SPEEDOMETER (SMITH SN.6363/23) (CALIBRATED IN MILES)	1	FOR 3.54:1 RATIO AXLE
C.13037	SPEEDOMETER (SMITH SN.6363/24) (CALIBRATED IN KILOS)	1	FOR 3.54:1 RATIO AXLE
C.12989	REMOTE CONTROL OPERATING TRIP MILEAGE RECORDER ON SPEEDOMETER	1	
C.12606	REV. COUNTER AND CLOCK (RN.7450)	1	
C.12704	FLEXIBLE REV. COUNTER CABLE (DI.1190/00/13½)	1	
6284	Inner Cable only (DI.1110/00/13½)	1	
6897	Outer Cable only (DO.1110/06/13½)	1	
C.8305	FLEXIBLE SPEEDOMETER CABLE (DI.1104/00/70)	1	
6272	Inner Cable only (DI.1110/00/70)	1	
6273	Outer Cable only (DO.1104/00/70)	1	
C.12605	OIL PRESSURE AND WATER TEMPERATURE GAUGE (GD.1600/02)	1	
C.12604	PETROL GAUGE (FC.26 1/00)	1	
C.12741	HEATER FEED PIPE	1	
C.12745	HEATER RETURN PIPE	1	
C.12443	ELBOW HOSE FOR HEATER	3	
<u>ELECTRICAL EQUIPMENT</u> <u>For cars fitted with Overdrive Unit.</u>			
C.12748	ELECTRICAL HARNESS FOR RELAY SWITCH (864550)	1	L.H.DRIVE CARS ONLY
C.12749	ELECTRICAL HARNESS FOR RELAY SWITCH (864551)	1	R.H.DRIVE CARS ONLY

Continued on page 13.

<u>Part No.</u>	<u>Description</u>	<u>No. per Unit.</u>	<u>Remarks.</u>
C.13038	SPEEDOMETER (SMITH SN.6363/19) (CALIBRATED IN MILES)	1	FOR 3.77:1 AXLE RATIO
C.13039	SPEEDOMETER (SMITH SN.6363/20) (CALIBRATED IN KILOS)	1	FOR 3.77:1 AXLE RATIO
C.12756	FLEXIBLE SPEEDOMETER CABLE (DF.1104/00/78)	1	
6898	Inner Cable only (DI.1110/00/78)	1	
6899	Outer Cable only (DO.1104/00/77)	1	
C.12750	ANTI-CREEP SOLENOID VALVE (LUCAS 76502/D)	1	
C.12751	ANTI-CREEP PRESSURE CONTROL SWITCH (LUCAS 31393/A)	1	
C.12752	SWITCH OPERATING REVERSE LIGHT AND STARTER CUT-OUT (LUCAS 31680/A- 55.3A)	1	
C.12791	BRACKET FOR MOUNTING OF STARTER AND REVERSE SWITCHES	1	
C.13111	Bracket for fixing of Starter/ Reverse Switch Bracket	1	
C.12740	SOLENOID OPERATING INTERMEDIATE GEAR CONTROL (LUCAS 76459/A)	1	
C.12649	Washer for fixing of Solenoid	4	
C.12743	HARNESS FOR ANTI-CREEP SOLENOID	1	
C.13040	SPEEDOMETER (SMITH SN.6363/17) CALIBRATED IN MILES	1	For 3.54:1 AXLE RATIO
C.13041	SPEEDOMETER (SMITH SN.6363/18) (CALIBRATED IN KILOS)	1	FOR 3.54:1 AXLE RATIO
C.12544	FLEXIBLE SPEEDOMETER CABLE (DF.1302/00/54)	1	
6972	Inner Cable only (DI.1314/01/54)	1	
6973	Outer Cable only (DO.1314/00/54)	1	
C.12558	SWITCH FOR INTERMEDIATE GEAR CONTROL	1	
C.12570	Escutcheon for Switch	1	

Index Reference - Section 2.

MAY 1957

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO.212

VARIOUS SERVICING TITLES

REAR ROAD SPRINGS - RUBBER INTERLEAVED TYPE

<u>Models affected</u>	<u>Commencing Chassis Numbers</u>	
	<u>R.H.Drive</u>	<u>L.H.Drive</u>
Mark V11	750788	740195
Mark V111	750476	780462

On cars with the above chassis numbers and onwards Rear Springs Part Number C.13109 are fitted replacing Rear Springs Part Number C.7914.

Rear Springs C.13109 are fitted with synthetic rubbers buttons between the spring leaves, and therefore no gaiters are fitted.

Interchangeability.

Rear Springs C.13109 are interchangeable with the previous type C.7914 but should be fitted in pairs.

Index Reference. Section K.



RADIATOR ASSEMBLY

<u>Model affected</u>	<u>Commencing Chassis Numbers</u>	
	<u>R.H.Drive</u>	<u>L.H.Drive</u>
2.4 litre	906964	942194

On cars with the above chassis numbers and onwards Radiator Part Number C.12672 is fitted replacing Radiator Part Number C.8972.

Radiator C.12672 has a separate filler and inlet pipe whereas Radiator C.8972 has the filler incorporated in the inlet pipe.

Note:- Radiator C.12672 is fitted on the 3.4 litre model from the commencement of production.

Interchangeability

Radiator C.12672 is interchangeable with the previous type of radiator C.8972. The radiator hoses are unchanged.

Index Reference. Section D.

VOLTAGE AND CURRENT REGULATOR

<u>Model affected</u>	<u>Commencing Chassis Numbers</u>	
2.4 litre	R.H.Drive 906949	L.H.Drive 942190

On cars with the above chassis numbers and onwards an RB.310 Voltage and Current Regulator Part Number C.8821 is fitted replacing the RB.106 Voltage Regulator Part Number C.9631. To suit this change chassis harness C.13550 is fitted replacing chassis harness Part Number C.8914.

Interchangeability

The RB.310 regulator is interchangeable with the RB.106 regulator provided the following instructions are carried out.

1. Remove the existing regulator and dispense with the plate on which the regulator is mounted.
2. Join the two wires originally connected to the A and A1 terminal and solder them to a spade terminal. Connect these wires to the "B" terminal on the regulator.
3. Join the two wires originally connected to the "D" terminal and solder them to a spade terminal. Connect these wires to the "D" terminal on the new regulator.
4. Solder a spade terminal to the wire originally connected to the "F" terminal. Connect this wire to the "F" terminal on the new regulator.
5. The wire originally connected to the "E" terminal should be taped up and dispensed with, as the RB.310 regulator is earth by the securing screws.
6. Secure the regulator and shield plate to the scuttle with the existing setscrews in the cage nuts already fitted.

Index Reference Section P.

DISTRIBUTOR SUPPRESSOR

- Models affected
Mark V111 cars fitted with ignition suppression
2.4 litre cars fitted with ignition suppression
3.4 litre cars fitted with ignition suppression

Note that the DMBZ type of distributor fitted to the above models incorporates an inbuilt suppressor.

The suppressor normally fitted in the centre terminal post of the distributor is therefore unnecessary and must not be fitted.

Index Reference. Section P.

MAY 1957

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO. 213

VARIOUS SERVICING ITEMS

RADIATOR GRILLE AND APERTURE

Model affected

3.4 Litre

Commencing Chassis Numbers

L.H. Drive Only

985600

On left-hand drive cars with the above chassis numbers and onwards the aperture for the radiator grille is slightly smaller and a modified grille is fitted to suit; the modified grille also has a five stud mounting as against the four stud mounting of the previous type.

Note: All right-hand drive cars are fitted with the latest conditions of radiator grille and front wings.

Radiator Grille - Interchangeability

The two types of radiator grille are not interchangeable and should be fitted in accordance with the following details:-

	Prior to Chassis No. 985600	On and after Chassis No. 985600
Radiator Grille Assy	BD.12472/19	BD.13161
Medallion	BD.12448	BD.12448
Medallion Backing Piece	BD.11499	BD.11499
Medallion Packing Piece	BD.12558	BD.12558
Medallion Boss Assy	BD.12472/1	BD.13160

FRONT WINGS - SERVICE REPLACEMENT PROCEDURE

For service replacements only the latest type of front wings with the small aperture will be supplied, and it will necessary carry out the following procedure, (on L.H. Drive cars prior to chassis No. 985600) depending on whether one or both of the front wings are to be fitted.

One front wing only to be replaced

The half of the radiator grille aperture in the replacement front wing will have to be enlarged to suit the other front wing and the existing larger type radiator grille. Two new holes for the radiator grille mounting studs will have to be drilled in the replacement wing.

Both front wings to be replaced.

If the radiator grille is damaged and needs replacing, the latest type radiator grille (see Radiator Grille - Interchangeability) can be fitted without alteration to the wings.

If the radiator grille is not damaged and it is desired to refit it, the aperture will have to be enlarged and new holes drilled for the radiator grille studs.

The part numbers of the 3.4 litre front wings are as follows:-

371/196 Right-hand
371/197 Left-hand

Index Reference. Section N.

INTERMEDIATE SPEED HOLD SOLENOID

<u>Model affected</u>	<u>Commencing Engine Number</u>
Mark V111 Automatic Transmission Model	N.7197

On automatic transmission cars with the above engine numbers and onwards a modified solenoid Part number C.12740 is fitted, replacing solenoid Part number C.12594.

Solenoid C.12740 has a three point mounting and a large diameter plunger whereas Solenoid C.12594 has a two point mounting and a small diameter plunger.

Interchangeability

Solenoid C.12740 is not interchangeable with the previous type C.12594.

Index Reference. Section FF.

Amendment to Service Bulletin No.211A

On page 13 immediately above
C.12750 Anti-Creep Solenoid Valve 1
insert the heading:-

ELECTRICAL EQUIPMENT
For cars fitted with Automatic Transmission

MAY 1957

JAGUAR

SERVICE AND SPARES ORGANISATION

SERVICE BULLETIN NO.214

VARIOUS SERVICING ITEMS

"J.S." SUFFIX GEARBOX

Models affected

All

A new type of gearbox with shaved gears which has the suffix "J.S." to the gearbox number is now in production. The gearbox ratios are as follows:-

Top	1:1
3rd	1.283:1
2nd	1.86:1
1st & rev	3.378:1

The importance of quoting the gearbox number together with both the prefix and suffix letters is again stressed when ordering spare parts for a particular gearbox.

The parts which vary from other production gearboxes are as follows:-

C.11931	Front End Cover	1	} J.L. and S.L. prefix series	
C.11934	Front End Cover Oil Seal	1		
C.11932	Locknut - Front Bearing	2		
C.11933	Tab Washer for Locknut	1		
C.10200	Constant Pinion Shaft	1		
C.10208	3rd/Top Synchro Sleeve	1		
C.10201	1st Speed Mainshaft Gear	1		
C.10202	2nd Speed Mainshaft Gear	1		
C.10203	3rd Speed Mainshaft Gear	1		
C.10204	Countershaft Cluster	1		
C.10205/1	Reverse Gear Assy	1		
C.10209	2nd Speed Synchro Sleeve Assy	1		
C.10210	Spacer for Needle Rollers	1		
C.10206/1	Thrust Washer (.471"/.472" thick)	2	} Front and rear of	
C.10206/2	Thrust Washer (.473"/.474" thick)	2		} 2nd and 3rd speed
C.10206/3	Thrust Washer (.475"/.476" thick)	2		
C.12178	Clutch Housing Assy	1	} G.B. prefix series	
C.11934	Clutch Housing Oil Seal	1		

Note: With the "J.S." type gearbox the constant pinion shaft is located by a nut and locknut and a smaller front oil seal is fitted.

Index Reference Section F.

CARBURETTOR NEEDLES - CHANGE IN RECOMMENDATION

Model affected

3.4 litre

The recommended carburettor needle for the above model is changed from L.B.1 to T.L. Service Bulletin No.211 should be amended in accordance with this information.

Index Reference - Section C.

CHASSIS SIDE MEMBER ASSEMBLY - SERVICE CONDITION

Models affected

2.4 litre
3.4 litre

A service condition of the body chassis side members (Item 1, Fig 2 in the Repair Manual for Integral Body/Chassis Construction) will, in future, be obtainable from the Jaguar Spares Department.

This assembly is a more suitable condition for repair work and consists of the complete chassis side member back as far as the front mounting point of the rear springs, with all the brackets and reinforcements etc, but less the front jacking bracket.

The part numbers of the "Service condition" chassis side members are as follows:-

471/102 Right-hand
471/103 Left-hand

and comprise -

371/022-3 Member Chassis Side Assy,
less -
171/700-1 Longitudinal Member Rear
371/714-5 Bracket Attachment Front Jacking Tube Assy
371/712-3 Bracket Attachment Rear Jacking Tube Assy
171/702-3 Extension Rear - Chassis side
171/852 Brackets Front Mounting Plate Rear Springs

Index Reference - Section N.

PANEL VALANCE ASSEMBLY - SERVICE CONDITION

Model affected

2.4 litre
3.4 litre

A service condition of the Panel Valance will, in future, be obtainable from the Jaguar Spares Department.

This condition is the panel valance (Item 11 Fig 2) but complete with all the captive nuts which are not included on the production condition. 171/088 Right-hand and 171/089 Left-hand

The part numbers of the "Service Condition" panel valances are as follows:-

471/100 Right-hand
471/101 Left-hand

Index Reference - Section N.

JULY 1957

JAGUAR

SERVICE AND SPARES ORGANISATION

SERVICE BULLETIN NO. 216.

VARIOUS SERVICE ITEMS

HYDRAULIC CHAIN TENSIONER FILTER.

<u>Models affected</u>	<u>Commencing Engine Number</u>
2.4 litre	BC.1884
3.4 litre	KE.2705
Mark V111	N.8252
XK.150	V.1191

On cars with the above engine number and onwards a conical filter gauze (Part number C.13457) is fitted to the oil feed hole for the hydraulic chain tensioner in the cylinder block.

Service Note.

If the hydraulic tensioner is removed for any reason on engines prior to the above numbers a filter gauze can be fitted to the cylinder block. The gauze should be inserted into the hole pointed end first until the ferrule is located by the small shoulder in the hole.

Index Reference - Section B.



RADIATOR GRILLE FRAME AND BONNET TOP MOTIF

<u>Model affected.</u>	<u>Commencing Chassis Numbers</u>	
	R.H. Drive	L.H. Drive
Mark V111.	761116	780870

On cars with the above chassis number and onwards the radiator grille and bonnet top motif are die-cast alloy the previous types being brass.

The part numbers of the relevant parts are as follows:-

	1st Type. (Brass)	2nd Type. (Die-cast)
Radiator grille frame	BD.12294	BD.12745 - J24
Bonnet top motif	BD.12301	BD.14154
Jaguar mascot base.	BD.12717	BD.12253

Index Reference - Section N.

CARBURETTER INSULATING WASHER.

<u>Model affected.</u>	<u>Commencing Engine Number.</u>
2.4 litre	BC.2011

On cars with the above engine number and onwards Carburetter insulating washer Part number C.13562 replaces C.11549.

In future, only the latest type washer will be supplied from the Jaguar Spares Department.

Index Reference - Section C.

Continued.....

REMOVAL OF WAX COATING ON NEW CARS.

Further to Service Bulletin No.196 which gave instructions for the removal of the protective wax coating on new cars, experience has shown that the following procedure is advantageous. The use of paraffin is advised instead of petrol or white spirit (petrol distillate.)

The following procedure should now be adopted:-

1. Place car on wash.
2. Remove all dust and grit by thoroughly hosing down car, using high pressure hose.

NOTE:- Do not dry car.

3. Dissolve wax coating, using paraffin liberally, applied by mutton cloth or similar non abrasive cloth.
4. Dry off car using compressed air only.
5. Polish car in normal way, using liquid polish, not wax polish.

The time required for the complete operation is four hours per car.

Index Reference - Section Q.



WHEEL BEARING ADJUSTMENT

Model affected.
XK.150

Note that on cars fitted with disc brakes the end float of the wheel bearing must be kept to a minimum otherwise the brakes may tend to drag and not function correctly.

The correct end float for both front and rear wheel hub bearings is .003" to .005" (.07 to .13 mm).

Adjustment of the front wheel bearings is by means of the hub nut which should be tightened until there is no end float, that is, when rotation of the hub feels slightly "sticky." The hub nut should be slackened back one castellation and the split pin inserted in the nearest hole.

Adjustment of the rear wheel bearings is by shims between the flanges of the axle tubes and the caliper mounting plates. The normal procedure applies but it will be necessary to remove the brake caliper, brake disc and hub before access to the shims is gained. Installation instructions for the brake assemblies are given in the Disc Brake booklet for the XK.150 model.

Index Reference - Section J. and H.

JULY 1957

JAGUAR

SERVICE AND SPARES ORGANISATION

SERVICE BULLETIN NO.217

VARIOUS SERVICING ITEMS.

OIL FILTER AND BLANKING PLATE - MODIFIED TYPE


<u>Model affected.</u>	<u>Commencing Engine Number</u>
2.4 litre	BC.2256
3.4 litre	KF.3054

On cars with the above engine numbers and onwards a modified type of oil filter is fitted.

The modified type of oil filter has a dome nut to retain the oil pressure relief valve and has a straight outlet adaptor for the hose to the oil sump whereas the previous type of filter had a banjo connection.

The modified blanking plate has a "dimple" formed in the plate to ensure that it cannot be fitted the wrong way round.

The part effected by this change are as follows, the remaining parts are as for the previous type of oil filter C.12532.



<u>Part Number</u>	<u>Description</u>	<u>No. off</u>
C.12776	Oil filter, complete (FA.2720)	1
6884	Canister assembly	1
6886	Pressure plate at bottom of canister	1
6885	Bolt through canister	1
6877	Filter head assembly	1
6882	Outlet adaptor for attachment of hose to oil sump	1
6881	Sealing washer on outlet adaptor	1
6883	Sealing ring between filter head and canister	1
6879	Spring for relief valve	1
6154	Dome nut retaining relief valve spring	1
6880	Washer under dome nut	1
C.12803	Blanking plate between filter head and cylinder block	1
C.13091	Gasket at each side of blanking plate	2
NB.131/15D	Bolt (short) securing oil cleaner to cylinder block	2
C.12861	Hose between oil filter and oil sump	1

NOTE:- Oil filter C.12776 may be used to replace oil filter C.12532 providing the following parts are also changed:-

Fit C.12803 Blanking plate to replace C.12381
Fit C.13091 Gasket to replace C.12177
Fit C.12861 Hose to replace C.12382
Fit NB.131/15D Bolt to replace C.NB.131/11D

Index Reference - Section B.

WINDSCREEN WIPER MOTOR - CHANGE IN TYPE

<u>Model affected.</u>	<u>Commencing Chassis Numbers.</u>	
	<u>R.H.Drive</u>	<u>L.H.Drive</u>
Mark V111	760989	780777
2.4 litre	907359	942311
3.4 litre	970327	986134

On cars with the above chassis numbers and onwards a DR 3 type windscreen wiper motor is fitted replacing the DR.1 type motor.


The part numbers are as follows:-

	<u>Mark V111</u>	<u>2.4 and 3.4 litre</u>	
		<u>R.H.Drive</u>	<u>L.H.Drive</u>
Windscreen wiper motor	C.13501	C.13503	C.13504
Windscreen wiper motor harness	C.13485	C.13492	C.13492

The motor cables should be connected to the lead cables at the snap connectors as follows:-

Green with white tracer to White
 Green with blue tracer to Blue
 Green with brown tracer to Brown
 Green with yellow tracer to Yellow
 Green with red tracer to Red
 Green to Green.

The connections to the two speed wiper switch are as follows:-



<u>Terminal Number</u>	<u>Mark V111.</u>	<u>2.4 and 3.4 litre</u>
	1.	-
2.	Green with blue	-
3.	Green with brown	Green with yellow
4.	Black	-
5.	Green with yellow	Green with brown
6.	Green with red	-
7.	Green with white	-
8.	-	Green with blue
10.	-	Green with white
11.	-	-
12.	-	-
13.	-	Green with red

Index Reference - Section P.

SPARKING PLUGS - CHANGE IN DESIGNATION

Models affected
 All

In the near future Champion sparking plugs will have a simplified type designation. The new designations for sparking plugs fitted to current production vehicles are as follows:-

<u>Old designation</u>	<u>New designation.</u>
L.10 S	L.7
N.8 B	N.8
NA 8	N.5
NA 10	N.3

Note that this is a numbering change only and involves no change in the heat value for individual sparking plugs. Under the new system a lower number indicates a colder plug.

Index Reference - Section B and P.

JULY 1957

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO.219

VARIOUS SERVICING ITEMS


REAR AXLE FOULING BODY

Model affected
3.4 litre.

On the majority of cars prior to chassis number 970592 R.H.Drive and 986301 L.H.Drive there is a possibility that the rear axle cover plate may foul the body giving rise to a knock from the rear of the car under fully laden or full bump conditions.

All cars coming in Distributors and Dealers premises should be examined for signs of the paint having been rubbed off the rear axle cover plate. If fouling is evident carry out the following procedure.

1. Drain the rear axle.
2. Remove the rear axle cover plate and gasket.
3. Modify the rear cover plate in accordance with following sketch. It will be necessary to locally heat the portion to be flattened and when modified the distance to the flange of the cover plate must not be less than $2\frac{3}{4}$ " (70 mm.)
4. Offer up the rear cover plate to the rear axle case without the gasket, and temporarily secure with four setscrews.
5. Check that no fouling occurs between the rear cover plate and the drive gear, by jacking up both rear wheels and rotating in the same direction. Examine the inside of the cover plate for signs of contact.
6. If satisfactory refit cover plate and gasket and replenish with oil.



Index Reference - Sections H. and N.

PANHARD ROD - DETAILS AND ADJUSTMENT.

Model affected

3.4 litre

It should be noted that the Panhard rod tube on the 3.4 litre model is shorter by $\frac{1}{2}$ " (12 mm) than that fitted to the 2.4 litre model owing to a difference in the location of the bracket on the rear axle.

The procedure for the assembly of the panhard rod is as given in Service Bulletin No.203 for the 2.4 litre, but the rod should be adjusted to $14 \frac{3}{16}$ " (36 cm) between the inner faces of the Panhard rod brackets on the rear axle and body.

The part number for the 3.4 litre panhard rod tube assembly is C.12186 the remaining parts are as for the 2.4 litre model.

Index Reference - Section K.

ACCELERATOR PEDAL - HEAVY OPERATION

Model affected

3.4 litre Automatic Transmission

If the accelerator on 3.4 litre Automatic Transmission models is hard to operate the return spring between the governor control lever (at left-hand rear of the transmission unit) and the rear engine mounting cradle should be removed and examined.

If the overall length of the spring is less than $7\frac{3}{4}$ " (19.7 cm) the spring should be discarded and a new spring Part number C.13355 fitted.

At the same time the accelerator linkage should be thoroughly lubricated.

Index Reference - Section M.

AUGUST 1957.

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO. 220


VARIOUS SERVICING ITEMS

OVERDRIVE HYDRAULIC PRESSURE

The following are the working oil pressures for overdrives fitted to the various model and should be referred to when testing the hydraulic pressure as a check for faulty operation of an overdrive unit.

	<u>Pressure</u>	<u>Overdrive unit type</u>
Mark V11	480-500 p.s.i.	28/1270
Mark V111	480-500 p.s.i.	28/1270
XK.140		
Early cars	420-440 p.s.i.	28/1390
Later cars	480-500 p.s.i.	28/1482
2.4 litre	350-370 p.s.i.	28/1369
3.4 litre	420-440 p.s.i.	28/1474
XK.150	480-500 p.s.i.	18/1516

Index Reference - Section F.



BRAKE AND CLUTCH MASTER CYLINDERS - IDENTIFICATION

Models affected
2.4 litre
3.4 litre

The brake and clutch master cylinders are now fitted with an hexagon end plug in place of a circular end plug.

The means of differentiating between the two cylinders remains the same, that is:-

The brake master cylinder has a plain hexagon.
The clutch master cylinder has a groove at each point of the hexagon.

Note that some cars have been fitted with one cylinder having an hexagon end plug and the other a circular end plug.

Index Reference - Section L.


Continued

OIL FILTER ELEMENTS AND SEALING RINGS - SUMMARY

The following is a summary of the oil filter elements and sealing rings (fitted between canister and filter head) for all post-war models.

ELEMENTS

Jaguar Part No.	Tecalemit Part No.	Remarks
1523	FG.2312	1946-8 1½ litre R.H.D.
1527	FG.2346	1946-8 1½ litre L.H.D.
1526	FG.2306	1946-8 2¼/3½ litre Mark V 2½ and 3½ litres 2.4 litre 3.4 litre XK.150
1535	FG.2383	XK.120 up to Eng.No.W.4382
1538	FG.2388	XK.120 for W.4383 and subs Mk.V11 up to Eng.No.B.5304
1550	FG.2421	Mk.V11 for B.5305 and subs XK.140 "C" Type.
6691	FG.2326	"D" Type XK.'SS'



SEALING RINGS

C.1088/W	-	1946-8 1½/2¼/3½ litres Mk V 2½ and 3½ litres
5911	137353	XK.120 Mark V11 up to Eng.No.B.5304
5180	137365	Mark V11 for B.5305 and subs XK.140, "D" Type, XK 'SS'. 2.4 litre up to Eng.No.BC.2255 3.4 litre up to Eng.No.KE.3053
6883	137493	2.4 litre for BC.2256 and subs 3.4 litre for KE.3054 and subs XK.150

Index Reference - Section B.

AUGUST 1957

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO.221

VARIOUS SERVICING ITEMS

ENGINE COMPRESSION PRESSURES.

Models affected

Mark V111
XK.150
2.4 litre
3.4 litre

The following are the compression pressures at starter cranking speed for the current production range of vehicles.

Compression pressures should be taken with all sparking plugs removed, carburetter throttles wide open and engine at normal operating temperature (70° C approx)

<u>7 to 1 compression ratio</u>	<u>8 to 1 compression ratio</u>
125 p.s.i. (approx) (8.79 kg/cm ²)	155 p.s.i. (approx) (10.90 kg/cm ²)

The compression pressures for previous models fitted with the XK type engine are:-

<u>7 to 1 compression ratio</u>	<u>8 to 1 compression ratio</u>
110 p.s.i. (approx) (7.73 kg/cm ²)	120 p.s.i. (approx) (8.44 kg/cm ²)

Index Reference - Section B.

PROCEDURE TO OVERCOME FOULING BETWEEN WATER HOSE AND TIMING COVER SETSCREWS

Model affected

XK.150

Cars affected

Prior to chassis numbers
F.H.Coupe 834380 L.H.Drive
D.H.Coupe 837005 L.H.Drive


In some instances, on left hand drive cars prior to the above chassis numbers, the water hose between the water pump and the metal pipe may be positioned too close to the timing cover with consequent chafing between the hose and timing cover setscrews.

Distributors and dealers are, therefore, requested to examine all XK.150 cars prior to the above chassis numbers, which come into their premises, for adequate clearance between the hose and timing cover setscrews. If insufficient clearance exists the following rectification procedure should be carried out and if chafing of the hose has occurred a new hose (Part number C.12924) must be fitted.

Continued...

Rectification Procedure

Carry out the instructions detailed on the following sketch.



Remove clip and dispense with rubber packing.
Lengthen elongated holes to allow clip to be fitted as far forward as possible.
To allow the metal water pipe to move forward, have the clip securing pipe to front cross-member slackened whilst tightening clip in new position on chassis side member.

Index Reference - Section B.

September 1957.

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO.222

WINDSCREEN WIPER MOTOR - REPLACING TYPE DR1 WITH TYPE DR3.

Models affected.


Mark V11
MK.140
Mark V111
2.4 litre
3.4 litre

See Service Bulletin No.217 for introduction point of DR3 type motor.

As present stocks of DR1 wiper motors become exhausted DR3 motor will be supplied as a service replacement. The DR3 wiper motor and the DR1 motor are similar type units, both being two speed, self-parking wipers, the main difference between the two units being that whereas with the DR1 the mounting pillars are secured to the motor portion, the pillars are cast as part of the gearbox with DR3 units. Therefore a conversion bracket Jaguar Part number 7259 (Lucas Part number 744144) will be necessary with each DR3 replacement which when bolted to the DR3 mounting pillars, will allow the new unit to be fitted as a direct replacement for the DR1 motor.

NOTE:- When replacing the DR1 motor on the 2.4 litre model it will be found that the conversion bracket is not necessary, since the DR3 mounting pillars will fit directly into the holes drilled in the wheel valance after removing the DR1 complete with the original fixing bracket.

Fitting Instructions.

- 
- 1) Disconnect the cables and remove the original motor from the vehicle. To disconnect the crosshead and flexible rack, the circlip (or hexagon nut on earlier DR1 motors) around the gear shaft on the underside of the gearbox should be removed. This will allow the final gear assembly to be partially withdrawn so that the connecting rod can be lifted clear of the crosshead.
 - 2) Remove the gearbox cover and circlip from the replacement DR3. Partially withdraw the final gear assembly and connecting rod, and attach the crosshead to the connecting rod. Push the final gear back into its original position and replace the circlip and gearbox cover
 - 3) Fit the conversion bracket to the motor, and bolt the assembly in position on the vehicle.

Wiring Instructions.



- 1) Cut off the original five connectors from the wiper motor harness, and solder on the five "bullet" connectors.
- 2) Using rubber snap connectors, connect the leads from the DR3 motor to the harness, as illustrated below. (it will be seen from the two circuits that two methods of wiring are involved dependent on whether the vehicle is equipped with a Model PRS5 or PRS7 panel switch.)

Continued....

3) It will be necessary to remove and tape up the green cable feeding the panel control switch, since it is no longer required. (With PR35 switches, the feed cable is connected to terminal 2; with PR37 switches, the feed cable is connected to terminal 8) Using the length of green cable supplied with the replacement motor, connect the green lead from the motor to the "A4" fuse box terminal.

NOTE:- The PR35 type switch is fitted to the Mark V11 and Mark V111 model; the PR37 is fitted to the XK.40, XK.150, 2.4 and 3.4 litre models.

If on testing the wiper it is found that the blades fail to park correctly, the parking position can be corrected by turning the knurled adjusting nut located near the gearbox cable outlet, one or two serrations at a time until the correct position is obtained.



DR3 Motor and PR37 Switch

September 1957

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO.223,

VARIOUS SERVICING ITEMS

DYNAMO SPEED - INCREASE.

<u>Model affected</u>	<u>Commencing Engine Number</u>
Mark V111	N.8974
2.4 litre	BC.2959
3.4 litre	KE.3888
XK.150	V.1599

On cars with the above engine number ^{and onwards} the dynamo speed has been increased by the fitting of a smaller dynamo pulley. The length of the fan belt has been shortened to suit.

The details are as follows:-

	Dynamo Pulley Size	Part Number	Fan Belt Part Number
Mark V111	3"	C.13594	C.13595
3.4 litre	3"	C.13594	C.13595
XK.150	3"	C.13594	C.13595

2.4 litre	3 $\frac{3}{8}$ "	C.13592	C.13593
-----------	-------------------	---------	---------

Index Reference - Section P.

TOP DEAD CENTRE MARKS - LOCATION

Model affected
2.4 litre-Automatic Transmission model
3.4 litre-Automatic Transmission model

On the above models T.D.C. indication is provided at the left-hand side of the converter housing, below the left-hand camshaft cover.

A T.D.C. mark, visible through a hole in the converter housing, is stamped on the converter behind the starter ring gear which should be aligned with the mark scribed on the converter housing and crankcase.

Index Reference - Section B.

Continued

CYLINDER BLOCK - REAR COVER AND SEALING RING

<u>Models affected</u>	<u>Commencing Engine Numbers</u>
2.4 litre	BC.3048
Mark V111	N.9062
3.4 litre	KE.4018
XK.150	V.1631

On cars with the above engine numbers and onwards the cylinder block rear cover (Part number C.2258) and sealing ring (Part number C.2332) are of a modified type.

On the modified type the Allen headed cap screws are inserted from the top instead of from the bottom as on the previous type.

Interchangeability.

As stocks of the earlier type of rear cover and sealing ring are now exhausted, it will be necessary, on all XK type engines prior to the above numbers, to fit both items as an assembly.

Index Reference - Section B.

ANTI-CREEP SOLENOID VALVE

<u>Model affected</u>	<u>Commencing Chassis Numbers</u>	
	<u>R.H. Drive</u>	<u>L.H. Drive</u>
Mark V111	761907	781082
3.4 litre	971141	986771
XK.150	F.H.Coupe 824046	834491
	D.H.Coupe -	837030

On automatic cars with the above chassis numbers and onwards Anti-creep solenoid valve Part No.C.12750 is fitted replacing Part number C.6857.

Solenoid valve Part number C.12750 (Lucas Part number 76502D) is of a larger diameter than C.6857 but the two parts are interchangeable.

Index Reference - Section FF.

Amendment to Service Bulletin No.220

Under the heading "Sealing Ring" delete Tecalemit Part number 137365 and insert Part number 137494.

In the "Remarks" column for Element, Jaguar Part number 1550 add "Mark V111".

In the Remarks column for Sealing Ring, Jaguar Part number 5180 add "Mark V111".

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO.224

VARIOUS SERVICING ITEMS

OVERDRIVE THROTTLE SWITCH - ADJUSTMENT

Model affected

Mark V11 Overdrive models.

Mark V11 cars are fitted with H.D.6 type carburetters which have no throttle adjusting screws it is therefore necessary to adjust the overdrive switch by a different method to that given on page 16 of the Mark V11 Overdrive Service Manual.

The procedure is as follows:-

1. Check that the idling speed of the engine is 500 r.p.m, if not, adjust the slow running by rotating the two volume screws by exactly equal amounts. Switch off engine.
2. Engage top gear.
3. With a screwdriver short out the C1 and C2 terminals on the top relay secured to the wing valance. The overdrive solenoid will then be heard to engage with a click and the manual switch warning light will become illuminated.
4. Slacken the pinch bolt securing the operating lever to the spindle of the throttle switch.
5. By trial and error position the operating lever on the spindle so that when the carburettor spindles are rotated, the full throttle stops on the spindles move approx $\frac{1}{8}$ " before the overdrive solenoid is heard to disengage and the warning light in manual switch goes out.

Index Reference — Section P.

OVERDRIVE THROTTLE SWITCH - ADJUSTMENT

Model affected

JK.150

The throttle switch is located in a bracket situated between the two carburetters.

1. Check that the idling speed of the engine is 500 r.p.m, if not, adjust the slow running by rotating the two volume screws by exactly equal amounts. Switch off engine.
2. Slacken the locknut and screw down the switch until the plunger in the centre of the switch is fully depressed by the lever on which it operates. Tighten the locknut.

Index Reference - Section P.

Continued....

ADJUSTMENT OF REVERSE LIGHT AND STARTER CUT-OUT SWITCH.

Models affected.

2.4 and 3.4 litre Automatic Transmission

On the above models the Starter cut-out and Reverse light switch is situated behind the dash casing and is connected to the manual selector control linkage.

The purpose of the switch to ensure that (i) the starter motor circuit is only operative when the manual selector lever is in the P (Park) or N (Neutral) so that the engine cannot be started when the transmission is in any one of the driving ranges (ii) the reverse light is closed when the manual selector lever is in the R (Reverse) position and the ignition is switched on.

The method of adjustment for the switch is as follows:-

1. Remove dash casing.
2. Raise the boot lid so that the reverse light can be seen through the rear window.
3. Switch on the ignition. Place the selector lever in the R (Reverse) position so that the centre line of lever is in line with the letter R; move lever $\frac{1}{8}$ " - $\frac{1}{4}$ " (3 - 6 mm) towards the L position.
4. Slacken the nut securing the switch bracket to the radio mounting bracket. Move the switch bracket until the reverse light becomes illuminated and tighten the securing nut.

Test the operation of the starter switch with the manual selector lever in the P N and D positions. The starter should operate only when the lever is in the P or N position.

Note:- When testing in the "D" position apply the footbrake firmly.

Index Reference - Section FT.

REAR BRAKE SHOE RETURN SPRINGS.

Model affected

Mark V11

On early Mark V11 cars the return spring (Part number 2515 or GB 41734) at the wheel cylinder end of the rear brake assembly was fitted between a pin in the backplate and the leading shoe. On later cars the return spring is a double formation spring (Part number 6169 or 48185) which is fitted between the leading and trailing shoes.

Interchangeability

The latest type spring can be fitted in place of the early type.

Index Reference - Section L.

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO.225

VARIOUS SERVICING ITEMS

PROCEDURE TO OVERCOME HANDBRAKE COMPENSATOR FOULING BODY

Model affected


- 3.4 litre
- 2.4 litre cars fitted with handbrake compensator

Under full bump conditions there is a possibility that the handbrake compensator fitted to the rear axle may foul the bottom of the luggage boot floor giving rise to a knock from the rear of the car.

Rectification Procedure.

1. Remove the handbrake compensator bracket which is secured by two of the rear axle cover screws.
2. With a hacksaw cut out a $\frac{1}{4}$ " (6 mm) strip of metal to reduce the effective height of the bracket. Weld the two halves of the bracket together. (see sketch).

NOTE: Do not cut more than $\frac{1}{4}$ " (6 mm) from the bracket, or when assembled the cross wires may foul the torque arms.



Index Reference - Section L and N.

Continued...

PRESSURE "BUILD-UP" IN HYDRAULIC SYSTEM

Model affected

Mark V11
Mark V111

A number of complaints of pressure "build-up" in the hydraulic system have been traced to blockage of the breather hole in the brake fluid supply tank filler cap.

Blockage of the breather hole is usually due to an accumulation of brake fluid and dirt on top of the filler cap and is usually indicated by an escape of air pressure when the cap is removed.

Rectification Procedure

1. Clean out the existing breather hole and wash cap in methylated spirits. Lift the spring retainer on the inside of the cap to allow hole to be cleaned.
2. Drill a further $1/16"$ (1.61 mm) diameter breather hole at 90° to the existing breather hole and $3/8"$ (9.5 mm) from the centre of the cap.
3. Obtain a $1/16"$ or $3/64"$ (1.6 or 1.2 mm) split pin and cut off legs to a length of $1/2"$ (12.5 mm). Insert the split pin in the hole from the top and bend the legs at right-angles at $1/8"$ (3 mm) from the bottom of each leg.

Ensure that the split pin is a free sliding fit in the hole.

Index Reference - Section L.



BRAKE SERVO - AIR CLEANER

Models affected

XK.150
2.4 litre cars fitted with disc brakes
3.4 litre cars fitted with disc brakes

On the above types of cars fitted with the large type brake servo ($67/8"$ diameter) an air cleaner is fitted to air intake of the servo.

Maintenance

Every 5,000 miles (8,000 kilometres) the air cleaner should be removed and washed in methylated spirits. After drying out re-lubricate the wire mesh with brake fluid.

Location.

On the XK.150 model the air cleaner is connected directly to the brake servo which is situated in a compartment at the rear of the left-hand front wheel opening.

On the 2.4 litre and 3.4 litre the air cleaner is attached to the right-hand wing valance.

Index Reference - Section L.

September 1957.

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO.226

VARIOUS SERVICING ITEMS

WHEEL BEARING ADJUSTMENT - CARS WITH DISC BRAKES.

Models affected

- 2.4 litre cars with disc brakes
- 3.4 litre cars with disc brakes

Further to Service Bulletin No.216 dealing with Wheel bearing adjustment on the XK.150 model, attention is drawn to the importance of keeping the end-float of the wheel bearings to a minimum, on cars with disc brakes.

In production, the end float of both front and rear wheel bearings will be set at between .003" - .005" (.07 - .13 mm) on both cars fitted with disc and drum brakes.

When setting the end-float in service it is IMPORTANT that on cars fitted with disc brakes the end-float does not exceed .005" (.13 mm).

On cars fitted with drum brakes a wider tolerance of .003" - .008" (.07-.20mm) for the rear wheel bearing end float is permitted.

Index Reference - Section J and K.



INLET VALVE GUIDES - LONGER TYPE

<u>Model affected</u>	<u>Commencing Engine Numbers.</u>
Mark V111	N.8478
3.4 litre	KE.3025
XK.150	V.1281

On cars with the above engine numbers and future, plus certain individual engines prior to these numbers, longer inlet valve guides are fitted.

The details are as follows:-

	1st Type	2nd Type
Length	1 $\frac{1}{2}$ "	1 13/16"
Part Number	C.9867	C.7260

The 2nd type inlet valve guides are interchangeable with the first type in complete sets.

Index Reference - Section B.

REVISED MARKING ON IGNITION COILS

Models affected

All

The markings S. (switch) and CB (contact breaker) for the coil terminals is to be replaced by the positive sign (+) and the negative sign (-).

On positive earth circuits the lead from the distributor must be connected to the + (positive) terminal of the coil and the lead from the ignition switch to the - (negative) terminal.

On negative earth circuits the connections must be the reverse, ie distributor to - (negative) terminal and switch to + (positive) terminal.

Index Reference - Section P.


SILENCERS AND TAILPIPPES

Model affected
3.4 litre

Commencing Chassis Numbers
R.H. Drive L.H. Drive
970877 986554

On cars with the above chassis numbers and onwards modified silencers and tailpipes are fitted:-

The details are as follows:-



	<u>1st type</u>	<u>2nd type</u>
	<u>Part number</u>	<u>Part number</u>
Twin silencer assy	C. 2717	C. 3578
Inner silencer only	C. 13225	C. 13578/1
Outer silencer only	C. 13226	C. 13578/2
Inner tail pipe	C. 2723	C. 13577
Outer tail pipe	C. 2724	C. 13576
Mounting bracket	C. 2725	C. 13609

Interchangeability

The above parts are not interchangeable.

Index Reference - Section M.

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO. 228

VARIOUS SERVICING ITEMS

HANDBRAKE ADJUSTMENT

Models affected.

All cars fitted with disc brakes.

If reasonable travel of the handbrake lever cannot be obtained by following the method detailed in the handbook, the following procedure should be adopted.

Adjust handbrake pads by means of adjuster bolt until a solid contact between the pads and disc is obtained and with the handbrake lever in the full off position, adjust the handbrake cable to eliminate all slack, but ensuring that a tight condition of the cables is not created.

Fully release handbrake pads by means of the adjuster bolt and with a .006" (.15 mm) feeler inserted between the face of one pad and the disc face re-adjust with the adjuster bolt until the feeler is just nipped.

With the handbrake lever in the "off" position rotate the discs and check that the handbrake friction pads are not rubbing.

Index Reference. Section L.

UPPER STEERING COLUMN ASSEMBLY.

<u>Models affected</u>	<u>Commencing Chassis Numbers.</u>	
	R.H. Drive	L.H. Drive.
2.4 litre	908570	942574
3.4 litre	971313	986950
XK.150 F.H. Coupe	824076	834600
XK.150 D.H. Coupe	827001	837071

On cars with the above chassis numbers and onwards a modified upper steering column is fitted. This modification is to provide more positive locking of the steering wheel

The part numbers are as follows:-

	R.H. Drive	L.H. Drive.
2.4 and 3.4 litre.	C.13669	C.13670
XK.150	C.13666	C.13666

Interchangeability. The above numbered upper steering columns are interchangeable with the previous types fitted as complete assemblies.

Index Reference Section I.

OIL PRESSURE. RELIEF VALVE - MODIFIED TYPE.

<u>Model affected.</u>	<u>Commencing Engine numbers.</u>
2.4 litre	BC.3600
3.4 litre	KE.4856
MK.150	V.2011

On cars with the above engine numbers and onwards a modified type of oil pressure relief valve is fitted.

The modification consists of a stop pin part number 7357 fitted in the centre of spring which limits the travel of the oil pressure relief valve. In conjunction with the stop a new relief valve spring (Part number 7315) is fitted. This spring is longer and lighter than the previous type of spring fitted (Part number 6879).

Interchangeability. The new spring (Part number 7315) can be fitted in place of the previous type of spring (Part number 6879) fitted to Oil Filter C.12776 (FA 2720) but the stop pin, must also be fitted. (Part number 7357).

The following table gives the position regarding oil pressure relief valves since the commencement of production of each model:

<u>RELIEF VALVE SPRING Part No.</u>	<u>Free Length</u>	<u>Fitted to Oil Filter</u>	<u>Fitted to Engine Numbers.</u>		
			<u>2.4 litre</u>	<u>3.4 litre</u>	<u>MK.150</u>
6462.	2" (50.8mm)	C.9085 (FA2705) C12532 (FA2705)	BB1001-9000 BB9001-9999 BC1001-2255	KE1001 to 3053	-
6879	1 1/4" (44.5mm)	C12776 (FA2720)	BC2256-3599	KEE3054 to 4855	V1001 to V2010
7315 (and Stop Pin.7357)	2 1/16" (52.4mm)	C.12776 (FA2720)	BC3600 - onwards	KE4856- onwards	V2011 onwards

Index Reference Section B.

TIMING COVER AND SETSCREWS.

<u>Models affected.</u>	<u>Commencing Engine Numbers.</u>
MK.V111	N9460
3.4 litre	KE4580
MK.150	V1921

On cars with the above engine numbers and onwards the five bottom setscrew hole bosses are machined to the same length. The five setscrews are of the same length and setscrew part number NB.137/11D must be fitted at the five lower holes.

On engine prior to the above numbers, one short setscrew NB.137/11D and four longer setscrews NB.137/13D were fitted.

Index Reference Section B.

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO.229VARIOUS SERVICING ITEMSTIMING CHAIN DAMPERS - RUBBER TYPE.

<u>Models affected.</u>	<u>Commencing Engine numbers.</u>
2.4 litre	BC.3699
3.4 litre	KE.4964
XK.150	V.2029
Mark VIII	N.9628

On cars with the above engine numbers and onwards synthetic rubber bonded chain dampers are fitted replacing the nylon type. The part numbers are as follows:-

	3.4 litre, XK.150. Mark VIII.	2.4litre.
Left-hand Damper (Upper chain)	C.13616.	C.13616.
Right-hand Damper (Upper chain)	C.13617.	C.13617.
Distance Piece. 4 off	C.13660.	C.13660.
Intermediate Damper (Upper chain)	C.13615.	-
Damper (Lower chain)	C.13614.	C.13613.

Interchangeability: The rubber type of chain dampers are interchangeable with the previous types fitted.

Index Reference. Section B.

EXHAUST SILENCERS AND DOWNPIPES.

<u>Model affected</u>	<u>Commencing Chassis numbers.</u>	
	R.H.Drive.	L.H.Drive.
3.4 litre.	971503	987132

On cars with the above chassis numbers and onwards the stub pipes at the front of the exhaust silencers (Part numbers C13578/1 and C13578/2) are increased in length by 2" (50 mm). To suit this modification the down pipes are shortened in length by 2" and /1 added to the part number, that is C.12720/1 for the rear pipe and C.12718/1 for the front pipe.

Interchangeability. The latest type of silencers are interchangeable with the previous type fitted from chassis numbers 970877 R.H.Drive and 986554 L.H.Drive, but it will be necessary to cut 2" (50 mm) off each of the down pipes.

Index Reference. Section M.

OIL BATH AIR CLEANER - INTRODUCTION.

<u>Model affected.</u>	<u>Commencing Chassis numbers</u>	
	<u>R.H.Drive.</u>	<u>L.H.Drive.</u>
3.4 litre	971637	987293

On cars with the above chassis numbers and onwards an oil bath air cleaner is fitted as standard. With the introduction of this type of cleaner the carburettor needles are changed from TL to SC.

An oval shaped air silencer, is also fitted across the cylinder head. This silencer is similar in appearance to the previous type of air cleaner but is not fitted with a wire mesh element and is without a detachable end cover. The silencer requires no maintenance.

It is important that only an air silencer is fitted in conjunction with the oil bath air cleaner ; a wire mesh air cleaner must not be fitted.

Maintenance.

The periods at which the following procedure must be carried out will vary according to the conditions under which the car is operated. For normal conditions every 2,500 miles (4,000 kms) can be taken as the proper cleaning periods, but in dusty territories more frequent cleaning, as often as 1,000 miles (1,600 kms) or less, may be necessary.

The cleaner is situated underneath the left-hand front wing and should be completely removed from the car for attention.

Slacken the clip and disconnect the large diameter hose from the cleaner. Slacken the pinch bolt securing the cleaner in the circular retainer and lift out the cleaner complete. Remove the rubber band, unscrew the central screw and withdraw the shell and top cover from the oil base. Lift out filter element, and wash element by swishing up and down in a bowl of paraffin and allow to drain thoroughly. Empty oil from the oil base and clean out the accumulated sludge. Fill oil base with engine oil to the level indicated by the arrow. Ensure that the top cover gasket is in good condition. It is unnecessary to re-oil the filter element as this is done automatically when the car is driven.

Re-insert the centre screw through the shell and top cover and assemble to oil base. Refit rubber band to cover the join between shell and oil base.

Index Reference. Section B and C

BRAKE AND CLUTCH PEDALS.

Models affected.
XK.150.

On earlier XK.150 cars certain of the pedals were made with alternative holes for use as either brake or clutch pedals.

If the master cylinder push rod is disconnected from the pedal it is most important that they are reconnected as follows:-

Brake pedal. - Top hole.
Clutch pedal. - Bottom hole.

Index Reference. Sections L and E.

November, 1957.

JAGUAR

SERVICE AND SPARES ORGANISATION

SERVICE BULLETIN NO.230

VARIOUS SERVICING ITEMS

5 1/2" BRAKE SERVO UNIT - MODIFIED TYPE.

<u>Models affected.</u>	<u>Commencing Chassis numbers</u>	
	<u>R.H. Drive.</u>	<u>L.H. Drive.</u>
2.4 litre cars with drum brakes.	908095	942483
3.4 litre cars with drum brakes.	970948	986592

On cars with the above chassis numbers and onwards a modified Brake Servo Unit Part No. C.13821 is fitted, replacing Servo Unit Part No. C.11000.

The effect of this modification is to introduce an adjustable type of Push Rod and, as the parts affected are all internal (which eliminates the possibility of identifying the revised Unit) a tab is wired to the modified Servo Unit bearing the number 89368.

Interchangeability.

Servo Unit Assembly Part No. C.13821 may be used to replace a Servo Unit Part No. C.11000 fitted prior to the above Chassis numbers but if it is desired to reduce internal items interchangeability is affected and reference should be made to the items listed below.

<u>Servo Unit C.11000</u>		<u>Servo Unit C.13821</u>		<u>Remarks</u>
<u>Part No.</u>	<u>Description</u>	<u>Part No.</u>		
6352	Slave Cylinder Body	7268		Interchangeable, Use modified Cylinder Body
6381	Distance Piece	7265		Not interchangeable
6387	Vacuum Cyl. Piston Assembly	7269		Not interchangeable
6396	End Stop	7270		Not interchangeable
6393	Piston Plate (Outer)	7271		Not interchangeable
6390	Piston Plate (Inner)	7272		Not interchangeable
6389	Locating Washer	7273		Not interchangeable
6388	Push Rod	7274		Not interchangeable
6391	'O' Ring	7142		Not interchangeable
FW.106/T	Backing Washer	7276		Not interchangeable
UPN.137/L	Nut	7277		Not interchangeable
C.741	Shakeproof Washer	7278		Not interchangeable
-	Spring	7266		Additional item
-	Washer	7171		Additional item
-	Circlip	6444		Additional item
-	Adjuster Nut	7275		Additional item
-	Nut	7279		Additional item
-	Gasket	2538		Additional item
6597	Vacuum Cyl. Piston Repair Kit	7280		Not interchangeable

Index Reference Section L.

BRAKE SERVO UNIT - REPAIR KIT.

Models affected.

Mark VII
Mark VIII

A Repair Kit is now available for servicing the Hydraulic Cylinder on Brake Servo Units fitted to Mark VII and Mark VIII models.

Supplies of the Repair Kit may be obtained from Jaguar Spares Department through the Distributor organisation under Part No.7317.

This Kit is additional to the Main Repair Kit (Part No.6995) which is already available for this Servo Unit.

Index Reference. Section L.

CLUTCH MASTER CYLINDER REPAIR KIT.

Model affected.

XK.150

A Repair Kit is available for the servicing of Clutch Master Cylinders on XK.150 models. Repair Kits may be obtained from Jaguar Spares Department through the Distributor organisation under Part No.7012.

Index Reference Section E.

Amendment to Service Bulletin No.224

Under the heading "Overdrive Throttle Switch Adjustment" alter Mark VII under "Model affected" and on the first line to read Mark VIII.

CORRECTION TO 2.4 LITRE SPARES PARTS CATALOGUE (PUBLICATION J.20.)

There has unfortunately been a transposition of Part Nos. on Page 31A of the above publication. The following correction should be made:-

Plate No.AH.5 - The item should read

Part No.6817 Seating Gasket between Element Assembly and Oil Container(1573510)

Plate No.AH.6 - The item should read

Part No.6816 Seating Gasket between Element Assembly and Cover (1579931).

November, 1957.

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO. 231

VARIOUS SERVICING ITEMS

BRAKE FLUID - CHANGE IN SPECIFICATION.

Model affected.

- 2.4 litre cars with drum brakes.
- 3.4 litre cars with drum brakes.

Note that the specification for the Lockheed brake fluid recommended for 2.4 and 3.4 litre cars fitted with drum brakes has been changed from SAE Spec: 70R2 to SAE Spec: 70R1.

Index Reference. Section L.

FRONT WINGS - NOSE SECTION.

Models affected.

XK.140.

A service condition of the XK.140 front wings is now available from the Jaguar Spares Dept., and will be found useful for accident repair where damage is confined to the nose of the wing.

The service condition of the front wing consists of the nose section and includes the headlamp and sidelamp nacelles.

The part numbers are as follows:-

Front wing nose section Left-hand 7319
Front wing nose section Right-hand 7320

Index Reference. Section N.

ENGINE OIL CHANGING - ADVERSE CONDITIONS.

Models affected

All

Under certain adverse operating conditions, conducive to oil dilution and sludge formation, more frequent oil changing than the normal 2,500 mile (4,000 km) period is advised.

Where the car is used mainly for low-speed city driving, stop-start driving particularly in cold weather or in dusty territory the oil should be changed at least every 1,000 miles (1,600 km).

Index Reference. Section B.

CARBURETTOR FLOAT CHAMBER - CLEANING.

Models affected.

Mark VIII
3.4 litre.
XK.150

It has been found that on cars fitted with the MD.6 type of carburettor, blowing out the float chamber with compressed air is likely to cause rupture of the rubber jet diaphragm. This method of cleaning out the float chamber should, therefore, not be resorted to.


Index Reference. Section C.

50 AMP ELECTRICAL FUSES - INTRODUCTION.

<u>Models affected.</u>	<u>Commencing Chassis numbers.</u>	
	<u>R.H.Drive.</u>	<u>L.H.Drive.</u>
2.4 litre	908751	942616
Mark VIII	762263	781141
3.4 litre.	971462	987106
XK.150 F.H.Coupe.	824096	834658
XK.150 D.H.Coupe.	827001	837090

On cars with the above chassis numbers and onwards 50 amp fuses are fitted to certain of the electrical circuits in place of the 35 amp type.

Taking the appropriate Operating Handbook illustration as a guide, fuses are now fitted as follows:-



	<u>Fuse number.</u>					
	1	2	3	4	5	6
Mark VIII	35 amp	35 amp	50 amp	50 amp	-	-
2.4/3.4 litre.	50 amp	50 amp	-	-	-	-
XK.150	50 amp	50 amp	35 amp	35 amp	50 amp	50 amp

If required 50 amp fuses can be fitted to the circuits detailed above, on cars prior to the above chassis numbers.

Index Reference. Section P

RETRACTOR PIN SLEEVES.

Models affected

All cars fitted with disc brakes.

As stated in the Dunlop Disc Brake booklet for the XK.150 model the amount of friction pad wear can be estimated by the amount the retractor pins have receded into the cylinder block - when the ends of the retractor pins are approximately 5/16" (8 mm) below the face of the cylinder block the pads need renewing.

It may be found, however, that some cars are fitted with sleeves around the retractor pins which project above the cylinder block. In this case the sleeves, which are only a taper fit in the cylinder block can be withdrawn with a pair of pliers. The sleeves need not be refitted as they are provided primarily for protection of the retractor pins during transit.

Index Reference. Section L.

J A G U A R
S E R V I C E A N D S P A R E S O R G A N I S A T I O N
S E R V I C E B U L L E T I N N O . 2 3 2

DIVIDED PROPELLER SHAFT ALIGNMENT

Models affected.

- 3.4 litre Automatic Transmission.
- 2.4 litre Automatic Transmission.

The alignment of the divided propeller shaft is most important and if removal of the engine or propeller shafts has taken place the following checks should be made on replacement. Failure to do this may result in Transmission shudder when taking up the drive from a standing start.


NOTE -

Before carrying out any checking or rectification work ensure -

- (a) That the Engine Stabilizer at the rear of the cylinder head is disconnected. To disconnect the engine stabilizer remove the self-locking nut and flanged washer from the top of the stabilizer and screw the lower washer down the centre pin by engaging a thin bladed screwdriver in the slot in the washer through the centre hole of the rubber mounting.
- (b) That the rear engine mounting rubbers are not distorted. Note that the holes in the rear engine mounting cradle are slotted and the holes in the bracket attached to the extension case are enlarged to allow the positions of the rubbers to be adjusted.

Check 1.

Check the distance from the bottom of the front flange of the front propeller shaft to the bottom faces of the longitudinal chassis side members. This distance should be $3.11/16" \pm 1/16"$ ($93.5 \text{ mm} \pm 1.5 \text{ mm}$). A simple checking jig can be made for checking this distance as shown in the following sketch.



Remedy

If the propeller shaft flange is too LOW suitable packings can be fitted between the rear engine mounting rubbers and the mounting brackets at the top or bottom of the rubbers.


If the propeller shaft is too HIGH suitable packing can be fitted between the rear engine mounting cradle and the body floor.

Check 2.

Check that the front and rear propeller shafts are in a straight line in the horizontal plane.

Cont'd.....

The most convenient way to do this is to make up a simple jig as shown in the following sketch. The jig consists of 3 pieces of flat bar 8" x 1" x 3/16" (20.5 cm x 2.5 cm x 4.75 mm) which are welded exactly in line on to a piece of tube of 1 1/8" (28.5 mm) outer diameter at the distances shown in the sketch. The jig is then held against the front and rear propeller shafts, with the three bars vertical, when any malalignment will be evident.



An alternative method is to use three plumb bobs and sight along the three cords. Two cords should be positioned at the front and rear of the front propeller shaft tube and the remaining cord at the rear end of the rear propeller shaft tube.

Remedy.

Alignment of the propeller shafts is carried out at the centre bearing bracket by elongating the two holes through which the setscrews pass to secure the bracket to the body floor. The position of the centre bearing bracket can then be adjusted to allow the propeller shafts to be aligned.

Adjustment of Engine Stabilizer.

After having carried out the work and tightened up the rear engine mounting adjust the stabilizer as follows:-

1. Screw the lower flanged washer up the stabilizer pin until the flange contacts the bottom of the stabilizer rubber mounting. The washer is slotted on its upper face and can be screwed up the pin by engaging a thin bladed screwdriver in the slot through the centre hole of the rubber mounting.
2. Fit the upper flanged washer and tighten down with the self-locking nut.

Failure to observe the above procedure may cause engine vibration and/or fouling of the gearbox in the cowl owing to the engine being pulled up on its mountings.

Index Reference Section G.

January, 1958.

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO. 234

SPARE PARTS CATALOGUE.
(Publication J.22).

Model affected.

3.4 litre.

Some confusion appears to exist regarding the ordering of spares details from the 3.4 litre Spare Parts Catalogue. Orders are being received by Jaguar Spares Department for items which are peculiar to cars fitted with Overdrive Unit or Automatic Transmission and the part numbers for such items are being taken from the above publication.

Will all Distributors and Dealers please note that the 3.4 litre Spare Parts Catalogue, in its present form, is intended to be used for cars fitted with Standard Transmission as has been the practice in previous Spare Parts Catalogues (e.g. Mark VII, XK.140, 2.4 litre) whilst details of items used for Overdrive or Automatic Transmission models have been the subject of separate Catalogues (e.g. Publications J.18 and J.19). In due course, an amendment will be published to incorporate in Publication J.22 those items which are used only when 3.4 litre cars are fitted with Overdrive Unit or Automatic Transmission.

In the meantime, the part number should be omitted from orders for such items as Propeller Shaft, Speedometer, Speedometer Cable, Carpets, Gearbox Cover and, in the case of stock orders, these items should be clearly marked on the order "For Overdrive Unit" or, alternatively, "For Automatic Transmission". If these parts are required for an individual car, it will suffice if the Chassis number is quoted, providing the suffix letters "DN" or "BN" (whichever applies) are quoted after the Chassis number.

Index Reference. Section 3.

JAGUAR
SERVICE AND SPARES ORGANISATION

SERVICE BULLETIN NO.235
VARIOUS SERVICING ITEMS

COLD STARTING IN EXTREME CONDITIONS - MODIFICATION.

Model affected.

2.4 litre

Where difficulty is experienced with starting from cold in extreme conditions, that is, temperature consistently in the region of - 15°F (-26°C) the following alterations can be carried out to the Solex carburetters.

- (i) Remove the GS.105 Starter Petrol Jet and fit a GS.135 jet (This jet is Item 20 Plate G in the 2.4 litre Spare Parts Catalogue).
- (ii) Remove the GA.4.5 Starter Air Jet (Item 19 Plate G in the 2.4 litre Spare Parts Catalogue), and leave the hole in the carburetter open.

Note: The above settings must only be used when extreme cold conditions in the region of -15°F (-26°C) prevail and when normal conditions return the standard starter petrol jet and starter air jet must be refitted.



Index Reference. Section B and C.

REAR SPRING MOUNTING MODIFICATION

Model affected.

2.4 litre
3.4 litre

It should be noted that the modification to the rear spring mounting as detailed in Service Bulletin No.210 was carried out in production from the following approximate chassis numbers:-

	<u>R.H.Drive</u>	<u>L.H.Drive</u>
2.4 litre	906119	941878
3.4 litre	Commencement of production	

At a later date a different modification was incorporated which did not include the Support brackets C.12779 as shown in Service Bulletin 210, and we understand that in some cases it has been assumed that the rear spring mounting has not been strengthened.

It will be appreciated therefore that the absence of the Support brackets welded between the rear spring clamp and the channel is now no indication that this part has not been strengthened.

Index Reference. Section W.

Cont'd.....

SERVICE BULLETIN NO.235 CONT'D.

THERMOSTAT - MODIFIED TYPE

Models affected.

Mark VIII
2.4 litre
3.4 litre

Commencing Engine numbers.

NA.1076
BC.4408
KE.5733

On cars with the above engine numbers and onwards a modified Thermostat Part number C.13944 is fitted replacing Thermostat C.3731/1.

To suit this change the bore in the water outlet pipe to take the thermostat has been increased in diameter by .010" (.25 mm) and the part numbers changed as follows:-


2.4 litre.	C.14134 replaces C.11533
3.4 litre and Mark VIII	C.14133 replaces C.12439

Interchangeability.

The new thermostat C.13944 must not be fitted in place of Thermostat C.3731/1 (that is, to cars prior to the above engine numbers) as there is a possibility of the movement of the thermostat being restricted in the smaller bore water outlet pipe.

Thermostat C.3731/1 can be used to replace C.13944 on cars on and after the above engine numbers if the latter type is not available.

Identification.



Index Reference. Section B and D.

VACUUM BRAKE SERVO KIT.

Model affected.

XK.140

For XK.140 owners who would prefer less effort to operate the brake pedal a servo kit is now available from the Jaguar Spares Department under Part number 7076.

Detailed instructions for carrying out this modification to the Fixed Head Coupe Model are included with each kit.

The details for the Open 2 seater and Drop Head Coupe models are similar to those for the Fixed Head Coupe Model except that on the side to which the servo unit is fitted, that is the steering column side, there is no battery compartment. It will therefore be necessary to make up a shield to protect the servo from mud thrown up from the road wheel, instead of the box described and illustrated in the instructions.

Index Reference. Section L.

Amendment to Service Bulletin No.233.

Under the heading "Multiple Disc Clutch" on page 1 delete the line:-

9 retractor springs (J20-348) are fitted instead of 12.

January, 1958.

JAGUAR

SERVICE AND SPARES ORGANISATION

SERVICE BULLETIN NO.236

DISC BRAKES AND WIRE SPOKE WHEELS-CONVERSION
KITS.

Models affected.

- 2.4 litre
- 3.4 litre

For customers who purchased cars just prior to the introduction of Disc brakes and Wire spoke wheels as optional equipment and who may have expressed a desire to have their cars converted, the above kits are now available from the Jaguar Spares Department. Instructions for carrying out these conversions will be included with each kit.

Requests for these kits should be made on a separate order form and the following particulars given:-

- Model - 2.4 litre or 3.4 litre.
- Right - hand or Left - hand Drive.
- Chassis number of vehicle (if possible).

FOR CONVERTING DRUM BRAKES TO DISC BRAKES ONLY



Requirements:-

Kit A (Part number 7389)

plus items listed below to suit the particular model.

	<u>2.4 litre</u>	<u>3.4 litre</u>
Handbrake compensator assembly R.H.Drive	C.13873	C.13875
L.H.Drive	C.13874	C.13876
Vacuum Check Valve	C.12790	-
Vacuum check mtg. plate	C.12798	-
Sleeve nut	C.12799 (2 off)	-
Bolt	UFS.125/7R (2 off)	-
Setscrew	UFS.125/5R (2 off)	-
Plain washer	FW.105/T (2 off)	-
Spring washer	FG.104/X (4 off)	-
Nuts	NN.125/L (2 off)	-
Vacuum pipe	C.13963 (1 off)	-
Vacuum pipe	C.13962 (1 off)	-
Hose - check valve	C.13964 (2 off)	-
Hose	C.14135 (1 off)	-
Hose	C.13965 (1 off)	C.13704
Adaptor plate	-	C.13254

Cont'd.....

FOR CONVERTING DRUM BRAKES TO DISC BRAKES
AND DISC WHEELS TO WIRE SPOKE WHEELS.

Requirements:-

Kit B (Part number 7390)
Kit C (Part number 7391)

plus items listed below to suit the particular model.

	<u>2.4 litre</u>	<u>3.4 litre</u>
Handbrake compensator assembly R.H.Drive	C.13873	C.13875
L.H.Drive	C.13874	C.13876
Vacuum Check Valve	C.12790	-
Vacuum check mtg. plate	C.12798	-
Sleeve nut	C.12799 (2 off)	-
Bolt	UFB.125/7R (2 off)	-
Setscrew	UFS.125/5R (2 off)	-
Plain washer	FW.104/T (2 off)	-
Spring washer	FG.104/K (4 off)	-
Nuts	IM.125/L (2 off)	-
Vacuum pipe	C.13963 (1 off)	-
Vacuum pipe	C.13962 (1 off)	-
Hose - check valve	C.13964 (2 off)	-
Hose	C.14135 (1 off)	-
Hose	C.13965 (1 off)	C.13704
Adaptor plate	-	C.13254



FOR CONVERTING FROM DISC WHEELS TO WIRE SPOKE WHEELS ONLY

Requirements:-

Kit C (Part number 7391)

PRICES.

Retail Price.

Kit A (Part number 7389) (including the individual items required)	£100
Kit B (part number 7390) (including the individual items required)	£80
Kit C (Part number 7391)	£83

Extras

Fully chrome wire wheels - extra cost per wheel £7. 19. 6d.

2.4 Litre model only.

If converting from disc wheels to wire spoke wheels it will be necessary to fit the following additional parts:-

5 inner tubes (if existing tyres are tubeless type)	£1. 8. 0d. each
2 rear wheel valances (cut-out type)	£4. 2. 0d. each

Index Reference. Section L. and M.

FOR CONVERTING DRUM BRAKES TO DISC BRAKES
AND DISC WHEELS TO WIRE SPOKE WHEELS.

Requirements:-

Kit B (Part number 7390)
Kit C (Part number 7391)

plus items listed below to suit the particular model.

	<u>2.4 litre</u>	<u>3.4 litre</u>
Handbrake compensator assembly R.H.Drive	C.13873	C.13875
L.H.Drive	C.13874	C.13876
Vacuum Check Valve	C.12790	-
Vacuum check mtg. plate	C.12798	-
Sleeve nut	C.12799 (2 off)	-
Bolt	UFB.125/7R (2 off)	-
Setscrew	UFS.125/5R (2 off)	-
Plain washer	FW.104/T (2 off)	-
Spring washer	FG.104/K (4 off)	-
Nuts	IM.125/L (2 off)	-
Vacuum pipe	C.13963 (1 off)	-
Vacuum pipe	C.13962 (1 off)	-
Hose - check valve	C.13964 (2 off)	-
Hose	C.14135 (1 off)	-
Hose	C.13965 (1 off)	C.13704
Adaptor plate	-	C.13254



FOR CONVERTING FROM DISC WHEELS TO WIRE SPOKE WHEELS ONLY

Requirements:-

Kit C (Part number 7391)

PRICES.

Retail Price.

Kit A (Part number 7389) (including the individual items required)	£100
Kit B (part number 7390) (including the individual items required)	£80
Kit C (Part number 7391)	£83

Extras

Fully chrome wire wheels - extra cost per wheel £7. 19. 6d.

2.4 Litre model only.

If converting from disc wheels to wire spoke wheels it will be necessary to fit the following additional parts:-

5 inner tubes (if existing tyres are tubeless type)	£1. 8. 0d. each
2 rear wheel valances (cut-out type)	£4. 2. 0d. each

Index Reference. Section L. and M.

March, 1958.

JAGUAR

SERVICE AND SPARES ORGANISATION

SERVICE BULLETIN NO. 241

MODIFICATION TO CIRCULAR HANDBRAKE CROSS CABLES FOULING BODY.

Models affected.

- 2.4 litre cars fitted with disc brakes
- 3.4 litre cars fitted with disc brakes

If complaints are received of the handbrake cross cables fouling the rear wheel arch when the car is heavily laden, the following modification can be carried out on a guarantee basis.

This modification was introduced in production at the following chassis numbers:-

	<u>R.H. Drive.</u>	<u>L.H. Drive.</u>
2.4 litre	910118	942854
3.4 litre	972401	988216

Parts required.

7492	Inner pad carrier assembly. Right hand	1
7493	Inner pad carrier assembly. Left hand	1
7494	Operating Lever	2
6926	Clevis pin	2
J.105/11.5S	Clevis pin	2
FW.105/T	Plain washer	2
L.102/4U	Split pin	2
L.103/7U	Split pin	2
6925	Setscrew securing Handbrake to Caliper	2
6932	Tab washer	2
C.13871	Handbrake cross cable	1
C.13872	Handbrake cross cable	1

Handbrake Compensator Bracket -
as detailed below for various models.

C.14258	2.4 litre - Right hand drive	1
C.14259	2.4 litre - Left hand drive	1
C.14260	3.4 litre - Right hand drive	1
C.14261 14261.	3.4 litre - Left hand drive	1
7481	Luggage compartment floor-patch plate	1

Modification to Caliper Handbrake.

It is necessary to replace each inner pad carrier and lever with the modified type supplied.

Disconnect the handbrake cross cable from the handbrake lever.

Unscrew the adjuster bolt completely to separate the inner and outer pad carriers.

Tap back the tab washers and remove the setscrew securing the inner pad carrier to the caliper.

Remove the inner pad carrier. When fitting the new carriers note that they are handed; the top end of the friction pad should conform with the periphery of the brake disc.

Cont'd.....

Fit the new inner pad carrier to the caliper using a new tab washer and setscrew if necessary. Lubricate the setscrews with zinc base grease on assembly. Attach the handbrake lever to the inner pad carrier as follows:-

Place the lever against the inner carrier. Hold the locknut firmly against the outer face of the trunnion and screw in the adjuster bolt until three or four threads engage the locknut.

Align the holes in the lever and pivot seats, fit the pivot pin and lock it with the split pin.

Note: The above procedure is described and illustrated under "Relining the Handbrake" in Disc Brake Descriptive and Maintenance Notes for the XK.150 model.

Do NOT fit the pivot pin connecting the lever to the inner pad carrier until the adjuster bolt has been screwed a few turns into the locknut otherwise the return spring will not be preloaded.

Repeat for the other rear brake.

Fitting the modified Compensator Bracket.

Disconnect the fork end at the front end of the handbrake cable.

Remove the self-locking nut which secures the handbrake compensator to the bracket attached to the rear axle. Remove the two setscrews securing the bracket to the rear axle. Replace the existing bracket with the modified type supplied.

Secure the bracket to the rear axle with the existing setscrews and attach the compensator to the bracket.

Fit the two cross cables supplied so that the fixed fork ends are connected to the compensator on the rear axle.

Adjust the handbrake and handbrake cables as follows:-

Screw in the handbrake adjuster bolt at each rear brake until the handbrake pads are in hard contact with the brake discs.

Fully release the handbrake lever. Remove the clevis pin securing the fork end to the operating link at the front of the main cable. Slacken the locknut and adjust the position of the fork end so that with the clevis pin refitted there is no slack in the main cable and the two cross cables. It is, however, important to ensure that the cables are not under tension.

Unscrew the adjuster bolt and insert a .004" (.10 mm) feeler gauge between the face on one handbrake pad the disc. Screw in the adjuster bolt until the feeler gauge is just nipped. Withdraw feeler gauge and check disc for free rotation. Repeat for the other side.

Modification to Luggage Compartment Floor.

To provide adequate clearance for the handbrake compensator in its new position it is necessary to cut out one of the longitudinal depressions in the trunk floor and weld in the patch plate provided.

It will be noted that there are six depressions in the trunk floor; for Left hand drive cars the patch plate should be fitted to the **third** depression from the left and for right hand drive cars the patch plate should be fitted to the third depression from the right - see sketch.

Using the patch plate as a template mark out the portion to be cut out. Cut out the portion marked so that when the plate is welded in position it will be flush with the surrounding metal.

Cont'd.....


If there is already a small patch plate welded in the depression this can be cut out to allow the patch plate supplied to be fitted.

Note: On Right-hand drive cars it will facilitate the use of a hacksaw if the spare wheel cover plate and spare wheel are removed.


Modification to Wheel Arch.

The flange of the chassis side member should be knocked back with a mallet flush with the box section as illustrated in the following sketch.


Note: It is IMPORTANT to carry out the above two body modifications otherwise fouling will take place between the handbrake compensator and trunk floor, and also between the handbrake cross cables and the wheel arches.



Position for Left-Hand Drive Cars



MODIFICATION TO WHEEL ARCH.



Existing Condition.

New Condition.

Index Reference. Sections L and N.

J A G U A R

S E R V I C E A N D S P A R I S O R G A N I S A T I O N

S E R V I C E B U L L E T I N N O . 2 4 6 .M O D I F I C A T I O N T O D I S C B R A K E M A S T E R C Y L I N D E R .Models affected

- 2.4 litre cars fitted with disc brakes.
- 3.4 litre cars fitted with disc brakes.
- XK.150 cars fitted with disc brakes.

To deal with cases where a long brake pedal action is sometimes experienced on the first application of the brake pedal when the car has been standing, but normal pedal action is obtained on the second action of the pedal the following modification has been introduced in production commencing with chassis numbers:-

	<u>Right-hand drive</u>	<u>Left-hand drive.</u>
2.4 litre	910970.	943035.
3.4 litre.	973377.	988746.
XK.150 Open 2 seater.	-	830438.
XK.150 Drop head coupe.	827072.	837434.
XK.150 Fixed head coupe.	824420.	835566.

and certain individual cars prior to these numbers.

IDENTIFICATION

Externally the Master Cylinder remains unchanged but is identified by a cable clip bearing the following relative new part numbers, fitted to the barrel of the Master Cylinder between the flange fitting and the outlet boss.

XK.150.	0.14580	(VBM 3248)
2.4/3.4 litre.	0.14579	(VBM 3249)

INTERNAL MODIFICATION

The following parts become redundant:-

Part Number.

6950	Seal	Item 9, Plate C on page 21 of the Dis Brake Spare Parts Catalogue.
6949	Bush	Item 10, " " " "
6952	Valve	Item 7, " " " "
6941	Spring Support	Item 6, " " " "

and are replaced by the following new parts:-

Dunlop Part Number.

VBO 3541	Seal
VBO 3539	Valve
VBO 3540	Spring Support

Note: A separate bush for the seal is no longer used. The drawings on the next page show the difference between the old and the new parts. The differences between the old and new parts are easily recognisable except in the case of the spring supports between which there is no visible difference. The old type spring support must not, in any instance, be refitted.

Cont'd....


INSTRUCTION FOR MODIFYING THE MASTER CYLINDER

(Refer to Plate C on page 21 of the Disc Brake Cores Catalogue)


- (1) Withdraw the dust excluder (14) at the push rod end of the master cylinder and with suitable liners remove the circlip (13).
- (2) Remove the push rod (11) and the washer (12).
- (3) Withdraw all internal components and dismantle the assembly comprising items (4) to (8) inclusive by disengaging the valve (7) via the key slot in the spring support (5).
- (4) Discard the valve seal (9), bush (10), valve (7), rear end spring support (6) and 'O' ring (3).
- (5) Clean the cylinder body and all remaining components with methylated spirit or hydraulic brake fluid. Examine the cylinder bore for damage and scoring. If there is evidence of these defects the master cylinder must be replaced by a new unit.
- (6) Using the new components (6), (7) and (9) shown in the sketch below reassemble items (4) to (9) inclusive in the order shown and retain them by engaging the valve (7) in the central bore of the spring support (5). **NOTE:** The old and new spring supports item (6) are almost identical in appearance but it is essential that only the new support is used for this modification.
- (7) Lubricate the new 'O' ring (3) with hydraulic brake fluid and fit it to the piston (2).
- (8) Slide the internal components into the bore of the cylinder body, position the washer (12) and the push rod (11) and retain them with the circlip (13).
- (9) Fill the dust excluder with the special Dunlop rubber grease provided in the modification kit. **NOTE:** No other grease must be used for this purpose. Reseat the dust excluder around the end of the master cylinder, ensuring that the lip registers properly in the groove.
- (10) Fit the appropriate identification clip around the master cylinder body, at a point between the attachment flange and the connection bosses.



OLD PARTS.



NEW PARTS.



SERVICE ACTION - EXPORT

All Distributors will be supplied with a small stock of modified Master Cylinders -

Part Number.

C.14580	UK.150.
C.14579	2.4 litre/3.4 litre

together with a supply of Master Cylinder Repair Kits Part Number 7660.

In every case when a report of long pedal action after standing is received the Master Cylinder is to be changed immediately for the modified type.

It is also considered desirable that all Master Cylinders of the original type not having a cable clip bearing the new part number should be changed as soon as is practicable. This operation is to be carried out on a guarantee basis irrespective of the age of the car.

The Distributor must withdraw from his Dealers all stocks of the following Master Cylinders -

Part Number.

C.13100 and C.14224	UK.150.
C.13675 and C.14225	2.4/3.4 litre.

and proceed as follows:-

1. All Master Cylinders having an aluminium body (Part numbers C.13100 and C.13675) are to be scrapped and a claim submitted for these units.
2. All Master Cylinders having a cast iron body (Part numbers C.14224 and C.14225) are to be reconditioned by the Distributor incorporating the modified parts included in Master Cylinder Repair Kit Part number 7660 which contains:-

	<u>Dunlop Part Number</u>
Dust Excluder	VBO.1869
'O' Ring	VBO.2417
Valve	VBO.3539
Seal	VBO.3541
Spring Support	VBO.3540
Tube of Rubber grease	VBO.3554
Identification Cable clip	VBO.3552 and VBO.3553
Fitting Instruction Sheet	-

Spare Parts Replacement

All stocks of the following parts held by Dealers are to be returned to their Distributor for credit.

Part Number.

6950	Seal
6949	Bush
6952	Valve
6941	Spring Support

These parts, or the new parts that replace them, will no longer be supplied as individual replacements parts. The new parts will form part of a new Master Cylinder Repair Kit - Part number 7660.

The Distributor is to scrap out these parts including their own stocks and submit a guarantee claim for the parts scrapped.

(3)

Cont'd....

J A G U A R
S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO. 261

BRAKES - MAINTENANCE AND RECTIFICATION

IMPORTANT

The following information is given to ensure more satisfactory brake maintenance and to simplify the handling of complaints.

Contents

	Page
Brake Maintenance	1
Brake Fluid Level	1
Long Pedal Travel - Rectified by Bleeding Brakes	2
Long Pedal Travel - Self Rectified When Car Has Been Standing	2
Long Pedal Travel on Road and When Stationary - Not Corrected by Bleeding	3
Long Pedal Travel on Road but Normal Pedal Travel When Stationary	3
Excess Braking on Front Wheels	4
Brakes Hanging on	4
Brakes Pulling, Locking or Knocking on Brake Application ...	4
Whistle from Engine	4

BRAKE MAINTENANCE

1. Ensure that only the brake fluids specified in Service Bulletin No. 242 are used.
2. Check the brake fluid level in the Reservoir on every occasion a customers car is in your hands for service and if the level is low investigate as detailed below.
3. Check for brake lining or friction pad wear whenever you carry out regular maintenance service and advise the owner if re-lining is necessary immediately or in the near future.
4. Fully bleed the hydraulic system and refill with new brake fluid whenever a brake re-line or overhaul is carried out.
5. Check the condition of the rubber brake hoses and the rubber servo hose connections when carrying out a brake re-line or overhaul.

RECTIFICATION

BRAKE FLUID LEVEL

If the brake fluid level in the reservoir is found to be low always make a careful check to find out WHY before topping up.

There will be a progressive reduction in level consistent with lining or pad wear due to the increased fluid volume contained in the wheel cylinders but if the fluid level has dropped to any extent carefully check the following points for fluid loss.

1. Push rod end of brake master cylinder.

If any trace of fluid is found on the push rod, pull back the rubber boot and observe whether there is evidence of brake fluid leaking past the master cylinder piston seal. If this condition exists fit a replacement master cylinder or overhaul the existing unit.

2. Apply and maintain full pressure at the brake pedal and carefully examine all brake connections and wheel cylinders for fluid loss. Note in the case of drum brake cars, when checking the wheel cylinders, pressure at the pedal should be maintained for some minutes and the drums then removed for inspection of the wheel cylinders.

If when pressure is maintained on the brake pedal the pedal progressively sinks, examine all connections and wheel cylinders and if no fluid loss is found, the loss of pressure should be traceable to the master cylinder recuperation seal or main seal. Fit a replacement master cylinder or overhaul the existing unit. Fully bleed the system and repeat the above pressure check.

If low fluid level is found and the foregoing checks do not reveal reason for fluid loss but fluid level is low enough to suggest loss is definitely occurring, measure the fluid level in the reservoir. Leave car standing without engine being run for 12/24 hours and re-check level. If level has dropped, remove brake servo (without having re-started engine) dismantle servo and examine for evidence of brake fluid having entered the servo vacuum cylinder or the servo operating valve chamber. If brake fluid is found, fit a replacement servo or replace all the seals in the servo unit.

LONG BRAKE PEDAL TRAVEL - RECTIFIED BY BLEEDING BRAKES

This complaint can only be due to air getting in the hydraulic system. If you deal with a car on which the brake pedal has to be pumped when the car is stationary to obtain a normal brake pedal action but bleeding the system produces normal brake pedal action, do not release the car until you have traced the reason for air getting into the hydraulic system.

Possible causes are:-

- (a) Air entry past servo piston rod seal (for Mark VII and Mark VIII Clayton-Dewandre servos see Service Bulletin No.260)
- (b) Air entry past servo plunger seal.
- (c) Air entry past wheel cylinder seals.
- (d) Air entry past master cylinder main seal (in this case bleeding will probably be difficult).
- (e) Air in hydraulic system due to brakes having being overheated and the fluid vapourised.

LONG PEDAL TRAVEL - SELF RECTIFIED WHEN CAR HAS BEEN STANDING

This complaint arises due to severe overheating of the brakes and boiling of the brake fluid - self rectified when fluid cools, and can be due to:-

- (a) Servo vacuum piston not fully returning and in this case all four brakes will show signs of having being overheated.
- (b) Insufficient free movement on master cylinder push rod, again all four brakes with show signs of overheating.
- (c) Automatic Transmission cars only.
Fault in anti-creep pressure switch (at rear of transmission unit) holding rear brakes on. Rear brakes only will show signs of overheating.
- (d) Car has been driven with hand brake on - rear brakes only will show signs of overheating.

Note: In the event of the brakes having been overheated the wheel cylinder piston seals should be examined. In the case of disc brake cars overheating of the wheel cylinder piston seals will result in loss of interference and long pedal action ON ROAD

LONG PEDAL TRAVEL ON ROAD AND WHEN STATIONARY - NOT CORRECTED BY BLEEDING

This complaint is only likely to occur on drum brake cars for the following reasons:-

Girling Brakes (Mark VII and Mark VIII)

- (a) Rear brakes not in adjustment.
- (b) No friction between front brake self adjuster friction pads and brake shoe webs.
- (c) Front brake shoes incorrectly set up relative to drums (see Service Bulletin No.256), or drums badly out of round.

Lockheed Brakes

- (a) Rear brake self adjusters not operating. (2.4/3.4 litre only)
- (b) Front brake self adjuster ratchet broken and/or no friction on self adjustment friction pads.
- (c) Front brake shoes incorrectly set up relative to drums or drums badly out of round.

LONG PEDAL TRAVEL ON ROAD BUT NORMAL PEDAL TRAVEL WHEN STATIONARY

Disc Brakes

- (a) Excess play in front hub bearings.
- (b) Excess end float of rear axle shafts.
- (c) Excess run out on discs.
- (d) Shake back on wheel cylinder pistons (due to insufficient interference between piston seal and wheel cylinder bore - see note under heading "Long pedal travel - self rectified when car has been standing")

Note: If excess disc run out is found check the hub flanges for run out and for dirt between the hub flange and disc mating faces.

Also note when checking Mark LX rear discs for run out or when setting the calipers relative to the discs, the disc should be securely bolted to the hub flange using suitable distance pieces under the wheel nuts.

Lockheed Drum Brakes

- (a) Insufficient friction or broken ratchet on front brake self adjusters.

/Cont'd...

- (b) Hydraulic check valve in end of servo (Part No.6466) not maintaining residual line pressure.

Girling Drum Brakes

Insufficient friction on front brake self adjuster friction pads.

Heavy Pedal Action - (sometimes wrongly described by owners as fade).

1. Servo connecting hose-vacuum pipe to inlet manifold take off - collapsed.
2. Vacuum check valve stuck or incorrectly assembled.
3. Servo performance low - sluggish piston or no interference between piston leather and vacuum cylinder.
4. Long brake pedal travel resulting in maximum servo point being passed before full braking effort obtained. (see foregoing paragraph on Long Pedal Travel).

EXCESS BRAKING ON FRONT WHEELS

Disc Brake Cars

Rear brake pads sticking in calipers (check by inserting feeler gauge between pad and disc and note if the feeler is nipped when the brakes are applied).

Drum Brake Cars

- (a) Rear wheel cylinder seized. (b) Rear brake shoes fitted incorrectly.

BRAKES HANGING ON

- (a) Brakes drag on all four wheels and do not release when the engine is switched off - Servo piston sticking in vacuum cylinder.
- (b) Brakes drag on all four wheels but release when engine is switched off - Servo plunger valve sticking.

BRAKES PULLING, LOCKING OR KNOCKING ON BRAKE APPLICATION

The above complaints can be due to:-

(a)

Disc Brake Cars

Slackness of the bolts securing the brake caliper and/or the bolts securing the caliper adaptor plate to the stub axle carrier or rear axle flange.

Drum Brake Cars

Slackness of the bolts securing the brake backplate to the stub axle carrier or the rear axle flange.

- (b) Grease or oil on the friction pads - clean off grease or oil from the brake disc with petrol or trichlorethylene.
- (c) On the Mark VII, Mark VIII and Mark IX models slackness of the bolts securing the lower wishbone brackets to the chassis frame. Slackness of the rear spring 'U' bolts.
- (d) On the 2.4/3.4 litre models, slackness of the rear spring centre bolts.

WHISTLE FROM ENGINE

An elusive whistle noticed at approximately 1200 r.p.m. on a small throttle opening but not reproduced when car is stationary or coasting in neutral with engine switched off will be traced to an air leak at the servo diaphragm chamber joint face (Lockheed 6 $\frac{7}{8}$ " Servo only)

Index Reference

Section L. ✓

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO.238
VARIOUS SERVICING ITEMSDISC BRAKE MASTER CYLINDER BODY - CHANGE IN MATERIALModels affected.

XK.150
2.4 litre cars with disc brakes
3.4 litre cars with disc brakes

Cars fitted with disc brakes now in production have a cast iron master cylinder body replacing a body made from aluminium. In conjunction with this change an unhardened piston is fitted to the master cylinder.

The relevant part numbers are as follows:-

	2.4 litre	XK.150
	3.4 litre	
Brake Master Cylinder Assembly.	C.14225	C.14224.
Master Cylinder body (cast iron).	7474	7474
Master Cylinder piston (unhardened).	7475	7475

Service Procedure.

In future it is not intended to supply Aluminium master cylinder bodies (Part number 6939) or hardened master cylinder pistons (Part number 6940) from the Jaguar Spares Department. Any outstanding orders will be supplied with the cast iron body and unhardened piston.

If it is considered necessary to replace a piston in an aluminium bodied master cylinder the whole unit should be replaced with a master cylinder having a cast iron body.

Index Reference. Section L.

MASTER CYLINDER DUST EXCLUDER - RUBBER GREASEModels affected.

XK.150
2.4 litre cars fitted with disc brakes.
3.4 litre cars fitted with disc brakes.

In the Descriptive and Maintenance Notes for Disc Brakes it is recommended that the rubber dust excluder at the end of the master cylinder be filled with Wakefield No.3 Rubber grease.

If this or no other recognised rubber grease is available the dust excluder should be assembled dry. Ordinary lubricating grease MUST NOT be used.

Index Reference. Section L.

Cont'd.....

SYNTHETIC PAINTWORK - SUMMARY OF COLOURS.Models affected.

Cars finished in synthetic enamel.

The following is a summary of the paint colours detailed in Service Bulletins 114, 138, 185 and 205 together with the more recent additions. The reference number given for each paint colour is for Quick Air Drying Enamel.

Where there has been a change in the shade of a particular colour the date when the change took place in production is given.

	<u>British Domolac.</u>	<u>Pinchin Johnson.</u>
Dove Grey	-	J.861
British Racing Green	Q.1076	J.860
Old English White		J.863 J.863/C
Birch Grey	Q.1079 Q.1079/1 (14.5.56.)	J.865
Pastel Blue (Non-Metallic)		J.867
Lavender Grey	Q.1072 Q.1072/1 (14.5.56.)	J.871
Suede Green	Q.1080 Q.1080/1 (14.5.56.)	J.873
Black	Q.1073	J.869
Battleship Grey	Q.1075 Q.1075/1 (14.5.56.)	J.875
Pastel Green (Non-Metallic)	Q.1081 Q.1081/1 (14.5.56.)	J.877
Red	Q.1089	
Pearl Grey	Q.1129 Q.1129/1 (5.3.56.) Q.1129/2 (14.5.56.)	
Pacific Blue	Q.1132/1	
Carmine Red	Q.1190	
Arbor Green	Q.1191 Q.1191/1 (14.5.56.)	
Maroon	Q.1135 Q.1135/1 (13.6.55.) Q.1135/2 (14.5.56.)	
Imperial Maroon	Q.1229 Q.1229/1 (25.2.57.)	
Claret	Q.1230 Q.1230/1 (25.2.57)	
Sherwood Green	Q.1231	
Forest Green	Q.1232	
Cornish Grey	Q.1236	
Mist Grey	Q.1235	J.889
Indigo Blue	Q.1233	
Cotswold Blue	Q.1234	

February, 1958

JAGUAR

SERVICE AND SPARES ORGANISATION

SERVICE BULLETIN NO.239
VARIOUS SERVICING ITEMS

DISC BRAKE CALIPER BRIDGE PIPE - VERY IMPORTANT

Models affected.

- KK.150
- 2.4 litre cars with disc brakes.
- 3.4 litre cars with disc brakes.

In the event of the removal of the bridge pipe connecting the two cylinder blocks fitted to each caliper, it is ABSOLUTELY ESSENTIAL that the pipe is refitted the correct way round.

It will be noted that one end of the pipe has an approximate right-angle bend whereas the other end has a more acute "hairpin" bend.

The end of the pipe with the "hairpin bend" MUST be connected to the INBOARD cylinder block. This is illustrated in Fig.1 in the Dunlop Disc Brake Descriptive and Maintenance Notes for the KK.150 model.

If the pipe is fitted the wrong way round the pipe will foul the road wheel.

Index Reference.

Section L.



FRONT WINGS - NOSE SECTION.

Model affected.

KK.150

Further to Service Bulletin No.231 regarding Front Wing nose sections for the KK.140 model a similar condition is now available from the Jaguar Spares Department for the KK.150 model.

Part number.

Front wing-nose section. Left Hand	7478 7477
Front wing-nose section. Right Hand	7479 7480

Index Reference.

Section N.

Cont'd.....

6⁷/₈" VACUUM SERVO - INTRODUCTION ON DRUM BRAKE CARS

<u>Models affected.</u>	<u>R.H.Drive.</u>	<u>L.H.Drive</u>
2.4 litre	909061	942677
3.4 litre	971732	987406

On cars with the above chassis numbers and onwards a larger brake servo (6⁷/₈" diameter) is fitted in place of the 5¹/₂" type.

In conjunction with this change a brake pedal of reduced ratio is fitted which also necessitates a change in the brake and clutch pedal housing.

The relevant part numbers are as follows:-

	<u>R.H.Drive.</u>	<u>L.H.Drive</u>
Vacuum Brake Servo (6 ⁷ / ₈ ")	- C.13672 -	-
Brake pedal (normal transmission and overdrive)	C.14024	C.14025
Brake pedal (automatic transmission)	C.14071	C.14025
Pedal housing	- C.14026 -	-

Index Reference.

Section L.

Amendment to Service Bulletin No.228.

If satisfactory travel of the handbrake lever cannot be obtained by using a .006" (.15 mm) feeler gauge to adjust the handbrake a .004" (.10 mm) feeler can be used.

Amendment to Service Bulletin No.236.

On page 2 under the heading "For Converting from Disc Wheels to Wire Spoke Wheels Only" insert (Applicable only to cars fitted with disc brakes)

Amendment to Service Bulletin No.235.

Amend the information on page 2 under "Thermostat, Modified type - Identification" as follows:-

Thermostat
C.13944
Smiths number K85024/74
stamped on body

Opening temperature 74°C.

Thermostat
C.3731/1
Smiths number 43570/5 or /28
stamped on body

Opening temperature 73°C.

February 1958.

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO.240

FRONT SUSPENSION - PROGRESSIVE BUMP STOPS.

<u>Models affected.</u>	<u>Commencing chassis numbers.</u>	
	<u>R.H. Drive.</u>	<u>L.H. Drive.</u>
2.4 litre	909536	942729
3.4 litre	972037	987685

On cars with the above chassis numbers and onwards, plus certain individual cars prior to these numbers, progressive bump stops are fitted to the front suspension.

This type of bump stop takes the form of a tapered rubber block attached to turret of the front suspension cross member and a bump stop plate fitted to the lower wishbone levers.

Interchangeability.

The progressive type of bump stop can be fitted in place of the previous arrangement if desired, but should only be carried out at the customers request and will be on a chargeable basis except in special circumstances.

Procedure.


The necessary welding should preferably take place with arc welding equipment but if this is not available and gas welding equipment is used, suitable asbestos or metal shields should be placed around the front suspension coil springs to protect them from the flame.

Jack up the car, remove the front wheels and place supports under the chassis side members. Jack up under the lower mounting of the shock absorber. Disconnect the top ball joint from the upper wishbone levers taking care not to lose or transpose the castor shims. Allow the stub axle carrier to fall outwards but do not permit the brake flexible hoses to become stretched.

1. Remove the bump stop cups from the flange at the bottom of the front suspension cross member turret. File the underside face of the flange flat and smooth. Clear the two holes already drilled in the flange.
2. Offer up the bump rubber bracket C.13917 to the front suspension cross member turret. To provide an accurate location two dimples or holes are formed in the bracket, which should register with the two holes drilled in the turret flange.
3. Clamp the bracket in position and weld to the front suspension cross member turret as shown in the sketch.
4. Secure the bump rubber C.13918 to the bracket with two 5/16" x 3/4" bolts and self locking nuts. (Bolt part no. UFS.131/6R Nut. C.8667/2).
5. Remove the two existing bump stop rubbers from the lower wishbone levers. Cut a 45° chamfer at the top of the holes from which the bump rubbers were removed.
6. Fit bump stop plate C.13919, in place of the bump stops and secure with the existing self-locking nuts. The lip of the plate is fitted inwards. (see sketch).
7. Repeat for the other side.

SERVICE BULLETIN NO.240

-2-



Index Reference.

Section J.

March, 1958

J A G U A R

S E R V I C E A N D S P A R T S O R G A N I S A T I O N

SERVICE BULLETIN NO. 242.

VARIOUS SERVICING ITEMS

WHEEL HUBS - OVER LUBRICATION.

Models affected.

All models.

Attention is drawn to the importance of not over-lubricating wheel hubs provided with grease nipples. Failure to observe this precaution will cause grease to find its way into the brake drum or on to the brake disc. Indications of when sufficient lubricant has been applied are as follows:-

FRONT WHEEL HUBS.

Disc Wheel Hubs.

Escape of grease from hole in hub end cap.

Wire Wheel Hubs.

Escape of grease past the outer hub bearing which can be observed through the bore of the splined hub.

REAR WHEEL HUBS.

Escape of grease through hole in the top of axle tube above grease nipple.

Index Reference. Sections H and J.

SPRAYING REAR SPRINGS - PRECAUTIONS.

Models affected.

Cars fitted with disc brakes.

When spraying rear springs with penetrating oil, every precaution must be taken to avoid oil getting on to the brake discs and friction pads. All lubrication bay operators must be informed of the importance of this instruction.

Index Reference. Section K.

Cont'd.....

HYDRAULIC FLUIDS FOR CLUTCH AND BRAKE SYSTEMS - IMPORTANT.


It is MOST IMPORTANT that the following revised recommendations regarding Brake Fluids are absorbed and strictly adhered to. All Distributors and Dealers service staff must be acquainted with these instructions.

DRUM BRAKES.

<u>Model.</u>	<u>Preferred Fluid.</u>	<u>Alternative Fluids.</u>
Mark VIII Mark VII Mark V	Wakefield Crimson Hydraulic Brake Fluid.	Lockheed No.102 Heavy Duty Brake Fluid. Delco Special No.11 Brake Fluid Chrysler MS 3511 Brake Fluid. <i>WAGNER 21B.</i>
2.4 litre 3.4 litre KK.120 KK.140	Lockheed No.102 Heavy Duty Brake Fluid.	Wakefield Crimson Hydraulic Brake Fluid Delco Special No.11 Brake Fluid Chrysler MS 3511 Brake Fluid. <i>WAGNER 21B</i>

DISC BRAKES.

KK.150 2.4 litre 3.4 litre	Wakefield Crimson Hydraulic Brake Fluid	Lockheed No.102 Heavy Duty Brake Fluid. Delco Special No.11 Brake Fluid. Chrysler MS 3511 Brake Fluid. <i>WAGNER 21B</i>
----------------------------------	-----------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------

CLUTCH OPERATION

<u>Model.</u>	<u>Preferred Fluid.</u>	<u>Alternative Fluids.</u>
Mark VIII KK.150 Mark VII	Wakefield Crimson Hydraulic Brake Fluid.	Lockheed No.102 Heavy Duty Brake Fluid. Delco Special No.11 Brake Fluid. Chrysler MS 3511 Brake Fluid. <i>WAGNER 21B</i>
2.4 litre 3.4 litre	Lockheed No.102 Heavy Duty Brake Fluid.	Wakefield Crimson Hydraulic Brake Fluid. Delco Special No.11 Brake Fluid. Chrysler MS 3511 Brake Fluid. <i>WAGNER. 21B.</i>

NOTE

In countries where the above fluids are unobtainable use only a recognised brake fluid guaranteed to conform to the S.A.E. Specification 70 R.1.

IMPORTANT.

In the event of deterioration of the rubber seals and hoses due to the use of incorrect fluids, all the seals and hoses must be replaced and the system thoroughly flushed and refilled with one of the above fluids.

Index Reference. Section L.

April, 1958.

J A G U A R
S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO.243

VARIOUS SERVICING ITEMS

DUNLOP R.S.4 ROAD SPEED TYRES

Model affected

3.4 litre model

As no doubt you will have noticed, 3.4 litre cars recently delivered from our Works have been equipped with Dunlop Road Speed tyres having a new pattern tread, this tread pattern being similar to that already in use with the tubeless tyre equipment fitted to the 2.4 litre model. This tyre is known as the Dunlop Road Speed R.S.4, as opposed to the previous Road Speed tyre fitted, the Dunlop R.S.3.

Certain changes have been made in the construction of the Road Speed tyre which, together with the change in tread pattern, have brought about greatly improved adhesion, particularly under wet road surface conditions.

In the event of tyres being replaced, but only two tyres requiring replacement at one particular time, it is recommended that the R.S.4 Road Speed tyres then fitted should be placed on the rear wheels of the car, but it is, of course, preferable that wherever possible all four tyres should be replaced at the same time.

Due to the construction of the R.S.4 Road Speed tyre, some light tyre thump may be noticeable on a smooth surfaced road in the first three to five miles after driving away from cold. This condition is due to tread distortion which occurs when standing, and exists only for a short period prior to the tyre warming up.

There is no reason for this complaint, if raised, to cause any concern. It is brought to your notice to avoid the possibility of any such complaint being thought to originate from a mechanical part of the car.

Index Reference. Section M. ✓

OVER - ADVANCING IGNITION

Models affected

All models .

It is pointed out that no improvement in performance will be gained by advancing the ignition above the recommended setting.

Over-advancing the ignition will result in rough running at idling speed, "jerky" operation when driving on a constant throttle, and may cause detonation with consequent piston ring breakage and allied troubles.

The above warning is particularly important now that 9 to 1 compression ratio engines are available on certain models.

Index Reference. Section B. ✓

Cont'd...

SERVICE BULLETIN NO.243.

-2-

THORNTON POWER-LOK DIFFERENTIAL - IDENTIFICATION

Rear axles fitted with a Thornton Power-Lok differential in production are now identified with a metal tag stamped P/L which is fitted underneath the head of the differential cover bolt adjacent to the bolt carrying the ratio tag.

In the event of the tag not being in position it can be ascertained if a Thornton power-lok differential is fitted to a particular rear axle by removing the filler plug. If the differential case can be seen adjacent to the filler plug hole it can be taken that a power-lok differential is fitted.

Index Reference Section H ✓

3.4 LITRE 9 to 1 COMPRESSION RATIO - IGNITION AND CARBURETTOR NEEDLE DATA

The following is the distributor, sparking plug and carburetter needle data for 9 to 1 compression ratio engines fitted to the 3.4 litre model.

Distributor - type	-	Lucas Service number 40617A
	-	Jaguar part number C.14269

Ignition Timing	T.D.C.
-----------------	--------

Sparking Plug type	Champion N.5 (or N.A.8.)
--------------------	--------------------------

Carburetter Needle	S.C.
--------------------	------

Index Reference Sections B and C. ✓

Addition to Service Bulletin No.242 page 2.

To each list of Alternative Fluids, add the following recommended fluid.

"Wagner 21B Brake Fluid". ✓

Amendment to Service Bulletin No.241

Alter the part number of the Handbrake Compensator Bracket for the 3.4 litre - Left-hand drive model from C.12461 to C.14261. ✓

MAY, 1958.

JAGUAR
SERVICE AND SPARES ORGANISATION

SERVICE BULLETIN NO. 245.

VARIOUS AIRVACUUM LINES.

RELAY VALVE - MODIFICATION

<u>Models affected.</u>	<u>Commencing Engine numbers</u>
Mark VIII Automatic transmission	H.A. 1938
3.4 litre Automatic transmission	K.E. 7052
XK.150 Automatic transmission	V. 3208

On automatic transmission cars with the above engine numbers and onwards a modification to the valve block is incorporated to eliminate the possibility of a jerk when a closed throttle downshift between intermediate and low gear takes place.

The modification entails removing and dispensing with the Relay valve spring (Item F. Fig. 22 in the Automatic Transmission Supplement), and inserting a slug (Part number 20-687) between the Relay valve plunger (2) and the cover (3). (Some cars are fitted with a double coil spring washer instead of a slug).

This has the effect of cutting off the hydraulic flow to the low band servo so that only the forward band is in operation for Automatic Low in the "D" (Drive) position.

Service Procedure

If complaints are received of a jerk being experienced on a closed throttle downshift between the intermediate and low gears, the above modification can be carried out.

Index Reference Section FF.

OIL CONTROL PISTON RINGS.

Models affected.

Mark VII
XK.140
Mark VIII
3.4 litre
XK.150

Note that the "Maxilite" oil control ring Part number C.11956 is not fitted to piston assemblies fitted in production or supplied for service replacement although shown in the Spares Parts Catalogues and Service Bulletin No.184.

The piston ring fitted to production and service replacement piston assemblies is the "Maxigroove" type - Part number C.5832.

The "Maxilite" oil control ring C.11956 is supplied only when piston rings are ordered separate from pistons.

Index Reference Section B

DISC BRAKE ADAPTOR PLATE BOLTS - CORRECT ASSEMBLYModels affected

All cars fitted with disc brakes.

Note that it is important that the bolts securing the adaptor plate to the rear axle tube are fitted the correct way, that is, with the head of the bolt toward the brake disc. If the bolt is fitted the reverse way the end of the bolt may foul the bolts securing the brake disc to the hub.

Index Reference

Sections H and L. ✓

REAR ROAD SPRINGS - CHANGE IN CAMBERModels affectedCommencing chassis numbers.

2.4 litre
3.4 litre


R.H.Drive.	L.H.Drive.
910309	942922
972599	988372

On cars with the above chassis numbers and onwards Rear springs Part number C.10791/1 are fitted replacing Rear spring C.10791. The difference between these two springs is in the free camber and the details are as follows:-

C.10791.

C.10791/1.

Free camber	C.10791.	C.10791/1.
	3.45" (87.5mm)	3.45" to 3.7" (87.5 to 94 mm)


Interchangeability

The latest type spring C.10791/1 is interchangeable with the previous type C.10791 fitted prior to above chassis numbers but they must be fitted in pairs.

Existing stocks of C.10791 should be used up on cars prior to the above chassis numbers.

Index Reference

Section K ✓

SERVO RETURN SPRING - ASSEMBLYModels affected

Mark VII.
Mark VIII.

Clayton Dowdall servo units fitted to later Mark VII and Mark VIII cars are fitted with the piston return spring the reverse way to that illustrated on page L.20 of the Mark VII and K.120 Service Manual.

When reassembling any Mark VII or Mark VIII servo unit the piston return spring should be fitted in the latest manner that is, with the smaller diameter end towards the piston.

Index Reference

Section L ✓

July, 1958.

J A G U A R
S E R V I C E A N D S P A R T S O R G A N I S A T I O N

SERVICE BULLETIN NO. 248

VARIOUS SLIGHTLY ITEMS

THORNTON LIMITED SLIP DIFFERENTIAL - PRECAUTIONS.

Models affected

Cars fitted with Thornton "Power-Lok" differential

1. On a car fitted with a Thornton Power-Lok differential the engine must NOT be run with the car in gear and one wheel off the ground otherwise, owing to the action of the differential, the car may drive itself off the jack or stand.

If it is desired to turn the transmission by running the engine with the car in gear both wheels must be jacked up clear of the ground.

2. Note that when withdrawing an axle shaft it is possible for the axle shaft spacer to be drawn out of the differential and to fall into the axle tube which will be evident when attempting to replace the axle shaft.

If this should happen the spacer can be removed with a length of magnetised rod. The spacer can be replaced as follows:-

Insert the spacer into the end of a length of tubing in which it is a tight fit.

Pass the tubing into the axle tube and enter the spacer in its bore in the differential.

Pass a long rod down the centre of the tubing until it contacts the spacer.

The tubing can now be disengaged from the thrust button by holding the rod firmly and pulling on the tubing.

If both axle shafts have been removed do not attempt to fit both spacers and then the axle shafts. Fit one spacer and an axle shaft to the same side, before fitting the other spacer and axle shaft.

3. If a Thornton power-lok differential is fitted to an existing rear axle the filler plug will foul the differential case.

A special cover plate is available for use with a Thornton Power-lok differential under the following part numbers.

Cover plate only.	4 HA-010-1
Cover plate with filler plug.	4 HA-064-3

If a special cover plate is not available, the end threads of the filler plug can be cut off to obtain at least 1/16" (1.5 mm) clearance between the end of the plug and the differential case.

Index Reference.

Section H. ✓

COIL SPRING PACKING PIECE.

<u>Models affected</u>	<u>Commencing chassis numbers.</u>	
	<u>R.H. Drive.</u>	<u>L.H. Drive.</u>
2.4 litre	911033	943054
3.4 litre	975493	988794

On cars with above chassis numbers and on cars a packing piece may be fitted at the top of the coil spring to compensate for slight manufacturing variation in the fitted lengths of the springs.

The packing pieces are in $\frac{1}{8}$ " (3.2 mm) and $\frac{3}{16}$ " (5.4 mm) thicknesses and are fitted in accordance with the following details:-

<u>Colour code of spring.</u>	<u>Thickness of packing piece.</u>
<u>2.4 litre</u>	
White	$\frac{3}{16}$ " (5.4 mm) Pt. number C11874
Blue	$\frac{1}{8}$ " (3.2 mm) Pt. number C11874/1
Green	No packing piece fitted.
<u>3.4 litre</u>	
Red	$\frac{3}{16}$ " (5.4 mm) Pt. number C11874
Yellow	$\frac{1}{8}$ " (3.2 mm) Pt. number C11874/1
Purple	No packing piece fitted.

In service, if the coil springs are removed for any reason on a car prior to above chassis numbers, packing pieces can be fitted in accordance with the above details.



Index Reference. Section J.

HEATER RHEOSTAT MOTOR

<u>Models affected.</u>	<u>Commencing chassis numbers.</u>	
	<u>R.H. Drive</u>	<u>L.H. Drive.</u>
K.150	-	830439
Open 2 seater	-	830439
Fixed Road Coupe	824420	835366
Drop Head Coupe	827072	857434

On cars with the above chassis numbers and onwards a rheostat switch is fitted to allow the heater motor speed to be controlled.

The switch is positioned adjacent to the revolution counter and is marked "Heater, Fast-Slow".

The switch is off when rotated fully anti-clockwise. Rotation clockwise switches on the motor at its maximum speed, further rotation brings the rheostat into operation and the motor speed progressively falls until the knob reaches the end of its travel. The motor is wired through the ignition switch and will be automatically switched off with the ignition.

Index Reference. Sections O and P

Amendment to Service Bulletin 239

Amend the part numbers under "Front Wing, - Nose Section" as follows:-

	<u>Part number</u>
Front wing - nose section. Left-hand	7479
Front wing - nose section. Right-hand.	7480

July, 1958.

J A G U A R
S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO. 249

VARIOUS SERVICING ITEMS

PANHARD ROD - ADJUSTMENT

Models affected

2.4 litre
3.4 litre

After setting the panhard rod to the dimension giving on page K8 of the "Rear Suspension" section, a further check should be carried out to ensure that the rear wheels are central in relation to the front wheels. The procedure is as follows:-

Place a straight edge across one rear tyre and check the distance to the flange of the chassis side member at the point at which the rear spring centre clamping plate is bolted; repeat for the other side. The dimension at each side should be the same; if not, re-adjust the panhard rod as necessary. Note: the rear tyres must be of the same type and set at the same pressure when carrying out this check.

The point of the chassis side member flange at which the dimension should be taken is between the two bolts which secure the rear spring centre clamping plate.

Index Reference. Section K ✓

OVERDRIVE MANUAL SWITCH.

Models affected

2.4 litre
3.4 litre
~~Mark VIII~~

The clear plastic manual switch and relay has now been superseded by a metal switch, similar in appearance to the Intermediate Speed Hold switch fitted to Automatic transmission cars.

No relay is fitted with the later type switch and it is important that the earlier type switch is not used to replace the later type as the switch may burn out due to the absence of a relay in the circuit.

Index Reference. Sections F and P. ✓

BRAKE LININGS - EXAMINATION FOR WEAR.

Models affected.

All models.

Please note that the period for examining the brake linings or friction pads for wear is being reduced from every 10,000 miles (16,000 km) to every 5,000 miles (8,000 km).

This applies to either cars fitted with drum or disc brakes.

Index Reference. Section L. ✓

Jaguar Cars Limited 2005

Cont'd....

N.D.V. SUPPORT BRACKET.Models affected.

2.4 litre
3.4 litre

Please note that the chrome plated bracket to which the No Draught Ventilator hinge is attached, is not supplied as a separate item under the following part numbers.

N.D.V. Support bracket.	Left-hand	BD.9653
N.D.V. Support bracket.	Right-hand	BD.9654

Index Reference. Section N.

DISC BRAKE BRIDGE PIPE.Models affected

Cars fitted with disc brakes.

Reference Service Bulletin number 239, note that to assist in the correct fitting of the caliper bridge pipe an identification tag is now fitted marked "Inner top".

Index Reference. Section L.

REAR SPRING NYLON INTERLEAF.Models affected

Mark VIII	
IX.150	Open 2 seater
	Fixed Road Coupe
	Drop Road Coupe

Commencing chassis numbers.

R.H. Drive.	L.H. Drive.
754370	781366
-	830960
824551	835671
827168	837573

On cars with the above chassis number, and onwards the rear springs are fitted with full length nylon interleaving between the top and second leaves.

The relevant part numbers are as follows:-

	Mark VIII	IX.150
Rear spring with nylon interleaf	C13109/1	C14473
Nylon Interleaf	C.13109/2	C13109/2

Service Procedure.

If complaints of rear spring squeak are received on cars equipped with springs having rubber buttons, a nylon interleaf can be fitted between the top and second leaves but the following points should be noted.

1. On the Mark VIII model a rubber button is fitted between the top and second leaves at the rear end of the spring. When fitting a nylon interleaf this button should be discarded.
2. On the IX.150 model it will be necessary to cut 2" (51 mm) off the longer end of the interleaf before fitting.

Index Reference. Section H.

July, 1958.

JAGUAR
SERVICE AND SPARES ORGANISATION

SERVICE BULLETIN NO. 250.

VARIOUS SERVICING ITEMS.

LOSS OF DRIVE IN "D" (DRIVE) AND REVERSE

<u>Models affected</u>	<u>Cars affected</u> prior to transmission numbers
Mark VIII Automatic Transmission	JB8 3302
2.4 litre Automatic Transmission	J2B 1522
3.4 litre Automatic Transmission	J3B 3619

If a complaint is received of loss of drive in the "D" (Drive) and R (Reverse) positions on automatic transmission cars prior to the above numbers the most likely cause of the trouble is that the two low brake drum plate dowels (E.Pig.116 in the Automatic Transmission Service Manual) have become displaced due to a faulty snap ring.

The actual symptoms are as follows:-

No drive in Automatic Low in the "D" (Drive) position.

No drive in the "R" (Reverse) position.

Drive possible in the "L" (Selected Low) position.

The car can be driven if desired by starting off in the "L" position and then selecting "D" when the car has reached a speed of approximately 15 m.p.h. (24 k.p.h.). If the car is stopped for any reason this procedure will have to be repeated.

To rectify this trouble, it will be necessary to remove the transmission unit and withdraw the main shaft assembly as described on page 67 of the Automatic Transmission Service Manual.

Remove the rear bearing and forward brake drum as described in paragraphs 9-11 on page 70. Collect the two dowels if they have become displaced; the dowels can be refitted if they are not damaged.

Remove the low brake drum plate snap ring (as described in paragraph 15 page 70).

Discard the existing snap ring and fit the dowels and a new snap ring (Part number J20-350). Check that the snap ring is a good fit in its groove and that the gap between the ends of the ring is narrower than the diameter of one of the dowels.

This rectification should be carried out on a guarantee basis and the claim endorsed "Reference Service Bulletin Number 250".

Note: The only other fault which will give similar symptoms to those listed above is a faulty reverse free-wheel.

If the dowels are found to be in position and the snap ring is secure, the reverse free-wheel can be examined at the same time without further dismantling.

Index Reference.

Section FF.

REAR SPRING - MODIFIED TYPE.

<u>Models affected.</u>	<u>Commencing Chassis Numbers.</u>	
	<u>R.H. Drive.</u>	<u>L.H. Drive.</u>
KK.150 Open 2 seater	-	830960
Fixed Head Coupe	824551	835671
Drop Head Coupe	827168	837573

On cars with the above chassis numbers and onwards a modified Rear spring (Part number C.14476) replaces Rear spring Part number C.13006.

The modified type of rear spring C.14476 has a thicker top leaf than the previous type, and a front spring eye of different design. A full length nylon interleaf is fitted between the top and second leaves - see Service Bulletin No.249.

Interchangeability.

Rear spring C.14476 is interchangeable with Rear Spring C.13006 in pairs.

Index Reference. Section K. ✓

CLUTCH RELEASE BEARING.Models affected.

Mark VII
 Mark VIII
 KK.120
 KK.140
 KK.150
 2.4 litre
 3.4 litre

To ensure adequate clearance between the back of the clutch release bearing and the gearbox front oil seal cover to allow the necessary clearance between the release bearing and the clutch to be obtained use only Clutch release bearing Part number 2590 (BB 48443).

This release bearing can be easily identified by the presence of two grooves machined in the lugs of the release bearing cup.

Index Reference. Section E. ✓

Amendment to Service Bulletin No.249

Under "Overdrive Manual Switch" delete Mark VIII model.

September, 1958.

JAGUAR
SERVICE AND SPARES ORGANISATION

SERVICE BULLETIN NO. 251.

VARIOUS SERVICING ITEMS.

PRESSURE "BUILD-UP" IN HYDRAULIC SYSTEM

Models affected

XK.150

2.4 litre cars fitted with $6\frac{7}{8}$ " Lockheed vacuum servo.

3.4 litre cars fitted with $6\frac{7}{8}$ " Lockheed vacuum servo.

The $6\frac{7}{8}$ " Lockheed servo is fitted to all cars with disc brakes and also to cars equipped with drum brakes on and after the following chassis numbers:-

	<u>R.H.Drive.</u>	<u>L.H.Drive.</u>
2.4 litre	909061	982677
3.4 litre	971732	987406

A number of complaints of brake drag or binding, caused by a slow pressure build-up in the hydraulic system, have been traced to insufficient clearance between the servo piston rod and the slave cylinder piston (Item B and H, Fig. 40 in the "Brakes" section of the 2.4/3.4 litre Service Manual).

The trouble will be indicated by a reduction of brake pedal travel, or varying pedal travel, which returns to normal after the car has been left standing.

CORRECTIVE ACTION.

The correct method of adjustment of the push-rod is described and illustrated on page L.43 of the 2.4/3.4 litre Brake section but entails partial dismantling of the slave cylinder.

The simple method to overcome pressure build-up is as follows:-

Remove the servo unit from the car.

Remove the end cover (six nuts and bolts).

Slacken the locknut at the end of the piston push rod.

Unscrew the push rod one complete turn and tighten the locknut.

Re-fit the end cover. Re-fit the servo unit and bleed the hydraulic system.

Carry out a road test making frequent applications of the brake pedal, to ensure that no brake drag exists.

If pressure "build-up" is still present, increase the clearance between the push-rod and piston by unscrewing the push rod a further half a turn.

Index Reference.

Section L ✓

Cont'd.....

OIL BATH AIR CLEANER - INTRODUCTION.

<u>Models affected.</u>	<u>Commencing Chassis Numbers.</u>	
	<u>R.H.Drive.</u>	<u>L.H.Drive.</u>
2.4 litre	911658	943149

On cars with the above chassis numbers and onwards plus certain individual cars prior to these numbers, an oil bath air cleaner (Part number C.14213) is fitted as standard. Air is drawn into the air cleaner through the short pipe which runs forward to the radiator. The large diameter pipe located under the left-hand front wing is retained to assist the under bonnet ventilation.

The air cleaner is fitted on top of the cylinder head and the maintenance instructions are as follows:-

The periods at which maintenance should be carried out will vary according to the conditions under which the car is operated. For normal conditions every 2,500 miles (4,000 kms) can be taken as the proper cleaning periods, but in dusty territories more frequent cleaning, as often as 1,000 miles (1,600 kms) or less, may be necessary.

Unscrew the wing nut and remove the top cover. Spring back the three clips and lift out the filter element. Wash the element by swishing up and down in a bowl of paraffin and allow to drain thoroughly.

Remove the three set bolts securing the oil base to the support brackets. Lift off the oil base, empty out the oil and clean out the accumulated sludge. Fill the oil base with engine oil to the level indicated by the arrow. It is unnecessary to re-oil the filter element as this is done automatically when the car is driven. Ensure that the top cover gasket is in good condition and re-assemble the filter.

Index Reference. Section C. 4

60 WATT HEADLAMP BULBS - INTRODUCTION.

<u>Models affected.</u>	<u>Commencing Chassis Numbers.</u>	
	<u>R.H.Drive.</u>	
2.4 litre Home and R.H.Drive		
Export	910846	
3.4 litre Home and R.H.Drive		
Export.	973206	

On cars with above chassis numbers and onwards modified headlamps incorporating 60 watt bulbs are fitted.

The part numbers are as follows:-

	<u>Part Number</u>
Headlamp complete	C.14237
Bulb. 60 watt (Lucas No.404)	C.8904.

Interchangeability.

1. The complete headlamp C.14237 is interchangeable with the previous type C.8808.
2. The 60 watt bulb cannot be fitted to headlamp C.8808.

Index Reference. Section P. ✓

September, 1958.

J A G U A R
S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO. 252.

VARIOUS SERVICING ITEMS.

FRESH AIR HEATING EQUIPMENT.

<u>Models affected.</u>	<u>Commencing chassis numbers.</u>	
	<u>R.H. Drive</u>	<u>L.H. Drive.</u>
XK. 150.		
Open Two Seater		831140
Fixed Head Coupe	824585	835719
Drop Head Coupe	827194	837628

On cars with the above chassis numbers and onwards fresh air heating and ventilating equipment replaces the Re-circulating equipment.

The following are the revised instructions:-

The car heating and ventilating equipment consists of a heating element and an electrically driven fan mounted on the engine side of the scuttle. Air from the heater unit is conducted:-

- 
- (a) To a built-in duct fitted with two doors situated under the instrument panel.
 - (b) To vents at the bottom of the windscreen to provide demisting and defrosting.

FRESH AIR is introduced into the system by opening the air intake in the left-hand front wing and switching on the fan.

Temperature Control.

The lever controlling the flow of water from the engine cooling system to the heating element is situated at the top of the instrument panel.

When the lever knob is placed in the Cold position, the supply of hot water from the engine is completely cut off; placed in the fully Hot position the maximum possible amount of hot water from the engine is allowed to pass through the heater element. By placing the lever knob in intermediate positions the temperature of the air from the heater can be varied between these two extremes.

Fan switch

The heater fan switch situated at the bottom left of the instrument panel is off when rotated fully anti-clockwise. Rotation clockwise switches on the motor at its maximum speed; further rotation brings a rheostat into operation and the motor speed progressively falls until the knob reaches the end of its travel. The motor will be automatically switched off with the ignition if the fan switch is inadvertently left on.

The following directions for heating the car interior in cold weather and ventilating the car interior in hot weather are given as a guide but it will be appreciated that the degree of heating can be regulated by the controls.

Cont'd.....

Fresh air is introduced into the system by opening the door in the left-hand front wing. The lever operating the door is situated in the driving compartment forward of the left-hand door; push the lever forward to open the intake door, pull the lever rearward to close the door.

Note: The air intake must always be open when using the heating and ventilating equipment.

COLD WEATHER

To obtain car heating, demisting and defrosting.

- (a) OPEN air intake (in left-hand front wing).
- (b) Set temperature control to the DESIRED POSITION.
- (c) Switch ON fan (to required speed).
- (d) OPEN heater doors.

To obtain rapid demisting and defrosting.

- (a) OPEN air intake (in left-hand front wing).
- (b) Set temperature control to HOT.
- (c) Switch ON fan (at maximum speed).
- (d) CLOSE heater doors.

HOT WEATHER

To obtain ventilation and demisting.

- (a) OPEN air intake (in left-hand front wing).
- (b) Set temperature control to COLD.
- (c) Switch ON fan (to required speed).
- (d) OPEN heater doors.
- (e) OPEN ventilator (in right-hand front wing).

Index Reference. Section O. ✓

AIR CLEANER MAINTENANCE.

Models affected

All

As it has been found that Distributors and Dealers have not been carrying out maintenance of air cleaners, attention is again drawn to the importance of carrying out this service at the recommended periods. (see Service Bulletin Nos. 229 and 251 for maintenance instructions for the oil bath type of air cleaners).

Failure to carry out periodic maintenance of air cleaners will cause high petrol consumption, reduced performance and premature engine wear.

Index Reference Section C ✓

IMPORTANT NOTICE. It has come to our notice that some of the instructions contained in certain of our Service Bulletins are not being carried out. Particular attention is called to the following Service Bulletins the instructions in which must be observed.

<u>Service Bulletin Number</u>	<u>Subject.</u>
241	"Modification to overcome Handbrake cross cables fouling body".
242	"Hydraulic Fluid for Clutch and Brake Systems-Important".
246	"Modification to Disc Brake Master Cylinder."

November, 1958

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO. 255VARIOUS SERVICING ITEMSGEARING HYDRAULIC DAMPERS - MODIFIED TYPE

<u>Models affected.</u>	<u>Componenting Chassis Numbers</u>	
	<u>R.H. Drive</u>	<u>L.H. Drive</u>
2.4 litre - Front	911522	943124
Rear	912637	943269
3.4 litre - Front	973987	989137
Rear	975162	990176

On cars with the above chassis numbers and onwards modified hydraulic dampers are fitted giving consistent damping at all operating temperatures.

The part numbers are as follows:-

Front	C.14586	2 off
Rear	C.14587	2 off

Interchangeability

The new dampers are interchangeable with the previous types, but must be fitted in pairs to either front or rear.

Index Reference Sections J and K. ✓

REAR CALIPER ADAPTOR PLATE BOLTSModels affected.

2.4 litre cars with disc brakes.
3.4 litre cars with disc brakes.
XK.150

Disc brake cars now in production are fitted with a revised arrangement for attaching the adaptor plate to the rear axle.

The original arrangement of bolts, shakeproof washers and nuts is superseded by longer bolts and self-locking nuts.

The part number of the new bolts and nuts are as follows:-

<u>Model</u>		<u>Part number</u>	<u>No. off per car</u>
2.4/3.4 litre	Bolt.	7755	8
XK.150	Bolt.	7757	8
All	Nut - self locking	7756	8

Index Reference Section L. ✓

9 to 1 COMPRESSION ENGINES - FUEL REQUIREMENTS.Models affected

All cars fitted with 9 to 1 compression engines.

It is important that only super grade fuel with a minimum octane

/Cont'd.....

rating of 98 (Research method) is used with engines having 9 to 1 compression ratio pistons (indicated by /9 after the engine number).

If, of necessity, the car has to be operated on lower octane fuel do not use full throttle otherwise detonation may occur with resultant piston trouble.

Index Reference Section B. ✓

12 BLADED FAN - INTRODUCTION

<u>Models affected.</u>	<u>Commencing Chassis Numbers</u>	
	R.H. Drive	L.H. Drive
2.4 litre	915349.	943118

On cars with the above chassis numbers and onwards a 12 bladed fan is introduced.

The fan cowl fitted with the previous type 4 bladed fan is dispensed with, but a fan shield is fitted at the top of the radiator.

The part numbers are as follows:-

12 bladed fan.	C.12391.
Fan shield.	C.14732.

Index Reference Section D. ✓

SELECTOR LINKAGE ADJUSTMENT

Models affected

- Mark VII Automatic Transmission.
- Mark VIII Automatic Transmission.

If the selector linkage is found to be persistently in need of adjustment and to disengage from the "D" position under hard acceleration or heavy braking the most likely cause of the trouble is slackness or softening of the engine mounting rubbers.

In this case new engine mountings should be fitted all round and the manual selector linkage re-adjusted as described on page 22 of the Automatic Transmission Service Manual.

Index Reference Section FF. ✓

January, 1959

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO. 257

VARIOUS SERVICING ITEMS

BRIDGE TYPE CALIPERS WITH QUICK CHANGE PADS

<u>Models affected</u>	<u>Commencing Chassis Numbers</u>	
	R.H. Drive	L.H. Drive
2.4 litre cars with disc wheels	913144	943331
2.4 litre cars with wire wheels	913234	943343
3.4 litre cars with disc wheels	975688	990694
3.4 litre cars with wire wheels	975783	990795
XK.150 Open 2-Seater	820004	831712
XK.150 Drop Head Coupe	827236	837836
XK.150 Fixed Head Coupe	824669	835886

On cars with the above chassis numbers and onwards bridge type calipers with quick change pads are fitted.

The servicing instructions are as follows:-

Every 5,000 miles (8,000 km)

Friction Pads - Examination for Wear

At the recommended intervals, or if a loss of braking efficiency is noticed, the brake friction pads (2 per brake) should be examined for wear; the ends of the pads can be easily observed through the apertures in the brake caliper. When the friction pads have worn down to a thickness of approximately a $\frac{1}{4}$ " (7 mm) they need renewing.

Friction Pads - Renewal

To remove the friction pads, unscrew the nut from the bolt attaching the friction pad retainer to the caliper and extract the bolt. Withdraw the pad retainer.

Insert a piece of strong cord (or wire) through the hole in the metal tag attached to the friction pad and withdraw the pad by pulling on the cord.

To enable the new friction pads to be fitted it will be necessary to force the pistons back into the cylinder blocks by the use of Special Tool 7840 or by means of suitable levers.

Before doing this, it is advisable to half empty the brake supply tank otherwise forcing back the friction pad will eject fluid from the tank with possible damage to the paintwork. When all the new friction pads have been fitted, top up the supply tank to the recommended level.

Insert the new friction pads into the caliper ensuring that the slot in the metal plate attached to each pad engages with the button in the centre of the piston.

Finally, refit the friction pad retainer and secure with the bolt and nut. Apply the footbrake a few times to operate the self-adjusting mechanism, so that normal travel of the pedal is obtained.

SERVICE BULLETIN NO.257

- 2 -

The new part numbers are as follows:-

XK.150 and XK.150 'S'

C.14874 R.H. Front Caliper Assembly.
C.14875 L.H. Front Caliper Assembly.
C.14876 R.H. Rear Caliper Assembly.
C.14877 L.H. Rear Caliper Assembly.
7654 Friction Pad Assembly.

2.4 and 3.4 litre

C.14874 R.H. Front Caliper Assembly.
C.14875 L.H. Front Caliper Assembly.
C.14894 R.H. Rear Caliper Assembly.
C.14895 L.H. Rear Caliper Assembly.
7654 Friction Pad Assembly.

Index Reference Section L. ✓

1/2" FAN BELT - INTRODUCTION

Models affected Commencing Engine Numbers

XK.150	V.5733
XK.150 'S'	VS.1523
3.4 litre	KF.2501



On cars with the above engine numbers and onwards a 1/2" (12.5 mm) fan belt is fitted; the pulleys are modified to suit.

The part numbers are as follows:

C.14535 Fan Belt.
C.14588 Fan Pulley.
C.14589 Crankshaft Pulley.
C.14590 Dynamo Pulley.

Index Reference Section B.

CALIPER PISTON RETRACTOR TOOL

Models affected

Disc brake cars fitted with quick change pads.

When replacing friction pads it is necessary to force back the pistons into the caliper before the new pads can be fitted. A special tool (Part No. 7840) to carry out this operation is now available from the Jaguar Spares Department, price 13/3d.

Index Reference Section L. ✓

JAGUAR

SERVICE AND SPARES ORGANISATION

SERVICE BULLETIN NO. 258

VARIOUS SERVICING ITEMS.BRAKE VACUUM RESERVOIR - INTRODUCTION

<u>Models affected</u>	<u>Commencing Engine Numbers</u>
2.4 litre	B.C. 8075
3.4 litre	K.F. 2501

On cars with the above engine numbers and onwards a vacuum reservoir is incorporated in the vacuum line between the inlet manifold and the servo.

The vacuum reservoir tank is located underneath the right-hand front wing forward of the wheel. The tank has a vacuum check valve attached, to which the hoses are connected as follows:-

Hose from inlet manifold - to longer check valve connection.

Hose to servo - to shorter check valve connection.

Inlet Manifold

The vacuum check valves originally fitted to the 2.4 litre and 3.4 litre models are now discontinued, and the hose to the inlet manifold is now taken to an adaptor at the rear of the manifold which also incorporates a connection for the windscreen washer pipe.

The re-designed inlet manifold for the 3.4 litre model also incorporates a six branch distribution arrangement for the auxiliary starting carburetter.

The part numbers of the main items are as follows:-

No. off.

1	Vacuum Reservoir	C.14681
1	Check Valve.	C.14693
1	Adaptor at rear of inlet manifold.	C.14715
1	Hose - Manifold to Vacuum Reservoir	C.14714
1	Hose-Vacuum Reservoir to Servo	C.14963
1	Inlet Manifold (2.4 litre)	C.14893
1	Inlet Manifold (3.4 litre)	C.14651/A.

Index Reference Section L. ✓

PETROL FILTER-INTRODUCTION

<u>Model affected</u>	<u>Commencing Engine Number</u>
3.4 litre	KF.2501

On cars with the above engine number and onwards a petrol filter of the glass bowl type is fitted. The filter is fitted to the right-hand wing valance and the maintenance instructions are as given in Service Bulletin 227 for the 2.4 litre model.

Index Reference Section C. ✓

/Cont'd....

UPPER WISHBONE BALL JOINT


<u>Models affected</u>	<u>Commencing Chassis Numbers</u>	
	R.H. Drive	L.H. Drive
2.4 litre with drum brakes	912622	943267
2.4 litre with disc brakes	912744	943288
3.4 litre	975232	990270
XK.150 Open 2-seater	820004	831698
XK.150 Fixed Head Coupe	824668	835882
XK.150 Drop Head Coupe	827235	837831
Mark IX	770220	790196

On cars with the above chassis numbers and onwards modified upper wishbone ball joints are fitted. These modified ball joints have a larger diameter ball and an increased angle of movement. In the case of the 2.4 litre and 3.4 litre models the ball joint bolt hole centres in the upper wishbone levers and packing piece are increased from 1.11/16" (4.28 cm) to 1 $\frac{3}{4}$ " (4.44 cm).

The new part numbers are as follows:-

Number per car	Part Number
2 off Upper Wishbone Ball Joint	C.14434
4 off Upper Wishbone Levers (2.4 and 3.4 litre only)	C.14436
2 off Packing Piece (2.4 and 3.4 litre only)	C.4740

Interchangeability

- 
- (i) On the Mark IX and XK.150 models upper wishbone ball joint C.14434 is interchangeable with the previous type, but it will also be necessary to fit grease nipple C.9048, Self-locking nut C.8737/5 and Plain washer C.791.
- (ii) On the 2.4 litre and 3.4 litre models the upper wishbone ball joint C.14434 is not interchangeable with the previous types fitted.

Index Reference

Section J. ✓

SPARKING PLUGS - CHANGE FROM N.8 to N.5 TYPEModels affected

All

The Champion N.5 (old designation N.A.8) sparking plug is now fitted to all current production engines for which the N.8 (N.8.B) type was originally specified. Engines prior to this change must have N.5 sparking plugs fitted when replacement becomes necessary.

It is also recommended that this change takes place on non-current production engines originally equipped with N.8 or N.8.B plugs.

Index Reference

Sections B ✓ and P.

JANUARY, 1959.

J A G U A R
S E R V I C E A N D S P A R E S O R G A N I S A T I O N
S E R V I C E B U L L E T I N N O . 2 5 9 .
V A R I O U S S E R V I C I N G I T E M S .

60 WATT HEADLAMP BULBS - INTRODUCTION ON L.H. DRIVE CARS

Models affected	Commencing Chassis Numbers
	L.H. Drive
2.4 litre	943324
3.4 litre	990610

On cars with the above chassis numbers and onwards modified headlamps incorporating 60 watt bulbs are fitted.

The part numbers are as follows:-

	Part Number
Headlamp complete	C.14238
Bulb. 60 watt (Lucas No. 406)	C.8905

Interchangeability

1. The complete headlamp C.14238 is interchangeable with the previous type C.8809
2. The 60 watt bulb cannot be fitted to headlamp C.8809.

Index Reference

Section P. ✓

AIR INTAKE LEVER SEALING RUBBERS

Models affected

XK.150 cars with fresh air heater (see Service Bulletin No. 252).

Cars now in production are fitted with a sponge rubber seal (Part No. BD.16680 - 2 off) at the top and bottom of the air intake lever situated at the left-hand side of the driving compartment.

These seals are fitted to prevent the ingress of cold air when the air intake is opened for operation of the heating system.

The seals are affixed to the air vent box with rubber solution and contact each other along the whole of their lengths.

Index Reference

Section O. ✓

/Cont'd....

72 SPOKE WIRE WHEELS

<u>Model affected</u>	<u>Commencing Chassis Numbers</u>	
	R.H. Drive	L.H. Drive
3.4 litre cars fitted with wire wheels	975230	990262

On cars with the above chassis numbers and onwards 72 spoke wire wheels are fitted, replacing 60 spoke wire wheels.

The new part numbers are as follows:-

72 spoke Wire Wheel (painted)	C.14766
72 spoke Wire Wheel (chrome plated)	C.14802

60 spoke and 72 spoke wheels should only be fitted to individual cars in complete sets.

Index Reference

Section M. ✓

POWER STEERING INNER COLUMN AND VALVE ASSEMBLYModels affected

Mark VIII cars fitted with power steering.
Mark IX model.

The 'O' ring (Item 16 plate CC in the Mark VIII Spares Catalogue) is now superseded by an oil excluding sleeve, retaining washer and circlip.

The original type of inner column and valve assembly will be serviced with the later type incorporating the oil excluding sleeve; the original part numbers for this assembly (7566 for L.H. Drive and 7565 for R.H. Drive) will be retained.

Index Reference

Section I. ✓

GUM DEPOSIT ON INLET VALVESModels affected

All

If allowed to stand for any length of time, some present day fuels have a tendency to form gum which may be deposited on the inlet valves when the engine is started after a period of storage; this may cause sticking valves.

It is therefore suggested, that in cases where a car is likely to be stored for any length of time, the fuel should be drained from the petrol tank and carburetters. A small quantity of oil should also be injected into each cylinder.

Index Reference

Section B. ✓

APRIL, 1959.

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO. 262

VARIOUS SERVICING ITEMS

STEERING UNIT AND IDLER - MODIFIED TYPE

<u>Models affected</u>	<u>Commencing Chassis Numbers</u>	
	<u>R.H. Drive</u>	<u>L.H. Drive</u>
2.4 litre	914564	943496
3.4 litre	976917	991866

On cars with the above chassis numbers and onwards a re-designed Steering box and Idler assembly is fitted.

The steering unit is lower geared than the previous type and gives approximately $4\frac{1}{2}$ turns from lock to lock. The hole centres in the steering drop arm and in the idler lever are reduced from $5\frac{7}{8}$ " (14.92 cm) to $5\frac{1}{2}$ " (13.97 cm).

The part numbers of the main items are as follows:-

	<u>Part Number</u>
Steering Unit RHD	C.14845
LHD	C.14846
Steering Drop Arm	C.14847
Steering Idler Assembly	C.14887
Steering Idler Lever	C.14848

Interchangeability

It is important that only the correct drop arm and idler lever are fitted with the new steering unit.

The above parts are not individually interchangeable with the previous types fitted.

Index Reference

Section I ✓

FOULING OF CLUTCH PEDAL

Model affected

XK.150

If fouling of the clutch pedal is experienced, the most likely cause is that the clutch over-centre spring bracket is contacting the split pin end of the clevis pin which secures the brake master cylinder fork end to the brake pedal.

In this event the position of the clevis pin should be reversed so the head of the pin is facing the clutch pedal linkage.

Index Reference

Section E ✓

/Cont'd...

LEAD INDIUM BIG END BEARINGS - INTRODUCTION

<u>Models affected</u>	<u>Commencing Engine Numbers</u>
2.4 litre	BE.1116
3.4 litre	KF.6219
XK.150	V.6709
Mark VIII	NA.3386

On cars with the above engine numbers and onwards lead indium big end bearings are fitted.

The part number is as follows:-

12 halves Big-end bearing C.5893

Interchangeability

The lead-indium bearings are interchangeable with the previous white metal type in complete sets.

Section Reference

Section B ✓

11 PLATE BATTERY - INTRODUCTION

<u>Models affected</u>	<u>Commencing Chassis Numbers</u>	
	<u>R.H. Drive</u>	<u>L.H. Drive</u>
3.4 litre	976364	991361
Cars for U.S.A. and Canada commenced at	-	990336

On cars with the above chassis numbers and onwards a 11 plate battery replaces the 9 plate type.

The details are as follows:-

	<u>Jaguar Part Number</u>	<u>Lucas type</u>	<u>Capacity</u>
9 plate battery	C.8792	GTW9A	57 amp. hr. at 20 hr rat
11 plate battery	C.14886	BV.11A	72 amp. hr. at 20 hr rate

Index Reference

Section P ✓

NOISE FROM REAR WHEEL ARCHES

Models affected.

Later Mark VIII models
Early Mark IX models

If a rubbing noise is experienced from the rear when the car is fully laden, it may possibly be due to the sliding roof rear drain tubes in the rear wheel arches fouling the tyres. If so, the drain tubes should be shortened so that they clear the tyres.

Index Reference

Section N ✓

J A G U A R
S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO.263

VARIOUS SERVICING ITEMS

POWER STEERING BANJO AND BANJO BOLT

<u>Models affected</u>	<u>Commencing Chassis Numbers</u>	
	<u>R.H. Drive</u>	<u>L.H. Drive</u>
Mark IX	770927	790559

On cars with the above chassis numbers and onwards a modified banjo bolt C.15273 (Item CG.13 in the Mark VIII Spares Catalogue) is fitted at the top end of the steering unit to obtain greater depth of thread engagement. With the introduction of this bolt, banjo C.13857 originally fitted for Right-hand drive cars only, is now also specified for Left-hand drive cars.

Interchangeability

For replacement purposes -
Use Banjo bolt C.15273 with aluminium banjo C.13857.
Use banjo bolt C.1506 with phosphor bronze banjo C.1505.

Index Reference

Section I ✓

MECHANICALLY OPERATED OVERDRIVE

<u>Models affected</u>	<u>Commencing Chassis Numbers</u>	
	<u>R.H. Drive</u>	<u>L.H. Drive</u>
XK.150 'S' Open 2-seater	-	831963

Cars with the above chassis numbers and onwards are fitted with a mechanically operated overdrive. The operating lever is mounted forward of the normal gearshift lever and will only allow the overdrive to operate on top gear.

To engage overdrive from top gear pull the lever rearward; to change down from overdrive to top gear push the lever forward. If a change is made direct from overdrive to third gear the lever will automatically disengage from overdrive.

Index Reference

Section F ✓

KNOCK-ON HUB CAPS - GERMANY ONLY

Models affected

All models fitted with wire wheels.

Cars now in production are fitted with special knock-on hub caps to comply with German safety regulations. These hub caps have shorter lugs and require the use of a special tool for removal and replacement. This removal tool fits over the hub cap and has suitable lugs to allow a copper mallet to be used.

/Cont'd...

(2)

The part numbers are as follows:-

Hub cap - right-hand	C.14891
Hub cap - left-hand	C.14892
Hub cap remover	C.14927

Index Reference

Section M ✓

DISC BRAKE HANDBRAKE SETTING


Models affected

All models fitted with disc brakes.

If complaints are received of the handbrakes being in need of frequent adjustment the following procedure should be carried out.

Check that there is a gap between the square spring retaining nut and the spring cage through which the adjuster bolt is screwed. If not, unscrew the adjuster bolt and proceed as follows:-

Prior to screwing the adjuster bolt into the 'self' locking nut, insert a screwdriver between the square spring retaining nut and the spring cage to partly compress the spring. Hold the locknut firmly against the trunnion and ensure that the adjuster bolt engages the threads of the locknut at the first turn. After screwing in the adjuster bolt three or four turns the screwdriver can be released from the spring cage and the normal adjustment carried out.



Insert screwdriver here

Index Reference

Section L ✓

SERVICE BULLETIN NO.265

Unscrew the two self-locking nuts which secure the air cleaner cover plate. Remove the cover plate when the paper element can be withdrawn taking care not to lose the distance pieces from the studs.

The maintenance instructions are as follows:-

Every 2,500 miles (4,000 km)

Remove the paper element and blow out the accumulated dirt with compressed air. Take care not to perforate the paper with the air line nozzle.

Every 10,000 miles (16,000 km)

Renew the paper element. (Part number C.15258)

Index Reference Section B

OIL FILTER CHANGING

Models affected

All models

It has come to our notice that oil filter elements are not being cleaned and changed at the recommended periods.

The importance of carrying out this service cannot be overstressed. Under conditions conducive to oil dilution and sludge formation more frequent changing of the element than the normal 5,000 miles is advised.

With a worn engine or when the car is used mainly for low speed, stop-start city driving the filter element should be changed every 2,500 miles.

NEVER CHANGE THE ENGINE OIL WITHOUT EITHER CLEANING OR CHANGING THE OIL FILTER ELEMENT.

Index Reference Section B ✓

WHEEL BALANCING WITH WHEELS ON CAR

Models affected

All models

If balancing equipment is used which dynamically balances the road wheels on the car, the following precaution should be observed.

In the case of the rear wheels always jack both wheels off the ground otherwise damage may be caused to the differential.

This is doubly important in the case of cars fitted with a Thornton "Powr-Lok" differential as in addition to possible damage to the differential, the car may drive itself off the jack or stand.

Index Reference Sections M ✓ and H ✓

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

S E R V I C E B U L L E T I N N O . 2 6 6

V A R I O U S S E R V I C I N G I T E M SO I L F I L T E R B L A N K I N G P L A T E

<u>Models affected</u>	<u>Commencing Engine numbers</u>
2.4 litre	BE.1582
3.4 litre	KF.7140
XK.150	V.6861

On cars with the above engine numbers and onwards the blanking plate C.12803 originally fitted between the oil filter and cylinder block is no longer used.

In conjunction with this change the following modifications are incorporated.

(1) Cylinder Block

The oil filter joint face on the cylinder block is modified as follows:-

- (a) The oil feed drilling for the centre main bearing is now threaded and blanked off with a grub screw.
- (b) The hole originally drilled completely through the crankcase is no longer drilled.

(2) Oil Filter

- (a) Shorter oil filter bolts are fitted.
- (b) Only copper washers are fitted under the bolt heads.
- (c) Only one gasket C.13091 is used between the filter and cylinder block.

(3) Oil Sump

The joint face flange of the sump is cut-a-way to clear the oil filter head casting.

The new part numbers are as follows:-

Part number	No. off
C.15950 Cylinder block - 2.4 litre	1
C.15951 Cylinder block - 3.4 litre XK.150	1
NB131/35D Oil filter bolt	1
NB131/13D " " "	2
NB131/25D " " "	1
C.15964 Oil sump 2.4 and 3.4 litre	1

InterchangeabilityCYLINDER BLOCK2.4 litre

The new cylinder block C.15950 can be used to replace cylinder block C.8611 on engines with a pressed steel sump which have an external return pipe from the oil pressure relief valve.

3.4 litre and XK.150

The new cylinder block C.15951 is interchangeable with cylinder

/Cont'd...

(2)

block C8610/1 when used on the 3.4 litre and XK.150 models.

Note: The new cylinder block is NOT interchangeable with cylinder block C.8610/1 when used on Mark VII, Mark VIII and XK.140 models that is, engines with a vertical oil filter.

OIL SUMP

The new sump C.15964 can be used to replace pressed steel sumps C.9155 and C.12386 fitted to the 2.4 litre and 3.4 litre models but if it is required to fit an early type sump to engines after the above engine numbers it will be necessary to file the edge of the sump flange to clear the oil filter head casting.

Index Reference Section B ✓

CHECKING AUTOMATIC TRANSMISSION FLUID LEVEL - REVISED INSTRUCTIONS

Models affected

All cars fitted with Automatic Transmission

To obtain a more accurate reading, the following method of checking the automatic transmission fluid level is now recommended.

1. Remove the cover plate from beneath the floor carpet to expose the dipstick. Clean the area around the dipstick hole.
2. With the car on a level floor, set the hand brake firmly. Set the selector lever in the P position and start engine. With the footbrake applied move the selector lever to L and raise the transmission fluid temperature by running the engine at 800 r.p.m. for 2 or 3 minutes.
3. Remove the dipstick and wipe it dry. With the foot still on the brake and the selector lever at L run the engine at its normal idling speed and check the fluid level. Add sufficient fluid to bring the level up to the "Full" mark on the dipstick. DO NOT OVERFILL. The space between the "Full" and "Low" marks on the dipstick represents approximately one pint.

Index Reference Section FF

SHELL AND B.P. AUTOMATIC TRANSMISSION FLUIDS - NEW SPECIFICATION

Models affected

All cars fitted with Automatic Transmission

The two following new automatic transmission fluids are now in production.

Shell, Donax T6 - AQ/ATF/844A

BP Energol ATF Type A Suffix A - AQ/ATF/1020A

These two fluids are much lighter in colour than the previous type fluids being similar colour to engine oil. They can, however, be mixed with the other Automatic fluids that we recommend.

Index Reference Section FF ✓

MAY, 1959

J A G U A R
S E R V I C E A N D S P A R E S O R G A N I S A T I O N
S E R V I C E B U L L E T I N N O . 2 6 7

25 AMP DYNAMO AND NEW VOLTAGE/CURRENT REGULATOR

<u>Models affected</u>	<u>Commencing Chassis numbers</u>	
	R.H. Drive	L.H. Drive
2.4 litre	913953	943437
3.4 litre	977762	992494
XK.150 Open 2-seater	-	832088
Drop Head Coupe	827273	838259
Fixed Head Coupe	824900	836222
Mark 1X	771237	790713

On cars with the above chassis numbers and onwards a 25 amp output dynamo and voltage/current regulator with a revised current setting are fitted.

The details are as follows:-

	<u>2.4 litre</u>	<u>3.4 litre</u>	<u>XK.150</u>	<u>Mark 1X</u>
Dynamo				
Jaguar part number	C.15256	C.15255	C.15255	C.15254
Lucas type	C45-FV-6	C45-FVS-6	C45-FVS-6	C45-PVS-6
Lucas part number	22489D	22496A	22496A	22528D
Voltage/current regulator				
Jaguar part number	C.15257	C.15257	C.15257	C.15257
Lucas type	RB.310	RB.310	RB.310	RB.310
Lucas part number	37297.F	37297.F	37297.F	37297.F

The revised current setting of the new voltage regulator is as follows:-

24 to 26 amperes at 4,000 dynamo r.p.m.

Interchangeability

- (i) The new voltage/current regulator is not interchangeable with the previous type fitted.
- (ii) The new 25 amp dynamo can be used to replace the previous type fitted.

Index Reference

Section P ✓

JAGUAR

SERVICE AND SPARES ORGANISATION

SERVICE BULLETIN NO. 268

VARIOUS SERVICING ITEMSELECTRIC REVOLUTION COUNTER - INTRODUCTION

<u>Models affected</u>	<u>Commencing Chassis numbers</u>	
	R.H. Drive	L.H. Drive
2.4 litre	915214	943590
3.4 litre	977860	992652
XK.150 Open 2-seater	820043	832088
Fixed Head Coupe	824905	836233
Drop Head Coupe	827373	838272
Mark IX	771820	791072

On cars with the above chassis numbers and onwards plus certain individual cars prior to these numbers an electrically operated revolution counter replaces the cable operated type.

The revolution counter instrument is energised by a small generator driven from the rear of the inlet camshaft. As the generator drive and mounting at the rear of the cylinder head is different to that for the right-angle cable drive, the cylinder head, inlet camshaft, inlet camshaft cover and gasket are modified to suit the new arrangement.

The details are as follows:-

	2.4 litre	Mark IX	XK.150
Electric Rev. Counter	C.14993	C.14995	C.14994
Instrument with Clock			
Harness for Electric Revolution Counter	C.15268	C.15268	C.15269
Revolution Counter Generator	C.14996	C.14996	C.14996
Driving Flaw	C.14989	C.14989	C.14989
Plate Washer	C.15918	C.15918	C.15918
Lock Washer (3 off)	C.15919	C.15919	C.15919
'O' Ring	C.14990	C.14990	C.14990
Setscrews (3 off)	C.14992	C.14992	C.14992
Cylinder Head	C.14955(2.4 litre) C.14956(3.4 litre)	C.14958	C.14956(XK.150) C.14957(XK.150'S')
Inlet Camshaft Cover	C.14987	C.14987	C.14987
Inlet Camshaft Cover Gasket	C.14988	C.14988	C.14988
Neoprene Sealing Ring	C.14991	C.14991	C.14991
Rear Bearing Cap	C.14984	C.14984	C.14984
Inlet Camshaft	C.14986(2.4 litre) C.14985(3.4 litre)	C.14985	C.14985

Interchangeability

Note that the new inlet camshafts detailed above are interchangeable with the previous types but the earlier type camshafts must NOT be fitted to cars with an electric revolution counter.

Index Reference

Sections B and P

CHANGING BRAKE DISCSModels affected

Cars fitted with disc brakes

There have been a number of cases of brake discs having been changed in the mistaken belief that they have been cracked. On examination the suspected crack has been found to be a grinding mark or a corrosion mark at a point where the handbrake pad has stopped against the disc.

Of the discs returned to us for examination not one has been found to be cracked.

Index Reference Section L ✓

REAR SPRING INTERLEAVING

Models affected

Mark VIII
Mark IX
XK.150

If on cars with nylon interleaved rear springs (see Service Bulletin No. 249) it is found that the interleaving has a tendency to work out from between the spring leaves, the ends of each rear spring should be bound with plastic or similar tape from the spring eyes to a point just short of the adjacent clip.

Index Reference Section K ✓

CLUTCH SLAVE CYLINDER BRACKET - STRENGTHENED TYPE

Models affected

Commencing Chassis numbers

R.H. Drive L.H. Drive

	R.H. Drive	L.H. Drive
Mark IX	771823	791081
XK.150 Open 2-seater	820043	832089
Fixed Head Coupe	824903	836227
Drop Head Coupe	827379	838273

On cars with the above chassis numbers and onwards a stronger type of clutch slave cylinder bracket is fitted. The new part numbers are as follows:-

	Part number
Mark IX	C.15706
XK.150	C.15709

Service Procedure

If, on cars prior to the above numbers, a case of the clutch not disengaging is experienced when the normal pedal adjustment is correct, an examination should be made to ascertain if the clutch slave cylinder mounting bracket is flexing when the clutch pedal is fully depressed.

If this is found to be so, a strengthened type of bracket should be fitted.

Index Reference Section E ✓

Addition to Service Bulletin No. 255

With the introduction of the 12-bladed fan on Home market 2.4 litre cars add the following commencing chassis number under the heading "12-bladed Fan - Introduction" ----- R.H. Drive
915349 ✓

Amendment to Service Bulletin No. 265

Amend the part numbers of the Rear caliper assembly for the 2.4 and 3.4 litre models to read as follows:-

Rear Caliper Assembly - right hand	C.15646	and not	C.14894 ✓
- left hand	C.15647		C.14895 ✓

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N


SERVICE BULLETIN NO. 269

VARIOUS SERVICING ITEMS6 $\frac{7}{8}$ " VACUUM SERVO - DIFFERENCE BETWEEN DRUM AND DISC BRAKE TYPEModels affectedCars fitted with 6 $\frac{7}{8}$ " diameter servo.

It will be noted that the 6 $\frac{7}{8}$ " servo unit used in conjunction with drum brakes varies from the unit used with disc brakes.

The only difference between the two servo's is that units used in conjunction with drum brakes incorporate a check valve (item 53a, Plate AW in the 2.4 litre Spare Parts Catalogue) and a rubber seat in the adaptor at the end of the slave cylinder whereas units for use with disc brakes do not have these parts fitted.

Note: On early units the check valve was incorporated in a separate housing as shown in Fig. 39 of Section L - 2.4/3.4 litre Service Manual.



There have been several instances of noise attributed to the rear axle, having in actual fact been due to one of the following causes.

1. Wind noise from roof-rack.
Re-test with rack removed.
2. Tread noise from non-standard tyres.
Re-test with standard tyres fitted.
3. Noises being conducted through sliding roof drain tubes (in rear wheel arches). Mark VII, VIII and LX models
Re-test with drain tubes blanked off with corks. (Remove corks after test).

<u>Index Reference</u>	Section H
<u>POWER STEERING RESERVOIR DIPSTICK</u>	
<u>Models affected</u>	
Mark VIII and Mark LX cars fitted with power-assisted steering	
The reservoir dipstick fitted to early power-assisted cars is marked "Use 10 W oil". This should be disregarded and only one of the recommended Automatic Transmission fluids used in the system.	
<u>Index Reference</u>	Section I

POWER STEERING RESERVOIR DIPSTICKModels affected

Mark VIII and Mark LX cars fitted with power-assisted steering

The reservoir dipstick fitted to early power-assisted cars is marked "Use 10 W oil". This should be disregarded and only one of the recommended Automatic Transmission fluids used in the system.

<u>Index Reference</u>	Section I

POWER STEERING UNIT - TOP OIL SEAL REPLACEMENTModels affected

Cars fitted with power-assisted steering

When removing the top end plate of the steering unit to replace the oil seal it is ESSENTIAL that the flange of the top adjustable ball race (Item 18, Plate CC of the Mark VIII Spare Parts Catalogue) is not allowed to lift otherwise the loose balls which form the upper ball race will drop into the box.

When refitting the top end plate, cover the serrations of the input shaft with cellulose tape or thin paper in order not to damage the lip of the seal.

Remove all traces of the tape or paper after the top end plate has been secured.

Index Reference Section I

FLUID LEAKAGE FROM AUTOMATIC TRANSMISSION UNITModels affected

Cars fitted with Automatic Transmission

Cases of fluid leakage from the transmission brought to our notice, have in most instances been caused by incorrect servicing such as neglecting to observe torque specifications or instructions regarding the use of new gaskets and washers.

As even slight leakage is likely to be accentuated by the high pressures under operational conditions, a considerable amount of fluid will be lost in a very short time. It is emphasized that any loss of fluid in excess of two pints (1 litre) will cause slip of the friction bands and clutches with risk of serious damage to the transmission.

It is imperative, therefore, that any cases of fluid loss reported is rectified without delay.

Index Reference Section FF

HIGH SETTING THERMOSTATSModels affected

2.4 litre
3.4 litre
Mark IX
XK.150

Special high temperature thermostats are available for countries where extreme winter conditions prevail. The details are as follows:

	Part Number	Opening Temperature
2.4 litre, 3.4 litre	C.13944/1	80/85° C.
Mark IX, XK.150	C.12867/1	80/85° C.

Index Reference Section D

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO.270

VARIOUS SERVICING ITEMS

6 $\frac{7}{8}$ " SERVO - INTRODUCTION OF CUP SPREADER


Models affected

Cars fitted with 6 $\frac{7}{8}$ " diameter servo unit

Current production servo units are fitted with a cup spreader in the slave cylinder.

This cup spreader (Part No. 7896) will be included in future repair kits and should be incorporated in all servo units undergoing overhaul.

The spreader is fitted between the cup and spring (Items 60 and 49 in Fig.41 of Section L, 2.4/3.4 litre Service Manual) with the concave side towards the spring. (See sketch).



Index Reference

Section L

(2)

GIRLING HYDRAULIC DAMPER - MODIFIED TYPE

<u>Model affected</u>	<u>Commencing Chassis Numbers</u>	
	<u>R.H. Drive</u>	<u>L.H. Drive</u>
Mark IX	772081	791442

On cars with the above chassis numbers and onwards modified hydraulic dampers are fitted at the front. These dampers are of the C.S.V. type and give consistent damping at all operating temperatures.

The part number is as follows:-

Front damper C.15999 2 off

Interchangeability

The new dampers are interchangeable with the previous type in pairs.

Index Reference Section J

HANDBRAKE ASSEMBLY - MODIFIED TYPE

<u>Model affected</u>	<u>Commencing Chassis Numbers</u>	
	<u>R.H. Drive</u>	<u>L.H. Drive</u>
Mark IX	772085	791445

On cars with the above chassis numbers and onwards rear calipers with modified handbrakes are fitted.

The handbrakes are of a stronger section and incorporate M.34 type handbrake pads of the quick change type. A brass retractor is now fitted to each handbrake to keep the handbrake pads clear of the disc when the handbrake is in the "off" position.

The part numbers are as follows:-

Rear Caliper assembly - right hand	C.15860
Rear Caliper assembly - left hand	C.15861
Right Hand Handbrake assembly	C.15858
Left Hand Handbrake assembly	C.15859
Right Hand Inner Pad Carrier	8022
Right Hand Outer Pad Carrier	8023
Left Hand Inner Pad Carrier	8025
Left Hand Outer Pad Carrier	8026
Operating Lever	8024
Handbrake Repair Kit (set of pads and fixings)	8021

Interchangeability

The new type handbrakes are not interchangeable with the previous type.

Spares Bulletin K.16 refers.

Index Reference Section L

2.4 litre (Mark 1) Model

COMPRESSION RATIO	TYPE OF CYLINDER HEAD	CAM LIFT	EXHAUST SYSTEM	CARBURETTER TYPE	CARBURETTER SETTINGS	DISTRIBUTOR		DISTRIBUTOR CONTACT BREAKER GAP	STATIC IGNITION TIMING	CHAMPION SPARKING PLUG TYPE & GAP	
						Jaguar Part Number	Lucas Service Number			Touring	Racing
7 to 1	Standard (Silver Top)	$\frac{5}{16}$ "	Single	Solex 23 mm Choke	Main Jet 110 Air Correction Jet 200 Pump Jet 55	C8789	40557A*	.014"-.016"	4° BTDC*	L.7 (.030")	L.5 (.030")
8 to 1	Standard (Silver Top)	$\frac{5}{16}$ "	Single	Solex 24 mm Choke	Main Jet 110 Air Correction Jet 180 Pump Jet 55	C11903	40528A	.014"-.016"	6° BTDC	N.5 (.030")	N.3 (.030")
8 to 1 Stage 1 Tuning	Standard (Silver Top)	$\frac{5}{16}$ "	Single Straight Through	Solex 26 mm Choke	Main Jet 120 Air Correction Jet 190 Pump Jet 60	C11903	40528A	.014"-.016"	6° BTDC	N.5 (.025")	N.3 (.025")
8 to 1 Stage 2 Tuning	Standard (Silver Top)	$\frac{3}{8}$ "	Single Straight Through	Solex 26 mm Choke	Main Jet 120 Air Correction Jet 190 Pump Jet 60	7068	40591A	.014"-.016"	8° BTDC	N.5 (.025")	N.3 (.025")
8 to 1 Stage 3 Tuning	'B' Type (Light blue top)	$\frac{3}{8}$ "	Twin	S.U. HD. 6 $1\frac{1}{4}$ " bore	T.O. Needles.	C13428	40584A	.014"-.016"	5° BTDC	N.5 (.025")	N.3 (.025")

Tuning Data
2.4 litre and 3.4 litre (Mark 1) Models

JAGUAR
SERVICE AND SPARES ORGANISATION
SERVICE BULLETIN No. 271

*Early cars were fitted with the 8 to 1 compression ratio distributor 40528A and the ignition timing set at 1° B.T.D.C.

3.4 litre (Mark 1) Model

COMPRESSION RATIO	TYPE OF CYLINDER HEAD	CAM LIFT	EXHAUST SYSTEM	CARBURETTER TYPE	CARBURETTER NEEDLES		DISTRIBUTOR		DISTRIBUTOR CONTACT BREAKER GAP	STATIC IGNITION TIMING	CHAMPION SPARKING PLUG TYPE & GAP	
					with Wire mesh air cleaner	with Oil bath air cleaner	Jaguar Part Number	Lucas Service Number			Touring	Racing
7 to 1	'B' Type (Light blue top)	$\frac{3}{8}$ "	Twin	S.U. HD. 6 $1\frac{1}{2}$ " bore	T.L.*	S.C.	C12733	40578A	.014"-.016"	TDC	L.7 (.025")	L.5 (.025")
8 to 1	'B' Type (Light blue top)	$\frac{3}{8}$ "	Twin	S.U. HD. 6 $1\frac{1}{2}$ " bore	T.L.*	S.C.	C12732	40576A	.014"-.016"	2° BTDC	N.5 (.025)	N.3 (.025")
9 to 1	'B' Type (Light blue top)	$\frac{3}{8}$ "	Twin	S.U. HD. 6 $1\frac{1}{2}$ " bore	T.L.*	S.C.	C14269	40617A	.014"-.016"	TDC	N.5 (.025")	N.3 (.025")

*L.B.I. needles fitted to early cars.

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO.273

VARIOUS SERVICING ITEMSVEHICLE OPERATION ON MOTORWAYS

The following points should be brought to the notice of owners who are likely to operate their cars on the new motorways.

Speeds

Do not maintain an engine speed in excess of 5,000 r.p.m. for any length of time.

Occasionally, release accelerator slightly and allow car to overrun for a few seconds.

Oil Pressure and Water Temperature Gauges

Occasionally check if the oil pressure and water temperature are normal, although there may be slight variations from normal after a long period of sustained high speed driving.

Tyre Pressures

Tyres should be inflated to a pressure of 6 lbs per sq. in above normal for sustained high speed driving (as already recommended in the Operating Handbooks).

Winter Grip Tyres

Although the advice of the particular tyre manufacturer should be taken on the question of maximum speeds with these types of tyre it is generally recommended that speeds in excess of 85 m.p.h. should not be maintained.

Index Reference

Section Q

CLAYTON DEWANDRE SERVO UNIT - IMPORTANCE OF FITTING PISTON RODModels affected

Mark VI1
Mark VI11

With reference to Service Bulletin No.260 and the introduction of the new repair kit Part No. 7876, it is pointed out that the piston rod (Part No. 1771) included in the kit must be fitted in conjunction with the new seals when overhauling the unit, even if the existing piston rod appears to be serviceable.

Index Reference

Section L

STICKING FORWARD SERVOModels affected

All cars fitted with Automatic Transmission

Symptoms

Car drives forward in Neutral, transmission drags in Reverse, normal operation in D and L selector positions.

Action

The reason for a sticking servo is not always obvious but the following action will normally effect a cure:-

- (1) Ensure that there are no burrs or ragged edges on the outside diameter of the piston.
- (2) If bore of servo is rough, polish with fine emery cloth.
- (3) Inspect hole in centre of the steel servo plate. Ensure that the piston moves freely in the hole which should have a smooth finish.
- (4) Refit servo, tightening bolts to a torque of 15/18 lbs ft.
- (5) Check forward and low band adjustments.

Index Reference Section FF

OVERDRIVE OPERATIONModels affected

Cars fitted with an overdrive

In the Mark 2 Operating Handbooks it is recommended that the overdrive should not be brought into operation at high speed with a wide throttle opening. The accelerator should be momentarily released when engaging the overdrive otherwise the cone clutch may stick and cause the overdrive to remain in engagement even though switched "out" and when in gears other than top.

This also applies to other overdrive models and as the new instructions appear to contradict the previous ones they should be brought to the notice of all service personnel.

Note: If the overdrive does not disengage at anytime, do not reverse the car otherwise damage may be caused to the unit. On some occasions it may be possible to disengage the cone clutch by tapping the cast iron brake ring, which is sandwiched between the front and rear casing of the overdrive, with a block of wood.

Index Reference Section F

NOVEMBER, 1959

J A G U A R

S E R V I C E A N D S P A R E S O R G A N I S A T I O N

SERVICE BULLETIN NO.274

VARIOUS SERVICING ITEMS

LACK OF SERVO ASSISTANCE

Models affected

3.4 litre
Mark VIII
XK.150

If on cars with the vacuum check valve in the underside of the inlet manifold (see Fig.17, 2.4/3.4 litre Service Manual) lack of servo assistance is experienced, the valve seal should be removed and examined for signs of swelling or hardening. If faulty, a replacement seal should be fitted.

Other causes of lack of servo assistance are:

- (i) Servo breather blocked.
- (ii) Vacuum hose(s) blocked.
- (iii) Dry vacuum piston leather in servo unit.

Index Reference

Section L

FITTING SNOW CHAINS - PRECAUTIONS

Models affected

Cars fitted with Disc Brakes

On cars fitted with disc brakes, strap-on type snow chains must not be fitted as the straps will foul the caliper bridge pipe. However, chains which fit completely around the periphery of the tyre can be used provided that the rear wing valances are removed.

Index Reference

Section M

DRAIN HOLES IN NEW TYPE REAR LAMPS


Models affected

Cars with new type tail lamps

A certain number of 1960 cars with the new type rear lamps (with separate flasher and tail light bulbs) were sent out of the factory without the drain holes in the bottom of the lamp lens.

Cars in stock or cars coming in for servicing should be checked for having two holes drilled in the bottom of the rear lamp lens. If not so drilled, two holes should be made in the bottom of the lens as shown in the sketch overleaf.

/Cont'd...



Index Reference Section P

TWIN LIP OIL SEAL - INTRODUCTION

Models affected

Commencing chassis numbers

Mark LX

R.H. Drive L.H. Drive

773282

792205

On cars with the above chassis numbers and onwards a twin lipped oil seal (Part number 8216) is fitted at the top of the power steering unit (Item 25 Plate CC in the Mark VIII Spare Parts Catalogue).

The twin lipped oil seal can be used to replace the previous type of seal 7588 but attention is drawn to the instructions given in Service Bulletin No. 269 page 2. The seal must be fitted with the circular spring facing the steering unit.

A dust shield (Part number C.16396) should be fitted in conjunction with the twin lipped seal.

This is fitted over the wormshaft, concave side downwards, and should be tapped down the shaft with a tubular punch until the top face of the shield is 1.5/16" (33.5 mm) below the top of the wormshaft.

Index Reference Section I

JAGUAR

SERVICE AND SPARES ORGANISATION

SERVICE BULLETIN NO. 275

HYDRAULIC BRAKE FLUIDS - IMPORTANT

The absolute importance of adhering to the instructions already given on the subject of hydraulic brake fluids is once again stressed and we will appreciate your bringing the following instructions to the notice of any of your staff who have anything to do with the servicing of the braking systems on Jaguar cars.

1. Use ONLY the recommended grades of brake fluids, as listed hereunder:

Wakefield Crimson Hydraulic Brake Fluid.	} Preferred fluids
Lockheed No. 102 Heavy Duty Brake Fluid.	
Delco Special No. 11 Brake Fluid	} Alternatives if preferred fluids not available.
Chrysler MS 3511 Brake Fluid.	
Wagner 21B Brake Fluid	

In countries where the above fluids are unobtainable use only a recognised brake fluid guaranteed to conform to the S.A.E. Specification 70 R.1

2. Great care must be taken that any container that is used either for the purpose of topping-up the reservoir or during the bleeding operation is perfectly clean and must not have previously contained any form of mineral oil that is, engine oil or paraffin etc.,

Containers used for these purposes must be cleaned only with methylated spirits. If this is not available, clear petrol should be used and the container thoroughly dried out and then rinsed with new brake fluid.

3. Brake fluid must in no circumstances be stored in containers which are left open to the atmosphere since the brake fluid can absorb water from the atmosphere with consequent reduction in boiling point.
4. It is preferable that brake fluid stocks should be held in small sealed containers, that is, $\frac{1}{2}$ pint, 1 pint or 1 quart tins so that there is no likelihood of small quantities being used from containers that have been standing with only a small quantity in them.
5. Clean the exterior of brake units such as master cylinders, wheel cylinders with petrol and not paraffin. Bear in mind when handling such units that cleanliness is of vital importance.
6. When dismantling brake units for overhaul or seal replacement do so on a bench free from any possible mineral oil contamination. Use a shallow tray kept solely for this purpose. Clean tray after use as described in paragraph 2 and use only one of the recommended brake fluids for cleaning internal parts.
7. Before removing the reservoir filler cap carefully clean the area around the cap with a clean non-fluffy rag and avoid the possibility of dirt or fluff entering the reservoir when the filler cap is removed.

/Cont'd...

8. Please impress on your staff that a high percentage of brake troubles arise through carelessness in servicing hydraulic systems and that if the above precautions are taken the possibility of such troubles occurring can be greatly reduced.

Index Reference Section L

EXHAUST SILENCERS AND TAILPIPES

Models affected

- Mark VIII
- Mark IX
- XK.150

Cars now in production have the tailpipes clipped to the silencers instead of being welded.

The new silencers (Part numbers unchanged) have saw cuts at the end of exit pipes which are of increased length to take the tailpipes.

The new silencers can be used to replace the previous welded type and the original tailpipe clipped to the silencer with the following parts:

Part number		No. off
C.13063	Clip	1
UFB131/22R	Bolt	1
FW105T	Washer	2
UFN131/L	Nut	1

When separating the old silencer from the tailpipe cut through the tailpipe immediately behind the point where it is welded to the silencer.

Index Reference Section M

JAGUAR

SERVICE AND SPARES ORGANISATION

SERVICE BULLETIN NO. 276

VARIOUS SERVICING ITEMSBRAKE FLUID LEVEL WARNING LIGHT CONVERSIONModels affected

- 2.4 litre Mark 1 cars with disc brakes
- 3.4 litre Mark 1 cars with disc brakes

This conversion is made available following a number of requests from Mark 1 2.4 litre and 3.4 litre owners for a similar brake fluid level warning device to that fitted to the Mark 2 models. This conversion does not incorporate the handbrake warning and it is suggested that as a check on the bulb, the float pin on the top of reservoir filler cap should be occasionally depressed when the bulb should light up.

Parts required:-

	<u>Jaguar Part No.</u>	<u>Lucas Part No.</u>
Warning light	C.16178	-
Escutcheon	C.16183	-
Bracket	C.16184	-
Filler cap	C.16177	-
"Lucar" connectors (female) 2 off	8193	54942078
Insulating sleeve 2 off	8194	54190042
Double snap connector (2.4 litre only)	3570	851868
Bullets	3585	900269

Modification to Glovebox

Remove the glovebox on the drivers side of the car (described on page P.40 of Section P, 2.4/3.4 litre Service Manual).

Make a 1.9/32" (32.5 mm) hole in a suitable position to take the warning light.

Fit the warning light bracket (C.16184) into the hole just made and secure with two wood screws.

From the rear of the escutcheon scrape off the word "Handbrake" and fill in with black cellulose.

Fit the warning light holder to the bracket and secure with the bezel and escutcheon from the front face of the glovebox.

Remove the existing filler cap from the brake fluid reservoir. If the fluid level is higher than 1/4" from the top of the filler neck drain the fluid by disconnecting pipe until the level is at this figure; this will allow for displacement of the float attached to the new filler cap. Fit the new filler cap and float (C.16177) to the existing reservoir.

Note: It may be necessary to lower the reservoir in its clip to ensure clearance between the filler cap and the bonnet.

Electrical Connections

Remove the dash casing.

1. On the 2.4 litre model fit a double snap connector in place of the single connector which feeds the mixture control warning light.

Take a cable from the connector to one of the connections on the warning light holder.

On the 3.4 litre model there is a loose cable (coloured green) behind the instrument panel. (This is the cable which feeds the mixture control warning light on the 2.4 litre model). Take a wire from the connector at the end of this cable to one of the connections on the warning light holder.

2. Take a cable from the other connection on the warning light holder to one of the connections on the reservoir filler cap.
3. Take a cable from the other connection on the filler cap to a good earth.

Note: The terminal connections on the filler cap are of the "Lucar" type and it will be necessary to fit connectors of this type to the ends of the two cables which are connected to the supply tank. To connect the cable to the "Lucar" connector, the cable should be bared back about 5/16", the wire strands passed through the 'D' flap, bent back and soldered to the underside of the connector. Care should be taken not to allow solder to run through the spring blade. The cable should be secured by crimping the cleats over the cable insulation. Fit the insulating sleeves.

After refitting the glovebox test the warning light by switching on the ignition and depressing the float pin on top of the reservoir filler cap when the warning light should become illuminated.

Index Reference

Section L

GUM DEPOSITS ON INLET VALVES

Models affected

All

We again refer to the above subject covered in Service Bulletin No.259 and stress the point that some present day fuels form gum deposits in a comparatively short space of time if a relatively small quantity of petrol is left in the tank(s). These deposits will result in sticking valves when the car is put into service.

Cars should not be stored with a small quantity of petrol in the tank(s). If the car is to be stored for a long period, drain the tank(s) and carburettors. If the storage period is likely to be only of short duration the tank(s) should be completely filled.

Index Reference

Section B

IMPORTANT

The attention of Distributors and Dealers is again drawn to the absolute importance of quoting letter references and chassis or other serial numbers when corresponding with the factory. A great deal of unnecessary delay and inconvenience is caused if this is not complied with.