



# Select HPE 79xx Switch Chassis, MPU, Module and Accessory Products

## Key Dates

Public End of Sale Announcement Date: June 14, 2019  
Planned End of Sale Date: November 30, 2019

## HPE Aruba Product End of Sale Announcement

HPE Aruba is planning to make the following product end of sale on the dates specified above or while supplies last.

END OF SALE SKU	DESCRIPTION	RECOMMENDED REPLACEMENT PRODUCTS
JG682A	HPE 7904 Switch Chassis	Indirect replacement are as follows: 5945 (see 5945 Data Sheet for details): <ul style="list-style-type: none"> <li>• HPE FF 5945 2-slot Switch (JQ075A)</li> <li>• HPE FF 5945 4-slot Switch (JQ076A)</li> </ul> 12900 (see 12900 Data Sheet for details): <ul style="list-style-type: none"> <li>• HPE FlexFabric 12902E Switch Chassis (JH345A)</li> <li>• HPE FlexFabric 12904E Switch Chassis (JH262A)</li> </ul>
JG683B	HPE 7900 12p 40GbE QSFP+ FX Mod	Indirect replacement are as follows: 5945 (see 5945 Data Sheet for details): <ul style="list-style-type: none"> <li>• HPE FF 5945 2-slot Switch (JQ075A)</li> <li>• HPE FF 5945 4-slot Switch (JQ076A)</li> </ul> 12900 (see 12900 Data Sheet for details): <ul style="list-style-type: none"> <li>• HPE FlexFabric 12902E Switch Chassis (JH345A)</li> <li>• HPE HPE FlexFabric 12904E Switch Chassis (JH262A)</li> </ul>
JG684A	HPE 7904 Frt(prt) Bck(pwr) Fan Tray	Indirect replacement are as follows: 5945 (see 5945 Data Sheet for details): <ul style="list-style-type: none"> <li>• HPE FF 5945 2-slot Switch (JQ075A)</li> <li>• HPE FF 5945 4-slot Switch (JQ076A)</li> </ul> 12900 (see 12900 Data Sheet for details): <ul style="list-style-type: none"> <li>• HPE FlexFabric 12902E Switch Chassis (JH345A)</li> <li>• HPE FlexFabric 12904E Switch Chassis (JH262A)</li> </ul>
JG841A	HPE 7910 Switch Chassis	Indirect replacement are as follows: 5945 (see 5945 Data Sheet for details): <ul style="list-style-type: none"> <li>• HPE FF 5945 2-slot Switch (JQ075A)</li> <li>• HPE FF 5945 4-slot Switch (JQ076A)</li> </ul> 12900 (see 12900 Data Sheet for details): <ul style="list-style-type: none"> <li>• HPE FlexFabric 12902E Switch Chassis (JH345A)</li> <li>• HPE FlexFabric 12904E Switch Chassis (JH262A)</li> </ul>




END OF SALE SKU	DESCRIPTION	RECOMMENDED REPLACEMENT PRODUCTS
JG842A	HPE 7910 7.2Tbps Fabric/MPU	<p>Indirect replacement are as follows:                      5945 (see 5945 Data Sheet for details):</p> <ul style="list-style-type: none"> <li>• HPE FF 5945 2-slot Switch (JQ075A)</li> <li>• HPE FF 5945 4-slot Switch (JQ076A)</li> </ul> <p>12900 (see 12900 Data Sheet for details):</p> <ul style="list-style-type: none"> <li>• HPE FlexFabric 12902E Switch Chassis (JH345A)</li> <li>• HPE FlexFabric 12904E Switch Chassis (JH262A)</li> </ul>
JG843A	HPE 7910 Frt(prt) Bck(pwr) Fan Tray	<p>Indirect replacement are as follows:                      5945 (see 5945 Data Sheet for details):</p> <ul style="list-style-type: none"> <li>• HPE FF 5945 2-slot Switch (JQ075A)</li> <li>• HPE FF 5945 4-slot Switch (JQ076A)</li> </ul> <p>12900 (see 12900 Data Sheet for details):</p> <ul style="list-style-type: none"> <li>• HPE FlexFabric 12902E Switch Chassis (JH345A)</li> <li>• HPE FlexFabric 12904E Switch Chassis (JH262A)</li> </ul>
JG845A	HPE 7900 24p 1/10GbE SFP+ FX Mod	<p>Indirect replacement are as follows:                      5945 (see 5945 Data Sheet for details):</p> <ul style="list-style-type: none"> <li>• HPE FF 5945 2-slot Switch (JQ075A)</li> <li>• HPE FF 5945 4-slot Switch (JQ076A)</li> </ul> <p>12900 (see 12900 Data Sheet for details):</p> <ul style="list-style-type: none"> <li>• HPE FlexFabric 12902E Switch Chassis (JH345A)</li> <li>• HPE FlexFabric 12904E Switch Chassis (JH262A)</li> </ul>
JH001A	HPE 7910 2.4Tbps Fabric/MPU	<p>Indirect replacement are as follows:                      5945 (see 5945 Data Sheet for details):</p> <ul style="list-style-type: none"> <li>• HPE FF 5945 2-slot Switch (JQ075A)</li> <li>• HPE FF 5945 4-slot Switch (JQ076A)</li> </ul> <p>12900 (see 12900 Data Sheet for details):</p> <ul style="list-style-type: none"> <li>• HPE FlexFabric 12902E Switch Chassis (JH345A)</li> <li>• HPE FlexFabric 12904E Switch Chassis (JH262A)</li> </ul>
JH002A	HPE 7900 2p 100G/6p 40G/4p 10G FX Mod	<p>Indirect replacement are as follows:                      5945 (see 5945 Data Sheet for details):</p> <ul style="list-style-type: none"> <li>• HPE FF 5945 2-slot Switch (JQ075A)</li> <li>• HPE FF 5945 4-slot Switch (JQ076A)</li> </ul> <p>12900 (see 12900 Data Sheet for details):</p> <ul style="list-style-type: none"> <li>• HPE FlexFabric 12902E Switch Chassis (JH345A)</li> <li>• HPE FlexFabric 12904E Switch Chassis (JH262A)</li> </ul>
JH041A	HPE 7910 Cable Management Frame	<p>Indirect replacement are as follows:                      5945 (see 5945 Data Sheet for details):</p> <ul style="list-style-type: none"> <li>• HPE FF 5945 2-slot Switch (JQ075A)</li> <li>• HPE FF 5945 4-slot Switch (JQ076A)</li> </ul> <p>12900 (see 12900 Data Sheet for details):</p> <ul style="list-style-type: none"> <li>• HPE FlexFabric 12902E Switch Chassis (JH345A)</li> <li>• HPE FlexFabric 12904E Switch Chassis (JH262A)</li> </ul>

For warranty and support information  
[hpe.com/networking/warranty](https://www.hpe.com/networking/warranty)



## Product End of Sale Announcement

 Share with colleagues

---

---

© Copyright 2019 Hewlett Packard Enterprise Development LP. The information contained herein is subject to change without notice. The only warranties for Hewlett Packard Enterprise products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. Hewlett Packard Enterprise shall not be liable for technical or editorial errors or omissions contained herein.

July 2019

