



End of Sale Announcement – UPDATED 23-Jan-12

Select HP A8800 Routers and Modules

Announcement Date: 1-September-11

Target End of Sale Date: 1-October-11 or while supplies last

Select HP A8800 Routers and Modules

The following HP routers and modules indicated below have served HP customers for years. Due to market factors and HP product strategy, we are announcing the end of sale of the devices effective October 1, 2011 and are releasing some new next generation modules respectively.

The End of Sale of HP A8800 Routers and modules are listed below:

Planned End of Sale (ES) Product	
Product Number	Product Description
JC147B	HP A8802 Router Chassis
JC141A	HP A8802 Main Control Unit Module
JC146A	HP A8802 800W 90-264V AC Power Supply
JC140A	HP A8802 1300W 36-92V DC Power Supply
JC138A	HP A8805/08/12 (1E) Main Control Unit Module
JC137A	HP A8805/08/12 (2E) Main Control Unit Module
JC139A	HP Single Service Processing Engine A8800 Module
JC142A	HP Dual Service Processing Engine A8800 Module
JC144A	HP A8800 NAT Processing Module

Below is a table of the affected products and replacement SKUs:

Recommended Replacement Products

Planned End of Sale (ES) Product		Recommended Replacement Product(s)	
Product Number	Product Description	Product Number	Product Description
JC147B	HP A8802 Router Chassis	N/A	
JC141A	HP A8802 Main Control Unit Module	N/A	
JC146A	HP A8802 800W 90-264V AC Power Supply	N/A	
JC140A	HP A8802 1300W 36-92V DC Power Supply	N/A	
JC138A	HP A8805/08/12 (1E) Main Control Unit Module	JC597A	HP A8800 Single Fabric Main Processing Unit
JC137A	HP A8805/08/12 (2E) Main Control Unit Module	JC596A	HP A8800 Dual Fabric Main Processing Unit
JC139A	HP Single Service Processing Engine A8800 Module	JC598A	HP A8800 Single Processor Service Engine Module
JC142A	HP Dual Service Processing Engine A8800 Module	JC599A	HP A8800 Dual Processor Service Engine Module
JC144A	HP A8800 NAT Processing Module	JC607A	HP A8800 Network Address Translation Service Module

EOS Products & Replacement Products Compatibility Table:

MPU/SPE Module Compatibility Table

Modules	SPE-1010 (JC139A)	SPE-1020 (JC142A)	SPE-1010-II (JC598A)	SPE-1020-II (JC599A)	MCU-1E (JC138A)	MCU-2E (JC137A)	MPU-1F (JC597A)	MPU-2F (JC596A)
MCU-1E (JC138A)	√	√	√	√	√	×	×	×
MCU-2E (JC137A)	√	√	√	√	×	√	×	×
MPU-1F (JC597A)	√	√	√	√	×	×	√	×
MPU-2F (JC596A)	√	√	√	√	×	×	×	√
SPE-1010 (JC139A)	√	√	√	√	√	√	√	√
SPE-1020 (JC142A)	√	√	√	√	√	√	√	√
SPE-1010-II (JC598A)	√	√	√	√	√	√	√	√
SPE-1020-II (JC599A)	√	√	√	√	√	√	√	√

Q&A

- Can a HP A8805/08/12 (1E) Main Control Unit Module (JC138A) co-exist with a HP A8800 Single Fabric Main Processing Unit (JC597A) or a HP A8805/08/12 (2E) Main Control Unit Module (JC137A) co-exist with a HP A8800 Dual Fabric Main Processing Unit (JC596A)(and vice versa)?**
A: No
- Can one have a mixed HP A8800 Single Service Processing Engine Module (JC139A) / HP A8800 Single Processor Service Engine Module (JC598A) / HP A8800 Dual Service Processing Engine Module (JC142A) / HP A8800 Dual Processor Service Engine Module (JC599A)?**
A: Yes

Replacement Products

Each of these products may have one possible replacement products listed. Product functionalities and product lines are regularly evolving. Therefore we strongly recommend our customers to check the latest up to date portfolio information on www.hp.com to assess what is the best alternative for them.

HP Warranty

For warranty and support information, please refer to the below link:

www.hp.com/networking/warranty