RADIO SEALING REPORT

UNITED STATES COAST GUARD Captain of the Port San Francisco

-- 11 4

Dete 10/31/43 Time of			
Vessel Horace Greeley Class Steam Ship Nationality American			
Owners/Operators Meratime	Commission	Master Otto Gr	ent
REPAIRS TO RADIO APPARATUS			
The repairs to radio apparatus are necessary as follows:			
Transmitter Not Tested			

			MASTER
	DESCRIPTION O	F RADIO APPARATUS	file gas albert of the
Transmitters: Senior radio operator C. W. Austin			
Number 1 :: Type # ET-8024	Manufactured	by RGA	Power 200-Watts
			400-425-454-468-500-Kcs
Number 2 :: Type #			
		Calibrated to	
Emergency: Type #ET-8025			
			400-425-454-468-500-Kcs
Lifeboat :: Type #ET-8026			
Frequency range 500-Kcs Calibrated to 500-Kcs			
Receivers: Type #	Manufacture	l by Frequency ran	nge Location
Number 1 ; AR-8510	ReA	14-650-Kes	Radio Room
Number 2 ; C	RCA	350-515-Kes	Radio Room
Number 3 ;			
Number 4 ;			
Lifeboat ;			
Direction Finder; STO	ATTOW RCA	270-520-Kes	Chart Room
Auto - Alarm; AR-8601	RCA	**************************************	Radio Room
(Over)			

Copy to: Port Director

12th Naval District

Room 447 - Federal Office Building
Federal Communications Commission,

328 Custom House