

# RESERVOIRS

## DORMAN OE FIX SOLUTIONS

### Dorman Engineered Solutions to Known OE Problems



**603-5103**

International 2008-03

**OE Numbers:**

2508700C91, 2508700C92,  
2508700C93, 3565217F93

#### PRESSURIZED COOLANT RESERVOIR

- Comes with reservoir cap
- Improved design removing OE failure points
- Direct replacement for a proper fit every time
- Quality tested to ensure trouble-free installation and performance



#### OE PROBLEM:

Original design is constructed out of black plastic and relies on fluid level indicator ports to gage fluid levels. These ports are often the source for fluid leaks.



Changed tank construction material to a clear plastic that improves reading fluid levels, eliminating the need for fluid level indicator ports, lessening the risk for fluid leaks.



**603-5107**

International 2011-01

**OE Numbers:**

2587216C1, 2591802C2

#### PRESSURIZED COOLANT RESERVOIR

- Direct replacement for a proper fit every time
- Comes with reservoir cap
- Level sensor included (where applicable)
- Quality tested to ensure trouble-free installation and performance



#### OE PROBLEM:

Original design is constructed out of black plastic, making it difficult to determine fluid level.



Changed tank construction material to a clear plastic that improves reading fluid levels without the need of opening reservoir cap.

**Growing the Heavy Duty Aftermarket**

# RESERVOIRS

## DORMAN OE FIX SOLUTIONS

### Dorman Engineered Solutions to Known OE Problems



**603-5206**

Freightliner 2014-08

**OE Numbers:**

A1414796003,  
A1419133000

#### POWER STEERING RESERVOIR

- Includes reservoir cap and dipstick (where applicable)
- Direct replacement for a proper fit every time
- Weather-resistant
- Rigorous quality control measures have been undertaken to ensure that this part conforms to product standards



#### OE PROBLEM:

The OE cap that connects to the internal filter gets locked into place after use and is often broken during filter replacement. If the OE cap breaks, installer is forced to purchase a full reservoir.



Dorman OE fix adds a hex-head to the base of the hose port on this cap to allow for easy removal and filter replacement.



**603-5106**

International 2016-12,  
International 2010-02

**OE Numbers:**

3558153C93, 3558153C94,  
3558303C4, 3569593C93,  
4043516C91

#### POWER STEERING RESERVOIR

- Includes reservoir cap, dipstick and filter (where applicable)
- Direct replacement for a proper fit every time
- Weather-resistant
- Rigorous quality control measures have been undertaken to ensure that this part conforms to product standards



#### OE PROBLEM:

Due to the part's placement in the vehicle, the original design allowed for debris to enter under the cap, damaging the internal gasket.



Replaced the OE designed cap with an improved threaded cap; which provides a better seal to keep road debris from entering the reservoir.

### Growing the Heavy Duty Aftermarket