



A subsidiary of Pinnacle West Capital Corporation

June 5, 2002

Ms. Nancy Bruce, Senior Project Manager, PVNGS
Mr. Steve Kessler, Electrical Engineering Section Leader, PVNGS
Mr. Harvey Leake, Senior Consulting Engineer, PVNGS
Mr. Stephen Peace, Owner Services Consultant, PVNGS

Dear Ms. Bruce and Messrs. Kessler, Leake, Peace:

Enclosed for your records is a copy of the final report for the 2002 Palo Verde-Hassayampa Operating Study: A Sensitivity Study Evaluating a Single-Line-to-Ground Fault at Palo Verde with 7% Generation Margin and 900 MVARs Bucking. Authored by Tom Isham of APS, this report represents the completion of a significant effort to identify the stability limits for the Palo Verde/Hassayampa Common Bus.

Should you have any questions on this matter, please contact Tom Isham at (602) 250-1499 or at Tommy.Isham@aps.com.

Sincerely,

Robert Smith

Cc: Tom Isham

Digitally signed by 60326
cn=60326, ou=9
o=DEEG, c=US
Date: 2002.06.12 13:55:00
-07'00'
Reason: Received from APS
Transmission Operations
Harvey Leake

A/11

2002 PALO VERDE/HASSAYAMPA SUPPLEMENTARY OPERATING STUDY REPORT

L. INTRODUCTION

This report documents a supplementary study to determine the plant operating limits for several new categories. Those categories include increased bucking of the Palo Verde generating units up to 780MVARs bucking and facilities initially out of service in the Palo Verde/Hassayampa area. The critical outage is the double line Palo Verde-Westwing outage initiated by a single-line-to-ground fault for all categories except one Palo Verde-Westwing line out. The fault and the lines were cleared in four cycles. The initially out of service categories included the following facilities:

Series Capacitors out of service in the following lines:

1. Hassayampa-North Gila-Imperial Valley-Miguel 500kV line
2. Hassayampa-North Gila 500kV line
3. North Gila-Imperial Valley-Miguel 500kV line
4. Palo Verde-Devers 500kV line two segments
5. Palo Verde-Devers 500kV line one segment out on the Arizona side

Lines out of service:

6. Hassayampa-North Gila 500kV line
7. Hassayampa-Kyrene 500kV line
8. Palo Verde-Devers 500kV line
9. One Palo Verde-Westwing 500kV line

With one Palo Verde-Westwing 500kV line out, the critical outage is loss of the remaining Westwing line but initiated by a three-phase fault. The single-line-to-ground fault only applies to a double line outage.

II. RESULTS/CONCLUSIONS

The original study was most limited by the light spring base case with the Palo Verde/Hassayampa units bucking and the double line outage of the Palo Verde-Westwing 500kV lines. The Light Spring base case with three Palo Verde units and all three new units (1600 MW of new generation) represented and the units bucking a total of approximately 450 MVARs was the starting point for this study. The voltage at Palo Verde was represented at 525kV, which again produced the most conservative results. The study results are summarized in Tables 1 through 4. A summary of the new operating limits for the new categories can be seen in Table 5 and Figure 1.

All lines in service with Palo Verde units bucking up to 780MVARs.

The original SLG study evaluated the Palo Verde units bucking up to 450MVARs. The results from that study indicated that the system was stable with 1600MW of additional generation. This study evaluated increasing the amount of bucking at Palo Verde from 450MVARs to 780MVARs. The results indicate that 1600MW of new generation for a

total of 5461MW of Palo Verde/Hassayampa generation can be realized up to 565MVARs bucking. Beyond 565MVARs, the total generation has to be reduced. A second point was found at 780MVARs bucking. At 780MVARs bucking, the total generation had to be reduced to 5361MW. From these two points, the operating nomogram shown in Figure 1 was obtained up to a total of 1000MVARs bucking. The powerflow base cases and stability results are summarized in Table 1.

Series capacitors initially-out-of-service.

The results for series capacitors initially out of service are summarized below. Tables 2 and 3 summarize the powerflow and stability results for all categories.

1. Hassayampa-North Gila-Imperial Valley-Miguel 500kV line

With all the series compensation out of the Hassayampa to Miguel line(3 segments), the stability limit without unit tripping was reduced from 5461MW to 5261MW. An increase of 100MW more resulted in an unstable case. Unit tripping 500MW with the maximum generation output of 5461MW was stable.

With two new units on at Hassayampa with 1100MW for a total of 4961MW, the single-line-to-ground fault and double line outage was stable.

2. Hassayampa-North Gila 500kV line

With the series compensation out of the Hassayampa to North Gila line, the stability limit without unit tripping was reduced from 5461MW to 5411MW. The limitation was the 40-cycle voltage dip duration at the Palo Verde 500kV bus. Unit tripping 160MW with the maximum generation output of 5461MW was stable.

3. North Gila-Imperial Valley-Miguel 500kV line

With the series compensation out of the North Gila to Miguel line, the stability limit without unit tripping was reduced from 5461MW to 5411MW. The limitation was the 40-cycle voltage dip duration at the Palo Verde 500kV bus. Unit tripping 160MW with the maximum generation output of 5461MW was stable.

4. Palo Verde-Devers 500kV line two segments

With all the series compensation out of the Palo Verde to Devers line(2 segments), the stability limit without unit tripping was reduced from 5461MW to 5261MW. An increase of 100MW more resulted in an unstable case. Unit tripping 500MW with the maximum generation output of 5461MW was stable.

With two new units on at Hassayampa with 1100MW for a total of 4961MW, the single-line-to-ground fault and double line outage was stable.

5. Palo Verde-Devers 500kV line one segment out on the Arizona side

With the series compensation segment out of the Palo Verde to Devers line on the Arizona side of the line, the stability limit without unit tripping was reduced from 5461MW to 5361MW. The limitation was the 40-cycle voltage dip duration at the

Palo Verde 500kV bus. Unit tripping 320MW with the maximum generation output of 5461MW was stable.

Lines out of service:

6. Hassayampa-North Gila 500kV line

With the Hassayampa to North Gila line initially out of service, the stability limit is 3601MW. An increase of 100MW more resulted in an unstable case. This was with the Palo Verde generating units bucking a net 300MVARs.

7. Hassayampa-Kyrene 500kV line

With the Hassayampa to Kyrene line initially out of service, the stability limit is 3152MW. An increase of 50MW more resulted in an unstable case. This was with the Palo Verde generating units bucking a net 235MVARs.

8. Palo Verde-Devers 500kV line

With the Palo Verde to Devers line initially out of service, the stability limit is 3701MW. An increase of 100MW more resulted in an unstable case. This was with the Palo Verde generating units bucking a net 294MVARs.

9. One Palo Verde-Westwing 500kV line

For this category, the critical outage is loss of the remaining Palo Verde-Westwing line initiated by a three-phase fault at Palo Verde. With the three new units on line, the stability limit was 5111MW, 1250MW above the 3861MW maximum Palo Verde generation level. This was with the Palo Verde generating units bucking a net 230MVARs. This was consistent with the original all lines in service operating study that evaluated a three-phase fault with the double line outage. The results for two units were taken from that original study. The stability limit with two units generating 790MW was 4651MW. This was with the Palo Verde generating units bucking a net 363MVARs. Unit tripping was not applied. The result for one unit was taken from that original study. The stability limit with one unit generating 410MW was 4271MW. This was with the Palo Verde generating units bucking a net 321MVARs. Unit tripping was not applied.

FIGURE 1
2002 PALO VERDE/HASSAYAMPA OPERATING LIMITS
WITH UP TO THREE NEW UNITS ON LINE
(MAXIMUM 1600 MW)




TABLE 1
2002 SINGLE-LINE-TO-GROUND SUPPLEMENTARY STABILITY STUDY SUMMARY
ALL LINES IN SERVICE

SE O.	PRE-PROJECT CASE DESCRIPTION	POWER FLOW (MW)										COMMENTS	
		SCIT FLOW	EOR FLOW	PDCI FLOW	PV+HASS VAR FLOW	PV GEN GROSS	PV NET VARS	HASS NET VARS	NEW GEN	PV WEST	PV EAST	PV/HSP TOT	
A - (02LSP-567ME1600)		10522	3977	1858	-168	4056	-567	9	1600	1980	3473	5453	2 REDHAWK + 1 ARLINGTON
B - (02LSP-780ME1500)		10524	3986	1859	-31	4056	-781	3	1500	1970	3383	5353	2 REDHAWK + 1 ARLINGTON

	STABILITY RESULTS			COMMENTS
	BUS	Vdip	%	
BAE\$LG FLT TWO PV-WWG	PV500	0.820	21.9%	Stable and well damped; another 50MVARs unstable
BAE\$LG FLT TWO PV-WWG	PV500	0.745	29.0%	Stable and well damped; another 50MW unstable

TABLE 2
2002 SINGLE-LINE-TO-GROUND STUDY SUMMARY
PALO VERDE/HAGSAYAMPA POWER FLOW SUMMARY TABLE

CASE NO.	PRE-PROJECT CASE DESCRIPTION	POWER FLOW (MW)										COMMENTS	
		SCT FLOW	EDR FLOW	PDCI FLOW	PV-HASS VAR FLOW	PV GEN GROSS	PV NET VARS	HASS NET VARS	NEW GEN	PV WEST	PV EAST	PV/HSP TOT	
A - (P2LSP-430ME1600)		10522	3979	1858	-111	4056	429	9	1600	1982	3471	5153	2 REDHAWK + 1 ARLINGTON
B - (P2LSP-HASNIGSC1400)		10523	3928	1859	-191	4056	462	6	1400	1805	3448	5253	2 REDHAWK + 1 ARLINGTON
B1 - (P2LSP-HASNIGSC)		10523	3946	1859	-175	4056	441	9	1600	1830	3623	5153	2 REDHAWK + 1 ARLINGTON
B2 - (P2LSP-HASNIGSC1100)		10525	3905	1859	-109	4056	483	-15	1100	1774	3159	4933	1 REDHAWK + 1 ARLINGTON
C - (P2LSP-HASNIGSC1500)		10528	3948	1857	-132	4056	450	9	1500	1881	3522	5153	2 REDHAWK + 1 ARLINGTON
C1 - (P2LSP-HASNIGSC)		10528	3955	1848	-105	4056	393	9	1600	1888	3565	5153	2 REDHAWK + 1 ARLINGTON
D - (P2LSP-HGMIGSC1500)		10529	3960	1847	-201	4056	495	4	1500	1897	3506	5153	2 REDHAWK + 1 ARLINGTON
D1 - (P2LSP-HGMIGSC)		10521	3964	1847	-192	4056	483	9	1600	1902	3551	5153	2 REDHAWK + 1 ARLINGTON
E - (P2LSP-PVDVSC1400)		10522	3928	1847	15	4056	441	6	1400	1722	3531	5253	2 REDHAWK + 1 ARLINGTON
E1 - (P2LSP-PVDVSC)		10522	3944	1847	22	4056	450	9	1600	1745	3708	5153	2 REDHAWK + 1 ARLINGTON
E2 - (P2LSP-PVDVSC1100)		10522	3903	1847	17	4056	468	-15	1100	1693	3240	4933	1 REDHAWK + 1 ARLINGTON
F - (P2LSP-PVDVSC1500)		10522	3947	1847	9	4056	462	9	1500	1808	3545	5153	2 REDHAWK + 1 ARLINGTON
F1 - (P2LSP-PVDV150)		10522	3955	1847	9	4056	438	9	1600	1817	3636	5153	2 REDHAWK + 1 ARLINGTON
G - (P2LSP-HANG3601)		10291	3497	1847	-79	3156	311	-24	0	1098	2582	3601	
H - (P2LSP-HAKYR3152)		10269	3651	1847	48	3406	233	-24	0	1705	1448	3153	
I - (P2LSP-PVDV3701)		10243	3514	1847	13	3356	193	-24	0	979	2722	3701	

TABLE 3
2002 SINGLE-LINE-TO-GROUND STUDY SUMMARY
PALO VERDE/HASSAYAMPA STABILITY SUMMARY TABLE

			STABILITY RESULTS		COMMENTS
			BUS	VdIp	
ST-1 BASE A*	SLG FLT TWO PV-WWG	PV500	0.840	20.0%	Stable and well damped
ST-2 BASE B	SLG FLT TWO PV-WWG	PV500	0.790	24.8%	Stable and well damped; unstable with 100MW more
ST-3 BASE B1	SLG FLT 2 PV-WWG OUT U/T RED 500MW	PV500	0.770	26.7%	Stable and well damped
ST-4 BASE B2	SLG FLT 2 PV-WWG OUT	PV500	0.780	27.6%	Stable and well damped
ST-5 BASE C	SLG FLT TWO PV-WWG	PV500	0.76	27.6%	Stable and well damped; 40 cycle duration
ST-6 BASE C1	SLG FLT 2 PV-WWG OUT U/T RED 160MW	PV500	0.78	25.7%	Stable and well damped
ST-7 BASE D	SLG FLT TWO PV-WWG	PV500	0.78	25.7%	Stable and well damped; 38 cycle duration
ST-8 BASE D1	SLG FLT 2 PV-WWG OUT U/T RED 160MW	PV500	0.79	24.8%	Stable and well damped
ST-9 BASE E	SLG FLT TWO PV-WWG	PV500	0.780	25.7%	Stable and well damped; 40 cycle duration
ST-10. BASE E1	SLG FLT 2 PV-WWG OUT U/T RED 500MW	PV500	0.750	28.8%	Stable and well damped; 40 cycle duration
ST-11 BASE E2	SLG FLT 2 PV-WWG OUT	PV500	0.770	26.7%	Stable and well damped
ST-12 BASE F	SLG FLT TWO PV-WWG	PV500	0.780	25.7%	Stable and well damped; 38 cycle duration
ST-13 BASE F1	SLG FLT 2 PV-WWG OUT U/T RED 320MW	PV500	0.780	25.7%	Stable and well damped; 40 cycle duration
ST-14 BASE G	SLG FLT TWO PV-WWG	PV500	0.770	28.7%	Stable and well damped; unstable with 100MW more
ST-15 BASE H	SLG FLT TWO PV-WWG	PV500	0.820	21.9%	Stable and well damped; unstable with 50MW more
ST-16 BASE I	SLG FLT TWO PV-WWG	PV500	0.750	28.6%	Stable and well damped; unstable with 100MW more

* Base case identifying letter can be found in Table 2.

TABLE 4
2002 SINGLE-LINE-TO-GROUND SUPPLEMENTARY STABILITY STUDY SUMMARY
ONE PALO VERDE-WESTWING 500KV LINE INITIALLY OUT OF SERVICE

CASE NO.	PRE-PROJECT CASE DESCRIPTION	POWER FLOW (MW)												COMMENTS
		SCIT FLOW	EOR FLOW	PDCI FLOW	PV-HASS VAR FLOW	PV GEN GROSS	PV NET VARS	HASS NET VARS	NEW GEN	PV WEST	PV EAST	PV/HSP TOT		
J - #2LSP-231PVIWW1250)	10522	3968	1858	-120	4058	-21	14	1250	2073	3030	5103	2 REDHAWK + 1 ARLINGTON		
K - #2LSP-R450A360)*	10271	3721	1859	-32	4056	-33	-29	810	1774	2877	4651	1 REDHAWK + 1 ARLINGTON		
L - #2LSP-1R450)*	10271	3669	1859	-16	4056	-31	-25	450	1721	2550	4271	1 REDHAWK or 1 ARLINGTON		
		<u>STABILITY RESULTS</u>			<u>COMMENTS</u>									
#1 BASE J 3P FLT PV-WWG OUT	PV500	0.820	21.9%		Stable and well damped; another 50MW unstable									
#2 BASE K 3P FLT PV-WWG OUT	PV500	0.720	31.4%		Stable and well damped; another 50MW unstable									
#3 BASE L 3P FLT PV-WWG OUT	PV500	0.730	30.5%		Stable and well damped; another 50MW unstable									

* Results taken from original study titled "2002 Palo Verde/Hesseyampa Operating Study".


TABLE 5
2002 SINGLE-LINE-TO-GROUND SUPPLEMENTARY STUDY
OPERATING LIMITS

CATEGORY	Maximum Net Generation Level at :			Total Generation	Amount of Hass. Generation required to tripped
	Palo Verde	Hassayampa	# of New Units		
All lines in service	3861	1600	3	5481(-565MVARs)	N/A
All lines in service (See Nomogram in Figure 1)	3861	1510	3	5361(-780MVARs)	N/A
Hassayampa-Miguel series comp. Bypassed	3861	1400	3	5261	N/A
	3861	1600	3	5461	660
	3861	1100	2	4961	N/A
Hassayampa-N.Gila series comp. Bypassed	3861	1850	3	5411	320
	3861	1600	3	5461	N/A
N.Gila-Miguel series comp. Bypassed	3861	1550	3	5411	320
	3861	1600	3	5461	N/A
Palo Verde-Devers series comp.	3861	1400	3	5261	N/A
	3861	1600	3	5461	660
Bypassed(2 segments)	3861	1100	2	4961	N/A
Palo Verde-Devers series comp.	3861	1500	3	5361	500
Bypassed(1 seg. In AZ)	3861	1600	3	5461	N/A
Hassa.-N.Gila line Initially out of service	3601	0	0	3601	N/A
Hassa.-Kyrene line Initially out of service	3152	0	0	3152	N/A
PV-Devers line Initially out of service	3701	0	0	3701	N/A
One PV-WWG line Initially out of service	3861	1250	3	5111	N/A
	3861	790*	2	4741	N/A
	3861	410*	1	4271	N/A

* Obtained from the original study titled "2002 Palo Verde/Hassayampa Operating Study".

Arizona 500 & 345kV EHV System

AZ50002a_hg11a.drw



General Electric International, Inc. PRF Program

APS
TRANSMISSION
OPERATIONS


WESTERN SYSTEMS COORDINATING COUNCIL
2002 LSP2 OPERATING CASE
MAY 11, 2001


10/10/01

Mod May 16 19720127 2002

c:\top\stata\az500.hgsympa.dz
c:\top\stata\02lsp-567mc1600.ss
Rating = 1


A-02 LSP-567 ME 1600






MOTION SYSTEMS COORDINATING COUNCIL
2001 LSPS OPERATING CASE
MAY 16, 2001
STAB. SLS FAULT ON PV 500 BY BUS 100 PHASE BUT19 C CLR FLT WPP-H464
TC TRIP RECALLS,SEE DIRECT. PAGES121-125

COMMENTS RUE TO AREA COORDINATORS MAY 16, 2001
AREA COORDINATOR COMMENTS RUE TO STAFF MAY 25, 2001




MOTION SYSTEMS COORDINATING COUNCIL
2001 LSPS OPERATING CASE
MAY 16, 2001
STAB. SLS FAULT ON PV 500 BY BUS 100 PHASE BUT19 C CLR FLT WPP-H464
TC TRIP RECALLS,SEE DIRECT. PAGES121-125

COMMENTS RUE TO AREA COORDINATORS MAY 16, 2001
AREA COORDINATOR COMMENTS RUE TO STAFF MAY 25, 2001



MOTION SYSTEMS COORDINATING COUNCIL
2001 LSPS OPERATING CASE
MAY 16, 2001
STAB. SLS FAULT ON PV 500 BY BUS 100 PHASE BUT19 C CLR FLT WPP-H464
TC TRIP RECALLS,SEE DIRECT. PAGES121-125

COMMENTS RUE TO AREA COORDINATORS MAY 16, 2001
AREA COORDINATOR COMMENTS RUE TO STAFF MAY 25, 2001





MOTION SYSTEMS COORDINATING COUNCIL
2001 LSPS OPERATING CASE
MAY 16, 2001
STAB. SLS FAULT ON PV 500 BY BUS 100 PHASE BUT19 C CLR FLT WPP-H464
TC TRIP RECALLS,SEE DIRECT. PAGES121-125

COMMENTS RUE TO AREA COORDINATORS MAY 16, 2001
AREA COORDINATOR COMMENTS RUE TO STAFF MAY 25, 2001


ARIZONA 500 & 345kV EHV System

0250002-hs01a.drv







C:\OPS\stab\021sp-78
P mis = 0.0000 MW
Q mis = -0.0000 MVAR




MOTOR SYSTEM COORDINATING COUNCIL
2002 LIPS OPERATING CASE
MAY 11, 2002
STAB. SLE FAULT ON PV 300 KV BUS TWO PH-AE OUT/19 C CLR FLT W/H/H-
76 TRIP RHO, MLO, 20E THREY, MOTORS/RELSPZL, PVS
COMMENTS DUE TO AREA COORDINATORS MAY 16, 2002
AREA COORDINATOR COMMENTS DUE TO STAFF MAY 26, 2002




MOTOR SYSTEM COORDINATING COUNCIL
2002 LIPS OPERATING CASE
MAY 11, 2002
STAB. SLE FAULT ON PV 300 KV BUS TWO PH-AE OUT/19 C CLR FLT W/H/H-
76 TRIP RHO, MLO, 20E THREY, MOTORS/RELSPZL, PVS
COMMENTS DUE TO AREA COORDINATORS MAY 16, 2002
AREA COORDINATOR COMMENTS DUE TO STAFF MAY 26, 2002



MOTOR SYSTEM COORDINATING COUNCIL
2002 LIPS OPERATING CASE
MAY 11, 2002
STAB. SLE FAULT ON PV 300 KV BUS TWO PH-AE OUT/19 C CLR FLT W/H/H-
76 TRIP RHO, MLO, 20E THREY, MOTORS/RELSPZL, PVS
COMMENTS DUE TO AREA COORDINATORS MAY 16, 2002
AREA COORDINATOR COMMENTS DUE TO STAFF MAY 26, 2002



MOTOR SYSTEM COORDINATING COUNCIL
2002 LIPS OPERATING CASE
MAY 11, 2002
STAB. SLE FAULT ON PV 300 KV BUS TWO PH-AE OUT/19 C CLR FLT W/H/H-
76 TRIP RHO, MLO, 20E THREY, MOTORS/RELSPZL, PVS
COMMENTS DUE TO AREA COORDINATORS MAY 16, 2002
AREA COORDINATOR COMMENTS DUE TO STAFF MAY 26, 2002



WESTERN SYSTEMS COORDINATING COUNCIL
2002 LSP2 OPERATING CASE


MAY 11, 2001


STAB, SLG FAULT ON PV 500 KV BUS; TWO PV-WNG OUT; 4 C CLR FLT W/PV-WNG;
7c TRIP REDO, ARLO, 20% INDUCT. MOTORS, 02LSP21, DYD

COMMENTS DUE TO AREA COORDINATORS MAY 18, 2001
AREA COORDINATOR COMMENTS DUE TO STAFF MAY 25, 2001

Arizona 500 & 345kV EHV System


AS50002-h01a.drw






C:\OPS\stab\021sp-45
 mis = 0.0001 MW
 mis = 0.0000 MUAR

General Electric International, Inc.	PSF Projects		NUMBER	DATE MAY 29 2001 01012002
APS TRANSMISSION, OPERATIONS	WESTERN SYSTEM COORDINATING COUNCIL 2002 LSP2 OPERATING CASE MAY 11, 2001		c:\ops\stab\021sp-4500.hssyamp.dr c:\ops\stab\021sp-150mef1600.su Rating = 1.	




WESTERN SYSTEM COORDINATING COUNCIL
2002 LOAD OPERATING CASE
MAY 16, 2002
STAB. SEE FAULT ON PV 500 IN BUS 101 PHASE B/119 C CLR FLT WPP-146
TC TRIP REEDER,200 MW TIECT. METERS/COLSP21,378

COORDINATE BUE TO AREA COORDINATORS MAY 16, 2002
AREA COORDINATOR COORDS BUE TO STAB MAY 26, 2002




WESTERN SYSTEM COORDINATING COUNCIL
2002 LOAD OPERATING CASE
MAY 16, 2002
STAB. SEE FAULT ON PV 500 IN BUS 101 PHASE B/119 C CLR FLT WPP-146
TC TRIP REEDER,200 MW TIECT. METERS/COLSP21,378

COORDINATE BUE TO AREA COORDINATORS MAY 16, 2002
AREA COORDINATOR COORDS BUE TO STAB MAY 26, 2002



WESTERN SYSTEM COORDINATING COUNCIL
2002 LOAD OPERATING CASE
MAY 16, 2002
STAB. SEE FAULT ON PV 500 IN BUS 101 PHASE B/119 C CLR FLT WPP-146
TC TRIP REEDER,200 MW TIECT. METERS/COLSP21,378

COORDINATE BUE TO AREA COORDINATORS MAY 16, 2002
AREA COORDINATOR COORDS BUE TO STAB MAY 26, 2002





WESTERN SYSTEM COORDINATING COUNCIL
2002 LOAD OPERATING CASE
MAY 16, 2002
STAB. SEE FAULT ON PV 500 IN BUS 101 PHASE B/119 C CLR FLT WPP-146
TC TRIP REEDER,200 MW TIECT. METERS/COLSP21,378

COORDINATE BUE TO AREA COORDINATORS MAY 16, 2002
AREA COORDINATOR COORDS BUE TO STAB MAY 26, 2002

Arizona 500 & 345kV EHV System


AZ50002L-H014.EHV






C:\OPS\stab\021sp-ha
 P mis = 0.0001 MW
 Q mis = -0.0000 MVAR

General Electric International, Inc. PSC Reports			IN/OUT	File Apr 22 15132110 2002
N	APS TRANSMISSION OPERATIONS	WESTERN SYSTEMS COORDINATING COUNCIL 2002 LSP2 OPERATING CASE MAY 11, 2001	Hassayampa-Miguel series comp. bypassed Hass. Gen = 1400MW	c:\ops\stab\021sp-ha\500-hassayampa.dr c:\ops\stab\021sp-ha\500-hassayampa1400 Rating = 1




MOTOR SYSTEM COORDINATING COUNCIL
2002 LIPS OPERATING CASE
APR 11, 2001
STAB. SLE FAULT ON PV 500 IN BUSBAR PV-HAS OUT14 C CLR FLT WPH-044
TC TRIP RECALLS,300 DIRECT, MOTORS/1000,370

Neutral-point-diode series comp. bypassed




MOTOR SYSTEM COORDINATING COUNCIL
2002 LIPS OPERATING CASE
APR 11, 2001
STAB. SLE FAULT ON PV 500 IN BUSBAR PV-HAS OUT14 C CLR FLT WPH-044
TC TRIP RECALLS,300 DIRECT, MOTORS/1000,370

Neutral-point-diode series comp. bypassed



MOTOR SYSTEM COORDINATING COUNCIL
2002 LIPS OPERATING CASE
APR 11, 2001
STAB. SLE FAULT ON PV 500 IN BUSBAR PV-HAS OUT14 C CLR FLT WPH-044
TC TRIP RECALLS,300 DIRECT, MOTORS/1000,370


Neutral-point-diode series comp. bypassed




MOTOR SYSTEM COORDINATING COUNCIL
2002 LIPS OPERATING CASE
APR 11, 2001
STAB. SLE FAULT ON PV 500 IN BUSBAR PV-HAS OUT14 C CLR FLT WPH-044
TC TRIP RECALLS,300 DIRECT, MOTORS/1000,370

Neutral-point-diode series comp. bypassed

Arizona 500 & 345kV EHV System



HASSYAH
15030



C:\ops\stab\021sp-45
P mis = 0.0001 MW
Q mis = -0.0000 MVAR





General Electric International, Inc., P.O. Box 3000

APS TRANSMISSION OPERATIONS

WESTERN SYSTEMS COORDINATING COUNCIL
2002 LSP2 OPERATING CASE
MAY 11, 2001

Mon Apr 22 18:18:43 2002

C:\wp\site\W21sp-450me1600.sq
Rating = 1





WESTERN SYSTEMS COORDINATING COUNCIL
2000 LIPS OPERATING CASE
May 11, 2000
STAB. SLE FAULT ON PW 500 KV BUS/THE PHASE B/19 C CLR FLT WPP-1464
TC TRIP REEDER, MIL, 200, 1000, DIRECT, MOTORS/OLSPSI, PWS

WPS/EPRI-Relay Setting Curve - Impedance

Arizona 500 & 345KV EHV System


ASZ500US_HSC100_4.PW






C:\OPS\stab\021sp-ha
 P mis = -0.0001 MW
 Q mis = 0.0000 MUAR

General Electric International, Inc., PPSI Program	WESTERN SYSTEMS COORDINATING COUNCIL 2002 LSP2 OPERATING CASE MAY 11, 2001	NEW GEN(100MW)2 UNITS) HASS-H16 SC 105	MUTUAL Wed Apr 29 09:51:27 2002 C:\OPS\stab\2500_hassyamp.dg C:\OPS\stab\021sp-ha\sc1100.dg Rating = 1
27 APS TRANSMISSION, OPERATIONS			




WESTERN SYSTEMS COORDINATING COUNCIL
2002 LPS OPERATING CASE
MAY 11, 2002
STAB. 3L FAULT ON PU 300 BY BARTHO PHASE B/LY/C CLR FLT MPP-MAC
TC TRIP RECLOSAL,SEE DIRECT. ROTORS(CLSPL21,37)

COOPTS BAC TO AREA COORDINATORS MAY 10, 2002
AREA COORDINATOR COOPTS BAC TO STAFF MAY 26, 2002




WESTERN SYSTEMS COORDINATING COUNCIL
2002 LPS OPERATING CASE
MAY 11, 2002
STAB. 3L FAULT ON PU 300 BY BARTHO PHASE B/LY/C CLR FLT MPP-MAC
TC TRIP RECLOSAL,SEE DIRECT. ROTORS(CLSPL21,37)

COOPTS BAC TO AREA COORDINATORS MAY 10, 2002
AREA COORDINATOR COOPTS BAC TO STAFF MAY 26, 2002



WESTERN SYSTEMS COORDINATING COUNCIL
2002 LPS OPERATING CASE
MAY 11, 2002
STAB. 3L FAULT ON PU 300 BY BARTHO PHASE B/LY/C CLR FLT MPP-MAC
TC TRIP RECLOSAL,SEE DIRECT. ROTORS(CLSPL21,37)

COOPTS BAC TO AREA COORDINATORS MAY 10, 2002
AREA COORDINATOR COOPTS BAC TO STAFF MAY 26, 2002





WESTERN SYSTEMS COORDINATING COUNCIL
2002 LPS OPERATING CASE
MAY 11, 2002
STAB. 3L FAULT ON PU 300 BY BARTHO PHASE B/LY/C CLR FLT MPP-MAC
TC TRIP RECLOSAL,SEE DIRECT. ROTORS(CLSPL21,37)

COOPTS BAC TO AREA COORDINATORS MAY 10, 2002
AREA COORDINATOR COOPTS BAC TO STAFF MAY 26, 2002

Arizona 500 & 345kV EHV System


E2000US-INP01A.EPU






C:\ops\stab\n021sp-ha
 P mis = -0.0001 MW
 Q mis = -0.0000 MVAR

General Electric International, Inc.	PSF Program		Date
APS TRANSMISSION OPERATIONS	WESTERN SYSTEMS COORDINATING COUNCIL 2002 LSP2 OPERATING CASE MAY 11, 2001	Hassayampa-N. Gila SC Out New gen=1550M	Tue Apr 23 09:06:21 2002 C:\ops\stab\n021sp-hassyanpdc C:\ops\stab\n021sp-hassycsc1550. Rating = 1




WESTERN SYSTEM COORDINATING COUNCIL
2002 LIPS OPERATING CASE
APR 11, 2003
STAB, CLR FAULT ON PV 500 KV BUS 15015 PH-1404 OUT/15 CLR PLT WPN-H46
TO TRIP RGEN,MLA,200 (INJECT, MOTORS) COLSPN,370

CONVENTS DUE TO AREA COORDINATORS APR 16, 2003
AREA COORDINATOR CONVENTS DUE TO STAFF APR 25, 2003




WESTERN SYSTEM COORDINATING COUNCIL
2002 LIPS OPERATING CASE
APR 11, 2003
STAB, CLR FAULT ON PV 500 KV BUS 15015 PH-1404 OUT/15 CLR PLT WPN-H46
TO TRIP RGEN,MLA,200 (INJECT, MOTORS) COLSPN,370

CONVENTS DUE TO AREA COORDINATORS APR 16, 2003
AREA COORDINATOR CONVENTS DUE TO STAFF APR 25, 2003




WESTERN SYSTEM COORDINATING COUNCIL
2002 LIPS OPERATING CASE
APR 11, 2003
STAB, CLR FAULT ON PV 500 KV BUS 15015 PH-1404 OUT/15 CLR PLT WPN-H46
TO TRIP RGEN,MLA,200 (INJECT, MOTORS) COLSPN,370

CONVENTS DUE TO AREA COORDINATORS APR 16, 2003
AREA COORDINATOR CONVENTS DUE TO STAFF APR 25, 2003



WESTERN SYSTEM COORDINATING COUNCIL
2002 LIPS OPERATING CASE
APR 11, 2003
STAB, CLR FAULT ON PV 500 KV BUS 15015 PH-1404 OUT/15 CLR PLT WPN-H46
TO TRIP RGEN,MLA,200 (INJECT, MOTORS) COLSPN,370

CONVENTS DUE TO AREA COORDINATORS APR 16, 2003
AREA COORDINATOR CONVENTS DUE TO STAFF APR 25, 2003



WESTERN SYSTEMS COORDINATING COUNCIL
2002 LSP2 OPERATING CASE


MAY 11, 2001

STAB, SLG FAULT ON PU 500 KV BUS; TWO PU-HWG OUT; 4 C CLR FLT W/PV-HWG;
7C TRIP REDO, ARLO, 20% INDUCT. MOTORS; 02LSP21.DYD

COMMENTS DUE TO AREA COORDINATORS MAY 18, 2001
AREA COORDINATOR COMMENTS DUE TO STAFF MAY 25, 2001

Arizona 500 & 345kV EHU System


435000usches01a.drw



KYRENE 13.041 E25.0
 15050 1.050
 KYRENE 620.0 E25.0
 105.70 1.057
 KYRENE 7 21.057
 105.13 1.051
 SILVERKID 546.3
 BROWNING 541.2
 KYRENE 525.0
 15021 1.050
 PALOURDE 525.0
 15021 1.050
 N. GILA 524.0
 22536 1.050
 ARLINTON 525.0
 15092 1.050
 REDHAWK 525.0
 15091 1.050
 WESTWING 1185.4 14009
 218.1 1.055 532.7
 1185.4 14009
 218.1 1.055 532.7
 1284.7 55 14931
 131.0 1.057 23.31
 1284.7 55 14932
 131.0 1.057 23.31
 1284.7 55 14933
 131.0 1.057 23.31
 1284.7 55 14934
 131.0 1.057 14.15
 1284.7 55 14935
 131.0 1.057 14.15
 1087.7 34801 DEVENS
 218.1 1.053 531.4
 N. GILA 521.2 5813220
 7.1 1.019 70.26
 22760 IMPRLULY
 1.045 522.4
 ARL-CT1 170.0 5813148
 2.0 1.005 18.16
 ARL-CT2 170.0 5813149
 2.0 1.005 18.16
 ARL-ST1 170.0 5815147
 2.0 1.005 18.16
 RED-CT1 160.0 5814270
 1.2 1.005 18.09
 RED-CT2 160.0 5814271
 1.2 1.005 18.09
 RED-ST1 160.0 5814272
 1.2 1.005 18.00
 RED-CT3 160.0 5814273
 1.2 1.005 18.09
 RED-CT4 160.0 5814274
 1.2 1.005 18.09
 RED-ST2 160.0 5814275
 1.2 1.005 18.00


C:\ops\stab\021sp-ha
P mis = -0.0000 MW
Q mis = 0.0000 MVAR

General Electric International, Inc. PRF Program
APS **TRANSMISSION** **OPERATIONS** **WESTERN SYSTEMS COORDINATING COUNCIL**
2002 LSP2 OPERATING CASE
MAY 11, 2001




MONTGOMERY COUNTY COORDINATING COUNCIL
2000 LIPS OPERATING CASE
APR 11, 2001
STAG, SLS FAULT ON PV 300 IN BUS 108 PV-148 OUT19 C CLR FLT W/PW-148
TC TRIP R0148,M018,200 DIRECT, ROTORS/OLP19,179

COMMENTS DUE TO AREA COORDINATORS APR 16, 2001
AREA COORDINATOR COMMENTS DUE TO STAFF APR 25, 2001




MONTGOMERY COUNTY COORDINATING COUNCIL
2000 LIPS OPERATING CASE
APR 11, 2001
STAG, SLS FAULT ON PV 300 IN BUS 108 PV-148 OUT19 C CLR FLT W/PW-148
TC TRIP R0148,M018,200 DIRECT, ROTORS/OLP19,179

COMMENTS DUE TO AREA COORDINATORS APR 16, 2001
AREA COORDINATOR COMMENTS DUE TO STAFF APR 25, 2001



MONTGOMERY COUNTY COORDINATING COUNCIL
2000 LIPS OPERATING CASE
APR 11, 2001
STAG, SLS FAULT ON PV 300 IN BUS 108 PV-148 OUT19 C CLR FLT W/PW-148
TC TRIP R0148,M018,200 DIRECT, ROTORS/OLP19,179

COMMENTS DUE TO AREA COORDINATORS APR 16, 2001
AREA COORDINATOR COMMENTS DUE TO STAFF APR 25, 2001




MONTGOMERY COUNTY COORDINATING COUNCIL
2000 LIPS OPERATING CASE
APR 11, 2001
STAG, SLS FAULT ON PV 300 IN BUS 108 PV-148 OUT19 C CLR FLT W/PW-148
TC TRIP R0148,M018,200 DIRECT, ROTORS/OLP19,179

COMMENTS DUE TO AREA COORDINATORS APR 16, 2001
AREA COORDINATOR COMMENTS DUE TO STAFF APR 25, 2001

Arizona 500 & 345kV EHV System

AZ500042_hes91sp.dew



General Electric International, Inc. PSF Program


APS
TRANSMISSION,
OPERATIONS
WESTERN SYSTEMS COORDINATING COUNCIL
2002 LSP OPERATING CASE
MAY 11, 2001.

N. Gila-Miguel series comp. bypassed
NEC GEN 1550MW


PSF/PSF

Rev App 22 13120146 2002
cflops/statis500_hes91sp.dew
cflops/statis2021sp-hes91sp/az500
Rating: 1


D-0267-NGHIGSC1500.EAV




C:\OPS\stab\021sp-ns
P mis = -0.0000 MW
Q mis = -0.0000 MVAR




MOTOR SYSTEMS COORDINATING COUNCIL
2002 LPS OPERATING CASE
APR 11, 2001
STAB. SLS FAULT ON PU 300 IN BUS 100 PHASE BUT19 C CLR FLT W/W/HG
TC TRIP REC/MILS/300 DIRECT. MOTORS/100LPS21-079




MOTOR SYSTEMS COORDINATING COUNCIL
2002 LPS OPERATING CASE
APR 11, 2001
STAB. SLS FAULT ON PU 300 IN BUS 100 PHASE BUT19 C CLR FLT W/W/HG
TC TRIP REC/MILS/300 DIRECT. MOTORS/100LPS21-079



MOTOR SYSTEMS COORDINATING COUNCIL
2002 LPS OPERATING CASE
APR 11, 2001
STAB. SLS FAULT ON PU 300 IN BUS 100 PHASE BUT19 C CLR FLT W/W/HG
TC TRIP REC/MILS/300 DIRECT. MOTORS/100LPS21-079




MOTOR SYSTEMS COORDINATING COUNCIL
2002 LPS OPERATING CASE
APR 11, 2001
STAB. SLS FAULT ON PU 300 IN BUS 100 PHASE BUT19 C CLR FLT W/W/HG
TC TRIP REC/MILS/300 DIRECT. MOTORS/100LPS21-079



WESTERN SYSTEMS COORDINATING COUNCIL
2002 LSP2 OPERATING CASE
MAY 11, 2001
STAB, SLG FAULT ON PV 500 KV BUS; TWO PV-HWG OUT; 4 C CLR FLT W/PV-HWG;
7C TRIP REDO, ARLO, 20% INDUCT. MOTORS102LSP21-DYD

Arizona 500 & 345kV EHV System

AZ500042_headline.drw



DU PALOVERDE

General Electric Information Inc. PAF Projects

APS
TRANSMISSION,
OPERATIONS

WESTERN SYSTEMS COORDINATING COUNCIL
2002 LSP2 OPERATING CASE
MAY 11, 2001


N. Gila-Miguel series comp. bypassed

D1-02LSP-NGMIGSC.SAV

10/1/01

Mon Apr 22 19291122 2002

c:\ops\stab\102500.hssympa.drw
c:\ops\stab\021sy-ayalgscc.sav
Rating = 1



C:\OPS\stab\021sp-ns
P mis = 0.0001 MW
Q mis = -0.0000 MVAR

General Electric International, Inc., P.R.C. Project


WESTERN SYSTEM
2002 LSP2 OP
MAY 11, 2001

WESTERN SYSTEMS COORDINATING COUNCIL
2002 LSP2 OPERATING CASE
MAY 11, 2001

M.61a-Miguel series comp. bypassed


MM/MAR Page APP-22-12121117 2002

C:\ops\stab\12500_hassyaapl.de
C:\ops\stab\021sp-nomigsc.sav
Rating. 1




WESTERN SYSTEM COORDINATING COUNCIL
2002 LPS OPERATING CASE
MAY 11, 2002
STAB. 2E FAULT ON PV 500 KV BUS 1100 PHASE BUT19 C CLR FLT WPH-MAG
TC TRIP RCH160,MUL,200 DIRECT, WESTON/CELSPI,1,070

Reserve Margin: 0.00000 Margin: 0.00000




WESTERN SYSTEM COORDINATING COUNCIL
2002 LPS OPERATING CASE
MAY 11, 2002
STAB. 2E FAULT ON PV 500 KV BUS 1100 PHASE BUT19 C CLR FLT WPH-MAG
TC TRIP RCH160,MUL,200 DIRECT, WESTON/CELSPI,1,070

Reserve Margin: 0.00000 Margin: 0.00000



WESTERN SYSTEM COORDINATING COUNCIL
2002 LPS OPERATING CASE
MAY 11, 2002
STAB. 2E FAULT ON PV 500 KV BUS 1100 PHASE BUT19 C CLR FLT WPH-MAG
TC TRIP RCH160,MUL,200 DIRECT, WESTON/CELSPI,1,070


Reserve Margin: 0.00000 Margin: 0.00000




WESTERN SYSTEM COORDINATING COUNCIL
2002 LPS OPERATING CASE
MAY 11, 2002
STAB. 2E FAULT ON PV 500 KV BUS 1100 PHASE BUT19 C CLR FLT WPH-MAG
TC TRIP RCH160,MUL,200 DIRECT, WESTON/CELSPI,1,070

Reserve Margin: 0.00000 Margin: 0.00000

Arizona 500 & 345kV EHV System
AZ500C4-NSD10A.DFW





C:\ops\stab\021\sp-pv
 Pmis = 0.0002 MW
 Qmis = 0.0000 MUAR


General Electric International, Inc. P.O. Box 900

**APS
TRANSMISSION,
OPERATIONS**


**WESTERN SYSTEMS COORDINATING COUNCIL
2002 LSP2 OPERATING CASE**

PALO VERDE-DEVERS series comp. bypassed
Hess. Gen • 1400MW


1994 Apr 22 12121137 2002




MOTOR SYSTEM COORDINATING COUNCIL
2002 LPPS OPERATING CASE
APR 11, 2002
STAB. SLS FAULT ON PH 000 TV BUS/100 PHASES OUT/100 C CLR FLT W/PPH-M4
TC TRIP ACCELERATE, 300 INDUCT. MOTORS/SEL/SP1-373




MOTOR SYSTEM COORDINATING COUNCIL
2002 LPPS OPERATING CASE
APR 11, 2002
STAB. SLS FAULT ON PH 000 TV BUS/100 PHASES OUT/100 C CLR FLT W/PPH-M4
TC TRIP ACCELERATE, 300 INDUCT. MOTORS/SEL/SP1-373




MOTOR SYSTEM COORDINATING COUNCIL
2002 LPPS OPERATING CASE
APR 11, 2002
STAB. SLS FAULT ON PH 000 TV BUS/100 PHASES OUT/100 C CLR FLT W/PPH-M4
TC TRIP ACCELERATE, 300 INDUCT. MOTORS/SEL/SP1-373



MOTOR SYSTEM COORDINATING COUNCIL
2002 LPPS OPERATING CASE
APR 11, 2002
STAB. SLS FAULT ON PH 000 TV BUS/100 PHASES OUT/100 C CLR FLT W/PPH-M4
TC TRIP ACCELERATE, 300 INDUCT. MOTORS/SEL/SP1-373




HASSYAMP
15090




C:\OPS\stab\02L1sp-p
P mis = 0.0001 MW
Q mis = -0.0000 MVAR

General Electric Informational Inc., PSCF Program APE TRANSMISSION OPERATIONS	WESTERN SYSTEMS COORDINATING COUNCIL 2002 LSP2 OPERATING CASE MAY 11, 2001	PV-DEVERS SC OUT	REV 4/23 10:13:01 2002 C:\Ops\stab\02L1sp-pdvc.sv C:\Ops\stab\02L1sp-pdvc.sav Filing = 1
--	--	------------------	---




NET/NET SYSTEM COORDINATING COUNCIL
2002 LSTS OPERATING CASE
APR 11, 2001
STAT: SLS FAULT ON PV 500 KV BUS 1 NO PHASE BUSES C CLR FLT BASH-HASH
TC TRIP REEDCO, ALEX, 300 DIRECT. MOTORS/GENS/PLANT, BYT

COMMENTS DUE TO AREA COORDINATORS APR 16, 2001
AREA COORDINATOR COMMENTS DUE TO STAFF APR 25, 2001




NET/NET SYSTEM COORDINATING COUNCIL
2002 LSTS OPERATING CASE
APR 11, 2001
STAT: SLS FAULT ON PV 500 KV BUS 1 NO PHASE BUSES C CLR FLT BASH-HASH
TC TRIP REEDCO, ALEX, 300 DIRECT. MOTORS/GENS/PLANT, BYT

COMMENTS DUE TO AREA COORDINATORS APR 16, 2001
AREA COORDINATOR COMMENTS DUE TO STAFF APR 25, 2001




NET/NET SYSTEM COORDINATING COUNCIL
2002 LSTS OPERATING CASE
APR 11, 2001
STAT: SLS FAULT ON PV 500 KV BUS 1 NO PHASE BUSES C CLR FLT BASH-HASH
TC TRIP REEDCO, ALEX, 300 DIRECT. MOTORS/GENS/PLANT, BYT

COMMENTS DUE TO AREA COORDINATORS APR 16, 2001
AREA COORDINATOR COMMENTS DUE TO STAFF APR 25, 2001




NET/NET SYSTEM COORDINATING COUNCIL
2002 LSTS OPERATING CASE
APR 11, 2001
STAT: SLS FAULT ON PV 500 KV BUS 1 NO PHASE BUSES C CLR FLT BASH-HASH
TC TRIP REEDCO, ALEX, 300 DIRECT. MOTORS/GENS/PLANT, BYT


COMMENTS DUE TO AREA COORDINATORS APR 16, 2001
AREA COORDINATOR COMMENTS DUE TO STAFF APR 25, 2001



WESTERN SYSTEMS COORDINATING COUNCIL
2002 LSP2 OPERATING CASE
MAY 11, 2001
STAB, SLG FAULT ON PV 500 KV BUS; TWO PV-WNG OUT; 4 C CLR FLT W/PV-WNG;
7C TRIP RED500, ARLO, 20% INDUCT. MOTORS; 02LSP21, DYD


COMMENTS DUE TO AREA COORDINATORS MAY 18, 2001
AREA COORDINATOR COMMENTS DUE TO STAFF MAY 25, 2001






C:\OPS\stab\021sp-pv
 P mis = 0.0000 MW
 Q mis = -0.0000 MVAR

APACHE INDIAN TRIBES, INC.	PST PROGRAM		INV/IMM
APS TRANSMISSION, OPERATIONS	WESTERN SYSTEMS COORDINATING COUNCIL 2002 LSP2 OPERATING CASE MAY 11, 2001	NEW ROMANTIC UNITSI PV-DEVERS SC 105	Med APP 21 10220102 2002 ctropsstab021sp-hassyamp.dr ctropsstab021sp-prvsc100.s Rating = 1




MOTOR SYSTEM COORDINATING COUNCIL
2001 LPS OPERATING CASE
MAY 11, 2001
STAB. SLE FAULT ON PV 500 TO BUS 101 PHASE B/W 14 C CLR FLT SUPPLY-MAIN
TC TRIP RECD, A/LA, ZOE DIRECT, MOTORS/SEL/SP1, SP2

COverts due to AREA COORDINATORS MAY 10, 2001
AREA COORDINATOR COverts due to STAB MAY 10, 2001




MOTOR SYSTEM COORDINATING COUNCIL
2001 LPS OPERATING CASE
MAY 11, 2001
STAB. SLE FAULT ON PV 500 TO BUS 101 PHASE B/W 14 C CLR FLT SUPPLY-MAIN
TC TRIP RECD, A/LA, ZOE DIRECT, MOTORS/SEL/SP1, SP2

COverts due to AREA COORDINATORS MAY 10, 2001
AREA COORDINATOR COverts due to STAB MAY 10, 2001



MOTOR SYSTEM COORDINATING COUNCIL
2001 LPS OPERATING CASE
MAY 11, 2001
STAB. SLE FAULT ON PV 500 TO BUS 101 PHASE B/W 14 C CLR FLT SUPPLY-MAIN
TC TRIP RECD, A/LA, ZOE DIRECT, MOTORS/SEL/SP1, SP2


COverts due to AREA COORDINATORS MAY 10, 2001
AREA COORDINATOR COverts due to STAB MAY 10, 2001



MOTOR SYSTEM COORDINATING COUNCIL
2001 LPS OPERATING CASE
MAY 11, 2001
STAB. SLE FAULT ON PV 500 TO BUS 101 PHASE B/W 14 C CLR FLT SUPPLY-MAIN
TC TRIP RECD, A/LA, ZOE DIRECT, MOTORS/SEL/SP1, SP2

COverts due to AREA COORDINATORS MAY 10, 2001
AREA COORDINATOR COverts due to STAB MAY 10, 2001

Arizona 500 & 345kV EHV System



GENERAL ELECTRIC International, Inc., P&G Division

APS
TRANSMISSION,
OPERATIONS


WESTERN SYSTEMS COORDINATING COUNCIL
2002 LSP2 OPERATING CASE
MAY 11, 2001

PV-DU SC 1051AZ SIDE
NEW GEN 1500W
E = 0.21 SP -

100%

TUE APR 22 1993 100 2002
C:\LOPS\SLAB\12500_hassyamp.
C:\LOPS\SLAB\021sp.pvd\151SC
Rating = 1

HASSYAMP
15050



C:\OPS\stab\021SP-PV
P mis = -0.0000 MW
Q mis = 0.0000 MUAR

General Electric International, Inc.

PLF_Promote

APS
TRANSMISSION,
OPERATIONS


WESTERN SYSTEMS COORDINATING COUNCIL
2002 LSP2 OPERATING CASE
MAY 11, 2001

PV-IN SC (1051AZ SIDE)
NEW GEN=1500MW

PLANT


Tue Apr 22 16123111 2002

c:\ops\stab\021SP-PV\dsc1500.
Rating = 1




WESTERN SYSTEM COORDINATING COUNCIL
2000 LIPS OPERATING CASE
MAY 11, 2000
STAN, SLE FAULT ON PU 500 KV BUS 100 THE PH-146 OUT19 C CLR FLT 1000-146
TC TRIP RECD, AML, ZONE IMPACT, RETRIES/1000-146

COMPONENTS DUE TO AREA COORDINATORS MAY 16, 2000
AREA COORDINATOR COMPONENTS DUE TO STAFF MAY 25, 2001




WESTERN SYSTEM COORDINATING COUNCIL
2000 LIPS OPERATING CASE
MAY 11, 2000
STAN, SLE FAULT ON PU 500 KV BUS 100 THE PH-146 OUT19 C CLR FLT 1000-146
TC TRIP RECD, AML, ZONE IMPACT, RETRIES/1000-146

COMPONENTS DUE TO AREA COORDINATORS MAY 16, 2000
AREA COORDINATOR COMPONENTS DUE TO STAFF MAY 25, 2001




WESTERN SYSTEM COORDINATING COUNCIL
2000 LIPS OPERATING CASE
MAY 11, 2000
STAN, SLE FAULT ON PU 500 KV BUS 100 THE PH-146 OUT19 C CLR FLT 1000-146
TC TRIP RECD, AML, ZONE IMPACT, RETRIES/1000-146

COMPONENTS DUE TO AREA COORDINATORS MAY 16, 2000
AREA COORDINATOR COMPONENTS DUE TO STAFF MAY 25, 2001



WESTERN SYSTEM COORDINATING COUNCIL
2000 LIPS OPERATING CASE
MAY 11, 2000
STAN, SLE FAULT ON PU 500 KV BUS 100 THE PH-146 OUT19 C CLR FLT 1000-146
TC TRIP RECD, AML, ZONE IMPACT, RETRIES/1000-146


COMPONENTS DUE TO AREA COORDINATORS MAY 16, 2000
AREA COORDINATOR COMPONENTS DUE TO STAFF MAY 25, 2001



WESTERN SYSTEMS COORDINATING COUNCIL
 2002 LSP2 OPERATING CASE
 MAY 11, 2001
 STAB, SLG FAULT ON PU 500 KV BUS; TWO PU-HNG OUT; 4 C CLR FLT W/PU-HNG;
 7C TRIP REDO, ARLO, 20% INDUCT. MOTORS; 02LSP21.DYD

COMMENTS DUE TO AREA COORDINATORS MAY 18, 2001
 AREA COORDINATOR COMMENTS DUE TO STAFF MAY 25, 2001

Arizona 500 & 345kV EHV System



General Electric International, Inc., P.R.F. Programs

**APS
TRANSMISSION,
OPERATIONS**


CONFIDENTIAL
WESTERN SYSTEMS COORDINATING COUNCIL
2002 LSP2 OPERATING CASE
MAY 11, 2001

[View Details](#)

PV-DV SC 1051A1 SIDE1


34/35

c:\ops\stab\z500_hassymp.d
c:\ops\stab\02\sp-pv\d1sc.sav
Rating = 1




C:\ops\stab\021sp-pv
 P mis = -0.0001 MW
 Q mis = 0.0000 MUAR


General Electric International, Inc.	PSF Program		Run#	Tue Apr 23 15:47:11 2002
APS TRANSMISSION, OPERATIONS	WESTERN SYSTEMS COORDINATING COUNCIL 2002 LSP2 OPERATING CASE MAY 11, 2001	PV-DV SC 105(AZ SIDE)		c:\ops\stab\12500\hassyamp.dv c:\ops\stab\021sp-pv\dvisc.sv Rating = 1




MOTION SYSTEM COORDINATING COUNCIL
2000 LIPS OPERATING CASE
MAY 11, 2000
STAB, SLS FAULT ON PV 500 TO BUS 102 PHASE B/114 C CLR FLT MPPH-104
TC TRIP REVERSE, MFLA, 200 DIRECT, MOTORS(02,579), 179
COMPUTES RUE TO AREA COORDINATOR MAY 16, 2000
AREA COORDINATOR COMPUTES RUE TO STAFF MAY 26, 2000



MOTION SYSTEM COORDINATING COUNCIL
2000 LIPS OPERATING CASE
MAY 11, 2000
STAB, SLS FAULT ON PV 500 TO BUS 102 PHASE B/114 C CLR FLT MPPH-104
TC TRIP REVERSE, MFLA, 200 DIRECT, MOTORS(02,579), 179
COMPUTES RUE TO AREA COORDINATOR MAY 16, 2000
AREA COORDINATOR COMPUTES RUE TO STAFF MAY 26, 2000




MOTION SYSTEM COORDINATING COUNCIL
2000 LIPS OPERATING CASE
MAY 11, 2000
STAB, SLS FAULT ON PV 500 TO BUS 102 PHASE B/114 C CLR FLT MPPH-104
TC TRIP REVERSE, MFLA, 200 DIRECT, MOTORS(02,579), 179
COMPUTES RUE TO AREA COORDINATOR MAY 16, 2000
AREA COORDINATOR COMPUTES RUE TO STAFF MAY 26, 2000



MOTION SYSTEM COORDINATING COUNCIL
2000 LIPS OPERATING CASE
MAY 11, 2000
STAB, SLS FAULT ON PV 500 TO BUS 102 PHASE B/114 C CLR FLT MPPH-104
TC TRIP REVERSE, MFLA, 200 DIRECT, MOTORS(02,579), 179
COMPUTES RUE TO AREA COORDINATOR MAY 16, 2000
AREA COORDINATOR COMPUTES RUE TO STAFF MAY 26, 2000

Arizona 500 & 345kV EHV System



General Electric International, Inc. PSF Program

APS
TRANSMISSION
OPERATIONS

WESTERN SYSTEMS COORDINATING COUNCIL
2002 LSP2 OPERATING CASE
MAY 11, 2001


M/M/R

Ref APP 26 11102125 2002

c:\ops\psf\12\z500_hassya\psf_021sp-hang3601.sav
Rating = 1

HASS-K-GILA IIS
PV GEN=3601MA


G - 02LSP - HANG 3601 .SAV



021SP-hang3601.sav

P mis = .0.0000 MW

Q mis = 0.0000 MUAR



NETTOM SYSTEMS COORDINATING COUNCIL


2002 LGEN OPERATING CASE

FRI 11:10:09

STAS: SLS FAULT ON PV 300 IN BARTON PH-MAR BATTY C CLR FLT MPP-MAR
TC TRIP RECALL,MALE,302 DIRECT, NETTOM/BL3271,373

COMENTS DUE TO AREA COORDINATORS FRI 16, 2002

AREA COORDINATOR COMMENTS DUE TO STAFF FRI 26, 2002



NETTOM SYSTEMS COORDINATING COUNCIL


2002 LGEN OPERATING CASE

FRI 11:10:09

STAS: SLS FAULT ON PV 300 IN BARTON PH-MAR BATTY C CLR FLT MPP-MAR
TC TRIP RECALL,MALE,302 DIRECT, NETTOM/BL3271,373

COMENTS DUE TO AREA COORDINATORS FRI 16, 2002

AREA COORDINATOR COMMENTS DUE TO STAFF FRI 26, 2002



NETTOM SYSTEMS COORDINATING COUNCIL


2002 LGEN OPERATING CASE

FRI 11:10:09

STAS: SLS FAULT ON PV 300 IN BARTON PH-MAR BATTY C CLR FLT MPP-MAR
TC TRIP RECALL,MALE,302 DIRECT, NETTOM/BL3271,373

COMENTS DUE TO AREA COORDINATORS FRI 16, 2002

AREA COORDINATOR COMMENTS DUE TO STAFF FRI 26, 2002



NETTOM SYSTEMS COORDINATING COUNCIL

2002 LGEN OPERATING CASE

FRI 11:10:09


STAS: SLS FAULT ON PV 300 IN BARTON PH-MAR BATTY C CLR FLT MPP-MAR
TC TRIP RECALL,MALE,302 DIRECT, NETTOM/BL3271,373

COMENTS DUE TO AREA COORDINATORS FRI 16, 2002


AREA COORDINATOR COMMENTS DUE TO STAFF FRI 26, 2002

Arizona 500 & 345kV EHV System

AS2600UB-HS01a.drw



HASSYAMP
15090



KYRENEC
101.07
PALOURDE
23.37
N. BILA
22.38
ARLINTON
23.37
REDHAWK
23.37

WESTWING
526.4
WESTWING
526.4
PALOURD1
23.38
PALOURD2
23.37
PALOURDE
23.37
PUNGSET1
14.15
PUNGSET2
14.15

DEUVERS
521.6

C:\ops\stab\021sp-ha
P mis = -0.0000 MW
Q mis = 0.0000 MUAR


General Electric Information, Inc. PNL/PMS

APS
TRANSMISSION,
OPERATIONS

WESTERN SYSTEMS COORDINATING COUNCIL
2002 LSP2 OPERATING CASE
MAY 11, 2001

MAS-KYR 105
PULSE BX= 3152H

File Date: 29-10-2002
C:\ops\stab\021sp-ha
C:\ops\stab\021sp-ha\pms\3152.ha
Rating = 1




MOTOR SYSTEMS COORDINATING COUNCIL
2003 LIPS OPERATING CASE
MAY 11, 2003

STAR: SLE FAULT ON PV 500 IV BUS 1 THE PH-ME OUT11 C CLR FLT MPPH-MPH

TC TRIP RECALLABLE,300 DIRECT, MOTORS\GSP2P1,375

COMMENTS DUE TO AREA COORDINATORS MAY 16, 2003
AREA COORDINATOR COMMENTS DUE TO STAFF MAY 26, 2003




MOTOR SYSTEMS COORDINATING COUNCIL
2003 LIPS OPERATING CASE
MAY 11, 2003

STAR: SLE FAULT ON PV 500 IV BUS 1 THE PH-ME OUT11 C CLR FLT MPPH-MPH

TC TRIP RECALLABLE,300 DIRECT, MOTORS\GSP2P1,375

COMMENTS DUE TO AREA COORDINATORS MAY 16, 2003
AREA COORDINATOR COMMENTS DUE TO STAFF MAY 26, 2003




MOTOR SYSTEMS COORDINATING COUNCIL
2003 LIPS OPERATING CASE
MAY 11, 2003

STAR: SLE FAULT ON PV 500 IV BUS 1 THE PH-ME OUT11 C CLR FLT MPPH-MPH

TC TRIP RECALLABLE,300 DIRECT, MOTORS\GSP2P1,375

COMMENTS DUE TO AREA COORDINATORS MAY 16, 2003
AREA COORDINATOR COMMENTS DUE TO STAFF MAY 26, 2003



MOTOR SYSTEMS COORDINATING COUNCIL
2003 LIPS OPERATING CASE
MAY 11, 2003


STAR: SLE FAULT ON PV 500 IV BUS 1 THE PH-ME OUT11 C CLR FLT MPPH-MPH


TC TRIP RECALLABLE,300 DIRECT, MOTORS\GSP2P1,375

COMMENTS DUE TO AREA COORDINATORS MAY 16, 2003
AREA COORDINATOR COMMENTS DUE TO STAFF MAY 26, 2003


Arizona 500 & 345KV EHV System

PERIOD: 1-HOUR, 4PM







C:\ops\stab\021sp-pv
 P mis = 0.0002 MW
 Q mis = -0.0000 MVAR




WESTON SYSTEMS COORDINATING COUNCIL
2002 LSP2 OPERATING CASE
MAY 11, 2001
STAL: SLE FAULT ON PV 500 KV BUS#10 PV-HM4 BUST11 C CLR FLT HPM-HM4
TC TRIP RCDL,MLD,200 INLET, MOTORS|GOLSP21,379
COMENTS BUC TO AREA COORDINATORS MAY 18, 2001
AREA COORDINATOR COMENTS BUC TO STAFF MAY 25, 2001




WESTON SYSTEMS COORDINATING COUNCIL
2002 LSP2 OPERATING CASE
MAY 11, 2001
STAL: SLE FAULT ON PV 500 KV BUS#10 PV-HM4 BUST11 C CLR FLT HPM-HM4
TC TRIP RCDL,MLD,200 INLET, MOTORS|GOLSP21,379
COMENTS BUC TO AREA COORDINATORS MAY 18, 2001
AREA COORDINATOR COMENTS BUC TO STAFF MAY 25, 2001




WESTON SYSTEMS COORDINATING COUNCIL
2002 LSP2 OPERATING CASE
MAY 11, 2001
STAL: SLE FAULT ON PV 500 KV BUS#10 PV-HM4 BUST11 C CLR FLT HPM-HM4
TC TRIP RCDL,MLD,200 INLET, MOTORS|GOLSP21,379
COMENTS BUC TO AREA COORDINATORS MAY 18, 2001
AREA COORDINATOR COMENTS BUC TO STAFF MAY 25, 2001




WESTON SYSTEMS COORDINATING COUNCIL
2002 LSP2 OPERATING CASE
MAY 11, 2001
STAL: SLE FAULT ON PV 500 KV BUS#10 PV-HM4 BUST11 C CLR FLT HPM-HM4
TC TRIP RCDL,MLD,200 INLET, MOTORS|GOLSP21,379
COMENTS BUC TO AREA COORDINATORS MAY 18, 2001
AREA COORDINATOR COMENTS BUC TO STAFF MAY 25, 2001






C:\ops\stab\021sp-23
P mis = -0.0000 MW
Q mis = -0.0000 MUAR




WESTON SYSTEM COORDINATING COUNCIL
2001 LIPS OPERATING CASE
MAY 16, 2001
STAR: 3P FAULT ON PU 500 KV BUS; PHASE CUTTH C CLR FLT MPP-H465;
TC TRIP RCD,ALD,2SC DIRECT, MOTORS/GSP11,373

COMMENTS DUE TO AREA COORDINATORS MAY 16, 2001
AREA COORDINATOR COMMENTS DUE TO STARF MAY 26, 2001




WESTON SYSTEM COORDINATING COUNCIL
2001 LIPS OPERATING CASE
MAY 16, 2001
STAR: 3P FAULT ON PU 500 KV BUS; PHASE CUTTH C CLR FLT MPP-H465;
TC TRIP RCD,ALD,2SC DIRECT, MOTORS/GSP11,373

COMMENTS DUE TO AREA COORDINATORS MAY 16, 2001
AREA COORDINATOR COMMENTS DUE TO STARF MAY 26, 2001



WESTON SYSTEM COORDINATING COUNCIL
2001 LIPS OPERATING CASE
MAY 16, 2001
STAR: 3P FAULT ON PU 500 KV BUS; PHASE CUTTH C CLR FLT MPP-H465;
TC TRIP RCD,ALD,2SC DIRECT, MOTORS/GSP11,373

COMMENTS DUE TO AREA COORDINATORS MAY 16, 2001
AREA COORDINATOR COMMENTS DUE TO STARF MAY 26, 2001



WESTON SYSTEM COORDINATING COUNCIL
2001 LIPS OPERATING CASE
MAY 16, 2001
STAR: 3P FAULT ON PU 500 KV BUS; PHASE CUTTH C CLR FLT MPP-H465;
TC TRIP RCD,ALD,2SC DIRECT, MOTORS/GSP11,373


COMMENTS DUE TO AREA COORDINATORS MAY 16, 2001
AREA COORDINATOR COMMENTS DUE TO STARF MAY 26, 2001

76

APS
TRANSMISSION
OPERATIONS

15021 PALOURDE 500
Thu May 16 10:28:30 2002

plot5.acf



WESTERN SYSTEMS COORDINATING COUNCIL

2002 LSP2 OPERATING CASE

MAY 11, 2001

STAB, 3P FAULT ON PU 500 KV BUS; PU-HWG OUT14 C CLR FLT H/PV-HWG

7C TRIP REDO, ARLO, 20% INDUCT. MOTORS|02LSP21.DYD

COMMENTS DUE TO AREA COORDINATORS MAY 18, 2001


AREA COORDINATOR COMMENTS DUE TO STAFF MAY 25, 2001

27

APS
TRANSMISSION
OPERATIONS

15021 PALOURDE 500
Thu May 16 10:28:30 2002

plot6.acf



WESTERN SYSTEMS COORDINATING COUNCIL

2002 LSP2 OPERATING CASE

MAY 11, 2001

STAB, 3P FAULT ON PU 500 KV BUS; PU-HWG OUT14 C CLR FLT H/PV-HWG

7C TRIP REDO, ARLO, 20% INDUCT. MOTORS|02LSP21.DYD

COMMENTS DUE TO AREA COORDINATORS MAY 18, 2001

AREA COORDINATOR COMMENTS DUE TO STAFF MAY 25, 2001