



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
137X-1	522-1136-011	\$110.00	\$0.00	N/A	SVC ONLY
2001 SERIES		N/A	\$450.00	\$0.00	Flat rate repair from factory
2101 SERIES		N/A	\$500.00	\$0.00	Flat rate repair from factory
313N-2	522-2447-005	\$0.00	\$0.00	\$0.00	
313N-2	522-2447-015	\$220.00	\$550.00	\$770.00	
313N-2	522-2447-046	\$220.00	\$550.00	\$770.00	
313N-2	522-2447-052	\$220.00	\$550.00	\$770.00	
313N-2	522-2447-053	\$220.00	\$550.00	\$770.00	
313N-2	522-2447-055	\$220.00	\$550.00	\$770.00	
313N-2	522-2447-205	\$220.00	\$550.00	\$770.00	
313N-2	522-2447-215	\$220.00	\$550.00	\$770.00	
313N-2	522-2447-252	\$220.00	\$550.00	\$770.00	
313N-2	522-2447-253	\$220.00	\$550.00	\$770.00	
313N-2	522-2447-255	\$220.00	\$550.00	\$770.00	
313N-2	522-2447-261	\$220.00	\$550.00	\$770.00	
313N-2	522-2447-262	\$220.00	\$550.00	\$770.00	
313N-2	522-2447-266	\$220.00	\$550.00	\$770.00	
313N-2	522-2447-267	\$220.00	\$550.00	\$770.00	
313N-2	522-2447-268	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-025	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-035	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-048	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-050	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-051	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-056	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-057	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-058	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-059	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-225	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-235	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-248	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-250	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-251	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-256	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-257	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-259	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-260	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-263	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-264	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-269	\$220.00	\$550.00	\$770.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
313N-2D	522-2447-270	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-271	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-272	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-273	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-556	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-557	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-563	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-564	\$220.00	\$550.00	\$770.00	
313N-2D	522-2447-571	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-005	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-015	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-025	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-035	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-045	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-055	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-056	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-057	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-058	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-059	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-060	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-061	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-063	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-065	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-066	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-067	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-069	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-072	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-073	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-074	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-075	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-205	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-215	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-216	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-217	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-218	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-219	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-220	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-221	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-222	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-223	\$220.00	\$550.00	\$770.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
313N-3	522-2448-224	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-225	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-235	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-245	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-246	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-247	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-248	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-249	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-250	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-251	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-253	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-254	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-255	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-256	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-258	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-259	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-260	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-261	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-263	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-265	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-266	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-267	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-269	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-272	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-273	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-274	\$220.00	\$550.00	\$770.00	
313N-3	522-2448-276	\$220.00	\$550.00	\$770.00	
313N-4B	522-3614-000	\$220.00	\$550.00	\$770.00	
313N-4B	522-3614-001	\$220.00	\$550.00	\$770.00	
313N-4B	522-3614-003	\$220.00	\$550.00	\$770.00	
313N-4B	522-3614-004	\$220.00	\$550.00	\$770.00	
313N-4B	522-3614-200	\$220.00	\$550.00	\$770.00	
313N-4B	522-3614-203	\$220.00	\$550.00	\$770.00	
313N-4B	522-3614-205	\$220.00	\$550.00	\$770.00	
313N-4B	522-3614-206	\$220.00	\$550.00	\$770.00	
313N-4B	522-3614-300	\$220.00	\$550.00	\$770.00	
313N-4B	522-3614-500	\$220.00	\$550.00	\$770.00	
313N-4B	522-3614-503	\$220.00	\$550.00	\$770.00	
313N-4B	522-3614-506	\$220.00	\$550.00	\$770.00	
313N-4C	522-3615-001	\$220.00	\$550.00	\$770.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
313N-4C	522-3615-002	\$220.00	\$550.00	\$770.00	
313N-4C	522-3615-003	\$220.00	\$550.00	\$770.00	
313N-4C	522-3615-005	\$220.00	\$550.00	\$770.00	
313N-4C	522-3615-201	\$220.00	\$550.00	\$770.00	
313N-4C	522-3615-202	\$220.00	\$550.00	\$770.00	
313N-4C	522-3615-205	\$220.00	\$550.00	\$770.00	
313N-4D	522-3616-000	\$220.00	\$550.00	\$770.00	
313N-4D	522-3616-001	\$220.00	\$550.00	\$770.00	
313N-4D	522-3616-200	\$220.00	\$550.00	\$770.00	
313N-4D	522-3616-201	\$220.00	\$550.00	\$770.00	
313N-4D	522-3616-202	\$220.00	\$550.00	\$770.00	
313N-4D	522-3616-204	\$220.00	\$550.00	\$770.00	
313N-4D	522-3616-501	\$220.00	\$550.00	\$770.00	
313N-4D	522-3616-502	\$220.00	\$550.00	\$770.00	
313N-4D	522-3616-503	\$220.00	\$550.00	\$770.00	
313N-4D	522-3616-504	\$220.00	\$550.00	\$770.00	
313N-5	522-2599-000	\$220.00	\$550.00	\$770.00	
313N-5	522-2599-001	\$220.00	\$550.00	\$770.00	
313N-5	522-2599-002	\$220.00	\$550.00	\$770.00	
313N-5	522-2599-003	\$220.00	\$550.00	\$770.00	
313N-5	522-2599-004	\$220.00	\$550.00	\$770.00	
313N-5	522-2599-500	\$220.00	\$550.00	\$770.00	
313N-5	522-2599-501	\$220.00	\$550.00	\$770.00	
313N-5	522-2599-502	\$220.00	\$550.00	\$770.00	
313N-5	522-2599-503	\$220.00	\$550.00	\$770.00	
313N-5	522-2599-504	\$220.00	\$550.00	\$770.00	
313N-5A	522-3617-00	\$220.00	\$550.00	\$770.00	
313N-5A	522-3617-000	\$220.00	\$550.00	\$770.00	
313N-5A	522-3617-001	\$220.00	\$550.00	\$770.00	
313N-5A	522-3617-002	\$220.00	\$550.00	\$770.00	
313N-5A	522-3617-003	\$220.00	\$550.00	\$770.00	
313N-5A	522-3617-500	\$220.00	\$550.00	\$770.00	
313N-5A	522-3617-503	\$220.00	\$550.00	\$770.00	
323A-2G	522-4945-001	\$220.00	\$550.00	N/A	SVC ONLY
323A-3G	522-2634-00	\$220.00	\$330.00	N/A	SVC ONLY
328A-3G	522-2644-000	\$220.00	\$330.00	\$750.00	
328A-3G	522-2644-001	\$220.00	\$550.00	\$750.00	
328A-3G	522-2644-011	\$220.00	\$550.00	\$750.00	
328A-3G	522-2644-013	\$220.00	\$550.00	\$750.00	
331A-3F	522-3082-00	\$220.00	\$575.00	\$700.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
331A-3F	522-3082-000	\$220.00	\$575.00	\$700.00	
331A-3F	522-3082-001	\$220.00	\$575.00	\$700.00	
331A-3F	522-3082-002	\$220.00	\$575.00	\$700.00	
331A-3G	522-2638-000	\$220.00	\$575.00	\$700.00	
331A-3G	522-2638-001	\$220.00	\$575.00	\$700.00	
331A-3G	522-2638-002	\$220.00	\$575.00	\$700.00	
331A-3G	522-2638-003	\$220.00	\$575.00	\$700.00	
331A-3G	522-2638-005	\$220.00	\$575.00	\$700.00	
331A-3G	522-2638-006	\$220.00	\$575.00	\$700.00	
331A-3G	522-2638-007	\$220.00	\$575.00	\$700.00	
331A-3G	522-2638-008	\$220.00	\$575.00	\$700.00	
331A-3G	522-2638-009	\$220.00	\$575.00	\$700.00	
331A-3G	522-2638-010	\$220.00	\$575.00	\$700.00	
331H-3G	522-3306-00	\$220.00	\$440.00	N/A	SVC ONLY
331H-3G	522-3306-001	\$220.00	\$440.00	N/A	SVC ONLY
331H-3G	522-3306-011	\$220.00	\$440.00	N/A	SVC ONLY
331H-3G	522-3306-014	\$220.00	\$440.00	N/A	SVC ONLY
332C-10	622-0555-001	\$220.00	\$450.00	\$600.00	
332C-10	622-0555-002	\$220.00	\$450.00	\$600.00	
332C-10	622-0555-003	\$220.00	\$450.00	\$600.00	
332C-10	622-0555-004	\$220.00	\$450.00	\$600.00	
332C-10	622-0555-005	\$220.00	\$450.00	\$600.00	
332C-10	622-0555-006	\$220.00	\$450.00	\$600.00	
332C-10	622-0555-007	\$220.00	\$450.00	\$600.00	
332C-10	622-0555-008	\$220.00	\$450.00	\$600.00	
332C-10	622-0555-010	\$220.00	\$450.00	\$600.00	
332C-10	622-0555-011	\$220.00	\$450.00	\$600.00	
332E-4	522-3241-00	\$220.00	N/A	\$660.00	Overhauls are not performed by SEA
332E-4	522-3241-000	\$220.00	N/A	\$1,100.00	Overhauls are not performed by SEA
339F-12	622-1234-001	\$220.00	\$500.00	\$650.00	
339F-12	622-1234-002	\$220.00	\$500.00	\$650.00	
339F-12	622-1234-003	\$220.00	\$500.00	\$650.00	
339F-12	622-1234-004	\$220.00	\$500.00	\$650.00	
339F-12	622-1234-005	\$220.00	\$500.00	\$650.00	
339F-12	622-1234-007	\$220.00	\$500.00	\$650.00	
339F-12	622-1234-012	\$220.00	\$500.00	\$650.00	
339F-12	622-1234-013	\$220.00	\$500.00	\$650.00	
339F-12	622-1234-016	\$220.00	\$500.00	\$650.00	
339F-12	622-1234-017	\$220.00	\$500.00	\$650.00	
339F-12	622-1234-103	\$220.00	\$500.00	\$650.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
339F-12	622-1234-113	\$220.00	\$500.00	\$650.00	
339F-12	622-1234-207	\$220.00	\$500.00	\$650.00	
339F-12	622-1234-313	\$220.00	\$500.00	\$650.00	
339F-12A	622-2012-011	\$220.00	\$500.00	\$650.00	
339F-12A	622-2012-012	\$220.00	\$500.00	\$650.00	
339F-12A	622-2012-013	\$220.00	\$500.00	\$650.00	
339F-12A	622-2012-014	\$220.00	\$500.00	\$650.00	
339F-12A	622-2012-201	\$220.00	\$500.00	\$650.00	
339F-12B	622-2175-001	\$220.00	\$500.00	\$650.00	
339F-12B	622-2175-002	\$220.00	\$500.00	\$650.00	
339F-12B	622-2175-003	\$220.00	\$500.00	\$650.00	
339F-12B	622-2175-004	\$220.00	\$500.00	\$650.00	
339F-12B	622-2175-201	\$220.00	\$500.00	\$650.00	
339F-12C	622-2176-001	\$220.00	\$500.00	\$650.00	
339F-12C	622-2176-002	\$220.00	\$500.00	\$650.00	
339F-12C	622-2176-201	\$220.00	\$500.00	\$650.00	
339F-12D	622-2177-001	\$220.00	\$500.00	\$650.00	
339F-12E	622-3001-001	\$220.00	\$500.00	\$650.00	
339H-1	522-4114-001	\$220.00	\$500.00	\$650.00	
339H-1	522-4114-002	\$220.00	\$500.00	\$650.00	
339H-1	522-4114-003	\$220.00	\$500.00	\$650.00	
339H-1	522-4114-004	\$220.00	\$500.00	\$650.00	
339H-1	522-4114-006	\$220.00	\$500.00	\$650.00	
339H-1	522-4114-008	\$220.00	\$500.00	\$650.00	
339H-1	522-4114-010	\$220.00	\$500.00	\$650.00	
339H-1	522-4114-012	\$220.00	\$500.00	\$650.00	
339H-1A	522-4354-001	\$220.00	\$500.00	\$650.00	
339H-1A	522-4354-002	\$220.00	\$500.00	\$650.00	
339H-1B	522-4363-001	\$220.00	\$500.00	\$650.00	
339H-1B	522-4363-002	\$220.00	\$500.00	\$650.00	
339H-1B	522-4363-004	\$220.00	\$500.00	\$650.00	
339H-1B	522-4363-006	\$220.00	\$500.00	\$650.00	
339H-1B	522-4363-007	\$220.00	\$500.00	\$650.00	
339H-1C	522-4504-001	\$220.00	\$500.00	\$650.00	
339H-1D	522-4625-001	\$220.00	\$500.00	\$650.00	
339H-2	522-4825-001	\$220.00	\$500.00	\$650.00	
339H-2	522-4825-002	\$220.00	\$500.00	\$650.00	
339H-2	522-4825-004	\$220.00	\$500.00	\$650.00	
339H-2	522-4825-005	\$220.00	\$500.00	\$650.00	
339H-2	522-4825-006	\$220.00	\$500.00	\$650.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
339H-2	522-4825-007	\$220.00	\$500.00	\$650.00	
339H-2	522-4825-008	\$220.00	\$500.00	\$650.00	
339H-2	522-4825-011	\$220.00	\$500.00	\$650.00	
339H-3	622-0171-001	\$220.00	\$500.00	\$650.00	
339H-3	622-0171-002	\$220.00	\$500.00	\$650.00	
339H-4	622-1204-001	\$220.00	\$500.00	\$650.00	
339H-4	622-1204-002	\$220.00	\$500.00	\$650.00	
339H-4	622-1204-003	\$220.00	\$500.00	\$650.00	
339H-4	622-1204-004	\$220.00	\$500.00	\$650.00	
339H-4	622-1204-005	\$220.00	\$500.00	\$650.00	
339H-4	622-1204-006	\$220.00	\$500.00	\$650.00	
339H-4	622-1204-007	\$220.00	\$500.00	\$650.00	
339H-4	622-1204-008	\$220.00	\$500.00	\$650.00	
339H-4	622-1204-010	\$220.00	\$500.00	\$650.00	
339H-4A	622-1205-001	\$220.00	\$500.00	\$650.00	
339H-4A	622-1205-002	\$220.00	\$500.00	\$650.00	
339H-4A	622-1205-003	\$220.00	\$500.00	\$650.00	
339H-4A	622-1205-004	\$220.00	\$500.00	\$650.00	
339H-4A	622-1205-005	\$220.00	\$500.00	\$650.00	
339H-4A	622-1205-006	\$220.00	\$500.00	\$650.00	
339H-5	622-5038-001	\$220.00	\$500.00	\$650.00	
339H-6	622-4563-001	\$220.00	\$500.00	\$650.00	
339H-6	622-4563-002	\$220.00	\$500.00	\$650.00	
339H-6	622-4563-004	\$220.00	\$500.00	\$650.00	
339H-6	622-4563-005	\$220.00	\$500.00	\$650.00	
339H-6	622-4563-006	\$220.00	\$500.00	\$650.00	
339H-6	622-4563-007	\$220.00	\$500.00	\$650.00	
339H-6	622-4563-008	\$220.00	\$500.00	\$650.00	
339H-6	622-4563-009	\$220.00	\$500.00	\$650.00	
339H-6	622-4563-011	\$220.00	\$500.00	\$650.00	
341C-1	341C-1	\$220.00	\$330.00	\$375.00	
341C-1	522-1400-00	\$220.00	\$330.00	\$375.00	
341C-1	522-1400-000	\$220.00	\$330.00	\$375.00	
346B-3	522-3763-001	\$220.00	\$350.00	\$500.00	
346B-3	522-3763-002	\$220.00	\$350.00	\$500.00	
346B-3	522-3763-003	\$220.00	\$350.00	\$500.00	
356C-4	522-2866-00	\$110.00	\$200.00	\$300.00	
356C-4	522-2866-000	\$110.00	\$200.00	\$300.00	
356F-3	522-2867-00	\$110.00	\$200.00	\$300.00	
356F-3	ALL	\$110.00	\$200.00	\$300.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
360 GPS	ALL	N/A	N/A	\$220.00	Flat rate repair from factory
360 MAP	ALL	N/A	N/A	\$0.00	Flat rate repair from factory
37P-4	522-0688-003	\$110.00	\$0.00	N/A	SVC ONLY
37P-4	522-0688-013	\$110.00	\$220.00	N/A	SVC ONLY
37P-4	522-0688-063	\$110.00	\$220.00	N/A	SVC ONLY
37P-4	522-0688-103	\$110.00	\$220.00	N/A	SVC ONLY
37P-4	522-0688-123	\$110.00	\$220.00	N/A	SVC ONLY
37P-4	522-0688-133	\$110.00	\$220.00	N/A	SVC ONLY
37P-4	522-0688-163	\$110.00	\$220.00	N/A	SVC ONLY
37P-4	522-0688-183	\$110.00	\$220.00	N/A	SVC ONLY
37P-4	522-0688-186	\$110.00	\$220.00	N/A	SVC ONLY
37R-2	522-1135-011	\$110.00	\$220.00	N/A	SVC ONLY
37R-2	522-1135-012	\$110.00	\$220.00	N/A	SVC ONLY
37R-2U	522-2572-000	\$110.00	\$330.00	N/A	
37R-2U	522-2572-002	\$110.00	\$330.00	N/A	
37R-2U	522-2572-012	\$110.00	\$330.00	N/A	
37R-2U	522-2572-054	\$110.00	\$330.00	N/A	
37R-2U	522-2572-055	\$110.00	\$330.00	N/A	
37X-2	522-0854-003	\$110.00	\$0.00	N/A	SVC ONLY
37X-2	522-0854-013	\$110.00	\$220.00	N/A	SVC ONLY
37X-2	522-0854-023	\$110.00	\$220.00	N/A	SVC ONLY
37X-2	522-0854-043	\$110.00	\$220.00	N/A	SVC ONLY
37X-2	522-0854-053	\$110.00	\$220.00	N/A	SVC ONLY
37X-2	522-0854-063	\$110.00	\$220.00	N/A	SVC ONLY
37X-2	522-0854-064	\$110.00	\$220.00	N/A	SVC ONLY
37X-2	522-0854-065	\$110.00	\$220.00	N/A	SVC ONLY
37X-2	522-0854-066	\$110.00	\$220.00	N/A	SVC ONLY
37X-2	522-0854-067	\$110.00	\$220.00	N/A	SVC ONLY
37X-2	522-0854-068	\$110.00	\$220.00	N/A	SVC ONLY
387C-4	522-2899-00	\$110.00	\$220.00	N/A	SVC ONLY
387C-4	522-2899-000	\$220.00	\$440.00	N/A	SVC ONLY
387C-4	522-2899-012	\$220.00	\$440.00	N/A	SVC ONLY
387C-4	522-2899-013	\$220.00	\$440.00	N/A	SVC ONLY
406 Survival	S1823502-05	\$220.00	\$550.00	N/A	Repair includes program, battery replacement
406AF	S1821502-02	\$220.00	\$550.00	N/A	Repair includes program, battery replacement
406AF(6D)	S1821502-06	\$220.00	\$550.00	N/A	Repair includes program, battery replacement
406AF-Compact	S1840501-02	\$220.00	\$550.00	N/A	Repair does not include battery replacement
406AF-H	S1822502-02	\$220.00	\$550.00	N/A	Repair includes program, battery replacement
406AP	S1820502-02	\$220.00	\$550.00	N/A	Repair includes program, battery replacement
406AP-H	S1820502-04	\$220.00	\$550.00	N/A	Repair includes program, battery replacement

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
406AS	S1823502-03	\$220.00	\$550.00	N/A	Repair includes program, battery replacement
437X-1	522-4140-001	\$110.00	\$220.00	N/A	SVC ONLY
437X-1	522-4140-002	\$110.00	\$220.00	N/A	SVC ONLY
437X-1	522-4140-003	\$110.00	\$220.00	N/A	SVC ONLY
437X-1	522-4140-004	\$110.00	\$220.00	N/A	SVC ONLY
437X-1	522-4140-005	\$110.00	\$220.00	N/A	SVC ONLY
437X-1	522-4140-006	\$110.00	\$220.00	N/A	SVC ONLY
437X-1	522-4140-007	\$110.00	\$220.00	N/A	SVC ONLY
437X-1A	522-4255-001	\$110.00	\$220.00	N/A	SVC ONLY
437X-1A	522-4255-002	\$110.00	\$220.00	N/A	SVC ONLY
437X-1A	522-4255-003	\$110.00	\$220.00	N/A	SVC ONLY
437X-1A	522-4255-004	\$110.00	\$220.00	N/A	SVC ONLY
437X-1A	522-4255-005	\$110.00	\$220.00	N/A	SVC ONLY
437X-1A	522-4255-006	\$110.00	\$220.00	N/A	SVC ONLY
437X-1A	522-4255-007	\$110.00	\$220.00	N/A	SVC ONLY
437X-1B	622-0954-001	\$110.00	\$220.00	N/A	SVC ONLY
437X-1B	622-0954-002	\$110.00	\$220.00	N/A	SVC ONLY
613L-3	270-2436-010	\$110.00	\$300.00	\$550.00	
613L-3	270-2436-020	\$220.00	\$300.00	\$550.00	
613L-3	270-2436-030	\$220.00	\$300.00	\$550.00	
613L-3	270-2436-040	\$220.00	\$300.00	\$550.00	
613L-3	270-2436-050	\$220.00	\$300.00	\$550.00	
613L-3	270-2436-060	\$220.00	\$300.00	\$550.00	
613L-3	270-2436-070	\$220.00	\$300.00	\$550.00	
613L-3	270-2436-080	\$220.00	\$300.00	\$550.00	
613L-3	270-2436-090	\$220.00	\$300.00	\$550.00	
613L-3	270-2436-100	\$220.00	\$300.00	\$550.00	
614L-11	777-1493-001	\$220.00	\$440.00	\$600.00	
614L-11	777-1493-002	\$220.00	\$440.00	\$600.00	
614L-11	777-1493-003	\$220.00	\$440.00	\$600.00	
614L-11	777-1493-004	\$220.00	\$440.00	\$600.00	
614L-11	777-1493-005	\$220.00	\$440.00	\$600.00	
614L-11	777-1493-006	\$220.00	\$440.00	\$600.00	
614L-11	777-1493-007	\$220.00	\$440.00	\$600.00	
614L-11	777-1493-008	\$220.00	\$440.00	\$600.00	
614L-11	777-1493-009	\$220.00	\$440.00	\$600.00	
614L-11	777-1493-010	\$220.00	\$440.00	\$600.00	
614L-12	787-6366-001	\$220.00	\$440.00	\$600.00	
614L-12	787-6366-002	\$220.00	\$440.00	\$600.00	
614L-12	787-6366-003	\$220.00	\$440.00	\$600.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
614L-12	787-6366-004	\$220.00	\$440.00	\$600.00	
614L-12	787-6366-005	\$220.00	\$440.00	\$600.00	
614L-12	787-6366-006	\$220.00	\$440.00	\$600.00	
614L-12	787-6366-007	\$220.00	\$440.00	\$600.00	
614L-12	787-6366-008	\$220.00	\$440.00	\$600.00	
614L-12	787-6366-009	\$220.00	\$440.00	\$600.00	
614L-12	787-6366-010	\$220.00	\$440.00	\$600.00	
614L-12	787-6366-011	\$220.00	\$440.00	\$600.00	
614L-12	787-6366-012	\$220.00	\$440.00	\$600.00	
614L-13	792-6275-001	\$220.00	\$440.00	\$600.00	
614L-13	792-6275-002	\$220.00	\$440.00	\$600.00	
614L-13	792-6275-003	\$220.00	\$440.00	\$600.00	
614L-13	792-6275-004	\$220.00	\$440.00	\$600.00	
614L-13	792-6275-005	\$220.00	\$440.00	\$600.00	
614L-13	792-6275-006	\$220.00	\$440.00	\$600.00	
614L-13	792-6275-007	\$220.00	\$440.00	\$600.00	
614L-13	792-6275-008	\$220.00	\$440.00	\$600.00	
699Z-1	622-1032-001	\$220.00	\$400.00	\$550.00	
A151B	93A151-20	\$220.00	\$400.00	\$600.00	
A151B	93A151-30	\$220.00	\$400.00	\$600.00	
A151B	93A151-40	\$220.00	\$400.00	\$600.00	
A152	93A152-00	\$220.00	\$400.00	\$600.00	
A152	93A152-04	\$220.00	\$400.00	\$600.00	
A152B	93A152-20	\$220.00	\$400.00	\$600.00	
A152B	93A152-25	\$220.00	\$400.00	\$600.00	
A152B	93A152-30	\$220.00	\$400.00	\$600.00	
A152B	93A152-40	\$220.00	\$400.00	\$600.00	
A152B	93A152-50	\$220.00	\$400.00	\$600.00	
A152B	93A152-60	\$220.00	\$400.00	\$600.00	
A152B	93A152-70	\$220.00	\$400.00	\$600.00	
A55B	93A055-03	\$220.00	\$300.00	N/A	
A55B	93A055-04	\$110.00	\$300.00	N/A	
A55B	93A055-30	\$110.00	\$300.00	N/A	
A55B	93A055-40	\$110.00	\$300.00	N/A	
A55B	93A055-60	\$110.00	\$300.00	N/A	
A55B	93A055-67	\$110.00	\$300.00	N/A	
A55B	93A055-95	\$110.00	\$300.00	N/A	
AA-1210A	4000525-1210	\$110.00	\$110.00	N/A	Inspection Only
AA-1212A	4000525-1212	\$110.00	\$110.00	N/A	Inspection Only
AA-1218A	4000525-1218	\$110.00	\$110.00	N/A	Inspection Only

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
AA-2010H	071-01528-0100	\$110.00	\$110.00	N/A	Inspection Only
AA-2010V	071-01549-0100	\$110.00	\$110.00	N/A	Inspection Only
AA-2012H	071-01528-0200	\$110.00	\$110.00	N/A	Inspection Only
AA-2012V	071-01549-0200	\$110.00	\$110.00	N/A	Inspection Only
AA-4510A	4000525-4510	\$110.00	\$110.00	N/A	Inspection Only
AA-4512A	4000525-4512	\$110.00	\$110.00	N/A	Inspection Only
AA-4518A	4000525-4518	\$110.00	\$110.00	N/A	Inspection Only
AA-5510A	4000525-5510	\$110.00	\$110.00	N/A	Inspection Only
AA-5510B	071-1316-00	\$110.00	\$110.00	N/A	Inspection Only
AA-5510B	3614165-5510	\$110.00	\$110.00	N/A	Inspection Only
AA-5512A	4000525-5512	\$110.00	\$110.00	N/A	Inspection Only
AA-5512B	071-1317-00	\$110.00	\$110.00	N/A	Inspection Only
AA-5512B	3614165-5512	\$110.00	\$110.00	N/A	Inspection Only
AAC-200	622-2884-001	\$330.00	\$750.00	\$1,250.00	Overhaul subject to parts availability
AAC-200	622-2884-002	\$330.00	\$750.00	\$1,250.00	Overhaul subject to parts availability
AAC-200	622-2884-003	\$330.00	\$750.00	\$1,250.00	Overhaul subject to parts availability
AAC-200	622-2884-004	\$330.00	\$750.00	\$1,250.00	Overhaul subject to parts availability
AAC-200	622-2884-005	\$330.00	\$750.00	\$1,250.00	Overhaul subject to parts availability
AAC-220P	622-6471-001	\$330.00	\$750.00	\$1,250.00	Overhaul subject to parts availability
AAC-220P	622-6471-002	\$330.00	\$750.00	\$1,250.00	Overhaul subject to parts availability
ADA-650	622-2609-001	\$110.00	\$400.00	N/A	SVC ONLY
ADF-462	622-7382-001	\$220.00	\$450.00	\$650.00	
ADF-462	622-7382-101	\$220.00	\$450.00	\$650.00	
ADF-462	622-7382-111	\$220.00	\$450.00	\$650.00	
ADF-60A	622-2362-001	\$220.00	\$400.00	\$600.00	
ADF-60B	622-2873-001	\$220.00	\$400.00	\$600.00	
ALI-55	622-2937-001	\$220.00	\$750.00	\$1,150.00	
ALI-55	622-2937-002	\$220.00	\$750.00	\$1,150.00	
ALI-55	622-2937-003	\$220.00	\$750.00	\$1,150.00	
ALI-55	622-2937-004	\$220.00	\$750.00	\$1,150.00	
ALI-55	622-2937-005	\$220.00	\$750.00	\$1,150.00	
ALI-55	622-2937-008	\$220.00	\$750.00	\$1,150.00	
ALI-55	622-2937-009	\$220.00	\$750.00	\$1,150.00	
ALI-55A	622-2938-001	\$220.00	\$750.00	\$1,150.00	
ALI-55A	622-2938-002	\$220.00	\$750.00	\$1,150.00	
ALI-55A	622-2938-003	\$220.00	\$750.00	\$1,150.00	
ALI-55A	622-2938-004	\$220.00	\$750.00	\$1,150.00	
ALI-55B	622-5367-001	\$220.00	\$750.00	\$750.00	
ALT-50A	622-3201-001	\$220.00	\$550.00	\$800.00	
ALT-50A	622-3201-002	\$220.00	\$550.00	\$800.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
ALT-50A	622-3201-011	\$220.00	\$550.00	\$800.00	
ALT-50A	622-3201-012	\$220.00	\$550.00	\$800.00	
ALT-55B	622-2855-001	\$220.00	\$550.00	\$800.00	
ALT-55B	622-2855-002	\$220.00	\$550.00	\$800.00	
ALT-55B	622-2855-011	\$220.00	\$550.00	\$800.00	
ALT-55B	622-2855-012	\$220.00	\$550.00	\$800.00	
ANT-210	622-2495-001	\$220.00	\$550.00	See notes	Overhaul not possible in most cases
ANT-210	622-2495-002	\$220.00	\$550.00	See notes	Overhaul not possible in most cases
ANT-212	622-2494-001	\$220.00	\$550.00	See notes	Overhaul not possible in most cases
ANT-212	622-2494-002	\$220.00	\$550.00	See notes	Overhaul not possible in most cases
ANT-212D	622-4020-001	\$220.00	\$550.00	\$800.00	Overhaul subject to age of unit
ANT-310	622-2502-001	\$220.00	\$550.00	\$800.00	Overhaul subject to age of unit
ANT-310A	622-7444-001	\$220.00	\$550.00	\$800.00	Overhaul subject to age of unit
ANT-312	622-2501-001	\$220.00	\$550.00	\$800.00	Overhaul subject to age of unit
ANT-312A	622-6513-001	\$220.00	\$550.00	\$800.00	Overhaul subject to age of unit
ANT-318	622-2504-001	\$220.00	\$550.00	\$800.00	Overhaul subject to age of unit
ANT-318A	622-6633-001	\$220.00	\$550.00	\$800.00	Overhaul subject to age of unit
ANT-462A	622-7383-001	\$110.00	\$220.00	N/A	SVC ONLY
ANT-462B	622-7384-001	\$110.00	\$220.00	N/A	SVC ONLY
ANT-50A	622-3698-001	\$0.00	\$0.00	N/A	SVC ONLY
ANT-52	622-6793-001	\$110.00	\$220.00	N/A	SVC ONLY
ANT-60A	622-2363-001	\$110.00	\$220.00	N/A	SVC ONLY
ANT-60A	622-2363-002	\$110.00	\$220.00	N/A	SVC ONLY
ANT-60A	622-2363-011	\$110.00	\$220.00	N/A	SVC ONLY
ANT-60B	622-3710-001	\$110.00	\$220.00	N/A	SVC ONLY
ANT-650A	622-3586-001	\$110.00	\$220.00	N/A	SVC ONLY
AP-3001	MI-585224	\$220.00	\$450.00	See notes	Overhaul not possible in most cases
AP-3001	MI-585224-1	\$220.00	\$450.00	See notes	Overhaul not possible in most cases
AP-3001	MI-585224-2	\$220.00	\$450.00	See notes	Overhaul not possible in most cases
AP-3001	MI-585224-3	\$220.00	\$450.00	See notes	Overhaul not possible in most cases
AP-4001	MI-585202	\$220.00	\$450.00	See notes	Overhaul not possible in most cases
AP-4001	MI-585202-1	\$220.00	\$450.00	See notes	Overhaul not possible in most cases
AP-5001	MI-585302	\$220.00	\$450.00	See notes	Overhaul not possible in most cases
AP-5001	MI-585302-1	\$220.00	\$450.00	See notes	Overhaul not possible in most cases
ART-161A	4001018-6101	\$220.00	\$600.00	See notes	Overhaul not possible in most cases
ART-161A	4001018-6102	\$220.00	\$600.00	See notes	Overhaul not possible in most cases
ART-161A	4001018-6103	\$220.00	\$600.00	See notes	Overhaul not possible in most cases
ART-161A	4001018-6104	\$220.00	\$600.00	See notes	Overhaul not possible in most cases
ART-161A	4001018-6105	\$220.00	\$600.00	See notes	Overhaul not possible in most cases
ART-161A	4001018-6106	\$220.00	\$600.00	See notes	Overhaul not possible in most cases



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
ART-161A	4001018-6107	\$220.00	\$600.00	See notes	Overhaul not possible in most cases
ART-161A	4001018-6108	\$220.00	\$600.00	See notes	Overhaul not possible in most cases
ART-2000	071-01519-0101	\$330.00	\$1,250.00	\$2,750.00	Magnetron replace not included
ART-2100	071-01550-0101	\$330.00	\$1,250.00	\$2,750.00	Magnetron replace not included
B406-4	453-5004	\$220.00	\$545.00	N/A	Repair includes program, battery replacement
B406-4	453-5004-(999)	\$220.00	\$545.00	N/A	Repair includes program, battery replacement
BDI-36	622-3702-001	\$330.00	\$950.00	\$1,250.00	
BDI-36	622-3702-002	\$330.00	\$950.00	\$1,250.00	
BDI-36	622-3702-003	\$330.00	\$950.00	\$1,250.00	
BDI-36	622-3702-004	\$330.00	\$950.00	\$1,250.00	
BDI-36	622-3702-005	\$330.00	\$950.00	\$1,250.00	
BDI-36	622-3702-006	\$330.00	\$950.00	\$1,250.00	
BDI-36	622-3702-007	\$330.00	\$950.00	\$1,250.00	
BDI-36	622-3702-008	\$330.00	\$950.00	\$1,250.00	
BDI-36	622-3702-009	\$330.00	\$950.00	\$1,250.00	
BDI-36	622-3702-010	\$330.00	\$950.00	\$1,250.00	
BDI-36	622-3702-011	\$330.00	\$950.00	\$1,250.00	
BDI-36	622-3702-012	\$330.00	\$950.00	\$1,250.00	
BDI-36	622-3702-013	\$330.00	\$950.00	\$1,250.00	
BDI-36	622-3702-014	\$330.00	\$950.00	\$1,250.00	
BDI-36	622-3702-015	\$330.00	\$950.00	\$1,250.00	
BDI-36	622-3702-016	\$330.00	\$950.00	\$1,250.00	
C406-1	453-5002-XXX	\$220.00	\$545.00	N/A	Repair includes program, battery replacement
C406-1HM	453-5003-XXX	\$220.00	\$545.00	N/A	Repair includes program, battery replacement
C406-2	453-5000-XXX	\$220.00	\$545.00	N/A	Repair includes program, battery replacement
C406-2HM	453-5001-XXX	\$220.00	\$545.00	N/A	Repair includes program, battery replacement
C406-N	453-5060-XXX	\$220.00	\$545.00	N/A	Repair includes program, battery replacement
C406-NHM	453-5061-XXX	\$220.00	\$545.00	N/A	Repair includes program, battery replacement
CAD-31	622-8332-001	\$0.00	\$0.00	\$0.00	
CAD-31	622-8332-002	\$110.00	\$220.00	\$330.00	
CAD-62	622-6590-001	\$110.00	\$220.00	\$330.00	
CAD-62	622-6590-002	\$110.00	\$220.00	\$330.00	
CM-2000	071-00097-0100	\$110.00	\$220.00	\$330.00	
CNX-80	ALL	N/A	\$1,000.00	\$220.00	Flat rate repair from factory
CTL-20	622-4523-001	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-002	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-003	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-004	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-005	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-006	\$220.00	\$750.00	\$1,400.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-20	622-4523-007	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-008	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-009	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-010	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-011	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-012	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-013	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-014	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-015	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-016	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-017	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-018	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-201	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-202	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-203	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-204	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-205	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-206	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-207	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-208	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-209	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-210	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-211	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-212	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-213	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-214	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-215	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-216	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-217	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-218	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-801	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-802	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-803	\$220.00	\$750.00	\$1,400.00	
CTL-20	622-4523-804	\$220.00	\$750.00	\$1,400.00	
CTL-200	622-2885-001	\$220.00	\$1,320.00	See notes	Overhaul not possible in most cases
CTL-200	622-2885-002	\$220.00	\$440.00	See notes	Overhaul not possible in most cases
CTL-200	622-2885-003	\$220.00	\$440.00	See notes	Overhaul not possible in most cases
CTL-200	622-2885-004	\$220.00	\$440.00	See notes	Overhaul not possible in most cases
CTL-200	622-2885-005	\$220.00	\$440.00	See notes	Overhaul not possible in most cases
CTL-200	622-2885-006	\$220.00	\$440.00	See notes	Overhaul not possible in most cases

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-200	622-2885-011	\$220.00	\$440.00	See notes	Overhaul not possible in most cases
CTL-200	622-2885-012	\$220.00	\$440.00	See notes	Overhaul not possible in most cases
CTL-200	622-2885-013	\$220.00	\$440.00	See notes	Overhaul not possible in most cases
CTL-200	622-2885-014	\$220.00	\$440.00	See notes	Overhaul not possible in most cases
CTL-200	622-2885-015	\$220.00	\$440.00	See notes	Overhaul not possible in most cases
CTL-200	622-2885-016	\$220.00	\$440.00	See notes	Overhaul not possible in most cases
CTL-201	622-4471-001	\$220.00	\$440.00	\$660.00	
CTL-201A	622-4490-001	\$220.00	\$440.00	\$660.00	
CTL-201A	622-4490-002	\$220.00	\$440.00	\$660.00	
CTL-21	622-4530-001	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-002	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-003	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-004	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-005	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-006	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-007	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-008	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-009	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-010	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-011	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-012	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-013	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-014	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-015	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-016	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-017	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-018	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-201	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-202	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-203	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-204	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-205	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-206	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-207	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-208	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-209	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-210	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-211	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-212	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-213	\$220.00	\$750.00	\$1,400.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-21	622-4530-214	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-215	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-216	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-501	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-801	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-802	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-803	\$220.00	\$750.00	\$1,400.00	
CTL-21	622-4530-804	\$220.00	\$750.00	\$1,400.00	
CTL-22	622-6520-001	\$220.00	\$1,320.00	\$700.00	
CTL-22	622-6520-002	\$220.00	\$550.00	\$700.00	
CTL-22	622-6520-003	\$220.00	\$550.00	\$700.00	
CTL-22	622-6520-004	\$220.00	\$550.00	\$700.00	
CTL-22	622-6520-005	\$220.00	\$550.00	\$700.00	
CTL-22	622-6520-006	\$220.00	\$550.00	\$700.00	
CTL-22	622-6520-007	\$220.00	\$550.00	\$700.00	
CTL-22	622-6520-008	\$220.00	\$550.00	\$700.00	
CTL-22	622-6520-009	\$220.00	\$550.00	\$700.00	
CTL-22	622-6520-010	\$220.00	\$550.00	\$700.00	
CTL-22	622-6520-011	\$220.00	\$550.00	\$700.00	
CTL-22	622-6520-012	\$220.00	\$550.00	\$700.00	
CTL-22	622-6520-013	\$220.00	\$550.00	\$700.00	
CTL-22	622-6520-014	\$220.00	\$550.00	\$700.00	
CTL-22	622-6520-015	\$220.00	\$550.00	\$700.00	
CTL-22	622-6520-016	\$220.00	\$550.00	\$700.00	
CTL-22	622-6520-801	\$220.00	\$550.00	\$700.00	
CTL-22	622-6520-802	\$220.00	\$550.00	\$700.00	
CTL-220	622-4545-001	\$220.00	\$550.00	\$850.00	
CTL-220	622-4545-002	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-003	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-004	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-005	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-006	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-011	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-012	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-013	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-014	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-015	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-016	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-021	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-022	\$220.00	\$440.00	\$850.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-220	622-4545-023	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-024	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-025	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-026	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-031	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-032	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-033	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-034	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-035	\$220.00	\$440.00	\$850.00	
CTL-220	622-4545-036	\$220.00	\$440.00	\$850.00	
CTL-22C	822-1120-001	\$220.00	\$450.00	\$650.00	
CTL-22C	822-1120-002	\$220.00	\$450.00	\$650.00	
CTL-22C	822-1120-003	\$220.00	\$450.00	\$650.00	
CTL-22C	822-1120-004	\$220.00	\$450.00	\$650.00	
CTL-22C	822-1120-005	\$220.00	\$450.00	\$650.00	
CTL-22C	822-1120-006	\$220.00	\$450.00	\$650.00	
CTL-22C	822-1120-007	\$220.00	\$450.00	\$650.00	
CTL-22C	822-1120-008	\$220.00	\$450.00	\$650.00	
CTL-22C	822-1120-009	\$220.00	\$450.00	\$650.00	
CTL-22C	822-1120-010	\$220.00	\$450.00	\$650.00	
CTL-22C	822-1120-011	\$220.00	\$450.00	\$650.00	
CTL-22C	822-1120-012	\$220.00	\$450.00	\$650.00	
CTL-22C	822-1120-013	\$220.00	\$450.00	\$650.00	
CTL-22C	822-1120-014	\$220.00	\$450.00	\$650.00	
CTL-22C	822-1120-015	\$220.00	\$450.00	\$650.00	
CTL-22C	822-1120-016	\$220.00	\$450.00	\$650.00	
CTL-22C	822-1120-801	\$220.00	\$450.00	\$650.00	
CTL-22C	822-1120-802	\$220.00	\$450.00	\$650.00	
CTL-230	622-6614-001	\$220.00	\$550.00	\$770.00	
CTL-230	622-6614-002	\$220.00	\$550.00	\$770.00	
CTL-230	622-6614-003	\$220.00	\$550.00	\$770.00	
CTL-230	622-6614-004	\$220.00	\$550.00	\$770.00	
CTL-230	622-6614-005	\$220.00	\$550.00	\$770.00	
CTL-230	622-6614-006	\$220.00	\$550.00	\$770.00	
CTL-230	622-6614-007	\$220.00	\$550.00	\$770.00	
CTL-230	622-6614-008	\$220.00	\$550.00	\$770.00	
CTL-230	622-6614-021	\$220.00	\$550.00	\$770.00	
CTL-230	622-6614-022	\$220.00	\$550.00	\$770.00	
CTL-230	622-6614-023	\$220.00	\$550.00	\$770.00	
CTL-230	622-6614-024	\$220.00	\$550.00	\$770.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-230	622-6614-025	\$220.00	\$550.00	\$770.00	
CTL-230	622-6614-026	\$220.00	\$550.00	\$770.00	
CTL-230	622-6614-027	\$220.00	\$550.00	\$770.00	
CTL-230	622-6614-028	\$220.00	\$550.00	\$770.00	
CTL-30	622-4524-001	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-002	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-003	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-004	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-005	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-006	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-007	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-008	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-009	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-010	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-011	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-012	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-013	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-014	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-015	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-016	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-017	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-018	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-019	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-020	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-021	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-022	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-023	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-024	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-025	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-026	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-027	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-028	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-029	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-030	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-031	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-032	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-033	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-034	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-035	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-036	\$220.00	\$750.00	\$1,400.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-30	622-4524-037	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-038	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-039	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-040	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-041	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-042	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-043	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-044	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-045	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-046	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-047	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-048	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-049	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-050	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-051	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-052	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-053	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-054	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-055	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-056	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-057	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-058	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-059	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-060	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-061	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-062	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-063	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-064	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-065	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-066	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-067	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-068	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-069	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-070	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-071	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-072	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-073	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-074	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-075	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-076	\$220.00	\$750.00	\$1,400.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-30	622-4524-077	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-078	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-079	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-080	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-081	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-082	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-083	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-084	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-085	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-086	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-087	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-088	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-089	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-090	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-091	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-092	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-093	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-094	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-095	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-096	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-097	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-098	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-099	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-100	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-101	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-102	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-103	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-104	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-105	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-106	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-107	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-108	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-109	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-110	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-111	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-112	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-261	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-262	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-263	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-264	\$220.00	\$750.00	\$1,400.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-30	622-4524-265	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-266	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-267	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-268	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-269	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-270	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-271	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-272	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-273	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-274	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-275	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-276	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-277	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-278	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-279	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-801	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-802	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-803	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-804	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-805	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-806	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-807	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-808	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-809	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-810	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-811	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-812	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-813	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-814	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-815	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-816	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-817	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-818	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-819	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-820	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-821	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-822	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-823	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-824	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-825	\$220.00	\$750.00	\$1,400.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-30	622-4524-826	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-827	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-828	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-841	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-842	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-843	\$220.00	\$750.00	\$1,400.00	
CTL-30	622-4524-844	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-001	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-002	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-003	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-004	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-005	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-006	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-007	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-008	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-009	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-010	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-011	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-012	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-013	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-014	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-015	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-016	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-017	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-018	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-019	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-020	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-021	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-022	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-023	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-024	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-025	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-026	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-027	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-028	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-029	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-030	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-031	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-032	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-033	\$220.00	\$750.00	\$1,400.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-31	622-4531-034	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-035	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-036	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-037	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-038	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-039	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-040	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-041	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-042	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-043	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-044	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-045	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-046	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-047	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-048	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-049	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-050	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-051	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-052	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-053	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-054	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-055	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-056	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-057	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-058	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-059	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-060	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-061	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-062	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-063	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-064	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-065	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-066	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-067	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-068	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-069	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-070	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-071	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-072	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-073	\$220.00	\$750.00	\$1,400.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-31	622-4531-074	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-075	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-076	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-077	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-078	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-079	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-080	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-081	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-082	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-083	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-084	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-085	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-086	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-087	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-088	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-089	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-090	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-091	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-092	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-093	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-094	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-095	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-096	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-097	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-098	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-099	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-100	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-101	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-102	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-103	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-104	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-105	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-106	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-107	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-108	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-109	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-110	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-111	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-112	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-113	\$220.00	\$750.00	\$1,400.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-31	622-4531-501	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-801	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-802	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-803	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-804	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-805	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-806	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-807	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-808	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-809	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-810	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-811	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-812	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-813	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-814	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-815	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-816	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-817	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-818	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-819	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-820	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-821	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-822	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-823	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-824	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-825	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-826	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-827	\$220.00	\$750.00	\$1,400.00	
CTL-31	622-4531-828	\$220.00	\$750.00	\$1,400.00	
CTL-32	622-6521-001	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-002	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-003	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-004	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-005	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-006	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-007	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-008	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-009	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-010	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-011	\$220.00	\$450.00	\$600.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-32	622-6521-012	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-013	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-014	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-015	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-016	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-025	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-026	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-027	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-028	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-029	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-030	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-031	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-032	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-801	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-802	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-803	\$220.00	\$450.00	\$600.00	
CTL-32	622-6521-804	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-001	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-002	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-003	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-004	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-005	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-006	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-007	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-008	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-009	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-010	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-011	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-012	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-013	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-014	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-015	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-016	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-025	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-026	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-027	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-028	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-029	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-030	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-031	\$220.00	\$450.00	\$600.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-32A	622-8738-032	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-801	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-802	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-803	\$220.00	\$450.00	\$600.00	
CTL-32A	622-8738-804	\$220.00	\$450.00	\$600.00	
CTL-60	622-4526-001	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-002	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-003	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-004	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-005	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-006	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-007	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-008	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-009	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-010	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-011	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-012	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-013	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-014	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-015	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-016	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-017	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-018	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-019	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-020	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-021	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-022	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-023	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-024	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-025	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-026	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-027	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-028	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-029	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-030	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-031	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-032	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-033	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-034	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-801	\$220.00	\$750.00	\$1,400.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-60	622-4526-802	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-803	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-804	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-805	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-806	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-807	\$220.00	\$750.00	\$1,400.00	
CTL-60	622-4526-808	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-001	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-002	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-003	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-004	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-005	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-006	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-007	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-008	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-009	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-010	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-011	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-012	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-013	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-014	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-015	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-016	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-017	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-501	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-801	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-802	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-803	\$220.00	\$750.00	\$1,400.00	
CTL-61	622-4532-804	\$220.00	\$750.00	\$1,400.00	
CTL-62	622-6522-001	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-002	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-003	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-004	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-005	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-006	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-007	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-008	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-009	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-010	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-011	\$220.00	\$450.00	\$600.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-62	622-6522-012	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-013	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-014	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-015	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-016	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-017	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-018	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-019	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-020	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-021	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-022	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-023	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-024	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-025	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-026	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-027	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-028	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-029	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-030	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-031	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-032	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-801	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-802	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-803	\$220.00	\$450.00	\$600.00	
CTL-62	622-6522-804	\$220.00	\$450.00	\$600.00	
CTL-90	622-4527-001	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-002	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-003	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-004	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-005	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-006	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-007	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-008	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-009	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-010	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-011	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-012	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-013	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-014	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-015	\$220.00	\$750.00	\$1,400.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-90	622-4527-016	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-017	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-018	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-019	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-020	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-021	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-801	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-802	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-803	\$220.00	\$750.00	\$1,400.00	
CTL-90	622-4527-804	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-001	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-002	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-003	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-004	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-005	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-006	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-007	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-008	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-009	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-010	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-011	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-012	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-013	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-014	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-015	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-016	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-017	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-501	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-801	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-802	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-803	\$220.00	\$750.00	\$1,400.00	
CTL-91	622-4533-804	\$220.00	\$750.00	\$1,400.00	
CTL-92	622-6523-001	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-002	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-003	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-004	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-005	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-006	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-007	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-008	\$220.00	\$450.00	\$600.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-92	622-6523-009	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-010	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-011	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-012	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-013	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-014	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-015	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-016	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-201	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-202	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-203	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-204	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-205	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-206	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-207	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-208	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-209	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-210	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-211	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-212	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-213	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-214	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-215	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-305	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-306	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-307	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-308	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-309	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-310	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-311	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-312	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-313	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-314	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-315	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-316	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-801	\$220.00	\$450.00	\$600.00	
CTL-92	622-6523-802	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-001	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-002	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-003	\$220.00	\$450.00	\$600.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
CTL-92T	622-9614-004	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-005	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-006	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-007	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-008	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-009	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-010	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-011	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-012	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-013	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-014	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-015	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-016	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-101	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-102	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-103	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-104	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-105	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-106	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-107	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-108	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-109	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-110	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-111	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-112	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-113	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-114	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-115	\$220.00	\$450.00	\$600.00	
CTL-92T	622-9614-116	\$220.00	\$450.00	\$600.00	
DA-1203A	4000504-0301	\$220.00	\$450.00	N/A	SVC ONLY
DA-1203A	4000504-0302	\$220.00	\$450.00	N/A	SVC ONLY
DA-1203A	4000504-0303	\$220.00	\$450.00	N/A	SVC ONLY
DA-1203A	4000504-0304	\$220.00	\$450.00	N/A	SVC ONLY
DA-1203A	4000504-0305	\$220.00	\$450.00	N/A	SVC ONLY
DA-1203A	4000504-0306	\$220.00	\$450.00	N/A	SVC ONLY
DA-1203A	4000504-0307	\$220.00	\$450.00	N/A	SVC ONLY
DA-144A	4000790-4402	\$330.00	\$450.00	N/A	SVC ONLY
DA-144A	4000790-4403	\$220.00	\$450.00	N/A	SVC ONLY
DA-144A	4000790-4404	\$220.00	\$450.00	N/A	SVC ONLY
DA-144A	4000790-4405	\$220.00	\$450.00	N/A	SVC ONLY

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
DA-144A	4000790-4406	\$220.00	\$450.00	N/A	SVC ONLY
DA-144A	4000790-4407	\$220.00	\$450.00	N/A	SVC ONLY
DA-144A	4000790-4401	\$220.00	\$450.00	N/A	SVC ONLY
DI-2007	MI-585277	\$220.00	\$220.00	\$1,100.00	
DI-2007	MI-585277-1	\$220.00	\$660.00	\$1,100.00	
DI-2007	MI-585277-4	\$220.00	\$660.00	\$1,100.00	
DI-2007	MI-585277-5	\$220.00	\$660.00	\$1,100.00	
DI-2008	MI-585277-2	\$220.00	\$660.00	\$1,100.00	
DI-2008	MI-585277-3	\$220.00	\$660.00	\$1,100.00	
DI-3001	MI-585223	\$220.00	\$660.00	\$1,100.00	
DI-3001	MI-585223-1	\$220.00	\$660.00	\$1,100.00	
DI-3001	MI-585223-3	\$220.00	\$660.00	\$1,100.00	
DI-3003	MI-585228	\$220.00	\$660.00	\$1,100.00	
DI-3003	MI-585228-1	\$220.00	\$660.00	\$1,100.00	
DI-3003	MI-585228-2	\$220.00	\$660.00	\$1,100.00	
DI-3003	MI-585228-3	\$220.00	\$660.00	\$1,100.00	
DI-4001	MI-585201	\$220.00	\$660.00	\$1,100.00	
DI-4001	MI-585201-1	\$220.00	\$660.00	\$1,100.00	
DI-4001	MI-585201-2	\$220.00	\$660.00	\$1,100.00	
DI-4001	MI-585201-3	\$220.00	\$660.00	\$1,100.00	
DI-4002	MI-585343	\$220.00	\$660.00	\$1,100.00	
DI-4002	MI-585343-1	\$220.00	\$660.00	\$1,100.00	
DI-5001	MI-585301	\$220.00	\$660.00	\$1,100.00	
DI-5001	MI-585301-1	\$220.00	\$770.00	\$1,100.00	
DI-5001	MI-585301-2	\$220.00	\$770.00	\$1,100.00	
DI-5001	MI-585301-3	\$220.00	\$770.00	\$1,100.00	
DME-40	622-1233-001	\$220.00	\$600.00	\$850.00	Tube replacement not included
DME-42	622-6263-001	\$220.00	\$600.00	\$850.00	
DME-42	622-6263-002	\$220.00	\$600.00	\$850.00	
DME-42	622-6263-003	\$220.00	\$600.00	\$850.00	
DME-442	622-7309-001	\$220.00	\$600.00	\$850.00	
DME-442	622-7309-101	\$220.00	\$600.00	\$850.00	
DRI-55	622-4160-001	\$220.00	\$750.00	\$1,100.00	Overhaul subject to availability of parts
DRI-55	622-4160-002	\$220.00	\$750.00	\$1,100.00	Overhaul subject to availability of parts
DRI-55	622-4160-003	\$220.00	\$750.00	\$1,100.00	Overhaul subject to availability of parts
DRI-55	622-4160-004	\$220.00	\$750.00	\$1,100.00	Overhaul subject to availability of parts
DRI-55	622-4160-005	\$220.00	\$750.00	\$1,100.00	Overhaul subject to availability of parts
DRI-55	622-4160-006	\$220.00	\$750.00	\$1,100.00	Overhaul subject to availability of parts
DRI-55	622-4160-007	\$220.00	\$750.00	\$1,100.00	Overhaul subject to availability of parts
DRI-55	622-4160-008	\$220.00	\$750.00	\$1,100.00	Overhaul subject to availability of parts

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
DRI-55	622-4160-009	\$220.00	\$750.00	\$1,100.00	Overhaul subject to availability of parts
DRI-55	622-4160-010	\$220.00	\$750.00	\$1,100.00	Overhaul subject to availability of parts
DRI-55	622-4160-011	\$220.00	\$750.00	\$1,100.00	Overhaul subject to availability of parts
DRI-55	622-4160-012	\$220.00	\$750.00	\$1,100.00	Overhaul subject to availability of parts
DRI-55	622-4160-013	\$220.00	\$750.00	\$1,100.00	Overhaul subject to availability of parts
DRI-55	622-4160-014	\$220.00	\$750.00	\$1,100.00	Overhaul subject to availability of parts
DRI-55	622-4160-015	\$220.00	\$750.00	\$1,100.00	Overhaul subject to availability of parts
DRI-55	622-4160-016	\$220.00	\$750.00	\$1,100.00	Overhaul subject to availability of parts
DRI-55	622-4160-017	\$220.00	\$750.00	\$1,100.00	Overhaul subject to availability of parts
DRI-55	622-4160-018	\$220.00	\$750.00	\$1,100.00	Overhaul subject to availability of parts
FDU-70	622-5812-001	\$110.00	\$220.00	N/A	SVC ONLY
FDU-70	622-5812-002	\$110.00	\$220.00	N/A	SVC ONLY
FDU-70	622-5812-003	\$110.00	\$220.00	N/A	SVC ONLY
FDU-70	622-5812-004	\$110.00	\$220.00	N/A	SVC ONLY
FDU-70	622-5812-005	\$110.00	\$220.00	N/A	SVC ONLY
FDU-70	622-5812-006	\$110.00	\$220.00	N/A	SVC ONLY
FX-220	2594484	\$110.00	\$220.00	N/A	SVC ONLY
G406-1	453-5100-XXX	\$220.00	\$450.00	N/A	Repair includes program, battery replacement
G406-4	453-5012-XXX	\$220.00	\$450.00	N/A	Repair includes program, battery replacement
GA-56	011-00134-00	\$0.00	\$220.00	N/A	Repair is paint only
GAD-42	011-00417-00	N/A	\$700.00	\$0.00	
GDC-74A	011-00882-00	\$330.00	N/A	N/A	
GDC-74A	011-00882-01	\$330.00	N/A	N/A	
GDC-74A	011-00882-10	\$330.00	N/A	N/A	
GDC-74H	011-00882-11	\$330.00	N/A	N/A	
GLS-350	622-2084-001	\$0.00	\$0.00	N/A	
GMA-340	011-00401-00	\$220.00	\$695.00	\$0.00	
GMA-340	011-00401-01	\$220.00	\$695.00	\$0.00	
GMA-340	011-00401-10	\$220.00	\$695.00	\$0.00	
GMA-340	011-00401-20	\$220.00	\$695.00	\$0.00	
GNC-250	011-00082-00	\$220.00	\$645.00	\$0.00	
GNC-250XL	011-00295-00	\$220.00	\$645.00	\$0.00	
GNC-300	011-00128-00	\$220.00	\$645.00	\$0.00	
GNC-300XL	011-00433-00	\$220.00	\$645.00		
GNC-420	011-00506-00	\$330.00	\$660.00		
GNC-420	011-00506-10	\$330.00	\$660.00		
GNC-420	011-00506-30	\$330.00	\$660.00		
GNC-420A	011-00837-00	\$330.00	\$660.00		
GNC-420A	011-00837-10	\$330.00	\$660.00		
GNC-420AW	011-01059-00	\$330.00	\$660.00		

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
GNC-420AW	011-01059-10	\$330.00	\$660.00		
GNC-420AW	011-01059-40	\$330.00	\$660.00		
GNC-420AW	011-01059-50	\$330.00	\$660.00		
GNC-420W	011-01058-00	\$330.00	\$660.00		
GNC-420W	011-01058-10	\$330.00	\$660.00		
GNC-420W	011-01058-40	\$330.00	\$660.00		
GNC-420W	011-01058-50	\$330.00	\$660.00		
GNS-430	011-00280-00	N/A	N/A		No Longer Supported
GNS-430	011-00280-10	\$330.00	\$660.00		
GNS-430	011-00280-30	\$330.00	\$660.00		
GNS-430A	011-00836-00	\$330.00	\$660.00		
GNS-430A	011-00836-10	\$330.00	\$660.00		
GNS-430AW	011-01061-00	\$330.00	\$660.00		
GNS-430AW	011-01061-10	\$330.00	\$660.00		
GNS-430AW	011-01061-40	\$330.00	\$660.00		
GNS-430AW	011-01061-50	\$330.00	\$660.00		
GNS-430W	011-01060-00	\$330.00	\$660.00		
GNS-430W	011-01060-10	\$330.00	\$660.00		
GNS-430W	011-01060-40	\$330.00	\$660.00		
GNS-430W	011-01060-50	\$330.00	\$660.00		
GNS-530	011-00550-00	N/A	N/A		No Longer Supported
GNS-530	011-00550-10	\$330.00	\$1,000.00		
GNS-530	011-00550-30	\$330.00	\$880.00		
GNS-530	011-00940-00	\$330.00	\$880.00		
GNS-530	011-00940-10	\$330.00	\$880.00		
GNS-530	011-00940-31	\$0.00	\$880.00		
GNS-530	011-00940-01	\$330.00	\$880.00		
GNS-530	011-00940-11	\$330.00	\$880.00		
GNS-530A	011-00835-00	\$330.00	\$880.00		
GNS-530A	011-00835-10	\$330.00	\$880.00		
GNS-530A	011-00864-00	\$330.00	\$880.00		
GNS-530A	011-00864-10	\$330.00	\$880.00		
GNS-530A	011-00864-01	\$330.00	\$880.00		
GNS-530A	011-00864-11	\$330.00	\$880.00		
GNS-530AW	011-01066-00	\$330.00	\$880.00		
GNS-530AW	011-01066-10	\$330.00	\$880.00		
GNS-530AW	011-01066-40	\$330.00	\$880.00		
GNS-530AW	011-01066-50	\$330.00	\$880.00		
GNS-530AW	011-01067-00	\$330.00	\$880.00		
GNS-530AW	011-01067-10	\$330.00	\$880.00		

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
GNS-530AW	011-01067-40	\$330.00	\$880.00		
GNS-530AW	011-01067-50	\$330.00	\$880.00		
GNS-530W	011-01064-00	\$330.00	\$880.00		
GNS-530W	011-01065-00	\$330.00	\$880.00		
GNS-530W	011-01065-10	\$330.00	\$880.00		
GNS-530W	011-01065-40	\$330.00	\$880.00		
GNS-530W	011-01065-45	\$330.00	\$880.00		
GNS-530W	011-01065-50	\$330.00	\$880.00		
GPS-150	011-00054-00	\$0.00	\$450.00		
GPS-150XL	011-00345-00	\$220.00	\$400.00		
GPS-155XL	011-00412-00	\$220.00	\$400.00		
GPS-165	011-00106-00	\$220.00	\$615.00		
GPS-165	011-00106-01	\$220.00	\$615.00		
GPS-400	011-00504-10	\$220.00	\$660.00		
GPS-400	011-00504-00	\$330.00	\$660.00		
GPS-400W	011-01057-00	\$330.00	\$660.00		
GPS-400W	011-01057-10	\$330.00	\$660.00		
GPS-400W	011-01057-40	\$330.00	\$660.00		
GPS-400W	011-01057-50	\$330.00	\$660.00		
GPS-500W	011-01062-00	\$330.00	\$880.00		
GPS-500W	011-01062-10	\$330.00	\$880.00		
GPS-500W	011-01062-40	\$330.00	\$880.00		
GPS-500W	011-01062-50	\$330.00	\$880.00		
GPS-500W	011-01063-00	\$330.00	\$880.00		
GPS-500W	011-01063-10	\$330.00	\$880.00		
GPS-500W	011-01063-40	\$330.00	\$880.00		
GPS-500W	011-01063-50	\$330.00	\$880.00		
GTX-320	011-00259-00	N/A	N/A	N/A	No Longer Supported
GTX-320	011-00259-10	\$220.00	N/A	\$0.00	
GTX-320A	010-00247-00	\$220.00	\$500.00	\$0.00	
GTX-320A	010-00247-02	\$220.00	\$500.00	\$0.00	
GTX-327	011-00490-00	\$220.00	\$575.00	\$0.00	
GTX-330	011-00455-00	\$220.00	\$745.00	\$0.00	
GTX-330	011-00455-20	\$220.00	\$745.00	\$0.00	
GTX-330D	011-00455-10	\$220.00	\$745.00	\$0.00	
GTX-330D	011-00455-30	\$220.00	\$745.00	\$0.00	
Gyro Can	060-0016-00	\$220.00	\$650.00	\$650.00	
IN-1102A	4000964-0201	\$0.00	\$600.00	N/A	SVC Only
IN-1202A	4000503-0201	\$220.00	\$600.00	N/A	SVC Only
IN-1202A	4000503-0202	\$220.00	\$600.00	N/A	SVC Only

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
IN-1202A	4000503-0203	\$220.00	\$600.00	N/A	SVC Only
IN-1202A	4000503-0204	\$220.00	\$600.00	N/A	SVC Only
IN-1202A	4000503-0205	\$220.00	\$600.00	N/A	SVC Only
IN-1202A	4000503-0241	\$220.00	\$600.00	N/A	SVC Only
IN-1202A	4000503-0242	\$220.00	\$600.00	N/A	SVC Only
IN-1202A	4000503-0251	\$220.00	\$600.00	N/A	SVC Only
IN-1202A	4000503-0252	\$220.00	\$600.00	N/A	SVC Only
IN-1202A	4000503-0253	\$220.00	\$600.00	N/A	SVC Only
IN-1202B	4001098-0201	\$220.00	\$600.00	N/A	SVC Only
IN-1202B	4001098-0202	\$220.00	\$600.00	N/A	SVC Only
IN-1202B	4001098-0203	\$220.00	\$600.00	N/A	SVC Only
IN-1202B	4001098-0204	\$220.00	\$600.00	N/A	SVC Only
IN-1202B	4001098-0205	\$220.00	\$600.00	N/A	SVC Only
IN-1302A	4000965-0201	\$220.00	\$600.00	N/A	SVC Only
IN-1302A	4000965-0202	\$220.00	\$600.00	N/A	SVC Only
IN-1302A	4000965-0203	\$220.00	\$600.00	N/A	SVC Only
IN-1302A	4000965-0204	\$220.00	\$600.00	N/A	SVC Only
IN-1302A	4000965-0205	\$220.00	\$600.00	N/A	SVC Only
IN-1302A	4000965-0206	\$220.00	\$600.00	N/A	SVC Only
IN-1302A	4000965-0207	\$220.00	\$600.00	N/A	SVC Only
IN-1302A	4000965-0252	\$220.00	\$600.00	N/A	SVC Only
IN-132A	4000764-3201	\$220.00	\$600.00	N/A	SVC Only
IN-1402A	4000833-0201	\$220.00	\$650.00	\$1,100.00	Overhaul subject to availability of parts
IN-1402B	4000833-0207	\$220.00	\$650.00	\$1,100.00	Overhaul subject to availability of parts
IN-1402B	4000833-0208	\$220.00	\$650.00	\$1,100.00	Overhaul subject to availability of parts
IN-1402B	4000833-0209	\$220.00	\$650.00	\$1,100.00	Overhaul subject to availability of parts
IN-1402B	4000833-0210	\$220.00	\$650.00	\$1,100.00	Overhaul subject to availability of parts
IN-1402B	4000833-0211	\$220.00	\$650.00	\$1,100.00	Overhaul subject to availability of parts
IN-1402B	4000833-0212	\$220.00	\$650.00	\$1,100.00	Overhaul subject to availability of parts
IN-152A	4000946-5201	\$220.00	\$770.00	N/A	
IN-152A	4000946-5202	\$220.00	\$660.00	N/A	
IN-152A	4000946-5211	\$220.00	\$660.00	N/A	
IN-182A	066-3084-00	\$220.00	\$660.00	\$900.00	
IN-182A	066-3084-01	\$220.00	\$660.00	\$900.00	
IN-182A	066-3084-02	\$220.00	\$660.00	\$900.00	
IN-182A	066-3084-03	\$220.00	\$660.00	\$900.00	
IN-182A	066-3084-30	\$220.00	\$660.00	\$900.00	
IN-182A	066-3084-32	\$220.00	\$660.00	\$900.00	
IN-182A	066-3084-33	\$220.00	\$660.00	\$900.00	
IN-182A	3614078-8201	\$220.00	\$660.00	\$900.00	



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
IN-182A	3614078-8202	\$220.00	\$660.00	\$900.00	
IN-2021A	4001291-2101	\$220.00	\$660.00	\$1,100.00	
IN-2021A	4001291-2102	\$220.00	\$660.00	\$1,100.00	
IN-2021A	4001291-2103	\$220.00	\$660.00	\$1,100.00	
IN-2021A	4001291-2104	\$220.00	\$660.00	\$1,100.00	
IN-2022A	4001373-2201	\$220.00	\$660.00	\$1,100.00	
IN-2022A	4001373-2202	\$220.00	\$660.00	\$1,100.00	
IN-2022A	4001373-2203	\$220.00	\$660.00	\$1,100.00	
IN-2022A	4001373-2204	\$220.00	\$660.00	\$1,100.00	
IN-2022A	4001373-2205	\$220.00	\$660.00	\$1,100.00	
IN-2022A	4001373-2206	\$220.00	\$660.00	\$1,100.00	
IN-2022A	4001373-2207	\$220.00	\$660.00	\$1,100.00	
IN-2022A	4001373-2208	\$220.00	\$660.00	\$1,100.00	
IN-2025A	4001670-2501	\$220.00	\$660.00	\$1,210.00	
IN-2025A	4001670-2502	\$220.00	\$880.00	\$1,320.00	
IN-2025A	4001670-2503	\$220.00	\$880.00	\$1,320.00	
IN-2025A	4001670-2504	\$220.00	\$880.00	\$1,320.00	
IN-2025B	4001670-2511	\$220.00	\$880.00	\$1,320.00	Add 7000.00 if faceplate is bad
IN-2025B	4001670-2512	\$220.00	\$880.00	\$1,320.00	Add 7000.00 if faceplate is bad
IN-2025B	4001670-2513	\$220.00	\$880.00	\$1,320.00	Add 7000.00 if faceplate is bad
IN-2025B	4001670-2514	\$220.00	\$880.00	\$1,320.00	Add 7000.00 if faceplate is bad
IN-2026A	4001294-2601	\$220.00	\$600.00	\$950.00	Overhaul subject to availability of parts
IN-2026A	4001294-2602	\$220.00	\$600.00	\$950.00	Overhaul subject to availability of parts
IN-2026A	4001294-2603	\$220.00	\$600.00	\$950.00	Overhaul subject to availability of parts
IN-2026A	4001294-2604	\$220.00	\$600.00	\$950.00	Overhaul subject to availability of parts
IN-2026A	4001294-2605	\$220.00	\$600.00	\$950.00	Overhaul subject to availability of parts
IN-2027A	4001295-2701	\$220.00	\$600.00	\$950.00	Overhaul subject to availability of parts
IN-2027A	4001295-2702	\$220.00	\$600.00	\$950.00	Overhaul subject to availability of parts
IN-2027A	4001295-2703	\$220.00	\$600.00	\$950.00	Overhaul subject to availability of parts
IN-2027A	4001295-2704	\$220.00	\$600.00	\$950.00	Overhaul subject to availability of parts
IN-2027A	4001295-2705	\$220.00	\$600.00	\$950.00	Overhaul subject to availability of parts
IN-2027A	4001295-2706	\$220.00	\$600.00	\$950.00	Overhaul subject to availability of parts
IN-2027A	4001295-2707	\$220.00	\$600.00	\$950.00	Overhaul subject to availability of parts
IN-2027A	4001295-2708	\$220.00	\$600.00	\$950.00	Overhaul subject to availability of parts
IN-232A	4001846-3202	\$220.00	\$660.00	\$950.00	Overhaul subject to availability of parts
IN-232A	4001846-3203	\$220.00	\$660.00	\$950.00	Overhaul subject to availability of parts
IN-232A	4001846-3204	\$220.00	\$660.00	\$950.00	Overhaul subject to availability of parts
IN-232A	4001846-3205	\$220.00	\$660.00	\$950.00	Overhaul subject to availability of parts
IN-232A	4001846-3201	\$220.00	\$660.00	\$950.00	Overhaul subject to availability of parts
IN-812A	066-3114-00	\$220.00	\$880.00	\$900.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
IN-812A	066-3114-01	\$220.00	\$660.00	\$900.00	
IN-812A	8095537-8101	\$220.00	\$660.00	\$900.00	
IN-812A	8095537-8102	\$220.00	\$660.00	\$900.00	
IN-842A	066-3085-00	\$220.00	\$660.00	\$900.00	
IN-842A	066-3085-10	\$220.00	\$660.00	\$900.00	
IN-842A	066-3085-11	\$220.00	\$660.00	\$900.00	
IN-842A	066-3085-30	\$220.00	\$660.00	\$900.00	
IN-842A	066-3085-31	\$220.00	\$660.00	\$900.00	
IN-862A	3614477-8601	\$220.00	\$660.00	\$900.00	
IN-862A	3614477-8602	\$220.00	\$660.00	\$900.00	
IN-862A	3614477-8611	\$220.00	\$660.00	\$900.00	
IN-862A	3614477-8612	\$220.00	\$660.00	\$900.00	
IN-862A	066-3086-00	\$220.00	\$660.00	\$900.00	
IN-862A	066-3086-01	\$220.00	\$660.00	\$900.00	
IN-862A	066-3086-10	\$220.00	\$660.00	\$900.00	
IN-862A	066-3086-11	\$220.00	\$660.00	\$900.00	
IN-862A	066-3086-30	\$220.00	\$660.00	\$900.00	
IN-862A	066-3086-31	\$220.00	\$660.00	\$900.00	
IND-200A	622-4023-001	\$220.00	\$500.00	\$950.00	
IND-200A	622-4023-002	\$220.00	\$500.00	\$950.00	
IND-220	622-5940-001	\$220.00	\$600.00	\$950.00	
IND-220	622-5940-008	\$220.00	\$600.00	\$950.00	
IND-270	622-5941-001	\$220.00	\$600.00	\$950.00	
IND-270	622-5941-008	\$220.00	\$600.00	\$950.00	
IND-270A	822-0416-001	\$220.00	\$600.00	\$950.00	
IND-300	622-4331-001	\$220.00	\$600.00	\$950.00	
IND-300	622-4331-002	\$440.00	\$600.00	\$950.00	
IND-300	622-4331-003	\$440.00	\$600.00	\$950.00	
IND-31C	622-4483-001	\$440.00	\$880.00	\$550.00	
IND-31C	622-4483-002	\$220.00	\$330.00	\$550.00	
IND-31C	622-4483-003	\$220.00	\$330.00	\$550.00	
IND-351	622-4478-001	\$220.00	\$330.00	\$550.00	
IND-40	622-3915-001	\$220.00	\$330.00	\$0.00	
IND-40	622-3915-002	\$220.00	\$330.00	\$550.00	
IND-40A	622-3916-001	\$220.00	\$330.00	\$550.00	
IND-40A	622-3916-002	\$220.00	\$330.00	\$550.00	
IND-40B	622-3917-001	\$220.00	\$330.00	\$550.00	
IND-40B	622-3917-002	\$220.00	\$330.00	\$550.00	
IND-40B	622-3917-501	\$220.00	\$330.00	\$550.00	
IND-40C	622-3881-001	\$220.00	\$330.00	\$550.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace
Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
IND-40C	622-3881-002	\$220.00	\$330.00	\$550.00	
IND-41	622-3918-001	\$220.00	\$330.00	\$550.00	
IND-41	622-3918-002	\$220.00	\$330.00	\$550.00	
IND-41A	622-3919-001	\$220.00	\$330.00	\$550.00	
IND-41A	622-3919-002	\$220.00	\$330.00	\$550.00	
IND-41B	622-3920-001	\$220.00	\$330.00	\$550.00	
IND-41B	622-3920-002	\$220.00	\$330.00	\$550.00	
IND-41C	622-3921-001	\$220.00	\$330.00	\$550.00	
IND-41C	622-3921-002	\$220.00	\$330.00	\$550.00	
IND-42A	622-6524-001	\$220.00	\$330.00	\$550.00	
IND-42A	622-6524-002	\$220.00	\$550.00	\$770.00	
IND-42A	622-6524-003	\$220.00	\$550.00	\$770.00	
IND-42A	622-6524-004	\$220.00	\$550.00	\$770.00	
IND-42C	622-7318-001	\$220.00	\$550.00	\$770.00	
IND-42C	622-7318-002	\$220.00	\$550.00	\$770.00	
IND-42C	622-7318-003	\$220.00	\$550.00	\$770.00	
IND-42C	622-7318-004	\$220.00	\$550.00	\$770.00	
KA-118	071-1095-00	\$220.00	\$300.00	N/A	
KA-118	071-1095-01	\$220.00	\$300.00	N/A	
KA-120	066-1089-00	\$0.00	\$220.00	\$350.00	
KA-131	071-1114-00	\$110.00	\$300.00	N/A	
KA-131	071-1114-01	\$110.00	\$300.00	N/A	
KA-134	071-2009-00	\$0.00	\$0.00	N/A	
KA-134	071-2009-01	\$110.00	\$220.00	N/A	
KA-134	071-2009-02	\$110.00	\$220.00	N/A	
KA-134	071-2009-12	\$110.00	\$220.00	N/A	
KA-138	071-1251-00	\$110.00	\$220.00	N/A	
KA-158	071-0019-00	\$110.00	\$330.00	\$0.00	
KA-160	071-1269-00	\$110.00	\$440.00	\$550.00	
KA-160	071-1269-01	\$110.00	\$330.00	\$550.00	
KA-160	071-1269-02	\$110.00	\$330.00	\$550.00	
KA-162	071-1270-01	\$110.00	\$330.00	\$550.00	
KA-162	071-1270-02	\$110.00	\$330.00	\$550.00	
KA-25	071-2008-00	\$110.00	\$550.00	N/A	
KA-285	065-0032-00	\$220.00	\$300.00	N/A	
KA-285	065-0032-01	\$220.00	\$300.00	N/A	
KA-35A	066-3012-00	\$0.00	\$0.00	N/A	SVC ONLY
KA-35A	066-3012-01	\$110.00	\$220.00	N/A	SVC ONLY
KA-39	071-1041-00	\$110.00	\$220.00	N/A	
KA-39	071-1041-01	\$110.00	\$220.00	N/A	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KA-40	071-0003-00	\$110.00	\$220.00	N/A	
KA-42B	071-1133-00	\$110.00	\$220.00	N/A	SVC ONLY
KA-44	071-1196-00	\$110.00	\$220.00	N/A	SVC ONLY
KA-44B	071-1234-00	\$110.00	\$220.00	N/A	SVC ONLY
KA-44B	071-1234-01	\$110.00	\$220.00	N/A	SVC ONLY
KA-44B	071-1234-02	\$110.00	\$220.00	N/A	SVC ONLY
KA-51B	071-1242-00	\$110.00	\$300.00	\$400.00	
KA-51B	071-1242-01	\$110.00	\$300.00	\$400.00	
KA-51B	071-1242-02	\$110.00	\$300.00	\$400.00	
KA-51B	071-1242-03	\$110.00	\$300.00	\$400.00	
KA-51B	071-1242-04	\$110.00	\$300.00	\$400.00	
KA-51B	071-1242-05	\$110.00	\$300.00	\$400.00	
KA-51B	071-1242-06	\$110.00	\$300.00	\$400.00	
KA-51B	071-1242-07	\$110.00	\$300.00	\$400.00	
KA-51B	071-1242-08	\$110.00	\$300.00	\$400.00	
KA-51B	071-1242-09	\$110.00	\$300.00	\$400.00	
KA-51B	071-1242-11	\$110.00	\$300.00	\$400.00	
KA-51B	071-1242-12	\$110.00	\$300.00	\$400.00	
KA-52	071-1055-00	\$220.00	\$440.00	\$550.00	
KA-54	071-1059-00	\$220.00	\$440.00	\$550.00	
KA-54A	071-01501-0000	\$220.00	N/A	N/A	Includes Testing & Certification
KA-54A	071-01501-0100	\$220.00	N/A	N/A	Includes Testing & Certification
KA-57	071-0017-00	\$220.00	\$220.00	\$330.00	
KA-594	071-1268-00	\$220.00	\$440.00	\$850.00	
KA-594	071-1268-01	\$220.00	\$440.00	\$850.00	
KA-92	071-01553-0200	\$110.00	\$440.00	N/A	SVC ONLY
KAC-952	064-1017-01	\$330.00	\$750.00	\$950.00	
KAC-952	064-1017-02	\$330.00	\$660.00	\$1,210.00	
KAC-952	064-1017-00	\$330.00	\$880.00	\$1,500.00	
KAC-992	064-1029-00	\$330.00	\$660.00	\$1,800.00	Overhaul subject to availability of parts
KAC-992	064-1029-01	\$330.00	\$660.00	\$1,800.00	Overhaul subject to availability of parts
KAC-992	064-1029-10	\$330.00	\$660.00	\$1,210.00	Overhaul subject to availability of parts
KAS-297	065-0046-00	\$220.00	\$660.00	\$1,210.00	
KAS-297	065-0046-02	\$220.00	\$770.00	\$880.00	
KAS-297A	065-0053-00	\$220.00	\$770.00	\$880.00	
KAS-297A	065-0053-01	\$220.00	\$770.00	\$880.00	
KAS-297A	065-0053-02	\$220.00	\$770.00	\$880.00	
KAS-297A	065-0053-03	\$220.00	\$770.00	\$880.00	
KAS-297A	065-0053-04	\$220.00	\$770.00	\$880.00	
KAS-297A	065-0053-05	\$220.00	\$770.00	\$880.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KAS-297A	065-0053-06	\$220.00	\$770.00	\$880.00	
KAS-297A	065-0053-07	\$220.00	\$770.00	\$880.00	
KAS-297A	065-0053-08	\$220.00	\$770.00	\$880.00	
KAS-297A	065-0053-09	\$220.00	\$770.00	\$880.00	
KC-290	065-0033-00	\$220.00	\$300.00	N/A	
KC-290	065-0033-01	\$220.00	\$300.00	N/A	
KC-291	065-0035-01	\$220.00	\$300.00	N/A	
KC-295	065-0034-00	\$330.00	\$650.00	N/A	
KC-295	065-0034-01	\$330.00	\$650.00	N/A	
KC-295	065-0034-03	\$330.00	\$650.00	N/A	
KC-295	065-0034-04	\$330.00	\$650.00	N/A	
KC-295	065-0034-05	\$330.00	\$650.00	N/A	
KC-295	065-0034-06	\$330.00	\$650.00	N/A	
KC-295	065-0034-07	\$330.00	\$650.00	N/A	
KC-295	065-0034-08	\$330.00	\$650.00	N/A	
KC-295	065-0034-09	\$330.00	\$650.00	N/A	
KC-295	065-0034-10	\$330.00	\$650.00	N/A	
KC-295	065-0034-11	\$330.00	\$650.00	N/A	
KC-295	065-0034-12	\$330.00	\$650.00	N/A	
KC-295	065-0034-13	\$330.00	\$650.00	N/A	
KC-295	065-0034-14	\$330.00	\$650.00	N/A	
KC-295	065-0034-15	\$330.00	\$650.00	N/A	
KC-295	065-0034-16	\$330.00	\$650.00	N/A	
KC-295	065-0034-17	\$330.00	\$650.00	N/A	
KC-295 Adapter	065-5009-02	\$220.00			
KC-295 Adapter	065-5009-03	\$220.00			
KC-295 Adapter	065-5009-04	\$220.00			
KC-295 Adapter	065-5009-06	\$220.00			
KC-295 Adapter	065-5009-07	\$220.00			
KC-295 Adapter	065-5009-08	\$220.00			
KC-295 Adapter	065-5009-09	\$220.00			
KC-295 Adapter	065-5009-10	\$220.00			
KC-295 Adapter	065-5009-13	\$220.00			
KC-295 Adapter	065-5009-14	\$220.00			
KC-295 Adapter	065-5009-19	\$220.00			
KC-295 Adapter	065-5009-21	\$220.00			
KC-295 Adapter	065-5009-22	\$220.00			
KC-295 Adapter	065-5009-23	\$220.00			
KC-295 Adapter	065-5009-24	\$220.00			
KC-295 Adapter	065-5009-26	\$220.00			

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KC-295 Adapter	065-5009-27	\$220.00			
KC-295 Adapter	065-5009-30	\$220.00			
KC-295 Adapter	065-5009-32	\$220.00			
KC-295 Adapter	065-5009-34	\$220.00			
KC-295 Adapter	065-5009-35	\$220.00			
KC-295 Adapter	065-5009-36	\$220.00			
KC-295 Adapter	065-5009-39	\$220.00			
KC-295 Adapter	065-5009-40	\$220.00			
KC-295 Adapter	065-5009-44	\$220.00			
KC-295 Adapter	065-5009-45	\$220.00			
KC-295 Adapter	065-5009-46	\$220.00			
KC-295 Adapter	065-5009-48	\$220.00			
KC-295 Adapter	065-5009-50	\$220.00			
KC-295 Adapter	065-5009-51	\$220.00			
KC-295 Adapter	065-5009-52	\$220.00			
KC-295 Adapter	065-5009-53	\$220.00			
KC-295 Adapter	065-5009-54	\$220.00			
KC-295 Adapter	065-5009-55	\$220.00			
KC-295 Adapter	065-5009-56	\$220.00			
KC-295 Adapter	065-5009-57	\$220.00			
KC-295 Adapter	065-5009-58	\$220.00			
KC-295 Adapter	065-5009-60	\$220.00			
KC-295 Adapter	065-5009-61	\$220.00			
KC-295 Adapter	065-5009-63	\$220.00			
KC-295 Adapter	065-5009-67	\$220.00			
KC-295 Adapter	065-5009-68	\$220.00			
KC-295 Adapter	065-5009-69	\$220.00			
KC-295 Adapter	065-5009-70	\$220.00			
KC-295 Adapter	065-5009-71	\$220.00			
KC-295 Adapter	065-5009-72	\$220.00			
KC-295 Adapter	065-5009-74	\$220.00			
KC-295 Adapter	065-5009-75	\$220.00			
KC-295 Adapter	065-5009-77	\$220.00			
KC-295 Adapter	065-5009-78	\$220.00			
KC-295 Adapter	065-5009-80	\$220.00			
KC-295 Adapter	065-5009-81	\$220.00			
KC-295 Adapter	065-5009-82	\$220.00			
KC-295 Adapter	065-5009-84	\$220.00			
KC-295 Adapter	065-5009-85	\$220.00			
KC-295 Adapter	065-5009-86	\$220.00			

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KC-295 Adapter	065-5009-87	\$220.00			
KC-295 Adapter	065-5014-02	\$220.00			
KC-295 Adapter	065-5014-03	\$220.00			
KC-295 Adapter	065-5014-04	\$220.00			
KC-295 Adapter	065-5014-06	\$220.00			
KC-295 Adapter	065-5014-07	\$220.00			
KC-295 Adapter	065-5014-08	\$220.00			
KC-295 Adapter	065-5014-09	\$220.00			
KC-295 Adapter	065-5014-10	\$220.00			
KC-295 Adapter	065-5014-13	\$220.00			
KC-295 Adapter	065-5014-19	\$220.00			
KC-295 Adapter	065-5014-21	\$220.00			
KC-295 Adapter	065-5014-22	\$220.00			
KC-295 Adapter	065-5014-23	\$220.00			
KC-295 Adapter	065-5014-24	\$220.00			
KC-295 Adapter	065-5014-26	\$220.00			
KC-295 Adapter	065-5014-27	\$220.00			
KC-295 Adapter	065-5014-30	\$220.00			
KC-295 Adapter	065-5014-32	\$220.00			
KC-295 Adapter	065-5014-34	\$220.00			
KC-295 Adapter	065-5014-35	\$220.00			
KC-295 Adapter	065-5014-36	\$220.00			
KC-295 Adapter	065-5014-39	\$220.00			
KC-295 Adapter	065-5014-40	\$220.00			
KC-295 Adapter	065-5014-44	\$220.00			
KC-295 Adapter	065-5014-45	\$220.00			
KC-295 Adapter	065-5014-46	\$220.00			
KC-295 Adapter	065-5014-48	\$220.00			
KC-295 Adapter	065-5014-50	\$220.00			
KC-295 Adapter	065-5014-51	\$220.00			
KC-295 Adapter	065-5014-52	\$220.00			
KC-295 Adapter	065-5014-53	\$220.00			
KC-295 Adapter	065-5014-54	\$220.00			
KC-295 Adapter	065-5014-55	\$220.00			
KC-295 Adapter	065-5014-56	\$220.00			
KC-295 Adapter	065-5014-57	\$220.00			
KC-295 Adapter	065-5014-58	\$220.00			
KC-295 Adapter	065-5014-60	\$220.00			
KC-295 Adapter	065-5014-61	\$220.00			
KC-295 Adapter	065-5014-63	\$220.00			

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KC-295 Adapter	065-5014-67	\$220.00			
KC-295 Adapter	065-5014-68	\$220.00			
KC-295 Adapter	065-5014-69	\$220.00			
KC-295 Adapter	065-5014-70	\$220.00			
KC-295 Adapter	065-5014-71	\$220.00			
KC-295 Adapter	065-5014-72	\$220.00			
KC-295 Adapter	065-5014-74	\$220.00			
KC-295 Adapter	065-5014-75	\$220.00			
KC-295 Adapter	065-5014-78	\$220.00			
KC-295 Adapter	065-5014-80	\$220.00			
KC-295 Adapter	065-5014-81	\$220.00			
KC-295 Adapter	065-5014-82	\$220.00			
KC-295 Adapter	065-5014-83	\$220.00			
KC-295 Adapter	065-5014-84	\$220.00			
KC-295 Adapter	065-5014-85	\$220.00			
KC-295 Adapter	065-5014-86	\$220.00			
KC-295 Adapter	065-5014-87	\$220.00			
KC-296	065-0036-00	\$330.00	\$650.00	N/A	
KC-296	065-0036-01	\$330.00	\$650.00	N/A	
KC-296	065-0036-30	\$330.00	\$650.00	N/A	
KC-296	065-0036-31	\$330.00	\$650.00	N/A	
KCU-951	064-1016-00	\$330.00	\$700.00	\$850.00	
KCU-951	064-1016-01	\$330.00	\$700.00	\$850.00	
KCU-951	064-1016-02	\$220.00	\$550.00	\$880.00	
KCU-951	064-1016-03	\$220.00	\$550.00	\$880.00	
KCU-951	064-1016-04	\$220.00	\$550.00	\$880.00	
KCU-951	064-1016-10	\$220.00	\$550.00	\$880.00	
KCU-951	064-1016-11	\$220.00	\$550.00	\$880.00	
KCU-951	064-1016-12	\$220.00	\$550.00	\$880.00	
KCU-951	064-1016-13	\$220.00	\$550.00	\$880.00	
KCU-951	064-1016-14	\$220.00	\$550.00	\$880.00	
KDA-688	071-1232-00	\$220.00	\$350.00	\$550.00	
KDA-692	071-1217-00	\$220.00	\$550.00	\$660.00	Overhaul subject to age/condition
KDA-692	071-1217-01	\$220.00	\$550.00	\$660.00	Overhaul subject to age/condition
KDA-697	071-1076-00	\$220.00	\$550.00	\$660.00	Overhaul subject to age/condition
KDF-805	066-1047-00	\$220.00	\$550.00	N/A	SVC Only
KDF-805	066-1047-01	\$220.00	\$550.00	N/A	SVC Only
KDF-806	066-1077-00	\$220.00	\$770.00	\$650.00	
KDF-806	066-1077-01	\$220.00	\$550.00	\$650.00	
KDI-572	066-1069-00	\$220.00	\$450.00	\$600.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KDI-572	066-1069-01	\$220.00	\$450.00	\$600.00	
KDI-573	066-1069-02	\$220.00	\$450.00	\$600.00	
KDI-573	066-1069-03	\$220.00	\$450.00	\$600.00	
KDI-573	066-1069-09	\$220.00	\$450.00	\$600.00	
KDI-573	066-1069-10	\$220.00	\$450.00	\$600.00	
KDI-574	066-1069-04	\$220.00	\$450.00	\$600.00	
KDI-574	066-1069-05	\$220.00	\$450.00	\$600.00	
KDI-574	066-1069-11	\$220.00	\$450.00	\$600.00	
KDI-574	066-1069-13	\$220.00	\$450.00	\$600.00	
KDM-706	066-1066-00	\$220.00	\$475.00	\$600.00	
KDM-706	066-1066-01	\$220.00	\$475.00	\$600.00	
KDM-706	066-1066-02	\$220.00	\$475.00	\$600.00	
KDM-706	066-1066-41	\$220.00	\$475.00	\$600.00	
KDM-706A	066-1066-11	\$220.00	\$475.00	\$650.00	
KDM-706A	066-1066-20	\$220.00	\$475.00	\$650.00	
KDM-706A	066-1066-21	\$220.00	\$475.00	\$650.00	
KDM-706A	066-1066-22	\$220.00	\$475.00	\$650.00	
KDM-706A	066-1066-23	\$220.00	\$475.00	\$650.00	
KDM-706A	066-1066-24	\$220.00	\$475.00	\$650.00	
KDM-706A	066-1066-25	\$220.00	\$475.00	\$650.00	
KFS-560B	071-1054-02	\$220.00	\$350.00	N/A	
KFS-560B	071-1054-04	\$220.00	\$350.00	N/A	
KFS-560B	071-1054-05	\$220.00	\$350.00	N/A	
KFS-564	071-1216-12	\$220.00	\$450.00	\$600.00	
KFS-564	071-1216-13	\$220.00	\$450.00	\$600.00	
KFS-564	071-1216-15	\$220.00	\$450.00	\$600.00	
KFS-564	071-1216-16	\$220.00	\$450.00	\$600.00	
KFS-564	071-1216-17	\$220.00	\$450.00	\$600.00	
KFS-564	071-1216-18	\$220.00	\$450.00	\$600.00	
KFS-564	071-1216-20	\$220.00	\$450.00	\$600.00	
KFS-564	071-1216-21	\$220.00	\$450.00	\$600.00	
KFS-564	071-1216-22	\$220.00	\$450.00	\$600.00	
KFS-564	071-1216-23	\$220.00	\$450.00	\$600.00	
KFS-564	071-1216-25	\$220.00	\$450.00	\$600.00	
KFS-564	071-1216-26	\$220.00	\$450.00	\$600.00	
KFS-564	071-1216-27	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-12	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-13	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-15	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-16	\$220.00	\$450.00	\$600.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KFS-564A	071-1283-17	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-18	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-20	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-21	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-22	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-23	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-25	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-26	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-27	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-28	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-29	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-30	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-31	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-32	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-33	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-39	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-40	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-41	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-42	\$220.00	\$450.00	\$600.00	
KFS-564A	071-1283-43	\$220.00	\$450.00	\$600.00	
KFS-570B	071-1043-02	\$220.00	\$450.00	N/A	SVC Only
KFS-576	071-1192-00	\$220.00	\$450.00	\$600.00	
KFS-576	071-1192-01	\$220.00	\$450.00	\$600.00	
KFS-576	071-1192-02	\$220.00	\$450.00	\$600.00	
KFS-576	071-1192-03	\$220.00	\$450.00	\$600.00	
KFS-576	071-1192-04	\$220.00	\$450.00	\$600.00	
KFS-576	071-1192-05	\$220.00	\$450.00	\$600.00	
KFS-576	071-1192-06	\$220.00	\$450.00	\$600.00	
KFS-576	071-1192-07	\$220.00	\$450.00	\$600.00	
KFS-576	071-1192-08	\$220.00	\$450.00	\$600.00	
KFS-576	071-1192-09	\$220.00	\$450.00	\$600.00	
KFS-576	071-1192-10	\$220.00	\$450.00	\$600.00	
KFS-576	071-1192-11	\$220.00	\$450.00	\$600.00	
KFS-576	071-1192-13	\$220.00	\$450.00	\$600.00	
KFS-576	071-1192-14	\$220.00	\$450.00	\$600.00	
KFS-576	071-1192-15	\$220.00	\$450.00	\$600.00	
KFS-576	071-1192-16	\$220.00	\$450.00	\$600.00	
KFS-576	071-1192-18	\$220.00	\$450.00	\$600.00	
KFS-576	071-1192-22	\$220.00	\$450.00	\$600.00	
KFS-576	071-1192-26	\$220.00	\$450.00	\$600.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KFS-576A	071-1276-08	\$220.00	\$450.00	\$600.00	
KFS-576A	071-1276-09	\$220.00	\$450.00	\$600.00	
KFS-576A	071-1276-10	\$220.00	\$450.00	\$600.00	
KFS-576A	071-1276-11	\$220.00	\$450.00	\$600.00	
KFS-576A	071-1276-13	\$220.00	\$450.00	\$600.00	
KFS-576A	071-1276-14	\$220.00	\$450.00	\$600.00	
KFS-576A	071-1276-15	\$220.00	\$450.00	\$600.00	
KFS-576A	071-1276-16	\$220.00	\$450.00	\$600.00	
KFS-576A	071-1276-18	\$220.00	\$450.00	\$600.00	
KFS-576A	071-1276-19	\$220.00	\$450.00	\$600.00	
KFS-576A	071-1276-20	\$220.00	\$450.00	\$600.00	
KFS-576A	071-1276-21	\$220.00	\$450.00	\$600.00	
KFS-576A	071-1276-22	\$220.00	\$450.00	\$600.00	
KFS-576A	071-1276-23	\$220.00	\$450.00	\$600.00	
KFS-576A	071-1276-24	\$220.00	\$450.00	\$600.00	
KFS-576A	071-1276-25	\$220.00	\$450.00	\$600.00	
KFS-576A	071-1276-26	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-0901	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-1001	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-1101	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-1201	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-1301	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-1401	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-1501	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-1601	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-1701	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-1801	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-1901	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-2001	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-2201	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-2301	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-2501	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-2901	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-3201	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-3303	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-3403	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-3502	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-3503	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-3603	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-4102	\$220.00	\$450.00	\$600.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KFS-578A	071-01507-4202	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-4302	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-4304	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-4402	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-4404	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-4902	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-4903	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-5002	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-5003	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-5102	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-5103	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-5202	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-5203	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-5503	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-6503	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-6603	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-6703	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-6803	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-7504	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-7604	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-8103	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-8203	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-8303	\$220.00	\$450.00	\$600.00	
KFS-578A	071-01507-8403	\$220.00	\$450.00	\$600.00	
KFS-580B	071-1066-00	\$220.00	\$300.00	N/A	
KFS-586	071-1210-04	\$220.00	\$450.00	\$600.00	
KFS-586	071-1210-05	\$220.00	\$450.00	\$600.00	
KFS-586	071-1210-06	\$220.00	\$450.00	\$600.00	
KFS-586	071-1210-07	\$220.00	\$450.00	\$600.00	
KFS-586	071-1210-08	\$220.00	\$450.00	\$600.00	
KFS-586	071-1210-09	\$220.00	\$450.00	\$600.00	
KFS-586	071-1210-10	\$220.00	\$450.00	\$600.00	
KFS-586	071-1210-11	\$220.00	\$450.00	\$600.00	
KFS-586	071-1210-12	\$220.00	\$450.00	\$600.00	
KFS-586	071-1210-13	\$220.00	\$450.00	\$600.00	
KFS-586	071-1210-14	\$220.00	\$450.00	\$600.00	
KFS-586	071-1210-15	\$220.00	\$450.00	\$600.00	
KFS-586	071-1210-16	\$220.00	\$450.00	\$600.00	
KFS-586	071-1210-17	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-04	\$220.00	\$450.00	\$600.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KFS-586A	071-1284-05	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-06	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-07	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-08	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-09	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-10	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-11	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-12	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-13	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-14	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-15	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-16	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-17	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-18	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-19	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-20	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-21	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-22	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-23	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-24	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-29	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-30	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-31	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-32	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-33	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-34	\$220.00	\$450.00	\$600.00	
KFS-586A	071-1284-35	\$220.00	\$450.00	\$600.00	
KFS-590A	071-1012-09	\$220.00	\$350.00	N/A	
KFS-590A	071-1012-10	\$220.00	\$350.00	N/A	
KFS-590A	071-1012-11	\$220.00	\$350.00	N/A	
KFS-590B	071-1012-12	\$220.00	\$350.00	N/A	
KFS-590B	071-1012-13	\$220.00	\$350.00	N/A	
KFS-590B	071-1012-14	\$220.00	\$350.00	N/A	
KFS-590B	071-1012-15	\$220.00	\$350.00	N/A	
KFS-590B	071-1012-17	\$220.00	\$350.00	N/A	
KFS-594	071-1274-00	\$220.00	\$450.00	\$600.00	Not repairable
KFS-594	071-1274-01	\$220.00	\$450.00	\$600.00	
KFS-594	071-1274-02	\$220.00	\$450.00	\$600.00	
KFS-594	071-1274-03	\$220.00	\$450.00	\$600.00	
KFS-594	071-1274-04	\$220.00	\$450.00	\$600.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KFS-598	071-1215-00	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-24	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-24	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-25	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-25	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-26	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-26	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-27	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-27	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-28	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-29	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-29	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-30	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-31	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-32	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-33	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-34	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-35	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-36	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-37	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-38	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-39	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-40	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-41	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-42	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-43	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-44	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-45	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-54	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-55	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-56	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-57	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-59	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-60	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-61	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-62	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-64	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-65	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-66	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-67	\$220.00	\$450.00	\$600.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KFS-598	071-1215-70	\$220.00	\$450.00	\$600.00	
KFS-598	071-1215-71	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-24	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-25	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-26	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-27	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-29	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-30	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-31	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-32	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-34	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-35	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-36	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-37	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-38	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-39	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-40	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-41	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-42	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-43	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-44	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-45	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-46	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-47	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-48	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-49	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-50	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-51	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-52	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-53	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-54	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-55	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-56	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-64	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-65	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-66	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-67	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-69	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-70	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-71	\$220.00	\$450.00	\$600.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KFS-598A	071-1282-72	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-74	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-75	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-76	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-77	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-80	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-81	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-86	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-87	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-88	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-89	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-90	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-91	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-92	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-93	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-94	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-95	\$220.00	\$450.00	\$600.00	
KFS-598A	071-1282-96	\$220.00	\$450.00	\$600.00	
KFS-599A	071-01539-0101	\$220.00	\$450.00	\$600.00	
KFS-599A	071-01546-0202	\$220.00	\$450.00	\$600.00	
KFS-599A	071-01546-0401	\$220.00	\$450.00	\$600.00	
KG-102A	060-0015-00	\$330.00	\$750.00	\$1,300.00	Overhaul subject to can w/ Mod 1
KG-102A	065-0015-01	\$330.00	\$750.00	\$1,300.00	
KG-102A	065-0015-02	\$330.00	\$750.00	\$1,300.00	Overhaul subject to can w/ Mod 1
KG-258	060-0020-01	\$440.00	\$950.00	\$1,350.00	
KG-258	060-0020-02	\$440.00	\$950.00	\$1,350.00	
KG-258	060-0020-03	\$440.00	\$950.00	\$1,350.00	
KG-258	060-0020-04	\$440.00	\$950.00	\$1,350.00	
KG-258	060-0020-07	\$440.00	\$950.00	\$1,350.00	
KG-258	060-0020-08	\$440.00	\$950.00	\$1,350.00	
KG-258	060-0020-09	\$440.00	\$950.00	\$1,350.00	
KGM-691	066-1035-00	\$0.00	\$450.00	N/A	
KGM-691	066-1035-01	\$220.00	\$450.00	N/A	
KGM-691	066-1035-02	\$220.00	\$450.00	N/A	
KGS-681	066-1036-00	\$220.00	\$450.00	N/A	
KI-202	066-3034-07	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-202	066-3034-08	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-202	066-3034-09	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-202	066-3034-11	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-203	066-3034-00	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KI-203	066-3034-01	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-204	066-3034-02	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-204	066-3034-03	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-204	066-3034-18	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-204	066-3034-19	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-204	066-3034-20	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-204	066-3034-21	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-204	066-3034-22	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-204	066-3034-23	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-206	066-3034-04	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-206	066-3034-05	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-206	066-3034-10	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-206	066-3034-12	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-206	066-3034-13	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-206	066-3034-14	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-206	066-3034-15	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-206	066-3034-16	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-206	066-3034-24	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-207	066-3034-06	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-207	066-3034-17	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-207	066-3034-25	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-208	066-3056-00	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-208	066-3056-02	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-208A	066-3056-10	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-209	066-3056-01	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-209	066-3056-03	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-209A	066-3056-11	\$220.00	\$300.00	\$450.00	Overhaul subject to age/condition
KI-227	066-3063-00	\$220.00	\$550.00	\$880.00	
KI-227	066-3063-01	\$220.00	\$330.00	\$440.00	
KI-228	066-3059-00	\$220.00	\$330.00	\$440.00	
KI-228	066-3059-01	\$220.00	\$330.00	\$440.00	
KI-229	066-3038-00	\$220.00	\$330.00	\$750.00	
KI-229	066-3038-01	\$220.00	\$550.00	\$750.00	
KI-250	066-3054-00	\$220.00	\$450.00	\$650.00	Overhaul subject to age/condition
KI-250	066-3054-01	\$220.00	\$450.00	\$650.00	Overhaul subject to age/condition
KI-250	066-3054-02	\$220.00	\$450.00	\$650.00	Overhaul subject to age/condition
KI-250	066-3054-03	\$220.00	\$450.00	\$650.00	Overhaul subject to age/condition
KI-250	066-3054-04	\$220.00	\$450.00	\$650.00	Overhaul subject to age/condition
KI-250	066-3054-05	\$220.00	\$450.00	\$650.00	Overhaul subject to age/condition
KI-256	060-0017-00	\$440.00	\$1,150.00	\$1,450.00	Overhaul subject to mod status

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KI-256	060-0017-01	\$440.00	\$1,150.00	\$1,450.00	Overhaul subject to mod status
KI-525A	066-3046-00	\$220.00	\$0.00	\$0.00	Overhaul subject to age/condition
KI-525A	066-3046-01	\$220.00	\$550.00	\$770.00	Overhaul subject to age/condition
KI-525A	066-3046-02	\$220.00	\$550.00	\$770.00	Overhaul subject to age/condition
KI-525A	066-3046-03	\$220.00	\$550.00	\$770.00	Overhaul subject to age/condition
KI-525A	066-3046-04	\$220.00	\$550.00	\$770.00	
KI-525A	066-3046-05	\$220.00	\$550.00	\$770.00	
KI-525A	066-3046-06	\$220.00	\$550.00	\$770.00	
KI-525A	066-3046-07	\$220.00	\$550.00	\$770.00	
KI-525A	066-3046-08	\$220.00	\$550.00	\$770.00	
KI-525A	066-3046-09	\$220.00	\$550.00	\$770.00	
KI-525A	066-3046-10	\$220.00	\$550.00	\$770.00	
KI-525A	066-3046-11	\$220.00	\$550.00	\$770.00	
KI-525A	066-3046-12	\$220.00	\$550.00	\$770.00	
KI-525A	066-3046-13	\$220.00	\$550.00	\$770.00	
KLN-35A	066-01151-0101	\$220.00	\$550.00	\$770.00	
KLN-35A	066-01151-0102	\$220.00	\$440.00	\$660.00	
KLN-35A	066-01151-0103	\$220.00	\$440.00	\$660.00	
KLN-89B	066-01148-0101	\$220.00	\$440.00	\$650.00	Overhaul does not include display
KLN-89B	066-01148-0102	\$220.00	\$550.00	\$650.00	Overhaul does not include display
KLN-90	066-04031-0101	\$220.00	\$550.00	\$750.00	
KLN-90	066-04031-0201	\$220.00	\$550.00	\$750.00	
KLN-900	066-04034-0101	\$220.00	\$575.00	\$700.00	
KLN-900	066-04034-0102	\$220.00	\$575.00	\$700.00	
KLN-900	066-04034-0104	\$220.00	\$575.00	\$700.00	
KLN-900	066-04034-0201	\$220.00	\$575.00	\$700.00	
KLN-900	066-04034-0202	\$220.00	\$575.00	\$700.00	
KLN-900	066-04034-0204	\$220.00	\$575.00	\$700.00	
KLN-90A	066-04031-0111	\$220.00	\$550.00	\$650.00	
KLN-90A	066-04031-0311	\$220.00	\$550.00	\$650.00	
KLN-90A	066-04031-0411	\$220.00	\$550.00	\$650.00	
KLN-90B	066-04031-1121	\$220.00	\$550.00	\$650.00	
KLN-90B	066-04031-1122	\$220.00	\$550.00	\$650.00	
KLN-90B	066-04031-1221	\$220.00	\$550.00	\$650.00	
KLN-90B	066-04031-1321	\$220.00	\$550.00	\$650.00	
KLN-90B	066-04031-1322	\$220.00	\$550.00	\$650.00	
KLN-90B	066-04031-1421	\$220.00	\$550.00	\$650.00	
KLN-90B	066-04031-1422	\$220.00	\$550.00	\$650.00	
KLN-90B	066-04031-1622	\$220.00	\$550.00	\$650.00	
KLN-90B	066-04031-2121	\$220.00	\$550.00	\$650.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KLN-90B	066-04031-2122	\$220.00	\$550.00	\$650.00	
KLN-90B	066-04031-2221	\$220.00	\$550.00	\$650.00	
KLN-90B	066-04031-2222	\$220.00	\$550.00	\$650.00	
KLN-90B	066-04031-2321	\$220.00	\$550.00	\$650.00	
KLN-90B	066-04031-2322	\$220.00	\$550.00	\$650.00	
KLN-90B	066-04031-2421	\$220.00	\$550.00	\$650.00	
KLN-90B	066-04031-2422	\$220.00	\$550.00	\$650.00	
KLN-94	069-01034-0101	\$220.00	\$550.00	\$650.00	
KLN-94	069-01034-0102	\$220.00	\$550.00	\$650.00	
KLX-135A	069-01029-0701	\$220.00	\$550.00	\$650.00	
KLX-135A	069-01029-0702	\$220.00	\$550.00	\$650.00	
KLX-135A	069-01029-0703	\$220.00	\$550.00	\$650.00	
KLX-135A	070-01029-0010	\$220.00	\$550.00	\$650.00	
KLX-135A	070-01029-0011	\$220.00	\$550.00	\$650.00	
KLX-135A	070-01029-0012	\$220.00	\$550.00	\$650.00	
KM-275	065-0030-00	\$330.00	\$350.00	N/A	
KM-275	065-0030-02	\$330.00	\$350.00	N/A	
KM-275	065-0030-20	\$330.00	\$350.00	N/A	
KM-275	065-0030-27	\$330.00	\$350.00	N/A	
KM-275	065-0030-35	\$330.00	\$350.00	N/A	
KM-275	065-0030-36	\$330.00	\$350.00	N/A	
KM-275	065-0030-43	\$330.00	\$350.00	N/A	
KM-275	065-0030-60	\$330.00	\$350.00	N/A	
KMA-20	066-1024-00	\$220.00	\$0.00	N/A	SVC Only
KMA-20	066-1024-03	\$220.00	\$440.00	N/A	SVC Only
KMA-20	066-1024-04	\$220.00	\$440.00	N/A	SVC Only
KMA-20	066-1024-05	\$220.00	\$440.00	N/A	SVC Only
KMA-20	066-1024-06	\$220.00	\$440.00	N/A	SVC Only
KMA-20	066-1024-07	\$220.00	\$440.00	N/A	SVC Only
KMA-20	066-1024-08	\$220.00	\$440.00	N/A	SVC Only
KMA-20	066-1024-09	\$220.00	\$440.00	N/A	SVC Only
KMA-20	066-1024-10	\$220.00	\$440.00	N/A	SVC Only
KMA-20	066-1024-11	\$220.00	\$440.00	N/A	SVC Only
KMA-20	066-1024-12	\$220.00	\$440.00	N/A	SVC Only
KMA-20	066-1024-13	\$220.00	\$440.00	N/A	SVC Only
KMA-20	066-1024-14	\$220.00	\$440.00	N/A	SVC Only
KMA-20	066-1024-15	\$220.00	\$440.00	N/A	SVC Only
KMA-20	066-1024-16	\$220.00	\$440.00	N/A	SVC Only
KMA-24	066-1055-00	\$220.00	\$350.00	\$450.00	
KMA-24	066-1055-01	\$220.00	\$350.00	\$450.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KMA-24	066-1055-02	\$220.00	\$350.00	\$450.00	
KMA-24	066-1055-03	\$220.00	\$350.00	\$450.00	
KMA-24H	066-1055-50	\$220.00	\$350.00	\$450.00	
KMA-24H	066-1055-51	\$220.00	\$350.00	\$450.00	
KMA-24H	066-1055-52	\$220.00	\$350.00	\$450.00	
KMA-24H	066-1055-53	\$220.00	\$350.00	\$450.00	
KMA-24H	066-1055-70	\$220.00	\$350.00	\$450.00	
KMA-24H	066-1055-71	\$220.00	\$350.00	\$450.00	
KMR-675	066-1044-00	\$220.00	\$450.00	\$600.00	Overhaul subject to age/condition
KMR-675	066-1044-01	\$220.00	\$450.00	\$600.00	Overhaul subject to age/condition
KMT-112	071-1052-00	\$220.00	N/A	N/A	SVC Only
KN-53	066-1067-00	\$220.00	\$450.00	\$650.00	
KN-53	066-1067-01	\$220.00	\$450.00	\$650.00	
KN-53	066-1067-02	\$220.00	\$450.00	\$650.00	
KN-53	066-1067-03	\$220.00	\$450.00	\$650.00	
KN-53	066-1067-04	\$220.00	\$450.00	\$650.00	
KN-53	066-1067-05	\$220.00	\$450.00	\$650.00	
KN-53	066-1067-10	\$220.00	\$450.00	\$650.00	
KN-62	066-1064-00	\$220.00	\$575.00	\$750.00	
KN-62A	066-1068-00	\$220.00	\$575.00	\$750.00	
KN-62A	066-1068-01	\$220.00	\$575.00	\$750.00	
KN-62A	066-1068-04	\$220.00	\$575.00	\$750.00	
KN-63	066-1070-00	\$220.00	\$660.00	\$750.00	
KN-63	066-1070-01	\$220.00	\$660.00	\$750.00	
KN-64	066-1088-00	\$220.00	\$600.00	\$750.00	
KN-64	066-1088-01	\$220.00	\$600.00	\$750.00	
KN-72	066-4009-00	\$220.00	\$350.00	\$500.00	
KN-73	066-1033-00	\$220.00	\$350.00	N/A	SVC Only
KN-75	066-1063-00	\$220.00	\$350.00	\$500.00	
KN-77	066-4004-00	\$220.00	\$350.00	N/A	SVC Only
KNI-415	066-3031-00	\$220.00	\$440.00	\$660.00	
KNI-415	066-3031-01	\$220.00	\$440.00	\$660.00	
KNI-415	066-3031-02	\$220.00	\$440.00	\$660.00	
KNI-415	066-3031-03	\$220.00	\$440.00	\$660.00	
KNI-415	066-3031-04	\$220.00	\$440.00	\$660.00	
KNI-416	066-3044-00	\$220.00	\$440.00	\$660.00	
KNI-416	066-3044-01	\$220.00	\$440.00	\$660.00	
KNI-416	066-3044-02	\$220.00	\$440.00	\$660.00	
KNI-416	066-3044-03	\$220.00	\$440.00	\$660.00	
KNI-520	066-3011-01	\$220.00	\$440.00	N/A	SVC Only

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KNI-520	066-3011-04	\$220.00	\$330.00	N/A	SVC Only
KNI-581	066-3042-00	\$220.00	\$330.00	N/A	SVC Only
KNI-581	066-3042-01	\$220.00	\$660.00	N/A	SVC Only
KNI-581	066-3042-02	\$220.00	\$660.00	N/A	SVC Only
KNI-581	066-3042-03	\$220.00	\$660.00	N/A	SVC Only
KNI-581	066-3042-04	\$220.00	\$660.00	N/A	SVC Only
KNI-582	066-3060-00	\$220.00	\$550.00	\$750.00	
KNI-582	066-3060-01	\$220.00	\$550.00	\$750.00	
KNI-582	066-3060-02	\$220.00	\$550.00	\$750.00	
KNI-582	066-3060-03	\$220.00	\$550.00	\$750.00	
KNI-582	066-3060-04	\$220.00	\$550.00	\$750.00	
KNI-582	066-3060-05	\$220.00	\$550.00	\$750.00	
KNI-582	066-3060-06	\$220.00	\$550.00	\$750.00	
KNR-630	066-4007-00	\$220.00	\$450.00	N/A	SVC Only
KNR-631	066-4007-01	\$220.00	\$450.00	N/A	SVC Only
KNR-632	066-4007-02	\$220.00	\$450.00	N/A	SVC Only
KNR-633	066-4007-03	\$220.00	\$450.00	N/A	SVC Only
KNR-634	066-1078-00	\$220.00	\$450.00	\$675.00	
KNR-634	066-1078-01	\$220.00	\$450.00	\$675.00	
KNR-634	066-1078-02	\$220.00	\$450.00	\$675.00	
KNR-634	066-1078-03	\$220.00	\$450.00	\$675.00	
KNR-634	066-1078-04	\$220.00	\$450.00	\$675.00	
KNR-634	066-1078-05	\$220.00	\$450.00	\$675.00	
KNR-634	066-1078-06	\$220.00	\$450.00	\$675.00	
KNR-634	066-1078-07	\$220.00	\$450.00	\$675.00	
KNR-634	066-1078-08	\$220.00	\$450.00	\$675.00	
KNR-634A	066-1078-10	\$220.00	\$450.00	\$675.00	
KNR-634A	066-1078-11	\$220.00	\$450.00	\$675.00	
KNR-634A	066-1078-12	\$220.00	\$450.00	\$675.00	
KNR-634A	066-1078-13	\$220.00	\$450.00	\$675.00	
KNR-634A	066-1078-14	\$220.00	\$450.00	\$675.00	
KNR-634A	066-1078-15	\$220.00	\$450.00	\$675.00	
KNR-634A	066-1078-16	\$220.00	\$450.00	\$675.00	
KNR-634A	066-1078-17	\$220.00	\$450.00	\$675.00	
KNR-634A	066-1078-18	\$220.00	\$450.00	\$675.00	
KNS-80	066-4008-00	\$220.00	\$770.00	N/A	SVC ONLY
KNS-80	066-4008-01	\$220.00	\$660.00	N/A	SVC ONLY
KNS-80	066-4008-02	\$220.00	\$660.00	N/A	SVC ONLY
KNS-80	066-4008-03	\$220.00	\$660.00	N/A	SVC ONLY
KNS-81	066-4010-00	\$220.00	\$660.00	\$0.00	Overhaul subject to availability of parts

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KNS-81	066-4010-01	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-02	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-03	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-04	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-10	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-11	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-12	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-13	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-14	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-15	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-16	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-17	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-18	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-19	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-20	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-21	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-30	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-31	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-32	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-33	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-34	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-35	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-36	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-37	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-38	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-39	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-40	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-60	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-61	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-62	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-63	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-64	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-65	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-66	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-67	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-69	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-70	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-71	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-80	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-81	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KNS-81	066-4010-82	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-83	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-84	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-85	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-86	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-87	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-88	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KNS-81	066-4010-89	\$220.00	\$550.00	\$660.00	Overhaul subject to availability of parts
KR-21	066-1021-00	\$220.00	\$550.00	\$660.00	Overhaul subject to age/condition
KR-21	066-1021-01	\$220.00	\$220.00	\$330.00	Overhaul subject to age/condition
KR-21	066-1021-02	\$220.00	\$220.00	\$330.00	Overhaul subject to age/condition
KR-22	066-1065-00	\$220.00	\$220.00	\$330.00	
KR-86	066-1038-00	\$220.00	\$750.00	N/A	SVC ONLY
KR-86	066-1038-00	\$220.00	\$750.00	N/A	SVC ONLY
KR-87	066-1072-00	\$220.00	\$450.00	\$750.00	
KR-87	066-1072-01	\$220.00	\$450.00	\$750.00	
KR-87	066-1072-02	\$220.00	\$450.00	\$750.00	
KR-87	066-1072-03	\$220.00	\$450.00	\$750.00	
KR-87	066-1072-04	\$220.00	\$450.00	\$750.00	
KR-87	066-1072-05	\$220.00	\$450.00	\$750.00	
KR-87	066-1072-06	\$220.00	\$450.00	\$750.00	
KR-87	066-1072-07	\$220.00	\$450.00	\$750.00	
KR-87	066-1072-14	\$220.00	\$450.00	\$750.00	
KR-87	066-1072-15	\$220.00	\$450.00	\$750.00	
KR-87	066-1072-17	\$220.00	\$450.00	\$750.00	
KRA-10	066-1061-00	\$220.00	\$550.00	\$880.00	
KRA-10A	066-1061-03	\$220.00	\$550.00	\$880.00	
KRA-405	066-1048-00	\$220.00	\$550.00	\$880.00	Does not include stripline replacement
KRA-405	066-1048-02	\$220.00	\$660.00	\$880.00	Does not include stripline replacement
KRA-405B	066-01153-0101	\$220.00	\$770.00	\$950.00	
KRA-405B	066-01153-0202	\$220.00	\$770.00	\$950.00	
KRA-405B	066-01153-2001	\$220.00	\$770.00	\$950.00	
KS-177	065-0050-01	\$220.00	N/A	N/A	
KS-177	065-0050-02	\$220.00	N/A	N/A	
KS-177	065-0050-04	\$220.00	N/A	N/A	
KS-177	065-0050-06	\$220.00	N/A	N/A	
KS-177	065-0050-07	\$220.00	N/A	N/A	
KS-177	065-0050-09	\$220.00	N/A	N/A	
KS-177	065-0050-11	\$220.00	N/A	N/A	
KS-177	065-0050-12	\$220.00	N/A	N/A	



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KS-177	065-0050-60	\$220.00	N/A	N/A	
KS-178	065-0051-01	\$220.00	N/A	N/A	
KS-178	065-0051-02	\$220.00	N/A	N/A	
KS-178	065-0051-04	\$220.00	N/A	N/A	
KS-178	065-0051-06	\$220.00	N/A	N/A	
KS-178	065-0051-07	\$220.00	N/A	N/A	
KS-178	065-0051-08	\$220.00	N/A	N/A	
KS-179	065-0052-04	\$220.00	N/A	N/A	
KS-179	065-0052-06	\$220.00	N/A	N/A	
KS-179	065-0052-07	\$220.00	N/A	N/A	
KS-179	065-0052-10	\$220.00	N/A	N/A	
KS-179	065-0052-13	\$220.00	N/A	N/A	
KS-179	065-0052-14	\$220.00	N/A	N/A	
KS-179	065-0052-15	\$220.00	N/A	N/A	
KS-179	065-0052-16	\$220.00	N/A	N/A	
KS-179	065-0052-17	\$220.00	N/A	N/A	
KS-270	065-0027-01	\$220.00			
KS-270	065-0027-02	\$220.00			
KS-270	065-0027-03	\$220.00			
KS-270	065-0027-04	\$220.00			
KS-270	065-0027-05	\$220.00			
KS-270	065-0027-06	\$220.00			
KS-270A	065-0059-01	\$220.00	\$750.00	\$1,250.00	
KS-270A	065-0059-02	\$220.00	\$750.00	\$1,250.00	
KS-270A	065-0059-03	\$220.00	\$750.00	\$1,250.00	
KS-270A	065-0059-04	\$220.00	\$750.00	\$1,250.00	
KS-270A	065-0059-05	\$220.00	\$750.00	\$1,250.00	
KS-270A	065-0059-06	\$220.00	\$750.00	\$1,250.00	
KS-270A	065-0059-08	\$220.00	\$750.00	\$1,250.00	
KS-270A	065-0059-23	\$220.00	\$750.00	\$1,250.00	
KS-270C	065-00178-0100	\$220.00	\$750.00	\$1,150.00	
KS-270C	065-00178-2100	\$220.00	\$750.00	\$1,150.00	
KS-270C	065-00178-2200	\$220.00	\$750.00	\$1,150.00	
KS-270C	065-00178-2500	\$220.00	\$750.00	\$1,150.00	
KS-271	065-0028-00	\$220.00			
KS-271	065-0028-01	\$220.00			
KS-271	065-0028-02	\$220.00			
KS-271	065-0028-03	\$220.00			
KS-271	065-0028-04	\$220.00			
KS-271	065-0028-05	\$220.00			

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KS-271A	065-0060-00	\$220.00	\$750.00	\$1,250.00	
KS-271A	065-0060-01	\$220.00	\$750.00	\$1,250.00	
KS-271A	065-0060-02	\$220.00	\$750.00	\$1,250.00	
KS-271A	065-0060-03	\$220.00	\$750.00	\$1,250.00	
KS-271A	065-0060-04	\$220.00	\$750.00	\$1,250.00	
KS-271A	065-0060-05	\$220.00	\$750.00	\$1,250.00	
KS-271A	065-0060-09	\$220.00	\$750.00	\$1,250.00	
KS-271A	065-0060-30	\$220.00	\$750.00	\$1,250.00	
KS-271A	065-0060-61	\$220.00	\$750.00	\$1,250.00	
KS-271A	065-0060-62	\$220.00	\$750.00	\$1,250.00	
KS-271A	065-0060-63	\$220.00	\$750.00	\$1,250.00	
KS-271C	065-00179-0100	\$220.00	\$600.00	\$700.00	
KS-271C	065-00179-0200	\$220.00	\$600.00	\$700.00	
KS-271C	065-00179-0300	\$220.00	\$600.00	\$700.00	
KS-271C	065-00179-0500	\$220.00	\$600.00	\$700.00	
KS-271C	065-00179-0600	\$220.00	\$600.00	\$700.00	
KS-272	065-0029-00	\$220.00			
KS-272	065-0029-01	\$220.00			
KS-272	065-0029-02	\$220.00			
KS-272	065-0029-03	\$220.00			
KS-272	065-0029-04	\$220.00			
KS-272	065-0029-05	\$220.00			
KS-272	065-0029-06	\$220.00			
KS-272	065-0029-07	\$220.00			
KS-272	065-0029-08	\$220.00			
KS-272	065-0029-09	\$220.00			
KS-272	065-0029-10	\$220.00			
KS-272	065-0029-11	\$220.00			
KS-272	065-0029-12	\$220.00			
KS-272	065-0029-13	\$220.00			
KS-272	065-0029-14	\$220.00			
KS-272	065-0029-15	\$220.00			
KS-272	065-0029-16	\$220.00			
KS-272	065-0029-17	\$220.00			
KS-272	065-0029-18	\$220.00			
KS-272	065-0029-19	\$220.00			
KS-272	065-0029-21	\$220.00			
KS-272	065-0029-22	\$220.00			
KS-272	065-0029-24	\$220.00			
KS-272	065-0029-25	\$220.00			

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KS-272	065-0029-26	\$220.00			
KS-272	065-0029-27	\$220.00			
KS-272	065-0029-28	\$220.00			
KS-272	065-0029-29	\$220.00			
KS-272	065-0029-30	\$220.00			
KS-272	065-0029-31	\$220.00			
KS-272	065-0029-32	\$220.00			
KS-272	065-0029-33	\$220.00			
KS-272	065-0029-34	\$220.00			
KS-272	065-0029-35	\$220.00			
KS-272	065-0029-36	\$220.00			
KS-272	065-0029-37	\$220.00			
KS-272	065-0029-38	\$220.00			
KS-272	065-0029-39	\$220.00			
KS-272	065-0029-40	\$220.00			
KS-272A	065-0061-00	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-01	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-02	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-03	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-04	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-05	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-06	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-07	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-08	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-09	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-10	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-11	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-12	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-13	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-14	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-15	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-16	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-17	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-18	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-19	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-21	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-22	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-24	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-25	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-26	\$220.00	\$750.00	\$1,250.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KS-272A	065-0061-27	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-28	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-29	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-30	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-31	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-32	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-33	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-34	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-35	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-36	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-37	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-38	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-39	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-40	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-41	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-42	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-44	\$220.00	\$750.00	\$1,250.00	
KS-272A	065-0061-50	\$220.00	\$750.00	\$1,250.00	
KS-272C	065-00180-0400	\$220.00	\$600.00	\$700.00	
KS-272C	065-00180-0600	\$220.00	\$600.00	\$700.00	
KS-272C	065-00180-0800	\$220.00	\$600.00	\$700.00	
KS-272C	065-00180-1400	\$220.00	\$600.00	\$700.00	
KS-272C	065-00180-2700	\$220.00	\$600.00	\$700.00	
KS-272C	065-00180-6500	\$220.00	\$600.00	\$700.00	
KSG-105	060-0013-00	\$220.00	\$0.00	\$1,440.00	Overhaul subject to can w/ Mod 1
KSG-105	060-0013-01	\$220.00	\$550.00	\$1,440.00	Overhaul subject to can w/ Mod 1
KT-70	066-01141-0101	\$220.00	\$550.00	\$750.00	
KT-70	066-01141-0201	\$220.00	\$550.00	\$750.00	
KT-70	066-01141-1101	\$220.00	\$550.00	\$750.00	
KT-71	066-01141-5101	\$220.00	\$550.00	\$750.00	
KT-71	066-01141-5201	\$220.00	\$550.00	\$750.00	
KT-71	066-01141-6101	\$220.00	\$550.00	\$750.00	
KT-76A	066-1062-00	\$220.00	\$450.00	\$675.00	Overhaul not including tube replacement
KT-76A	066-1062-02	\$220.00	\$550.00	\$990.00	Overhaul not including tube replacement
KT-76A	066-1062-10	\$220.00	\$550.00	\$990.00	Overhaul not including tube replacement
KT-76C	066-01156-0101	\$220.00	\$550.00	\$675.00	
KT-78A	066-1062-01	\$220.00	\$550.00	\$675.00	
KT-79	066-1053-00	\$220.00	\$550.00	\$990.00	
KTR-905	064-1009-00	\$220.00	\$550.00	N/A	
KTR-905	064-1009-02	\$220.00	\$550.00	N/A	



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KTR-905E	064-1009-01	\$220.00	\$550.00	N/A	
KTR-905E	064-1009-03	\$220.00	\$550.00	N/A	
KTR-908	064-1023-00	\$220.00	\$550.00	\$700.00	
KTR-908	064-1023-01	\$220.00	\$550.00	\$700.00	
KTR-908	064-1023-02	\$220.00	\$550.00	\$700.00	
KTR-908	064-1023-03	\$220.00	\$550.00	\$700.00	
KTR-908	064-1023-04	\$220.00	\$550.00	\$700.00	
KTR-908	064-1023-05	\$220.00	\$550.00	\$700.00	
KTR-908	064-1023-06	\$220.00	\$550.00	\$700.00	
KTR-908	064-1023-07	\$220.00	\$550.00	\$700.00	
KTR-908	064-1023-08	\$220.00	\$550.00	\$700.00	
KTR-908	064-1023-09	\$220.00	\$550.00	\$700.00	
KTR-908	064-1023-10	\$220.00	\$550.00	\$700.00	
KTR-908	064-1023-11	\$220.00	\$550.00	\$700.00	
KTR-908	064-1023-12	\$220.00	\$550.00	\$700.00	
KTR-908	064-1023-13	\$220.00	\$550.00	\$700.00	
KTR-908	064-1023-14	\$220.00	\$550.00	\$700.00	
KTR-908	064-1023-15	\$220.00	\$550.00	\$700.00	
KTR-909	064-01065-0100	\$220.00	\$650.00	\$950.00	
KTR-909B	064-01076-0101	\$220.00	\$650.00	\$950.00	
KTR-953	064-1015-00	\$330.00	\$990.00	\$950.00	
KTR-953	064-1015-01	\$330.00	\$660.00	\$950.00	
KTR-953	064-1015-10	\$330.00	\$660.00	\$950.00	
KTR-953	064-1015-11	\$330.00	\$660.00	\$950.00	
KTR-953	064-1015-40	\$330.00	\$660.00	\$950.00	
KTR-953	064-1015-41	\$330.00	\$660.00	\$950.00	
KTR-953	064-1015-51	\$330.00	\$660.00	\$950.00	
KTR-953	064-1015-53	\$330.00	\$660.00	\$950.00	
KTR-993	063-1007-00	\$330.00	\$660.00	\$1,850.00	
KX-125	069-01028-1101	\$220.00	\$600.00	\$750.00	
KX-125	069-01028-0101	\$220.00	\$600.00	\$750.00	
KX-155	069-1024-00	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-01	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-02	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-03	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-04	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-05	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-06	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-07	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-08	\$220.00	\$575.00	\$950.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KX-155	069-1024-09	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-10	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-11	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-12	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-13	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-30	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-31	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-32	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-33	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-34	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-35	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-36	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-37	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-38	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-39	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-40	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-41	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-42	\$220.00	\$575.00	\$950.00	
KX-155	069-1024-43	\$220.00	\$575.00	\$950.00	
KX-155A	069-01032-0101	\$220.00	\$550.00	\$750.00	
KX-155A	069-01032-0201	\$220.00	\$550.00	\$750.00	
KX-165	069-1025-00	\$220.00	\$550.00	\$750.00	
KX-165	069-1025-01	\$220.00	\$550.00	\$750.00	
KX-165	069-1025-02	\$220.00	\$550.00	\$750.00	
KX-165	069-1025-03	\$220.00	\$550.00	\$750.00	
KX-165	069-1025-05	\$220.00	\$550.00	\$750.00	
KX-165	069-1025-06	\$220.00	\$550.00	\$750.00	
KX-165	069-1025-07	\$220.00	\$550.00	\$750.00	
KX-165	069-1025-20	\$220.00	\$550.00	\$750.00	
KX-165	069-1025-21	\$220.00	\$550.00	\$750.00	
KX-165	069-1025-22	\$220.00	\$550.00	\$750.00	
KX-165	069-1025-23	\$220.00	\$550.00	\$750.00	
KX-165	069-1025-24	\$220.00	\$550.00	\$750.00	
KX-165	069-1025-25	\$220.00	\$550.00	\$750.00	
KX-165	069-1025-26	\$220.00	\$550.00	\$750.00	
KX-165	069-1025-27	\$220.00	\$550.00	\$750.00	
KX-165	069-1025-35	\$220.00	\$550.00	\$750.00	
KX-165	069-1025-04	\$220.00	\$550.00	\$750.00	
KX-165A	069-01033-0101	\$220.00	\$550.00	\$750.00	
KX-165A	069-01033-0201	\$220.00	\$550.00	\$750.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KXP-755	066-1041-00	\$220.00	\$660.00	N/A	SVC ONLY
KXP-756	066-1071-00	\$220.00	\$650.00	\$800.00	
KY-196	064-1019-00	\$220.00	\$550.00	\$750.00	
KY-196	064-1019-01	\$220.00	\$550.00	\$750.00	
KY-196	064-1019-02	\$220.00	\$550.00	\$750.00	
KY-196	064-1019-05	\$220.00	\$550.00	\$750.00	
KY-196	064-1019-06	\$220.00	\$550.00	\$750.00	
KY-196	064-1019-07	\$220.00	\$550.00	\$750.00	
KY-196	064-1019-10	\$220.00	\$550.00	\$750.00	
KY-196	064-1019-11	\$220.00	\$550.00	\$750.00	
KY-196	064-1019-12	\$220.00	\$550.00	\$750.00	
KY-196	064-1019-20	\$220.00	\$550.00	\$750.00	
KY-196A	064-1054-30	\$220.00	\$550.00	\$750.00	
KY-196A	064-1054-31	\$220.00	\$550.00	\$750.00	
KY-196A	064-1054-32	\$220.00	\$550.00	\$750.00	
KY-196A	064-1054-50	\$220.00	\$550.00	\$750.00	
KY-196A	064-1054-60	\$220.00	\$550.00	\$750.00	
KY-196B	064-01084-0101	\$220.00	\$475.00	\$700.00	
KY-196B	064-01084-0201	\$220.00	\$475.00	\$700.00	
KY-197	064-1021-00	\$220.00	\$550.00	\$750.00	
KY-197	064-1021-01	\$220.00	\$550.00	\$750.00	
KY-197	064-1021-05	\$220.00	\$550.00	\$750.00	
KY-197	064-1021-10	\$220.00	\$550.00	\$750.00	
KY-197	064-1021-11	\$220.00	\$550.00	\$750.00	
KY-197	064-1021-20	\$220.00	\$550.00	\$750.00	
KY-197A	064-1053-30	\$220.00	\$550.00	\$750.00	
KY-197A	064-1053-31	\$220.00	\$550.00	\$750.00	
KY-197A	064-1053-32	\$220.00	\$550.00	\$750.00	
KY-197A	064-1053-60	\$220.00	\$550.00	\$750.00	
KY-92	064-1020-00	\$220.00	\$550.00	\$750.00	
KY-96A	064-1052-10	\$220.00	\$450.00	\$650.00	
KY-96A	064-1052-30	\$220.00	\$450.00	\$650.00	
KY-96A	064-1052-50	\$220.00	\$450.00	\$650.00	
KY-96A	064-1052-51	\$220.00	\$450.00	\$650.00	
KY-96A	064-1052-60	\$220.00	\$450.00	\$650.00	
KY-96A	064-1052-61	\$220.00	\$450.00	\$650.00	
KY-96A	064-1052-70	\$220.00	\$450.00	\$650.00	
KY-97A	064-1051-10	\$220.00	\$450.00	\$650.00	
KY-97A	064-1051-30	\$220.00	\$450.00	\$650.00	
KY-97A	064-1051-50	\$220.00	\$450.00	\$650.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
KY-97A	064-1051-51	\$220.00	\$450.00	\$650.00	
KY-97A	064-1051-60	\$220.00	\$450.00	\$650.00	
KY-97A	064-1051-61	\$220.00	\$450.00	\$650.00	
KY-97A	064-1051-70	\$220.00	\$450.00	\$650.00	
ME406	453-6603-XXX	\$220.00	\$440.00	N/A	Repair includes program, battery replacement
ME406HM	453-6604-XXX	\$220.00	\$440.00	N/A	Repair includes program, battery replacement
ME406P	453-6611-XXX	\$220.00	\$440.00	N/A	Repair includes program, battery replacement
MKL-351	622-2086-001	\$0.00	\$0.00	N/A	
MKL-351	622-3102-001	\$110.00	\$220.00	N/A	
MKR-350	622-2085-001	\$110.00	\$220.00	N/A	
MST-67A	066-01143-0201	\$330.00	\$750.00	\$1,250.00	
MST-67A	066-01143-0301	\$330.00	\$750.00	\$1,250.00	
MST-67A	066-01143-0601	\$330.00	\$750.00	\$1,250.00	
MST-67A	066-01143-1101	\$330.00	\$750.00	\$1,250.00	
MST-67A	066-01143-1201	\$330.00	\$750.00	\$1,250.00	
MST-67A	066-01143-1301	\$330.00	\$750.00	\$1,250.00	
MST-67A	066-01143-1602	\$330.00	\$750.00	\$1,250.00	
MST-67A	066-01143-2001	\$330.00	\$750.00	\$1,250.00	
MST-67A	066-01143-2101	\$330.00	\$750.00	\$1,250.00	
P-20	P-20	\$220.00	\$0.00	\$950.00	
P-20A	P-20A	\$220.00	\$660.00	\$950.00	
P-21	P-21	\$220.00	\$660.00	\$1,760.00	
PC-125	PC-125	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-14	PC-14	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-14A	PC-14A	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-14C	PC-14C	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-14D	PC-14D	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-15B	PC-15B	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-15BC	PC-15BC	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-15BC(D)	PC-15BC(D)	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-15BD	PC-15BD	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-15H	PC-15H	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-15H(F)	PC-15H(F)	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-16	PC-16	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-16-2	PC-16-2	\$220.00	\$550.00	\$1,200.00	Overhaul subject to age/condition
PC-16-3	PC-16-3	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC17	PC-17	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-17-3	PC-17-3	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-17A	PC-17A	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-250	PC-250	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace

Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
PC-251	PC-251	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-251	PC-451	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-251-1C	PC-251-1C	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-350	PC-350	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-350	PC-350	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-351	PC-351	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-6	PC-6	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PC-6B	PC-6B	\$220.00	\$660.00	\$1,200.00	Overhaul subject to age/condition
PS-835C	501-1228-03	\$220.00	\$600.00	\$790.00	
PS-835D	501-1228-04	\$220.00	\$600.00	\$790.00	
PWC-150	622-2093-001	\$110.00	\$220.00	N/A	
PWR-200	622-2883-001	\$220.00	\$220.00	\$800.00	Overhaul subject to age/condition
PWR-230	622-6667-001	\$330.00	\$550.00	\$1,500.00	
RA-210	4004444-901	\$220.00	\$550.00	\$2,200.00	
RA-215	4014267-901	\$220.00	\$550.00	\$770.00	
RA-315	7000839-901	\$220.00	\$550.00	\$770.00	
RA-315	7000839-902	\$220.00	\$550.00	\$770.00	
RA-315	7000839-903	\$220.00	\$550.00	\$770.00	
RA-315	7000839-906	\$220.00	\$550.00	\$770.00	
RA-315	7000839-922	\$220.00	\$550.00	\$770.00	
RA-335	7000839-904	\$220.00	\$550.00	\$770.00	
RA-335	7000839-905	\$220.00	\$550.00	\$770.00	
RA-335	7000839-923	\$220.00	\$550.00	\$770.00	
RMI-30	622-4938-001	\$220.00	\$440.00	\$800.00	
RMI-30	622-4938-002	\$220.00	\$605.00	\$800.00	
RMI-30	622-4938-003	\$220.00	\$605.00	\$800.00	
RMI-30	622-4938-004	\$220.00	\$605.00	\$800.00	
RMI-30	622-4938-005	\$220.00	\$605.00	\$800.00	
RMI-30	622-4938-006	\$220.00	\$605.00	\$800.00	
RMI-30	622-4938-007	\$220.00	\$605.00	\$800.00	
RMI-30	622-4938-021	\$220.00	\$605.00	\$800.00	
RMI-30	622-4938-022	\$220.00	\$605.00	\$800.00	
RMI-30	622-4938-023	\$220.00	\$605.00	\$800.00	
RMI-30	622-4938-024	\$220.00	\$605.00	\$800.00	
RMI-30	622-4938-025	\$220.00	\$605.00	\$800.00	
RMI-30	622-4938-026	\$220.00	\$605.00	\$800.00	
RMI-30	622-4938-027	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-001	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-002	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-003	\$220.00	\$605.00	\$800.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
RMI-36	622-2506-004	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-005	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-006	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-007	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-008	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-009	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-010	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-011	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-012	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-013	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-014	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-101	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-102	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-103	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-104	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-105	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-106	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-107	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-108	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-109	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-110	\$220.00	\$605.00	\$800.00	
RMI-36	622-2506-111	\$220.00	\$605.00	\$800.00	
RS-181A	071-1315-00	\$330.00	\$605.00	\$1,500.00	Magnetron replacement not included
RS-181A	071-1315-10	\$330.00	\$770.00	\$1,500.00	Magnetron replacement not included
RS-181A	071-1315-30	\$330.00	\$770.00	\$1,500.00	Magnetron replacement not included
RS-181A	3614077-8101	\$330.00	\$770.00	\$1,500.00	Magnetron replacement not included
RS-811A	071-1378-00	\$330.00	\$770.00	\$1,500.00	Magnetron replacement not included
RS-811A	8095536-8101	\$330.00	\$770.00	\$1,500.00	Magnetron replacement not included
RS-841A	071-1318-10	\$330.00	\$770.00	\$1,500.00	Magnetron replacement not included
RS-841A	071-1318-30	\$330.00	\$770.00	\$1,500.00	Magnetron replacement not included
RS-841A	071-1318-00	\$330.00	\$770.00	\$1,500.00	Magnetron replacement not included
RS-861A	3614475-8631	\$330.00	\$770.00	\$1,500.00	Magnetron replacement not included
RS-861A	3614475-8601	\$330.00	\$770.00	\$1,500.00	Magnetron replacement not included
RS-861A	071-1319-00	\$330.00	\$770.00	\$1,500.00	Magnetron replacement not included
RS-861A	071-1319-30	\$330.00	\$770.00	\$1,500.00	Magnetron replacement not included
RT-1151A	4001921-5101	\$330.00	\$700.00	\$1,500.00	Magnetron replacement not included
RT-1201A	4000502-0101	\$330.00	\$700.00	\$1,500.00	Magnetron replacement not included
RT-1299(V)1/ARC-186(V)	622-4037-001	\$220.00			No avg. repair, must be evaluated for cost
RT-1299(V)2/ARC-186(V)	622-4037-002	\$220.00			No avg. repair, must be evaluated for cost
RT-1299(V)3/ARC-186(V)	622-4037-003	\$220.00			No avg. repair, must be evaluated for cost

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
RT-1299(V)4/ARC-186(V)	622-4037-004	\$220.00			No avg. repair, must be evaluated for cost
RT-1299(V)5/ARC-186(V)	622-4037-005	\$220.00			No avg. repair, must be evaluated for cost
RT-1299(V)6/ARC-186(V)	622-4037-006	\$220.00			No avg. repair, must be evaluated for cost
RT-1299(V)7/ARC-186(V)	622-4037-007	\$220.00			No avg. repair, must be evaluated for cost
RT-1299(V)8/ARC-186(V)	622-4037-008	\$220.00			No avg. repair, must be evaluated for cost
RT-1300/ARC-186(V)	622-4038-001	\$220.00			No avg. repair, must be evaluated for cost
RT-1300A/ARC-186(V)	622-4038-002	\$220.00			No avg. repair, must be evaluated for cost
RT-1300B/ARC-186(V)	622-6347-001	\$220.00			No avg. repair, must be evaluated for cost
RT-1300C/ARC-186(V)	622-6347-002	\$220.00			No avg. repair, must be evaluated for cost
RT-1301A	4000966-0101	\$330.00	\$0.00	\$1,800.00	Magnetron replacement not included
RT-1301B	4000966-0103	\$330.00	\$880.00	\$1,800.00	Magnetron replacement not included
RT-1301B	4000966-0109	\$330.00	\$880.00	\$1,800.00	Magnetron replacement not included
RT-131A	4000763-3101	\$330.00	\$880.00	\$1,500.00	Magnetron replacement not included
RT-1354/ARC-186(V)	622-5528-001	\$220.00			No avg. repair, must be evaluated for cost
RT-1401A	4000831-0101	\$330.00	\$0.00	\$2,100.00	Magnetron replacement not included
RT-1401B	4000831-0102	\$330.00	\$880.00	\$2,100.00	Magnetron replacement not included
RT-1401B	4000831-0103	\$330.00	\$880.00	\$2,100.00	Magnetron replacement not included
RT-1401B	4000831-0105	\$330.00	\$880.00	\$2,100.00	Magnetron replacement not included
RT-1401B	4000831-0106	\$330.00	\$880.00	\$2,100.00	Magnetron replacement not included
RT-220	4004437-901	\$220.00	\$800.00	\$1,200.00	Tube replacement not included
RT-220	4004437-903	\$220.00	\$800.00	\$1,200.00	Tube replacement not included
RT-221	4004437-902	\$220.00	\$800.00	\$1,200.00	Tube replacement not included
RT-300	7001840-901	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-902	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-903	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-905	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-906	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-911	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-912	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-913	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-915	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-916	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-917	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-918	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-922	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-924	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-926	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-928	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-931	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-932	\$220.00	\$1,400.00	\$3,500.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
RT-300	7001840-934	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-936	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-937	\$220.00	\$1,400.00	\$3,500.00	
RT-300	7001840-938	\$220.00	\$1,400.00	\$3,500.00	
RT-3002	MI-585222-1	\$330.00	\$700.00	\$1,500.00	Magnetron replacement not included
RT-4001	MI-585200	\$330.00	\$700.00	\$1,500.00	Magnetron replacement not included
RT-4001	MI-585200-1	\$330.00	\$700.00	\$1,500.00	Magnetron replacement not included
RT-5001	MI-585300	\$330.00	\$700.00	\$1,500.00	Magnetron replacement not included
RT-5001	MI-585300-1	\$330.00	\$700.00	\$1,500.00	Magnetron replacement not included
RT-5001	MI-585300-4	\$330.00	\$700.00	\$1,500.00	Magnetron replacement not included
SL-30	ALL	N/A	\$450.00	\$3,850.00	Flat rate repair from factory
SL-40	ALL	N/A	\$450.00	\$0.00	Flat rate repair from factory
SL-50	ALL	N/A	\$400.00	\$0.00	Flat rate repair from factory
SL-60	ALL	N/A	\$500.00	\$0.00	Flat rate repair from factory
SL-70	ALL	N/A	\$450.00	\$0.00	Flat rate repair from factory
TCR-220	622-5337-001	\$330.00	\$0.00	\$0.00	Overhaul subject to age/condition
TCR-220	622-5337-002	\$330.00	\$550.00	\$770.00	Overhaul subject to age/condition
TCR-230	622-6557-001	\$330.00	\$550.00	\$770.00	Overhaul subject to age/condition
TCR-230	622-6557-002	\$330.00	\$550.00	\$770.00	Overhaul subject to age/condition
TCR-230	622-6557-003	\$330.00	\$0.00	\$0.00	Overhaul subject to age/condition
TCR-230	622-6557-011	\$330.00	\$550.00	\$770.00	Overhaul subject to age/condition
TCR-230	622-6557-012	\$330.00	\$550.00	\$770.00	Overhaul subject to age/condition
TCR-230	622-6557-013	\$330.00	\$550.00	\$770.00	Overhaul subject to age/condition
TDR-90	622-1270-001	\$220.00	\$550.00	\$750.00	Tube replacement not included
TDR-94	622-9352-001	\$220.00	\$550.00	\$950.00	
TDR-94	622-9352-002	\$220.00	\$770.00	\$950.00	
TDR-94	622-9352-003	\$220.00	\$770.00	\$950.00	
TDR-94D	622-9210-001	\$220.00	\$770.00	\$1,750.00	
TDR-94D	622-9210-002	\$220.00	\$770.00	\$1,750.00	
TDR-94D	622-9210-003	\$220.00	\$770.00	\$1,750.00	
TDR-950	622-2092-001	\$220.00	\$990.00		SVC Only
TDR-950L	622-3004-001	\$220.00	\$550.00		SVC Only
TRE-920	622-8973-001	\$350.00	N/A	\$4,500.00	Flat rate overhaul available for most units
TRE-920	622-8973-002	\$350.00	N/A	\$4,500.00	Flat rate overhaul available for most units
TRE-920	622-8973-003	\$350.00	N/A	\$4,500.00	Flat rate overhaul available for most units
TRE-920	622-8973-004	\$350.00	N/A	\$4,500.00	Flat rate overhaul available for most units
TRE-920	622-8973-011	\$350.00	N/A	\$4,500.00	Flat rate overhaul available for most units
TRE-920	622-8973-101	\$350.00	N/A	\$4,500.00	Flat rate overhaul available for most units
TRE-920	622-8973-102	\$350.00	N/A	\$4,500.00	Flat rate overhaul available for most units
TRE-920	622-8973-103	\$350.00	N/A	\$4,500.00	Flat rate overhaul available for most units

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
TRE-920	622-8973-104	\$350.00	N/A	\$4,500.00	Flat rate overhaul available for most units
VCT-186B	622-6347-001	\$220.00			No avg. repair, must be evaluated for cost
VCT-186B	622-6347-002	\$220.00			No avg. repair, must be evaluated for cost
VCT-186K	622-7362-001	\$220.00			No avg. repair, must be evaluated for cost
VCT-186KR	622-7879-001	\$220.00			No avg. repair, must be evaluated for cost
VCT-186P	622-4037-001	\$220.00			No avg. repair, must be evaluated for cost
VCT-186P	622-4037-002	\$220.00			No avg. repair, must be evaluated for cost
VCT-186P	622-4037-003	\$220.00			No avg. repair, must be evaluated for cost
VCT-186P	622-4037-004	\$220.00			No avg. repair, must be evaluated for cost
VCT-186P	622-4037-005	\$220.00			No avg. repair, must be evaluated for cost
VCT-186P	622-4037-006	\$220.00			No avg. repair, must be evaluated for cost
VCT-186P	622-4037-007	\$220.00			No avg. repair, must be evaluated for cost
VCT-186P	622-4037-008	\$220.00			No avg. repair, must be evaluated for cost
VCT-186P-1	622-5528-001	\$220.00			No avg. repair, must be evaluated for cost
VCT-186R	622-4038-001	\$220.00			No avg. repair, must be evaluated for cost
VCT-186R	622-4038-002	\$220.00			No avg. repair, must be evaluated for cost
VHF-20	792-6657-001	\$220.00	\$500.00	\$650.00	
VHF-20	792-6657-002	\$220.00	\$500.00	\$650.00	
VHF-20	792-6657-003	\$220.00	\$500.00	\$650.00	
VHF-20	792-6657-004	\$220.00	\$500.00	\$650.00	
VHF-20A	622-1879-001	\$220.00	\$500.00	\$650.00	
VHF-20A	622-1879-002	\$220.00	\$500.00	\$650.00	
VHF-20B	622-1334-001	\$220.00	\$500.00	\$650.00	
VHF-20B	622-1334-002	\$220.00	\$500.00	\$650.00	
VHF-21A	622-6389-001	\$220.00	\$550.00	\$750.00	
VHF-21A	622-6389-002	\$220.00	\$550.00	\$750.00	
VHF-21A	622-6389-011	\$220.00	\$550.00	\$750.00	
VHF-21A	622-6389-012	\$220.00	\$550.00	\$750.00	
VHF-21B	622-6390-001	\$220.00	\$550.00	\$750.00	
VHF-21B	622-6390-002	\$220.00	\$550.00	\$750.00	
VHF-22A	622-6152-001	\$220.00	\$550.00	\$750.00	
VHF-22A	622-6152-002	\$220.00	\$550.00	\$750.00	
VHF-22A	622-6152-011	\$220.00	\$550.00	\$750.00	
VHF-22A	622-6152-012	\$220.00	\$550.00	\$750.00	
VHF-22A	622-6152-021	\$220.00	\$550.00	\$750.00	
VHF-22A	622-6152-022	\$220.00	\$550.00	\$750.00	
VHF-22A	622-6152-023	\$220.00	\$550.00	\$750.00	
VHF-22A	622-6152-031	\$220.00	\$550.00	\$750.00	
VHF-22A	622-6152-032	\$220.00	\$550.00	\$750.00	
VHF-22A	622-6152-033	\$220.00	\$550.00	\$750.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
VHF-22B	622-6153-001	\$220.00	\$550.00	\$750.00	
VHF-22B	622-6153-002	\$220.00	\$550.00	\$750.00	
VHF-22B	622-6153-021	\$220.00	\$550.00	\$750.00	
VHF-22B	622-6153-022	\$220.00	\$550.00	\$750.00	
VHF-22B	622-6153-023	\$220.00	\$550.00	\$750.00	
VHF-22C	822-1113-001	\$220.00	\$550.00	\$750.00	
VHF-22C	822-1113-021	\$220.00	\$550.00	\$750.00	
VHF-22C	822-1113-023	\$220.00	\$550.00	\$750.00	
VHF-22D	822-1114-001	\$220.00	\$550.00	\$750.00	
VHF-22D	822-1114-021	\$220.00	\$550.00	\$750.00	
VHF-22D	822-1114-023	\$220.00	\$550.00	\$750.00	
VHF-422A	622-7292-001	\$220.00	\$550.00	\$750.00	
VHF-422A	622-7292-002	\$220.00	\$550.00	\$750.00	
VHF-422A	622-7292-101	\$220.00	\$550.00	\$750.00	
VHF-422A	622-7292-102	\$220.00	\$550.00	\$750.00	
VHF-422A	622-7292-121	\$220.00	\$550.00	\$750.00	
VHF-422A	622-7292-122	\$220.00	\$550.00	\$750.00	
VHF-422A	622-7292-123	\$220.00	\$550.00	\$750.00	
VHF-422B	622-7293-001	\$220.00	\$550.00	\$750.00	
VHF-422B	622-7293-002	\$220.00	\$550.00	\$750.00	
VHF-422B	622-7293-101	\$220.00	\$550.00	\$750.00	
VHF-422B	622-7293-102	\$220.00	\$550.00	\$750.00	
VHF-422B	622-7293-121	\$220.00	\$550.00	\$750.00	
VHF-422B	622-7293-122	\$220.00	\$550.00	\$750.00	
VHF-422B	622-7293-123	\$220.00	\$550.00	\$750.00	
VHF-422C	822-1115-001	\$220.00	\$550.00	\$750.00	
VHF-422C	822-1115-021	\$220.00	\$550.00	\$750.00	
VHF-422C	822-1115-023	\$220.00	\$550.00	\$750.00	
VHF-422D	822-1116-001	\$220.00	\$550.00	\$750.00	
VHF-422D	822-1116-021	\$220.00	\$550.00	\$750.00	
VHF-422D	822-1116-023	\$220.00	\$550.00	\$750.00	
VIR-30A	622-0876-001	\$220.00	\$550.00	\$675.00	
VIR-30A	622-0876-002	\$220.00	\$550.00	\$675.00	
VIR-30A	622-0876-003	\$220.00	\$550.00	\$675.00	
VIR-30A	622-0876-004	\$220.00	\$550.00	\$675.00	
VIR-30A	622-0876-011	\$220.00	\$550.00	\$675.00	
VIR-30A	622-0876-012	\$220.00	\$550.00	\$675.00	
VIR-30A	622-0876-013	\$220.00	\$550.00	\$675.00	
VIR-30A	622-0876-014	\$220.00	\$550.00	\$675.00	
VIR-30A	622-0876-201	\$220.00	\$550.00	\$675.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
VIR-30A	622-0876-202	\$220.00	\$550.00	\$675.00	
VIR-30A	622-0876-203	\$220.00	\$550.00	\$675.00	
VIR-30A	622-0876-204	\$220.00	\$550.00	\$675.00	
VIR-30A	622-0876-211	\$220.00	\$550.00	\$675.00	
VIR-30A	622-0876-212	\$220.00	\$550.00	\$675.00	
VIR-30A	622-0876-213	\$220.00	\$550.00	\$675.00	
VIR-30A	622-0876-214	\$220.00	\$550.00	\$675.00	
VIR-30M	622-0877-001	\$220.00	\$550.00	\$675.00	
VIR-30M	622-0877-002	\$220.00	\$550.00	\$675.00	
VIR-30M	622-0877-003	\$220.00	\$550.00	\$675.00	
VIR-30M	622-0877-004	\$220.00	\$550.00	\$675.00	
VIR-30M	622-0877-201	\$220.00	\$550.00	\$675.00	
VIR-30M	622-0877-202	\$220.00	\$550.00	\$675.00	
VIR-30M	622-0877-203	\$220.00	\$550.00	\$675.00	
VIR-30M	622-0877-204	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-001	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-002	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-003	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-004	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-005	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-006	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-007	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-008	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-009	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-011	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-012	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-013	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-014	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-015	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-016	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-027	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-201	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-202	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-203	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-204	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-207	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-208	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-209	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-211	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-212	\$220.00	\$550.00	\$675.00	

PLEASE NOTE: The average prices listed above are historic averages only. These do not represent a firm price to repair and should be used for reference only.



Southeast Aerospace
Service Capabilities List

Last Update: 11/29/2010

Model Number:	Part Number:	Average Bench Check:	Average Repair:	Average Overhaul:	Notes:
VIR-31A	622-1239-213	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-214	\$220.00	\$550.00	\$675.00	
VIR-31A	622-1239-227	\$220.00	\$550.00	\$675.00	
VIR-31H	622-2819-001	\$220.00	\$550.00	\$675.00	
VIR-31H	622-2819-002	\$220.00	\$550.00	\$675.00	
VIR-31H	622-2819-003	\$220.00	\$550.00	\$675.00	
VIR-31H	622-2819-004	\$220.00	\$550.00	\$675.00	
VIR-31H	622-2819-201	\$220.00	\$550.00	\$675.00	
VIR-31H	622-2819-202	\$220.00	\$550.00	\$675.00	
VIR-31H	622-2819-203	\$220.00	\$550.00	\$675.00	
VIR-31H	622-2819-204	\$220.00	\$550.00	\$675.00	
VIR-32	622-6137-001	\$220.00	\$550.00	\$675.00	
VIR-32	622-6137-201	\$220.00	\$550.00	\$675.00	
VIR-432	622-7194-001	\$220.00	\$550.00	\$675.00	
VIR-432	622-7194-011	\$220.00	\$550.00	\$675.00	
VIR-432	622-7194-101	\$220.00	\$550.00	\$675.00	
VIR-432	622-7194-201	\$220.00	\$550.00	\$675.00	
WXR-250	622-3338-001	\$220.00	\$660.00	\$1,100.00	Magnetron replacement not included
WXT-200A	622-4021-001	\$220.00	\$660.00	\$1,100.00	Magnetron replacement not included
WXT-250A	622-4022-001	\$220.00	\$660.00	\$1,100.00	Magnetron replacement not included
WXT-250B	622-7337-001	\$220.00	\$660.00	\$1,100.00	Magnetron replacement not included