

PA-261894

Product Advisory

Issue Date: May 9, 2023

Change Type:

Packaging update to consolidate labeling

Parts Affected:

Part Numbers			
BCM95719A1904AC	BCM957414A4140C	BCM957504-M1100G16	BCM957508-N2100GI
BCM95719N1905C	BCM957414A4142CC	BCM957504-N1100G	BCM957508-P1200G
BCM95719N1905CI	BCM957414M4142C	BCM957504-N1100GD	BCM957508-P2100G
BCM95720A2003AC	BCM957414M4143C	BCM957504-N1100GI	BCM958802A8046C
BCM95720A2003ACBLK	BCM957414M4146C	BCM957504-N2100GI	
BCM957302A3021AC	BCM957414N4140C	BCM957504-N425G	
BCM957314A3143CC	BCM957414N4140CI	BCM957504-N425GI	
BCM957412A4120AC	BCM957416A4160C	BCM957504-P425G	
BCM957412M4122C	BCM957416M4163C	BCM957508-N1200G	
BCM957412M4123C	BCM957416N4160C	BCM957508-N1200GI	
BCM957412N4120C	BCM957416N4160CI	BCM957508-N2100G	
BCM957412N4120CI	BCM957502-N150G	BCM957508-N2100GD	



Description and Extent of Change:

The Product Factory ID label, MAC Address label and Serial Number label will be combined into a single new label.

Current PCBA labels (PCIe card):





Image of label is for illustrative purposed only – Actual label may contain different data

New PCBA labels (PCIe card):




Made In Vietnam REV: 022 BCM957414A4142CC SN: A41422246000V2FG MAC: 00-62-0B-F7-D8-50

New BRCM consolidated PCBA Label


Label size: 12.7 x 11.1mm




Current PCBA labels (OCP 3.0 card):




New PCBA labels (OCP 3.0 card):









Reasons for Change:

The change is being implement to further enhance supply continuity and standardize package labeling across the product line.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The adapter specification will remain the same. No changes to adapter form, fit, function, quality and reliability.



Effective Date of Change:

The label consolidation will be implemented as a running change. Product shipments start after May 15, 2023.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.