



Countries:	CANADA, UNITED STATES, MEXICO, PUERTO RICO	Document ID:	IK1200799
Availability:	ISIS, Bus ISIS, FleetISIS, Body Builder	Revision:	1
Major System:	ENGINES	Created:	8/20/2012
Current Language:	English	Last Modified:	2/5/2014
Other Languages:	Français , Español ,	Author:	Octavio Ortiz
Viewed:	856		

[Less Info](#)

Hide Details

Coding Information

Copy Link 	Copy Relative Link 	Bookmark View My Bookmarks	Add to Favorites 	Print 	Provide Feedback 	Helpful 11	Not Helpful 2
----------------------	-------------------------------	--	-----------------------------	------------------	-----------------------------	--------------------------	-----------------------------

Title: Oil Filter Kit Packaging Change

Applies To: Oil Filter Kits P/N 1842639C92 and 1842655C92 used to service I-313, I-326 model engines built 2003 and later.

DESCRIPTION

Oil Filter Kit Packaging Changes.

SYMPTOMS

- Replacement of the oil drain plug o-rings is only required when the o-ring is damaged or worn the oil drain plug o-ring P/N 1814695C1 will no longer be included in the oil filter kits listed. When servicing an engine utilizing these kits it will be necessary to order the oil drain plug o-ring seperately if required.
- PDC inventory of the original kits P/N1842639C91 and P/N1842655C91 will be available until exhausted then replaced with the C92 part.

PARTS INFORMATION

Part #	Description
1842639C92	Kit, Oil Filter (Long), removed two O-Rings PN 1814695C1
1842655C92	Kit, Oil Filter (Short), removed two O-Rings PN 1814695C1
1814695C1	Drain Plug O-Ring

Hide Details

Feedback Information

Viewed: 855
Helpful: 11
Not Helpful: 2
No Feedback Found