

This Technical Advisory describes an issue which may or may not affect the customer's product

Intel Technical Advisory

TA-1135

5200 NE Elam Young Parkway
Hillsboro, OR 97124

May 28, 2018

Wrong version number printed on the package label for Intel® 2/4U Premium Rail AXXFULLRAIL, Intel® 2/4U Premium Rail AXXSHRTRAIL and Intel® Cable Management Arm AXXCMA2

Affected Products

Product Code	MM#	Version
AXXCMA2	939211	H59208-001
AXXFULLRAIL	939209	H59206-001
AXXSHRTRAIL	939210	H59207-001

Description

Intel® has discovered a mistake in the assembly and version number printed on the package labels for Intel® 2/4U Premium Rail AXXFULLRAIL, Intel® 2/4U Premium Rail AXXSHRTRAIL and Intel® Cable Management Arm AXXCMA2. The current assembly and version number printed on the labels corresponds to an internal control number instead of the external version used with customers. The table below shows both the wrong version number and the correct one. The location of the affected numbers in the label are shown in the images below.




Figure 1. Example of incorrect Version and Assembly number location in the label




Figure 2. Example of correct Version and Assembly number location in the label

Product Code	MM#	Correct	Wrong
AXXCMA2	939211	H59208-001	H59204_R01
AXXFULLRAIL	939209	H59206-001	H59202_R01
AXXSHRTRAIL	939210	H59207-001	H59203_R01

Root Cause

When printing the labels, the factory used the Intel Part Number of the reference document for the rail kits, instead of the Intel Part Number for the actual rail kits.

Corrective Action

Intel® will replace the incorrect labels for all the existing inventory at Intel's warehouse.

Recommended Customer Action / Workaround

Intel® believes this issue does not impact the usage of the products listed on the Affected Products List. Customers can use the table above to identify and track the affected rail kits.

For further assistance and help customers can contact their Intel® representative.

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Intel® Corporation