

Xerox® Replacement Cartridges For HP, Lexmark and Brother Printers Quick Reference Guide



HP Color Printer replacement toner supplies

Machine Type	Xerox Part Number	Equivalent OEM Part Number	For Use In	OEM Stated Yield	Xerox Stated Yield
LJ4600*	6R941	C9720A – Black	HP Color LaserJet 4600, 4600n, 4600dn, 4600dtn, 4600hdn, 4650, 4650n, 4650dn, 4650dtn, 4650hdn	9,000†	9,000‡
LJ4600*	6R942	C9721A – Cyan	HP Color LaserJet 4600, 4600n, 4600dn, 4600dtn, 4600hdn, 4650, 4650n, 4650dn, 4650dtn, 4650hdn	8,000†	8,000‡
LJ4600*	6R943	C9722A – Yellow	HP Color LaserJet 4600, 4600n, 4600dn, 4600dtn, 4600hdn, 4650, 4650n, 4650dn, 4650dtn, 4650hdn	8,000†	8,000‡
LJ4600*	6R944	C9723A – Magenta	HP Color LaserJet 4600, 4600n, 4600dn, 4600dtn, 4600hdn, 4650, 4650n, 4650dn, 4650dtn, 4650hdn	8,000†	8,000‡
LJ2500/LJ2800*	6R1285	C9700A/Q3960A Black	HP Color LaserJet 1500, 2500, 2550, 2800 Series	5,000†	5,000‡
LJ2500/LJ2800*	6R1286	C9701A/Q3961A Cyan	HP Color LaserJet 1500, 2500, 2550, 2800 Series	4,000†	4,000‡
LJ2500/LJ2800*	6R1287	C9702A/Q3962A Yellow	HP Color LaserJet 1500, 2500, 2550, 2800 Series	4,000†	4,000‡
LJ2500/LJ2800*	6R1288	C9703A/Q3963A Magenta	HP Color LaserJet 1500, 2500, 2550, 2800 Series	4,000†	4,000‡
LJ3500/LJ3550 LJ3700*	6R1289	Q2670A – Black	HP Color LaserJet 3500 Series, 3550 Series, 3700 Series	6,000†	6,000‡
LJ3500/LJ3550*	6R1290	Q2671A – Cyan	HP Color LaserJet 3500 Series, 3550 Series	4,000†	4,000‡
LJ3500/LJ3550*	6R1291	Q2672A – Yellow	HP Color LaserJet 3500 Series, 3550 Series	4,000†	4,000‡
LJ3500/LJ3550*	6R1292	Q2673A – Magenta	HP Color LaserJet 3500 Series, 3550 Series	4,000†	4,000‡
LJ3700*	6R1293	Q2681A – Cyan	HP Color LaserJet 3700 Series	6,000†	6,000‡
LJ3700*	6R1294	Q2682A – Yellow	HP Color LaserJet 3700 Series	6,000†	6,000‡
LJ3700*	6R1295	Q2683A – Magenta	HP Color LaserJet 3700 Series	6,000†	6,000‡
LJ5500/LJ5550*	6R1313	C9730A – Black	HP Color LaserJet 5500 Series, 5550 Series	13,000†	13,000‡
LJ5500/LJ5550*	6R1314	C9731A – Cyan	HP Color LaserJet 5500 Series, 5550 Series	12,000†	12,000‡
LJ5500/LJ5550*	6R1315	C9732A – Yellow	HP Color LaserJet 5500 Series, 5550 Series	12,000†	12,000‡
LJ5500/LJ5550*	6R1316	C9733A – Magenta	HP Color LaserJet 5500 Series, 5550 Series	12,000†	12,000‡
CP4005*	6R1326	CB400A – Black	HP Color Printer 4005 Series	7,500†	7,500‡
CP4005*	6R1327	CB401A – Cyan	HP Color Printer 4005 Series	7,500†	7,500‡
CP4005*	6R1328	CB402A – Yellow	HP Color Printer 4005 Series	7,500†	7,500‡
CP4005*	6R1329	CB403A – Magenta	HP Color Printer 4005 Series	7,500†	7,500‡

*Contains a smart chip to enable smart print functions.

†Yields declared in accordance with ISO/IEC 19752 Standard. ‡Yields declared in accordance with ISO/IEC 19798 Standard.

HP Color Printer replacement toner supplies

Machine Type	Xerox Part Number	Equivalent OEM Part Number	For Use In	OEM Stated Yield	Xerox Stated Yield
LJ4700*	6R1330	Q5950A – Black	HP Color LaserJet 4700 Series	11,000‡	11,000‡
LJ4700*	6R1331	Q5951A – Cyan	HP Color LaserJet 4700 Series	10,000‡	10,000‡
LJ4700*	6R1332	Q5952A – Yellow	HP Color LaserJet 4700 Series	10,000‡	10,000‡
LJ4700*	6R1333	Q5953A – Magenta	HP Color LaserJet 4700 Series	10,000‡	10,000‡
LJ3800/LJ3600 CP3505*	6R1338	Q6470A – Black	HP Color LaserJet 3800 Series, 3600 Series, Color Printer 3505 Series	6,000‡	6,000‡
LJ3600*	6R1339	Q6471A – Cyan	HP Color LaserJet 3600 Series	4,000‡	4,000‡
LJ3600*	6R1340	Q6472A – Yellow	HP Color LaserJet 3600 Series	4,000‡	4,000‡
LJ3600*	6R1341	Q6473A – Magenta	HP Color LaserJet 3600 Series	4,000‡	4,000‡
LJ3800/CP3505*	6R1343	Q7581A – Cyan	HP Color LaserJet 3800 Series, Color Printer 3505 Series	6,000‡	6,000‡
LJ3800/CP3505*	6R1344	Q7582A – Yellow	HP Color LaserJet 3800 Series, Color Printer 3505 Series	6,000‡	6,000‡
LJ3800/CP3505*	6R1345	Q7583A – Magenta	HP Color LaserJet 3800 Series, Color Printer 3505 Series	6,000‡	6,000‡
LJ2600/1600*	6R1410	Q6000A – Black	HP Color LaserJet 2600, 1600 Series, CM1015mfp, CM1017mfp	2,500‡	2,500‡
LJ2600/1600*	6R1411	Q6001A – Cyan	HP Color LaserJet 2600, 1600 Series, CM1015mfp, CM1017mfp	2,000‡	2,000‡
LJ2600/1600*	6R1412	Q6003A – Magenta	HP Color LaserJet 2600, 1600 Series, CM1015mfp, CM1017mfp	2,000‡	2,000‡
LJ2600/1600*	6R1413	Q6002A – Yellow	HP Color LaserJet 2600, 1600 Series, CM1015mfp, CM1017mfp	2,000‡	2,000‡
CP1215*	6R1439	CB540A – Black	HP Color LaserJet CP1201, 1215, 1510, 1515n, CM 1300, 1320 MFP	2,200‡	2,200‡
CP1215*	6R1440	CB541A – Cyan	HP Color LaserJet CP1201, 1215, 1510, 1515n, CM 1300, 1320 MFP	1,400‡	1,400‡
CP1215*	6R1441	CB542A – Yellow	HP Color LaserJet CP1201, 1215, 1510, 1515n, CM 1300, 1320 MFP	1,400‡	1,400‡
CP1215*	6R1442	CB543A – Magenta	HP Color LaserJet CP1201, 1215, 1510, 1515n, CM 1300, 1320 MFP	1,400‡	1,400‡
CP2025*	6R1485	CC530A – Black	HP Color LaserJet CP2025 Series, CM2320 Series	3,500‡	3,500‡
CP2025*	6R1486	CC531A – Cyan	HP Color LaserJet CP2025 Series, CM2320 Series	2,800‡	2,800‡
CP2025*	6R1487	CC533A – Magenta	HP Color LaserJet CP2025 Series, CM2320 Series	2,800‡	2,800‡
CP2025*	6R1488	CC532A – Yellow	HP Color LaserJet CP2025 Series, CM2320 Series	2,800‡	2,800‡

*Contains a smart chip to enable smart print functions.

‡Yields declared in accordance with ISO/IEC 19752 Standard. †Yields declared in accordance with ISO/IEC 19798 Standard.

HP Color Printer replacement toner supplies

Machine Type	Xerox Part Number	Equivalent OEM Part Number	For Use In	OEM Stated Yield	Xerox Stated Yield
CP3525 <small>Coming Soon</small>	106R01583	CE250A-Black	HP Color LaserJet CP3525dn, CP3525n, CP3525x, CM3530mfp, CM3530fs	5000	5000
CP3525 <small>Coming Soon</small>	106R01584	CE251A-Cyan	HP Color LaserJet CP3525dn, CP3525n, CP3525x, CM3530mfp, CM3530fs	7,000	7,000
CP3525 <small>Coming Soon</small>	106R01585	CE252A-Yellow	HP Color LaserJet CP3525dn, CP3525n, CP3525x, CM3530mfp, CM3530fs	7,000	7,000
CP3525 <small>Coming Soon</small>	106R01586	CE253A-Magenta	HP Color LaserJet CP3525dn, CP3525n, CP3525x, CM3530mfp, CM3530fs	7,000	7,000
CP3525 <small>Coming Soon</small>	106R02137	CE250X-Black	HP Color LaserJet CP3525dn, CP3525n, CP3525x, CM3530mfp, CM3530fs	10,500	10,500
CP6015 <small>Coming Soon</small>	106R02138	CB380A-Black	HP Color LaserJet CP6015de, CP6015dn, CP6015x, CP6015xh	16,500	16,500
CP6015 <small>Coming Soon</small>	106R02139	CB381A-Cyan	HP Color LaserJet CP6015de, CP6015dn, CP6015x, CP6015xh, CM6030mfp, CM6030f mfp, 6040mfp, 6040f mfp	21,000	21,000
CP6015 <small>Coming Soon</small>	106R02140	CB382A-Yellow	HP Color LaserJet CP6015de, CP6015dn, CP6015x, CP6015xh, CM6030mfp, CM6030f mfp, 6040mfp, 6040f mfp	21,000	21,000
CP6015 <small>Coming Soon</small>	106R02141	CB383A-Magenta	HP Color LaserJet CP6015de, CP6015dn, CP6015x, CP6015xh, CM6030mfp, CM6030f mfp, 6040mfp, 6040f mfp	21,000	21,000

*Contains a smart chip to enable smart print functions.

†Yields declared in accordance with ISO/IEC 19752 Standard. ‡Yields declared in accordance with ISO/IEC 19798 Standard.

HP Monochrome Printer replacement toner supplies

Machine Type	Xerox Part Number	Equivalent OEM Part Number	For Use In	OEM Stated Yield	Xerox Stated Yield
PX	6R899	HP92274A M2045GA	HP LaserJet 4L, 4ML, 4LC, 4P, 4MP, 4PJ, Apple Personal LaserWriter 300, 320	3,350†	3,600‡
EX	6R903	HP92298A M2473G/A	HP LaserJet 4, 4+, 4M, 4M+, 5, 5M, 5N Apple LaserWriter 16/600, Pro 600, 630	6,800‡	7,300‡
EX Extended Yield	6R904	HP92298X M273G/A	HP LaserJet 4, 4+, 4M, 4M+, 5, 5M, 5N Apple LaserWriter 16/600, Pro 600, 630	8,800‡	9,800‡
VX	6R905	HPC3903A	HP LaserJet 5P, 5MP, 6P, 6MP	4,000‡	4,000‡
WX	6R906	HPC3909A	HP LaserJet 5si, 5siMX/NX, 5si Mopier, LaserJet 8000, HP240	15,000†	16,500‡
AX	6R908	HPC3906A	HP 5L, 6L, 3100, 3150	2,500†	2,500‡

*Contains a smart chip to enable smart print functions.

†Yields declared in accordance with ISO/IEC 19752 Standard. ‡Yields based on 5% toner area coverage.

HP Monochrome Printer replacement toner supplies

Machine Type	Xerox Part Number	Equivalent OEM Part Number	For Use In	OEM Stated Yield	Xerox Stated Yield
62X	6R925	C4129X	HP LaserJet 5000, 5000N, 5000DN, 5000GN, 5100	10,000+	10,000‡
52X	6R926	HPC4127X	HP LaserJet 4000, 4000N, 4000T, 4000TN, 4050, 4050N, 4050T, 4050TN, 4050se	10,000+	10,000‡
22X	6R927	C4092A	HP LaserJet 1100, 1100se, 1100xi, 1100A, 1100A se, 1100A xi, 3200, 3200se	2,500+	2,500‡
32X	6R928	C4096A	HP LaserJet 2100, 2100M, 2100TN, 2100SE, 2100XI, 2200DN, 2200DSE, 2200DT, 2200DTN	5,000+	5,000‡
72X	6R929	C4182X	HP LaserJet 8100, 8100N, 8100DN, 8150, 8150N, 8150DN, 8150HN, 8150MFP	20,000+	20,000‡
LJ1200	6R932	C7115X	HP LaserJet 1000, 1200, 1200N, 1200se, 1220, 1220se, 3300MFP, 3310, 3320MFP, 3320NMFP, 3330MFP	3,500+	3,500‡
LJ4100	6R933	C8061X	HP LaserJet 4100, 4100N, 4100TN, 4100DTN, 4100MFP, 4101MFP	10,000+	10,000‡
LJ4200*	6R934	Q1338A	HP LaserJet 4200, 4200n, 4200tn, 4200dtn, 4200dtns, 4200dtnsl	12,000‡	13,200+
LJ4300/LJ4345mfp*	6R935	Q1339A Q5945A	HP LaserJet 4300, 4300n, 4300tn, 4300dtn, 4300dtns, 4300dtnsl, HP LaserJet 4345mfp, 4345x mfp, 4345xm mfp, 4345xs mfp	18,000‡	19,800+
LJ2300*	6R936	Q2610A	HP LaserJet 2300, 2300d, 2300n, 2300dn, 2300dtn	6,000+	6,600+
LJ1150	6R956	Q2624X	HP LaserJet 1150	4,000+	4,000‡
LJ1300	6R957	Q2613X	HP LaserJet 1300, 1300n	4,000+	4,000‡
LJ9000*	6R958	C8543X	HP LaserJet 9000, 9000n, 9000dn, 9000hns, 9000mfp, 9040mfp, 9050, 9050dn, 9050mfp	30,000+	33,000+
LJ4250/LJ4350*	6R959	Q5942X	HP LaserJet 4250, 4250n, 4250tn, 4250dtn, 4250dtnsl HP LaserJet 4350, 4350n, 4350tn, 4350dtn, 4350dtnsl	20,000+	22,000+
LJ1160/LJ1320/ LJ3390*	6R960	Q5949A	HP LaserJet 1160, 1320 Series, 3390 Series	2,500+	3,500+
LJ2400*	6R961	Q6511X	HP LaserJet 2410, 2420, 2420d, 2420dn, 2430, 2430dtn, 2430n, 2430t, 2430tn	12,000+	12,000+
LJ1320/LJ3390*	6R1320	Q5949X	HP LaserJet 1320 Series, 3390 Series	6,000+	6,000+
LJP2015/LJM2727mfp*	6R1387	Q7553X	HP LaserJet P2015 Series, M2727mfp	7,000+	7,000+
LJP3005/LJM3027mfp/ LJM3035mfp*	6R1388	Q7551X	HP LaserJet P3005 Series, M3027mfp, M3035mfp	13,000+	13,000+
LJ5200*	6R1389	Q7516A	HP LaserJet 5200 Series	12,000+	12,000+
LJ1010	6R1414	Q2612A	HP LaserJet 1010, 1012, 1015, 1018, 1020, 1022 Series, 3015, 3030 Series, 3050, 3052, 3055, M1319f mfp	2,000+	2,000+
LJ1006*	6R1429	CB435A	HP LaserJet P1005, P1006	1,500+	1,500+

*Contains a smart chip to enable smart print functions.

†Yields declared in accordance with ISO/IEC 19752 Standard. ‡Yields based on 5% toner area coverage.

HP Monochrome Printer replacement toner supplies

Machine Type	Xerox Part Number	Equivalent OEM Part Number	For Use In	OEM Stated Yield	Xerox Stated Yield
LJ1505*	6R1430	CB436A	HP LaserJet P1505, P1505n, M1522n, M1522nf	2,000†	2,000†
P4015*	6R1443	CC364A	HP LaserJet P4014n, 4015 Series, 4515 Series	10,000†	10,000†
P4015 <small>Coming Soon</small>	6R1444	CC364X	HP LaserJet P4015n, P4015dn, P4015tn, P4015x, P4515n, P4515x	24,000	24,000
P2035/P2055*	6R1489	CE505A	HP LaserJet P2035 Series, P2055 Series	2,300‡	2,300‡
P2055*	6R1490	CE505X	HP LaserJet P2055 Series	6,500‡	6,500‡
P3015 <small>Coming Soon</small>	106R01621	CE255A	HP LaserJet P3015d, P3015dn, P3015n, P3015x	6,000	6,000
P3015 <small>Coming Soon</small>	106R01622	CE255X	HP LaserJet P3015d, P3015dn, P3015x	12,500	12,500

*Contains a smart chip to enable smart print functions.

†Yields declared in accordance with ISO/IEC 19752 Standard. ‡Yields based on 5% toner area coverage.

Lexmark Monochrome Printer replacement cartridges

Machine Type	Xerox Part Number	Equivalent OEM Part Number/ Lexmark Return Program Number	For Use In	OEM Stated Yield	Xerox Stated Yield
E230, E232, E234, E240, E330, E340, E332, E342	106R01549	24035SA/24015SA	Lexmark Laser Printer E230, E232, E234, E240, E330, E340, E332, E342	2,500	2,500‡
E450	106R01550	E450A21A/E450A11A	Lexmark Laser Printer E450	6,000	6,000‡
E450	106R01551	E450H21A/EA450H11A	Lexmark Laser Printer E450	11,000	11,000‡
E250, E350, E352	106R01552	E250A21A/E250A11A	Lexmark Laser Printer E250, E350, E352	3,500	3,500‡
E350, E352	106R01553	E352H21A/E352H11A	Lexmark Laser Printer E350, E352	9,000	9,000‡
T420	106R01554	12A7315/12A7415	Lexmark Laser Printer T420	10,000	10,000‡
T520, T522 <small>Coming Soon</small>	106R01555	12A6735/12A6835	Lexmark Laser Printer T520, T522	20,000	20,000‡
T620, T622	106R01556	12A6765/12A6865	Lexmark Laser Printer T620, T622	30,000	30,000‡
T630, T632, T634	106R01557	12A7362/12A7462	Lexmark Laser Printer T630, T632, T634	21,000	21,000‡

Note: All cartridges contain a smart chip to enable smart print functions.

†Yields declared in accordance with ISO/IEC 19752 Standard. ‡Yields based on 5% toner area coverage.

Lexmark Monochrome Printer replacement cartridges

Machine Type	Xerox Part Number	Equivalent OEM Part Number/ Lexmark Return Program Number	For Use In	OEM Stated Yield	Xerox Stated Yield
T632, T634	106R01558	12A7365/12A7465	Lexmark Laser Printer T632, T634	32,000	32,000†
T644	106R01559	64435XA/64415XA	Lexmark Laser Printer T644	32,000	32,000†
E120	106R01560	12035SA/12015SA	Lexmark Laser Printer E120	2,000	2,000†
T430	106R01561	12A8325/12A8425	Lexmark Laser Printer T430	12,000	12,000†
T640, T642, T644	106R01562	64035HA/64015HA	Lexmark Laser Printer T640, T642, T644	21,000	21,000†
T610, T614, T616 <small>Coming Soon</small>	106R02135	12A5740/12A5840	Lexmark Laser Printer Optra T610, T614, T616	10,000	10,000
T610, T614, T616 <small>Coming Soon</small>	106R02136	12A5745/12A5845	Lexmark Laser Printer Optra T610, T614, T616	25,000	25,000

Note: All cartridges contain a smart chip to enable smart print functions.

†Yields declared in accordance with ISO/IEC 19752 Standard. ‡Yields based on 5% toner area coverage.

Brother Monochrome Laser Printer replacement toner and drum cartridges

Machine Type	Xerox Part Number	Equivalent OEM Part Number	For Use In	OEM Stated Yield	Xerox Stated Yield
HL-2040	6R1415	TN350	Fax-2820/Fax-2910/Fax-2920/HL-2040/	2,500	2,500
	6R1416	DR350	HL-2070N/DCP-7020/MFC-7220/MFC-7225N/ MFC-7420/MFC-7820N	12,000	12,000
HL-5250	6R1417	TN550	DCP-8060/DCP-8065/DCP-8065DN/HL-5240/	3,500	3,500
	6R1418	TN580	HL-5250DN/HL-5250DNT/HL-5280DW/MFC-8460N/	7,000	7,000
	6R1419	DR520	MFC-8660DN/MFC-8670/MFC-8860DN/MFC-8870DW	25,000	25,000
HL-1240	6R1420	TN430	DCP-1200/DCP-1400/Fax-4100/Fax-4100e/Fax-4750/	3,000	3,000
	6R1421	TN460	Fax-4750e/Fax-5750/Fax-5750e/HL-1200/HL-1230/	6,000	6,000
	6R1422	DR400	HL-1240/HL-1250/HL-1270/HL-1435/HL-1440/ HL-1450/HL-1470N/MFC-1260/MFC-8300/MFC-8500/MFC- 8600/MFC-8700/MFC-9600/MFC-9700/MFC-9800	20,000	20,000
HL-5140	6R1423	TN540	DCP-8040/DCP-8045D/HL-5100/HL-5140/HL-5150/	3,500	3,500
	6R1424	TN570	HL-5150D/HL-5150DLT/HL-5170DN/HL-5170DNL/	6,700	6,700
	6R1425	DR510	MFC-8120/MFC-8220/MFC-8440/MFC-8640D/ MFC-8840/MFC-8840D/MFC-8840DN	20,000	20,000

Replacement cartridges from Xerox

OEM Quality. No compromise.

We invented laser printing and we invented the cartridge. We know color xerographic technology. Put Xerox knowledge and experience into your HP, Brother or Lexmark printer. You can get OEM quality, yield and reliability for less money. It's what your documents deserve.

Save money sustainably. No hassle.

Our replacement cartridges re-use plastic hulks that still have productive life left—that is better for the environment and for your wallet. Although over 90% of cartridge parts are re-used, crucial xerographic components are replaced to ensure top quality. We know how to give you the most value for your money, while reclaiming a cartridge that still has usable life. It's only right.

Total Satisfaction Guarantee. No risk. No worries.

At Xerox, we are as satisfied as you are. If you have any doubts at all about your Xerox® replacement cartridge, our Total Satisfaction Guarantee is your answer. We will replace any cartridge that you are dissatisfied with and in the event that a cartridge should damage your printer, Xerox will pay to have the machine brought back to OEM standard performance. It's a smart choice.



For more information and the latest additions to our product line,
be sure to visit www.xerox.com/replacementcartridges



©2011 Xerox Corporation. All rights reserved. XEROX® and XEROX and Design® are trademarks of Xerox Corporation in the United States and/or other countries. "HP" is a registered trademark of Hewlett-Packard. BROTHER is a registered trademark of Brother Industries, Ltd. Japan in the U.S. and many other countries. Lexmark is a trademark of Lexmark International, Inc. registered in the United States and/or other countries. 02/11 0-184