

Micron 5100 Firmware Update – Version D0MU071 / D0MU441 / D0MU841

PCN: 33378

Published: 2019-07-30

Туре:	Firmware Revision			
·	Changes and improvements made in firmware D0MU071 / D0MU441 / D0MU841 over previous firmware D0MU051 / D0MU417 / D0MU817 are: • Improved asynchronous power-loss handling • General error handling and stability improvements • Write performance stability improvements • Enhanced background media scan and wear-leveling algorithms • Drive hang fix for corner conditions Updating directly from all older revisions is supported.			
	Improved Product Quality and Reliab			
Product Affected:	Micron 5100 SSD			
Affected Micron Part Number	Recommended Replace	ement	Customer Part Number	
Component				
MTFDDAK1T9TBY-1AR16ABYY				
MTFDDAK1T9TBY-1AR1ZABYY				
MTFDDAK1T9TCB-1AR16ABYY				
MTFDDAK1T9TCB-1AR1ZABYY				
MTFDDAK1T9TCC-1AR16ABYY				
MTFDDAK1T9TCC-1AR1ZABYY				
MTFDDAK240TCB-1AR16ABYY				
MTFDDAK240TCB-1AR1ZABYY			557-1807-ND	
MTFDDAK240TCC-1AR16ABYY				
MTFDDAK240TCC-1AR1ZABYY				
MTFDDAK3T8TBY-1AR16ABYY				
MTFDDAK3T8TBY-1AR1ZABYY				
MTFDDAK3T8TCB-1AR16ABYY				
MTFDDAK3T8TCB-1AR1ZABYY				
MTFDDAK480TBY-1AR16ABYY				
MTFDDAK480TBY-1AR1ZABYY				
MTFDDAK480TCB-1AR16ABYY				
MTFDDAK480TCB-1AR1ZABYY			557-1810-ND	
MTFDDAK480TCC-1AR16ABYY				
MTFDDAK480TCC-1AR1ZABYY				
MTFDDAK7T6TBY-1AR16ABYY				
MTFDDAK7T6TBY-1AR1ZABYY				
MTFDDAK960TBY-1AR16ABYY				
MTFDDAK960TBY-1AR1ZABYY				
MTFDDAK960TCB-1AR16ABYY				
MTFDDAK960TCB-1AR1ZABYY				
MTFDDAK960TCC-1AR16ABYY				
MTFDDAK960TCC-1AR1ZABYY				
MTFDDAV1T9TBY-1AR16ABYY				
MTFDDAV1T9TBY-1AR1ZABYY				

Micron Sites Affected:	Firmware revision can be identified on the product label All Sites							
Method of Identification:	Firmware revisi	ion can be identified on the	product label					
*Materials that have been ordered are in bold .								
MTFDDAV960TCB-1AR1ZABYY								
MTFDDAV960TCB-1AR16ABYY								
MTFDDAV960TBY-1AR1ZABYY								
MTFDDAV960TBY-1AR16ABYY								
MTFDDAV480TCB-1AR1ZABYY								
MTFDDAV480TBY-1AR1ZABYY MTFDDAV480TCB-1AR16ABYY								
MTFDDAV480TBY-1AR16ABYY								
MTFDDAV240TCB-1AR1ZABYY				557-1814-ND				
MTFDDAV240TCB-1AR16ABYY								
MTFDDAV1T9TCB-1AR1ZABYY								
MTFDDAV1T9TCB-1AR16ABYY								

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Attachments