

OWNER: AVIATIS LLC
ADDRESS: PO BOX 107
 MOSCOW REGION 141426
PHONE:
FAX:

OPERATOR: AVIATIS LLC
ADDRESS: PO BOX 107
 MOSCOW REGION 141426
PHONE:
FAX:

ANALYST: AYMEN TOHAMI BAKHIT +33-1.55.93.45.86 (DIRECT)
EMAIL: AYMEN.TOHAMI.BAKHIT@CAMPSYSTEMS. +33 (0) 1.55.93.45.80 (OFFICE)
 EU WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 20317/RA-67250 **MODEL:** CH 300 **MANUFACTURER:** BOMBARDIER INCORPORATED

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE:	28-JAN-2011	2765:48 A/C HRS	as of 27-JUL-2020	_____ A/C HRS	as of ____/____/____
INSERVICE DATE:	03-NOV-2011	1553 AFL	as of 27-JUL-2020	_____ AFL	as of ____/____/____
		3781:55 APH	as of 27-JUL-2020	_____ APH	as of ____/____/____

APU SERIAL/PART: P-430/3800774-1 **MODEL:** GTCP36-150(BD) **MANUFACTURER:** HONEYWELL

INSTALLED ON 06-APR-2018		LAST ACTUALS		CURRENT ACTUAL	
2692:15 APU HRS		3781:55 APU HRS	as of 27-JUL-2020	_____ APU HRS	as of ____/____/____
0 APUS		0 APUS	as of 10-JUL-2020	_____ APUS	as of ____/____/____

ENGINE NO. 1 SERIAL/PART: P118773/3030001-4 **MODEL:** AS907-1-1A **MANUFACTURER:** HONEYWELL

INSTALLED ON 12-JAN-2011		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	2777:21 ENG. HRS	as of 27-JUL-2020	_____ ENG. HRS	as of ____/____/____
0 ENC		1564 ENC	as of 27-JUL-2020	_____ ENC	as of ____/____/____

ENGINE NO. 2 SERIAL/PART: P118771/3030001-4 **MODEL:** AS907-1-1A **MANUFACTURER:** HONEYWELL

INSTALLED ON 12-JAN-2011		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	2777:21 ENG. HRS	as of 27-JUL-2020	_____ ENG. HRS	as of ____/____/____
0 ENC		1563 ENC	as of 27-JUL-2020	_____ ENC	as of ____/____/____



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS							
05C012	12 MONTH TASKS							
+	TRACKED ITEM							
	PKG 1	MOS	12	+1m/-1m	-16	23-DEC-2019 2630:03 1481	07-DEC-2020	07-JAN-2021
	REF: AMM GENERIC	HRS/MSC AFL						
05C024	24 MONTH TASKS							
+	PKG 2	MOS	24	+1m/-1m	-50	23-DEC-2019 2630:03 1481	03-NOV-2021	03-DEC-2021
	REF: AMM GENERIC	HRS/MSC AFL						
05C036	36 MONTH TASKS							
	PKG 3	MOS	36	+1m/-1m	-34	07-DEC-2017 1913:50 1121	03-NOV-2020	03-DEC-2020
	REF: AMM GENERIC	HRS/MSC AFL						
05C048	48 MONTH TASKS							
+	PKG 4	MOS	48	+1m/-1m	-50	23-DEC-2019 2630:03 1481	03-NOV-2023	03-DEC-2023
	REF: AMM GENERIC	HRS/MSC AFL						
05C096	96 MONTH TASKS							
+	PKG 5	MOS	96	+1m/-1m	-50	23-DEC-2019 2630:03 1481	03-NOV-2027	03-DEC-2027
	REF: AMM GENERIC	HRS/MSC AFL						



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05C192	192 MONTH TASKS							
+								
	PKG 6	MOS	192			03-NOV-2011	03-NOV-2027	03-DEC-2027
	REF: AMM GENERIC	HRS/MSC AFL						
05H0400	400 HOUR TASKS							
+								
	PKG 7	MOS	400		6:18	23-DEC-2019 2630:03 1481	3036:21	3076:21
	REF: AMM GENERIC	HRS/MSC AFL						
05H0600	600 HOUR TASKS							
	PKG 8	MOS	600			23-DEC-2019 2630:03 1481	3230:03	3270:03
	REF: AMM GENERIC	HRS/MSC AFL						
05H0800	800 HOUR TASKS							
+								
	PKG 9	MOS	800			06-DEC-2018 2236:21 1275	3036:21	3076:21
	REF: AMM GENERIC	HRS/MSC AFL						
05H1200	1200 HOUR TASKS							
	PKG 10	MOS	1200			06-DEC-2018 2236:21 1275	3436:21	3476:21
	REF: AMM GENERIC	HRS/MSC AFL						



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05H1600	1600 HOUR TASKS							
+	PKG 11	MOS				20-MAY-2016		
	REF: AMM GENERIC	HRS/MSC AFL	1600 +40/-40		18:13	1581:47 936	3200	3240
05H2400	2400 HOUR TASKS							
+	PKG 12	MOS				06-DEC-2018		
	REF: AMM GENERIC	HRS/MSC AFL	2400 +40/-40			2236:21 1275	4636:21	4676:21
05H3200	3200 HOUR TASKS							
+	PKG 13	MOS				28-JAN-2011		
	REF: AMM GENERIC	HRS/MSC AFL	3200 +40/-40			0 0	3200	3240
05H4200	4200 HOUR TASKS							
	PKG 14	MOS				(EFF)		
	REF: AMM GENERIC	HRS/MSC AFL	4200 +40/-40				4200	4240
05H9600	9600 HOUR TASKS							
+	PKG 15	MOS				28-JAN-2011		
	REF: AMM GENERIC	HRS/MSC AFL	9600 +40/-40			0 0	9600	9640

APU Model : GTCP36-150(BD) Serial # P-430 Part # 3800774-1



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05A0800	APU - 800 HOUR APU CHECK							
	PKG 18	MOS				23-DEC-2019		
	REF:	HRS/MSC	600	+40/-40	39:15	3569	4208:15	4248:15
		APUS						
05A1200	APU - *** 1600 HOUR APU CHECK ***							
	PKG 19	MOS				06-DEC-2018		
	REF:	HRS/MSC	1200	+40/-40		3008:15	4208:15	4248:15
		APUS						
05A2400	APU - 2400 HOUR APU CHECK							
	PKG 20	MOS				23-DEC-2019		
	REF:	HRS/MSC	2400	+40/-40		3569	5969	6009
		APUS						

ENGINE NO. 1 Model : AS907 Serial # P118773 Part # 3030001-4

05EH4800	NO. 1 ENGINE - 4800 ENG HOUR TASKS							
	PKG 17	MOS		+40/-40				
	REF: See Workcard	HRS/MSC	4800	+40/-40		0	(4800) 4788:27	4840
		ENC						

ENGINE NO. 2 Model : AS907 Serial # P118771 Part # 3030001-4

05EH4800	NO. 2 ENGINE - 4800 ENG HOUR TASKS							
	PKG 17	MOS		+40/-40				
	REF: See Workcard	HRS/MSC	4800	+40/-40		0	(4800) 4788:27	4840
		ENC						

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
00-IJM-001	RENEW RADIO STATION LICENSE	MOS						31-MAY-2025	M
CUSTOMER CODE	REF:	HRS/MSC	DUE						
		AFL							
ARC-FULL	PERFORM FULL AIRWORTHINESS REVIEW TRACKED ITEM	MOS	24				26-FEB-2019	26-FEB-2021	
AIRWORTHINESS	REF:	HRS/MSC							
		AFL							
ARC-IJM	PERFORM EXTENSION OF THE AIRWORTHINESS REVIEW CERTIFICATE TRACKED ITEM	MOS	12				26-FEB-2020	26-FEB-2021	
AIRWORTHINESS	REF:	HRS/MSC							
		AFL							
C300-141031	REVIEW CH300 TLMC R11 AND MPD R08 DATED OCT 31/2014	MOS					28-JAN-2011		
REQUIREMENT CHANGE FORMS	REF: RCF C300	HRS/MSC	-				0		
		AFL					0		
C300-150205	REVIEW CH300 TLMC R12 AND MPD R09 DATED FEB 05/2015	MOS					26-MAR-2015		
REQUIREMENT CHANGE FORMS	REF: RCF C300	HRS/MSC	-						
		AFL							
C300-150217	REVIEW CH300 MPD TR-175 AND TR-176 DATED FEB 17/2015	MOS					26-MAR-2015		
REQUIREMENT CHANGE FORMS	REF: RCF C300	HRS/MSC	-						
		AFL							



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C300-150317	REVIEW CH300 TLMC TR 5-2-74; MPD TR-177 AND TR-178 DATED MAR 17/2015	MOS						26-MAR-2015	
REQUIREMENT CHANGE FORMS	REF: RCF C300	HRS/MSC - AFL							
C300-150630	REVIEW BOMBARDIER CH300 TLMC REV 13	MOS						07-SEP-2015	
REQUIREMENT CHANGE FORMS	REF: RCF C300	HRS/MSC - AFL							
C300-150928	REVIEW CH300 TLMC R14 AND MPD R11 DATED SEP 28/2015	MOS						30-OCT-2015	
REQUIREMENT CHANGE FORMS	REF: RCF C300	HRS/MSC - AFL							
C300-151022	REVIEW BOMBARDIER TLMC TRS 5-2-75; 5-2-76; 5-2-77 AND MPD TRS 179; 180; 181; 182; 183; 184; 185; 186; 187; 188; 189; 190; 191 DATE: OCT 22/2015	MOS						22-DEC-2015	
REQUIREMENT CHANGE FORMS	REF: RCF C300	HRS/MSC - AFL							
C300-151222	REVIEW BOMBARDIER CH300 TLMC REV 15 AND MPD REV 12 DATE: DEC 22/2015	MOS						25-JAN-2016	
REQUIREMENT CHANGE FORMS	REF: RCF 00	HRS/MSC - AFL							
C300-160920	REVIEW TLMC REV 16 DATED 20-SEPTEMBER-2016	MOS						08-NOV-2016	
REQUIREMENT CHANGE FORMS	REF: RCF 00	HRS/MSC - AFL							



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C300-160921	REVIEW CHALLENGER 300 - TLMC - TR 5-2-78, TR 5-2-79 & TR 5-2-80 ISSUED SEP 21/ 2016	MOS						08-NOV-2016	
REQUIREMENT CHANGE FORMS	REF: RCF 00	HRS/MSC - AFL							
C300-161215	REVIEW TLMC REV 17 DATED 15-DEC-2016	MOS						10-JAN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF 00	HRS/MSC - AFL							
C300-170217	REVIEW TLMC - TR 5-2-85 AND TR 5-2-86 DATED 17-FEB-2017	MOS						17-MAR-2017	
REQUIREMENT CHANGE FORMS	REF: RCF 00	HRS/MSC - AFL							
C300-170703 TR 5-2-87	REVIEW CH300 TLMC TR 5-2-87 DATED JUL 03/2017	MOS						21-JUL-2017	
REQUIREMENT CHANGE FORMS	REF: RCF 00	HRS/MSC - AFL						1802:57 1057	
C300-170703-MPD	REVIEW MPD REV 15 DATED JUL 03/2017	MOS						21-JUL-2017	
REQUIREMENT CHANGE FORMS	REF: RCF 00	HRS/MSC - AFL						1802:57 1057	
+ C300-170703-TLMC	REVIEW TLMC REV 18 DATED JUL 03/2017	MOS						21-JUL-2017	
REQUIREMENT CHANGE FORMS	REF: RCF 00	HRS/MSC - AFL						1802:57 1057	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C300-171218	REVIEW TIME LIMITS/MAINTENANCE CHECKS	REV 19						30-MAR-2018	
REQUIREMENT CHANGE FORMS	REF: RCF 00	MOS HRS/MSC - AFL							
C300-181101-TLMC	REVIEW TLMC - TR 5-2-88, TR 5-2-89 - DATED NOV 01/2018							20-NOV-2018	
REQUIREMENT CHANGE FORMS	REF: RCF 00	MOS HRS/MSC - AFL							
C300-190411-TLMC	REVIEW TLMC TR 5-2-90 DATED APRIL 11/2019							24-APR-2019	
REQUIREMENT CHANGE FORMS	REF: RCF 00	MOS HRS/MSC - AFL							
C300-200115 (TLMC)	REVIEW TIME LIMITS / MAINTENANCE CHECKS, CHALLENGER 300 (TLMC) REVISION 20,DATED. JAN. 15TH, 2020							03-MAR-2020	
REQUIREMENT CHANGE FORMS	REF: RCF 00	MOS HRS/MSC - AFL							
C300-200115-MPD	REVIEW MAINTENANCE PLANNING DOCUMENT REVISION 18, DATED JAN 15/2020							03-MAR-2020	
REQUIREMENT CHANGE FORMS	REF: RCF C300	MOS HRS/MSC - AFL							
C300-200115-MRIP-MRBR	REVIEW AIRCRAFT ANNUAL UTILIZATION (HOURS) AND SELECT PROGRAM (MRIP OR MRBR) PER TLMC REV 20 AND MPD REV 18							10-APR-2020	
REQUIREMENT CHANGE FORMS	REF: RCF C300-200115-MRIP-MRBR	MOS HRS/MSC - AFL							



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C300-200116-TLMC-TR	REVIEW TIME LIMITS / MAINTENANCE CHECKS - TEMPORARY REVISIONS DATED JAN 16/2020								
		MOS						03-MAR-2020	
REQUIREMENT CHANGE FORMS	REF: RCF C300	HRS/MSC - AFL							
APU Model : GTCP36-150(BD) Serial # P-430 Part # 3800774-1									
A300-151218	APU - REVIEW 36-150[BD] CMM REVISION 4								
		MOS						06-SEP-2016	
REQUIREMENT CHANGE FORMS	REF: RCF A300	HRS/MSC - APUS							
A300-161102	APU - REVIEW GTCP36-150(BD) SIL APU-56 REV 2								
		MOS						10-JAN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF A300	HRS/MSC - APUS							
A300-170410	APU - REVIEW HONEYWELL GTCP36-150(BD) CMM REV 5								
		MOS						10-MAY-2017 2408:20	
REQUIREMENT CHANGE FORMS	REF: RCF A300	HRS/MSC - APUS							
A300-180112	APU - REVIEW HONEYWELL GTCP 36-150(BD) APU-49 SIL REV 10								
		MOS						(EBT)	
REQUIREMENT CHANGE FORMS	REF: RCF APU-SIL-49	HRS/MSC - APUS							
ENGINE NO. 1 Model : AS907-1-1A Serial # P118773 Part # 3030001-4									
E300-151007	NO. 1 ENGINE - REVIEW HONEYWELL AS907 LMM REV31, DATED 30-JUL-2015								
		MOS						22-OCT-2015	
REQUIREMENT CHANGE FORMS	REF: RCF E300	HRS/MSC - ENC							

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E300-160525	NO. 1 ENGINE - REVIEW HONEYWELL AS907 LMM, REV. 32, DATED 25 MAY 16	MOS						06-JUL-2016	
REQUIREMENT CHANGE FORMS	REF: RCF E300	HRS/MSC - ENC							
E300-180209	NO. 1 ENGINE - REVIEW HONEYWELL AS907 LMM REV 33	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E300	HRS/MSC - ENC							
E300-190308	NO. 1 ENGINE - REVIEW HONEYWELL AS907 LMM REV 34	MOS					13-MAY-2019		
REQUIREMENT CHANGE FORMS	REF: RCF E300	HRS/MSC - ENC							
E300-200115	NO. 1 ENGINE - REVIEW HONEYWELL AS907 LMM REV 35	MOS					03-MAR-2020		
REQUIREMENT CHANGE FORMS	REF: RCF E300	HRS/MSC - ENC							
E300-200707	NO. 1 ENGINE - REVIEW HONEYWELL AS907 LMM REV 36	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E300	HRS/MSC - ENC							
	NEW REQUIREMENT ADDED ON 22-JUL-2020 (EFFECTIVE: 07-JUL-2020). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								
ENGINE NO. 2 Model : AS907-1-1A Serial # P118771 Part # 3030001-4									
E300-151007	NO. 2 ENGINE - REVIEW HONEYWELL AS907 LMM REV31, DATED 30-JUL-2015	MOS						22-OCT-2015	
REQUIREMENT CHANGE FORMS	REF: RCF E300	HRS/MSC - ENC							



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
E300-160525	NO. 2 ENGINE - REVIEW HONEYWELL AS907 LMM, REV. 32, DATED 25 MAY 16	MOS						06-JUL-2016	
REQUIREMENT CHANGE FORMS	REF: RCF E300	HRS/MSC - ENC							
E300-180209	NO. 2 ENGINE - REVIEW HONEYWELL AS907 LMM REV 33	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E300	HRS/MSC - ENC							
E300-190308	NO. 2 ENGINE - REVIEW HONEYWELL AS907 LMM REV 34	MOS					24-APR-2019		
REQUIREMENT CHANGE FORMS	REF: RCF E300	HRS/MSC - ENC							
E300-200115	NO. 2 ENGINE - REVIEW HONEYWELL AS907 LMM REV 35	MOS					03-MAR-2020		
REQUIREMENT CHANGE FORMS	REF: RCF E300	HRS/MSC - ENC							
E300-200707	NO. 2 ENGINE - REVIEW HONEYWELL AS907 LMM REV 36	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E300	HRS/MSC - ENC							
	NEW REQUIREMENT ADDED ON 22-JUL-2020 (EFFECTIVE: 07-JUL-2020). REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								

CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS

05-51-01-210-801	GENERAL VISUAL INSPECTION AFTER AN OVERWEIGHT LANDING	MOS					28-JAN-2011		
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 01 210 801	HRS/MSC A/R AFL					0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-51-05-210-801	GENERAL VISUAL INSPECTION	AFTER A HARD LANDING							
		MOS					28-JAN-2011		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 05 210 801	AFL					0		
05-51-09-210-801	GENERAL VISUAL INSPECTION	AFTER EXTREME TURBULENCE/MANEUVER							
		MOS					28-JAN-2011		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 09 210 801	AFL					0		
05-51-13-210-801	GENERAL VISUAL INSPECTION	AFTER LIGHTNING STRIKE							
		MOS					28-JAN-2011		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 13 210 801	AFL					0		
05-51-15-210-801	GENERAL VISUAL INSPECTION	AFTER RUDDER CONTROL-SYSTEM MALFUNCTION							
		MOS					28-JAN-2011		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 15 210 801	AFL					0		
05-51-17-210-801	GENERAL VISUAL INSPECTION	OF THE FLAPS AND THE LANDING GEAR AFTER OVERSPEED CONDITION							
		MOS					28-JAN-2011		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 17 210 801	AFL					0		
05-51-19-210-801	GENERAL VISUAL INSPECTION	AFTER BLEED AIR LEAK							
		MOS					28-JAN-2011		
		HRS/MSC	A/R				0		
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 19 210 801	AFL					0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-51-20-210-801	GENERAL VISUAL INSPECTION FOR HIGH ENERGY STOP/REJECTED TAKEOFF (RTO) DAMAGE	MOS						28-JAN-2011	
	REF: AMM 05 51 20 210 801	HRS/MSC	A/R					0	
		AFL						0	
05-51-21-210-801	GENERAL VISUAL INSPECTION AFTER TIRE BURST ON THE NLG	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 21 210 801	HRS/MSC	A/R					0	
		AFL						0	
05-51-21-210-802	GENERAL VISUAL INSPECTION AFTER A TIRE BURST ON THE MAIN LANDING GEAR (MLG)	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 21 210 802	HRS/MSC	A/R					0	
		AFL						0	
05-51-21-210-803	GENERAL VISUAL INSPECTION AFTER A TIRE DEFLATES	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 21 210 803	HRS/MSC	A/R					0	
		AFL						0	
05-51-23-210-801	GENERAL VISUAL INSPECTION AFTER NOSE LANDING GEAR (NLG) EXCEEDS TOW LIMITS	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 23 210 801	HRS/MSC	A/R					0	
		AFL						0	
05-51-24-280-801	SPECIAL DETAILED INSPECTION OF THE LANDING GEAR AFTER ALTERNATE SERVICING	MOS						28-JAN-2011	
	REF: AMM 05 51 24 280 801	HRS/MSC	A/R					0	
		AFL						0	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-51-25-210-801	GENERAL VISUAL INSPECTION OF THE WING LEADING-EDGE AFTER AN OVERHEAT CONDITION	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 25 210 801	HRS/MSC	A/R				0		
		AFL					0		
05-51-29-210-801	GENERAL VISUAL INSPECTION OF THE ENGINE DRIVEN PUMP (EDP) AFTER DRY OPERATION	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 29 210 801	HRS/MSC	A/R				0		
		AFL					0		
05-51-33-281-801	CHECK (ACIDITY) OF THE HYDRAULIC FLUID AFTER SYSTEM OVERHEAT	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 33 281 801	HRS/MSC	A/R				0		
		AFL					0		
05-51-37-210-801	CHECK FUEL CONTAMINATION	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 37 210 801	HRS/MSC	A/R				0		
		AFL					0		
05-51-39-220-801	DETAILED INSPECTION OF THE AFT EQUIPMENT AFTER A FUEL OR HYDRAULIC SPILL OR LEAK	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 39 220 801	HRS/MSC	A/R				0		
		AFL					0		
05-51-39-220-802	DETAILED INSPECTION AFTER A HYDRAULIC FLUID SPILL OR LEAK	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 39 220 802	HRS/MSC	A/R				0		
		AFL					0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-51-41-210-801	GENERAL VISUAL INSPECTION OF THE PITOT-STATIC VISUAL DRAIN AFTER ADVERSE WEATHER OPERATIONS	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 41 210 801	HRS/MSC	A/R				0		
		AFL					0		
05-51-43-210-801	INSPECTION AFTER THE AIRCRAFT IS PARKED IN STRONG WINDS OR WINDGUSTS	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 43 210 801	HRS/MSC	A/R				0		
		AFL					0		
05-51-43-210-802	INSPECTION AFTER THE AIRCRAFT IS TAXIED IN STRONG WINDS OR WINDGUSTS	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 43 210 802	HRS/MSC	A/R				0		
		AFL					0		
05-51-43-220-801	DETAILED INSPECTION AFTER LAVATORY OR OTHER FIELD LEAKS	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: See Workcard	HRS/MSC	A/R				0		
		AFL					0		
05-51-45-210-801	GENERAL VISUAL INSPECTION AFTER BIRD STRIKE	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 51 45 210 801	HRS/MSC	A/R				0		
		AFL					0		
05-52-01-220-801	DETAILED INSPECTION ENGINE AFTER A COMPRESSOR STALL	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 52 01 220 801	HRS/MSC	A/R				0		
		AFL					0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-52-03-280-801	SPECIAL DETAILED INSPECTION OF THE ENGINE AFTER A HOT ENGINE SHUTDOWN	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 52 03 280 801	HRS/MSC	A/R					0	
		AFL						0	
05-52-05-220-801	DETAILED INSPECTION OF THE ENGINE AFTER LIGHTNING STRIKE	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 52 05 220 801	HRS/MSC	A/R					0	
		AFL						0	
05-52-09-220-801	DETAILED INSPECTION OF THE ENGINE AFTER INGESTION OF VOLCANIC ASH	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 52 09 220 801	HRS/MSC	A/R					0	
		AFL						0	
05-52-13-220-801	DETAILED INSPECTION OF THE ENGINE AFTER BIRD STRIKE	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 52 13 220 801	HRS/MSC	A/R					0	
		AFL						0	
05-52-17-220-801	DETAILED INSPECTION OF THE ENGINE OPERATED AT VIBRATION LEVELS MORE THAN THE ALLOWABLE LIMITS	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 52 17 220 801	HRS/MSC	A/R					0	
		AFL						0	
05-52-17-220-802	DETAILED INSPECTION OF THE ENGINE AFTER A COMPRESSOR VARIABLE GEOMETRY (CVG) SYSTEM MALFUNCTION OR A COMPRESSOR STALL	MOS						28-JAN-2011	
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 52 17 220 802	HRS/MSC	A/R					0	
		AFL						0	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
05-52-21-220-801	DETAILED INSPECTION OF THE ENGINE AFTER SHEDDING/INGESTION OF ICE	MOS					28-JAN-2011		
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 52 21 220 801	HRS/MSC AFL	A/R				0 0		
05-52-25-220-801	DETAILED INSPECTION OF THE ENGINE AFTER IN-FLIGHT SHUTDOWN	MOS					28-JAN-2011		
UNSCHEDULED MAINTENANCE CHECK	REF: AMM 05 52 25 220 801	HRS/MSC AFL	A/R				0 0		
05-CUS-01	UPDATE JAPPESEN ELECTRONIC CHARTS	DAYS	14				10-JUL-2020	29-JUL-2020 M	
	REF:	HRS/MSC AFL					2738:37 1539		
05-CUS-02	WALKAROUND INSPECTION	DAYS	30	+15			28-JUN-2020	28-JUL-2020	12-AUG-2020
	REF:	HRS/MSC AFL					2723:48 1530		
CHAPTER 08	LEVELING AND WEIGHING								
080000	PERFORM AIRCRAFT WEIGHING	MOS	48				19-JAN-2017	19-JAN-2021	
EUROPEAN OPS REQ	REF:	HRS/MSC AFL					1703:13 1002		
CHAPTER 11	PLACARDS AND MARKINGS								
+ 11-30-30-601 (s)	GENERAL VISUAL INSPECTION CABIN PLACARDS - INTERNAL						PKG		
	PKG 1	MOS	12	+1m/-1m			23-DEC-2019		
STLMC	REF:	HRS/MSC AFL					2630:03 1481		
CHAPTER 21	AIR CONDITIONING								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-00-00-106 (s)	OPERATIONAL TEST OF THE PACK BULKHEAD CHECK VALVE PKG 12	MOS HRS/MSC	2400	+40/-40		40	PKG 06-DEC-2018 2236:21 1275		
	REF: AMM 21 21 01 710 801	AFL							
21-23-05-301 (s)	OPERATIONAL TEST AVIONICS COOLING FAN PKG 4	MOS HRS/MSC	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 21 23 05 710 803	AFL							
21-30-00-301 (s)	FUNCTIONAL TEST CABIN-PRESSURE LEAKAGE RATE PKG 5	MOS HRS/MSC	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 21 31 00 720 801	AFL							
21-30-00-302 (s)	DETAILED INSPECTION DITCHING FLAPPER VALVE PKG 10	MOS HRS/MSC	1200	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 21 31 07 220 801	AFL							
21-31-00-201 (s)	OPERATIONAL TEST MANUAL MODE OF THE PRESSURIZATION SYSTEM PKG 11	MOS HRS/MSC	1600	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 21 31 00 710 804	AFL							
21-31-00-302 (s)	OPERATIONAL TEST EMERGENCY DEPRESSURIZATION FUNCTION PKG 10	MOS HRS/MSC	1200	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 21 31 00 710 802	AFL							
21-31-00-303 (s)	OPERATIONAL TEST DITCHING FUNCTION PKG 12	MOS HRS/MSC	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 21 31 00 710 803	AFL							



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-31-05-101	DETAILED INSPECTION MPE1 88056A010102 428	OUTFLOW VALVE MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 21 31 05 220 801	AFL	3750				0	3750	
21-31-05-201	DETAILED INSPECTION 88056A010102 428	OUTFLOW VALVE MOS HRS/MSC					28-JAN-2011 0		
MRB	REF: AMM 21 31 05 220 801	AFL	7500	+40/-40			0	7500	7540
21-31-05-202	GENERAL VISUAL INSPECTION REF: AMM 21 31 05 210 801	OUTFLOW VALVE MOS HRS/MSC					28-JAN-2011 0		
MRB		AFL	3750				0	3750	
21-31-09-101 (s)	FUNCTIONAL TEST POSITIVE AND NEGATIVE PRESSURE RELIEF OF THE SAFETY VALVES PKG 11 REF: AMM 21 31 09 720 801	MOS HRS/MSC AFL	1600				PKG 20-MAY-2016 1581:47 936		
21-31-09-102	DISCARD LH SAFETY VALVE FILTER 81141A010303 PKG 13 785 REF: AMM 21 31 09 961 801	MOS HRS/MSC AFL	3200				28-JAN-2011 0	3200	
21-31-09-203	CLEANING OF THE SAFETY VALVE PART NO. 81141A010302 PRESSURE PORT REF: AMM 21 31 09 160 801	MOS HRS/MSC AFL	N/A						
21-51-01-101	SPECIAL DETAILED INSPECTION LH OZONE CONVERTER 264A030000 8015 REF: AMM 21 51 01 280 801	MOS HRS/MSC AFL	N/A						



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-51-01-101	SPECIAL DETAILED INSPECTION RH OZONE CONVERTER 264A030000 8144 REF: AMM 21 51 01 280 801	MOS HRS/MSC AFL	N/A						
21-51-01-301-1	RESTORATION LH OZONE CONVERTER 264A030000 8015 REF: AMM 21 51 01 840 801	MOS HRS/MSC AFL	2500	+40/-40			29-JUL-2019 2500:25 1416	4897:19	4937:19
MRB									
21-51-01-301-2	RESTORATION RH OZONE CONVERTER 264A030000 8144 REF: AMM 21 51 01 840 801	MOS HRS/MSC AFL	2500	+40/-40			23-SEP-2019 2606:02 1467	5106:02	5146:02
MRB									
21-52-05-201	DETAILED INSPECTION PLENUM REF: AMM 21 52 05 220 801	MOS HRS/MSC AFL	8000	+40/-40			28-JAN-2011 0 0	8000	8040
MRB									
21-52-21-201	DETAILED INSPECTION REHEATER/CONDENSER REF: AMM 21 52 21 220 801	MOS HRS/MSC AFL	8000	+40/-40			28-JAN-2011 0 0	8000	8040
MRB									
21-53-13-201 (s)	GENERAL VISUAL INSPECTION RAM-AIR INLET DUCTING PKG 12 REF: AMM 21 53 13 210 801	MOS HRS/MSC AFL	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB									
21-53-21-301 (s)	OPERATIONAL TEST RAM AIR VALVE PKG 11 REF: AMM 21 53 21 710 801	MOS HRS/MSC AFL	1600	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB									

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-60-00-201 (s)	OPERATIONAL TEST MANUAL TEMPERATURE CONTROL PKG 11	MOS					PKG		
MRB	REF: AMM 21 60 00 710 801	HRS/MSC AFL	1600	+40/-40			06-DEC-2018 2236:21 1275		
21-61-01-201 (s)	OPERATIONAL TEST HOT AIR CHECK-VALVES PKG 12	MOS					PKG		
MRB	REF: AMM 21 61 01 710 801	HRS/MSC AFL	2400	+40/-40			06-DEC-2018 2236:21 1275		
21-61-01-202 (s)	DETAILED INSPECTION HOT AIR CHECK-VALVES PKG 12	MOS					PKG		
MRB	REF: AMM 21 61 01 220 801	HRS/MSC AFL	2400	+40/-40			06-DEC-2018 2236:21 1275		
21-61-07-301 (s)	OPERATIONAL TEST PRE-COOLER CROSS OVER VALVE PKG 10	MOS					PKG		
MRB	REF: AMM 21 61 07 710 801	HRS/MSC AFL	1200	+40/-40			06-DEC-2018 2236:21 1275		
212101-0101	CHECK VALVE 52701A010000 425	MOS						28-JAN-2011	
	REF: See Workcard	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
212105-0101	PILOT OUTLET AIR GASPER 9725B020000 336	MOS						28-JAN-2011	
	REF: See Workcard	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		
212105-0102	COPILOT OUTLET AIR GASPER 9726B020000 335	MOS						28-JAN-2011	
	REF: See Workcard	HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212105-0301	FEED GASPER 9724B030000 722 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212105-0401	AVIONICS VALVE TEE JOINT 9755B020000 1193 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212105-0501	TEE JUNCTION DUCT GASPER 9739B010000 346 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212109-0101	LEFT VENTILATOR 9731B020000 1189 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212109-0102	RIGHT VENTILATOR 9733B020000 1200 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212111-0101	COCKPIT FEED FLEX DUCT 9792B030000 745 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212111-0102	AFT FUSELAGE COCKPIT FEED SUPPLY DUCT 9727B020000 1448 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212111-0103	AFT FUSELAGE COCKPIT FEED SUPPLY DUCT 9727B020000 1451 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212113-0101	CENTER FUSELAGE COCKPIT FEED SUPPLY DUCT 9727B020000 1450 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212113-0102	CENTER FUSELAGE COCKPIT FEED SUPPLY DUCT 9727B020000 1456 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212115-0101	FEED TEE PIECE 9728B020000 724 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212115-0201	FLEXIBLE HOSE 9729B020000 938 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212115-0202	FLEXIBLE HOSE 9729B020000 933 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212115-0301	RH JUNCTION 9730B020000 714 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212115-0302	LH JUNCTION 9738B020000 711 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212117-0101	RIGHT FOOT WARMER HOSE 9736B020000 942 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212117-0102	LEFT FOOT WARMER HOSE 9736B020000 914 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212117-0103	RIGHT FACE WEEMAC HOSE 9737B020000 939 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212117-0104	LEFT FACE WEEMAC HOSE 9737B020000 929 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212117-0301	RH FWD FEED HOSE 9734B020000 975 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212117-0302	LH FWD FEED HOSE 9734B020000 974 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212117-0401	RH FWD TEE HOSE 9735B020000 933 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212117-0402	LH FWD TEE HOSE 9735B020000 929 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212201-0101	MIXER MANIFOLD 9786B050000 701 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212205-0101	LOWER GASPER 9787B030000 747 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212205-0201	TRANSITION GASPER 9788B030000 720 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212205-0301	LH CENTER GASPER 9791B030000 713 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212205-0302	RH CENTER GASPER 9789B030000 729 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212207-0101	LOWER RISER 9793B010000 343 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212209-0101	FLOOR INTERFACE RISER 9794B020000 329 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212209-0102	UPPER RISER 9795B030000 723 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212209-0103	TRANSITION RISER 9796B020000 726 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212209-0201	UPPER JOIN FLEX DUCT 9798B020000 726 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212209-0301	LH UPPER CORNER 9799B020000 724 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212211-0101	LH UPPER FORWARD FLEX DUCT 9776B020000 997 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212211-0102	RH UPPER FORWARD FLEX DUCT 9776B020000 1014 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212211-0103	LH UPPER FORWARD FLEX DUCT 9777B020000 986 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212211-0104	RH UPPER FORWARD FLEX DUCT 9777B020000 983 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212213-0101	RIGID TEE DUCT 9782B040000 746 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212215-0101	RH FLEXIBLE HOSE 9768B030000 943 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212215-0102	LH FLEXIBLE HOSE 9768B030000 944 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212217-0101	LH LOWER RIGID DUCT 9784B020000 323 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212217-0102	RH LOWER RIGID DUCT 9785B030000 338 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212301-0101	LEFT AVIONICS COOLING RACK VENTILATED TEMPERATURE SENSOR GG436-2041-3 5115 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212301-0102	RIGHT AVIONICS COOLING RACK VENTILATED TEMPERATURE SENSOR GG436-2041-3 5178 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212305-0101	AVIONIC COOLING FAN 39274A030000 L00140 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:2 R:0 R:0			16-JAN-2015 1251:43 739		
212309	AVIONIC COOLING VALVE 7041A010001 433 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212311-0101	FAN MANIFOLD 9760B010000 338 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212313-0101	SILENCER DUCT 9764B010000 334 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212315-0101	RH DISPLAY COOLING TUBE 9752B010000 342 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212315-0102	LH DISPLAY COOLING TUBE 9765B010000 354 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212315-0201	FLEXIBLE HOSE 9754B010000 336 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212317-0101	COCKPIT SIDE HOSE 9756B010000 343 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212317-0201	FLEXIBLE HOSE 9759B010000 309 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212319-0101	FLEXIBLE HOSE 9757B020000 334 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212321-0101	LH AVIONICS OUT HOSE 9761B020000 851 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212321-0102	RH AVIONICS OUT HOSE 9762B020000 350 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212321-0201	LH LOWER RACK OUTLET HOSE 9866B020000 318 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212321-0202	RH LOWER RACK OUTLET HOSE 9867B020000 343 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212323-0101	RIGID #1 AVIONICS DUCT 9745B010000 338 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
212327-0101	SILENCER EXTENSION DUCT 9929B010000 322 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
213101-0101	NO. 1 CABIN PRESSURE INTEGRATED AIR SYSTEM (IASC) CONTROLLER 92175A030500 92175-00883 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:48 N:1232:52 N:727			02-JAN-2015 1232:52 727		
213101-0102	NO. 2 CABIN PRESSURE INTEGRATED AIR SYSTEM (IASC) CONTROLLER 92175A030500 92175-00884 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:48 N:1232:52 N:727			02-JAN-2015 1232:52 727		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213105-0101	MPE1 OUTFLOW VALVE 88056A010102 428 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
213109-0101	LH SAFETY VALVE 81141A010303 785 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
213109-0102	RH SAFETY VALVE 81141A010303 784 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
215101-0101	LH OZONE CONVERTER 264A030000 8015 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:103:06			29-JUL-2019 2500:25 1416		
215101-0102	RH OZONE CONVERTER 264A030000 8144 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-SEP-2019 2606:02 1467		
215103-0101	NO. 1 MT23 DIFFERENTIAL PRESSURE SENSOR 92277A010000 851 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
215103-0102	NO. 2 MT24 DIFFERENTIAL PRESSURE SENSOR 92277A010000 852 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215109-0101	NO. 1 MPE3 FLOW CONTROL VALVE 60079A020000 759 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
215109-0102	NO. 2 MPE4 FLOW CONTROL VALVE 60079A020000 762 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
215111	AIR COND PACK INLET PRECOOLER 1556A010000 434 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
215115-0101	PRECOOLER UNIT 3737A020000 T0323 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
215117	AIR COND PACK OUTLET PRECOOLER 1558A010000 445 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
215205	AIR COND PACK PLENUM GG431-2008-5 2542 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
215209	AIR COND PACK DUAL HEAT EXCHANGER GG670-95008-3 51171 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215213	PACK COOLING UNIT 3517A030000 475 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
215213-0101	AIR CYCLE MACHINE 3471A020000 00165 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			21-MAR-2019 2354:02 1337		
215217-0101	MT29 - COMPRESSOR DISCHARGE TEMPERATURE SENSOR GG436-2005-3 07113R REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
215221	AIR COND PACK REHEATER CONDENSER GG474-2053-3 50196 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
215225-0101	AIR COND PACK MIX MANIFOLD TEMPERATURE SENSOR GG436-2015-3 9879 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
215229	AIR COND PACK WATER EXTRACTOR GG670-95013-1 2077 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
215233	AIR COND PACK TEMPERATURE CONTROL (TCV) VALVE GG670-95010-3 1872 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215237-0101	AIR COND PACK DISCHARGE TEMPERATURE SENSOR GG436-2015-3 11026 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
215241	AFT EQUIP BAY PACK DISCHARGE DUCT 12723B010000 365 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
215301	RAM AIR INLET DUCT WATER SPRAYER GG431-2022-3 2725 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
215305	MPE9 RAM AIR REGULATING (RARV) VALVE 7084A010000 773 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
215309-0101	RAM AIR VENT DUCT 9769B010000 347 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
215309-0201	RAM AIR DUCT SLEEVE 9770B010000 24010/332 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
215313-0101	RAM AIR UPPER INTAKE 9771B010000 356 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215313-0201	SLEEVE 9772B010000 11509/336 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
215317-0101	RAM AIR LOWER INTAKE 9773B010000 832 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			21-MAR-2019 2354:02 1337		
215321	MPE40 RAM AIR (RAV) VALVE GG670-95019-1 1075 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
216101-0101	LOWER HOT AIR CHECK (HACKV) VALVE 41175A010000 770 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
216101-0102	UPPER HOT AIR CHECK (HACKV) VALVE 41175A010000 771 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
216103-0101	TRIM AIR BULKHEAD ADAPTOR ADAPTOR 1563A020000 788 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
216103-0102	TRIM AIR BULKHEAD ADAPTOR ADAPTOR 1563A020000 787 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216105-0101	NO. 1 HOT AIR REGULATING& SHUTOFF (HARSOV) MPE5 REGULATING & SHUTOFF VALVE 7039A010001 755 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
216105-0102	NO. 2 HOT AIR REGULATING& SHUTOFF (HARSOV) MPE6 REGULATING & SHUTOFF VALVE 7039A010001 754 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
216107	PRE-COOLER CROSS OVER VALVE MPE11 REGULATING& SHUTOFF VALVE 6151A010010 766 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
216109-0101	FLIGHT COMPARTMENT DUCT MIX MANIFOLD TEMPERATURE SENSOR GG436-2015-3 10527 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
216113-0101	CABIN DUCT MIX MANIFOLD TEMPERATURE SENSOR GG436-2015-3 10533 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
216121-0101	CABIN VENTILATED TEMPERATURE SENSOR GG436-2041-3 5174 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
216125-0101	FLIGHT COMPARTMENT VENTILATED TEMPERATURE SENSOR GG436-2041-3 5257 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216129-0101	MT27 - HOT AIR TEMPERATURE SENSOR GG436-2005-3 08181R REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
216133-0101	MT25 - PACK INLET TEMPERATURE SENSOR GG436-2005-3 13990R REF: See Workcard	MOS HRS/MSC AFL	O/C	N:7 N:0 N:0			05-AUG-2016 1683:42 991		
216140-0101	LINE TRIM 12716B020000 436 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
216140-0102	LINE TRIM 12717B020000 443 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
216140-0103	TRIM SPLIT DUCT 12718B020000 452 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
216140-0104	COCKPIT TRIM DUCT 12719B020000 447 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
216140-0105	COCKPIT FEED DUCT 12720B010000 351 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216140-0106	CABIN TRIM DUCT 12721B020000 434 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
216140-0107	CABIN FEED DUCT 12722B020000 445 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
216149-0101	CABIN TRIM INJECTOR 12724B010000 355 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
CHAPTER 22 AUTO FLIGHT									
22-11-05-201 (s)	GENERAL VISUAL INSPECTION L/HIRF PROTECTION ON THE FLIGHT GUIDANCE PANEL CONNECTORS AND MOUNTING POINTS PKG 5 REF: AMM 22 11 05 210 801	MOS HRS/MSC AFL	96	+1m/-1m			23-DEC-2019 2630:03 1481		
22-11-09-201	FUNCTIONAL TEST AILERON SERVO MOUNT REF: AMM 22 11 09 720 802	MOS HRS/MSC AFL	12000	+40/-40			28-JAN-2011 0 0	12000	12040
22-11-13-201	FUNCTIONAL TEST ELEVATOR SERVO MOUNT REF: AMM 22 11 13 720 802	MOS HRS/MSC AFL	12000	+40/-40			28-JAN-2011 0 0	12000	12040

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-22-01-301 (s)	OPERATIONAL TEST YAW DAMPER LINEAR-ACTUATOR PKG 8	MOS					PKG		
MRB	REF: AMM 22 22 01 710 803	HRS/MSC AFL	600	+40/-40			23-DEC-2019 2630:03 1481		
221101-0101	NO. 1 FLIGHT GUIDANCE (FGC-3002) COMPUTER 822-1592-626 3J3NX REF: See Workcard	MOS HRS/MSC AFL	O/C	N:107 N:2630:03 N:1481			23-DEC-2019 2630:03 1481		
221101-0102	NO. 2 FLIGHT GUIDANCE (FGC-3002) COMPUTER 822-1592-626 3J3YP REF: See Workcard	MOS HRS/MSC AFL	O/C	N:107 N:2630:03 N:1481			23-DEC-2019 2630:03 1481		
221105-0101	FLIGHT GUIDANCE (FGP-5020) (PL9) PANEL 822-1574-001 3PR4M REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
221109-0101	AILERON SERVO MOUNT 622-5735-104 44TND REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
221113-0101	ELEVATOR SERVO MOUNT 622-5735-104 3LK4J REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
221117-0101	AILERON (SVO-3000) (A126) SERVO 822-1168-032 3W7VC REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221121-0101	ELEVATOR (SVO-3000) (A125) SERVO 822-1168-033 3W8PX REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
222201	YAW DAMPER ACTUATOR 622-9968-003 5700 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
CHAPTER 23 COMMUNICATIONS									
+ 23-30-00-601 (s)	OPERATIONAL TEST PASSENGER ADDRESS SYSTEM PKG 7 REF:	MOS HRS/MSC AFL	400	+40/-40			PKG 23-DEC-2019 2630:03 1481		
STLMC									
23-51-05-201 (s)	OPERATIONAL TEST AUDIO CONTROL-PANEL, EMERGENCY-SWITCH PKG 3 REF: AMM 23 51 05 710 802	MOS HRS/MSC AFL	36	+1m/-1m			PKG 07-DEC-2017 1913:50 1121		
MRB									
23-61-01-201 (s)	FUNCTIONAL TEST STATIC DISCHARGERS PKG 3 REF: AMM 23 61 01 720 801	MOS HRS/MSC AFL	36	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB									
23-71-00-201 (s)	OPERATIONAL TEST COCKPIT VOICE RECORDER SYSTEM PKG 4 REF: AMM 23 71 00 710 801	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-AUG-2018 2152:49 1228		
MRB									
23-71-21-201	FUNCTIONAL TEST CVR (ULD) UNDERWATER LOCATOR DEVICE 266-E5542-00 PKG 4 ULB024300 REF: AMM 23 71 21 720 801	MOS HRS/MSC AFL	48	+1m/-1m			25-JUL-2018 2112:06 1211	25-JUL-2022	25-AUG-2022
MRB									

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-71-21-202	DISCARD CVR (ULD) UNDERWATER LOCATOR DEVICE BATTERY 266-E5542-00 ULB024300 REF: AMM 23 71 21 961 801	MOS HRS/MSC AFL	DUE				25-JUL-2018 2112:06 1211	01-MAY-2025 M	
231101-0101	NO. 1 (A7) VHF COMM (VHF-4000) TRANSCEIVER 822-1468-102 45W0V REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
231101-0102	NO. 2 (A8) VHF COMM (VHF-4000) TRANSCEIVER 822-1468-102 45W0X REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
231101-0103	NO. 3 (A10) VHF COMM (VHF-4000) TRANSCEIVER 822-1468-302 45X7D REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
231109-0101	NO. 1 VHF ANTENNA S65-8280-10 310-34185 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
231109-0102	NO. 2 VHF ANTENNA S65-8280-10 310-21508 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
231109-0103	NO. 3 VHF ANTENNA S65-8280-10 310-34182 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231201-0101	NO. 1 REAR FUSELAGE A61 HF (HF9031A) RECEIVER 822-0101-002 5262 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
231201-0102	NO. 2 REAR FUSELAGE A62 HF (HF9031A) RECEIVER 822-0101-002 5261 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
231205-0101	MT-9030A HF RADIO MOUNT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
231205-0102	MT-9030A HF RADIO MOUNT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
231209-0101	LH ANTENNA (HF9041A) COUPLER 622-8114-002 10668 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			23-DEC-2019 2630:03 1481		
231209-0102	RH ANTENNA (HF9041A) COUPLER 622-8114-002 10833 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			23-DEC-2019 2630:03 1481		
231413-0101	COCKPIT DATA BUS (CDBR) REPEATER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231726-0101	IRIDIUM ANTENNA 500644-1 333973 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
231726-7101	ICS-200 IRIDIUM TRANSCEIVER 500617-4-1 6934 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
235101-0101	COCKPIT SPEAKER 5064-1 6470 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
235101-0102	COCKPIT SPEAKER 5064-1 6445 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
235105-0101	LEFT AUDIO CONTROL PANEL 822-2171-090 48RDJ REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
235105-0102	RIGHT AUDIO CONTROL PANEL 822-2171-090 4948F REF: See Workcard	MOS HRS/MSC AFL	O/C	R:6 R:0 R:0			06-NOV-2014 1164:01 690		
235109-0101	PILOT A167 ELECTRONIC CONTROL (CPE-4100 / CPE-5200) PANEL 822-2172-010 455WF REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
235109-0102	COPILOT A168 ELECTRONIC CONTROL (CPE-4100 / CPE-5200) PANEL 822-2172-010 455WD REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
235121-0101	NO. 1 RADIO INTERFACE UNIT 822-1469-652 3XGCP REF: See Workcard	MOS HRS/MSC AFL	O/C	N:107 N:2630:03 N:1481			23-DEC-2019 2630:03 1481		
235121-0102	NO. 2 RADIO INTERFACE UNIT 822-1590-152 3B25Y REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
237105-0101	CVR MOUNTING TRAY 2100-8001-00 658579 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
237109	CENTER PEDESTAL PL30 COCKPIT VOICE RECORDER PANEL S251-1170-00 682414 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
237113	(CVR) COCKPIT VOICE RECORDER 2100-1225-22 001108240 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 N:1062:12 R:0 N:640 R:0			25-JUL-2018 2112:06 1211		
237113-0101	VOICE RECORDER MICROPHONE S055-0065-00 633791 REF:	MOS HRS/MSC AFL	O/C						

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237117-0101	CVR SWITCH 3LO-453/3 91494 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
237121-0101	CVR (ULD) UNDERWATER LOCATOR DEVICE 266-E5542-00 ULB024300 REF: See Workcard	MOS HRS/MSC AFL	O/C				25-JUL-2018 2112:06 1211		
CHAPTER 24 ELECTRICAL POWER									
24-00-00-501 (s)	OPERATIONAL CHECK (CYCLING) OF THERMAL CIRCUIT BREAKERS PKG 1 REF: AMM 24 00 00 710 801	MOS HRS/MSC AFL	12	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MPD									
24-20-00-602 (s)	OPERATIONAL TEST RESIDUAL CURRENT DISRUPTER (RCD) PKG 1 REF:	MOS HRS/MSC AFL	12	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
STLMC									
24-31-01-201 (s)	OPERATIONAL TEST ELECTRICAL CONTROL PANEL PKG 4 REF: AMM 24 31 01 710 801	MOS HRS/MSC AFL	48	+1m/-1m			PKG 07-DEC-2017 1913:50 1121		
MRB									
24-31-09-201	RESTORATION APU DC GENERATOR A3579-102 3631 REF: AMM 24 31 09 610 801	MOS HRS/MSC AFL APH	3000	+40/-40			06-DEC-2018 2236:21 1275 3008:15	6008:15	6048:15
MRB									

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-31-09-202	LUBRICATION OF THE AUXILIARY POWER UNIT (APU) GENERATOR (POST SB 100-24-21 OR A/C 20379 AND SUBS)	MOS HRS/MSC AFL APH	N/A						
	REF: AMM 12 22 00 640 821								
24-32-05-101	RESTORATION INTEGRATED STANDBY INSTRUMENT (ISI) BATTERY	MOS HRS/MSC AFL	36				23-DEC-2019 2630:03 1481	23-DEC-2022	
	100-2410-02 1187444								
AIRWORTHINESS	REF: AMM 24 32 05 610 801								
24-32-05-201 (s)	OPERATIONAL TEST OF THE BUILT-IN TEST (BIT) FOR THE INTEGRATED STANDBY-INSTRUMENT (ISI) BATTERY	MOS HRS/MSC AFL	24	+1m/-1m			23-DEC-2019 2630:03 1481		
	PKG 2								
MRB	REF: AMM 24 32 05 710 802								
24-32-05-302 (s)	OPERATIONAL TEST OF THE INTEGRATED STANDBY-INSTRUMENT (ISI) BATTERY CAPACITY	MOS HRS/MSC AFL	12	+1m/-1m			23-DEC-2019 2630:03 1481		
	PKG 1								
MRB	REF: AMM 24 32 05 710 801								
24-33-00-201	OPERATIONAL TEST HMDG SYSTEM (POST SB 100-24-04 OR POST SB 350-24-001)	MOS HRS/MSC AFL	N/A						
	REF: AMM 24 33 00 710 801								
24-61-13-201 (s)	OPERATIONAL TEST AUXILIARY POWER CONTACTOR	MOS HRS/MSC AFL	48	+1m/-1m			07-DEC-2017 1913:50 1121		
	PKG 4								
MRB	REF: AMM 24 61 13 710 801								
24-61-25-201 (s)	OPERATIONAL TEST ELECTRICAL SYSTEM EMERGENCY MODE	MOS HRS/MSC AFL	48	+1m/-1m			07-DEC-2017 1913:50 1121		
	PKG 4								
MRB	REF: AMM 24 61 25 710 801								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-61-29-201 (s)	OPERATIONAL TEST BUS TIE CONTACTOR PKG 4	MOS	48	+1m/-1m			PKG 07-DEC-2017 1913:50 1121		
MRB	REF: AMM 24 61 29 710 801	HRS/MSC AFL							
24-61-41-900-801-01	LH DC HALL EFFECT SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
24-61-41-900-801-02	RH DC HALL EFFECT SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
242501-0101	REAR EQUIPMENT BAY STATIC INVERTER SB200 245 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	R:28 R:0 R:0			04-JAN-2016 1503:55 893		
243105-0101	LEFT G1 MAIN GENERATOR A3579-102 2111 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
243105-0101A	RESTORATION LEFT G1 MAIN GENERATOR (24-31-05-201) A3579-102 2111 MRB REF: AMM 24 31 05 610 801	MOS HRS/MSC AFL	3000	+40/-40			28-JAN-2011 0 0	3000	3040
243105-0102	RIGHT G2 MAIN GENERATOR A3579-102 2108 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243105-0102A	RESTORATION RIGHT G2 MAIN GENERATOR (24-31-05-201) A3579-102 2108 REF: AMM 24 31 05 610 801	MOS HRS/MSC AFL	3000	+40/-40			28-JAN-2011 0 0	3000	3040
MRB									
243109-0101	APU DC GENERATOR A3579-102 3631 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			06-DEC-2018 2236:21 1275		
243117-0201	GCU HARNESS 1004900010-003 20162 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
243201-0101	BT1 BATTERY 441CH1 V05332 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:6 O:85:52 O:45			18-JUN-2020 2715:55 1526		
243201-0101A	FUNCTIONAL TEST BT1 BATTERY (24-32-01-201) 441CH1 V05332 REF: AMM 24 32 01 720 801	MOS HRS/MSC AFL	6	+10%			18-JUN-2020	18-DEC-2020	05-JAN-2021
MRB									
243201-0101B	RESTORATION BT1 BATTERY (24-32-01-302) 441CH1 PKG 1 V05332 REF: AMM 24 32 01 610 801	MOS HRS/MSC AFL	12	+1m/-1m			17-DEC-2019	17-DEC-2020	17-JAN-2021
MRB									
243201-0102	BT2 BATTERY 441CH1 V05333 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:6 O:85:52 O:45			18-JUN-2020 2715:55 1526		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243201-0102A	FUNCTIONAL TEST BT2 BATTERY (24-32-01-201) 441CH1 V05333 REF: AMM 24 32 01 720 801	MOS HRS/MSC AFL	6	+10%			18-JUN-2020	18-DEC-2020	05-JAN-2021
MRB									
243201-0102B	RESTORATION BT2 BATTERY (24-32-01-302) 441CH1 PKG 1 V05333 REF: AMM 24 32 01 610 801	MOS HRS/MSC AFL	12	+1m/-1m			17-DEC-2019	17-DEC-2020	17-JAN-2021
MRB									
243205	INTEGRATED STANDBY INSTRUMENT (ISI) BATTERY 100-2410-02 1187444 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
244105-0101	EXTERNAL POWER CONTROL PANEL 100GC03Y00 322 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
246101-0101	LEFT DC POWER CENTER 975GC02Y06 423R REF: See Workcard	MOS HRS/MSC AFL	O/C				28-JAN-2011 0 0		
246101-0102	RIGHT DC POWER CENTER 970GC02Y06 423R REF: See Workcard	MOS HRS/MSC AFL	O/C				28-JAN-2011 0 0		
246173-0101	LH (PCB3) DC POWER CENTER PRIMARY-LOGIC PCB PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
246173-0102	RH (PCB4) DC POWER CENTER PRIMARY-LOGIC PCB PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
246201-0101	RH (SPC) SECONDARY POWER CENTER 980GC02Y06 409 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
246201-0201	LH DC (SPC) SECONDARY POWER CENTER 985GC02Y04 407 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
246301	JB1 BOX ASSEMBLY 00514-0289-0005 604 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
246305	JB2 BOX ASSEMBLY 00514-0290-0007 599 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
246309	JB3 BOX ASSEMBLY 00514-0291-0005 593 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
246313	JB4 BOX ASSEMBLY 00514-0292-0006 596 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
246401-0101	AUXILIARY DC POWER CENTER UNIT 320GC03Y06 423R REF: See Workcard	MOS HRS/MSC AFL	O/C				28-JAN-2011 0 0		
246417-7101	APU DC HALL EFFECT SENSOR 190CG03Y02 2057 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			10-DEC-2012 368:45 200		
CHAPTER 25 EQUIPMENT/FURNISHINGS									
25-00-00-601	RETREATMENT OF FABRICS OF SILK OR SILK BLEND, 36 SQUARE INCHES OR MORE REF:	MOS HRS/MSC AFL	A/R						
25-00-00-602	RETREATMENT OF FABRICS OF NON-SILK OR NON-SILK BLEND, 36 SQUARE INCHES OR MORE REF:	MOS HRS/MSC AFL	A/R						
25-11-00-201 (s)	GENERAL VISUAL INSPECTION SAFETY STRAPS PKG 9 REF: AMM 25 11 00 210 801	MOS HRS/MSC AFL	800	+40/-40			PKG 23-DEC-2019 2630:03 1481		
25-11-00-202 (s)	OPERATIONAL TEST INERTIA REEL AND INERTIA REEL CONTROL PKG 9 REF: AMM 25 11 00 710 801	MOS HRS/MSC AFL	800	+40/-40			PKG 23-DEC-2019 2630:03 1481		
25-21-00-601 (s)	OPERATIONAL TEST PASSENGER RESTRAINTS PKG 1 REF:	MOS HRS/MSC AFL	12	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-21-00-602 (s)	OPERATIONAL TEST PASSENGER SEAT ASSEMBLIES PKG 1	MOS HRS/MSC AFL	12	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
STLMC	REF:								
25-30-00-601 (s)	GENERAL VISUAL INSPECTION GALLEY DRAINAGE LINES PKG 1	MOS HRS/MSC AFL	12	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
STLMC	REF:								
25-30-00-602 (s)	DETAILED INSPECTION GALLEY WASTE CONTAINER PKG 1	MOS HRS/MSC AFL	12	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
STLMC	REF:								
25-40-00-601 (s)	DETAILED INSPECTION LAVATORY WASTE CONTAINER PKG 1	MOS HRS/MSC AFL	12	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
STLMC	REF:								
25-61-00-201	OPERATIONAL TEST EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (P/N S1821502-02)	MOS HRS/MSC AFL	N/A						
MRB	REF: AMM 25 61 00 710 801								
25-61-01-201	DISCARD OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY (KANNAD TRANSMITTER: P/N S1821502-02, BATTERY: P/N S1820516-99)	MOS HRS/MSC AFL	N/A						
MRB	REF: AMM 25 61 01 961 801								
25-62-00-604 (s)	VISUAL CHECK OF THE FIRST AID KIT SEAL PKG 1	MOS HRS/MSC AFL	12	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
STLMC	REF:								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-63-00-201 (s)	OPERATIONAL TEST ARTEX EMERGENCY LOCATOR TRANSMITTER (ELT) PKG 1	MOS	12	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
STLMC	REF:	AFL							
25-63-00-202	DISCARD ARTEX EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY	MOS					09-DEC-2015 1470:55 878	01-OCT-2020 M	
SMM	REF:	HRS/MSC AFL	DUE						
25-CUS-001	DISCARD MEDAIRE UNIVERSAL PRECAUTION KIT PN SN-UNKNOWN	MOS					03-JUL-2020	08-APR-2021 M	
Expiry Date: 08-APR-2021	REF:	HRS/MSC AFL	DUE						
25-CUS-02	DISCARD PORTABLE ELT PARM-406A	MOS	180				22-NOV-2018	22-NOV-2033	
REF:		HRS/MSC AFL							
25-CUS-03	DISCARD PORTABLE ELT PARM-406A BATTERY BP-214M	MOS	36				22-NOV-2018	16-NOV-2021 M	
REF:		HRS/MSC AFL							
25-CUST-7101	INSPECT SYNTHETIC HARNESSSES (I.A.W. LTA 91)	MOS	240					03-NOV-2031 M	
REF:		HRS/MSC AFL							
251113-0101	PILOT SEAT 1002510001-003 3391-1405	MOS		N:0			28-JAN-2011 0 0		
REF: See Workcard		HRS/MSC AFL	O/C	N:0					

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251113-0102	CO-PILOT SEAT 1002510001-004 3390-1405 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
251301-0103	CREW HR3 - FLOOR MAT HEATER 596A010000 1997 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
251301-0104	CREW HR4 - FLOOR MAT HEATER 596A010000 1982 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
251301-0105	CREW HR5 - FLOOR MAT HEATER 596A010000 1984 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
251301-0106	CREW HR6 - FLOOR MAT HEATER 596A010000 1985 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
251400-7101	ESPRESSO MAKER 400-1794-08 06-10-39853 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
252101-0101	L1 PASSENGER SEAT 1002599406-001-BS1 63188 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
252101-0102	R1 PASSENGER SEAT 1002599406-002-BS1 63190 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252101-0103	L2 PASSENGER SEAT 1002599406-003-BYS1 63187 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252101-0104	R2 PASSENGER SEAT 1002599406-004-BYS1 63191 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252101-0105	L3 PASSENGER SEAT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252101-0106	R3 PASSENGER SEAT 1002599406-006-BS1 63189 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252101-0107	L4 PASSENGER SEAT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252101-0108	R4 PASSENGER SEAT 1002599406-008-BS1 63192 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252101-7110	RH 16G BELTED LAV TOILET 1002543000-001 7512882/001 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252103-0101	L3, L4, L5 AFT LH DIVAN 1002599407-001-BS1 63193 REF:	MOS HRS/MSC AFL	O/C						

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252400-7501	POWER AUDIO AMPLIFIER APA0106-001-001 276 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252400-7601	DIGITAL AUDIO PCM ENCODER DAE0106-001-001 248 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252400-7701	SWITCH ETHERNET ESU1206-001-001 557 REF:	MOS HRS/MSC AFL	O/C	N:6 N:0 N:0			27-JAN-2012 93 56		
252400-7702	SWITCH ETHERNET ESU1206-001-001 568 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252415-7101	PCU CORE MODULE PCS2306-001-001 12016 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252415-7102	PCU CORE MODULE PCS2306-001-001 12017 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252415-7103	PCU CORE MODULE PCS2306-001-001 12018 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252415-7104	PCU CORE MODULE PCS2306-001-001 12020 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252415-7105	PCU CORE MODULE PCS2306-001-001 12019 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252415-7106	PCU CORE MODULE PCS2306-001-001 12022 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252415-7107	PCU CORE MODULE PCS2306-001-001 12023 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252415-7108	PCU CORE MODULE PCS2306-001-001 12024 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252416-7101	ENHANCED PCIU PCU0106-001-001 633 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252416-7102	ENHANCED PCIU PCU0106-001-001 631 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252416-7103	ENHANCED PCIU PCU0106-001-001 0183 REF:	MOS HRS/MSC AFL	O/C				08-JUL-2013 578:31 328		
252419-7102	IPOD AUDIO ENCODER DAE1906-001-001 40307 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252430-7101	STANDARD PCU PSM0106-001-001 1768 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252430-7102	STANDARD PCU PSM0106-001-001 1770 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252430-7103	STANDARD PCU PSM0106-001-001 1771 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252430-7104	STANDARD PCU PSM0106-001-001 2717 REF:	MOS HRS/MSC AFL	O/C				19-JAN-2017 1703:13 1002		
252430-7105	STANDARD PCU PSM0106-001-001 1772 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252430-7106	STANDARD PCU PSM0106-001-001 1765 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252430-7107	STANDARD PCU PSM0106-001-001 1769 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252430-7108	STANDARD PCU PSM0106-001-001 1533 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252460-7101	SINGLE BUTTON SWITCH PSC0106-001-000 210 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
252460-7102	SINGLE BUTTON SWITCH PSC0106-002-000 252 REF:	MOS HRS/MSC AFL	O/C						
252460-7201	TRIPLE BUTTON SWITCH PSC0106-010-000 211 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
253000-7301	FORWARD VIP PCU GALLEY CONTROL GCP0628-100-001 509 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
253000-7302	AFT VIP PCU GALLEY CONTROL GCP0628-100-001 510 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
256101-0101	(ELT) EMERGENCY LOCATOR TRANSMITTER (PN: S1821502-02) PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	N/A						
256101-7001	ARTEX (ELT) EMERGENCY LOCATOR TRANSMITTER 453-5060 9992 REF:	MOS HRS/MSC AFL	O/C	N:107 N:2630:03 N:1481			23-DEC-2019 2630:03 1481		
256105-0102	EMERGENCY LOCATOR TRANSMITTER ANTENNA 110-340 343003 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256115-0101	PILOT LIFEVEST P0723E105PWC 15092410010 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:4			03-MAR-2016 1536:51 908		
256115-0101A	RESTORATION PILOT LIFEVEST (25-62-00-201) P0723E105PWC 15092410010 REF: AMM 25 62 01 610 801	MOS HRS/MSC AFL	60	+1m/-1m			03-MAR-2016 1536:51 908	03-MAR-2021	03-APR-2021
MRB									
256115-0101B	DETAILED INSPECTION PILOT LIFEVEST (25-62-00-209) P0723E105PWC PKG 3 15092410010 REF: AMM 25 62 01 220 801	MOS HRS/MSC AFL	36	+1m/-1m		-16	23-DEC-2019 2630:03 1481	07-DEC-2022	07-JAN-2023
MRB									
256115-0102	COPILOT LIFEVEST P0723E105PWC 15092410027 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:4			03-MAR-2016 1536:51 908		
256115-0102A	RESTORATION COPILOT LIFEVEST (25-62-00-201) P0723E105PWC 15092410027 REF: AMM 25 62 01 610 801	MOS HRS/MSC AFL	60	+1m/-1m			03-MAR-2016 1536:51 908	03-MAR-2021	03-APR-2021
MRB									
256115-0102B	DETAILED INSPECTION COPILOT LIFEVEST (25-62-00-209) P0723E105PWC PKG 3 15092410027 REF: AMM 25 62 01 220 801	MOS HRS/MSC AFL	36	+1m/-1m		-16	23-DEC-2019 2630:03 1481	07-DEC-2022	07-JAN-2023
MRB									
256115-0103	L1 PASSENGER LIFEVEST 63600-101 L1626943 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
256115-0103A	RESTORATION L1 PASSENGER LIFEVEST (25-62-00-601) 63600-101 L1626943 REF:	MOS HRS/MSC AFL	120				01-APR-2011	01-APR-2021	
STLMC									

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256115-0103B	DETAILED INSPECTION L1 PASSENGER LIFEVEST (25-62-00-612) 63600-101 PKG 1 L1626943 REF:	MOS HRS/MSC AFL	12	+1m/-1m		-17	23-DEC-2019 2630:03 1481	06-DEC-2020	06-JAN-2021
STLMC									
256115-0104	R1 PASSENGER LIFEVEST 63600-101 L1608582 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
256115-0104A	RESTORATION R1 PASSENGER LIFEVEST (25-62-00-601) 63600-101 L1608582 REF:	MOS HRS/MSC AFL	120				01-MAR-2011	01-MAR-2021	
STLMC									
256115-0104B	DETAILED INSPECTION R1 PASSENGER LIFEVEST (25-62-00-612) 63600-101 PKG 1 L1608582 REF:	MOS HRS/MSC AFL	12	+1m/-1m		-17	23-DEC-2019 2630:03 1481	06-DEC-2020	06-JAN-2021
STLMC									
256115-0105	L2 PASSENGER LIFEVEST 63600-101 L1626948 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
256115-0105A	RESTORATION L2 PASSENGER LIFEVEST (25-62-00-601) 63600-101 L1626948 REF:	MOS HRS/MSC AFL	120				01-APR-2011	01-APR-2021	
STLMC									
256115-0105B	DETAILED INSPECTION L2 PASSENGER LIFEVEST (25-62-00-612) 63600-101 PKG 1 L1626948 REF:	MOS HRS/MSC AFL	12	+1m/-1m		-17	23-DEC-2019 2630:03 1481	06-DEC-2020	06-JAN-2021
STLMC									
256115-0106	R2 PASSENGER LIFEVEST 63600-101 L1630172 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256115-0106A	RESTORATION R2 PASSENGER LIFEVEST (25-62-00-601) 63600-101 L1630172 REF:	MOS HRS/MSC AFL	120				01-APR-2011	01-APR-2021	
STLMC									
256115-0106B	DETAILED INSPECTION R2 PASSENGER LIFEVEST (25-62-00-612) 63600-101 PKG 1 L1630172 REF:	MOS HRS/MSC AFL	12	+1m/-1m		-17	23-DEC-2019 2630:03 1481	06-DEC-2020	06-JAN-2021
STLMC									
256115-0107	L3 PASSENGER LIFEVEST 63600-101 L1608587 REF:	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		28-JAN-2011 0 0		
256115-0107A	RESTORATION L3 PASSENGER LIFEVEST (25-62-00-601) 63600-101 L1608587 REF:	MOS HRS/MSC AFL	120				01-MAR-2011	01-MAR-2021	
STLMC									
256115-0107B	DETAILED INSPECTION L3 PASSENGER LIFEVEST (25-62-00-612) 63600-101 PKG 1 L1608587 REF:	MOS HRS/MSC AFL	12	+1m/-1m		-17	23-DEC-2019 2630:03 1481	06-DEC-2020	06-JAN-2021
STLMC									
256115-0108	R3 PASSENGER LIFEVEST 63600-101 L1608588 REF:	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		28-JAN-2011 0 0		
256115-0108A	RESTORATION R3 PASSENGER LIFEVEST (25-62-00-601) 63600-101 L1608588 REF:	MOS HRS/MSC AFL	120				01-MAR-2011	01-MAR-2021	
STLMC									
256115-0108B	DETAILED INSPECTION R3 PASSENGER LIFEVEST (25-62-00-612) 63600-101 PKG 1 L1608588 REF:	MOS HRS/MSC AFL	12	+1m/-1m		-17	23-DEC-2019 2630:03 1481	06-DEC-2020	06-JAN-2021
STLMC									

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256115-0109	L4 PASSENGER LIFEVEST 63600-101 L1626946 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
256115-0109A	RESTORATION L4 PASSENGER LIFEVEST (25-62-00-601) 63600-101 L1626946 REF:	MOS HRS/MSC AFL	120				01-APR-2011	01-APR-2021	
256115-0109B	STLMC DETAILED INSPECTION L4 PASSENGER LIFEVEST (25-62-00-612) 63600-101 PKG 1 L1626946 REF:	MOS HRS/MSC AFL	12	+1m/-1m	-17		23-DEC-2019 2630:03 1481	06-DEC-2020	06-JAN-2021
256115-0110	R4 PASSENGER LIFEVEST 63600-101 L1608586 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
256115-0110A	STLMC RESTORATION R4 PASSENGER LIFEVEST (25-62-00-601) 63600-101 L1608586 REF:	MOS HRS/MSC AFL	120				01-MAR-2011	01-MAR-2021	
256115-0110B	STLMC DETAILED INSPECTION R4 PASSENGER LIFEVEST (25-62-00-612) 63600-101 PKG 1 L1608586 REF:	MOS HRS/MSC AFL	12	+1m/-1m	-17		23-DEC-2019 2630:03 1481	06-DEC-2020	06-JAN-2021
256115-0111	L5 PASSENGER LIFE VEST 63600-101 L1630171 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
256115-0111A	STLMC RESTORATION L5 PASSENGER LIFE VEST (25-62-00-601) 63600-101 L1630171 REF:	MOS HRS/MSC AFL	120				01-APR-2011	01-APR-2021	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256115-0111B	DETAILED INSPECTION L5 PASSENGER LIFE VEST (25-62-00-612) 63600-101 PKG 1 L1630171 REF:	MOS HRS/MSC AFL	12	+1m/-1m		-17	23-DEC-2019 2630:03 1481	06-DEC-2020	06-JAN-2021
STLMC									
256115-0112	AFT LAVATORY LIFE VEST 63600-101 L1608589 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
256115-0112A	RESTORATION AFT LAVATORY LIFE VEST (25-62-00-601) 63600-101 L1608589 REF:	MOS HRS/MSC AFL	120				01-MAR-2011	01-MAR-2021	
STLMC									
256115-0112B	DETAILED INSPECTION AFT LAVATORY LIFE VEST (25-62-00-612) 63600-101 PKG 1 L1608589 REF:	MOS HRS/MSC AFL	12	+1m/-1m		-17	23-DEC-2019 2630:03 1481	06-DEC-2020	06-JAN-2021
STLMC									
256200-0101	NO. 1 FWD LIFE RAFT 46FASA-6J1-1-108 4UL-02333 REF:	MOS HRS/MSC AFL	O/C				06-APR-2018 1974:15 1149		
256200-0101B	RESTORATION NO. 1 FWD LIFE RAFT (25-62-00-602) 46FASA-6J1-1-108 4UL-02333 REF:	MOS HRS/MSC AFL	36				07-DEC-2017 1913:50 1121	07-DEC-2020	
STLMC									
256200-0101C	DISCARD NO. 1 FWD LIFE RAFT ELT BATTERY 46FASA-6J1-1-108 4UL-02333 REF:	MOS HRS/MSC AFL	DUE				07-DEC-2017 1913:50 1121	31-OCT-2023 M	
256200-0101D	HYDROSTATIC TEST NO. 1 FWD LIFE RAFT PRESSURE CYLINDER 46FASA-6J1-1-108 4UL-02333 REF:	MOS HRS/MSC AFL	DUE				01-DEC-2017	31-DEC-2022 M	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256200-0101E	DETAILED INSPECTION NO. 1 FWD LIFE RAFT (25-62-00-613) 46FASA-6J1-1-108 4UL-02333 REF:	MOS HRS/MSC AFL	12	+1m/-1m		-16	23-DEC-2019 2630:03 1481	07-DEC-2020	07-JAN-2021
STLMC									
256200-0102	NO. 2 FWD LIFE RAFT 46FASA-6J1-1-108 4UL-02334 REF:	MOS HRS/MSC AFL	O/C				06-APR-2018 1974:15 1149		
256200-0102B	RESTORATION NO. 2 FWD LIFE RAFT (25-62-00-602) 46FASA-6J1-1-108 4UL-02334 REF:	MOS HRS/MSC AFL	36				07-DEC-2017 1913:50 1121	07-DEC-2020	
STLMC									
256200-0102C	DISCARD NO. 2 FWD LIFE RAFT ELT BATTERY 46FASA-6J1-1-108 4UL-02334 REF:	MOS HRS/MSC AFL	DUE				07-DEC-2017 1913:50 1121	31-OCT-2023 M	
256200-0102D	HYDROSTATIC TEST NO. 2 FWD LIFE RAFT PRESSURE CYLINDER 46FASA-6J1-1-108 4UL-02334 REF:	MOS HRS/MSC AFL	DUE				07-DEC-2017 1913:50 1121	31-DEC-2022 M	
256200-0102E	DETAILED INSPECTION NO. 2 FWD LIFE RAFT (25-62-00-613) 46FASA-6J1-1-108 4UL-02334 REF:	MOS HRS/MSC AFL	12	+1m/-1m		-16	23-DEC-2019 2630:03 1481	07-DEC-2020	07-JAN-2021
STLMC									
256200-0103	NO. 3 AFT LIFE RAFT 46FASA-6J1-1-201 4UL-02332 REF:	MOS HRS/MSC AFL	O/C				06-APR-2018 1974:15 1149		
256200-0103B	RESTORATION NO. 3 AFT LIFE RAFT (25-62-00-602) 46FASA-6J1-1-201 4UL-02332 REF:	MOS HRS/MSC AFL	36				07-DEC-2017 1913:50 1121	07-DEC-2020	
STLMC									

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256200-0103C	DISCARD NO. 3 AFT LIFE RAFT ELT BATTERY 46FASA-6J1-1-201 4UL-02332 REF:	MOS HRS/MSC AFL	DUE				07-DEC-2017 1913:50 1121	31-OCT-2023 M	
256200-0103D	HYDROSTATIC TEST NO. 3 AFT LIFE RAFT PRESSURE CYLINDER 46FASA-6J1-1-201 4UL-02332 REF:	MOS HRS/MSC AFL	DUE				07-DEC-2017 1913:50 1121	31-DEC-2022 M	
256200-0103E	DETAILED INSPECTION NO. 3 AFT LIFE RAFT (25-62-00-613) 46FASA-6J1-1-201 4UL-02332 REF:	MOS HRS/MSC AFL	12	+1m/-1m	-16		23-DEC-2019 2630:03 1481	07-DEC-2020	07-JAN-2021
256204	FIRST AID KIT AFAK 92111025 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				31-AUG-2016 1702:09 1001		
257201-0101	SHELF 1005336376-003 550009-6 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
257201-0102	SHELF 1005336377-003 585132-9 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
257201-0103	SHELF 1005336378-003 614616-5 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
257201-0104	SHELF 1005336379-001 550010-4 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
257201-0105	SHELF 1005336379-002 469511-10 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
257201-0106	SHELF 1005337356-001 614602-1 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
257201-0107	SHELF 1005337357-003 558164-1 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
259008-7101	WAVEJET-28VDC MICROWAVE OVEN 400-1338-02-L-N 07-02-40436 REF:	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			31-DEC-2017 1935:08 1127		
259400-7101	IPOD DOCKING STATION IDS0106-002-000 0323 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
CHAPTER 26 FIRE PROTECTION									
26-10-00-604	RESTORATION BAGGAGE COMPARTMENT SMOKE DETECTOR (P/N 473597-19)	MOS HRS/MSC AFL	18 2500	+1m/-1m +40/-40			26-NOV-2019 2630:03 1481	26-MAY-2021 5130:03	26-JUN-2021 5170:03
STLMC	REF:								
26-14-00-201-1 (s)	GENERAL VISUAL INSPECTION LEFT MAIN LANDING GEAR (MLG) WHEEL WELL GROUND WIRE AND TERMINAL PKG 11	MOS HRS/MSC AFL	1600	+40/-40			06-DEC-2018 2236:21 1275		
MRB	REF: AMM 26 14 00 210 801								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-14-00-201-2 (s)	GENERAL VISUAL INSPECTION RIGHT MAIN LANDING GEAR (MLG) WHEEL WELL GROUND WIRE AND TERMINAL PKG 11	MOS HRS/MSC	1600	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 26 14 00 210 801	AFL							
26-14-00-202-1 (s)	FUNCTIONAL TEST LEFT MAIN LANDING GEAR (MLG) OVERHEAT-DETECTION SYSTEM PKG 13	MOS HRS/MSC	3200	+40/-40			PKG 28-JAN-2011 0 0		
MRB	REF: AMM 26 14 00 720 801	AFL							
26-14-00-202-2 (s)	FUNCTIONAL TEST RIGHT MAIN LANDING GEAR (MLG) OVERHEAT-DETECTION SYSTEM PKG 13	MOS HRS/MSC	3200	+40/-40			PKG 28-JAN-2011 0 0		
MRB	REF: AMM 26 14 00 720 801	AFL							
26-15-05-201	RESTORATION BAGGAGE-COMPARTMENT SMOKE DETECTOR (P/N 473597-2)	MOS HRS/MSC	N/A						
MRB	REF: AMM 26 15 05 615 801	AFL							
26-21-00-301 (s)	GENERAL VISUAL INSPECTION ENGINE FIRE-EXTINGUISHING-SYSTEM DISCHARGE-LINES PKG 13	MOS HRS/MSC	3200	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 26 21 00 210 801	AFL							
26-21-00-302 (s)	OPERATIONAL TEST ENGINE FIRE-EXTINGUISHING SYSTEM PKG 12	MOS HRS/MSC	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 26 21 00 710 801	AFL							
26-21-00-303 (s)	OPERATIONAL TEST EICAS FIRE-BOTTLE PRESSURE INDICATION PKG 13	MOS HRS/MSC	3200	+40/-40			PKG 28-JAN-2011 0 0		
MRB	REF: AMM 26 21 00 710 802	AFL							
26-21-00-304 (s)	OPERATIONAL TEST APU FIRE-EXTINGUISHING SYSTEM PKG 12	MOS HRS/MSC	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 26 21 00 710 803	AFL							



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-21-00-305 (s)	GENERAL VISUAL INSPECTION APU FIRE-EXTINGUISHING SYSTEM DISCHARGE LINES PKG 13	MOS HRS/MSC	3200	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 26 21 00 210 802	AFL							
26-21-00-306 (s)	OPERATIONAL TEST L/R ENGINE FIRE PUSH BUTTON ANNUNCIATOR (PBA) PKG 8	MOS HRS/MSC	600	+40/-40			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 26 21 00 710 804	AFL							
26-21-00-307 (s)	OPERATIONAL TEST APU FIRE PUSH BUTTON ANNUNCIATOR (PBA) PKG 8	MOS HRS/MSC	600	+40/-40			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 26 21 00 710 805	AFL							
261101	BAGGAGE COMPARTMENT SMOKE DETECTOR 473597-19 SGA0658 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:28 R:0 N:716:13 R:0 N:360 R:0			23-DEC-2019 2630:03 1481		
261101-0101	FIRE EXTINGUISHER CONTROL UNIT 474112-3 ADB0350 REF: See Workcard	MOS HRS/MSC AFL	O/C				06-DEC-2018 2236:21 1275		
262101-0101	NO. 1 FIRE EXTINGUISHER CONTAINER 474109-4 0539J REF: See Workcard	MOS HRS/MSC AFL	O/C	N:1875:30 N:1114			22-JUL-2013 601:22 339		
+ 262101-0101A	WEIGHT CHECK NO. 1 FIRE EXTINGUISHER CONTAINER (26-21-01-202) 474109-4 0539J REF: AMM 26 21 01 720 802	MOS HRS/MSC AFL	60	+1m/-1m			23-JUN-2018	23-JUN-2023	23-JUL-2023
MRB									
+ 262101-0101B	HYDROSTATIC TEST NO. 1 FIRE EXTINGUISHER CONTAINER (26-21-01-201) 474109-4 0539J REF: AMM 26 21 01 615 801	MOS HRS/MSC AFL	120	+1m/-1m			22-MAY-2013	22-MAY-2023	22-JUN-2023
MRB									



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262101-0102	NO. 2 FIRE EXTINGUISHER CONTAINER 474109-4 1820J REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			23-DEC-2019 2630:03 1481		
262101-0102A	WEIGHT CHECK NO. 2 FIRE EXTINGUISHER CONTAINER (26-21-01-202) 474109-4 1820J REF: AMM 26 21 01 720 802	MOS HRS/MSC AFL	60	+1m/-1m			19-JUL-2019	19-JUL-2024	19-AUG-2024
MRB									
262101-0102B	HYDROSTATIC TEST NO. 2 FIRE EXTINGUISHER CONTAINER (26-21-01-201) 474109-4 1820J REF: AMM 26 21 01 615 801	MOS HRS/MSC AFL	120	+1m/-1m			19-JUL-2019	19-JUL-2029	19-AUG-2029
MRB									
+ 262105-0101	NO. 1 FIRE EXTINGUISHER CONTAINER (A111) LH ENGINE DISCHARGE CARTRIDGE PART NO.: 446518-1 446518-1 ABP4684 REF: See Workcard Manufacture Date: 01-MAR-2011	MOS HRS/MSC AFL	120	N:0			01-MAR-2011 5:48 4	01-MAR-2021	
LIFE LIMIT									
262105-0102	NO. 1 FIRE EXTINGUISHER CONTAINER (A112) RH ENGINE DISCHARGE CARTRIDGE PART NO.: 446518-1 446518-1 ABP4735 REF: See Workcard Manufacture Date: 01-MAR-2011	MOS HRS/MSC AFL	120	N:0 N:0 N:0			01-MAR-2011 5:48 4	01-MAR-2021	
LIFE LIMIT									
+ 262105-0103	NO. 2 FIRE EXTINGUISHER CONTAINER (A113) LH ENGINE DISCHARGE CARTRIDGE PART NO.: 446518-1 446518-1 ABP4682 REF: See Workcard Manufacture Date: 01-MAR-2011	MOS HRS/MSC AFL	120	N:0 N:0 N:0			01-MAR-2011 5:48 4	01-MAR-2021	
LIFE LIMIT									
262105-0104	NO. 2 FIRE EXTINGUISHER CONTAINER (A114) RH ENGINE DISCHARGE CARTRIDGE PART NO.: 446518-1 446518-1 ABP4731 REF: See Workcard Manufacture Date: 01-MAR-2011	MOS HRS/MSC AFL	120	N:0 N:0 N:0			01-MAR-2011 5:48 4	01-MAR-2021	
LIFE LIMIT									



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262105-0105	NO. 2 FIRE EXTINGUISHER CONTAINER (A115) APU DISCHARGE CARTRIDGE PART NO.: 446518-1 446518-1 ABP4776 REF: See Workcard Manufacture Date: 01-MAR-2011	MOS HRS/MSC AFL	120	N:0 N:0 N:0			01-MAR-2011 5:48 4	01-MAR-2021	
262117-0101	CHECK TEE 446651 3311 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
262117-0102	CHECK TEE 446651 3310 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
262301	FLIGHT COMPARTMENT PORTABLE FIRE EXTINGUISHER 30H673 Y-21065 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:90 N:2112:06 N:1211			25-JUL-2018 2112:06 1211		
262301-0102	FWD WARDROBE PORTABLE FIRE EXTINGUISHER 30H673 B-78224660 REF:	MOS HRS/MSC AFL	O/C	N:38 N:926:50 N:479			23-DEC-2019 2630:03 1481		
262301-0102A (s)	WEIGHT CHECK FWD WARDROBE PORTABLE FIRE EXTINGUISHER (25-62-00-609) 30H673 PKG 1 B-78224660 REF:	MOS HRS/MSC AFL	12				PKG 20-DEC-2019		
262301-0102B	RESTORATION FWD WARDROBE PORTABLE FIRE EXTINGUISHER (25-62-00-610) 30H673 B-78224660 REF:	MOS HRS/MSC AFL	72				01-OCT-2016	01-OCT-2022	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262301-0102C	HYDROSTATIC TEST FWD WARDROBE PORTABLE FIRE EXTINGUISHER (25-62-00-611) 30H673 B-78224660 REF:	MOS HRS/MSC AFL	144				01-OCT-2016	01-OCT-2028	
STLMC									
262301-0103	AFT LAVATORY PORTABLE FIRE EXTINGUISHER 466090 Y-110035 REF:	MOS HRS/MSC AFL	O/C	N:107 N:2630:03 N:1481			23-DEC-2019 2630:03 1481		
262301-0103A (s)	WEIGHT CHECK AFT LAVATORY PORTABLE FIRE EXTINGUISHER (25-62-00-609) 466090 PKG 1 Y-110035 REF:	MOS HRS/MSC AFL	12				PKG 20-DEC-2019		
STLMC									
262301-0103C	HYDROSTATIC TEST AFT LAVATORY PORTABLE FIRE EXTINGUISHER (25-62-00-611) 466090 Y-110035 REF:	MOS HRS/MSC AFL	144				01-JAN-2011	01-JAN-2023	
STLMC									
262301A	WEIGHT CHECK FLIGHT COMPARTMENT PORTABLE FIRE EXTINGUISHER (26-23-00-201) 30H673 Y-21065 REF: AMM 26 23 01 720 801	MOS HRS/MSC AFL	36	+1m/-1m			24-JUL-2018	24-JUL-2021	24-AUG-2021
MRB									
262301C	HYDROSTATIC TEST FLIGHT COMPARTMENT PORTABLE FIRE EXTINGUISHER (26-23-00-203) 30H673 Y-21065 REF: AMM 26 23 01 720 802	MOS HRS/MSC AFL	144	+1m/-1m			01-JAN-2011	01-JAN-2023	01-FEB-2023
MRB									
CHAPTER 27	FLIGHT CONTROLS								
27-00-00-201 (s)	DETAILED INSPECTION FLIGHT CONTROL CABLES IN THE FORWARD FUSELAGE- (FS220.00 TO FS326.00) PKG 12 REF: AMM 27 00 00 220 801	MOS HRS/MSC AFL	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB									

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-202 (s)	DETAILED INSPECTION FLIGHT CONTROL CABLES UNDER THE CABIN FLOOR- (FS326.00 TO FS669.76)						PKG		
	PKG 5	MOS	96	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 27 00 00 220 802	HRS/MSC AFL					2630:03 1481		
27-00-00-204 (s)	DETAILED INSPECTION FLIGHT CONTROL ROUTING IN THE INBOARD AND OUTBOARD TRAILING EDGES- (WS35.60 TO WS292.00)						PKG		
	PKG 4	MOS	48	+1m/-1m			07-DEC-2017		
MRB	REF: AMM 27 00 00 220 803	HRS/MSC AFL					1913:50 1121		
27-00-00-205 (s)	OPERATIONAL TEST FLIGHT CONTROL POWER-CONTROL UNITS (PCU)						PKG		
	PKG 9	MOS					23-DEC-2019		
MRB	REF: AMM 27 00 00 710 801	HRS/MSC AFL	800	+40/-40			2630:03 1481		
27-00-00-206 (s)	GENERAL VISUAL INSPECTION FLIGHT CONTROL ROUTING IN THE AFT EQUIPMENT COMPARTMENT- (FS669.76 TO REAR SPAR DATUM)						PKG		
	PKG 4	MOS	48	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 27 00 00 210 802	HRS/MSC AFL					2630:03 1481		
27-00-00-207 (s)	DETAILED INSPECTION FLIGHT CONTROL CABLES IN THE AFT EQUIPMENT COMPARTMENT- (FS669.76 TO FS788.53)						PKG		
	PKG 4	MOS	48	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 27 00 00 220 805	HRS/MSC AFL					2630:03 1481		
27-00-00-208 (s)	DETAILED INSPECTION FLIGHT CONTROL ROUTING IN THE OUTBOARD WING - (WS292.00 TO WS370.00)						PKG		
	PKG 4	MOS	48	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 27 00 00 220 809	HRS/MSC AFL					2630:03 1481		
27-00-00-209 (s)	DETAILED INSPECTION FLIGHT CONTROL ROUTING IN THE VERTICAL STABILIZER- (FRONT SPAR TO REAR SPAR)						PKG		
	PKG 5	MOS	96	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 27 00 00 220 806	HRS/MSC AFL					2630:03 1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-303 (s)	DETAILED INSPECTION FLIGHT CONTROL ROUTING AND AILERON GUST LOCK ASSEMBLY IN THE MAIN LANDING GEAR (MLG) WHEEL WELL						PKG		
	PKG 2	MOS	24	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 27 00 00 220 804	HRS/MSC AFL					2630:03 1481		
27-00-00-308 (s)	DETAILED INSPECTION RUDDER CONTROL PATH IN THE VERTICAL STABILIZER- (FRONT SPAR TO REAR SPAR)						PKG		
	PKG 5	MOS	96	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 27 21 00 220 803	HRS/MSC AFL					2630:03 1481		
27-00-00-309 (s)	DETAILED INSPECTION ELEVATOR CENTERING SPRING CARTRIDGE						PKG		
	PKG 4	MOS	48	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 27 31 27 220 801	HRS/MSC AFL					2630:03 1481		
27-00-00-310 (s)	DETAILED INSPECTION RUDDER POWER CONTROL UNIT (PCU) CENTERING SPRING						PKG		
	PKG 4	MOS	48	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 27 21 00 220 805	HRS/MSC AFL					2630:03 1481		
27-10-00-101	GENERAL VISUAL INSPECTION AILERON GEARED TAB MECHANISM - CONTROL RODS								
		MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 27 11 21 210 802	HRS/MSC AFL	7500				0 0		7500
27-10-00-102	SPECIAL DETAILED INSPECTION AILERON GEARED TAB MECHANISM - FITTINGS								
		MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-27-10-001	HRS/MSC AFL	7500				0 0		7500
27-10-00-103	DETAILED INSPECTION AILERON GEARED TAB MECHANISM - PINS								
		MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 27 11 21 220 804	HRS/MSC AFL	7500				0 0		7500
27-10-00-104	RESTORATION MPE43 - AILERON TRIM TAB ACTUATOR								
	1002710029-003	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 27 12 05 610 801	HRS/MSC AFL	7500				0 0		7500

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-10-00-105	DETAILED INSPECTION AILERON TRIM TAB MECHANISM - PINS AND CRANKS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 27 12 09 220 804	HRS/MSC AFL	7500				0 0		7500
27-10-00-107	SPECIAL DETAILED INSPECTION AILERON TRIM TAB MECHANISM - FITTINGS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-27-10-002	HRS/MSC AFL	7500				0 0		7500
27-10-00-109	GENERAL VISUAL INSPECTION AILERON TRIM TAB MECHANISM -RODS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 27 12 09 210 802	HRS/MSC AFL	7500				0 0		7500
27-11-00-202-1	FUNCTIONAL TEST OF LEFT AILERON CABLE TENSION - WING CABLES (WS35.60 TO WS292.00)	MOS					06-DEC-2018		
MRB	REF: AMM 27 11 00 720 801	HRS/MSC AFL	1200	+40/-40			2236:21 1275	3436:21	3476:21
27-11-00-202-2	FUNCTIONAL TEST OF RIGHT AILERON CABLE TENSION - WING CABLES (WS35.60 TO WS292.00)	MOS					06-DEC-2018		
MRB	REF: AMM 27 11 00 720 801	HRS/MSC AFL	1200	+40/-40			2236:21 1275	3436:21	3476:21
27-11-00-203 (s)	FUNCTIONAL TEST OF THE AILERON CABLE TENSION - AUTOPILOT, CONTROL COLUMN AND FUSELAGE CABLES	MOS					PKG		
MRB	PKG 11 REF: AMM 27 11 00 720 805	HRS/MSC AFL	1600	+40/-40			06-DEC-2018 2236:21 1275		
27-11-00-301 (s)	OPERATIONAL TEST AILERON DISCONNECT SYSTEM	MOS					PKG		
MRB	PKG 8 REF: AMM 27 11 00 710 801	HRS/MSC AFL	600	+40/-40			23-DEC-2019 2630:03 1481		
27-11-00-303 (s)	FUNCTIONAL TEST (BACKLASH) OF AILERON SYSTEM	MOS					PKG		
MRB	PKG 15 REF: AMM 27 11 00 720 804	HRS/MSC AFL	9600	+40/-40			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-11-01-301 (s)	OPERATIONAL TEST SECONDARY LOAD PATH FOR THE PILOT CONTROL WHEEL PKG 15	MOS HRS/MSC	9600	+40/-40			PKG 28-JAN-2011 0		
MRB	REF: AMM 27 11 01 710 801	AFL					0		
27-11-17-201	LUBRICATION AILERON BRUSH SEALS	MOS HRS/MSC	12 600	+1m/-1m +40/-40		-50	23-DEC-2019 2630:03 1481	03-NOV-2020 3230:03	03-DEC-2020 3270:03
MRB	REF: AMM 12 22 00 640 816	AFL							
27-11-21-301 (s)	DETAILED INSPECTION MECHANISM FOR THE AILERON BALANCE GEARED-TAB PKG 4	MOS HRS/MSC	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 27 11 21 220 802	AFL							
27-11-21-302-1 (s)	FUNCTIONAL TEST LEFT AILERON GEARED-TAB LINKAGE BACKLASH PKG 12	MOS HRS/MSC	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 27 11 21 720 801	AFL							
27-11-21-302-2 (s)	FUNCTIONAL TEST RIGHT AILERON GEARED-TAB LINKAGE BACKLASH PKG 12	MOS HRS/MSC	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 27 11 21 720 801	AFL							
27-11-21-303-1 (s)	DETAILED INSPECTION LEFT LINKAGE FOR THE AILERON GEAR TAB PKG 4	MOS HRS/MSC	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 27 11 21 220 805	AFL							
27-11-21-303-2 (s)	DETAILED INSPECTION RIGHT LINKAGE FOR THE AILERON GEAR TAB PKG 4	MOS HRS/MSC	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 27 11 21 220 805	AFL							
27-11-25-201 (s)	GENERAL VISUAL INSPECTION ROLL DAMPER AND THE ROLL DAMPER QUADRANT ASSEMBLY PKG 5	MOS HRS/MSC	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 27 11 25 210 802	AFL							

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-12-05-301 (s)	RESTORATION (OVERHAUL) OF THE AILERON TRIM ACTUATOR PKG 15	MOS HRS/MSC	9600	+40/-40			PKG 28-JAN-2011 0 0		
MRB	REF: AMM 27 12 05 610 801	AFL							
27-12-09-301 (s)	DETAILED INSPECTION AILERON TRIM TAB MECHANISM PKG 4	MOS HRS/MSC	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 27 12 09 220 802	AFL							
27-12-09-302 (s)	FUNCTIONAL TEST AILERON TRIM-TAB LINKAGE BACKLASH PKG 12	MOS HRS/MSC	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 27 12 09 720 801	AFL							
27-12-21-301 (s)	DETAILED INSPECTION AILERON TRIM TAB-LINKAGE PKG 4	MOS HRS/MSC	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 27 12 09 220 802	AFL							
27-21-00-101	OPERATIONAL TEST RUDDER PCU MAIN CONTROL VALVE (MCV) JAM DETECTION	MOS HRS/MSC	5400				28-JAN-2011 0 0	5400	
	REF: AMM 27 21 05 710 801	AFL							
27-21-00-102	FUNCTIONAL TEST RUDDER PCU FOR INTERNAL LEAKAGE	MOS HRS/MSC	5400				28-JAN-2011 0 0	5400	
	REF: AMM 27 21 05 720 801	AFL							
27-21-00-201 (s)	FUNCTIONAL TEST RUDDER CABLE TENSION PKG 11	MOS HRS/MSC	1600	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 27 21 00 720 802	AFL							
27-21-00-202 (s)	DETAILED INSPECTION RUDDER PEDALS PKG 4	MOS HRS/MSC	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 27 21 00 220 801	AFL							

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-21-00-303 (s)	DETAILED INSPECTION RUDDER TRAVEL LIMITER PKG 13	MOS					PKG		
MRB	REF: AMM 27 21 00 220 804	HRS/MSC AFL	3200	+40/-40			28-JAN-2011 0 0		
27-21-00-304 (s)	FUNCTIONAL TEST RUDDER BACKLASH PKG 12	MOS					PKG		
MRB	REF: AMM 27 21 00 720 803	HRS/MSC AFL	2400	+40/-40			06-DEC-2018 2236:21 1275		
27-21-05-202	LUBRICATION RUDDER POWER-CONTROL UNIT (PCU) ATTACHMENT LINK	MOS	48	+1m/-1m					
MRB	REF: AMM 27 21 05 640 801	HRS/MSC AFL	1200	+40/-40	-32		06-DEC-2018 2236:21 1275	04-NOV-2022 3436:21	04-DEC-2022 3476:21
27-21-13-201 (s)	LUBRICATION RUDDER CONTROL SURFACE HINGES PKG 4	MOS	48	+1m/-1m			PKG		
MRB	REF: AMM 12 22 00 640 819	HRS/MSC AFL					23-DEC-2019 2630:03 1481		
27-30-00-101	FUNCTIONAL TEST (LEAK CHECK) ELEVATOR POWER CONTROL UNIT (PCU)	MOS							
	REF: AMM 27 31 09 720 801	HRS/MSC AFL	4500				28-JAN-2011 0 0	4500	
27-30-00-102	FUNCTIONAL TEST ELEVATOR POWER CONTROL UNIT (PCU) MAIN CONTROL-VALVE	MOS							
	REF: AMM 27 31 09 720 802	HRS/MSC AFL	4500				28-JAN-2011 0 0	4500	
27-30-00-301 (s)	DETAILED INSPECTION ELEVATOR TORQUE TUBE CENTERING MECHANISM PKG 4	MOS	48	+1m/-1m			PKG		
MRB	REF: AMM 27 31 05 220 801	HRS/MSC AFL					23-DEC-2019 2630:03 1481		
27-30-00-302 (s)	DETAILED INSPECTION FLIGHT CONTROL ROUTING IN THE HORIZONTAL STABILIZER PKG 5	MOS	96	+1m/-1m			PKG		
MRB	REF: AMM 27 00 00 220 807	HRS/MSC AFL					23-DEC-2019 2630:03 1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-31-00-201-1 (s)	FUNCTIONAL TEST LEFT ELEVATOR CABLE TENSION PKG 11	MOS					PKG		
MRB	REF: AMM 27 31 00 720 801	HRS/MSC AFL	1600	+40/-40			23-DEC-2019 2630:03 1481		
27-31-00-201-2 (s)	FUNCTIONAL TEST RIGHT ELEVATOR CABLE TENSION PKG 11	MOS					PKG		
MRB	REF: AMM 27 31 00 720 801	HRS/MSC AFL	1600	+40/-40			23-DEC-2019 2630:03 1481		
27-31-00-202 (s)	FUNCTIONAL TEST ELEVATOR CONTROL MANUAL REVERSION PKG 11	MOS					PKG		
MRB	REF: AMM 27 31 00 720 803	HRS/MSC AFL	1600	+40/-40			06-DEC-2018 2236:21 1275		
27-31-01-301 (s)	OPERATIONAL TEST PITCH DISCONNECT MECHANISM PKG 10	MOS					PKG		
MRB	REF: AMM 27 31 01 710 801	HRS/MSC AFL	1200	+40/-40			06-DEC-2018 2236:21 1275		
27-31-09-202-1	LUBRICATION LEFT ELEVATOR POWER-CONTROL UNIT (PCU) ATTACHMENT LINK	MOS	48	+1m/-1m			06-DEC-2018	06-DEC-2022	06-JAN-2023
MRB	REF: AMM 27 31 09 640 801	HRS/MSC AFL	1600	+40/-40			2236:21 1275	3836:21	3876:21
27-31-09-202-2	LUBRICATION RIGHT ELEVATOR POWER-CONTROL UNIT (PCU) ATTACHMENT LINK	MOS	48	+1m/-1m			06-DEC-2018	06-DEC-2022	06-JAN-2023
MRB	REF: AMM 27 31 09 640 801	HRS/MSC AFL	1600	+40/-40			2236:21 1275	3836:21	3876:21
27-31-09-301-1 (s)	FUNCTIONAL TEST LEFT ELEVATOR POWER-CONTROL UNIT (PCU) PKG 13	MOS					PKG		
MRB	REF: AMM 27 31 09 720 804	HRS/MSC AFL	3200	+40/-40			28-JAN-2011 0 0		
27-31-09-301-2 (s)	FUNCTIONAL TEST RIGHT ELEVATOR POWER-CONTROL UNIT (PCU) PKG 13	MOS					PKG		
MRB	REF: AMM 27 31 09 720 804	HRS/MSC AFL	3200	+40/-40			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-31-17-201-1 (s)	LUBRICATION LEFT ELEVATOR CONTROL SURFACE HINGES PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 12 22 00 640 820								
27-31-17-201-2 (s)	LUBRICATION RIGHT ELEVATOR CONTROL SURFACE HINGES PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 12 22 00 640 820								
27-31-17-302 (s)	FUNCTIONAL TEST ELEVATOR CONTROL SURFACE BACKLASH PKG 13	MOS HRS/MSC AFL	3200	+40/-40			PKG 28-JAN-2011 0 0		
MRB	REF: AMM 27 31 17 720 801								
27-32-00-301 (s)	OPERATIONAL TEST AUTOMATIC AUTOPILOT DISCONNECT PKG 11	MOS HRS/MSC AFL	1600	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 27 32 00 710 802								
27-33-01-301-1 (s)	FUNCTIONAL TEST LEFT ELEVATOR PITCH FEEL SIMULATOR PKG 13	MOS HRS/MSC AFL	3200	+40/-40			PKG 28-JAN-2011 0 0		
MRB	REF: AMM 27 33 01 720 801								
27-33-01-301-2 (s)	FUNCTIONAL TEST RIGHT ELEVATOR PITCH FEEL SIMULATOR PKG 13	MOS HRS/MSC AFL	3200	+40/-40			PKG 28-JAN-2011 0 0		
MRB	REF: AMM 27 33 01 720 801								
27-40-00-104	RESTORATION (HSTA) HORIZONTAL STABILIZER TRIM ACTUATOR (OVERHAUL) HORIZONTAL-STABILIZER TRIM-ACTUATOR (HSTA) PART NO. C47100-004 C47100-004 0341	MOS HRS/MSC AFL	10000			I:2925:18	23-DEC-2019 2630:03 1481	9704:45	
MRB	REF: AMM 27 41 05 610 801								
27-40-00-105	FUNCTIONAL TEST (HSTA) HORIZONTAL STABILIZER TRIM ACTUATOR HSTA TORQUE LIMITER C47100-004 0341	MOS HRS/MSC AFL	3000				23-DEC-2019 2630:03 1481	5630:03	
MRB	REF: AMM 27 41 05 720 801								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40-00-106 (s)	LUBRICATION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) PKG 11	MOS					PKG 23-DEC-2019 2630:03 1481		
	REF: AMM 12 22 00 640 809	HRS/MSC AFL	1600	+40/-40					
27-40-00-107	FUNCTIONAL TEST (HSTA) HORIZONTAL STABILIZER TRIM ACTUATOR HORIZONTAL STABILIZER-TRIM ACTUATOR (HSTA) NO BACK C47100-004 0341	MOS					23-DEC-2019 2630:03 1481	5630:03	
	REF: AMM 27 41 05 720 802	HRS/MSC AFL	3000						
27-40-00-201	SPECIAL DETAILED INSPECTION HORIZONTAL-STABILIZER TRIM-ACTUATOR	MOS					28-JAN-2011 0		
MRB	REF: AMM 27 41 00 280 801	HRS/MSC AFL	7500	+40/-40			0	7500	7540
27-41-05-101	RESTORATION HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) (PN C47100-003)	MOS							
	REF: AMM 27 41 05 610 801	HRS/MSC AFL	N/A						
27-41-05-104	RESTORATION (OVERHAUL) (HSTA) HORIZONTAL STABILIZER TRIM ACTUATOR (PART NO. C47100-004) C47100-004 0341	MOS					23-DEC-2019 2630:03 1481		
AIRWORTHINESS	REF: AMM 27 41 05 610 801	HRS/MSC AFL	7500	I:1500				7481	
27-41-05-105	FUNCTIONAL TEST HORIZONTAL STABILIZER-TRIM ACTUATOR (HSTA) BRAKE SYSTEM C47329-012 605	MOS							
	REF: AMM 27 41 05 720 803	HRS/MSC AFL	N/A						
27-41-05-301 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER-TRIM ACTUATOR (HSTA) FULL RANGE TRIMMING PKG 9	MOS					PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 27 41 05 710 801	HRS/MSC AFL	800	+40/-40					
27-50-00-105 (s)	FUNCTIONAL TEST INBOARD AND OUTBOARD FLAP ACTUATOR TORQUE LIMITERS PKG 12	MOS					PKG 06-DEC-2018 2236:21 1275		
	REF: AMM 27 52 00 720 804	HRS/MSC AFL	2400						

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50-00-106 (s)	FUNCTIONAL TEST FLAP ALTERNATE HYDRAULIC-SYSTEM PKG 7	MOS HRS/MSC	400				PKG 23-DEC-2019 2630:03 1481		
	REF: AMM 27 52 00 720 802	AFL							
27-50-00-107	DETAILED INSPECTION INBOARD AND OUTBOARD FLAP ACTUATOR	MOS HRS/MSC					06-DEC-2018 2236:21 1275		
CMR	REF: See Workcard	AFL	450					1725	
27-50-00-108	FUNCTIONAL TEST INBOARD AND OUTBOARD FLAP ACTUATORS	MOS HRS/MSC					06-DEC-2018 2236:21 1275		
	REF: AMM 27 52 00 720 803	AFL	450					1725	
27-52-00-203 (s)	SERVICING FLAP SYSTEM PKG 12	MOS HRS/MSC	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 27 52 00 610 801	AFL							
27-52-01-201 (s)	LUBRICATION FLEXIBLE SHAFTS OF THE FLAP SYSTEM PKG 9	MOS HRS/MSC	800	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 12 22 00 640 817	AFL							
27-52-01-202 (s)	GENERAL VISUAL INSPECTION FLEXIBLE SHAFTS OF THE FLAP SYSTEM PKG 11	MOS HRS/MSC	1600	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 27 52 01 210 801	AFL							
27-52-09-201 (s)	GENERAL VISUAL INSPECTION ADAPTOR GEARBOX OF THE FLAP SYSTEM PKG 9	MOS HRS/MSC	800	+40/-40			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 27 52 09 210 801	AFL							
27-52-13-201-1	LUBRICATION LEFT INBOARD AND OUTBOARD FLAP ACTUATOR	MOS HRS/MSC	12 600	+1m/-1m +40/-40		-50	23-DEC-2019 2630:03 1481	03-NOV-2020 3230:03	03-DEC-2020 3270:03
MRB	REF: AMM 27 52 00 640 801	AFL							

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-52-13-201-2	LUBRICATION RIGHT INBOARD AND OUTBOARD FLAP ACTUATOR	MOS	12	+1m/-1m		-14	23-DEC-2019	09-DEC-2020	09-JAN-2021
MRB	REF: AMM 27 52 00 640 801	HRS/MSC AFL	600	+40/-40			2630:03 1481	3230:03	3270:03
27-52-19-301 (s)	GENERAL VISUAL INSPECTION FLAP TRANSMISSION BRAKE	MOS					PKG		
MRB	PKG 9 REF: AMM 27 52 19 210 801	HRS/MSC AFL	800	+40/-40			23-DEC-2019 2630:03 1481		
27-52-29-301	DETAILED INSPECTION OF THE FLAP ROLLER CARRIAGE ROLLERS	MOS	24	+1m/-1m		-48	23-DEC-2019	05-NOV-2021	05-DEC-2021
MRB	REF: AMM 27 52 29 220 801	HRS/MSC AFL	1200	+40/-40			2630:03 1481	3830:03	3870:03
27-52-33-301 (s)	GENERAL VISUAL INSPECTION FLAP POWER UNIT (FPU)	MOS					PKG		
MRB	PKG 9 REF: AMM 27 52 33 210 801	HRS/MSC AFL	800	+40/-40			23-DEC-2019 2630:03 1481		
27-52-35-201 (s)	GENERAL VISUAL INSPECTION FLAP POWER UNIT (FPU) ECOLOGY BOTTLE	MOS					PKG		
MRB	PKG 11 REF: AMM 27 52 35 210 801	HRS/MSC AFL	1600	+40/-40			23-DEC-2019 2630:03 1481		
27-61-00-301 (s)	OPERATIONAL TEST FLIGHT SPOILER EMERGENCY DESCENT CAPABILITY	MOS					PKG		
MRB	PKG 9 REF: AMM 27 61 01 710 802	HRS/MSC AFL	800	+40/-40			06-DEC-2018 2236:21 1275		
27-62-00-301 (s)	OPERATIONAL TEST HOLD-DOWN CHECK RELIEF-VALVE IN THE MULTI-FUNCTION SPOILER POWER-CONTROL UNIT (MFS PCU) AND THE GROUND-SPOILER SELECTOR VALVE (GSSV)	MOS					PKG		
MRB	PKG 13 REF: AMM 27 62 00 710 803	HRS/MSC AFL	3200	+40/-40			28-JAN-2011 0 0		
271010-0101	PILOT HANDWHEEL	MOS							
	1002710020-005	HRS/MSC					28-JAN-2011		
	20317	O/C					0		
	REF: GENERIC NO REF	AFL					0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271010-0102	COPILOT RH HANDWHEEL 1002710021-005 20317 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
271101-0101	PILOT CONTROL WHEEL 1002710011-001 346 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
271101-0102	COPILOT CONTROL WHEEL 1002710011-002 338 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
271113-0101	AILERON DUAL CHANNEL (MPE45) POSITION SENSOR 1002710031-001 U0166 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
271113-0102	AILERON SINGLE CHANNEL (MPE46) POSITION SENSOR 1002710030-001 N9203 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
271117-0101	LH AILERON ASSEMBLY 1005761051-003 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
271117-0102	RH AILERON ASSEMBLY 1005761052-003 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
271121-0101	LH AILERON BALANCE GEARED - TAB ASSEMBLY 1005761053-001 20316 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271121-0102	RH AILERON BALANCE GEARED - TAB ASSEMBLY 1005761053-002 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
271125-0101	PILOT CONTROL COLUMN ROLL DAMPER 1002710042-003 341 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
271125-0102	COPILOT CONTROL COLUMN ROLL DAMPER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
271129-0101	LH UNDER FLOOR (MT111) ROLL FORCE SENSOR 1002710034-003 FR5043 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
271129-0102	RH UNDER FLOOR (MT112) ROLL FORCE SENSOR 1002710034-003 FR5042 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
271133-0101	LH CONTROL-WHEEL (MT125) POSITION SENSOR 1002710052-007 B0720 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
271133-0102	RH CONTROL-WHEEL (MT126) POSITION SENSOR 1002710052-007 B0715 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
271205-0101	MPE43 - AILERON TRIM TAB ACTUATOR 1002710029-003 354 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271209-0101	AILERON TRIM TAB ASSEMBLY 1005761054-001 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
272105-0101	UPPER RUDDER POWER CONTROL UNIT 1002720025-009 2160 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
272105-0102	LOWER RUDDER POWER CONTROL UNIT 1002720025-009 2165 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
272109	RUDDER DUAL CHANNEL - POSITION SENSOR 1002710031-001 P2268 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
272113	RUDDER ASSEMBLY 1005541000-001 336 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
272117-0101	PILOT PITCH SENSOR 1002720015-005 FR5045 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
272117-0102	COPILOT PITCH SENSOR 1002720015-005 FR5044 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
272121	RUDDER CONTROL FEEL UNIT 1002720026-003 FR0271 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
272125-0101	PILOT RUDDER PEDAL ADJUST ACTUATOR 1002720028-005 757 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
272125-0102	COPILOT RUDDER PEDAL ADJUST ACTUATOR 1002720028-005 758 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
272201-0101	NO. 1 VERTICAL STABILIZER - RUDDER TRIM ACTUATOR 1002720027-007 341 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
272201-0201	RUDDER CENTERING SPRING 1002720112-007 325 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
272205-0101	RUDDER LIMITER ACTUATOR 1002720018-003 349 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
272205-0201	RUDDER SINGLE CHANNEL POSITION SENSOR 1002710030-001 P2157 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273101-0101	CENTER PEDESTAL CENTER PEDESTAL - DISCONNECT PITCH HANDLE 1002730013-005 438 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273101-0201	CONTROL COLUMN ASSEMBLY 1002730140-011 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273105-0101	LEFT ELEVATOR CONTROL SPLIT ROD ASSEMBLY 1002730145-001 678 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273105-0102	RIGHT ELEVATOR CONTROL SPLIT ROD ASSEMBLY 1002730145-001 684 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273105-0201	LEFT HAND ELEVATOR - CENTERING SPRING CARTRIDGE 1002730144-005 633 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273105-0202	RIGHT HAND ELEVATOR - CENTERING SPRING CARTRIDGE 1002730144-005 670 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273109-0101	LEFT OUTBOARD ELEVATOR POWER CONTROL UNIT 1002730031-009 2325 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273109-0102	LEFT INBOARD ELEVATOR POWER CONTROL UNIT 1002730031-009 2326 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273109-0103	RIGHT INBOARD ELEVATOR POWER CONTROL UNIT 1002730031-009 2328 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273109-0104	RIGHT OUTBOARD ELEVATOR POWER CONTROL UNIT 1002730031-009 2335 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273113-0101	ELEVATOR DUAL CHANNEL - POSITION SENSOR 1002710031-001 P2269 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273113-0102	ELEVATOR SINGLE CHANNEL POSITION SENSOR 1002710030-001 T6559 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273115-0101	PILOT CONTROL COLUMN POSITION MPE53 - POSITION SINGLE SENSOR 1002730009-001 103448 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273115-0102	COPILOT CONTROL COLUMN POSITION MPE54 - POSITION SINGLE SENSOR 1002730009-001 106293 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273117-0101	LEFT ELEVATOR 1005521000-003 293 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273117-0102	RIGHT ELEVATOR 1005521000-004 293 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273121-0101	PILOT FORCE PITCH SENSOR 1002730015-003 FR5006 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273121-0102	COPILOT FORCE PITCH SENSOR 1002730015-003 FR5046 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273127-0101	LEFT ELEVATOR CONTROL VERTICAL STABILIZER LOCKOUT - HYDRAULIC ROD 1002730141-005 720 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273127-0102	RIGHT ELEVATOR CONTROL VERTICAL STABILIZER LOCKOUT - HYDRAULIC ROD 1002730141-005 655 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273131-0101	LEFT ELEVATOR CONTROL VERTICAL STABILIZER CONTROL ROD (SHEAR OUT ROD) ASSEMBLY 1002730142-003 653 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273131-0102	RIGHT ELEVATOR CONTROL VERTICAL STABILIZER CONTROL ROD (SHEAR OUT ROD) ASSEMBLY 1002730142-003 654 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273201	EQUIP RACK LH A178 STALL PROTECTION (SPC) COMPUTER 822-1792-003 48T8P REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273205-0101	CONTROL COLUMN A179 STICK SHAKER GH582-3003-1 1633 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273205-0102	CONTROL COLUMN A180 STICK SHAKER GH582-3003-1 1605 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273209-0101	LEFT ANGLE OF ATTACK (AOA) TRANSDUCER 0861GT 674 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273209-0102	RIGHT ANGLE OF ATTACK (AOA) TRANSDUCER 0861GT 675 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273213	COCKPIT UNDERFLOOR - STICK 501-1770-05 80258 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273217	COCKPIT UNDERFLOOR STICK 501-1771-05 80260 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273301-0101	LEFT VERTICAL STABILIZER PITCH FEEL SIMULATOR 1002730032-007 605 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
273301-0102	RIGHT VERTICAL STABILIZER PITCH FEEL SIMULATOR 1002730032-007 665 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
274105	(HSTA) HORIZONTAL STABILIZER TRIM ACTUATOR C47100-004 0341 REF: See Workcard	MOS HRS/MSC AFL	5800	R:0 N:2925:18 R:0 N:1500 R:0			23-DEC-2019 2630:03 1481		5781
274109-0101	(HSTA) PRIMARY MOTOR & BRAKE ASSEMBLY C47187-005 764 REF: See Workcard	MOS HRS/MSC AFL	5800	N:0 N:0 N:0			28-JAN-2011 0 0		5800
274109-0102	(HSTA) SECONDARY MOTOR & BRAKE ASSEMBLY C47187-006 765 REF: See Workcard	MOS HRS/MSC AFL	5800	N:0 N:0 N:0			28-JAN-2011 0 0		5800

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
274113	VERT STAB A131 HSTA MOTOR CONTROL UNIT C47331-005 567 REF: See Workcard	MOS HRS/MSC AFL	O/C				10-FEB-2019 2320:16 1317		
274121	(HSTECU) HORIZONTAL STABILIZER - TRIM ELECTRONIC CONTROL UNIT C47329-012 605 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			19-SEP-2019 2598:17 1463		
274125-0101	PRIMARY HSTB PIVOT BUSHING 1005510801-001 633 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
274125-0102	PRIMARY HSTB PIVOT BUSHING 1005510801-001 632 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
274125-0103	SECONDARY HSTB PIVOT BUSHING 1005510802-005 3043 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275101	A120 CONTROL LEVER FLAP 1760A0000-05 778 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275105	LH EQUIP RACK (A124) FCU FLAP CONTROL UNIT 10239750 480 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275201-0101	LEFT FLAP FLEXIBLE SHAFT 9148A0013-02 1463 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275201-0102	RIGHT FLAP FLEXIBLE SHAFT 9148A0013-02 1461 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275205-0101	LEFT FLAP SYSTEM NO.1 HARD SHAFT 1761A0800-01 33308-0080 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275205-0102	RIGHT FLAP SYSTEM NO.1 HARD SHAFT 1761A0800-01 33308-0103 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275205-0103	LEFT FLAP SYSTEM NO.2 HARD SHAFT 1761A0900-01 33309-0150 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275205-0104	RIGHT FLAP SYSTEM NO.2 HARD SHAFT 1761A0900-01 33309-0132 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275205-0105	LEFT FLAP SYSTEM NO.3 HARD SHAFT 1761A1000-01 33310-0037 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275205-0106	RIGHT FLAP SYSTEM NO.3 HARD SHAFT 1761A1000-01 33310-0009 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275205-0113	LEFT OUTBOARD ACTUATOR TO HARD SHAFT NO 3 - UNIVERSAL JOINT 1761A0100-02 4198 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275205-0114	RIGHT FLEXSHAFT TO HARD SHAFT NO 1 - UNIVERSAL JOINT 1761A0100-02 4196 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275205-0115	LEFT HARD SHAFT NO 3 TO FLAP TRANS BRAKE - UNIVERSAL JOINT 1761A0100-02 4207 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275205-0116	RIGHT HARD SHAFT NO 1 TO INBOARD ACTUATOR - UNIVERSAL JOINT 1761A0100-02 4199 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275205-0117	LEFT FLAP TRANS BRAKE TO HARD SHAFT NO 2 - UNIVERSAL JOINT 1761A0100-02 4209 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275205-0118	RIGHT INBOARD ACTUATOR TO HARD SHAFT NO 2 - UNIVERSAL JOINT 1761A0100-02 4204 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275205-0119	LEFT HARD SHAFT NO 2 TO INBOARD ACTUATOR - UNIVERSAL JOINT 1761A0100-02 4212 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275205-0120	RIGHT HARD SHAFT NO 2 TO FLAP TRANS BRAKE - UNIVERSAL JOINT 1761A0100-02 4205 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275205-0121	LEFT INBOARD ACTUATOR TO HARD SHAFT NO 1 - UNIVERSAL JOINT 1761A0100-02 4215 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275205-0122	RIGHT FLAP TRANS BRAKE TO HARD SHAFT NO 3 - UNIVERSAL JOINT 1761A0100-02 4208 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275205-0123	LEFT HARD SHAFT NO 1 TO FLEXSHAFT - UNIVERSAL JOINT 1761A0100-02 4218 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275205-0124	RIGHT HARD SHAFT NO 3 TO OUTBOARD ACT - UNIVERSAL JOINT 1761A0100-02 4216 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275209-0101	LEFT FLAP SYSTEM GEARBOX ADAPTER 1755A0000-01 769 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275209-0102	RIGHT FLAP SYSTEM GEARBOX ADAPTER 1755A0000-01 770 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275213-0101	L/H FLAP INBOARD ACTUATOR 2252A0000-01 529 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275213-0102	R/H FLAP INBOARD ACTUATOR 2252B0000-01 514 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275215-0101	L/H FLAP OUTBOARD ACTUATOR 2253A0000-01 523 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275215-0102	R/H FLAP OUTBOARD ACTUATOR 79889650 525 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275215-0201	FLAP INBOARD ACTUATOR (WING STATION (WS)122 LEFT) BOLT 1005756020-001 STR0557 REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
275215-0202	FLAP INBOARD ACTUATOR (WING STATION (WS)122 RIGHT) 1005756020-001 STR0549 REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
275215-0203	FLAP OUTBOARD ACTUATOR (WING STATION (WS)202 LEFT) 1005756020-003 STR0444 REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
275215-0204	FLAP OUTBOARD ACTUATOR (WING STATION (WS)202 RIGHT) 1005756020-003 STR0408 REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
275217-0101	LH FLAP POSITION SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275217-0102	RH FLAP POSITION SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275219-0101	LEFT A203 TRANSMISSION BRAKE FLAP 2264A0000-02 759 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275219-0102	RIGHT A204 TRANSMISSION BRAKE FLAP 2264A0000-02 760 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
275229-0101	LH MIDDLE FLAP SUPPORT ROLLER CARRIAGE BEARING ATF-4 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
275229-0102	RH MIDDLE FLAP SUPPORT ROLLER CARRIAGE BEARING ATF-4 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
275229-0103	LH MIDDLE FLAP SUPPORT ROLLER CARRIAGE BEARING ATF-4 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
275229-0104	RH MIDDLE FLAP SUPPORT ROLLER CARRIAGE BEARING ATF-4 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
275229-0201	LH INBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-001 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
275229-0202	RH INBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-001 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
275229-0203	LH INBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-001 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275229-0204	RH INBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-001 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0205	LH INBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-001 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0206	RH INBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-001 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0207	LH INBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-001 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0208	RH INBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-001 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0209	LH MID FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-001 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0210	RH MID FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-001 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0211	LH MID FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-001 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275229-0212	RH MID FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-001 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0213	LH MID FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-001 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0214	RH MID FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-001 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0215	LH MID FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-001 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0216	RH MID FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-001 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0401	LH OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0402	RH OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0403	LH OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275229-0404	RH OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0405	LH OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0406	RH OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0407	LH OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0408	RH OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751360-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0501	LH INBOARD FLAP (CARRIAGE SIDE ROLLER) BOLT 1005751361-001 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0502	RH INBOARD FLAP (CARRIAGE SIDE ROLLER) BOLT 1005751361-001 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0503	LH INBOARD FLAP (CARRIAGE SIDE ROLLER) BOLT 1005751361-001 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275229-0504	RH INBOARD FLAP (CARRIAGE SIDE ROLLER) BOLT 1005751361-001 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0601	LH INBOARD FLAP (CARRIAGE SIDE ROLLER) BOLT 1005751361-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0602	RH INBOARD FLAP (CARRIAGE SIDE ROLLER) BOLT 1005751361-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0603	LH INBOARD FLAP (CARRIAGE SIDE ROLLER) BOLT 1005751361-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0604	RH INBOARD FLAP (CARRIAGE SIDE ROLLER) BOLT 1005751361-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0605	LH OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751361-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0606	RH OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751361-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0607	LH OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751361-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275229-0608	RH OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751361-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0609	LH OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751361-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0610	RH OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751361-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0611	LH OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751361-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0612	RH OUTBOARD FLAP (CARRIAGE MAIN ROLLER) BOLT 1005751361-003 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0701	LH MID FLAP (CARRIAGE SIDE ROLLER) BOLT 1005751361-005 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0702	RH MID FLAP (CARRIAGE SIDE ROLLER) BOLT 1005751361-005 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0703	LH MID FLAP (CARRIAGE SIDE ROLLER) BOLT 1005751361-005 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275229-0704	RH MID FLAP (CARRIAGE SIDE ROLLER) BOLT 1005751361-005 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0801	LH MID FLAP (CARRIAGE SIDE ROLLER) BOLT 1005751361-007 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0802	RH MID FLAP (CARRIAGE SIDE ROLLER) BOLT 1005751361-007 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0803	LH MID FLAP (CARRIAGE SIDE ROLLER) BOLT 1005751361-007 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275229-0804	RH MID FLAP (CARRIAGE SIDE ROLLER) BOLT 1005751361-007 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
275233	FLAP POWER (FPU) UNIT 1751A0000-04 420	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
275235	FPU ECOLOGY BOTTLE 1754A0000-01 01269	MOS HRS/MSC	60	N:13 N:0			31-AUG-2016 1702:09	31-JUL-2020	
LIFE LIMIT	REF: See Workcard	AFL		N:0			1001		
276000-0104	RIGHT INBOARD AILERON - TAB ASSEMBLY PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF:	AFL		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276101	CENTER PEDESTAL CONTROL FLIGHT SPOILER LEVER C47302-005 FR0344 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
276101-0201	LIGHTING PANEL C47302-006 349 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
276105-0102	RIGHT NO. 1 EQUIP RACK A118 SPOILER ELECTRONIC CONTROL (SECU) UNIT C47330-008 741 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
276105-0104	RIGHT NO. 2 EQUIP RACK A119 SPOILER ELECTRONIC CONTROL (SECU) UNIT C47330-008 743 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
276109-0101	LH INBD GS (PX43) PROXIMITY SENSOR 40102-0101 25062 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
276109-0102	RH INBD GS (PX44) PROXIMITY SENSOR 40102-0101 25058 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
276109-0103	LH OUTBD GS (PX13) PROXIMITY SENSOR 40102-0101 25060 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
276109-0104	RH OUTBD GS (PX14) PROXIMITY SENSOR 40102-0101 25056 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276111-0101	L/H INBD (MT145) MULTI FUNCTION SPOILER (RVDT) ROTARY VARIABLE DIFFERENTIAL TRANSFORMER C84105-001 2471 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
276111-0102	R/H INBD (MT144) MULTI FUNCTION SPOILER (RVDT) ROTARY VARIABLE DIFFERENTIAL TRANSFORMER C84105-001 2442 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
276111-0103	L/H OUTBD (MT147) MULTI FUNCTION SPOILER (RVDT) ROTARY VARIABLE DIFFERENTIAL TRANSFORMER C84105-001 2478 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
276111-0104	R/H OUTBD (MT146) MULTI FUNCTION SPOILER (RVDT) ROTARY VARIABLE DIFFERENTIAL TRANSFORMER C84105-001 2467 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
276201-0101	LEFT OUTBOARD MPE39- MULTI-FUNCTION SPOILER (MFS PCU) POWER CONTROL UNIT C47030-003 1342A REF: See Workcard	MOS HRS/MSC AFL	O/C	R:2 R:0 R:0			09-DEC-2015 1470:55 878		
276201-0102	RIGHT INBOARD MPE36- MULTI-FUNCTION SPOILER (MFS PCU) POWER CONTROL UNIT C47030-003 1224A REF: See Workcard	MOS HRS/MSC AFL	O/C	R:2 N:635:24 R:0 N:560 R:0			09-DEC-2015 1470:55 878		
276201-0103	LEFT INBOARD MPE37- MULTI-FUNCTION SPOILER (MFS PCU) POWER CONTROL UNIT C47030-003 1343A REF: See Workcard	MOS HRS/MSC AFL	O/C	R:2 R:0 R:0			09-DEC-2015 1470:55 878		
276201-0104	RIGHT OUTBOARD MPE38- MULTI-FUNCTION SPOILER (MFS PCU) POWER CONTROL UNIT C47030-003 0384A REF: See Workcard	MOS HRS/MSC AFL	O/C	R:2 N:1923 R:0 N:1222 R:0			09-DEC-2015 1470:55 878		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276201-0201	LH INBOARD M/F SPOILER ACTUATOR SHOULDER BOLT 1005776030-001 10CAM0080	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
276201-0202	LH OUTBOARD M/F SPOILER ACTUATOR SHOULDER BOLT 1005776030-001 10CAM0083	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
276201-0203	RH INBOARD M/F SPOILER ACTUATOR SHOULDER BOLT 1005776030-001 10CAM0090	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
276201-0204	RH OUTBOARD M/F SPOILER ACTUATOR SHOULDER BOLT 1005776030-001 10CAM0089	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
276301-0101	LEFT MPE34 - SELECTOR GROUND SPOILER VALVE C47010-003 736	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
276301-0102	RIGHT MPE35 - SELECTOR GROUND SPOILER VALVE C47010-003 686	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
276305-0101	LEFT OUTBOARD GROUND SPOILER ACTUATOR C47000-005 1357	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
276305-0102	LEFT INBOARD GROUND SPOILER ACTUATOR C47000-005 0444	MOS HRS/MSC	O/C	N:1028 N:879			06-DEC-2018 2236:21		
	REF: See Workcard	AFL		N:879			1275		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276305-0103	RIGHT INBOARD GROUND SPOILER ACTUATOR C47000-005 1346 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
276305-0104	RIGHT OUTBOARD GROUND SPOILER ACTUATOR C47000-005 1355 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
276305-0201	LH INBOARD GROUND SPOILER SHOULDER BOLT 1005776020-001 10CAM0086 LIFE LIMIT REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
276305-0202	LH OUTBOARD GROUND SPOILER SHOULDER BOLT 1005776020-001 10CAM0085 LIFE LIMIT REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
276305-0203	RH INBOARD GROUND SPOILER SHOULDER BOLT 1005776020-001 10CAM0091 LIFE LIMIT REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
276305-0204	RH OUTBOARD GROUND SPOILER SHOULDER BOLT 1005776020-001 10CAM0093 LIFE LIMIT REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
277000-0101	AILERON GUST LOCK PUSH/PULL CONTROL CABLE ASSY 1002770010-009 425 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
277100-0101	LEFT INBOARD GROUND SPOILER ASSEMBLY 1005771010-001 F932273 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
277100-0102	RIGHT INBOARD GROUND SPOILER ASSEMBLY 1005771010-002 F932275 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
277100-0201	LEFT OUTBOARD GROUND SPOILER ASSEMBLY 1005771011-003 F932277 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
277100-0202	RIGHT OUTBOARD GROUND SPOILER ASSEMBLY 1005771011-004 F944165 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
277200-0101	LEFT INBOARD MULTI-FUNCTION SPOILER ASSEMBLY 1005771015-003 F932265 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
277200-0102	RIGHT INBOARD MULTI-FUNCTION SPOILER ASSEMBLY 1005771015-004 F932267 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
277200-0103	LEFT OUTBOARD MULTI-FUNCTION SPOILER ASSEMBLY 1005771018-003 F932268 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
277200-0104	RIGHT OUTBOARD MULTI-FUNCTION SPOILER ASSEMBLY 1005771018-004 F932270 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
278003-1	NO. 1 CARRIAGE SIDE ROLLER ATF-6 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL		N:0 N:0 N:0			28-JAN-2011 0 0		
LIFE LIMIT			7500					7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
278003-2	NO. 2 CARRIAGE SIDE ROLLER ATF-6 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
278003-3	NO. 3 CARRIAGE SIDE ROLLER ATF-6 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
278003-4	NO. 4 CARRIAGE SIDE ROLLER ATF-6 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
278005-1	NO. 1 CARRIAGE MAIN ROLLER ATF-8 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
278005-2	NO. 2 CARRIAGE MAIN ROLLER ATF-8 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
278005-3	NO. 3 CARRIAGE MAIN ROLLER ATF-8 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
278005-4	NO. 4 CARRIAGE MAIN ROLLER ATF-8 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
278007-1	NO. 1 CARRIAGE MAIN ROLLER ATF-10 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
278007-2	NO. 2 CARRIAGE MAIN ROLLER ATF-10 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0		7500
LIFE LIMIT									
278007-3	NO. 3 CARRIAGE MAIN ROLLER ATF-10 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0		7500
LIFE LIMIT									
278007-4	NO. 4 CARRIAGE MAIN ROLLER ATF-10 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0		7500
LIFE LIMIT									
278011-1	NO. 1 FLAP INBOARD SUPPORT RAIL 1005751400-001 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0		7500
LIFE LIMIT									
278011-2	NO. 2 FLAP INBOARD SUPPORT RAIL 1005751400-001 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0		7500
LIFE LIMIT									
278013-1	NO. 1 FLAP CENTER SUPPORT RAIL 1005751401-001 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0		7500
LIFE LIMIT									
278013-2	NO. 2 FLAP CENTER SUPPORT RAIL 1005751401-001 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0		7500
LIFE LIMIT									
278015-1	NO. 1 FLAP OUTBOARD SUPPORT RAIL 1005751402-001 NON-SERIALIZED REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0		7500
LIFE LIMIT									

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
278015-2	NO. 2 FLAP OUTBOARD SUPPORT RAIL 1005751402-001 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
278030-101	CENTER FORWARD FITTING FLAP ATTACHMENT, LH WS 121.50 BEARING HTY12-303 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
278030-102	LH INBOARD FORWARD FITTING FLAP ATTACHMENT BEARING HTY12-303 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
278030-103	LEFT (HTY10-303) OUTBOARD FORWARD FITTING FLAP ATTACHMENT BEARING HTY10-303 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	5500	N:0			0	5500	
278030-104	RIGHT (HTY10-303) OUTBOARD FORWARD FITTING FLAP ATTACHMENT BEARING HTY10-303 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	5500	N:0			0	5500	
278030-105	CENTER FORWARD FITTING FLAP ATTACHMENT, RH WS 121.50 BEARING HTY12-303 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
278030-106	RH INBOARD FORWARD FITTING FLAP ATTACHMENT BEARING HTY12-303 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	

CHAPTER 28 FUEL



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-00-00-103	DETAILED INSPECTION WING TANK #4 AND #11 RIB ASSEMBLIES REF: AMM 28 11 00 220 801	MOS HRS/MSC AFL	10000				28-JAN-2011 0 0	10000	
28-00-00-109 (s)	FUNCTIONAL TEST OF THE HYDROMECHANICAL UNIT (HMU) MOTIVE FLOW PRESSURE PKG 13 REF: AMM 73 20 01 720 801	MOS HRS/MSC AFL	3200	+40/-40			28-JAN-2011 0 0		
28-10-00-201 (s)	GENERAL VISUAL INSPECTION FUEL STORAGE SYSTEM PKG 13 MRB REF: AMM 28 10 00 210 801	MOS HRS/MSC AFL	3200	+40/-40			06-DEC-2018 2236:21 1275		
28-10-00-202 (s)	GENERAL VISUAL INSPECTION BLADDER VENT VALVE PKG 5 MRB REF: AMM 28 13 07 210 801	MOS HRS/MSC AFL	96	+1m/-1m			23-DEC-2019 2630:03 1481		
28-10-CUS-701 (s)	INSPECTION FUEL TANK MICROBIOLOGICAL GROWTH PKG 1 CUSTOMER CODE REF:	MOS HRS/MSC AFL	12				23-DEC-2019 2630:03 1481		
28-11-17-201 (s)	DETAILED INSPECTION GRAVITY FILLER CAP PKG 9 MRB REF: AMM 28 11 17 220 801	MOS HRS/MSC AFL	800	+40/-40			23-DEC-2019 2630:03 1481		
28-13-00-301 (s)	OPERATIONAL TEST FUEL VENT SYSTEM PKG 8 MRB REF: AMM 28 13 00 710 801	MOS HRS/MSC AFL	600	+40/-40			23-DEC-2019 2630:03 1481		
28-13-05-201 (s)	OPERATIONAL TEST SURGE-TANK CHECK VALVE PKG 5 MRB REF: AMM 28 13 05 710 801	MOS HRS/MSC AFL	96	+1m/-1m			23-DEC-2019 2630:03 1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-21-00-201 (s)	GENERAL VISUAL INSPECTION SHROUD DRAINS FOR THE FUEL LINES PKG 9	MOS HRS/MSC	800	+40/-40			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 28 21 00 210 801	AFL							
28-21-00-302 (s)	FUNCTIONAL TEST (PRESSURE TEST) OF THE FUEL LINE SHROUDS PKG 5	MOS HRS/MSC	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 28 21 00 780 801	AFL							
28-22-07-201 (s)	OPERATIONAL TEST GRAVITY-CROSSFLOW SYSTEM PKG 13	MOS HRS/MSC	3200	+40/-40			PKG 28-JAN-2011 0 0		
MRB	REF: See Workcard	AFL							
28-22-07-302 (s)	OPERATIONAL TEST GRAVITY-CROSSFLOW VALVE PUSH BUTTON ANNUNCIATOR (PBA) PKG 11	MOS HRS/MSC	1600	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 28 22 07 710 802	AFL							
281101-0101	FUEL ACCESS COVER (161AB) ASSEMBLY 1005721042-001 4443	MOS HRS/MSC	O/C		N:0 N:0		28-JAN-2011 0 0		
	REF: See Workcard	AFL			N:0				
281101-0102	FUEL ACCESS COVER (162AB) ASSEMBLY 1005721042-001 4444	MOS HRS/MSC	O/C		N:0 N:0		28-JAN-2011 0 0		
	REF: See Workcard	AFL			N:0				
281101-0103	FUEL ACCESS COVER (161BB) ASSEMBLY 1005721042-001 4445	MOS HRS/MSC	O/C		N:0 N:0		28-JAN-2011 0 0		
	REF: See Workcard	AFL			N:0				
281101-0104	FUEL ACCESS COVER (162BB) ASSEMBLY 1005721042-001 4446	MOS HRS/MSC	O/C		N:0 N:0		28-JAN-2011 0 0		
	REF: See Workcard	AFL			N:0				

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281101-0105	FUEL ACCESS COVER (531AB) ASSEMBLY 1005721042-001 4447 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0106	FUEL ACCESS COVER (631AB) ASSEMBLY 1005721042-001 4448 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0107	FUEL ACCESS COVER (531BB) ASSEMBLY 1005721042-001 4449 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0108	FUEL ACCESS COVER (631BB) ASSEMBLY 1005721042-001 4450 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0109	FUEL ACCESS COVER (531CB) ASSEMBLY 1005721042-001 4451 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0110	FUEL ACCESS COVER (631CB) ASSEMBLY 1005721042-001 4452 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0111	FUEL ACCESS COVER (531DB) ASSEMBLY 1005721042-001 4453 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0112	FUEL ACCESS COVER (631DB) ASSEMBLY 1005721042-001 4454 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281101-0113	FUEL ACCESS COVER (531EB) ASSEMBLY 1005721042-001 4455 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0114	FUEL ACCESS COVER (631EB) ASSEMBLY 1005721042-001 4456 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0115	FUEL ACCESS COVER (531FB) ASSEMBLY 1005721042-003 3185 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0116	FUEL ACCESS COVER (631FB) ASSEMBLY 1005721042-003 3186 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0117	FUEL ACCESS COVER (531GB) ASSEMBLY 1005721042-003 3187 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0118	FUEL ACCESS COVER (631GB) ASSEMBLY 1005721042-003 3188 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0119	FUEL ACCESS COVER (531HB) ASSEMBLY 1005721042-003 3189 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0120	FUEL ACCESS COVER (631HB) ASSEMBLY 1005721042-003 3190 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281101-0121	FUEL ACCESS COVER (531JB) ASSEMBLY 1005721042-003 3191 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0122	FUEL ACCESS COVER (631JB) ASSEMBLY 1005721042-003 3192 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0123	FUEL ACCESS COVER (531KB) ASSEMBLY 1005721042-003 3193 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0124	FUEL ACCESS COVER (631KB) ASSEMBLY 1005721042-003 3194 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0125	FUEL ACCESS COVER (531LB) ASSEMBLY 1005721042-005 1275 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0126	FUEL ACCESS COVER (631LB) ASSEMBLY 1005721042-005 1276 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0127	FUEL ACCESS COVER (531MB) ASSEMBLY 1005721042-005 1273 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0128	FUEL ACCESS COVER (631MB) ASSEMBLY 1005721042-005 1274 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281101-0129	FUEL ACCESS COVER (531NB) ASSEMBLY 1005721042-007 319 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0130	FUEL ACCESS COVER (631NB) ASSEMBLY 1005721042-008 327 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0131	FUEL ACCESS COVER (531PB) ASSEMBLY 1005721042-009 320 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0132	FUEL ACCESS COVER (631PB) ASSEMBLY 1005721042-010 320 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0133	FUEL ACCESS COVER (531QB) ASSEMBLY 1005721042-011 319 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281101-0134	FUEL ACCESS COVER (631QB) ASSEMBLY 1005721042-012 320 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281102-0101	SURGE TANK COVER (531RB) ASSEMBLY 1005721046-001 645 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281102-0102	SURGE TANK COVER (631RB) ASSEMBLY 1005721046-001 646 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281103-0101	LH TANK ACCESS PANEL ASSEMBLY 1005711024-001 325 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281103-0102	RH TANK ACCESS PANEL ASSEMBLY 1005711024-002 325 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281109-0101	LH PRESSURE RELIEF VALVE L97-63-607 E13901 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281109-0102	RH PRESSURE RELIEF VALVE L97-63-607 E13895 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0101	WING TANK FLAPPER CHECK VALVE L85-25-601 10107 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0102	WING TANK FLAPPER CHECK VALVE L85-25-601 10108 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0103	WING TANK FLAPPER CHECK VALVE L85-25-601 10105 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0104	WING TANK FLAPPER CHECK VALVE L85-25-601 10106 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281113-0105	WING TANK FLAPPER CHECK VALVE L85-25-601 10141 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0106	WING TANK FLAPPER CHECK VALVE L85-25-601 10142 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0107	WING TANK FLAPPER CHECK VALVE L85-25-601 10139 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0108	WING TANK FLAPPER CHECK VALVE L85-25-601 10140 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0109	WING TANK FLAPPER CHECK VALVE L85-25-601 10137 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0110	WING TANK FLAPPER CHECK VALVE L85-25-601 10138 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0111	WING TANK FLAPPER CHECK VALVE L85-25-601 10119 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0112	WING TANK FLAPPER CHECK VALVE L85-25-601 10120 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281113-0113	WING TANK FLAPPER CHECK VALVE L85-25-601 10111 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0114	WING TANK FLAPPER CHECK VALVE L85-25-601 10118 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0115	WING TANK FLAPPER CHECK VALVE L85-25-601 10109 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0116	WING TANK FLAPPER CHECK VALVE L85-25-601 10110 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0117	WING TANK FLAPPER CHECK VALVE L85-25-601 10103 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0118	WING TANK FLAPPER CHECK VALVE L85-25-601 10104 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0119	WING TANK FLAPPER CHECK VALVE L85-25-601 10101 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0120	WING TANK FLAPPER CHECK VALVE L85-25-601 10102 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281113-0121	WING TANK FLAPPER CHECK VALVE L85-25-601 10099 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281113-0122	WING TANK FLAPPER CHECK VALVE L85-25-601 10100 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281301-0101	LEFT FLOAT VALVE L87-31-602 E30299 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281301-0102	RIGHT FLOAT VALVE L87-31-602 E30300 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281305-0101	LEFT CHECK SURGE TANK VALVE L85-31-602 E14071 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
281305-0102	RIGHT CHECK SURGE TANK VALVE L85-31-602 E14070 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282001-0101	AILERON ACCESS COVER ASSEMBLY 1005721036-001 324 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282001-0102	AILERON ACCESS COVER ASSEMBLY 1005721036-002 327 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282101-0101	LEFT S4 PRIMARY - EJECTOR PUMP T99A31-606 E18295 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282101-0102	RIGHT S5 PRIMARY - EJECTOR PUMP T99A31-606 E08294 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282105-0101	LEFT PRIMARY EJECTOR PUMP S4 - PRESSURE SENSOR D98C07-609 3333 REF: See Workcard	MOS HRS/MSC AFL	O/C				15-FEB-2019 2325:50 1321		
282105-0102	RIGHT PRIMARY EJECTOR PUMP S5 - PRESSURE SENSOR D98C07-609 3513 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			06-DEC-2018 2236:21 1275		
282105-0103	PRESSURE SENSOR D98C07-609 1343 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282105-0104	PRESSURE SENSOR D98C07-609 1342 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282109-0101	LEFT BOOST PUMP CARTRIDGE P99C31-602 G61035 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:5 R:0 R:0			06-JUN-2018 2051:03 1184		
282109-0102	RIGHT BOOST PUMP CARTRIDGE P99C31-602 B46177 REF: See Workcard	MOS HRS/MSC AFL	O/C				30-JUN-2015 1370:14 820		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282113-0101	LEFT BOOST PUMP CANISTER C93R31-603 E14257 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282113-0102	RIGHT BOOST PUMP CANISTER C93R31-603 E14256 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282117-0101	LEFT SCAVENGE - EJECTOR PUMP T99A31-602 E22803 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282117-0102	RIGHT SCAVENGE - EJECTOR PUMP T99A31-602 E32790 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282121-0101	LEFT ENGINE FEED SHUTOFF VALVE B97-31-611 E12891 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282121-0102	RIGHT ENGINE FEED SHUTOFF VALVE B97-31-611 E12892 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282125-0101	LEFT ENGINE FUEL FEED SHUTOFF VALVE HP3 - ELECTRICAL ACTUATOR D97C00-614 E41927 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282125-0102	RIGHT ENGINE FUEL FEED SHUTOFF VALVE HP2 - ELECTRICAL ACTUATOR D97C00-614 E41928 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282129	APU FEED SHUTOFF VALVE B97-13-604 E32716 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
282133	FUEL FEED SHUTOFF VALVE HP4 - ELECTRICAL ACTUATOR D97C00-614 D82083 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
282141-0101	LEFT ENGINE FEED - CHECK VALVE L85-31-601 E11917 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
282141-0102	RIGHT ENGINE FEED - CHECK VALVE L85-31-601 E11918 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
282147-0101	LEFT FUEL FEED TUBE ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
282147-0102	RIGHT FUEL FEED TUBE ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
282147-0103	LEFT FUEL TRANSFER / FEED TUBE ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
282147-0104	RIGHT FUEL TRANSFER / FEED TUBE ASSEMBLY PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282201	WING TRANSFER SHUTOFF - VALVE ASSEMBLY B97-31-610 E12875 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282205	VALVE ASSY - WING TRANSFER SHUTOFF - ELECTRICAL ACTUATOR D97C00-614 E41929 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282207	GRAVITY CROSS FLOW SHUTOFF VALVE B97-31-608 E12603 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282208	VALVE - CROSS FLOW SHUTOFF - ELECTRICAL ACTUATOR D97C00-614 D11360 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282300-7101	ELECTRICAL RECEPTACLE AC62-105 2904 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282300-7102	ELECTRICAL RECEPTACLE AC62-105 2914 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282300-7103	ELECTRICAL RECEPTACLE AC62-105 2855 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282301-0001	REFUEL/DEFUEL CONTROL PANEL 798945-3-1 798945IN00472 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282305	REFUEL ADAPTOR K97-63-609 E83874 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282309	A59 REFUEL/DEFUEL MANIFOLD L93E38-603 E58229 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282313-0101	LEFT REFUEL/DEFUEL - VALVE ASSEMBLY L94L38-652 E04978 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
282313-0102	RIGHT REFUEL/DEFUEL - VALVE ASSEMBLY L94L38-652 E28169 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
284101	EQUIP RACK LH A57 - FUEL QUANTITY GAUGING (FQGC) COMPUTER 738360-1-2 432 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
284109-0101	LEFT CENTER TANK NO 8 MT13 - FUEL PROBE 762020-2-0 939 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
284109-0102	RIGHT CENTER TANK NO 8 MT14 - FUEL PROBE 762020-2-0 952 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
284113-0101	LEFT NO 1 MT1 - FUEL PROBE 762025-2-0 2031 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284113-0102	RIGHT NO 1 MT2- FUEL PROBE 762025-2-0 2032 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
284113-0103	LEFT NO 2 MT3 - FUEL PROBE 762025-2-0 2033 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
284113-0104	RIGHT NO 2 MT4 - FUEL PROBE 762025-2-0 2034 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
284113-0105	LEFT NO 3 MT5 - FUEL PROBE 762025-2-0 2035 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
284113-0106	RIGHT NO 3 MT6 - FUEL PROBE 762025-2-0 2036 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
284113-0107	LEFT NO 4 MT7 - FUEL PROBE 762024-2-0 757 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
284113-0108	RIGHT NO 4 MT8 - FUEL PROBE 762024-2-0 758 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
284113-0109	LEFT NO 5 MT9 - FUEL PROBE 762023-3-0 947 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284113-0110	RIGHT N0 5 MT10 - FUEL PROBE 762023-3-0 948 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
284113-0111	LEFT N0 6 MT11 - FUEL PROBE 762022-2-0 1379 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
284113-0112	RIGHT N0 6 MT12 - FUEL PROBE 762022-2-0 1376 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
284113-0113	LEFT N0 7 MT17 - FUEL PROBE 762021-2-0 747 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
284113-0114	RIGHT N0 7 MT18 - FUEL PROBE 762021-2-0 748 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
284113-0115	LEFT N0 9 MT107 - FUEL PROBE 762022-2-0 1377 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
284113-0116	RIGHT N0 9 MT108 - FUEL PROBE 762022-2-0 1378 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
284117-0101	LEFT MT15 - HIGH LEVEL SENSOR 722707-1-0 843 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284117-0102	RIGHT MT16 - HIGH LEVEL SENSOR 722707-1-0 1341 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:15 N:0 N:0			23-JUL-2015 1384:24 833		
284121	CENTER TANK TC1 - TEMPERATURE SENSOR 798840-1-0 2222 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
APU Model : GTCP36-150(BD) Serial # P-430 Part # 3800774-1									
28-21-29-301	APU - FUNCTIONAL TEST APU FUEL SHUTOFF-VALVE FOR LEAKS REF: See Workcard	MOS HRS/MSC APUS	2000	+40/-40			24-JUN-2015 1939:45	3939:45	3979:45
CHAPTER 29 HYDRAULIC POWER									
29-00-00-105	FUNCTIONAL TEST ENGINE DRIVEN HYDRAULIC PUMP AUTO DEPRESSURIZATION AND FIREWALL HYDRAULIC SHUTOFF VALVE CIRCUITRY REF: AMM 29 12 00 720 801	MOS HRS/MSC AFL	10000				28-JAN-2011 0 0	10000	
29-00-00-106 (s)	OPERATIONAL TEST POWER TRANSFER UNIT (PTU) PKG 8 REF: AMM 29 12 57 710 801	MOS HRS/MSC AFL	600				PKG 23-DEC-2019 2630:03 1481		
29-00-00-107 (s)	FUNCTIONAL TEST POWER TRANSFER UNIT (PTU) PKG 9 REF: AMM 29 12 57 720 801	MOS HRS/MSC AFL	800				PKG 06-DEC-2018 2236:21 1275		
29-00-00-501 (s)	FUNCTIONAL TEST (CONTAMINATION TEST) OF THE LEFT, RIGHT AND AUXILIARY HYDRAULIC SYSTEMS FLUID PKG 1 REF: AMM 29 00 00 281 801	MOS HRS/MSC AFL	12	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MPD									

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-10-00-309 (s)	FUNCTIONAL TEST RESERVOIR RETURN-LINE CHECK-VALVE PKG 15	MOS					PKG		
MRB	REF: AMM 29 12 27 720 801	HRS/MSC AFL	9600	+40/-40			28-JAN-2011 0 0		
29-12-00-501	DETAILED INSPECTION OF THE DC MOTOR-DRIVEN-PUMP BRUSHES (PRE SB100-29-18)	MOS							
MPD	REF: AMM 29 12 05 220 801	HRS/MSC AFL	N/A				09-DEC-2015 1470:55 878		
29-12-00-502	VISUAL CHECK OF THE DIFFERENTIAL PRESSURE INDICATORS (DPI) FOR THE PRESSURE, RETURN, AND CASE-DRAIN FILTER MANIFOLDS	MOS							
CUSTOMER CONVENIENCE	REF: AMM 29 00 00 210 801	HRS/MSC AFL	600	+40/-40			06-DEC-2018 2236:21 1275	2836:21	2876:21
29-12-09-301	FUNCTIONAL TEST HYDRAULIC SYSTEM 275 DEGREE TEMPERATURE SWITCH	MOS							
MRB	REF: AMM 29 12 09 720 801	HRS/MSC AFL	4800	+40/-40			28-JAN-2011 0 0	4800	4840
29-12-33-301 (s)	OPERATIONAL TEST FIREWALL HYDRAULIC SHUTOFF-VALVE (FWSOV) PKG 8	MOS					PKG		
MRB	REF: AMM 29 12 33 710 801	HRS/MSC AFL	600	+40/-40			23-DEC-2019 2630:03 1481		
29-21-00-301 (s)	FUNCTIONAL TEST AUXILIARY HYDRAULIC SYSTEM PKG 10	MOS					PKG		
MRB	REF: AMM 29 21 00 720 801	HRS/MSC AFL	1200	+40/-40			06-DEC-2018 2236:21 1275		
29-21-17-301 (s)	VISUAL CHECK ACCUMULATOR CHARGE MANIFOLD PKG 8	MOS					PKG		
MRB	REF: AMM 29 21 17 210 801	HRS/MSC AFL	600	+40/-40			23-DEC-2019 2630:03 1481		
29-33-01-301 (s)	FUNCTIONAL TEST HYDRAULIC TEMPERATURE TRANSDUCER PKG 11	MOS					PKG		
MRB	REF: AMM 29 33 01 720 802	HRS/MSC AFL	1600	+40/-40			06-DEC-2018 2236:21 1275		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291201-0101	LEFT ENGINE DRIVEN (EDP) PUMP ASSEMBLY 51160-06 K1037 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:2 R:0 R:0			09-DEC-2015 1470:55 878		
291201-0102	RIGHT ENGINE DRIVEN (EDP) PUMP ASSEMBLY 51160-06 K0769 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:1 N:3298:18 R:0 N:1923 R:0			09-DEC-2015 1470:55 878		
291201-0201	LH - ENGINE HYDRAULIC PUMP (EDP) QUICK DISCONNECT COUPLING PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291201-0202	LH - ENGINE HYDRAULIC PUMP (EDP) QUICK DISCONNECT COUPLING HALF PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291201-0203	RH - ENGINE HYDRAULIC PUMP (EDP) QUICK DISCONNECT COUPLING PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291201-0204	RH - ENGINE HYDRAULIC PUMP (EDP) QUICK DISCONNECT COUPLING HALF PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291205-0101	LH (A71) DC MOTOR-DRIVEN PUMP ASSEMBLY 945202-3 AD11047 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2015 1470:55 878		
291205-0102	RH (A70) DC MOTOR-DRIVEN PUMP ASSEMBLY 945202-3 AD11043 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-DEC-2015 1470:55 878		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291209-0101	LEFT RESERVOIR MT133 - TEMPERATURE SWITCH 8SC0738-1 RA3068 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291209-0102	RIGHT RESERVOIR MT134 - TEMPERATURE SWITCH 8SC0738-1 RA3071 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291209-0103	TEMPERATURE SWITCH 8SC0738-1 RA3062 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291209-0104	TEMPERATURE SWITCH 8SC0738-1 RA3069 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291213-0101	LH FILTER PRESSURE MANIFOLD 945173-3 97 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291213-0102	RH FILTER PRESSURE MANIFOLD 945173-3 98 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291213-0201	LH PRESSURE FILTER MANIFOLD CHECK VALVE 945173-3 0097 REF: See Workcard	MOS HRS/MSC AFL	O/C				03-NOV-2014 1164:01 690		
291213-0202	RH PRESSURE FILTER MANIFOLD CHECK VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291217-0101	LEFT FILTER RETURN MANIFOLD 945174-1 PT2366 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291217-0102	RIGHT FILTER RETURN MANIFOLD 945174-1 PT2368 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291221-0101	LEFT FILTER CASE DRAIN MANIFOLD 945175-1 PT4695 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291221-0102	RIGHT FILTER CASE DRAIN MANIFOLD 945175-1 PT4697 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291221-0103	LEFT FILTER CASE DRAIN MANIFOLD 945175-1 PT4696 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291221-0104	RIGHT FILTER CASE DRAIN MANIFOLD 945175-1 PT4816 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291222-0101	LEFT MANIFOLD - FILTER CASE DRAIN CHECK VALVE 975254-5 5705 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291222-0102	RIGHT MANIFOLD - FILTER CASE DRAIN CHECK VALVE 975254-5 5706 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291224-0101	LEFT HYDRAULIC VISUAL QUANTITY INDICATOR ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291224-0102	RIGHT HYDRAULIC VISUAL QUANTITY INDICATOR ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291225-0101	LEFT #1 MT81 - HYDRAULIC 750 CU.IN. RESERVOIR 960452-3 315 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291225-0102	RIGHT #2 MT82 - HYDRAULIC RESERVOIR 960458-1 350 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291227-0101	LEFT IN LINE RESERVOIR - HYD 750 CU.IN. CHECK VALVE 975254-11 656 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291227-0102	RIGHT IN LINE RESERVOIR - HYD 525 CU.IN. CHECK VALVE 975254-11 657 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291229-0101	LEFT SYSTEM 1 - PRESSURE RELIEF VALVE 975296-1 689 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291229-0102	RIGHT SYSTEM 2 - PRESSURE RELIEF VALVE 975296-1 690 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291233-0101	LEFT ENGINE SYSTEM 1 - HYDRAULIC SHUTOFF FIREWALL VALVE ASSEMBLY 975266-3 2243 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291233-0102	RIGHT ENGINE SYSTEM 2 - HYDRAULIC SHUTOFF FIREWALL VALVE ASSEMBLY 975266-301 2462 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:2725 N:1640			23-DEC-2019 2630:03 1481		
291235-0101	HYDRAULIC RETURN CHECK VALVE 975254-1 5779 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291235-0102	HYDRAULIC RETURN CHECK VALVE 975254-1 5780 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291235-0103	HYDRAULIC RETURN CHECK VALVE 975254-1 5782 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291235-0104	HYDRAULIC RETURN CHECK VALVE 975254-1 5781 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291235-0105	HYDRAULIC RETURN CHECK VALVE 975254-1 5926 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291235-0201	HYDRAULIC DCMP & EDP TO NWS CHECK VALVE 975254-3 1782 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291235-0202	HYDRAULIC DCMP & EDP TO NWS CHECK VALVE 975254-3 1783 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291235-0203	HYDRAULIC DCMP & EDP TO NWS CHECK VALVE 975254-3 1784 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291235-0301	HYDRAULIC EDP TO MLG CHECK VALVE 975254-8 1859 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291237-0101	NOSE WHEEL STEERING HYDRAULIC PRIORITY VALVE 975291-1 655 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291237-0102	NOSE WHEEL STEERING HYDRAULIC PRIORITY VALVE 975291-1 656 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291241-0101	LEFT HEAT EXCHANGER GX474-0010-1 4332 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291241-0102	RIGHT HEAT EXCHANGER GX474-0010-1 4344 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291245-0101	SYSTEM 1 - BYPASS HEAT EXCHANGER VALVE 975244-3 PN4611 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291245-0102	SYSTEM 2- BYPASS HEAT EXCHANGER VALVE 975244-3 PN4612 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291257	POWER TRANSFER (PTU) UNIT 51161 K0328 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291261	MT115 - SELECT PTU VALVE 975284-3 347 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291265-0101	NO. 1 SYSTEM 1 - BALANCED RELIEF VALVE 975275-3 3311 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291265-0102	NO. 2 SYS 2 - BALANCE RELIEF VALVE 975275-3 PN3250 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291501-0101	DUST CAP PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291501-0102	DUST CAP PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291501-0201	HYDRAULIC PRESSURE QUICK DISCONNECT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291501-0202	HYDRAULIC PRESSURE QUICK DISCONNECT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291505-0101	DUST CAP PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291505-0102	DUST CAP PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291505-0201	HYDRAULIC FILL QUICK DISCONNECT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291505-0202	HYDRAULIC FILL QUICK DISCONNECT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291505-0203	HYDRAULIC FILL QUICK DISCONNECT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291509-0101	DUST CAP PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291509-0102	DUST CAP PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291509-0201	HYDRAULIC RETURN QUICK DISCONNECT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291509-0202	HYDRAULIC RETURN QUICK DISCONNECT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291513-0101	DUST CAP PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291701-0101	CHECK VALVE 975254-7 1041 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291701-0102	CHECK VALVE 975292-1 357 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
291801-0101	DISCARD THE FAIRLEAD (PART NO. 1005354666-001) BLOCK PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						
292101	AUX DC MOTOR DRIVEN PUMP 66182-02 K0757 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
292105	FILTER PRESSURE AUX MANIFOLD 945170-3 678 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
292113	AUXILIARY HYDRAULIC SYSTEM ACCUMULATOR 8SC0726-1 60199-1520E	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	15000	N:0			0	15000	
292117-0101	LEFT ACCUMULATOR CHARGING GAUGE MANIFOLD 8SC0137-003 10A3759	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
292117-0102	RIGHT ACCUMULATOR CHARGING GAUGE MANIFOLD 8SC0137-003 10A3760	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
292121	AUXILIARY HYDRAULIC - 150 CU.IN. RESERVOIR 960443-7 748	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
292121-7101	AUXILIARY HYDRAULIC RESERVOIR QTY INDICATOR ASSY 960443-901 1387	MOS HRS/MSC	O/C				23-OCT-2013 763		
	REF:	AFL					456		
292129-0101	MT128 - PRESSURE SWITCH 967008-1 6537	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
292129-0102	MT130 - PRESSURE SWITCH 967008-1 6453	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
292129-0103	PRESSURE SWITCH 967008-1 6454	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
292129-0104	MT138 - TEMPERATURE TRANSDUCER 970286-1 3147 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
292129-0105	MT136 - PRESSURE TRANSDUCER 970281-1 7799-9-16 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
292129-0201	HYDRAULIC SWITCHING VALVE 975290-3 355 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
292129-0301	MT132 - PRESSURE SWITCH 966996-3 K043827 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
292137-0101	RESERVOIR BOOTSTRAP INTENSIFIER 935104-1 334 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
293101-0101	LEFT SYSTEM 1 MT83 - PRESSURE TRANSDUCER 970281-1 7799-9-21 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
293101-0102	RIGHT SYSTEM 2 MT84 - PRESSURE TRANSDUCER 970281-1 7799-9-17 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
293105-0101	LEFT SYSTEM 1 MT77 - PRESSURE SWITCH 967008-1 6538 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
293105-0102	RIGHT SYSTEM 2 MT78 - PRESSURE SWITCH 967008-1 6452 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
293105-0103	PRESSURE SWITCH 967008-1 6447 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
293105-0104	PRESSURE SWITCH 967008-1 6448 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
293301-0101	LEFT SYSTEM 1 MT75 - TEMPERATURE TRANSDUCER 970286-1 3146 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
293301-0102	RIGHT SYSTEM 2 MT76 - TEMPERATURE TRANSDUCER 970286-1 3173 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
CHAPTER 30	ICE AND RAIN PROTECTION								
30-11-00-301	FUNCTIONAL TEST OF THE WING ANTI-ICE SENSORS	MOS HRS/MSC AFL	N/A						
MRB	REF: AMM 30 12 00 720 801								
30-11-09-201 (s)	GENERAL VISUAL INSPECTION L/HIRF PROTECTION ON THE ANTI-ICE CONTROL PANEL CONNECTORS AND MOUNTING POINTS	PKG 5	96	+1m/-1m			23-DEC-2019 2630:03 1481		
MRB	REF: AMM 30 11 09 210 801								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-41-00-201 (s)	FUNCTIONAL TEST WINDSHIELD RAIN REPELLANT LAYER PKG 9	MOS					PKG		
MRB	REF: AMM 30 40 00 720 801	HRS/MSC AFL	800	+40/-40			23-DEC-2019 2630:03 1481		
301101-0101	LEFT INBOARD WING TEMPERATURE SENSOR 92247B010000 1853 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301101-0102	RIGHT INBOARD WING TEMPERATURE SENSOR 92247B010000 01837 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301103-0101	LEFT OUTBOARD WING TEMPERATURE SENSOR 92247B010000 1839 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301103-0102	RIGHT OUTBOARD WING TEMPERATURE SENSOR 92247B010000 03999 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
301105	MPE10 - WING ISOLATION VALVE 60083A010000 429 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301201-0101	LEFT MPE13 - WING ANTI-ICE VALVE 60082A020000 797 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301201-0102	RIGHT MPE12 - WING ANTI-ICE VALVE 60082A020000 796 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301207-0101	LH S DUCT DUCT 12739B020000 443 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301207-0102	RH S DUCT DUCT 12740B020000 430 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301209-0101	LH CROSS UNDER DUCT 12741B020000 437 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301209-0102	RH CROSS UNDER DUCT 12742B020000 454 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301211-0101	LH FUSE DUCT 12743B020000 511 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301211-0102	RH FUSE DUCT 12744B020000 450 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301213-0101	LH WHEELWELL DUCT 12745B020000 512 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301213-0102	RH WHEELWELL DUCT 12746B020000 471 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301215-0101	LH OVERWING DUCT 12747B020000 464 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301215-0102	RH OVERWING DUCT 12748B020000 470 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301217-0101	LH WING SUPPLY DUCT 12749B020000 471 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301217-0102	RH WING SUPPLY DUCT 12750B020000 503 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301219-0101	LEFT WING ROOT PICCOLO TUBE 12751B010000 344 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301219-0102	RIGHT WING ROOT PICCOLO TUBE 12752B010000 524 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301221-0101	LEFT MIDDLE PICCOLO TUBE 12753B010000 520 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301221-0102	RIGHT MIDDLE PICCOLO TUBE 12754B010000 530 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301223-0101	LEFT OUTBOARD PICCOLO TUBE 12755B010000 527 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301223-0102	RIGHT OUTBOARD PICCOLO TUBE 12756B010000 361 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301225-0101	LH SLIP JOINT 12731B010000 511 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301225-0102	RH SLIP JOINT 12732B010000 502 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301227-0101	LH SLIP JOINT 12733B010000 508 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
301227-0102	RH SLIP JOINT 12734B010000 500 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
302100-0101	LEFT COWL ANTI-ICE (PRSOV) VALVE ASSEMBLY WBA3020G103-005 775 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
302100-0102	RIGHT COWL ANTI-ICE (PRSOV) VALVE ASSEMBLY WBA3020G103-005 776 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
302103-0101	LEFT DUAL PRESSURE COWL ANTI-ICE SWITCH WBA3020G107-005 678 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
302103-0102	RIGHT DUAL PRESSURE COWL ANTI-ICE SWITCH WBA3020G107-005 675 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
303101-0101	LEFT A135 HEATER CURRENT MONITOR AIR-DATA SENSOR 3701J1 810 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
303101-0102	RIGHT A136 HEATER CURRENT MONITOR AIR-DATA SENSOR 3701J1 811 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
304101-0101	LEFT A157 - TEMPERATURE WINDSHIELD CONTROLLER 3801A1 682 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			13-DEC-2014 1213 716		
304101-0102	RIGHT A158 - TEMPERATURE WINDSHIELD CONTROLLER 3801A1 758 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:45 N:1139:19 N:676			13-OCT-2014 1139:19 676		
304105-0101	LEFT A159 - TEMPERATURE SIDE WINDOW CONTROLLER 3801B1 722 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
304105-0102	RIGHT A160 - TEMPERATURE SIDE WINDOW CONTROLLER 3801B1 727 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
308101-0101	LEFT A65 - ICE DETECTOR 92174A010200 1458 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
308101-0102	RIGHT A66 - ICE DETECTOR 92174A010200 1224 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
CHAPTER 31 INDICATING/RECORDING SYSTEMS									
31-31-00-201 (s)	FUNCTIONAL TEST FLIGHT DATA RECORDER (FDR) DEDICATED SENSORS PKG 5 REF: AMM 31 31 00 720 801	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
31-31-09-201 (s)	FUNCTIONAL TEST TRIAXIAL ACCELEROMETER FOR THE FLIGHT DATA RECORDER PKG 5 REF: AMM 31 31 09 720 801	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
31-31-13-201 (s)	FUNCTIONAL TEST FLIGHT DATA RECORDER (FDR) UNDERWATER LOCATING DEVICE (ULD) PKG 4 REF: AMM 31 31 13 720 801	MOS HRS/MSC AFL	48	+1m/-1m			PKG 07-DEC-2017 1913:50 1121		
31-31-13-202	DISCARD FDR UNDERWATER LOCATOR DEVICE BATTERY 266E0305-00 SC91426 REF: AMM 31 31 13 961 801	MOS HRS/MSC AFL	DUE				31-JUL-2017 1820:47 1066	01-MAY-2023 M	
31-52-17-301 (s)	OPERATIONAL TEST AURAL WARNING CONTROL-PANEL PKG 8 REF: AMM 31 52 17 710 801	MOS HRS/MSC AFL	600	+40/-40			PKG 23-DEC-2019 2630:03 1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-61-00-301 (s)	OPERATIONAL TEST ELECTRONIC FLIGHT-INSTRUMENT SYSTEM (EFIS) PKG 8	MOS					PKG		
MRB	REF: AMM 31 61 00 710 802	HRS/MSC AFL	600	+40/-40			23-DEC-2019 2630:03 1481		
31-61-01-201 (s)	GENERAL VISUAL INSPECTION L/HIRF PROTECTION ON THE ADAPTIVE FLIGHT DISPLAY CONNECTORS AND MOUNTING POINTS PKG 5	MOS	96	+1m/-1m			PKG		
MRB	REF: AMM 31 61 01 210 801	HRS/MSC AFL					23-DEC-2019 2630:03 1481		
31-61-05-201 (s)	GENERAL VISUAL INSPECTION L/HIRF PROTECTION ON THE DISPLAY CONTROL PANEL CONNECTORS AND MOUNTING POINTS PKG 5	MOS	96	+1m/-1m			PKG		
MRB	REF: AMM 31 61 05 210 801	HRS/MSC AFL					23-DEC-2019 2630:03 1481		
31-61-13-301 (s)	OPERATIONAL TEST OF THE REVERSION SELECT PANEL PKG 9	MOS	800				PKG		
MRB	REF: AMM 31 61 13 710 801	HRS/MSC AFL					06-DEC-2018 2236:21 1275		
311701-0101	LEFT CBP1 CIRCUIT BREAKER PANEL 995GC02Y10 411 REF: GENERIC NO REF	MOS	O/C		N:0			28-JAN-2011 0 0	
311701-0102	RIGHT CBP2 CIRCUIT BREAKER PANEL 990GC02Y07 407 REF: GENERIC NO REF	MOS	O/C		N:0			28-JAN-2011 0 0	
312101-0101	GPS CLOCK 2619-02-2 CLK10809 REF: See Workcard	MOS	O/C		N:0			28-JAN-2011 0 0	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
313101	A145 FLIGHT DATA (FDR) RECORDER 2100-2045-22 707049 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
313109	A146 ACCELEROMETER 3001-01-111 0211-DTF8172 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
313113-0101	FDR UNDERWATER LOCATOR DEVICE 266E0305-00 SC91426 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
313117	FDR S81 - IMPACT SWITCH 3L0-453/3 92388 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
314101	RIGHT EQUIP RACK A14 CONCENTRATOR - DATA (DCU-5000) UNIT 822-1578-007 3YB5D REF: See Workcard	MOS HRS/MSC AFL	O/C	N:107 N:2630:03 N:1481			23-DEC-2019 2630:03 1481		
314101-0101	MOUNTING (UMT-18) TRAY 622-9977-005 3Y7NM REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
314105	LEFT EQUIP RACK A13 CONCENTRATOR - REMOTE DATA (RDC-5000) UNIT 822-1581-001 3PL5C REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
314105-0101	MOUNTING (UMT-18) TRAY 622-9977-005 3Y7NK REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
314501	RIGHT EQUIP RACK A4 CAGE - IAPS (ICC-3001) CARD 822-2191-001 4K3739 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				23-DEC-2019 2630:03 1481	
314505-0101	LEFT IAPS CARD CAGE IOC NO.1 CONCENTRATOR - INPUT/OUTPUT (IOC-3100) UNIT 822-1362-171 4K37LP REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				23-DEC-2019 2630:03 1481	
314505-0102	RIGHT IAPS CARD CAGE IOC NO.2 CONCENTRATOR - INPUT/OUTPUT (IOC-3100) UNIT 822-1362-171 4K37LR REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				23-DEC-2019 2630:03 1481	
314509-0101	LEFT IAPS CARD CAGE PWR NO.1 - IAPS (PWR-3000) POWER SUPPLY 822-1137-001 3XR0W REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
314509-0102	RIGHT IAPS CARD CAGE PWR NO.2 - IAPS (PWR-3000) POWER SUPPLY 822-1137-001 3XR0X REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
314513	IAPS CARD CAGE - IAPS ENVIRONMENTAL (IEC-3000) CONTROLLER 822-1131-001 3J8RV REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
314517-0101	LEFT IAPS CARD CAGE CSU NO.1 CONFIGURATION STRAPPING (CSU-3100) UNIT 822-1363-002 3XR8V REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
314517-0102	RIGHT IAPS CARD CAGE CSU NO.2 CONFIGURATION STRAPPING (CSU-3100) UNIT 822-1363-002 3XRCC REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
314521-0101	LEFT IAPS CARD CAGE USED ON CSU-3100 NO.1- CONTROL (OCM-3100) OPTION FMS 3D NAV MAP MODULE 822-1484-237 4K35KH REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				23-DEC-2019 2630:03 1481	
314521-0102	RIGHT IAPS CARD CAGE USED ON CSU-3100 NO.2 - CONTROL (OCM-3100) OPTION FMS 3D NAV MAP MODULE 822-1484-222 4K35KG REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				23-DEC-2019 2630:03 1481	
314521-0103	LEFT IAPS CARD CAGE USED ON CSU-3100 NO.1- CONTROL (OCM-3100) MODULE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
314521-0104	RIGHT IAPS CARD CAGE USED ON CSU-3100 NO.2 - CONTROL (OCM-3100) MODULE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
315201	A52 LAMP DRIVER (LDU-4000) UNIT 622-9822-001 3N4VH REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
315221-0101	NO. 1 (A163) LAMP DRIVER POWER SUPPLY LT-45D 2818 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
315221-0102	NO. 2 (A72) LAMP DRIVER POWER SUPPLY LT-45D 2810 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				28-JAN-2011 0 0	
316101-0101	PFD1 (A27) ADAPTIVE FLIGHT DISPLAY 822-1917-308 3V0LX REF: See Workcard	MOS HRS/MSC AFL	O/C	N:107 N:2630:03 N:1481				23-DEC-2019 2630:03 1481	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
316101-0102	PFD2 (A26) ADAPTIVE FLIGHT DISPLAY 822-1917-308 2C52Y REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			23-DEC-2019 2630:03 1481		
316101-0103	MFD1 (A29) ADAPTIVE FLIGHT DISPLAY 822-1917-308 2G7PJ REF: See Workcard	MOS HRS/MSC AFL	O/C	O:25 O:716:13 O:360			23-DEC-2019 2630:03 1481		
316101-0104	MFD2 (A28) ADAPTIVE FLIGHT DISPLAY 822-1917-308 3Y00K REF: See Workcard	MOS HRS/MSC AFL	O/C	O:65 O:1378:20 O:742			23-DEC-2019 2630:03 1481		
316105-0101	PILOT DISPLAY CONTROL PANEL 822-1561-001 3VHKF REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
316105-0102	COPILOT DISPLAY CONTROL PANEL 822-1561-001 3VHMJ REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
316109-0101	NO. 1 (CCP-5220) CURSOR CONTROL PANEL 822-2213-004 3VHNK REF: See Workcard	MOS HRS/MSC AFL	O/C				25-APR-2013 464:23 247		
316109-0102	NO. 2 (CCP-5220) CURSOR CONTROL PANEL 822-2213-004 2LLVC REF: See Workcard	MOS HRS/MSC AFL	O/C	R:1 R:0 R:0			11-APR-2016 1554:51 924		
316113-0101	REVERSION SWITCH (RSP-5020) PANEL 822-1569-103 3HMNR REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 32	LANDING GEAR								
32-00-00-501	CLEANING OF THE LANDING GEAR AND UNDERCARRIAGE AREA								
MPD	REF: AMM 12 21 00 110 809	MOS HRS/MSC AFL	A/R				(EBT)		
32-11-00-201-1 (s)	DETAILED INSPECTION LEFT MAIN-LANDING-GEAR PINTLE PINS								
MRB	REF: AMM 32 11 00 220 801	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
32-11-00-201-2 (s)	DETAILED INSPECTION RIGHT MAIN-LANDING-GEAR PINTLE PINS								
MRB	REF: AMM 32 11 00 220 801	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
32-11-00-202-1 (s)	DETAILED INSPECTION LEFT MAIN-LANDING-GEAR ATTACHMENT PINS AND LUGS								
MRB	REF: AMM 32 11 00 220 802	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
32-11-00-202-2 (s)	DETAILED INSPECTION RIGHT MAIN-LANDING-GEAR ATTACHMENT PINS AND LUGS								
MRB	REF: AMM 32 11 00 220 802	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
32-11-00-203-1 (s)	SPECIAL DETAILED INSPECTION LEFT MAIN LANDING GEAR SHOCK STRUT-INTERNAL								
MRB	REF: AMM 32 11 00 280 801	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
32-11-00-203-2 (s)	SPECIAL DETAILED INSPECTION RIGHT MAIN LANDING GEAR SHOCK STRUT-INTERNAL								
MRB	REF: AMM 32 11 00 280 801	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-00-204-1 (s)	SPECIAL DETAILED INSPECTION LEFT MAIN LANDING GEAR SIDE-BRACE ACTUATOR-INTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 32 11 00 280 802								
32-11-00-204-2 (s)	SPECIAL DETAILED INSPECTION RIGHT MAIN LANDING GEAR SIDE-BRACE ACTUATOR-INTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 32 11 00 280 802								
32-11-00-205-1 (s)	DETAILED INSPECTION LEFT MAIN LANDING GEAR AXLE ASSEMBLY PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 32 11 00 220 803								
32-11-00-205-2 (s)	DETAILED INSPECTION RIGHT MAIN LANDING GEAR AXLE ASSEMBLY PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 32 11 00 220 803								
32-11-00-206	LUBRICATION MAIN LANDING GEAR AND COMPONENTS	MOS HRS/MSC AFL	12 600	+1m/-1m +40/-40		-14	23-DEC-2019 2630:03 1481	09-DEC-2020 3230:03	09-JAN-2021 3270:03
MRB	REF: AMM 12 22 00 640 802								
32-11-00-207-1 (s)	DETAILED INSPECTION LEFT MAIN LANDING GEAR (MLG) ASSEMBLY PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 32 11 00 220 804								
32-11-00-207-2 (s)	DETAILED INSPECTION RIGHT MAIN LANDING GEAR (MLG) ASSEMBLY PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 32 11 00 220 804								
32-11-00-208-1 (s)	RESTORATION LEFT MAIN LANDING GEAR (MLG) ASSEMBLY PKG 6	MOS HRS/MSC AFL	192	+1m/-1m			PKG 03-NOV-2011		
MRB	REF: AMM 32 11 00 280 803								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-00-208-2 (s)	RESTORATION RIGHT MAIN LANDING GEAR (MLG) ASSEMBLY PKG 6	MOS HRS/MSC AFL	192	+1m/-1m			PKG 03-NOV-2011		
MRB	REF: AMM 32 11 00 280 803								
32-11-05-201-1 (s)	FUNCTIONAL TEST LEFT MAIN LANDING GEAR SHOCK-STRUT EXTENSION PKG 11	MOS HRS/MSC AFL	1600	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 32 11 05 720 801								
32-11-05-201-2 (s)	FUNCTIONAL TEST RIGHT MAIN LANDING GEAR SHOCK-STRUT EXTENSION PKG 11	MOS HRS/MSC AFL	1600	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 32 11 05 720 801								
32-21-00-201 (s)	DETAILED INSPECTION NOSE-LANDING-GEAR TRUNNION PINS PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 32 21 00 220 801								
32-21-00-202 (s)	DETAILED INSPECTION NOSE-LANDING-GEAR ATTACHMENT PINS AND LUGS PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 32 21 00 220 802								
32-21-00-203 (s)	SPECIAL DETAILED INSPECTION NOSE-LANDING-GEAR SHOCK-STRUT, STEERING, AND AXLE-INTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 32 21 00 280 801								
32-21-00-204 (s)	SPECIAL DETAILED INSPECTION NOSE-LANDING-GEAR RETRACTION ACTUATOR-INTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 32 21 00 280 802								
32-21-00-205	LUBRICATION NOSE LANDING GEAR AND COMPONENTS	MOS HRS/MSC AFL	12 600	+1m/-1m +40/-40		-14	23-DEC-2019 2630:03 1481	09-DEC-2020 3230:03	09-JAN-2021 3270:03
MRB	REF: AMM 12 22 00 640 801								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-21-00-206 (s)	DETAILED INSPECTION NOSE LANDING GEAR (NLG) ASSEMBLY PKG 5	MOS HRS/MSC	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 32 21 00 220 803	AFL							
32-21-00-207 (s)	RESTORATION NOSE LANDING GEAR (NLG) ASSEMBLY PKG 6	MOS HRS/MSC	192	+1m/-1m			PKG 03-NOV-2011		
MRB	REF: AMM 32 21 00 280 803	AFL							
32-21-05-201 (s)	FUNCTIONAL TEST SHOCK-STRUT EXTENSION OF THE NOSE LANDING GEAR PKG 11	MOS HRS/MSC	1600	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 32 21 05 720 801	AFL							
32-22-00-102	SPECIAL DETAILED INSPECTION OF THE NOSE-LANDING-GEAR DOOR HINGE FITTINGS, ACTUATOR FITTINGS AND ATTACHMENTS - INCLUDING LUGS AND PINS	MOS HRS/MSC	7500				28-JAN-2011 0 0	7500	
AIRWORTHINESS	REF: NDT ET-32-22-001	AFL							
32-22-00-103	DISCARD OF THE NLG DOOR HINGE FITTING PINS, PART NO. NAS6304, NON-SERIALIZED	MOS HRS/MSC	7500				28-JAN-2011 0 0	7500	
LIFE LIMIT	REF: AMM 32 22 01 961 801	AFL							
32-22-00-201	DETAILED INSPECTION NOSE-LANDING-GEAR DOOR HINGES AND ATTACHMENTS	MOS HRS/MSC	48	+1m/-1m	-50		23-DEC-2019 2630:03 1481	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 32 22 00 220 801	AFL							
32-34-00-201 (s)	OPERATIONAL TEST EXTENSION AND RETRACTION SYSTEM PKG 11	MOS HRS/MSC	1600	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 32 30 00 710 801	AFL							

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-34-00-204 (s)	DETAILED INSPECTION LANDING GEAR EMERGENCY EXTENSION SYSTEM MECHANICAL CONTROL ROUTING IN THE FORWARD FUSELAGE (FS220.00 TO FS326.00)						PKG		
	PKG 12	MOS						06-DEC-2018	
		HRS/MSC	2400	+40/-40				2236:21	
MRB	REF: AMM 32 34 00 220 803	AFL						1275	
32-34-00-205 (s)	DETAILED INSPECTION LANDING GEAR EMERGENCY EXTENSION SYSTEM CONTROL ROUTING UNDER THE CABIN FLOOR (FS326.00 TO FS669.76)						PKG		
	PKG 5	MOS	96	+1m/-1m				23-DEC-2019	
		HRS/MSC						2630:03	
MRB	REF: AMM 32 34 00 220 804	AFL						1481	
32-34-00-302 (s)	DETAILED INSPECTION LANDING GEAR EMERGENCY EXTENSION SYSTEM CONTROL ROUTING IN THE MAIN LANDING GEAR BAY						PKG		
	PKG 10	MOS						06-DEC-2018	
		HRS/MSC	1200	+40/-40				2236:21	
MRB	REF: AMM 32 34 00 220 801	AFL						1275	
32-34-00-303 (s)	DETAILED INSPECTION LANDING GEAR EMERGENCY EXTENSION SYSTEM CONTROL ROUTING IN THE NOSE LANDING GEAR BAY						PKG		
	PKG 10	MOS						06-DEC-2018	
		HRS/MSC	1200	+40/-40				2236:21	
MRB	REF: AMM 32 34 00 220 802	AFL						1275	
32-34-00-306 (s)	FUNCTIONAL TEST LANDING-GEAR NORMAL AND EMERGENCY EXTENSION						PKG		
	PKG 9	MOS						06-DEC-2018	
		HRS/MSC	800	+40/-40				2236:21	
MRB	REF: AMM 32 34 00 720 801	AFL						1275	
32-41-00-201-1	DETAILED INSPECTION NO. 1 MAIN LANDING GEAR (MLG) WHEEL								
	3-1609-1	MOS						15-OCT-2018	
	1173	HRS/MSC	T/C					2215:56	
MRB	REF: AMM 32 41 01 220 801	AFL						1263	
32-41-00-201-2	DETAILED INSPECTION NO. 2 MAIN LANDING GEAR (MLG) WHEEL								
	3-1609-1	MOS						05-AUG-2019	
	1585	HRS/MSC	T/C					2506:39	
MRB	REF: AMM 32 41 01 220 801	AFL						1420	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-41-00-201-3	DETAILED INSPECTION NO. 3 MAIN LANDING GEAR (MLG) WHEEL 3-1609-1 0323 REF: AMM 32 41 01 220 801	MOS HRS/MSC AFL	T/C				28-JUN-2019 2473:32 1402		
MRB									
32-41-00-201-4	DETAILED INSPECTION NO. 4 MAIN LANDING GEAR (MLG) WHEEL 3-1609-1 0745 REF: AMM 32 41 01 220 801	MOS HRS/MSC AFL	T/C				06-APR-2018 1974:15 1149		
MRB									
32-41-00-301-1	SPECIAL DETAILED INSPECTION NO. 1 MAIN LANDING GEAR (MLG) WHEEL 3-1609-1 1173 REF: See Workcard	MOS HRS/MSC AFL	T/C				15-OCT-2018 2215:56 1263		
MRB									
32-41-00-301-2	SPECIAL DETAILED INSPECTION NO. 2 MAIN LANDING GEAR (MLG) WHEEL 3-1609-1 1585 REF: See Workcard	MOS HRS/MSC AFL	T/C				05-AUG-2019 2506:39 1420		
MRB									
32-41-00-301-3	SPECIAL DETAILED INSPECTION NO. 3 MAIN LANDING GEAR (MLG) WHEEL 3-1609-1 0323 REF: See Workcard	MOS HRS/MSC AFL	T/C				28-JUN-2019 2473:32 1402		
MRB									
32-41-00-301-4	SPECIAL DETAILED INSPECTION NO. 4 MAIN LANDING GEAR (MLG) WHEEL 3-1609-1 0745 REF: See Workcard	MOS HRS/MSC AFL	T/C				06-APR-2018 1974:15 1149		
MRB									
32-42-01-201-1	SPECIAL DETAILED INSPECTION LH NOSE LANDING GEAR (NLG) WHEEL 3-1610-1 0917 REF: See Workcard	MOS HRS/MSC AFL	T/C				24-JUN-2018 2081:26 1196		
MRB									
32-42-01-201-2	SPECIAL DETAILED INSPECTION RH NOSE LANDING GEAR (NLG) WHEEL 3-1610-1 1124 REF: See Workcard	MOS HRS/MSC AFL	T/C				19-JAN-2017 1703:13 1002		
MRB									

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-42-01-202-1	DETAILED INSPECTION LH NOSE LANDING GEAR (NLG) WHEEL 3-1610-1 0917 MRB REF: AMM 32 42 01 220 801	MOS HRS/MSC AFL	T/C				24-JUN-2018 2081:26 1196		
32-42-01-202-2	DETAILED INSPECTION RH NOSE LANDING GEAR (NLG) WHEEL 3-1610-1 1124 MRB REF: AMM 32 42 01 220 801	MOS HRS/MSC AFL	T/C				19-JAN-2017 1703:13 1002		
32-43-00-201 (s)	DETAILED INSPECTION BRAKE WEAR INDICATORS PKG 8 MRB REF: AMM 32 43 00 220 801	MOS HRS/MSC AFL	600	+40/-40			PKG 23-DEC-2019 2630:03 1481		
32-43-00-202 (s)	OPERATIONAL TEST BRAKE SYSTEM PKG 11 MRB REF: AMM 32 43 00 710 801	MOS HRS/MSC AFL	1600	+40/-40			PKG 06-DEC-2018 2236:21 1275		
32-43-33-301 (s)	FUNCTIONAL TEST BRAKE HYDRAULIC FUSE PKG 12 MRB REF: AMM 32 43 33 720 801	MOS HRS/MSC AFL	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
32-43-49-201 (s)	GENERAL VISUAL INSPECTION L/HIRF PROTECTION ON THE WHEEL SPEED TRANSDUCER CONNECTORS PKG 5 MRB REF: AMM 32 43 49 210 801	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
32-44-05-301 (s)	FUNCTIONAL TEST OF THE BRAKE ACCUMULATORS PKG 8 MRB REF: AMM 32 44 05 720 801	MOS HRS/MSC AFL	600	+40/-40			PKG 23-DEC-2019 2630:03 1481		
32-44-09-201 (s)	DETAILED INSPECTION PARK/EMER BRAKE HANDLE/VALVE CABLE CONNECTIONS PKG 12 MRB REF: AMM 32 44 09 220 801	MOS HRS/MSC AFL	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-44-13-301 (s)	OPERATIONAL TEST EMERGENCY/PARKING-BRAKE PRESSURE SWITCH PKG 10	MOS HRS/MSC	1200	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 32 44 13 710 801	AFL							
32-44-17-301 (s)	FUNCTIONAL TEST EMERGENCY/PARKING-BRAKE HYDRAULIC FUSE PKG 11	MOS HRS/MSC	1600	+40/-40			PKG 20-MAY-2016 1581:47 936		
MRB	REF: AMM 32 44 17 720 801	AFL							
32-51-03-201 (s)	FUNCTIONAL TEST NOSE WHEEL STEERING COMPENSATOR PKG 14	MOS HRS/MSC	4200	+40/-40			PKG 28-JAN-2011 0 0		
MRB	REF: AMM 32 51 03 720 801	AFL							
32-51-09-301 (s)	OPERATIONAL TEST STEERING SELECTOR VALVE PKG 12	MOS HRS/MSC	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 32 51 09 710 801	AFL							
32-61-09-301 (s)	FUNCTIONAL TEST PROXIMITY-SYSTEM ELECTRONIC-UNIT CIRCUITRY PKG 12	MOS HRS/MSC	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 32 61 09 720 802	AFL							
32-ZL-00-201 (s)	GENERAL VISUAL INSPECTION NOSE LANDING GEAR PKG 2	MOS HRS/MSC	24	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard	AFL							
32-ZL-00-202-1 (s)	GENERAL VISUAL INSPECTION LEFT MAIN LANDING GEAR PKG 2	MOS HRS/MSC	24	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard	AFL							
32-ZL-00-202-2 (s)	GENERAL VISUAL INSPECTION RIGHT MAIN LANDING GEAR PKG 2	MOS HRS/MSC	24	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard	AFL							

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-ZL-00-203 (s)	GENERAL VISUAL INSPECTION NOSE GEAR DOORS PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
32-ZL-00-204-1 (s)	GENERAL VISUAL INSPECTION LEFT MAIN LANDING-GEAR DOORS PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
32-ZL-00-204-2 (s)	GENERAL VISUAL INSPECTION RIGHT MAIN LANDING-GEAR DOORS PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
321018-0101	LEFT MAIN LANDING GEAR MAIN FITTING 40140-101 08SPP5132	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0		7500
LIFE LIMIT	REF: See Workcard								
321018-0102	RIGHT MAIN LANDING GEAR MAIN FITTING 40140-102 SPP5006	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0		7500
LIFE LIMIT	REF: See Workcard								
321018-0103	LEFT MAIN LANDING GEAR SHOCK STRUT CYLINDER ASSEMBLY 40405-101 08SPP5225	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0		7500
LIFE LIMIT	REF: See Workcard								
321018-0104	RIGHT MAIN LANDING GEAR SHOCK STRUT CYLINDER ASSEMBLY 40405-101 08SPP5226	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0		7500
LIFE LIMIT	REF: See Workcard								
321101-0101	LEFT MAIN LANDING GEAR PINTLE PIN ASSEMBLY 40118-103 08SPP0681	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0		7500
LIFE LIMIT	REF: See Workcard								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321101-0102	RIGHT MAIN LANDING GEAR PINTLE PIN ASSEMBLY 40118-104 08SPP0685	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
321101-0103	LH MLG SIDE BRACE LOWER PIN TO MAIN FITTING ASSEMBLY 40245-105 08SPP5058	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
321101-0104	RH MLG SIDE BRACE LOWER PIN TO MAIN FITTING ASSEMBLY 40245-106 08SPP5058	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
321101-0201	LEFT MAIN LANDING GEAR (MLG) ASSEMBLY 40105-107 10MDT0544	MOS HRS/MSC	O/C	R:0 N:2630:03 R:0			23-DEC-2019 2630:03		
	REF: See Workcard	AFL		N:1481 R:0			1481		
321101-0202	RIGHT MAIN LANDING GEAR (MLG) ASSEMBLY 40105-108 10MDT0545	MOS HRS/MSC	O/C	R:0 N:2630:03 R:0			23-DEC-2019 2630:03		
	REF: See Workcard	AFL		N:1481 R:0			1481		
321105-0101	LEFT MAIN LANDING GEAR SHOCK STRUT UPPER PIN 40124-1 08CPS1325	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
321105-0102	RIGHT MAIN LANDING GEAR SHOCK STRUT UPPER PIN 40124-1 08CPS1357	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
321105-0103	LEFT MAIN LANDING GEAR SHOCK STRUT LOWER PIN 40124-1 08CPS1326	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	15000	N:0			0	15000	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321105-0104	RIGHT MAIN LANDING GEAR SHOCK STRUT LOWER PIN 40124-1 08CPS1362	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	15000	N:0			0	15000	
321105-0105	LEFT MAIN LANDING GEAR SHOCK STRUT PISTON 40415-101 08SPP5179	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
321105-0106	RIGHT MAIN LANDING GEAR SHOCK STRUT PISTON 40415-101 08SPP5180	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
321105-0201	LEFT MAIN LANDING GEAR SHOCK STRUT ASSEMBLY 40400-105 10SPP0646	MOS HRS/MSC O/C		N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
321105-0202	RIGHT MAIN LANDING GEAR SHOCK STRUT ASSEMBLY 40400-105 10SPP0647	MOS HRS/MSC O/C		N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
321109-0101	LEFT MAIN LANDING GEAR TRAILING ARM ASSEMBLY 40142-101 08SPP5273	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
321109-0102	RIGHT MAIN LANDING GEAR TRAILING ARM ASSEMBLY 40142-101 08SPP5274	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
321109-0103	LEFT MAIN LANDING GEAR PIVOT PIN 40111-1 08SPP0472	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321109-0104	RIGHT MAIN LANDING GEAR PIVOT PIN 40111-1 08SPP0476	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
321113-0101	LEFT MAIN LANDING GEAR INBOARD WSS & WOW #1 HARNESS 40120-103 15-324	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
321113-0102	RIGHT MAIN LANDING GEAR INBOARD WSS & WOW #1 HARNESS 40120-104 17-317	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
321113-0103	LEFT MAIN LANDING GEAR OUTBOARD WSS & WOW #2 HARNESS 40121-103 16-320	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
321113-0104	RIGHT MAIN LANDING GEAR OUTBOARD WSS & WOW #2 HARNESS 40121-104 18-321	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
321117-0101	LH MLG SIDE BRACE TO AIRCRAFT UPPER PIN 40241-101 08EXC668	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
321117-0102	RH MLG SIDE BRACE TO AIRCRAFT UPPER PIN 40241-101 08EXC671	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
321121-0101-1	L/H MLG SIDE BRACE DOWN LOCK PROXIMITY SENSOR #1 ASSEMBLY 40550-101 5-645	MOS HRS/MSC	O/C	N:2630:03			23-DEC-2019 2630:03		
	REF: See Workcard	AFL		N:1481			1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321121-0101-2	L/H MLG SIDE BRACE DOWN LOCK PROXIMITY SENSOR #2 ASSEMBLY 40550-102 6-642 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:2630:03 N:1481			23-DEC-2019 2630:03 1481		
321121-0102-1	R/H MLG SIDE BRACE DOWN LOCK PROXIMITY SENSOR #1 ASSEMBLY 40550-101 5-638 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:2630:03 N:1481			23-DEC-2019 2630:03 1481		
321121-0102-2	R/H MLG SIDE BRACE DOWN LOCK PROXIMITY SENSOR #2 ASSEMBLY 40550-102 6-635 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:2630:03 N:1481			23-DEC-2019 2630:03 1481		
321125-0101	LEFT MAIN LANDING GEAR AXLE 40112-1 08SPP0623 REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
321125-0102	RIGHT MAIN LANDING GEAR AXLE 40112-1 08SPP0624 REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
321201-0101	LEFT MAIN LANDING GEAR OUTBOARD DOOR ASSEMBLY 1005781051-001 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
321201-0102	RIGHT MAIN LANDING GEAR OUTBOARD DOOR ASSEMBLY 1005781051-002 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
322008-0101	NOSE LANDING GEAR TORQUE LINK LOWER PIN 40842-1 08EXC1551 REF: AMM 32 21 05 961 808	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322008-0103	NOSE LANDING GEAR LOWER TORQUE LINK 40646-101 09MER0399	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 32 21 05 961 806	AFL	7500	N:0			0	7500	
322008-0104	NOSE LANDING GEAR UPPER TORQUE LINK 40644-103 09MER0402	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 32 21 05 961 805	AFL	7500	N:0			0	7500	
322008-0106	NOSE LANDING GEAR PISTON 40831-1 09MBM0380	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 32 21 05 961 802	AFL	7500	N:0			0	7500	
322008-0107	NOSE LANDING GEAR TORQUE LINKS APEX PIN 40950-1 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
322008-0108	NOSE LANDING GEAR CUFF - STEERING ASSEMBLY 40650-105 08EXC0436	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
322008-0109	NLG FWD STEERING ACTUATOR 40653-101 1-20317	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: GENERIC NO REF	AFL		N:0			0		
322008-0110	NLG AFT STEERING ACTUATOR 40653-101 2-20317	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: GENERIC NO REF	AFL		N:0			0		
322008-0501	NOSE LANDING GEAR TORQUE LINK UPPER PIN 40637-1 09CPS0354	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 32 21 05 961 803	AFL	7500	N:0			0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322008-0601	NOSE LANDING GEAR PISTON TUBE PIN 40672-1 08EXC0403	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 32 21 05 961 807	AFL	7500	N:0			0	7500	
322009-0102	NOSE LANDING GEAR LOWER DRAG BRACE 40912-101 08EXC0338	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
322009-0201	NOSE LANDING GEAR UPPER DRAG BRACE 40910-101 10MBM0361	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
322100-0101	NLG CYLINDER ASSEMBLY 40710-101 08MBM0459	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: GENERIC NO REF	AFL		N:0			0		
322100-0201	NLG PISTON ROD 40720-1 09MBM0448	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: GENERIC NO REF	AFL		N:0			0		
322100-0301	NLG LOCKING SEGMENT 40682-1 09AB0095	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: GENERIC NO REF	AFL		N:0			0		
322105-0101	NOSE LANDING GEAR LEFT CYLINDER TRUNNION PIN 40631-1 09CPS0670	MOS HRS/MSC		N:2630:03			23-DEC-2019 2630:03		
LIFE LIMIT	REF: AMM 32 21 05 961 810	AFL	7500	N:1481			1481	7500	
322105-0102	NOSE LANDING GEAR RIGHT CYLINDER TRUNNION PIN 40631-1 09CPS0671	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 32 21 05 961 810	AFL	7500	N:0			0	7500	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322105-0103	NOSE LANDING GEAR ASSEMBLY 40610-113 10MDT0331 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
322105-0104	NOSE LANDING GEAR SHOCK STRUT ASSEMBLY 40630-113 10MDT0331 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:107 R:0 N:2630:03 R:0 N:1481 R:0			23-DEC-2019 2630:03 1481		
322109-0101	NOSE LANDING GEAR STEERING AND SENSOR #1 HARNESS 40622-103 12-336 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
322109-0102	NOSE LANDING GEAR LIGHTS AND SENSOR #2 HARNESS 40621-103 11-337 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
322113-0101	NOSE LANDING GEAR UPPER DRAG BRACE LEFT UPPER TRUNNION PIN 40914-1 10CPS0738 LIFE LIMIT REF: AMM 32 21 13 961 805	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
322113-0102	NOSE LANDING GEAR UPPER DRAG BRACE RIGHT UPPER TRUNNION PIN 40914-1 10CPS0739 LIFE LIMIT REF: AMM 32 21 13 961 805	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
322113-0103	NOSE LANDING GEAR LOWER DRAG/CYLINDER PIN 40615-1 08EXC0345 LIFE LIMIT REF: AMM 32 21 13 961 802	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
322113-0105	NOSE LANDING GEAR MAIN FITTING CYLINDER 40640-109 17MDC2119 LIFE LIMIT REF: AMM 32 21 05 961 801	MOS HRS/MSC AFL	3750	N:0 N:0 N:0			23-DEC-2019 2630:03 1481	5231	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322113-0201	DRAG BRACE ASSEMBLY 40900-103 10MDT0333 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:107 R:0 N:2630:03 R:0 N:1481 R:0			23-DEC-2019 2630:03 1481		
322113-0301	NOSE LANDING GEAR DRAG BRACE APEX PIN 16404-1 19CPS2870 REF: AMM 32 21 13 961 801	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			23-DEC-2019 2630:03 1481	8981	
322113-0401	SERVO VALVE 40753-103 LHC-0297 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-DEC-2019 2630:03 1481		
322121-0101	NOSE LANDING GEAR DRAG BRACE LEFT - DOWNLOCK SENSOR #1 HARNESS 40901-103 13-333 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
322121-0102	NOSE LANDING GEAR DRAG BRACE RIGHT - DOWNLOCK SENSOR #2 HARNESS 40902-103 14-329 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
322201-0101	NOSE LANDING GEAR FORWARD LEFT DOOR ASSEMBLY 1005321300-005 F875223 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
322201-0102	NOSE LANDING GEAR FORWARD RIGHT DOOR ASSEMBLY 1005321300-006 F814960 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
322205	NOSE LANDING GEAR AFT DOOR ASSEMBLY 1005321301-003 F814528 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322225-0101	LEFT NLG DOOR MECHANISM ASSEMBLY 40669-105 08MBM0663 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
322225-0102	RIGHT NLG DOOR MECHANISM ASSEMBLY 40669-106 08MBM0626 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
323043-0101-1	LH MLG SIDE BRACE ACTUATOR ROD-END ASSEMBLY 19400-1 4052 REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		8981
323043-0101-2	RH MLG SIDE BRACE ACTUATOR ROD-END ASSEMBLY 19400-1 4077 REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		8981
323043-0102-1	LH MLG SIDE BRACE ACTUATOR PISTON ASSEMBLY 40303-1 0460 REF: See Workcard	MOS HRS/MSC AFL	7500	N:2178 N:1045			23-DEC-2019 2630:03 1481		7936
323043-0102-2	RH MLG SIDE BRACE ACTUATOR PISTON ASSEMBLY 40303-2 1104 REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		8981
323043-0103-1	LH MLG SIDE BRACE ACTUATOR CYLINDER ASSEMBLY 40302-1 631 REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0		7500
323043-0103-2	RH MLG SIDE BRACE ACTUATOR CYLINDER ASSEMBLY 40302-1 610 REF: See Workcard	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0		7500

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323043-0201	LH MLG SIDE BRACE ACTUATOR ROD END CAP 17013-11 831-4056 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:2630:03 N:1481			23-DEC-2019 2630:03 1481		
323043-0202	RH MLG SIDE BRACE ACTUATOR ROD END CAP 17013-11 4797 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
323101	V9 - LANDING GEAR SELECTOR VALVE 17C17616 0267T REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
323105-0101	NOSE LANDING GEAR SEQUENCING CANISTER 41240-103 10CEP0657 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
323105-0102	MAIN LANDING GEAR SEQUENCING CANISTER 41240-103 08CEP0563 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
323113	CENTER CONSOLE LANDING GEAR CONTROL HANDLE 41210-101 ECE-487 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
323201-0101	LEFT MAIN LANDING GEAR AUXILIARY EXTEND ACTUATOR 40250-101 10FAH0654 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
323201-0102	RIGHT MAIN LANDING GEAR AUXILIARY EXTEND ACTUATOR 40250-101 10FAH0653 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323205-0101	LEFT MAIN LANDING GEAR UPLOCK ASSEMBLY 40500-101 06NGL1079 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
323205-0102	RIGHT MAIN LANDING GEAR UPLOCK ASSEMBLY 40500-102 10SM00011 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
323207-0101	LH MLG SIDE BRACE ACTUATOR 40310-107 0631G REF: See Workcard	MOS HRS/MSC AFL	O/C	N:2630:03 N:1481			23-DEC-2019 2630:03 1481		
323207-0102	RH MLG SIDE BRACE ACTUATOR 40310-107 0624G REF: See Workcard	MOS HRS/MSC AFL	O/C	N:2630:03 N:1481			23-DEC-2019 2630:03 1481		
323301	NOSE LANDING GEAR RETRACTION ACTUATOR 40700-103 10MDT0305 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:107 R:0 N:2630:03 R:0 N:1481 R:0			23-DEC-2019 2630:03 1481		
323301-0101	NOSE LANDING GEAR RETRACTION ACTUATOR UPPER PIN 40613-1 09CPS0721 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
323301-0102	NOSE LANDING GEAR RETRACTION ACTUATOR LOWER PIN 40613-1 09CPS0723 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
323305	NOSE LANDING GEAR UPLOCK ASSEMBLY 40800-101 09SM00002 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:567 N:514			06-NOV-2014 1164:01 690		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323401-0101	LANDING GEAR MANUAL RELEASE HANDLE 41310-105 374 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
323405-0101	RUN AROUND AND DUMP VALVE 17C17615 0280T REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
323409-0101	MANUAL SELECTOR VALVE 41360-103 0299T REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
323413-0101	MANUAL RELEASE QUADRANT ASSEMBLY 41320-101 10EXC0408 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
323415-0101	LANDING GEAR ASSIST ACCUMULATOR 900104-1 EFS0328 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324101-0101	NO. 1 MAIN LANDING GEAR (MLG) WHEEL 3-1609-1 1173 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:14 R:0 O:414:07 R:0 O:218 R:0			23-DEC-2019 2630:03 1481		
324101-0102	NO. 2 MAIN LANDING GEAR (MLG) WHEEL 3-1609-1 1585 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			05-AUG-2019 2506:39 1420		
324101-0103	NO. 3 MAIN LANDING GEAR (MLG) WHEEL 3-1609-1 0323 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 O:241 R:0 O:87 R:0			28-JUN-2019 2473:32 1402		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324101-0104	NO. 4 MAIN LANDING GEAR (MLG) WHEEL 3-1609-1 0745 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:21 R:0 O:655:48 R:0 O:332 R:0			23-DEC-2019 2630:03 1481		
324101-0105	NO. 1 MAIN LANDING GEAR (MLG) TIRE 269K43-2 80863204 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
324101-0106	NO. 2 MAIN LANDING GEAR (MLG) TIRE 269K43-2 80092774 REF: See Workcard	MOS HRS/MSC AFL	O/C				05-AUG-2019 2506:39 1420		
324101-0107	NO. 3 MAIN LANDING GEAR (MLG) TIRE 269K43-2 81363284 REF: See Workcard	MOS HRS/MSC AFL	O/C				28-JUN-2019 2473:32 1402		
324101-0108	NO. 4 MAIN LANDING GEAR (MLG) TIRE 269K43-2 80833222 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
324201-0101	LH NOSE LANDING GEAR (NLG) WHEEL 3-1610-1 0917 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			23-DEC-2019 2630:03 1481		
324201-0102	RH NOSE LANDING GEAR (NLG) WHEEL 3-1610-1 1124 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			23-DEC-2019 2630:03 1481		
324201-0103	LH NOSE LANDING GEAR (NLG) TIRE 185K03-1 82003033 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324201-0104	RH NOSE LANDING GEAR (NLG) TIRE 185K03-1 81502665 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
324301	EQUIP RACK LH A67 BRAKE CONTROL UNIT 142-045-1 448 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324305-0101	PILOT LEFT MT93 - POSITION BRAKE PEDAL TRANSDUCER 20-109500-1 839249 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324305-0102	COPILOT LEFT MT94 - POSITION BRAKE PEDAL TRANSDUCER 20-109500-1 839673 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324305-0103	PILOT RIGHT MT95 - POSITION BRAKE PEDAL TRANSDUCER 20-109500 847429 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324305-0104	COPILOT RIGHT MT96 - POSITION BRAKE PEDAL TRANSDUCER 20-109500 847428 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324309-0101	LEFT LG BAY MPE23 - BRAKE CONTROL VALVE 39-853-1 670D REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 N:1857 O:0 N:1027 O:0			09-DEC-2015 1470:55 878		
324309-0102	RIGHT LG BAY MPE24 - BRAKE CONTROL VALVE 39-853-1 783 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324313-0101	NO. 1 MAIN LANDING GEAR BRAKE ASSEMBLY 2-1662-2 1413 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324313-0102	NO. 2 MAIN LANDING GEAR BRAKE ASSEMBLY 2-1662-2 1412 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324313-0103	NO. 3 MAIN LANDING GEAR BRAKE ASSEMBLY 2-1662-2 1332 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324313-0104	NO.4 MAIN LANDING GEAR BRAKE ASSEMBLY 2-1662-2 1334 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324317-0101	BRAKE CONTROL SYSTEM PRESSURE TRANSDUCER 52-597500 7566-3-277 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324317-0102	BRAKE CONTROL SYSTEM PRESSURE TRANSDUCER 52-597500 7635-12-55 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324317-0103	BRAKE CONTROL SYSTEM PRESSURE TRANSDUCER 52-597500 7635-12-232 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324317-0104	BRAKE CONTROL SYSTEM PRESSURE TRANSDUCER 52-597500 7635-9-241 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324317-0105	BRAKE CONTROL SYSTEM PRESSURE TRANSDUCER 52-597500 7635-12-225 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324321-0101	SHUTTLE VALVE 38-881500-2 1253 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324321-0102	SHUTTLE VALVE 38-881500-2 1249 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324321-0103	SHUTTLE VALVE 38-881500-2 1332 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324321-0104	SHUTTLE VALVE 38-881500-2 1401 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324325-0101	LH (MPE27) BRAKE SHUTOFF VALVE 38-877500-1 755 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324325-0102	RH (MPE28) BRAKE SHUTOFF VALVE 38-877500-1 691 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324329-0101	CHECK VALVE 38-879500 1357 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324329-0102	CHECK VALVE 38-879500 1296 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324329-0103	CHECK VALVE 38-879500 1316 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324329-0104	CHECK VALVE 38-879500 1367 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324333-0101	LEFT LG BAY UPPER HYDRAULIC BRAKE FUSE 38-875500-1 1294 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324333-0102	RIGHT LG BAY UPPER HYDRAULIC BRAKE FUSE 38-875500-1 1326 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324333-0103	LEFT LG BAY LOWER HYDRAULIC BRAKE FUSE 38-875500-1 1285 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324333-0104	RIGHT LG BAY LOWER HYDRAULIC BRAKE FUSE 38-875500-1 1332 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324337-0101	OUTBOARD SYSTEM 2 BRAKE ACCUMULATOR 33-147500 60218-2024NAE REF: See Workcard	MOS HRS/MSC AFL		R:18 N:3240 R:0 N:2144 R:0			25-JUL-2018 2112:06 1211		14267
LIFE LIMIT			15200						

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324341-0101	CHARGE VALVE 35-829500 9C697 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324341-0102	CHARGE VALVE 35-829500 7F493 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324345-0101	RIGHT BRAKE PRESSURE SWITCH 52-599500 700 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324345-0102	LEFT BRAKE PRESSURE SWITCH 52-599500 576 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324349-0101	LEFT OUTBRD MT89 #1 - WHEEL SPEED TRANSDUCER 140-247-2 8865 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324349-0102	LEFT INBRD MT91 #2 - WHEEL SPEED TRANSDUCER 140-247-2 8869 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324349-0103	RIGHT INBRD MT90 #3 - WHEEL SPEED TRANSDUCER 140-247-2 8873 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324349-0104	RIGHT OUTBRD MT92 #4 - WHEEL SPEED TRANSDUCER 140-247-2 8867 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324401-0101	EMERGENCY PARKING BRAKE VALVE 38-883500-1 331 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324401-0201	EMERGENCY PARKING BRAKE CABLE 38-883500-3 357 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324405-0101	INBOARD SYSTEM 1 EMERGENCY / PARKING BRAKE ACCUMULATOR 33-155500 60219-2136NA LIFE LIMIT REF: See Workcard	MOS HRS/MSC AFL	8300	N:0 N:0 N:0			28-JAN-2011 0 0	8300	
324409-0101	PARK/EMERGENCY BRAKE HANDLE 38-883500-5 381 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324413-0101	PARKING BRAKE PRESSURE SWITCH 52-611500 350 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
324417-0101	HYDRAULIC FUSE 38-903500 345 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
325093-0101-1	L/H MLG SIDE BRACE LOCK SEGMENT UNIT 17016-3 WW2621 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
325093-0101-2	L/H MLG SIDE BRACE LOCK SEGMENT UNIT 17016-3 WW2622 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
325093-0101-3	L/H MLG SIDE BRACE LOCK SEGMENT UNIT 17016-3 WW2623 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
325093-0101-4	L/H MLG SIDE BRACE LOCK SEGMENT UNIT 17016-3 WW2624 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
325093-0102-1	R/H MLG SIDE BRACE LOCK SEGMENT UNIT 17016-3 14547 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:2630:03 N:1481			23-DEC-2019 2630:03 1481		
325093-0102-2	R/H MLG SIDE BRACE LOCK SEGMENT UNIT 17016-3 14548 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:2630:03 N:1481			23-DEC-2019 2630:03 1481		
325093-0102-3	R/H MLG SIDE BRACE LOCK SEGMENT UNIT 17016-3 14549 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:2630:03 N:1481			23-DEC-2019 2630:03 1481		
325093-0102-4	R/H MLG SIDE BRACE LOCK SEGMENT UNIT 17016-3 14550 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:2630:03 N:1481			23-DEC-2019 2630:03 1481		
325095-0101	L/H MLG SIDE BRACE LOCK INDICATOR RING 17235-2 7861 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
325095-0102	R/H MLG SIDE BRACE LOCK INDICATOR RING 17235-2 7879 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
325101-0000	STEERING CONTROL UNIT 46000-01 10-362 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
325103	COMPENSATOR - STEERING ASSEMBLY 41270-101 10CEP0317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
325105	MT85 HANDWHEEL - STEERING CONTROL ASSEMBLY 41120-105 ECE-0450 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
325109	V7 - SELECTOR STEERING VALVE 41130-107 345 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
325113	NOSE LANDING GEAR STEERING MANIFOLD 40750-103 LHC-0297 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:1 N:2195 R:0 N:872 R:0			05-MAR-2015 1274 758		
325117	RUDDER PEDAL TRANSDUCER 41150-101 661-34 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
325125-0101	NOSE WHEEL STEERING PRESSURE SWITCH 41140-101 L023866 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
325129-0101	NOSE WHEEL STEERING ROTARY VARIABLE TRANSDUCER 40760-3 2497 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-SEP-2019 2587:59 1454		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
326101-0101	LH MLG DOWNLOCK (PX09) PROXIMITY SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
326101-0102	RH MLG DOWNLOCK (PX08) PROXIMITY SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
326101-0103	LH MLG DOWNLOCK (PX39) PROXIMITY SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
326101-0104	RH MLG DOWNLOCK (PX38) PROXIMITY SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
326105-0301	NLG LH DOOR (PX34) PROXIMITY SENSOR 40102-0101 25155 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
326105-0302	NLG RH DOOR (PX35) PROXIMITY SENSOR 40102-0101 27820 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
326105-0401	PROXIMITY SENSOR 40102-0101 27740 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
326105-0402	PROXIMITY SENSOR 40102-0101 27811 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
326109-0101	PSEU UNIT 30227-0402 458 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
326110	NOSE LANDING GEAR AXLE 40642-101 08MDC04899 REF: AMM 32 21 05 961 804	MOS HRS/MSC AFL	7500	R:0 N:1724:24 R:0 N:1168 R:0			23-DEC-2019 2630:03 1481	7813	
CHAPTER 33 LIGHTS									
33-20-00-601 (s)	OPERATIONAL TEST ORDINANCE SIGNS PKG 1 REF:	MOS HRS/MSC AFL	12	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
STLMC									
33-43-00-201 (s)	GENERAL VISUAL INSPECTION WING TIP LENSES (CRAZING AND DIFFUSION OF LIGHT SOURCE) PKG 2 REF: AMM 33 43 00 210 801	MOS HRS/MSC AFL	24	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB									
33-51-00-601	RESTORATION UPPER CABIN EMERGENCY LIGHTS POWER SUPPLY REF:	MOS HRS/MSC AFL	12	+1m/-1m	-17		23-DEC-2019 2630:03 1481	06-DEC-2020	06-JAN-2021
STLMC									
33-51-00-602	RESTORATION EMERGENCY ESCAPE PATH LIGHTING POWER SUPPLY REF:	MOS HRS/MSC AFL	18	+1m/-1m			23-DEC-2019 2630:03 1481	23-JUN-2021	23-JUL-2021
STLMC									
33-51-00-603 (s)	OPERATIONAL TEST INTERIOR EMERGENCY LIGHTS PKG 1 REF:	MOS HRS/MSC AFL	12	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
STLMC									

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-51-17-201	RESTORATION AFT PS4 - EMERGENCY UNIT POWER SUPPLY (BENCH TEST) EMERGENCY-LIGHTING POWER SUPPLY 8ES455070-00 24677 REF: AMM 33 51 00 720 801	MOS HRS/MSC AFL	18	+1m/-1m			23-DEC-2019 2630:03 1481	23-JUN-2021	23-JUL-2021
MRB									
33-51-17-201	RESTORATION FWD PS3 - EMERGENCY UNIT POWER SUPPLY (BENCH TEST) EMERGENCY-LIGHTING POWER SUPPLY 8ES455070-00 24678 REF: AMM 33 51 00 720 801	MOS HRS/MSC AFL	18	+1m/-1m			23-DEC-2019 2630:03 1481	23-JUN-2021	23-JUL-2021
MRB									
331000-0101	FLIGHT CREW READING LIGHT 2LA004626-15 1692588 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
331000-0102	FLIGHT CREW READING LIGHT 2LA004626-15 1692583 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
331101-0101	INTEGRAL LIGHTING CONTROLLER 510ZT01Y01 632 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
331301-0101	COCKPIT DOME LIGHT 2LA455115-30 1545898 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
331309-0101	STAIR LIGHT 2LA455119-50 1684112 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331309-0102	STAIR LIGHT 2LA455119-50 1463339 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
331309-0103	STAIR LIGHT 2LA455119-50 1684110 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
331309-0104	STAIR LIGHT 2LA455119-50 1684133 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
331309-0105	STAIR LIGHT 2LA455119-50 1684124 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
331309-0106	STAIR LIGHT 2LA455119-50 1684111 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
331309-0107	STAIR LIGHT 2LA455119-50 1452417 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
331309-0108	STAIR LIGHT 2LA455119-50 1573162 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
332003-7002	RIGHT FORWARD LIGHTING POWER SUPPLY ELP-2824-101 102325-19-1 REF:	MOS HRS/MSC AFL	O/C				28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
332003-7004	RIGHT AFT LIGHTING POWER SUPPLY ELP-2824-401 102325-18-1 REF:	MOS HRS/MSC AFL	O/C				28-JAN-2011 0 0		
333101-0101	AFT EQUIPMENT LIGHT 2LA002607-22 1573936 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
333101-0102	AFT EQUIPMENT LIGHT 2LA002607-22 1573942 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
333105-0101	AFT EQUIPMENT BAY AUTO SHUT-OFF BOX 8ES007655-22 1626941 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
333109-0101	CARGO LOADING LIGHT 2LA455032-70 1584734 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
334105-0101	TAXI LIGHT 1X0003664-10 469 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
334109-0101	LANDING LIGHT 1X0003664-20 476 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
334113-0101	LEFT WING LANDING LIGHT ASSEMBLY 1X0455703-00 1743283 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334113-0102	RIGHT WING LANDING LIGHT ASSEMBLY 1X0455703-00 1743279 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
334117-0101	LH LANDING COVER LIGHT 9EL455212-03 M31715 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
334117-0102	RH LANDING COVER LIGHT 9EL455212-04 M41750 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
334121-0101	LEFT WING HID LANDING LIGHT POWER SUPPLY 109121 1733542 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
334121-0102	RIGHT WING HID LANDING LIGHT POWER SUPPLY 109121 1723959 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
334201-0101	LH WING RED (DS13) PRIMARY NAV LIGHT 2LA455705-00 1463410 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
334201-0102	RH WING GREEN (DS14) PRIMARY NAV LIGHT 2LA006178-02 1717607 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
334201-0103	LH WING RED (DS16) SECONDARY NAV LIGHT 2LA006178-02 1717597 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334201-0104	RH WING GREEN (DS17) SECONDARY NAV LIGHT 2LA455706-00 1522627 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
334205-0101	TAIL PRIMARY DS15 LIGHT NAV ASSEMBLY 2LA006419-30 1739816 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
334205-0102	TAIL SECONDARY DS18 LIGHT NAV ASSEMBLY 2LA006419-30 1555982 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
334301	LOWER DS20 LIGHT - STROBE/ANTI COLLISION ASSEMBLY 2LA003849-22 1613536 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
334305	UPPER DS19 LIGHT - STROBE/ANTI COLLISION ASSEMBLY 9HD402153-22 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:26 N:0 N:0			28-JUN-2016 1631:45 960		
334309-0101	LEFT PS1- STROBE/ANTI COLLISION POWER SUPPLY 8ES456037-02 1492167 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
334309-0102	RIGHT PS2- STROBE/ANTI COLLISION POWER SUPPLY 8ES456037-02 2425886 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:32 N:0 N:0			28-JUN-2016 1631:45 960		
334407	LEFT WING TIP STROBE POWER SUPPLY 8ES005421-19 1712340 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334408	RIGHT WING TIP STROBE POWER SUPPLY 8ES005421-19 1712341 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
334501-0101	LH WING (DS21) INSPECTION LIGHT 2LA455030-13 3419533 REF: See Workcard	MOS HRS/MSC AFL	O/C				19-JAN-2017 1703:13 1002		
334501-0102	RH WING (DS22) INSPECTION LIGHT 2LA455030-14 1473127 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
335000-7201	LAVA ORDINANCE SIGN ASSY MT1-AC40003-1 102739-17-1 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
335003	AFT EMERGENCY LIGHTS POWER SUPPLY BR9767-001 C1780 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
335005	FWD EMERGENCY LIGHTS POWER SUPPLY BR9767-001 C1773 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
335105-0201	EMERGENCY EXIT LIGHT 2LA004305-55 1674373 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
335105-0202	EMERGENCY EXIT LIGHT 2LA004305-55 1674372 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
335105-0203	EMERGENCY EXIT LIGHT 2LA004305-55 1674365 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
335105-7001	AFT EMERGENCY POWER SUPPLY BATTERY BR9767-001 C0758 REF:	MOS HRS/MSC AFL	O/C				09-DEC-2015 1470:55 878		
335117-0101	FWD PS3 - EMERGENCY UNIT POWER SUPPLY 8ES455070-00 24678 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
335117-0102	AFT PS4 - EMERGENCY UNIT POWER SUPPLY 8ES455070-00 24677 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
335117-7101	FWD BATTERY HOLDER ASSEMBLY 2013-1A 74837 REF:	MOS HRS/MSC AFL	O/C	N:55196 N:7372			04-NOV-2014 1164:01 690		
335117-7102	AFT BATTERY HOLDER ASSEMBLY 2013-1A 122661 REF:	MOS HRS/MSC AFL	O/C	N:4 N:0 N:0			13-FEB-2015 1268:30 752		
CHAPTER 34	NAVIGATION								
34-11-00-201 (s)	FUNCTIONAL TEST (LEAK TEST) OF THE PITOT-STATIC SYSTEM PKG 4	MOS HRS/MSC	48	+1m/-1m			PKG 23-DEC-2019 2630:03		
MRB	REF: AMM 34 11 00 790 801	AFL					1481		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-11-00-202 (s)	FUNCTIONAL TEST (LEAK TEST) OF THE STANDBY PITOT-STATIC SYSTEM PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 34 11 00 790 802								
34-11-00-203 (s)	DETAILED INSPECTION STATIC PORTS PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 34 11 00 220 801								
34-11-01-201 (s)	DETAILED INSPECTION PITOT-STATIC PROBE PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 34 11 01 220 802								
34-11-01-202 (s)	DETAILED INSPECTION P3 PITOT PROBE PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 34 11 03 220 801								
34-11-09-201 (s)	SERVICING PITOT-STATIC VISUAL DRAIN PKG 2	MOS HRS/MSC AFL	24	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 34 11 09 616 801								
34-11-13-201 (s)	GENERAL VISUAL INSPECTION L/HIRF PROTECTION ON THE TOTAL AIR TEMPERATURE (TAT) PROBE CONNECTOR PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 34 11 13 210 801								
34-12-01-201 (s)	FUNCTIONAL TEST INTEGRATED STANDBY INSTRUMENT PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 34 12 01 720 801								
34-12-01-202 (s)	GENERAL VISUAL INSPECTION L/HIRF PROTECTION ON THE INTEGRATED STANDBY INSTRUMENT CONNECTOR AND MOUNTING POINTS PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 34 12 01 210 801								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-13-00-101-1	FUNCTIONAL TEST LH A1 - AIR DATA (ADC-3000) COMPUTER (RVSM) 822-1109-020 PKG 2 3WGYH REF: AMM 34 13 01 720 801	MOS HRS/MSC AFL	24				23-DEC-2019 2630:03 1481	23-DEC-2021	
RVSM									
34-13-00-101-2	FUNCTIONAL TEST RH A2 - AIR DATA (ADC-3000) COMPUTER (RVSM) 822-1109-020 PKG 2 3WH1T REF: AMM 34 13 01 720 801	MOS HRS/MSC AFL	24				23-DEC-2019 2630:03 1481	23-DEC-2021	
RVSM									
34-13-00-501	DISCARD LH A1 - AIR DATA (ADC-3000) COMPUTER BATTERY 822-1109-020 3WGYH REF: AMM 34 13 01 960 801	MOS HRS/MSC AFL	72				02-JAN-2017	02-JAN-2023	
OPTIONAL									
34-13-00-501	DISCARD RH A2 - AIR DATA (ADC-3000) COMPUTER BATTERY 822-1109-020 3WH1T REF: AMM 34 13 01 960 801	MOS HRS/MSC AFL	72				02-JAN-2017	02-JAN-2023	
OPTIONAL									
34-21-13-201 (s)	SPECIAL DETAILED INSPECTION OF THE L/HIRF PROTECTION ON THE FLUX DETECTOR UNIT CONNECTOR (A/C 20003 TO 20407) PKG 5 REF: AMM 34 21 13 280 801	MOS HRS/MSC AFL	96	+1m/-1m			23-DEC-2019 2630:03 1481		
MRB									
34-42-00-701	CHECK EGPWS DATABASE STATUS AND UPDATE IF NECESSARY REF:	MOS HRS/MSC AFL	6	+1m			18-JUN-2020 2715:55 1526	18-DEC-2020	18-JAN-2021
CUSTOMER CODE									
34-55-00-201 (s)	GENERAL VISUAL INSPECTION OF THE L/HIRF PROTECTION ON THE CLOCK CONNECTOR (POST SB 100-34-23) PKG 5 REF: AMM 34 55 01 210 801	MOS HRS/MSC AFL	96	+1m/-1m			23-DEC-2019 2630:03 1481		
MRB									
34-61-00-501	DISCARD RIGHT EQUIP RACK FMC NO.1 - FLIGHT MANAGEMENT (FMC) COMPUTER BATTERY 822-2488-130 PKG 4 4K3726 REF: AMM 34 61 01 960 801	MOS HRS/MSC AFL	48				23-DEC-2019 2630:03 1481	23-DEC-2023	
OPTIONAL									

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-61-00-501	DISCARD RIGHT EQUIP RACK FMC NO.2 - FLIGHT MANAGEMENT (FMC) COMPUTER BATTERY 822-2488-130 PKG 4 4K3728 REF: AMM 34 61 01 960 801	MOS HRS/MSC AFL	48				23-DEC-2019 2630:03 1481	23-DEC-2023	
OPTIONAL									
34-61-09-701	UPDATE FMS NAV DATABASE REF:	DAYS HRS/MSC AFL	28				10-JUL-2020 2738:37 1539	12-AUG-2020 M	
CUSTOMER CODE									
341101-0101	LH A137 - PITOT-STATIC (34-11-00-101) PROBE 0856WC3 294674 REF: See Workcard	MOS HRS/MSC AFL	9600	N:0 N:0 N:0			09-DEC-2015 1470:55 878	11070:55	
DISCARD									
341101-0102	RH A138 - PITOT-STATIC (34-11-00-101) PROBE 0856WC4 294498 REF: See Workcard	MOS HRS/MSC AFL	9600	N:0 N:0 N:0			09-DEC-2015 1470:55 878	11070:55	
DISCARD									
341103-0103	STANDBY A143 - PITOT-STATIC PROBE 0851LV 280018 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
DISCARD									
341105-0101	LEFT A139 - STATIC PRESSURE STATIC PORT ST314-2L 1350011 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
DISCARD									
341105-0102	RIGHT A140 - STATIC PRESSURE STATIC PORT ST314-2R 1195512 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
DISCARD									
341113	RIGHT A16 - TOTAL AIR TEMPERATURE SENSOR 102AU1AG B165 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
DISCARD									

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341201	CENTER CONSOLE (A90) (ISI) INTEGRATED STANDBY INSTRUMENT C16786LA02 C16786001397 REF: See Workcard	MOS HRS/MSC AFL	O/C				19-JAN-2017 1703:13 1002		
341301-0101	LH A1 - AIR DATA (ADC-3000) COMPUTER 822-1109-020 3WGYH REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			19-JAN-2017 1703:13 1002		
341301-0102	RH A2 - AIR DATA (ADC-3000) COMPUTER 822-1109-020 3WH1T REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			19-JAN-2017 1703:13 1002		
342101-0101	LEFT EQUIP RACK A11 - ATTITUDE HEADING (AHC-3000) COMPUTER 822-1110-002 49MNY REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
342101-0102	RIGHT EQUIP RACK A12 - ATTITUDE HEADING (AHC-3000) COMPUTER 822-1110-002 454RB REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
342113-0101	LEFT WING A21 - FLUX (FDU-3000) DETECTOR 822-1193-001 44351 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
342113-0102	RIGHT WING A20 - FLUX (FDU-3000) DETECTOR 822-1193-001 44350 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
342117-0101	LEFT EQUIP RACK A23 EXTERNAL COMPENSATION (ECU-3000) UNIT 822-1200-002 4555C REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342117-0102	RIGHT EQUIP RACK A22 EXTERNAL COMPENSATION (ECU-3000) UNIT 822-1200-002 4555D REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
342201	FLIGHT COMPARTMENT- STANDBY COMPASS WL1001KCA1 BD4130709 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
344101-0101	RADOME - WEATHER RADAR ANTENNA 622-8440-004 33KWY REF: See Workcard	MOS HRS/MSC AFL	O/C	R:5 R:0 R:0			29-JUN-2017 1778:26 1043		
344201-0101	RIGHT EQUIP RACK A34 - TERRAIN-AVOIDANCE WARNING (TAS-5000) (TAWS) COMPUTER 822-1575-001 455TJ REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
344201-0102	RIGHT A185 EQUIP RACK ON TAS-5000 - TAWS MODULE 822-1791-001 3HPMV REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
344300-0101	TCAS MOUNT 270-2682-020 MA51327 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
344301	LEFT EQUIP RACK A5 - TCAS II (TTR-4000) TRANSMITTER/RECEIVER 822-1294-032 170839 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			09-DEC-2015 1470:55 878		
344309-1	UPPER E10 - TCAS ANTENNA 622-8973-001 3TH9X REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344309-2	LOWER E10- TCAS ANTENNA PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C						
344313	TCAS OMINDIRECTIONAL E11 - L BAND ANTENNA 7634400002-001 260-1350 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
344401	A32 - RADIO (ALT-4000) ALTIMETER 822-0615-206 3Y93M REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
344409-0101	LEFT RADIO ALTIMETER ANTENNA 7634400001-001 543-53228 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
344409-0102	RIGHT RADIO ALTIMETER ANTENNA 7634400001-001 543-54025 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
345101-0101	LEFT EQUIP RACK A47 - VOR/ILS/MKR/ADF (NAV-4000) RECEIVER 822-1465-001 2B11P REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			12-OCT-2018 2212:03 1261		
345101-0102	RIGHT EQUIP RACK A48 - VOR/ILS/MKR (NAV-4500 OR NAV-4500) RECEIVER 822-1465-001 3XG7J REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
345113-0101	LEFT VERTICAL STABILIZER E17 - VOR/LOC ANTENNA 7634500002-001 180-6044 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345113-0102	RIGHT VERTICAL STABILIZER E18 - VOR/LOC ANTENNA 763450002-001 180-6045 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
345117	RADOME - GLIDESLOPE ANTENNA S41422-2 111-6951 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
345121-0101	LEFT E21 - MARKER BEACON ANTENNA 763450001-001 102-8675 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
345121-0102	RIGHT E16 - MARKER BEACON ANTENNA 763450001-001 102-8678 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
345125-0103	E22 - ADF ANTENNA 622-7384-001 3Y87T REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
345301-0101	LEFT EQUIP RACK A49 - DME (DME-4000) TRANSCEIVER 822-1466-001 3YD3H REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
345301-0102	RIGHT EQUIP RACK A50 OPTION - DME (DME-4000) TRANSCEIVER 822-1466-001 3YD3L REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
345309-0101	FORWARD DME E19 - L BAND ANTENNA S65-5366-7L 261-102378 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345309-0102	AFT DME E20 OPTION - L BAND ANTENNA S65-5366-7L 261-133829 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
345401-0101	LEFT EQUIP RACK A31 - ATC (MODE S)(TDR94D) TRANSPONDER 622-9210-501 45CLJ REF: See Workcard	MOS HRS/MSC AFL	O/C				23-DEC-2019 2630:03 1481		
345401-0102	RIGHT EQUIP RACK A30 - ATC (MODE S)(TDR94D) TRANSPONDER 622-9210-501 45CLG REF: See Workcard	MOS HRS/MSC AFL	O/C				23-DEC-2019 2630:03 1481		
345409-0101	NO. 1 ATC LOWER RIGHT E4 - L BAND ANTENNA S65-5366-7L 261-129955 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			06-DEC-2018 2236:21 1275		
345409-0102	NO. 1 ATC UPPER LEFT E5 - L BAND ANTENNA S65-5366-7L 261-133053 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
345409-0103	NO. 2 ATC UPPER RIGHT E6 - L BAND ANTENNA S65-5366-7L 261-133048 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
345409-0104	NO. 2 ATC LOWER LEFT E7 - L BAND ANTENNA S65-5366-7L 261-102374 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
345501-0101	LEFT RECEIVER - GPS (GPS-4000A) OR (GPS-4000S) RECEIVER 822-2189-100 3VLPP REF: See Workcard	MOS HRS/MSC AFL	O/C	N:107 R:0 N:2630:03 R:0 N:1481 R:0			23-DEC-2019 2630:03 1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345501-0102	RIGHT RECEIVER - GPS (GPS-4000A) OR (GPS-4000S) RECEIVER 822-2189-100 3VLMJ REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			23-DEC-2019 2630:03 1481		
345509-0101	NO. 1 FORWARD E3 - GPS ANTENNA S67-1575-135 818-0987 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
345509-0102	NO. 2 AFT E2 OPTION - GPS ANTENNA S67-1575-135 818-0869 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
346101-0101	RIGHT EQUIP RACK FMC NO.1 - FLIGHT MANAGEMENT (FMC) COMPUTER 822-2488-130 4K3726 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
346101-0102	RIGHT EQUIP RACK FMC NO.2 - FLIGHT MANAGEMENT (FMC) COMPUTER 822-2488-130 4K3728 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
346105-0101	LEFT CENTER PEDESTAL A68 DISPLAY CONTROL - FMS (CDU-5200) UNIT 822-1560-106 3RKTL REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
346105-0102	RIGHT CENTER PEDESTAL A69 DISPLAY CONTROL - FMS (CDU-5200) UNIT 822-1560-106 1MC7L REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			23-DEC-2019 2630:03 1481		
346105-0201	FMC DATALOADER PANEL 1003148001-001 29983 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
346109	LEFT EQUIP RACK (A191) (DBU) DATA BASE UNIT 822-3000-203 4H1MP7 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
34FAR-1	INSPECT/TEST PITOT STATIC SYSTEM (91.411) REF: GENERIC NO REF	MOS HRS/MSC AFL	24				23-DEC-2019 2630:03 1481	23-DEC-2021	
34FAR-2	INSPECT/TEST LH A1 - AIR DATA (ADC-3000) COMPUTER (FAR 91.411) 822-1109-020 3WGYH REF: GENERIC NO REF	MOS HRS/MSC AFL	24				06-DEC-2018 2236:21 1275	06-DEC-2020	
34FAR-3	INSPECT/TEST RH A2 - AIR DATA (ADC-3000) COMPUTER (FAR 91.411) 822-1109-020 3WH1T REF: GENERIC NO REF	MOS HRS/MSC AFL	24				06-DEC-2018 2236:21 1275	06-DEC-2020	
34FAR-5	INSPECT/TEST LEFT EQUIP RACK A31 - ATC (MODE S)(TDR94D) TRANSPONDER (FAR 91.413) 622-9210-501 45CLJ REF: GENERIC NO REF	MOS HRS/MSC AFL	24				23-DEC-2019 2630:03 1481	23-DEC-2021	
34FAR-6	INSPECT/TEST RIGHT EQUIP RACK A30 - ATC (MODE S)(TDR94D) TRANSPONDER (FAR 91.413) 622-9210-501 45CLG REF: GENERIC NO REF	MOS HRS/MSC AFL	24				23-DEC-2019 2630:03 1481	23-DEC-2021	
34FAR-7	INSPECT/TEST 30 DAY VOR CHECK (FAR 91.171) REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A						

CHAPTER 35 OXYGEN

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-00-00-301 (s)	OPERATIONAL TEST OXYGEN SYSTEM PKG 3	MOS	36	+1m/-1m			PKG 07-DEC-2017 1913:50 1121		
MRB	REF: AMM 35 00 00 710 802	HRS/MSC AFL							
35-00-00-602	FUNCTIONAL TEST PASSENGER OXYGEN SYSTEM	MOS	72	+1m/-1m			26-JAN-2016 1505:49 896	26-JAN-2022	26-FEB-2022
STLMC	REF:	HRS/MSC AFL							
35-00-00-608	RESTORATION OF THE PASSENGER OXYGEN MASK DISPENSING UNIT AND MASK ASSEMBLIES	MOS	72				19-JAN-2017 1703:13 1002	19-JAN-2023	
STLMC	REF:	HRS/MSC AFL							
35-11-07-202-1	RESTORATION (OVERHAUL) OF PILOT CREW OXYGEN MASK MC20-019 B106063	MOS	72	+1m/-1m			01-DEC-2015	01-DEC-2021	01-JAN-2022
MRB	REF: AMM 35 11 07 610 801	HRS/MSC AFL							
35-11-07-202-2	RESTORATION (OVERHAUL) OF COPILOT CREW OXYGEN MASK MC20-019 B099640I	MOS	72	+1m/-1m			10-DEC-2016	10-DEC-2022	10-JAN-2023
MRB	REF: AMM 35 11 07 610 801	HRS/MSC AFL							
35-11-07-301 (s)	OPERATIONAL TEST CREW OXYGEN MASKS AND SMOKE GOGGLES PKG 2	MOS	24	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 35 11 07 710 801	HRS/MSC AFL							
35-12-00-301 (s)	OPERATIONAL TEST OXYGEN CONTENTS INDICATION-SYSTEM PKG 8	MOS	600	+40/-40			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 35 12 00 710 801	HRS/MSC AFL							

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351101	AFT CABIN (77 CU. FT.) OXYGEN STORAGE CYLINDER 806371-121 ALT-281-24699 REF: See Workcard Manufacture Date: 01-AUG-2010	MOS HRS/MSC AFL	180	R:34 R:530:29 R:272			06-DEC-2018 2236:21 1275	01-AUG-2025	
351101B	FUNCTIONAL TEST (HYDROSTATIC TEST) AFT CABIN (77 CU. FT.) OXYGEN STORAGE CYLINDER (35-11-00-201) 806371-121 ALT-281-24699 REF: AMM 35 11 00 720 801	MOS HRS/MSC AFL	36	+1m/-1m			26-NOV-2018	26-NOV-2021	26-DEC-2021
351105	AFT CABIN (115 CU. FT.) OXYGEN STORAGE CYLINDER 806371-111 CI6080853 REF: See Workcard Manufacture Date: 01-JUL-2016	MOS HRS/MSC AFL	180				06-DEC-2018 2236:21 1275	01-JUL-2031	
351105B	FUNCTIONAL TEST (HYDROSTATIC TEST) AFT CABIN (115 CU. FT.) OXYGEN STORAGE CYLINDER (35-11-00-201) 806371-111 CI6080853 REF: AMM 35 11 00 720 801	MOS HRS/MSC AFL	36	+1m/-1m			26-NOV-2018	26-NOV-2021	26-DEC-2021
351107-0101	PILOT CREW OXYGEN MASK MC20-019 B106063 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:12 N:0 N:0			19-JAN-2017 1703:13 1002		
351107-0102	COPILOT CREW OXYGEN MASK MC20-019 B099640I REF: See Workcard	MOS HRS/MSC AFL	O/C	O:1 N:1212 O:0 N:751 O:0			19-JAN-2017 1703:13 1002		
351107-0201	AFT LAVATORY CREW PBE, PERSONAL BREATHING UNIT 119003-21 0A4-45680M REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351107-0201B	RESTORATION AFT LAVATORY CREW PBE, PERSONAL BREATHING UNIT (35-00-00-605) 119003-21 0A4-45680M REF:	MOS HRS/MSC AFL	120				01-MAR-2018	01-MAR-2028	
STLMC									
351107-0201C	DISCARD AFT LAVATORY CREW PBE, PERSONAL BREATHING UNIT (35-00-00-606) 119003-21 0A4-45680M REF:	MOS HRS/MSC AFL	240				01-MAR-2018	01-MAR-2038	
STLMC									
351107-0201D	DETAILED INSPECTION AFT LAVATORY CREW PBE, PERSONAL BREATHING UNIT (35-00-00-607) 119003-21 PKG 1 0A4-45680M REF:	MOS HRS/MSC AFL	12				23-DEC-2019 2630:03 1481	23-DEC-2020	
STLMC									
351107-0202	FLIGHT COMPARTMENT (BULKHEAD) CREW PBE, PERSONAL BREATHING UNIT 119003-21 0A4-45497M REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
351107-0202B	RESTORATION FLIGHT COMPARTMENT (BULKHEAD) CREW PBE, PERSONAL BREATHING UNIT (25-62-00-202) 119003-21 0A4-45497M REF: AMM 25 62 05 610 801	MOS HRS/MSC AFL	120	+1m/-1m			01-MAR-2018	01-MAR-2028	01-APR-2028
MRB									
351107-0202C	DISCARD FLIGHT COMPARTMENT (BULKHEAD) CREW PBE, PERSONAL BREATHING UNIT (25-62-00-203) 119003-21 0A4-45497M REF: AMM 25 62 05 960 801	MOS HRS/MSC AFL	240	+1m/-1m			01-MAR-2018	01-MAR-2038	01-APR-2038
MRB									
351107-0202D	DETAILED INSPECTION FLIGHT COMPARTMENT (BULKHEAD) CREW PBE, PERSONAL BREATHING UNIT (25-62-00-208) 119003-21 PKG 2 0A4-45497M REF: AMM 25 62 05 220 801	MOS HRS/MSC AFL	24	+1m/-1m			23-DEC-2019 2630:03 1481	23-DEC-2021	23-JAN-2022
MRB									
351201	MT127 - TEMP/PRESSURE OXYGEN TRANSDUCER 10008789 20091906 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
352105	A186 - ELECTRICAL PNEUMATIC (EPAV) VALVE 448525-3 583 REF: See Workcard	MOS HRS/MSC AFL	O/C				26-JAN-2016 1505:49 896		
352125-7101	OXYGEN BOX OXYGEN BOX 833-830-01 D10120383 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
352125-7102	OXYGEN BOX OXYGEN BOX 833-830-01 D10120415 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
352125-7103	OXYGEN BOX OXYGEN BOX 833-830-01 D10120394 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
352125-7104	OXYGEN BOX OXYGEN BOX 833-830-01 D10120413 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
352125-7105	OXYGEN BOX OXYGEN BOX 833-830-01 D10120406 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
352125-7106	OXYGEN BOX OXYGEN BOX 833-830-01 D10120408 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
352125-7107	OXYGEN BOX OXYGEN BOX 833-830-01 D10120407 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
352125-7108	OXYGEN BOX OXYGEN BOX 833-830-01 D10120400 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
352125-7109	OXYGEN BOX OXYGEN BOX 833-830-01 D10120411 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
352125-7110	OXYGEN BOX OXYGEN BOX 833-830-02 D10070290 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
CHAPTER 36 PNEUMATIC									
36-11-00-201 (s)	DETAILED INSPECTION INTERMEDIATE-PRESSURE CHECK VALVE PKG 12	MOS HRS/MSC AFL	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 36 11 00 220 801								
361103-0101	LEFT MT21 - BLEED PRESSURE TRANSDUCER GG436-1007-1 2417 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361103-0102	RIGHT MT22 - BLEED PRESSURE TRANSDUCER GG436-1007-1 2416 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361105-0101	LEFT AFT EQUIPMENT BAY V3 - BLEED (BV) INTERMEDIATE PRESS VALVE 60081A020000 767 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361105-0102	RIGHT AFT EQUIPMENT BAY V4 - BLEED (BV) INTERMEDIATE PRESS VALVE 60081A020000 766 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361109-0101	LEFT AFT EQUIPMENT BAY - CHECK BLEED VALVE 2299A010000 669 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361109-0102	RIGHT AFT EQUIPMENT BAY - CHECK BLEED VALVE 2299A010000 668 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361115-0103	AFT EQUIPMENT BAY MPE2 - CROSS BLEED VALVE 6151A010001 167 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:114 R:0 N:4271:28 R:0 R:0			07-DEC-2012 368:45 200		
361117-0101	HIGH POWER GROUND CONNECTION GG514-1019-1 14100933 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361121-0101	HP GROUND DUCT 12700B020000 436 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361123-0101	APU DISCHARGE DUCT 12701B020000 441 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361125-0101	APU LINE DUCT 12702B020000 433 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361127-0101	LH IP PORT DISCHARGE DUCT 12707B020000 449 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361129-0101	RH IP PORT DISCHARGE DUCT 12703B020000 452 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361131-0101	LH ATS DUCT 12706B020000 507 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361133-0101	RH ATS DUCT 12704B020000 469 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361135-0101	IP CROSSOVER DUCT 12705B020000 460 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361137-0101	LWR FS VENTURI DUCT 12708B020000 437 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361139-0101	UPR FS VENTURI DUCT 12711B020000 462 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361141-0101	LWR BLEED DUCT 12709B020000 457 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361143-0101	UPR BLEED DUCT 12712B020000 447 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361145-0101	LWR PCE INLET DUCT 12710B020000 434 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361147-0101	UPR PCE INLET DUCT 12713B020000 436 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361149-0101	PACK INLET DUCT 12714B020000 461 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361149-0201	UROSEAL CONNECTOR GG468-4054-19 4038 REF: See Workcard	MOS HRS/MSC AFL	8000	N:0 N:0 N:0			28-JAN-2011 0 0	8000	
361151-0101	PACK OUTLET DUCT 12715B020000 433 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361501-0101	LEFT V5 - HIGH PRESS BLEED (HPV) VALVE 60078A020000 00821 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			19-JUN-2018 2074:46 1192		
361501-0102	RIGHT V6 - HIGH PRESS BLEED (HPV) VALVE 60078A020000 772 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361503-0101	LEFT MT19 - BLEED PRESSURE TRANSDUCER GG436-1007-1 2414 REF: See Workcard	MOS HRS/MSC AFL	O/C				06-JUN-2018 2051:03 1184		
361503-0102	RIGHT MT20 - BLEED PRESSURE TRANSDUCER GG436-1007-1 2415 REF: See Workcard	MOS HRS/MSC AFL	O/C				06-JUN-2018 2051:03 1184		
361505-0101	LH PORT DUCT 12735B020000 466 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361505-0102	RH PORT DUCT 12736B020000 498 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361507-0101	LH BLEED PIPE 12737B020000 442 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
361507-0102	RH BLEED PIPE 12738B020000 500 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
CHAPTER 38	WATER/WASTE								
38-10-00-602 (s)	GENERAL VISUAL INSPECTION POTABLE WATER SYSTEM PKG 1	MOS HRS/MSC	12	+1m/-1m			PKG 23-DEC-2019 2630:03		
STLMC	REF:	AFL					1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
38-10-00-603	STERILIZATION POTABLE WATER SYSTEM	MOS	6	+10%/-10%		-7	30-JUN-2020 2723:48 1530	31-DEC-2020	11-JAN-2021
STLMC	REF:	HRS/MSC AFL							
38-31-00-601 (s)	GENERAL VISUAL INSPECTION TOILET WASTE DISPOSAL SYSTEM	MOS	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
STLMC	REF:	HRS/MSC AFL							
389507-7101	WATER MODULAR SYSTEM	MOS					26-APR-2018 1981:25 1152		
	AR9017-11 1034773	HRS/MSC	O/C						
	REF:	AFL							
CHAPTER 44 CABIN SYSTEMS									
441003-0101	FORWARD WARDROBE POWER SWITCHING MODULE	MOS					28-JAN-2011 0 0		
	PN	HRS/MSC	O/C	N:0					
	SN-UNKNOWN	AFL		N:0					
	REF: GENERIC NO REF			N:0					
441003-0102	AFT CABIN POWER SWITCHING MODULE	MOS					28-JAN-2011 0 0		
	PN	HRS/MSC	O/C	N:0					
	SN-UNKNOWN	AFL		N:0					
	REF: GENERIC NO REF			N:0					
441003-0103	FORWARD CABIN POWER SWITCHING MODULE	MOS					28-JAN-2011 0 0		
	PN	HRS/MSC	O/C	N:0					
	SN-UNKNOWN	AFL		N:0					
	REF: GENERIC NO REF			N:0					
441005-0101	NO. 1 FORWARD WARDROBE DATABUS REPEATER	MOS					28-JAN-2011 0 0		
	PN	HRS/MSC	O/C	N:0					
	SN-UNKNOWN	AFL		N:0					
	REF: GENERIC NO REF			N:0					

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
441005-0102	NO. 2 FORWARD WARDROBE DATABUS REPEATER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
441005-0103	NO. 3 FORWARD WARDROBE DATABUS REPEATER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
441005-0104	NO.4 FORWARD WARDROBE DATABUS REPEATER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
441007-0101	NO. 1 FORWARD WARDROBE DATA BUS CONVERTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
441007-0102	FORWARD WARDROBE DATA BUS CONVERTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
441011-0101	FORWARD WARDROBE INFRARED RECEIVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
441011-0102	AFT BULKHEAD INFRARED RECEIVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
441015-0101	L/H NO. 1 PASSENGER CONTROL UNIT SWITCH PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
441015-0102	R/H NO. 1 PASSENGER CONTROL UNIT SWITCH PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
441015-0103	L/H NO. 2 PASSENGER CONTROL UNIT SWITCH PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
441015-0104	R/H NO. 2 PASSENGER CONTROL UNIT SWITCH PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
441015-0105	L/H NO.3 PASSENGER CONTROL UNIT SWITCH PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
441015-0106	R/H NO.3 PASSENGER CONTROL UNIT SWITCH PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
441015-0107	L/H NO.4 PASSENGER CONTROL UNIT SWITCH PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
441015-0108	R/H NO.4 PASSENGER CONTROL UNIT SWITCH PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
441015-0109	WARDROBE CABINET ASSEMBLY - FORWARD LEFT HAND SWITCH PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
441015-0110	LEFT BAGGAGE BULKHEAD BAGGAGE LIGHT MOMENTARY SWITCH PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
441015-0111	LAVATORY SWITCH PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
442201-7301	DUAL ETHERNET DVD PLAYER DVD0106-001-001 020004 REF:	MOS HRS/MSC AFL	O/C				31-DEC-2017 1935:08 1127		
442205-7301	FWD 20 INCH LCD MONITOR- LCD2005-000-100 30638 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
442205-7302	AFT 20 INCH LCD MONITOR- LCD2005-000-100 30637 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
442501-7101	HOT LIQUID CONTAINER D11752-20 862 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
442501-7102	HOT LIQUID CONTAINER D11752-20 537 REF:	MOS HRS/MSC AFL	O/C				26-DEC-2018 2269:19 1291		
442901-7101	FLIGHT DECK AIRSHOW CONTROLLER 922000-3 NG41G REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
442903-7101	DIGITAL INTERFACE AIRSHOW (DMU) UNIT 920055 G01000427 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
443009-7101	COCKPIT SIGMA-7 HANDSET 500905-10-10 0211-6013 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

CHAPTER 45 CENTRAL MAINT SYSTEM

45-45-00-501	DISCARD RIGHT EQUIP RACK MDC1 MAINTENANCE DIAGNOSTICS (MDC-4110) COMPUTER BATTERY 822-1988-104 3J93C REF: AMM 45 45 01 960 801	MOS HRS/MSC AFL	48				25-NOV-2019	25-NOV-2023	
454501	RIGHT EQUIP RACK MDC1 MAINTENANCE DIAGNOSTICS (MDC-4110) COMPUTER 822-1988-104 3J93C REF: See Workcard	MOS HRS/MSC AFL	O/C	N:107 R:0 N:2630:03 R:0 N:1481 R:0			23-DEC-2019 2630:03 1481		

ENGINE NO. 1 Model : AS907-1-1A Serial # P118773 Part # 3030001-4

45-76-00-201	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION ENGINE FAULT AND DIAGNOSTIC DATA PKG 7 REF: See Workcard	MOS HRS/MSC ENC	400	+40/-40		-5:15	23-DEC-2019 2641:36 1492	(3036:21) 3024:48	3076:21
--------------	-----------------------------------------------------------------------------------------------------------	-----------------------	-----	---------	--	-------	--------------------------------	-------------------	---------

ENGINE NO. 2 Model : AS907-1-1A Serial # P118771 Part # 3030001-4

45-76-00-201 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION ENGINE FAULT AND DIAGNOSTIC DATA PKG 7 REF: See Workcard	MOS HRS/MSC ENC	400	+40/-40			23-DEC-2019 2641:36 1491		
------------------	-----------------------------------------------------------------------------------------------------------	-----------------------	-----	---------	--	--	--------------------------------	--	--

CHAPTER 46 INFORMATION SYSTEMS

462101-0101	LH (FSU-501) FILE SERVER UNIT 822-1543-101 3LM4C REF:	MOS HRS/MSC AFL	O/C						
-------------	----------------------------------------------------------------	-----------------------	-----	--	--	--	--	--	--

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
462101-0102	RH (FSU-501) FILE SERVER UNIT 822-1543-101 44YCR REF:	MOS HRS/MSC AFL	O/C						
462117-0101	ECU-3000 EXTERNAL COMPENSATION UNIT 822-1200-996 4K1D9F REF:	MOS HRS/MSC AFL	O/C				23-DEC-2019 2630:03 1481		
462117-0102	EXTERNAL COMPENSATION UNIT 822-1200-998 454VR REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
462117-0103	EXTERNAL COMPENSATION UNIT 822-1200-998 46K3R REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
CHAPTER 49 AIRBORNE AUXILIARY POWER									
491505-0101	APU AIR INLET FLEXIBLE DUCT 1004953007-003 338 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
491509-0101	GENERATOR INLET DUCT HOSE 1004906002-003 11168 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
491509-0201	EXHAUST GENERATOR DUCT 1004906010-001 PFW0337 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
491601-0101	LCV REMOVABLE DUCT 1004955001-003 PFW0335 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
491605-0101	STUB EXH SURGE VALVE 1004955020-003 PFW0344 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
494020	IGNITER PLUG 3888002-2 NSN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-DEC-2019 2630:03 1481		
498101-0201	APU STUB 1004984060-001 PFW0338 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
49APU1 49.APU1	APU 3800774-1 P-430 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:2692:15			06-APR-2018 1974:15 1149		
APU Model : GTCP36-150(BD) Serial # P-430 Part # 3800774-1									
49-11-00-201	APU - GENERAL VISUAL INSPECTION APU MOUNT SYSTEM REF: See Workcard	MOS HRS/MSC APUS	3200	+40/-40			23-DEC-2019 3569	6769	6809
49-15-01-201	APU - GENERAL VISUAL INSPECTION APU INLET DUCT REF: See Workcard	MOS HRS/MSC APUS	1600	+40/-40			06-DEC-2018 3008:15	4608:15	4648:15

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
49-15-09-201 (s)	APU - GENERAL VISUAL INSPECTION APU GENERATOR COOLING DUCT PKG 18 REF: See Workcard	MOS HRS/MSC APUS	800	+40/-40			PKG 23-DEC-2019 3569		
49-16-01-201	APU - GENERAL VISUAL INSPECTION APU BLEED AIR DUCT IN THE APU ENCLOSURE REF: See Workcard	MOS HRS/MSC APUS	3200	+40/-40			23-DEC-2019 3569	6769	6809
49-16-03-301	APU - FUNCTIONAL TEST APU BLEED AIR CHECK VALVE 1004955040-005 PKG 20 2685 REF: See Workcard	MOS HRS/MSC APUS	2400	+40/-40			23-DEC-2019 3569	5969	6009
49-18-00-201 (s)	APU - VISUAL CHECK OF THE APU DRAINS PKG 18 REF: See Workcard	MOS HRS/MSC APUS	800	+40/-40			PKG 23-DEC-2019 3569		
49-20-00-201	APU - GENERAL VISUAL INSPECTION TURBINE ROTOR OF HOUSING 3615880-002 10-156101-08872 REF: See Workcard	MOS HRS/MSC APUS	3200	+40/-40			23-DEC-2019 3569	6769	6809
49-20-00-203	APU - SPECIAL DETAILED INSPECTION COMPRESSOR ROTOR HOUSING 3822101-1 10-162246-02804 REF: See Workcard	MOS HRS/MSC APUS	A/R				21-DEC-2010 0 0		
49-20-00-205	APU - DETAILED INSPECTION APU CONTAINMENT RING REF: See Workcard	MOS HRS/MSC APUS	A/R				21-DEC-2010 0 0		
49-20-00-206	APU - GENERAL VISUAL INSPECTION APU COMPRESSOR INLET DUCT REF: See Workcard	MOS HRS/MSC APUS	5000	+40/-40			21-DEC-2010 0 0	5000	5040



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
49-31-00-201 (s)	APU - VISUAL CHECK APU FUEL FILTER DIFFERENTIAL-PRESSURE-INDICATOR PKG 18 REF: See Workcard	MOS HRS/MSC APUS	800	+40/-40			PKG 23-DEC-2019 3569		
49-31-00-202 (s)	APU - GENERAL VISUAL INSPECTION APU FUEL SYSTEM COMPONENTS PKG 18 REF: See Workcard	MOS HRS/MSC APUS	600	+40/-40			PKG 23-DEC-2019 3569		
+ 49-41-09-201 (s)	APU - DETAILED INSPECTION IGNITER PLUG PKG 20 REF: See Workcard	MOS HRS/MSC APUS	2400	+40/-40			PKG 23-DEC-2019 3569		
49-42-00-201	APU - DETAILED INSPECTION APU ELECTRIC STARTER BRUSHES 519892-6-3 7863 REF: See Workcard	MOS HRS/MSC APUS	3000	+40/-40	-8:15		06-DEC-2018 3008:15	6000	6040
49-81-01-201	APU - GENERAL VISUAL INSPECTION APU EXHAUST MUFFLER ASSEMBLY APU EXHAUST MUFFLER AND ATTACHMENT FITTINGS 1004984001-005 PFW0332 REF: See Workcard	MOS HRS/MSC APUS	1600	+40/-40			06-DEC-2018 3008:15	4608:15	4648:15
49-91-00-201 (s)	APU - DISCARD OF THE APU OIL PKG 19 REF: See Workcard	MOS HRS/MSC APUS	1200	+40/-40			PKG 06-DEC-2018 3008:15		
49-91-00-501	APU - CHECK QUANTITY OF OIL SUPPLY IN APU REF: See Workcard	MOS HRS/MSC APUS	125	+40/-40		3	10-JUL-2020 3755 0	3883	3923
+ 49-91-05-201 (s)	APU - DETAILED INSPECTION APU MAGNETIC CHIP DETECTOR PKG 18 REF: See Workcard	MOS HRS/MSC APUS	800	+40/-40			PKG 23-DEC-2019 3569		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
49-91-13-201 (s)	APU - DISCARD APU OIL FILTER PKG 19	MOS					PKG		
DISCARD	REF: See Workcard	HRS/MSC APUS	1200	+40/-40			23-DEC-2019 3569		
490090	APU - APU CENTER PEDESTAL PANEL ASSEMBLY PN SN-UNKNOWN	MOS					21-DEC-2010		
	REF:	HRS/MSC APUS	O/C	N:0 N:0 N:0			0 0 0		
491603	APU - APU BLEED AIR CHECK VALVE 1004955040-005	MOS					21-DEC-2010		
	2685	HRS/MSC	O/C	N:0 N:0 N:0			0 0 0		
	REF:	APUS							
492000-0202	APU - COMPRESSOR ROTOR 3822101-1	MOS					21-DEC-2010		
	10-162246-02804	HRS/MSC	H/T	N:0 N:0 N:0			0 0 0		
	REF: AMM 49 20 00 961 803	APUS							
492000-0204	APU - TURBINE ROTOR 3615880-002	MOS					21-DEC-2010		
	10-156101-08872	HRS/MSC	H/T	N:0 N:0 N:0			0 0 0		
	REF: AMM 49 20 00 961 804	APUS							
492010	APU - APU SURGE VALVE 3884538-6	MOS					23-MAR-2018		
	2335	HRS/MSC	O/C				0		
	REF:	APUS							
493010	APU - FUEL CONTROL UNIT 3883964-3	MOS					21-DEC-2010		
	35339	HRS/MSC	O/C	N:0 N:0 N:0			0 0 0		
	REF: AMM 49 31 01 400 801	APUS							
493010-1	APU - APU FLOW DIVIDER VALVE ASSEMBLY PN	MOS					21-DEC-2010		
	SN-UNKNOWN	HRS/MSC	O/C	N:0 N:0 N:0			0 0 0		
	REF:	APUS							

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
493030	APU - ORIFICE FITTING PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			21-DEC-2010 0 0		
493040	APU - FUEL SHUTOFF SOLENOID VALVE 692545-18 T#04790 REF:	MOS HRS/MSC APUS	O/C				23-MAR-2018 0		
493060	APU - APU ELECTRONIC CONTROL UNIT 2119584-1002 110-L0364 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			21-DEC-2010 0 0		
493070	APU - LOAD CONTROL/PNEUMATIC SHUTOFF VALVE 109804-7 2288 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			21-DEC-2010 0 0		
494010	APU - IGNITION UNIT 3888000-3 J10410040 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			21-DEC-2010 0 0		
494010-1	APU - APU IGNITER LEAD PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			21-DEC-2010 0 0		
494080	APU - APU ELECTRIC STARTER 519892-6-3 7863 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			21-DEC-2010 0 0		
496010	APU - APU UPPER GEARBOX ADAPTER PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			21-DEC-2010 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
496015	APU - APU LEFT HAND GEARBOX ADAPTER PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			21-DEC-2010 0 0		
496020	APU - APU RIGHT HAND GEARBOX ADAPTER PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			21-DEC-2010 0 0		
497010	APU - MOTION PICK UP (SPEED SENSOR) TRANSDUCER PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			21-DEC-2010 0 0		
497020	APU - IMMERSION (EGT SENSOR) THERMOCOUPLE 3876003-3 1015027700859 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			21-DEC-2010 0 0		
497030	APU - HOURMETER PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			21-DEC-2010 0 0		
497040	APU - APU INLET TEMPERATURE SENSOR MS28034-1 178411 REF:	MOS HRS/MSC APUS	O/C				23-MAR-2018 0		
498010	APU - APU EXHAUST MUFFLER ASSEMBLY 1004984001-005 PFW0332 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			21-DEC-2010 0 0		
499010	APU - APU ROTARY OIL PUMP PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			21-DEC-2010 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
499050	APU - OIL PRESSURE REGULATING VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			21-DEC-2010 0 0		
499060	APU - HIGH OIL TEMPERATURE SWITCH MS28034-3 156181 REF:	MOS HRS/MSC APUS	O/C				23-MAR-2018 2692:25		
499070	APU - LOW OIL PRESSURE SWITCH 3876001-8 SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			21-MAR-2019 3169		
+ 499110	APU - SOAP CHECK OIL REF: SIL SIL APU-49	MOS HRS/MSC APUS	500				23-DEC-2019 3569	4069	
CHAPTER 52 DOORS									
52-11-00-101	DETAILED INSPECTION PASSENGER DOOR EXTERNAL SKIN STOPS AND SUPPORT STRUCTURE	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
AIRWORTHINESS	REF: AMM 52 11 01 220 801								
52-11-00-102	DETAILED INSPECTION PASSENGER DOOR STRUCTURE - INTERNAL	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
AIRWORTHINESS	REF: See Workcard								
52-11-00-201	DETAILED INSPECTION SURROUND STRUCTURE AND FITTINGS OF THE PASSENGER DOOR PKG 5	MOS HRS/MSC AFL	96 3750	+1m/-1m	-50		23-DEC-2019 2630:03 1481	03-NOV-2027 5231	03-DEC-2027
MRB	REF: AMM 52 11 00 220 802								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-11-00-202 (s)	DETAILED INSPECTION PASSENGER DOOR STRUCTURE-INTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
52-11-00-203 (s)	FUNCTIONAL TEST PASSENGER DOOR PKG 12	MOS HRS/MSC AFL	2400	+40/-40			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 52 11 00 720 801								
52-11-00-204	DETAILED INSPECTION EXTERNAL SKIN OF THE PASSENGER DOOR PKG 5	MOS HRS/MSC AFL	96	+1m/-1m		-50	23-DEC-2019 2630:03 1481	03-NOV-2027	03-DEC-2027
MRB	REF: AMM 52 11 00 220 803		3750					5231	
52-11-00-205 (s)	FUNCTION TEST EXIT-PULL SIGN OF THE PASSENGER DOOR PKG 3	MOS HRS/MSC AFL	36	+1m/-1m			PKG 07-DEC-2017 1913:50 1121		
MRB	REF: AMM 52 11 00 720 802								
52-11-29-301 (s)	DETAILED INSPECTION PASSENGER DOOR SEAL PKG 2	MOS HRS/MSC AFL	24	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 52 11 29 220 801								
52-21-00-201	DETAILED INSPECTION INTERNAL STRUCTURE OF THE OVER-WING EMERGENCY EXIT	MOS HRS/MSC AFL	48	+1m/-1m		-50	23-DEC-2019 2630:03 1481	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 52 21 00 220 801								
52-21-00-202 (s)	DETAILED INSPECTION SURROUND STRUCTURE AND INTEGRAL FITTINGS OF THE OVER-WING EMERGENCY EXIT PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 52 21 00 220 802								
52-21-00-204 (s)	FUNCTIONAL TEST EXIT-PULL SIGN OF THE OVER-WING EMERGENCY EXIT PKG 2	MOS HRS/MSC AFL	24	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 52 21 00 720 802								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-21-00-205 (s)	OPERATIONAL TEST EMERGENCY EXIT PROXIMITY-SENSOR PKG 2	MOS HRS/MSC	24	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 52 71 00 710 802	AFL							
52-21-00-206	DETAILED INSPECTION EXTERNAL SKIN OF THE OVER-WING EMERGENCY EXIT PKG 5	MOS HRS/MSC	96	+1m/-1m		-50	23-DEC-2019 2630:03 1481	03-NOV-2027	03-DEC-2027
MRB	REF: AMM 52 21 00 220 803	AFL	3750					5231	
52-21-00-303 (s)	FUNCTIONAL TEST OVER-WING EMERGENCY EXIT PKG 2	MOS HRS/MSC	24	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 52 21 00 720 801	AFL							
52-21-01-201 (s)	LUBRICATION OVER-WING EMERGENCY EXIT PKG 2	MOS HRS/MSC	24	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 12 22 00 640 805	AFL							
52-21-09-301 (s)	DETAILED INSPECTION OVER-WING EMERGENCY-EXIT SEAL PKG 2	MOS HRS/MSC	24	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 52 21 09 220 801	AFL							
52-31-00-101	DETAILED INSPECTION BAGGAGE DOOR STRUCTURE INCLUDING EXTERNAL AND INTERNAL SKIN PANELS, VENT DOOR SKIN, FRAMES, BEAMS AND INTERCOSTALS.	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 52 31 00 220 804	AFL	7500				0	7500	
52-31-00-102	DETAILED INSPECTION BAGGAGE DOOR STOPS AND LATCH FITTINGS.	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 52 31 00 220 805	AFL	7500				0	7500	
52-31-00-103	SPECIAL DETAILED INSPECTION BAGGAGE DOOR STRUCTURE INCLUDING TEE-CLIPS AND SURROUND FRAMES	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: See Workcard	AFL	7500				0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-31-00-201	DETAILED INSPECTION INTERNAL SUPPORT STRUCTURE OF THE BAGGAGE DOOR	MOS HRS/MSC AFL	48	+1m/-1m		-50	23-DEC-2019 2630:03 1481	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 52 31 00 220 801								
52-31-00-202	DETAILED INSPECTION SURROUND STRUCTURE AND FITTINGS OF THE BAGGAGE DOOR	MOS HRS/MSC AFL	96	+1m/-1m		-50	23-DEC-2019 2630:03 1481	03-NOV-2027	03-DEC-2027
MRB	REF: AMM 52 31 00 220 802		3750					5231	
52-31-00-203	DETAILED INSPECTION EXTERNAL SKIN OF THE BAGGAGE DOOR	MOS HRS/MSC AFL	96	+1m/-1m		-50	23-DEC-2019 2630:03 1481	03-NOV-2027	03-DEC-2027
MRB	REF: AMM 52 31 00 220 803		3750					5231	
52-31-09-301 (s)	DETAILED INSPECTION BAGGAGE DOOR SEAL	MOS HRS/MSC AFL	24	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 52 31 09 220 801								
52-41-00-101	DETAILED INSPECTION EMERGENCY EXIT DOOR	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
AIRWORTHINESS	REF: AMM 52 21 00 220 804								
52-41-01-201 (s)	GENERAL VISUAL INSPECTION AFT EQUIPMENT-COMPARTMENT DOOR-SEAL	MOS HRS/MSC AFL	800	+40/-40			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 52 41 01 210 801								
52-45-00-501	LUBRICATION OF THE SERVICE DOOR LOCKS	MOS HRS/MSC AFL	12	+6m/-6m				03-NOV-2020 M	03-MAY-2021
	REF: GENERIC NO REF								
52-71-00-201 (s)	OPERATIONAL TEST DOOR SENSORS	MOS HRS/MSC AFL	800	+40/-40			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 52 71 00 710 801								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-ZL-00-201 (s)	GENERAL VISUAL INSPECTION PASSENGER DOOR-EXTERNAL PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
52-ZL-00-202 (s)	GENERAL VISUAL INSPECTION PASSENGER DOOR-INTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
52-ZL-00-203 (s)	GENERAL VISUAL INSPECTION OVER-WING EMERGENCY EXIT-EXTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
52-ZL-00-204 (s)	GENERAL VISUAL INSPECTION BAGGAGE DOOR-INBOARD AND OUTBOARD SIDE PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
52-ZL-00-205 (s)	GENERAL VISUAL INSPECTION OVER-WING EMERGENCY EXIT-INTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
521100-0101	PAX DOOR HINGE 1005210007-003 F764267 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
521101	PASSENGER DOOR ASSEMBLY 1005210001-003 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
521113-0101	PASSENGER CONTROL UNIT SWITCH PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
521125	DISCARD THE PASSENGER DOOR ACTUATOR CABLE , PART NO.1005210091-008 1005210091-007 FR0338	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 52 11 25 961 801	AFL	7500	N:0			0	7500	
521127-0101	PASSENGER DOOR HANDRAIL ASSY ASSEMBLY 1005210200-005 W76	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
521127-0102	PASSENGER DOORSTRUT ASSY - HANDRAIL ASSEMBLY 1005210201-001 X17	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
521131	PASSENGER AIRSTAIR DOOR ASSEMBLY 1005210005-005 F737563	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
521141-0101	PASSENGER DOOR FORWARD END TELESCOPIC STRUT ASSEMBLY 1005210250-017 0338	MOS HRS/MSC	O/C	R:9 R:0			10-DEC-2012 368:45		
	REF: See Workcard	AFL		R:0			200		
521141-0102	PASSENGER DOOR AFT END TELESCOPIC STRUT ASSEMBLY 1005210250-017 0388	MOS HRS/MSC	O/C	R:3 R:0			09-DEC-2015 1470:55		
	REF: See Workcard	AFL		R:0			878		
522101-0101	OVER-WING EMERGENCY-EXIT DOOR 1005340143-001 20317	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
523105	BAGGAGE DOOR 1005231000-001 331	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
524101	AFT EQUIPMENT BAY DOOR 1005384900-013 7092850-001 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
524425-7001	LAVATORY WASTE SERVICE DOOR ASSEMBLY 1005384800-005 7092889-001 REF:	MOS HRS/MSC AFL	O/C						
524431-0101	BATTERY ACCESS DOOR LATCH PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
524431-7101	BATTERY DOOR ASSEMBLY 1005380010N503101 7092898-001 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
527101-0101	(PX16) DOOR PROXIMITY SENSOR 40102-0101 24672 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
527101-0102	(PX18) DOOR PROXIMITY SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
527101-0103	(PX15) DOOR PROXIMITY SENSOR 40102-0101 24667 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
527105-0101	(PX45) DOOR PROXIMITY SENSOR 40102-0101 27752 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
527105-0102	(PX46) DOOR PROXIMITY SENSOR 40102-0101 27695 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
527113-0101	(PX47) DOOR PROXIMITY SENSOR 40102-0101 25636 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
527121-0101	(PX49) DOOR PROXIMITY SENSOR 40102-0101 27816 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
527127-0101	(PX48) DOOR PROXIMITY SENSOR 40102-0101 24471 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
CHAPTER 53 FUSELAGE									
53-10-00-101	SPECIAL DETAILED INSPECTION SURROUND STRUCTURE OF THE COCKPIT WINDSHIELD AND SIDE WINDOWS	MOS HRS/MSC AFL					28-JAN-2011 0 0		
AIRWORTHINESS	REF: NDT ET-53-10-003		7500					7500	
53-10-00-103	DETAILED INSPECTION UPPER (SIDE) SKIN PANEL BETWEEN FS250.00, FS326.00, STR. 15 AND LOWER SILL INCLUDING FRAMES AND STRINGERS	MOS HRS/MSC AFL					28-JAN-2011 0 0		
AIRWORTHINESS	REF: AMM 53 10 00 220 808		7500					7500	
53-10-00-104	DETAILED INSPECTION LONGITUDINAL JOINT AT STR. 15 BETWEEN FS250.00 AND FS326.00	MOS HRS/MSC AFL					28-JAN-2011 0 0		
AIRWORTHINESS	REF: AMM 53 10 00 220 809		7500					7500	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-00-106	DETAILED INSPECTION LOWER SKIN PANELS BETWEEN FS250.00 TO FS326.00, STR. 15 LHS AND STR. 15 RHS INCLUDING FRAMES AND STRINGERS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 10 00 220 810	HRS/MSC AFL	7500				0 0		7500
53-10-00-107	DETAILED INSPECTION CIRCUMFERENTIAL (BARREL) JOINT AT FS327.82	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 10 00 220 812	HRS/MSC AFL	7500				0 0		7500
53-10-00-108	DETAILED INSPECTION FORWARD NOSE PANELS BETWEEN FS220.00 AND FS250.00 INCLUDING FRAMES AND LONGITUDINAL BEAMS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 10 00 220 813	HRS/MSC AFL	7500				0 0		7500
53-10-00-109	SPECIAL DETAILED INSPECTION OF THE FORWARD PRESSURE BULKHEAD AT FS250.00 INCLUDING ATTACHMENTS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-53-10-002	HRS/MSC AFL	7500				0 0		7500
53-10-00-111	DETAILED INSPECTION OF THE NOSE-LANDING-GEAR BOX PANELS INCLUDING LATERAL PANELS, UPPER PANEL AND FRAME FS291.00, AND FORWARD PRESSURE BULKHEAD - EXTERNAL	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 10 00 220 814	HRS/MSC AFL	7500				0 0		7500
53-10-00-113	DETAILED INSPECTION PORTAL AND BOOMERANG FRAMES SUPPORTING THE NOSE-LANDING-GEAR WHEEL WELL PANELS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 10 00 220 815	HRS/MSC AFL	7500				0 0		7500
53-10-00-115	SPECIAL DETAILED INSPECTION FRAME FS291.00 INCLUDING SPLICES, ATTACHMENT TO SKIN AND NOSE-LANDING-GEAR WHEEL WELL PANELS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-53-10-001	HRS/MSC AFL	7500				0 0		7500



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-00-116	DETAILED INSPECTION ATC ANTENNA CUTOUTS BETWEEN FS297.00 AND FS305.00, STR. 22L AND 22R	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 53 10 00 220 811	AFL	7500				0	7500	
53-10-00-117	DETAILED INSPECTION FUSELAGE SKIN CUTOUTS BETWEEN FS250.00 AND FS326.00, STR. 15 AND LOWER SILL INCLUDING AOA VANE CUTOUT, DOUBLERS, CLEATS AND GUSSETS	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 53 10 00 220 816	AFL	7500				0	7500	
53-10-00-118	DETAILED INSPECTION OF THE SURROUND STRUCTURE (CANOPY SKIN) OF THE COCKPIT WINDSHIELD AND SIDE WINDOWS	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 53 10 00 220 817	AFL	7500				0	7500	
+ 53-10-00-119	SPECIAL DETAILED INSPECTION OF THE LONGITUDINAL BUTT JOINT (HIDDEN STRAP AT STR. 15 BETWEEN FS250.00 AND FS326.00)	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: NDT ET-53-10-004	AFL	7500				0	7500	
53-10-00-201	DETAILED INSPECTION EXTERNAL AREAS OF THE NLG WHEEL WELL FROM FS220.00 TO FS291.00	MOS HRS/MSC	48	+1m/-1m	-14		23-DEC-2019 2630:03	09-DEC-2023	09-JAN-2024
MRB	REF: AMM 53 10 00 220 801	AFL	3750				1481	5231	
53-10-00-202 (s)	DETAILED INSPECTION AFT SIDE OF THE FORWARD BULKHEAD AT FS250.00 ABOVE THE FLOOR	MOS HRS/MSC	192	+1m/-1m			PKG 03-NOV-2011		
MRB	REF: AMM 53 10 00 220 802	AFL							
53-10-00-203 (s)	DETAILED INSPECTION INTERNAL OVERHEAD STRUCTURE OF THE FLIGHT COMPARTMENT	MOS HRS/MSC	192	+1m/-1m			PKG 03-NOV-2011		
MRB	REF: AMM 53 10 00 220 803	AFL							

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-00-204 (s)	DETAILED INSPECTION FRAME SURROUND STRUCTURE OF THE WINDSHIELD AND SIDE WINDOWS PKG 6	MOS HRS/MSC AFL	192	+1m/-1m			PKG 03-NOV-2011		
MRB	REF: AMM 53 10 00 220 804								
53-10-00-205 (s)	DETAILED INSPECTION FUSELAGE INTERNAL STRUCTURE FROM FS250.00 TO FS327.80 BETWEEN WINDOW LOWER SILL AND FLOOR PKG 6	MOS HRS/MSC AFL	192	+1m/-1m			PKG 03-NOV-2011		
MRB	REF: AMM 53 10 00 220 805								
53-10-00-206	DETAILED INSPECTION FUSELAGE INTERNAL STRUCTURE FROM FS250.00 TO FS327.80 BELOW THE FLOOR PKG 5	MOS HRS/MSC AFL	48	+1m/-1m		-50	23-DEC-2019 2630:03 1481	03-NOV-2023 5231	03-DEC-2023
MRB	REF: AMM 53 10 00 220 806		3750						
53-10-00-207	GENERAL VISUAL INSPECTION RETAINING STRUCTURE OF THE WINDSHIELD AND SIDE WINDOWS PKG 5	MOS HRS/MSC AFL	48	+1m/-1m		-50	23-DEC-2019 2630:03 1481	03-NOV-2023 5231	03-DEC-2023
MRB	REF: AMM 53 10 00 210 803		3750						
53-10-00-208	DETAILED INSPECTION EXTERNAL FUSELAGE SKINS FROM FS220.00 TO FS327.72 PKG 5	MOS HRS/MSC AFL	96	+1m/-1m		-50	23-DEC-2019 2630:03 1481	03-NOV-2027 5231	03-DEC-2027
MRB	REF: AMM 53 10 00 220 807		3750						
53-11-00-201 (s)	DETAILED INSPECTION SUPPORT STRUCTURE OF THE FUSELAGE FLOOR FROM FS250.00 TO FS327.80 PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 53 11 00 220 801								
53-20-00-201 (s)	DETAILED INSPECTION INTERNAL FUSELAGE STRUCTURE FROM FS327.80 TO FS403.14 ABOVE THE FLOOR PKG 6	MOS HRS/MSC AFL	192	+1m/-1m			PKG 03-NOV-2011		
MRB	REF: AMM 53 20 00 220 801								
53-20-00-202	DETAILED INSPECTION INTERNAL FUSELAGE STRUCTURE FROM FS327.80 TO FS403.14 BELOW THE FLOOR	MOS HRS/MSC AFL	48	+1m/-1m		-50	23-DEC-2019 2630:03 1481	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 53 20 00 220 803								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-00-203	DETAILED INSPECTION FRAME SURROUND STRUCTURE AND FITTINGS OF THE PASSENGER DOOR CUTOUT PKG 5	MOS HRS/MSC	48	+1m/-1m			23-DEC-2019 2630:03	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 53 20 00 220 802	AFL	3750				1481	5231	
53-20-00-204	DETAILED INSPECTION EXTERNAL FUSELAGE SKINS FROM FS327.80 TO FS403.14 ABOVE WL80.00 PKG 5	MOS HRS/MSC	96	+1m/-1m			23-DEC-2019 2630:03	03-NOV-2027	03-DEC-2027
MRB	REF: AMM 53 20 00 220 804	AFL	3750				1481	5231	
53-20-00-205	DETAILED INSPECTION EXTERNAL FUSELAGE SKINS FROM FS327.80 TO FS403.14 BELOW WL80.00 PKG 4	MOS HRS/MSC	48	+1m/-1m			23-DEC-2019 2630:03	09-DEC-2023	09-JAN-2024
MRB	REF: AMM 53 20 00 220 805	AFL	3750				1481	5231	
53-21-00-101	DETAILED INSPECTION PASSENGER DOOR SURROUND STRUCTURE INCLUDING THE DOOR STOPS	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 53 20 00 220 806	AFL	7500				0	7500	
53-21-00-102	DETAILED INSPECTION OF THE FORWARD FUSELAGE LOWER RHS SKIN PANELS, FRAMES AND STRINGERS - FS326.00 TO FS406.00, STR. 11R TO STR. 23L	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 53 20 00 220 807	AFL	7500				0	7500	
53-21-00-103	SPECIAL DETAILED INSPECTION OF THE LONGITUDINAL JOINTS AT STR. 3L, STR. 11R, AND STR. 22L FROM FS326.00 TO FS406.00	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: NDT ET-53-21-001	AFL	7500				0	7500	
53-21-00-105	DETAILED INSPECTION OF THE FORWARD FUSELAGE UPPER RHS SKIN PANELS, FRAMES AND STRINGERS - FS326.00 TO FS406.00, STR. 3L TO STR. 11R	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 53 20 00 220 808	AFL	7500				0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-21-00-106	DETAILED INSPECTION OF THE FORWARD FUSELAGE LHS SKIN PANELS, FRAMES AND STRINGERS - FS326.00 TO FS406.00, STR. 3L TO STR. 22L	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 20 00 220 810	HRS/MSC AFL	7500				0 0		7500
53-21-00-107	SPECIAL DETAILED INSPECTION VHF #2, DME #1 AND TCAS OMNI (OR TCAS DIRECTIONAL - IF INSTALLED) ANTENNA CUTOUTS BETWEEN FS326.00 AND FS392.00, STR. 23R AND STR. 23L	MOS							
AIRWORTHINESS	REF: NDT ET-53-21-002	HRS/MSC AFL	7500						7500
53-21-00-108	DETAILED INSPECTION TCAS, GPS #1, GPS #2 (IF INSTALLED), ATC #3 AND #4 ANTENNA CUTOUTS BETWEEN FS326.00 AND FS406.00, STR. 2L AND 2R	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 20 00 220 809	HRS/MSC AFL	7500				0 0		7500
53-21-00-201 (s)	DETAILED INSPECTION SUPPORT STRUCTURE FOR THE FUSELAGE FLOOR FROM FS327.80 TO FS403.14	MOS	96	+1m/-1m			PKG		
MRB	REF: AMM 53 21 00 220 801	HRS/MSC AFL					23-DEC-2019 2630:03 1481		
+ 53-30-00-101	DETAILED INSPECTION OF THE LONGITUDINAL BUTT JOINTS AT STR. 6 FROM FS406.00 TO FS619.00 (L&R) AND STR. 19 FROM FS406.00 TO FS486.00 (L&R)	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 30 00 220 831	HRS/MSC AFL	7500				0 0		7500
+ 53-30-00-102	DETAILED INSPECTION OF THE MACHINED FRAMES FS501.00, FS518.00, FS570.00, AND FS587.00 - INCLUDING CENTER LINE JOINT	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 30 00 220 832	HRS/MSC AFL	7500				0 0		7500
53-30-00-201 (s)	DETAILED INSPECTION INTERNAL FUSELAGE STRUCTURE FROM FS403.22 TO FS621.78 ABOVE THE FLOOR	MOS	192	+1m/-1m			PKG		
MRB	REF: AMM 53 30 00 220 801	HRS/MSC AFL					03-NOV-2011		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-00-202	DETAILED INSPECTION INTERNAL FUSELAGE STRUCTURE FROM FS403.22 TO FS486.82 BELOW THE FLOOR	MOS	48	+1m/-1m			23-DEC-2019	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 53 30 00 220 802	HRS/MSC AFL					2630:03 1481		
53-30-00-203	DETAILED INSPECTION FRAME SURROUND STRUCTURE AND FITTINGS OF THE OVER-WING EMERGENCY EXIT CUTOUT	MOS	48	+1m/-1m			23-DEC-2019	09-DEC-2023	09-JAN-2024
MRB	REF: AMM 53 30 00 220 803	HRS/MSC AFL	3750				2630:03 1481	5231	
53-30-00-204	DETAILED INSPECTION DETAILED INSPECTION OF THE EXTERNAL SKIN AROUND THE CABIN WINDOW OPENINGS	MOS	96	+1m/-1m			23-DEC-2019	03-NOV-2027	03-DEC-2027
MRB	REF: AMM 53 30 00 220 804	HRS/MSC AFL	3750				2630:03 1481	5231	
53-30-00-205	DETAILED INSPECTION EXTERNAL FUSELAGE SKINS FROM FS403.22 TO FS621.78 BELOW WL80.00 NOT COVERED BY THE WING-TO-FUSELAGE FAIRING	MOS	48	+1m/-1m			23-DEC-2019	09-DEC-2023	09-JAN-2024
MRB	REF: AMM 53 30 00 220 813	HRS/MSC AFL	3750				2630:03 1481	5231	
53-30-00-206 (s)	DETAILED INSPECTION WING-TO-FUSELAGE ATTACHMENT LUGS AT FS501.00 TO FS587.00	MOS	96	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 53 30 00 220 805	HRS/MSC AFL					2630:03 1481		
53-30-00-207 (s)	DETAILED INSPECTION FORWARD KEEL BEAM FROM FS454.00 TO FS497.27 AT BL0.0	MOS	96	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 53 30 00 220 806	HRS/MSC AFL					2630:03 1481		
53-30-00-208	DETAILED INSPECTION AFT FACE OF THE FORWARD WINGBOX PRESSURE BULKHEAD AT FS486.00	MOS	96	+1m/-1m			23-DEC-2019	03-NOV-2027	03-DEC-2027
MRB	REF: AMM 53 30 00 220 807	HRS/MSC AFL	3750				2630:03 1481	5231	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-00-209 (s)	DETAILED INSPECTION AFT KEEL BEAM FROM FS586.67 TO FS635.65 AT BL0.0 PKG 5	MOS	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 53 30 00 220 808	HRS/MSC AFL							
53-30-00-210	DETAILED INSPECTION FORWARD FACE OF THE AFT WINGBOX PRESSURE BULKHEAD AT FS635.00 PKG 5	MOS	96	+1m/-1m	-50		23-DEC-2019 2630:03 1481	03-NOV-2027	03-DEC-2027
MRB	REF: AMM 53 30 00 220 809	HRS/MSC AFL	3750					5231	
53-30-00-211	DETAILED INSPECTION OVERWING LONGERONS FROM FS486.00 TO FS635.00 PKG 5	MOS	48	+1m/-1m	-50		23-DEC-2019 2630:03 1481	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 53 30 00 220 810	HRS/MSC AFL	3750					5231	
53-30-00-212	DETAILED INSPECTION AFT FACE OF THE AFT WINGBOX PRESSURE BULKHEAD AT FS635.65 PKG 5	MOS	48	+1m/-1m	-50		23-DEC-2019 2630:03 1481	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 53 30 00 220 811	HRS/MSC AFL							
53-30-00-213	DETAILED INSPECTION EXTERNAL FUSELAGE SKINS FROM FS403.22 TO FS621.78 ABOVE WL80.00 PKG 5	MOS	96	+1m/-1m	-50		23-DEC-2019 2630:03 1481	03-NOV-2027	03-DEC-2027
MRB	REF: AMM 53 30 00 220 812	HRS/MSC AFL	3750					5231	
53-30-00-214	DETAILED INSPECTION EXTERNAL FUSELAGE SKINS FROM FS403.22 TO FS621.78 BELOW WL80.00 COVERED BY THE WING-TO-FUSELAGE FAIRING PKG 5	MOS	96	+1m/-1m	-50		23-DEC-2019 2630:03 1481	03-NOV-2027	03-DEC-2027
MRB	REF: AMM 53 30 00 220 814	HRS/MSC AFL	3750					5231	
53-31-00-201 (s)	DETAILED INSPECTION SUPPORT STRUCTURE FOR THE FUSELAGE FLOOR FROM FS398.55 TO FS486.00 PKG 5	MOS	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 53 31 00 220 801	HRS/MSC AFL							
53-31-00-202	DETAILED INSPECTION UPPER SURFACE OF THE PRESSURE FLOOR FROM FS486.00 TO FS635.65 PKG 5	MOS	48	+1m/-1m	-50		23-DEC-2019 2630:03 1481	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 53 31 00 220 802	HRS/MSC AFL							

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-31-00-203	DETAILED INSPECTION LOWER SURFACE OF THE PRESSURE FLOOR FROM FS486.00 TO FS635.65 PKG 5	MOS HRS/MSC	96	+1m/-1m			23-DEC-2019 2630:03	03-NOV-2027	03-DEC-2027
MRB	REF: AMM 53 31 00 220 803	AFL	3750				1481	5231	
53-40-00-201 (s)	DETAILED INSPECTION OF THE INTERNAL FUSELAGE STRUCTURE FROM FS621.00 TO FS670.00 ABOVE THE FLOOR PKG 6	MOS HRS/MSC	192	+1m/-1m			03-NOV-2011		
MRB	REF: AMM 53 40 00 220 801	AFL							
53-40-00-202	DETAILED INSPECTION INTERNAL FUSELAGE STRUCTURE FROM FS635.00 TO FS670.00 BELOW THE FLOOR	MOS HRS/MSC	48	+1m/-1m			23-DEC-2019 2630:03	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 53 40 00 220 802	AFL					1481		
53-40-00-203	DETAILED INSPECTION FRAME SURROUND STRUCTURE AND FITTINGS OF THE BAGGAGE DOOR CUTOUT PKG 5	MOS HRS/MSC	96	+1m/-1m			23-DEC-2019 2630:03	03-NOV-2027	03-DEC-2027
MRB	REF: AMM 53 40 00 220 803	AFL	3750				1481	5231	
53-40-00-204 (s)	DETAILED INSPECTION FORWARD SIDE OF THE REAR PRESSURE BULKHEAD AT FS670.00 ABOVE THE FLOOR PKG 6	MOS HRS/MSC	192	+1m/-1m			03-NOV-2011		
MRB	REF: AMM 53 40 00 220 804	AFL							
53-40-00-205 (s)	DETAILED INSPECTION FORWARD SIDE OF THE REAR PRESSURE BULKHEAD AT FS670.00 BELOW THE FLOOR PKG 5	MOS HRS/MSC	96	+1m/-1m			23-DEC-2019 2630:03		
MRB	REF: AMM 53 40 00 220 805	AFL					1481		
53-40-00-206	DETAILED INSPECTION AFT SIDE OF THE REAR PRESSURE BULKHEAD AT FS670.00 PKG 5	MOS HRS/MSC	48	+1m/-1m			23-DEC-2019 2630:03	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 53 40 00 220 806	AFL	3750				1481	5231	
53-40-00-207	SPECIAL DETAILED INSPECTION EXTERNAL FUSELAGE SKIN FROM FS621.00 TO 62.5% REAR SPAR ABOVE WL80.00 COVERED BY FAIRING PKG 5	MOS HRS/MSC	96	+1m/-1m			23-DEC-2019 2630:03	03-NOV-2027	03-DEC-2027
MRB	REF: AMM 53 40 00 280 801	AFL	3750				1481	5231	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-40-00-208 (s)	DETAILED INSPECTION KEEL BEAM STRUCTURE FROM FS641.90 TO FS689.45 PKG 5	MOS	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 53 40 00 220 808	HRS/MSC AFL							
53-40-00-209	DETAILED INSPECTION EXTERNAL FUSELAGE SKIN FROM FS621.00 TO 62.5% REAR SPAR ABOVE WL80.00 NOT COVERED BY FAIRING PKG 5	MOS	96	+1m/-1m		-50	23-DEC-2019 2630:03 1481	03-NOV-2027	03-DEC-2027
MRB	REF: AMM 53 40 00 220 809	HRS/MSC AFL	3750					5231	
53-40-00-210	DETAILED INSPECTION EXTERNAL FUSELAGE SKIN FROM FS621.00 TO 62.5% REAR SPAR BELOW WL80.00 NOT COVERED BY FAIRING PKG 4	MOS	48	+1m/-1m		-14	23-DEC-2019 2630:03 1481	09-DEC-2023	09-JAN-2024
MRB	REF: AMM 53 50 00 220 803	HRS/MSC AFL	3750					5231	
53-40-00-211	DETAILED INSPECTION OF THE EXTERNAL FUSELAGE SKIN FROM FS621.00 TO 62.5% REAR SPAR BELOW WL80.00 COVERED BY FAIRING PKG 5	MOS	96	+1m/-1m		-50	23-DEC-2019 2630:03 1481	03-NOV-2027	03-DEC-2027
MRB	REF: AMM 53 40 00 220 810	HRS/MSC AFL	3750					5231	
53-41-00-101	GENERAL VISUAL INSPECTION SKIN PANELS ABOVE THE FLOOR (WL80.00) BETWEEN FS404.00 AND FS621.00 - EXTERNAL	MOS					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 53 30 00 210 809	HRS/MSC AFL	7500				0	7500	
53-41-00-104	GENERAL VISUAL INSPECTION SKIN PANELS BELOW THE FLOOR (WL80.00) BETWEEN FS404.00 AND FS621.00 - EXTERNAL	MOS					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 53 30 00 210 810	HRS/MSC AFL	7500				0	7500	
53-41-00-105	SPECIAL DETAILED INSPECTION LONGITUDINAL JOINT AT STR. 6 FROM FS404.00 TO FS619.00 (L&R) AND STR. 19 FROM FS404.00 TO FS484.00 (L&R)	MOS					28-JAN-2011 0		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	7500				0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-41-00-106	DETAILED INSPECTION OF THE CABIN WINDOW SURROUND STRUCTURE - FS404.00 TO FS587.00 AND STR. 9 TO STR. 12 - EXTERNAL	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 30 00 220 817	HRS/MSC AFL	7500				0 0		7500
53-41-00-107	DETAILED INSPECTION OF THE OVER-WING EMERGENCY EXIT DOOR SURROUND STRUCTURE	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 30 00 220 818	HRS/MSC AFL	7500				0 0		7500
53-41-00-109	DETAILED INSPECTION OF THE WEB OF THE PRESSURE BULKHEAD MACHINED FRAMES FROM FS486.00 TO FS635.00	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 30 00 220 819	HRS/MSC AFL	7500				0 0		7500
53-41-00-110	DETAILED INSPECTION OF THE PRESSURE BULKHEAD SUPPORTING STRUCTURE - FS486.00 AND FS635.00	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 30 00 220 820	HRS/MSC AFL	7500				0 0		7500
53-41-00-111	SPECIAL DETAILED INSPECTION OF MACHINED FRAMES FS501.00, FS518, FS570.00 AND FS587.00 - INCLUDING CENTER LINE JOINT	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-53-41-003	HRS/MSC AFL	7500				0 0		7500
53-41-00-112	DETAILED INSPECTION FORWARD KEEL BEAM FROM FS454.00 TO FS498.00 AT BL0.0 INCLUDING ATTACHMENT TO WING FRONT SPAR	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 30 00 220 821	HRS/MSC AFL	7500				0 0		7500
53-41-00-114	DETAILED INSPECTION AFT KEEL BEAM FROM FS589.00 TO FS635.00 - INCLUDING LUGS AND ATTACHMENT TO WING REAR SPAR	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 30 00 220 823	HRS/MSC AFL	7500				0 0		7500

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-41-00-116	DETAILED INSPECTION OVERWING LONGERONS FROM FS486.00 TO FS635.00	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 53 30 00 220 810	AFL	7500				0	7500	
53-41-00-117	DETAILED INSPECTION OF THE PRESSURE FLOOR SKIN AND BEAMS FROM FS484.00 TO FS635.00	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 53 30 00 220 825	AFL	7500				0	7500	
53-41-00-118	DETAILED INSPECTION BUMP STOP BEAM AT FS544.00	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 53 30 00 220 826	AFL	7500				0	7500	
53-41-00-120	DETAILED INSPECTION OF THE WING ATTACHMENT FITTINGS AT FS501.00 AND FS587.00, BL45.0 AND BL0.0 AND THE SHEAR ATTACHMENT FROM FS518.00 TO FS570.00	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 53 30 00 220 827	AFL	7500				0	7500	
53-41-00-122	SPECIAL DETAILED INSPECTION OF THE CIRCUMFERENTIAL SKIN JOINTS AT FS406.00 AND FS621.00, FLOOR BEAM JOINTS AT FS398.00 AND FS641.00, FLOOR SHEAR WEB FROM FS635.00 TO FS641.00 AND FRAME FS635.65 SPLICE AT STR. 16	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: See Workcard	AFL	7500				0	7500	
53-41-00-124	SPECIAL DETAILED INSPECTION OF THE PRESSURE BULKHEAD MACHINED FRAMES INNER CAP (FS635.00), OUTER CAP (FS486.00 AND FS635.00), AND SPLICES (FS486.00 AND FS635.00)	MOS HRS/MSC							
AIRWORTHINESS	REF: NDT ET-53-41-002	AFL	7500					7500	
53-41-00-125	SPECIAL DETAILED INSPECTION AFT KEEL BEAM PINS AT FS589.16	MOS HRS/MSC							
AIRWORTHINESS	REF: NDT UT-53-41-001	AFL	7500					7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-41-00-126	SPECIAL DETAILED INSPECTION WING ATTACHMENT FITTING PINS AT FS501.00 AND FS587.00, BL45.0 AND BL0.0								
AIRWORTHINESS	REF: NDT UT-53-41-002	MOS HRS/MSC AFL	7500					7500	
53-41-00-127	DETAILED INSPECTION CIRCUMFERENTIAL SKIN JOINTS AT FS406.00 AND FS621.00								
AIRWORTHINESS	REF: AMM 53 30 00 220 828	MOS HRS/MSC AFL	7500					7500	
53-41-00-128	DETAILED INSPECTION OF THE BASELINE AND OPTIONAL (IF INSTALLED) ANTENNA CUTOUTS BETWEEN FS404.00 AND FS621.00, STR. 1L AND 1R AND THE CUTOUTS FOR THE EMERGENCY EXIT LIGHTS ON THE RHS OF THE FUSELAGE								
AIRWORTHINESS	REF: AMM 53 30 00 220 815	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
53-41-00-129	DETAILED INSPECTION DME #2 (IF INSTALLED) ANTENNA CUTOUT BETWEEN FS404.00 AND FS422.00, STR. 23L AND 23R								
AIRWORTHINESS	REF: AMM 53 30 00 220 816	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
53-41-00-130	DETAILED INSPECTION OUTFLOW VALVE CUTOUT AND SURROUND STRUCTURE								
AIRWORTHINESS	REF: AMM 53 30 00 220 822	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
+ 53-41-00-133	SPECIAL DETAILED INSPECTION OF THE PRESSURE BULKHEAD MACHINED FRAME INNER CAP AT FS486.00								
AIRWORTHINESS	REF: NDT ET-53-41-009	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
+ 53-41-00-134	SPECIAL DETAILED INSPECTION OF THE SANDWICHED STRUCTURES OF THE SKIN PANELS ABOVE THE FLOOR (WL80.0) BETWEEN FS404.00 AND FS621.00								
AIRWORTHINESS	REF: NDT UT-53-30-001	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-41-00-135	SPECIAL DETAILED INSPECTION OF THE SANDWICHED STRUCTURES OF THE SKIN PANELS BELOW THE FLOOR (WL80.0) BETWEEN FS404.00 AND FS621.00	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
AIRWORTHINESS	REF: See Workcard								
+ 53-41-00-136	SPECIAL DETAILED INSPECTION OF THE FORWARD KEEL BEAM FROM FS454.00 TO FS498.00 AT BL0.0 INCLUDING ATTACHMENT TO WING FRONT SPAR	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
AIRWORTHINESS	REF: NDT ET-53-30-006								
+ 53-41-00-137	SPECIAL DETAILED INSPECTION OF THE SANDWICHED STRUCTURES OF THE OVERWING LONGERON FROM FS486.00 TO FS635.00	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
AIRWORTHINESS	REF: NDT ET-53-30-007								
53-41-00-201	DETAILED INSPECTION SUPPORT STRUCTURE FOR THE FUSELAGE FLOOR FROM FS635.00 TO FS670.00	MOS HRS/MSC AFL	48	+1m/-1m	-50		23-DEC-2019 2630:03 1481	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 53 41 00 220 801								
+ 53-50-00-101	DETAILED INSPECTION OF THE REAR FUSELAGE BULKHEAD FS724.70	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
AIRWORTHINESS	REF: AMM 53 50 00 220 810								
53-50-00-201 (s)	DETAILED INSPECTION INTERNAL FUSELAGE STRUCTURE FROM FS670.00 TO THE ATTACH FRAME OF THE VERTICAL-STABILIZER REAR SPAR						PKG		
	PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			23-DEC-2019 2630:03 1481		
MRB	REF: AMM 53 50 00 220 801								
53-50-00-202 (s)	SPECIAL DETAILED INSPECTION AFT SIDE OF CANTED FRAME NO. 5 AND THE APU FITTINGS						PKG		
	PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			23-DEC-2019 2630:03 1481		
MRB	REF: AMM 53 50 00 280 801								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-51-00-104	SPECIAL DETAILED INSPECTION BAGGAGE DOOR SURROUND STRUCTURE - FRAMES, UPPER SILL, DOUBLER AND DOOR STOP BACKUP FITTINGS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-53-40-001	HRS/MSC AFL	7500				0 0	7500	
53-51-00-106	DETAILED INSPECTION REAR PRESSURE BULKHEAD-VERTICAL BEAMS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 40 00 220 813	HRS/MSC AFL	7500				0 0	7500	
53-51-00-107	SPECIAL DETAILED INSPECTION REAR PRESSURE BULKHEAD-CROSS HORIZONTAL BEAMS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-53-40-002	HRS/MSC AFL	7500				0 0	7500	
53-51-00-108	SPECIAL DETAILED INSPECTION REAR PRESSURE BULKHEAD-WEB	MOS					28-JAN-2011		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	7500				0 0	7500	
53-51-00-109	SPECIAL DETAILED INSPECTION REAR FUSELAGE FS724.70 FRAME INCLUDING SPLICES	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-53-51-004	HRS/MSC AFL	7500				0 0	7500	
53-51-00-110	SPECIAL DETAILED INSPECTION REAR FUSELAGE FS772.19 FRAME COVERED BY SPLICES	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-53-51-005	HRS/MSC AFL	7500				0 0	7500	
53-51-00-112	DETAILED INSPECTION AFT KEEL BEAM FROM FS642.00 AND FS688.00 INCLUDING SPLICES	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 40 00 220 814	HRS/MSC AFL	7500				0 0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-51-00-113	SPECIAL DETAILED INSPECTION BAGGAGE BAY FLOOR BEAMS AT BL4.50, BL13.50, BL26.25 AND CROSS BEAM AT FS653.00 INCLUDING JOINTS	MOS					28-JAN-2011		
AIRWORTHINESS	REF:	HRS/MSC AFL	7500				0 0		7500
53-51-00-115	GENERAL VISUAL INSPECTION REAR FUSELAGE - NON-PRESSURE SHELL SKIN PANEL - EXTERNAL	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 50 00 210 807	HRS/MSC AFL	7500				0 0		7500
53-51-00-116	DETAILED INSPECTION REAR FUSELAGE - NON-PRESSURE SHELL CUTOUTS INCLUDING SURROUNDING DOUBLERS AND STRINGERS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 50 00 220 804	HRS/MSC AFL	7500				0 0		7500
53-51-00-117	DETAILED INSPECTION REAR FUSELAGE PRESSURE SHELL SKIN PANELS AT FRAME ATTACHMENTS AND AROUND CUTOUTS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 40 00 220 811	HRS/MSC AFL	7500				0 0		7500
53-51-00-118	GENERAL VISUAL INSPECTION REAR FUSELAGE PRESSURE SHELL SKIN PANELS - EXTERNAL	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 40 00 210 808	HRS/MSC AFL	7500				0 0		7500
53-51-00-119	DETAILED INSPECTION REAR FUSELAGE PRESSURE SHELL FRAMES FS635.00, FS653.00 AND FS669.00	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 40 00 220 817	HRS/MSC AFL	7500				0 0		7500
53-51-00-120	SPECIAL DETAILED INSPECTION REAR FUSELAGE PRESSURE SHELL LONGITUDINAL JOINTS AT STR 6, FS621.00 TO FS660.00 AND STR 19, FS635.00 TO FS669.00	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-53-51-006	HRS/MSC AFL	7500				0 0		7500

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-51-00-121	DETAILED INSPECTION REAR FUSELAGE PRESSURE SHELL CIRCUMFERENTIAL JOINTS AT FS669.00								
AIRWORTHINESS	REF: AMM 53 40 00 220 818	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
53-51-00-122	DETAILED INSPECTION BAGGAGE DOOR SURROUND STRUCTURE - INCLUDING UPPER AND LOWER SILLS, INNER SKIN, DOUBLERS, SPLICE, INTERCOSTALS, FRAMES AND STRINGERS								
AIRWORTHINESS	REF: AMM 53 40 00 220 812	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
53-51-00-123	DETAILED INSPECTION BAGGAGE BAY FLOOR BEAM END PADS, CROSS STIFFENER ANGLES AT FS662.00 AND FS669.00 AND SHEAR WEBS								
AIRWORTHINESS	REF: AMM 53 40 00 220 815	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
53-51-00-124	DETAILED INSPECTION THALES OR ARTEX ELT (IF INSTALLED) ANTENNA CUTOUT								
AIRWORTHINESS	REF: AMM 53 40 00 220 816	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
53-51-00-125	DETAILED INSPECTION REAR PRESSURE BULKHEAD - WEB								
AIRWORTHINESS	REF: AMM 53 40 00 220 819	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
53-51-00-126	SPECIAL DETAILED INSPECTION REAR PRESSURE BULKHEAD WEB AT CROSS HORIZONTAL BEAMS ATTACHMENT								
AIRWORTHINESS	REF: AMM 53 40 00 280 803	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
53-51-00-127	DETAILED INSPECTION REAR FUSELAGE FS772.19 FRAME AND VERTICAL STABILIZER SPARS CANTED FRAMES								
AIRWORTHINESS	REF: AMM 53 50 00 220 808	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-51-00-128	SPECIAL DETAILED INSPECTION REAR FUSELAGE CIRCUMFERENTIAL JOINT DOUBLERS AT FS724.70 AND LONGITUDINAL JOINT SPLICES AT STR. 6 AND 19	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-53-51-007	HRS/MSC AFL	7500				0	7500	
53-51-00-129	DETAILED INSPECTION MAGNASTAR ANTENNA CUTOUT	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 53 50 00 220 807	HRS/MSC AFL	7500				0	7500	
+ 53-51-00-130	SPECIAL DETAILED INSPECTION OF THE SANDWICHED STRUCTURES OF THE REAR FUSELAGE PRESSURE STRUCTURE - SKIN PANELS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: GENERIC NO REF	HRS/MSC AFL	7500				0	7500	
53-ZL-00-201 (s)	GENERAL VISUAL INSPECTION RADOME-EXTERNAL/INTERNAL						PKG		
MRB	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-DEC-2019 2630:03 1481		
53-ZL-00-202 (s)	GENERAL VISUAL INSPECTION OF THE NOSE LANDING GEAR WHEEL WELL						PKG		
MRB	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-DEC-2019 2630:03 1481		
53-ZL-00-203 (s)	GENERAL VISUAL INSPECTION FORWARD LOWER FUSELAGE FROM FS250.00 TO FS327.00 BELOW WL91.25-EXTERNAL						PKG		
MRB	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			23-DEC-2019 2630:03 1481		
53-ZL-00-205 (s)	GENERAL VISUAL INSPECTION FORWARD LOWER FUSELAGE FROM FS327.00 TO FS406.00 BELOW WL80.00						PKG		
MRB	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			23-DEC-2019 2630:03 1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-ZL-00-209 (s)	GENERAL VISUAL INSPECTION LOWER SURFACE OF THE PRESSURE FLOOR FROM FS486.00 TO FS587.32 PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
53-ZL-00-210-1 (s)	GENERAL VISUAL INSPECTION LEFT MAIN LANDING GEAR MAIN-LANDING-GEAR WHEEL WELL PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
53-ZL-00-210-2 (s)	GENERAL VISUAL INSPECTION RIGHT MAIN LANDING GEAR MAIN-LANDING-GEAR WHEEL WELL PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
53-ZL-00-211 (s)	GENERAL VISUAL INSPECTION CENTER FUSELAGE BETWEEN THE PRESSURE FLOOR AND THE CABIN FLOOR FROM FS486.00 TO FS635.65-INTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
53-ZL-00-214 (s)	GENERAL VISUAL INSPECTION OVERWING SECTION OF THE LEFT/RIGHT WING-TO-FUSELAGE FAIRING PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
53-ZL-00-216 (s)	GENERAL VISUAL INSPECTION NOSE COMPARTMENT FROM FS220.00 TO FS250.00-EXTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
53-ZL-00-218 (s)	GENERAL VISUAL INSPECTION SUPPORT STRUCTURE AND INSTALLED EQUIPMENT INBOARD OF THE AFT WING/FUSELAGE FAIRING PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-ZL-00-219 (s)	GENERAL VISUAL INSPECTION FLIGHT COMPARTMENT FROM FS250.00 TO FS327.00 ABOVE WL91.25-EXTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
53-ZL-00-220 (s)	GENERAL VISUAL INSPECTION FLIGHT COMPARTMENT FROM FS250.00 TO FS327.00 ABOVE WL91.25-INTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
53-ZL-00-221 (s)	GENERAL VISUAL INSPECTION FORWARD UPPER FUSELAGE FROM FS327.00 TO FS406.00 ABOVE WL80.00-EXTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
53-ZL-00-222 (s)	GENERAL VISUAL INSPECTION FORWARD UPPER FUSELAGE FROM FS327.00 TO FS406.00 ABOVE WL80.00-INTERNAL PKG 6	MOS HRS/MSC AFL	192	+1m/-1m			PKG 03-NOV-2011		
MRB	REF: See Workcard								
53-ZL-00-223 (s)	GENERAL VISUAL INSPECTION MAIN AVIONIC EQUIPMENT RACKS BETWEEN FS326.25 TO FS344.18 ABOVE WL80.00 PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
53-ZL-00-225 (s)	GENERAL VISUAL INSPECTION FUSELAGE SKINS FROM FS406.00 TO FS621.00 ABOVE WL80.00-EXTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
53-ZL-00-226 (s)	GENERAL VISUAL INSPECTION MID FUSELAGE FROM FS406.00 TO FS621.00 ABOVE WL80.00-INTERNAL PKG 6	MOS HRS/MSC AFL	192	+1m/-1m			PKG 03-NOV-2011		
MRB	REF: See Workcard								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-ZL-00-227 (s)	GENERAL VISUAL INSPECTION EXTERNAL SKINS NOT COVERED BY THE WING/FUSELAGE FAIRING FROM FS669.76 TO FS788.53						PKG		
	PKG 4	MOS	48	+1m/-1m				23-DEC-2019	
MRB	REF: See Workcard	HRS/MSC AFL						2630:03 1481	
53-ZL-00-229 (s)	GENERAL VISUAL INSPECTION FUSELAGE STABILIZER SECTION FROM FS788.53 TO THE REAR SPAR DATUM OF THE VERTICAL STABILIZER-EXTERNAL						PKG		
	PKG 4	MOS	48	+1m/-1m				23-DEC-2019	
MRB	REF: See Workcard	HRS/MSC AFL						2630:03 1481	
53-ZL-00-230 (s)	GENERAL VISUAL INSPECTION AFT EQUIPMENT COMPARTMENT FROM FS788.53 TO THE TAILCONE FIREWALL-INTERNAL						PKG		
	PKG 5	MOS	96	+1m/-1m				23-DEC-2019	
MRB	REF: See Workcard	HRS/MSC AFL						2630:03 1481	
53-ZL-00-231 (s)	GENERAL VISUAL INSPECTION TAILCONE-EXTERNAL						PKG		
	PKG 5	MOS	96	+1m/-1m				23-DEC-2019	
MRB	REF: See Workcard	HRS/MSC AFL						2630:03 1481	
53-ZL-00-233 (s)	GENERAL VISUAL INSPECTION BAGGAGE COMPARTMENT SKIN, NOT COVERED BY WING/FUSELAGE FAIRING FS621.82 TO FS669.76-EXTERNAL						PKG		
	PKG 5	MOS	96	+1m/-1m				23-DEC-2019	
MRB	REF: See Workcard	HRS/MSC AFL						2630:03 1481	
53-ZL-00-304 (s)	GENERAL VISUAL INSPECTION FORWARD LOWER FUSELAGE FROM FS250.00 TO FS327.00 BELOW WL91.25-INTERNAL						PKG		
	PKG 4	MOS	48	+1m/-1m				23-DEC-2019	
MRB	REF: See Workcard	HRS/MSC AFL						2630:03 1481	
53-ZL-00-306 (s)	GENERAL VISUAL INSPECTION FORWARD FUSELAGE FROM FS327.00 TO FS406.00 BELOW WL80.00-INTERNAL						PKG		
	PKG 4	MOS	48	+1m/-1m				23-DEC-2019	
MRB	REF: See Workcard	HRS/MSC AFL						2630:03 1481	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-ZL-00-307 (s)	GENERAL VISUAL INSPECTION MID FUSELAGE COMPARTMENT FROM FS486.00 TO FS501.00 BELOW WL80.00 PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
53-ZL-00-308 (s)	GENERAL VISUAL INSPECTION MID FUSELAGE FROM FS406.00 TO FS635.65 BELOW WL80.00-EXTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
53-ZL-00-312 (s)	GENERAL VISUAL INSPECTION LOWER MID FUSELAGE FROM FS406.00 TO FS486.00 BELOW FLOOR-INTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
53-ZL-00-313 (s)	GENERAL VISUAL INSPECTION FORWARD WING-TO-FUSELAGE FAIRING-EXTERNAL/INTERNAL PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
53-ZL-00-315 (s)	GENERAL VISUAL INSPECTION INTERNAL AFT FUSELAGE FROM FS635.65 TO FS669.76 BELOW WL80.00 PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
53-ZL-00-317 (s)	GENERAL VISUAL INSPECTION REAR PANELS OF THE WING-TO-FUSELAGE FAIRING PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
53-ZL-00-324 (s)	GENERAL VISUAL INSPECTION BAGGAGE COMPARTMENT FROM FS621.65 TO FS669.76-INTERNAL PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
53-ZL-00-328 (s)	GENERAL VISUAL INSPECTION AFT EQUIPMENT COMPARTMENT FROM FS669.76 TO FS788.53-INTERNAL PKG 3	MOS HRS/MSC AFL	36	+1m/-1m			PKG 07-DEC-2017 1913:50 1121		
MRB	REF: See Workcard								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-ZL-00-329 (s)	GENERAL VISUAL INSPECTION TAILCONE-INTERNAL PKG 4	MOS	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard	HRS/MSC AFL							
532000-7101	COCKPIT & FWD FUSE JOINING ASSEMBLY 1005310001-001 20317 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
533000-0101	GA AIRCRAFT SYS STRUCTURE 1005340000-001 20317 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
533000-0201	SIDE SECTOR LH FRAME SPAR 1005340701-003 SHB/29/1729 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
533000-0202	FRONT SIDE R.H SPAR 1005340702-005 SHB/29/1727 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
533000-0203	REAR SIDE L.H SPAR 1005340705-007 SHB/29/1665 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
533000-0204	REAR SIDE R.H SPAR 1005340706-005 SHB/29/1695 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
533000-0301	M/C LINTEL STA 501-587 UNIT 1005341001-005 JHE1128 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
533000-0401	FWD SEMI PRESSURE BULKHEAD 1005342019-007 FA364 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
533000-0402	AFT SEMI PRESSURE BULKHEAD 1005342001-007 FA369 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
533000-0501	PRESSURE FLOOR SKIN 1005342400-009 K021185919 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
533101-0101	FLIGHT COMPARTMENT FLOOR STEP PANEL 1005320669-001 653488 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
533201-0101	LOWER WHEELBIN ASSEMBLY 1005342748-011X01 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
533201-0102	LOWER WHEELBIN ASSEMBLY 1005342748-012X01 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
533201-0103	UPPER WHEELBIN ASSEMBLY 1005342749-007X01 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
533201-0104	UPPER WHEELBIN ASSEMBLY 1005342749-008X01 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
534000-0101	AFT GA FUSELAGE 1005350000-001 322 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
535100-0101	TAILCONE ASSEMBLY 1005360001-005 HDH00320 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
535201-0101	AFT FUSELAGE GENERAL ASSEMBLY 1005351000-001 330 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
536101	RADOME ASSEMBLY 1005320200-005 F952958 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:107 R:0 N:2630:03 R:0 N:1481 R:0			23-DEC-2019 2630:03 1481		
536301-0101	FWD PANEL ASSEMBLY 1005380011-133 7008765-001 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
536301-0102	FWD LH PANEL ASSEMBLY 1005380011-135 7092823-001 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
536301-0103	FWD RH PANEL ASSEMBLY 1005380011-137 7221755-001 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
536301-0201	FWD PANEL RETAINER 69222 7092802-001 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
536301-0202	FWD PANEL RETAINER 1005381215-002 7092803-001 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
536301-0301	FWD JOINT STRAP ASSEMBLY 71385 6732397-001 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
536305-0101	UNDERWING PANEL FAIRING 1005380011-143 7092816-001 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
536305-0201	MLG BAY PANEL FAIRING ASSEMBLY 1005380011-145 7092809-001 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
536305-0301	REAR PANEL ASSEMBLY 1005380011-151 7092818-001 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
536305-0401	AFT JOINT STRAP ASSEMBLY 71899 6883536-001 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
536309-0101	FIXED WING TE PANEL ASSEMBLY 1005380011-153 6128272-001 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
536309-0102	FIXED WING TE PANEL ASSEMBLY 1005380011-154 6128275-001 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
536309-0103	AFT PANEL FWD LH FAIRING 1005380011-147 7221757-001 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
536309-0104	AFT, FWD RH PANEL ASSEMBLY 1005380011-149 7221756-001 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
536309-0105	AFT ACCESS PANEL ASSEMBLY 71387 7092813-001 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
536313-0101	FWD OVERWING PANEL ASSEMBLY 1005380010N503603 7092828-001 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
536313-0102	FWD OVERWING PANEL ASSEMBLY 1005380010N503604 7092829-001 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
536313-0103	AFT OVERWING PANEL ASSEMBLY 1005380010N503601 7092825-001 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
536313-0104	AFT OVERWING PANEL ASSEMBLY 1005380010N503602 7092826-001 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
536317-0101	FWD ACCESS PANEL ASSEMBLY 1005380011-155 7092815-001 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
C300-161216	REVIEW TLMC TR5-2-81/TR5-2-82/TR5-2-83/TR5-2-84 DATED 16-DEC-2016							10-JAN-2017	
REQUIREMENT CHANGE FORMS	REF: RCF 00	MOS HRS/MSC - AFL							
APU Model : GTCP36-150(BD) Serial # P-430 Part # 3800774-1									
53-51-00-201 (s)	APU - GENERAL VISUAL INSPECTION APU ENCLOSURE DRAIN PKG 18	MOS HRS/MSC	800	+40/-40			PKG 23-DEC-2019 3569		
	REF: See Workcard	APUS							
CHAPTER 54 NACELLES/PYLONS									
54-51-00-101-1	SPECIAL DETAILED INSPECTION NO. 1 ENGINE FORWARD MOUNT FRAME	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: NDT ET-54-51-001	AFL	7500				0	7500	
54-51-00-101-2	SPECIAL DETAILED INSPECTION NO. 2 ENGINE FORWARD MOUNT FRAME	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: NDT ET-54-51-001	AFL	7500				0	7500	
54-51-00-102-1	SPECIAL DETAILED INSPECTION NO. 1 ENGINE REAR MOUNT FRAME LUGS	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: NDT ET-54-51-003	AFL	7500				0	7500	
54-51-00-102-2	SPECIAL DETAILED INSPECTION NO. 2 ENGINE REAR MOUNT FRAME LUGS	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: NDT ET-54-51-003	AFL	7500				0	7500	
54-51-00-103-1	SPECIAL DETAILED INSPECTION NO. 1 ENGINE MOUNT THRUST LINK	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: NDT UT-54-51-002	AFL	7500				0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-51-00-103-2	SPECIAL DETAILED INSPECTION NO. 2 ENGINE MOUNT THRUST LINK	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT UT-54-51-002	HRS/MSC AFL	7500				0 0		7500
54-51-00-105	SPECIAL DETAILED INSPECTION FORWARD ENGINE MOUNT LUGS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	7500				0 0		7500
54-51-00-110	SPECIAL DETAILED INSPECTION OF THE AFT ENGINE MOUNT END PADS AREA	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-54-51-003	HRS/MSC AFL	7500				0 0		7500
54-51-00-111	DISCARD OF THE AFT ENGINE MOUNT BOLTS, PART NO. MS21250-7, NON-SERIALIZED	MOS					28-JAN-2011		
LIFE LIMIT	REF: AMM 54 51 00 961 804	HRS/MSC AFL	7500				0 0		7500
+ 54-51-00-112	NO. 1 ENGINE - DETAILED INSPECTION OF THE ENGINE MOUNT THRUST LINK	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 54 51 01 220 801	HRS/MSC AFL	7500				0 0		7500
+ 54-51-00-112	NO. 2 ENGINE - DETAILED INSPECTION OF THE ENGINE MOUNT THRUST LINK	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 54 51 01 220 801	HRS/MSC AFL	7500				0 0		7500
54-ZL-00-201 (s)	GENERAL VISUAL INSPECTION LEFT/RIGHT PYLON-EXTERNAL						PKG		
MRB	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			23-DEC-2019 2630:03 1481		
54-ZL-00-302 (s)	GENERAL VISUAL INSPECTION LEFT/RIGHT PYLON-INTERNAL						PKG		
MRB	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-DEC-2019 2630:03 1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
545100-0101	ENGINE THRUST LINK ASSEMBLY 1005451401-001 2401 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
545100-0102	ENGINE THRUST LINK ASSEMBLY 1005451401-001 2447 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
545100-0201	FWD ENGINE THRUST LINK BOLT 1005451657-005 3381 LIFE LIMIT	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
545100-0202	FWD ENGINE THRUST LINK BOLT 1005451657-005 3383 LIFE LIMIT	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
545100-0203	FWD ENGINE THRUST LINK BOLT 1005451657-005 3380 LIFE LIMIT	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
545100-0204	FWD ENGINE THRUST LINK BOLT 1005451657-005 3382 LIFE LIMIT	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
545100-0301	AFT ENGINE THRUST LINK BOLT 1005451658-005 3206 LIFE LIMIT	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	
545100-0302	AFT ENGINE THRUST LINK BOLT 1005451658-005 3208 LIFE LIMIT	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
545100-0401	REAR ENGINE MOUNT BOLT 1005451659-003 3412	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 54 51 00 961 801	AFL	7500	N:0			0	7500	
545100-0402	REAR ENGINE MOUNT BOLT 1005451659-003 3447	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 54 51 00 961 801	AFL	7500	N:0			0	7500	
545100-0403	REAR ENGINE MOUNT BOLT 1005451659-003 3395	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 54 51 00 961 801	AFL	7500	N:0			0	7500	
545100-0404	REAR ENGINE MOUNT BOLT 1005451659-003 3398	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 54 51 00 961 801	AFL	7500	N:0			0	7500	

CHAPTER 55 STABILIZERS

55-10-00-201 (s)	DETAILED INSPECTION TRIM-ACTUATOR ATTACHMENT FITTINGS, FRONT SPAR STUB, STEADY TEE, AND APPLICABLE BACKUP STRUCTURE ON THE HORIZONTAL STABILIZER						PKG		
	PKG 5	MOS HRS/MSC	96	+1m/-1m			23-DEC-2019 2630:03		
MRB	REF: AMM 55 10 00 220 806	AFL					1481		
55-10-00-202 (s)	SPECIAL DETAILED INSPECTION AFT SIDE AND HINGE FITTINGS OF THE HORIZONTAL-STABILIZER REAR SPAR AND STUB						PKG		
	PKG 5	MOS HRS/MSC	96	+1m/-1m			23-DEC-2019 2630:03		
MRB	REF: AMM 55 10 00 280 801	AFL					1481		
55-10-00-203 (s)	DETAILED INSPECTION EXTERNAL SURFACES OF THE HORIZONTAL-STABILIZER UPPER AND LOWER SKINS AND SPLICES COVERED BY FAIRINGS						PKG		
	PKG 5	MOS HRS/MSC	96	+1m/-1m			23-DEC-2019 2630:03		
MRB	REF: AMM 55 10 00 220 802	AFL					1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-00-204 (s)	DETAILED INSPECTION INTERNAL STRUCTURE OF THE HORIZONTAL STABILIZER THAT SURROUNDS THE PCUS PKG 4	MOS HRS/MSC	48	+1m/-1m			23-DEC-2019 2630:03 1481		
MRB	REF: AMM 55 10 00 220 803	AFL							
55-10-00-205	SPECIAL DETAILED INSPECTION INTERNAL STRUCTURE OF THE HORIZONTAL STABILIZER THAT DOES NOT SURROUND THE PCUS	MOS HRS/MSC	48	+1m/-1m		-50	23-DEC-2019 2630:03 1481	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 55 10 00 280 802	AFL							
55-10-00-206 (s)	DETAILED INSPECTION PIVOT FITTING AND BOLT OF THE HORIZONTAL STABILIZER PKG 5	MOS HRS/MSC	96	+1m/-1m			23-DEC-2019 2630:03 1481		
MRB	REF: AMM 55 10 00 220 805	AFL							
55-10-00-307 (s)	GENERAL VISUAL INSPECTION FORWARD SIDE OF THE HORIZONTAL-STABILIZER FRONT SPAR PKG 5	MOS HRS/MSC	96	+1m/-1m			23-DEC-2019 2630:03 1481		
MRB	REF: AMM 55 10 00 210 801	AFL							
55-11-00-101	DETAILED INSPECTION HORIZONTAL STABILIZER STRINGERS, RIBS, PCU DOOR AND SURROUND STRUCTURE	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 55 10 00 220 811	AFL	7500				0	7500	
55-11-00-103	SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER/ELEVATOR ACTUATOR ATTACHMENT AND BACKUP STRUCTURE INCLUDING FITTING LUGS AND BACKUP FITTINGS	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: NDT ET-55-11-001	AFL	7500				0	7500	
55-11-00-106	DETAILED INSPECTION HORIZONTAL STABILIZER CENTER RIB BOX	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 55 10 00 220 809	AFL	7500				0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-11-00-107	DETAILED INSPECTION HORIZONTAL STABILIZER SPARS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 55 10 00 220 810	HRS/MSC AFL	7500				0		7500
55-11-00-109	GENERAL VISUAL INSPECTION ELEVATOR SKINS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 55 20 00 210 802	HRS/MSC AFL	7500				0		7500
55-11-00-110	GENERAL VISUAL INSPECTION HORIZONTAL STABILIZER SKINS - EXTERNAL	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 55 10 00 210 804	HRS/MSC AFL	7500				0		7500
55-11-00-111	SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER DOUBLER AROUND PCU DOOR CUTOUT	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-55-11-003	HRS/MSC AFL	7500				0		7500
55-11-00-112	SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER CENTER RIB BOX - FRONT AND REAR SPAR STUBS AND SKIN COVERED BY SPLICES, STIFFENERS AND FITTINGS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-55-11-004	HRS/MSC AFL	7500				0		7500
55-11-00-113	SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER SPARS PCU ATTACHMENT AREA	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-55-11-002	HRS/MSC AFL	7500				0		7500
55-11-00-115	DETAILED INSPECTION ELEVATOR SKINS AROUND HINGE FITTINGS AND ELEVATOR MASS BALANCE ATTACHMENT AND BACKUP STRUCTURE	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 55 20 00 220 804	HRS/MSC AFL	7500				0		7500

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-11-00-117	DISCARD THE HORIZONTAL STABILIZER/ELEVATOR FITTING ATTACHMENT PINS	MOS					28-JAN-2011		
LIFE LIMIT	REF: AMM 27 31 17 961 801	HRS/MSC AFL	7500				0 0		7500
+ 55-11-00-119	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL STABILIZER/ELEVATOR ACTUATOR BACKUP STRUCTURE	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 55 10 00 280 803	HRS/MSC AFL	7500				0 0		7500
55-20-00-201 (s)	SPECIAL DETAILED INSPECTION FORWARD SIDE OF THE ELEVATOR FRONT SPAR COVERED BY THE LEADING EDGE						PKG		
MRB	REF: AMM 55 20 00 280 801	PKG 5 MOS HRS/MSC AFL	96	+1m/-1m			23-DEC-2019 2630:03 1481		
55-20-00-202 (s)	DETAILED INSPECTION FORWARD SIDE, HINGE FITTINGS, AND BOLTS OF THE ELEVATOR FRONT SPAR NOT COVERED BY THE LEADING EDGE						PKG		
MRB	REF: AMM 55 20 00 220 802	PKG 5 MOS HRS/MSC AFL	96	+1m/-1m			23-DEC-2019 2630:03 1481		
55-20-00-203	SPECIAL DETAILED INSPECTION BACKUP STRUCTURE OF THE ELEVATOR ATTACHMENT FITTINGS	MOS	48	+1m/-1m	-50		23-DEC-2019	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 55 20 00 280 802	HRS/MSC AFL					2630:03 1481		
55-30-00-201	DETAILED INSPECTION FORWARD SIDE OF THE VERTICAL-STABILIZER FRONT SPAR	MOS	48	+1m/-1m	-50		23-DEC-2019	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 55 30 00 220 801	HRS/MSC AFL					2630:03 1481		
55-30-00-202 (s)	DETAILED INSPECTION AFT SIDE AND HINGE FITTINGS OF THE VERTICAL-STABILIZER REAR SPAR						PKG		
MRB	REF: AMM 55 30 00 220 802	PKG 4 MOS HRS/MSC AFL	48	+1m/-1m			23-DEC-2019 2630:03 1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-00-203 (s)	DETAILED INSPECTION UPPER SIDE, PIVOT FITTINGS, AND HSTA ATTACH BOLT OF THE TOP CANTED RIB OF THE VERTICAL STABILIZER						PKG		
	PKG 5	MOS	96	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 55 30 00 220 803	HRS/MSC AFL					2630:03 1481		
55-30-00-204 (s)	DETAILED INSPECTION INTERNAL STRUCTURE THAT SURROUNDS THE PCUS IN THE VERTICAL STABILIZER						PKG		
	PKG 4	MOS	48	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 55 30 00 220 804	HRS/MSC AFL					2630:03 1481		
55-30-00-205	DETAILED INSPECTION INTERNAL STRUCTURE THAT DOES NOT SURROUND THE PCUS IN THE VERTICAL STABILIZER								
		MOS	48	+1m/-1m			23-DEC-2019	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 55 30 00 220 805	HRS/MSC AFL				-50	2630:03 1481		
55-31-00-101	SPECIAL DETAILED INSPECTION VERTICAL STABILIZER SPAR TO REAR FUSELAGE ATTACHMENT AREA - CANTED FRAME								
		MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-55-31-001	HRS/MSC AFL	7500				0 0	7500	
55-31-00-102	GENERAL VISUAL INSPECTION VERTICAL STABILIZER EXTERNAL SKIN PANELS								
		MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 55 30 00 210 806	HRS/MSC AFL	7500				0 0	7500	
55-31-00-104	DETAILED INSPECTION VERTICAL/HORIZONTAL STABILIZER TRIM ACUTATOR FITTINGS								
		MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 55 30 00 220 806	HRS/MSC AFL	7500				0 0	7500	
55-31-00-106	DETAILED INSPECTION VERTICAL/HORIZONTAL STABILIZER PIVOT FITTINGS AND BACKUP STRUCTURE								
		MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 55 30 00 220 807	HRS/MSC AFL	7500				0 0	7500	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-31-00-109	SPECIAL DETAILED INSPECTION VERTICAL STABILIZER/RUDDER ACTUATOR ATTACHMENT AND BACKUP STRUCTURE								
AIRWORTHINESS	REF: NDT ET-55-31-004	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
55-31-00-112	DETAILED INSPECTION VERTICAL STABILIZER DRAG ANGLES								
AIRWORTHINESS	REF: AMM 55 30 00 220 811	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
55-31-00-113	DETAILED INSPECTION RUDDER								
AIRWORTHINESS	REF: AMM 55 40 00 220 804	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
55-31-00-114	DETAILED INSPECTION VERTICAL STABILIZER SPARS ABOVE THE LOWER ATTACHMENT AREA								
AIRWORTHINESS	REF: AMM 55 30 00 220 816	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
55-31-00-115	SPECIAL DETAILED INSPECTION VERTICAL STABILIZER SPAR TO REAR FUSELAGE ATTACHMENT AREA - SPARS								
AIRWORTHINESS	REF: NDT ET-55-31-002	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
55-31-00-116	DETAILED INSPECTION VERTICAL STABILIZER SKIN PANELS, STRINGERS AND RIBS								
AIRWORTHINESS	REF: AMM 55 30 00 220 812	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
55-31-00-118	SPECIAL DETAILED INSPECTION VERTICAL STABILIZER STEADY FITTINGS								
AIRWORTHINESS	REF: NDT ET-55-31-007	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
55-31-00-120	SPECIAL DETAILED INSPECTION VERTICAL STABILIZER PIVOT FITTINGS AND BACKUP STRUCTURE								
AIRWORTHINESS	REF: See Workcard	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-31-00-121	DETAILED INSPECTION OF THE VERTICAL/HORIZONTAL STABILIZER PIVOT FITTING BUSHINGS								
AIRWORTHINESS	REF: AMM 55 30 00 220 809	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
55-31-00-123	SPECIAL DETAILED INSPECTION VERTICAL STABILIZER SPARS ABOVE ATTACHMENT AREA - PCU ATTACHMENT AREA								
AIRWORTHINESS	REF: NDT ET-55-31-003	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
55-31-00-124	DETAILED INSPECTION VERTICAL STABILIZER SKIN PANELS - VOR/LOC ANTENNA CUTOUTS								
AIRWORTHINESS	REF: AMM 55 30 00 220 813	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
55-31-00-125	DETAILED INSPECTION VERTICAL/HORIZONTAL STABILIZER PIVOT FITTINGS ATTACHMENT - LUGS AND ATTACHMENTS								
AIRWORTHINESS	REF: AMM 55 30 00 220 814	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
55-31-00-126	DETAILED INSPECTION VERTICAL STABILIZER/RUDDER ACTUATOR ATTACHMENT - DUAL MEMBER HINGE FITTINGS								
AIRWORTHINESS	REF: AMM 55 30 00 220 815	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
55-31-00-127	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER STEADY-TEE FITTINGS AND PITCH-TRIM ACTUATOR FITTING BACKUP STRUCTURE								
AIRWORTHINESS	REF: AMM 55 10 00 220 812	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
55-31-00-128	SPECIAL DETAILED INSPECTION OF THE COVERED SHEAR PLATE								
AIRWORTHINESS	REF: NDT ET-55-31-006	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-31-00-129	DISCARD THE VERTICAL STABILIZER PIVOT FITTING PIN, PART NO. NAS6707DHU211, NON-SERIALIZED	MOS					28-JAN-2011		
LIFE LIMIT	REF: AMM 27 41 05 961 803	HRS/MSC AFL	7500				0 0		7500
55-31-00-130	DISCARD THE VERTICAL/RUDDER AND PCU/RUDDER ATTACHMENT FITTING PINS	MOS					28-JAN-2011		
LIFE LIMIT	REF: AMM 27 21 13 961 801	HRS/MSC AFL	7500				0 0		7500
55-40-00-201	SPECIAL DETAILED INSPECTION FORWARD SIDE OF THE RUDDER FRONT SPAR COVERED BY THE LEADING EDGE	MOS	48	+1m/-1m		-50	23-DEC-2019	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 55 40 00 280 801	HRS/MSC AFL					2630:03 1481		
55-40-00-202	DETAILED INSPECTION FORWARD SIDE, HINGE FITTINGS, AND BOLTS OF THE RUDDER FRONT SPAR NOT COVERED BY THE LEADING EDGE	MOS	48	+1m/-1m		-50	23-DEC-2019	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 55 40 00 220 802	HRS/MSC AFL					2630:03 1481		
55-40-00-203 (s)	SPECIAL DETAILED INSPECTION BACKUP STRUCTURE OF THE ATTACHMENT FITTINGS OF THE RUDDER	MOS	96	+1m/-1m			PKG		
MRB	REF: AMM 55 40 00 280 802	HRS/MSC AFL					23-DEC-2019 2630:03 1481		
55-ZL-00-201 (s)	GENERAL VISUAL INSPECTION VERTICAL-STABILIZER, RAM AIR FAIRING, AND DRAG ANGLES-EXTERNAL	MOS	96	+1m/-1m			PKG		
MRB	REF: See Workcard	HRS/MSC AFL					23-DEC-2019 2630:03 1481		
55-ZL-00-202 (s)	GENERAL VISUAL INSPECTION LEADING EDGE OF THE VERTICAL STABILIZER, INCLUDING RAM AIR FAIRING-INTERNAL	MOS	96	+1m/-1m			PKG		
MRB	REF: See Workcard	HRS/MSC AFL					23-DEC-2019 2630:03 1481		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-ZL-00-205 (s)	GENERAL VISUAL INSPECTION LEFT/RIGHT HORIZONTAL STABILIZER-EXTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
55-ZL-00-207 (s)	GENERAL VISUAL INSPECTION EXTERNAL SURFACE OF THE RUDDER PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
55-ZL-00-208 (s)	GENERAL VISUAL INSPECTION RUDDER LEADING EDGE-INTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
55-ZL-00-303 (s)	GENERAL VISUAL INSPECTION VERTICAL-STABILIZER-INTERNAL PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
55-ZL-00-304 (s)	GENERAL VISUAL INSPECTION TIP OF THE VERTICAL-STABILIZER-INTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
55-ZL-00-305 (s)	GENERAL VISUAL INSPECTION LEFT/RIGHT HORIZONTAL-STABILIZER FLIGHT-CONTROL COMPARTMENT AND LEFT/RIGHT ELEVATOR-HINGE ATTACH POINTS-INTERNAL PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
551007	HORIZONTAL STABILIZER 1005510051-001 292	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
REF: See Workcard									
553005-0101	RAM AIR ACCESS PANEL ASSEMBLY 1005351831-001 336	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
REF: See Workcard									

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
553101-0101	VERTICAL STABILIZER PITCH TRIM BOLT NAS6704DU114 NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 27 41 05 961 804	AFL	7500	N:0			0	7500	
553101-0102	VERTICAL STABILIZER PITCH TRIM PRIMARY LOADPATH BUSHING 1005510807-005 395	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 27 41 05 961 804	AFL	7500	N:0			0	7500	
553101-0103	VERTICAL STABILIZER PITCH TRIM SECONDARY LOADPATH BUSHING 1005510809-001 316	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 27 41 05 961 804	AFL	7500	N:0			0	7500	
CHAPTER 56 WINDOWS									
561101-0101	PILOT WINDSHIELD ASSY, (LH) 185901-3 10235H7804	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
561101-0102	COPILOT WINDSHIELD ASSY, (LH) 185901-4 10246H9178	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
561201-0101	PILOT SIDE WINDOW 185902-1 10240H8580	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
561201-0102	COPILOT SIDE WINDOW 185902-2 10258H1211	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562101-0101	L/H #1 F/S 412 - CABIN WINDOW 1005340003-001 10/1000198 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
562101-0102	R/H #1 F/S 412 - CABIN WINDOW 1005340003-001 10/1000195 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
562101-0103	L/H #2 F/S 444 - CABIN WINDOW 1005340003-001 10/1000194 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
562101-0104	R/H #2 F/S 444 - CABIN WINDOW 1005340003-001 10/1000203 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
562101-0105	L/H #3 F/S 478 - CABIN WINDOW 1005340003-001 10/1000176 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
562101-0106	R/H #3 F/S 478 - CABIN WINDOW 1005340003-001 10/1000202 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
562101-0107	L/H #4 F/S 510 - CABIN WINDOW 1005340003-001 10/1000200 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
562101-0108	R/H #4 F/S 510 - CABIN WINDOW 1005340003-001 10/1000177 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562101-0109	L/H #5 F/S 545 - CABIN WINDOW 1005340003-001 10/1000201 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
562101-0110	EMERGENCY EXIT R/H #5 F/S 545 - CABIN WINDOW 1005340003-001 10/1000186 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
562101-0111	L/H #6 F/S 580 - CABIN WINDOW 1005340003-001 10/1000193 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
562101-0112	R/H #6 F/S 580 - CABIN WINDOW 1005340003-001 10/1000178 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
CHAPTER 57 WINGS									
57-00-00-401A	SPECIAL DETAILED INSPECTION OF THE WING TANK ACCESS HOLES ACCESS 161BB REF:	MOS HRS/MSC AFL	4183						4183
57-00-00-401B	SPECIAL DETAILED INSPECTION OF THE WING TANK ACCESS HOLES ACCESS 531JB REF:	MOS HRS/MSC AFL	7500						7500
57-00-00-401C	SPECIAL DETAILED INSPECTION OF THE WING TANK ACCESS HOLES 161AB REF:	MOS HRS/MSC AFL	7500						7500

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-00-00-401D	SPECIAL DETAILED INSPECTION OF THE WING TANK ACCESS HOLES ACCESS 531BB	MOS HRS/MSC REF: AFL	7500					7500	
57-00-00-401E	SPECIAL DETAILED INSPECTION OF THE WING TANK ACCESS HOLES ACCESS 631BB	MOS HRS/MSC REF: AFL	7500					7500	
57-00-00-401F	SPECIAL DETAILED INSPECTION OF THE WING TANK ACCESS HOLES ACCESS 531GB	MOS HRS/MSC REF: AFL	7500					7500	
57-00-00-401G	SPECIAL DETAILED INSPECTION OF THE WING TANK ACCESS HOLES ACCESS 631JB	MOS HRS/MSC REF: AFL	7500					7500	
57-00-00-401H	SPECIAL DETAILED INSPECTION OF THE WING TANK ACCESS HOLES ACCESS 531HB	MOS HRS/MSC REF: AFL	7500					7500	
57-00-00-401I	SPECIAL DETAILED INSPECTION OF THE WING TANK ACCESS HOLES ACCESS 162BB	MOS HRS/MSC - REF: AFL							
57-10-00-201 (s)	DETAILED INSPECTION FORWARD SIDE OF THE CENTER-WING FRONT SPAR						PKG		
	PKG 5	MOS	96	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 57 10 00 220 801	HRS/MSC AFL					2630:03 1481		
57-10-00-202 (s)	DETAILED INSPECTION WING-TO-FUSELAGE ATTACHMENT FITTINGS						PKG		
	PKG 5	MOS	96	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 57 10 00 220 806	HRS/MSC AFL					2630:03 1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-00-203 (s)	DETAILED INSPECTION AFT SIDE OF THE CENTER-WING REAR SPAR PKG 5	MOS HRS/MSC	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 57 10 00 220 802	AFL							
57-10-00-204 (s)	DETAILED INSPECTION INTERNAL STRUCTURE OF THE CENTER WING PKG 5	MOS HRS/MSC	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 57 10 00 220 805	AFL							
57-10-00-205 (s)	DETAILED INSPECTION EXTERNAL SURFACE OF THE CENTER-WING UPPER PLANK PKG 5	MOS HRS/MSC	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 57 10 00 220 803	AFL							
57-10-00-206 (s)	GENERAL VISUAL INSPECTION EXTERNAL SURFACE OF THE CENTER-WING LOWER PLANK NOT COVERED BY THE UNDER-WING FAIRING PKG 4	MOS HRS/MSC	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 57 10 00 210 801	AFL							
57-10-00-207 (s)	DETAILED INSPECTION EXTERNAL SURFACE OF THE CENTER-WING LOWER PLANK COVERED BY THE UNDER-WING FAIRING PKG 5	MOS HRS/MSC	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 57 10 00 220 804	AFL							
57-11-00-101	SPECIAL DETAILED INSPECTION LOWER WING PLANK SPLICE AT BL0.0	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: See Workcard	AFL	7500				0		7500
57-11-00-102	SPECIAL DETAILED INSPECTION LOWER WING PLANK SPLICE AT WS237.00 TO WS257.00	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: NDT ET-57-11-009	AFL	7500				0		7500

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-11-00-103	DETAILED INSPECTION LOWER CENTER PLANK OF THE WING INCLUDING SPLICES	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 57 00 00 220 801	HRS/MSC AFL	6791				0 0		6791
57-11-00-104	SPECIAL DETAILED INSPECTION LOWER WING PLANK UTILITY HOLES AT BL12.00 AND WS299.34	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-11-004	HRS/MSC AFL	7500				0 0		7500
57-11-00-105	SPECIAL DETAILED INSPECTION LOWER WING PLANK DRAIN HOLES - INBOARD - BL0.0, STR. 14	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-11-002	HRS/MSC AFL	7500				0 0		7500
57-11-00-106	SPECIAL DETAILED INSPECTION REAR SPAR SPLICE AT WS35.6	MOS					28-JAN-2011		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	7500				0 0		7500
57-11-00-107	SPECIAL DETAILED INSPECTION FRONT SPAR SPLICE AT WS35.6	MOS					28-JAN-2011		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	7500				0 0		7500
57-11-00-108	SPECIAL DETAILED INSPECTION REAR SPAR LOWER CAP AND LOWER AFT PLANK	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-11-001	HRS/MSC AFL	5718				0 0		5718
57-11-00-109	SPECIAL DETAILED INSPECTION FRONT SPAR-LOWER CAP AND LOWER FORWARD PLANK	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-11-018	HRS/MSC AFL	7500				0 0		7500
57-11-00-110	DETAILED INSPECTION RIB AT BL0.0	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 57 10 00 220 807	HRS/MSC AFL	7500				0 0		7500

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-11-00-111	DETAILED INSPECTION RIB AT WS35.6	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 57 10 00 220 808	HRS/MSC AFL	7500				0 0		7500
57-11-00-112	DETAILED INSPECTION RIB AT THE MAIN-LANDING-GEAR SUPPORT AT WS67.0	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 57 20 00 220 811	HRS/MSC AFL	7500				0 0		7500
57-11-00-113	DETAILED INSPECTION FLAP SUPPORT RIBS AT WS115.05, WS196.43 AND WS257.47	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 57 20 00 220 815	HRS/MSC AFL	7500				0 0		7500
57-11-00-115-1	SPECIAL DETAILED INSPECTION LEFT MAIN LANDING GEAR ATTACHMENT AND LOCAL WING STRUCTURE ATTACHMENTS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-11-006	HRS/MSC AFL	7500				0 0		7500
57-11-00-115-2	SPECIAL DETAILED INSPECTION RIGHT MAIN LANDING GEAR ATTACHMENT AND LOCAL WING STRUCTURE ATTACHMENTS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-11-006	HRS/MSC AFL	7500				0 0		7500
57-11-00-117	SPECIAL DETAILED INSPECTION LOWER WING PLANK AT THE FLAP TRACK ATTACHMENT AFT FITTING - WS121.50, WS202.75 AND WS263.50 INCLUDING BOLTS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	7500				0 0		7500
57-11-00-120	SPECIAL DETAILED INSPECTION LOWER WING PLANK ACCESS HOLES - CONTOUR OF ACCESS HOLES AND FLAP FAIRING FASTENER HOLES	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-11-003	HRS/MSC AFL	7500				0 0		7500

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-11-00-121	DETAILED INSPECTION LOWER WING PLANK DRAIN HOLES - INBOARD - BL0.0, STR. 8 AND OUTBOARD - WS330.60, STR. 14	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 57 00 00 220 803	HRS/MSC AFL	7500				0	7500	
57-11-00-122	DETAILED INSPECTION REAR SPAR WEB AND LOWER AFT PLANK OF THE WING INCLUDING SPLICES	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 57 00 00 220 804	HRS/MSC AFL	6791				0	6791	
57-11-00-123	DETAILED INSPECTION FRONT SPAR WEB AND LOWER FORWARD PLANK OF THE WING INCLUDING SPLICES	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 57 00 00 220 805	HRS/MSC AFL	6791				0	6791	
57-11-00-124	SPECIAL DETAILED INSPECTION RIB AT THE MAIN-LANDING GEAR SUPPORT AT WS67.0 UPPER AND LOWER CHORDS AND BACKUP FITTINGS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-11-005	HRS/MSC AFL	7500				0	7500	
57-11-00-125-1	SPECIAL DETAILED INSPECTION LEFT FLAP SUPPORT RIBS AT WS115.05, WS196.43 AND WS257.47 - UPPER AND LOWER CHORDS, LOWER FLANGE AND BACKUP FITTINGS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-11-016	HRS/MSC AFL	7500				0	7500	
57-11-00-125-2	SPECIAL DETAILED INSPECTION RIGHT FLAP SUPPORT RIBS AT WS115.05, WS196.43 AND WS257.47 - UPPER AND LOWER CHORDS, LOWER FLANGE AND BACKUP FITTINGS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-11-016	HRS/MSC AFL	7500				0	7500	
57-11-00-126-1	SPECIAL DETAILED INSPECTION LEFT MAIN LANDING GEAR SIDE STAY FITTING	MOS					28-JAN-2011		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	7500				0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-11-00-126-2	SPECIAL DETAILED INSPECTION RIGHT MAIN LANDING GEAR SIDE STAY FITTING	MOS					28-JAN-2011		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	7500				0 0	7500	
57-11-00-127	DETAILED INSPECTION OF THE LOWER WING PLANK AT THE FLAP TRACK ATTACHMENT FORWARD FITTING - WS121.50, WS202.75 AND WS263.50	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 57 20 00 220 814	HRS/MSC AFL	7500				0 0	7500	
57-11-00-128-1	GENERAL VISUAL INSPECTION LEFT MAIN LANDING GEAR SIDE STAY FITTING - FASTENERS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 57 10 00 210 804	HRS/MSC AFL	7500				0 0	7500	
57-11-00-128-2	GENERAL VISUAL INSPECTION RIGHT MAIN LANDING GEAR SIDE STAY FITTING - FASTENERS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 57 10 00 210 804	HRS/MSC AFL	7500				0 0	7500	
57-11-00-131	SPECIAL DETAILED INSPECTION MAIN LANDING GEAR LOWER SKIN-TO-TRUNNION ATTACHMENT	MOS					28-JAN-2011		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	7500				0 0	7500	
57-11-00-132	GENERAL VISUAL INSPECTION MAIN LANDING GEAR ATTACHMENT FASTENERS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 57 20 00 210 806	HRS/MSC AFL	7500				0 0	7500	
57-11-00-133	SPECIAL DETAILED INSPECTION OF THE REAR SPAR LOWER CAP BETWEEN LBL20.0 TO RBL20.0	MOS					28-JAN-2011		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	7500				0 0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-11-00-134	SPECIAL DETAILED INSPECTION OF THE REAR SPAR LOWER CAP FASTENER HOLES AT WS35.00, WS67.00, AND WS80.00								
AIRWORTHINESS	REF: NDT ET-57-11-008	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
57-11-00-135	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR LOWER CAP BETWEEN LBL20.0 TO RBL20.0								
AIRWORTHINESS	REF: See Workcard	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
57-11-00-137	DETAILED INSPECTION OF THE OUTER-WING REAR SPAR ATTACHMENT TO FLIGHT CONTROL FITTING ASSEMBLIES FROM WS94.704 TO WS356.473								
AIRWORTHINESS	REF: AMM 57 20 00 220 818	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
57-11-00-138	SPECIAL DETAILED INSPECTION OF THE RIB BACK-UP FITTINGS: TENSION BOLT REMOVAL FOR BHEC								
AIRWORTHINESS	REF: NDT ET-57-11-013	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
57-11-00-139	SPECIAL DETAILED INSPECTION OF THE TRUNNION FITTING: TENSION BOLT REMOVAL FOR BHEC								
AIRWORTHINESS	REF: NDT ET-57-11-014	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
57-11-00-140	DISCARD THE TRUNNION TO REAR SPAR TENSION PINS, PART NO. MS21250-08, NON-SERIALIZED								
LIFE LIMIT	REF: AMM 57 51 07 961 801	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
+ 57-11-00-141	DETAILED INSPECTION OF THE REAR SPAR SPLICE AT WS35.60								
AIRWORTHINESS	REF: AMM 57 10 00 220 810	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-11-00-142	DETAILED INSPECTION OF THE FRONT SPAR SPLICE AT WS35.60	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 57 10 00 220 811	HRS/MSC AFL	7500				0 0		7500
+ 57-11-00-143	SPECIAL DETAILED INSPECTION OF THE LOWER WING PANEL AND TRUNNION FASTENER HOLES	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-11-021	HRS/MSC AFL	7500				0 0		7500
+ 57-11-00-144	DETAILED INSPECTION OF THE MLG TRUNNION AND OUTBOARD RIB RADII	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 57 20 00 220 819	HRS/MSC AFL	7500				0 0		7500
57-20-00-101	SPECIAL DETAILED INSPECTION DRY BAY INCLUDING THE AILERON ACCESS PANEL AND SKIN SPLICE	MOS					28-JAN-2011		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	7500				0 0		7500
57-20-00-102	SPECIAL DETAILED INSPECTION OF THE WINGLET ATTACHMENT - SPARS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-20-001	HRS/MSC AFL	7500				0 0		7500
57-20-00-201 (s)	DETAILED INSPECTION FORWARD SIDE OF THE WING FRONT SPAR						PKG		
MRB	PKG 5 REF: AMM 57 20 00 220 801	MOS HRS/MSC AFL	96	+1m/-1m			23-DEC-2019 2630:03 1481		
57-20-00-202-1	DETAILED INSPECTION LEFT WING SPOILER ATTACHMENT AND ACTUATOR FITTINGS	MOS	48	+1m/-1m		-50	23-DEC-2019	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 57 20 00 220 810	HRS/MSC AFL					2630:03 1481		
57-20-00-202-2	DETAILED INSPECTION RIGHT WING SPOILER ATTACHMENT AND ACTUATOR FITTINGS	MOS	48	+1m/-1m		-50	23-DEC-2019	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 57 20 00 220 810	HRS/MSC AFL					2630:03 1481		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-20-00-203	DETAILED INSPECTION AFT SIDE OF THE WING REAR SPAR	MOS	48	+1m/-1m			23-DEC-2019	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 57 20 00 220 802	HRS/MSC AFL			-50		2630:03 1481		
57-20-00-204-1	DETAILED INSPECTION LEFT MAIN LANDING GEAR ATTACHMENT FITTINGS	MOS	48	+1m/-1m			23-DEC-2019	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 57 20 00 220 805	HRS/MSC AFL			-50		2630:03 1481		
57-20-00-204-2	DETAILED INSPECTION RIGHT MAIN LANDING GEAR ATTACHMENT FITTINGS	MOS	48	+1m/-1m			23-DEC-2019	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 57 20 00 220 805	HRS/MSC AFL			-50		2630:03 1481		
57-20-00-205-1 (s)	DETAILED INSPECTION LEFT WING INTERNAL STRUCTURE FROM WS35.60 TO WS342.70						PKG		
MRB	PKG 5 REF: AMM 57 20 00 220 803	MOS HRS/MSC AFL	96	+1m/-1m			23-DEC-2019 2630:03 1481		
57-20-00-205-2 (s)	DETAILED INSPECTION RIGHT WING INTERNAL STRUCTURE FROM WS35.60 TO WS342.70						PKG		
MRB	PKG 5 REF: AMM 57 20 00 220 803	MOS HRS/MSC AFL	96	+1m/-1m			23-DEC-2019 2630:03 1481		
57-20-00-206-1	DETAILED INSPECTION LEFT WING INTERNAL STRUCTURE FROM WS331.35 TO WS356.73	MOS	48	+1m/-1m			23-DEC-2019	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 57 20 00 220 804	HRS/MSC AFL			-50		2630:03 1481		
57-20-00-206-2	DETAILED INSPECTION RIGHT WING INTERNAL STRUCTURE FROM WS331.35 TO WS356.73	MOS	48	+1m/-1m			23-DEC-2019	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 57 20 00 220 804	HRS/MSC AFL			-50		2630:03 1481		
57-20-00-207 (s)	DETAILED INSPECTION WINGLET ATTACHMENT FITTINGS						PKG		
MRB	PKG 5 REF: AMM 57 20 00 220 807	MOS HRS/MSC AFL	96	+1m/-1m			23-DEC-2019 2630:03 1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-20-00-208-1 (s)	DETAILED INSPECTION LEFT FLAP ATTACHMENT AND ACTUATOR FITTINGS ON THE WING PKG 5	MOS HRS/MSC	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 57 20 00 220 808	AFL							
57-20-00-208-2 (s)	DETAILED INSPECTION RIGHT FLAP ATTACHMENT AND ACTUATOR FITTINGS ON THE WING PKG 5	MOS HRS/MSC	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 57 20 00 220 808	AFL							
57-20-00-209-1	DETAILED INSPECTION LEFT AILERON ATTACHMENT FITTINGS ON THE WING	MOS HRS/MSC	48	+1m/-1m		-50	23-DEC-2019 2630:03 1481	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 57 20 00 220 809	AFL							
57-20-00-209-2	DETAILED INSPECTION RIGHT AILERON ATTACHMENT FITTINGS ON THE WING	MOS HRS/MSC	48	+1m/-1m		-50	23-DEC-2019 2630:03 1481	03-NOV-2023	03-DEC-2023
MRB	REF: AMM 57 20 00 220 809	AFL							
57-20-00-210 (s)	DETAILED INSPECTION FLAP SUPPORT RAILS - WS121.50, WS202.75 AND WS263.9 PKG 4	MOS HRS/MSC	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 57 20 00 220 817	AFL							
57-50-00-101	SPECIAL DETAILED INSPECTION FLAP SUPPORTS AND ATTACHMENTS - INCLUDING LUGS AND ATTACHMENTS	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: See Workcard	AFL 7500					0	7500	
57-50-00-102	SPECIAL DETAILED INSPECTION FLAP CARRIAGES AND THE AFT LINKS	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: NDT ET-57-50-006	AFL 7500					0	7500	
57-50-00-103	SPECIAL DETAILED INSPECTION FLAP HINGE FITTINGS - INCLUDING LUGS AND ATTACHMENTS	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: NDT ET-57-50-007	AFL 7500					0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-50-00-104	SPECIAL DETAILED INSPECTION FLAP SKIN SPLICE AND SPLICE PLATE	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-50-004	HRS/MSC AFL	7500				0 0		7500
57-50-00-105	SPECIAL DETAILED INSPECTION OF THE FLAP LOWER SKIN AT THE SPAR ATTACHMENTS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-50-005	HRS/MSC AFL	7500				0 0		7500
57-50-00-106	SPECIAL DETAILED INSPECTION FLAP ACTUATOR FITTINGS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-50-003	HRS/MSC AFL	7500				0 0		7500
57-50-00-107	DETAILED INSPECTION FLAP STRUCTURE FOR ACTUATOR DISCONNECTED	MOS					06-DEC-2018		
AIRWORTHINESS	REF: AMM 57 50 00 220 801	HRS/MSC AFL	450				2236:21 1275		1725
57-50-00-108	DETAILED INSPECTION FLAP UPPER AND LOWER SKIN AND ACCESS HOLE CUTOUTS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 27 52 21 220 802	HRS/MSC AFL	7500				0 0		7500
57-50-00-109	DETAILED INSPECTION FLAP ACTUATOR BACKUP FITTINGS (A/C 20001 TO 20022)	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 57 20 00 220 816	HRS/MSC AFL	N/A				0 0		
57-50-00-110	GENERAL VISUAL INSPECTION FLAP ACTUATOR FASTENERS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: See Workcard	HRS/MSC AFL	7500				0 0		7500
57-50-00-111	SPECIAL DETAILED INSPECTION OF THE FLAP SUPPORT FORWARD FITTING	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-50-001	HRS/MSC AFL	5599				0 0		5599

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-50-00-112	DETAILED INSPECTION OF THE FLAP UPPER SKIN PANEL AND THE FLAP SPARS								
AIRWORTHINESS	REF: AMM 27 52 00 220 803	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
57-51-00-101	DISCARD THE ATTACHMENT PINS OF THE FLAP INBOARD SUPPORT, PART NO. MS21250-03, NON-SERIALIZED								
LIFE LIMIT	REF: AMM 57 51 00 961 807	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
57-51-00-102	DISCARD THE ATTACHMENT PINS OF THE FLAP MID SUPPORT, PART NO. MS21250-03, NON-SERIALIZED								
LIFE LIMIT	REF: AMM 57 51 00 961 808	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
57-51-00-103	DISCARD THE ATTACHMENT PINS OF THE FLAP OUTBOARD SUPPORT, PART NO. B0206003AG6, NON-SERIALIZED								
LIFE LIMIT	REF: AMM 57 51 00 961 809	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
57-51-00-104	DISCARD THE INBOARD AND MID SUPPORT BOLTS OF THE FLAP, PART NO. NAS6710, NON-SERIALIZED								
LIFE LIMIT	REF: AMM 57 51 00 961 810	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
57-51-00-105	DISCARD THE OUTBOARD SUPPORT BOLT OF THE FLAP, PART NO. NAS6309, NON-SERIALIZED								
LIFE LIMIT	REF: AMM 57 51 00 961 811	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
57-51-00-106	DISCARD THE OUTBOARD SUPPORT BOLT OF THE FLAP, PART NO. NAS6309-27DH, NON-SERIALIZED (IPC 57-51-00 FIGURE 4, ITEM 45)								
	REF:	MOS HRS/MSC AFL	N/A				28-JAN-2011 0 0		
57-51-00-113	DISCARD THE BOLTS OF THE INBOARD FORWARD FITTING OF THE FLAP, PART NO. MS21250H05, NON-SERIALIZED								
LIFE LIMIT	REF: AMM 57 51 00 961 819	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-51-00-114	DISCARD THE BOLTS OF THE MID FORWARD FITTING OF THE FLAP, PART NO. MS21250H05, NON-SERIALIZED	MOS					28-JAN-2011		
LIFE LIMIT	REF: AMM 57 51 00 961 820	HRS/MSC AFL	7500				0 0		7500
57-51-00-115	DISCARD THE BOLTS OF THE OUTBOARD FORWARD FITTING OF THE FLAP, PART NO. MS21250H04, NON-SERIALIZED	MOS					28-JAN-2011		
LIFE LIMIT	REF: AMM 57 51 00 961 821	HRS/MSC AFL	7500				0 0		7500
57-51-00-201 (s)	DETAILED INSPECTION LEFT INBOARD DETAILED INSPECTION LEFT INBOARD SUPPORT FITTINGS, SUPPORT STRUCTURE, AND BOLTS OF THE FLAP	MOS	96	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 57 51 00 220 801	HRS/MSC AFL					2630:03 1481		
57-51-00-201 (s)	DETAILED INSPECTION LEFT OUTBOARD DETAILED INSPECTION LEFT OUTBOARD SUPPORT FITTINGS, SUPPORT STRUCTURE, AND BOLTS OF THE FLAP	MOS	96	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 57 51 00 220 801	HRS/MSC AFL					2630:03 1481		
+ 57-51-00-201 (s)	DETAILED INSPECTION MID LH SUPPORT FITTINGS, SUPPORT STRUCTURE, AND BOLTS OF THE FLAP	MOS	96	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 57 51 00 220 801	HRS/MSC AFL					2630:03 1481		
+ 57-51-00-201 (s)	DETAILED INSPECTION MID RH SUPPORT FITTINGS, SUPPORT STRUCTURE, AND BOLTS OF THE FLAP	MOS	96	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 57 51 00 220 801	HRS/MSC AFL					2630:03 1481		
57-51-00-201 (s)	DETAILED INSPECTION RIGHT INBOARD DETAILED INSPECTION RIGHT INBOARD SUPPORT FITTINGS, SUPPORT STRUCTURE, AND BOLTS OF THE FLAP	MOS	96	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 57 51 00 220 801	HRS/MSC AFL					2630:03 1481		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-51-00-201 (s)	DETAILED INSPECTION RIGHT OUTBOARD DETAILED INSPECTION RIGHT OUTBOARD SUPPORT FITTINGS, SUPPORT STRUCTURE, AND BOLTS OF THE FLAP						PKG		
	PKG 5	MOS	96	+1m/-1m			23-DEC-2019		
MRB	REF: AMM 57 51 00 220 801	HRS/MSC					2630:03		
		AFL					1481		
57-60-00-102	DETAILED INSPECTION AILERON UPPER AND LOWER SKIN								
		MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 27 11 17 220 802	HRS/MSC					0		
		AFL	7500				0	7500	
57-60-00-103	SPECIAL DETAILED INSPECTION AILERON SPARS								
		MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-60-001	HRS/MSC					0		
		AFL	7500				0	7500	
57-60-00-104	SPECIAL DETAILED INSPECTION AILERON TRIM TAB SPAR CAPS AND BACKUP FITTINGS								
		MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-60-002	HRS/MSC					0		
		AFL	7500				0	7500	
57-60-00-106	SPECIAL DETAILED INSPECTION OF THE AILERON PUSHING ROD SUPPORT STRUCTURE - SUPPORT FITTINGS AND LUGS								
		MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-60-004	HRS/MSC					0		
		AFL	7500				0	7500	
57-60-00-107	SPECIAL DETAILED INSPECTION OF THE AILERON HINGE FITTINGS, BACKUP STRUCTURE								
		MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-60-006	HRS/MSC					0		
		AFL	7500				0	7500	
57-60-00-108	GENERAL VISUAL INSPECTION AILERON HINGE FASTENERS								
		MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 27 11 17 210 801	HRS/MSC					0		
		AFL	7500				0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-60-00-109	SPECIAL DETAILED INSPECTION AILERON LOWER SKIN AROUND CUTOUTS								
AIRWORTHINESS	REF: NDT ET-57-60-005	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
57-60-00-110	DETAILED INSPECTION AILERON TRIM TAB SKINS AND SPARS - EXTERNAL								
AIRWORTHINESS	REF: AMM 27 12 09 220 803	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
57-60-00-111	GENERAL VISUAL INSPECTION AILERON TRIM TAB TENSION BOLTS, PIANO HINGES AND PINS								
AIRWORTHINESS	REF: AMM 27 12 09 210 801	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
57-60-00-112	SPECIAL DETAILED INSPECTION AILERON GEARED TAB FRONT SPAR CAPS AND BACKUP FITTINGS								
AIRWORTHINESS	REF: NDT ET-57-60-003	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
57-60-00-113	DETAILED INSPECTION AILERON GEARED TAB STRUCTURE, SPAR AND SKINS - EXTERNAL								
AIRWORTHINESS	REF: AMM 27 11 21 220 803	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
57-60-00-114	GENERAL VISUAL INSPECTION OF THE AILERON GEARED TAB STRUCTURE - HINGE LUGS AND FASTENERS								
AIRWORTHINESS	REF: AMM 27 11 21 210 801	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
57-60-00-115	GENERAL VISUAL INSPECTION AILERON PUSHING ROD SUPPORT FITTING FASTENERS								
AIRWORTHINESS	REF: AMM 27 11 17 210 802	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
57-60-00-116	DISCARD THE AILERON HINGE PINS, PART NO. NAS6204, NON-SERIALIZED								
LIFE LIMIT	REF: AMM 27 11 17 961 802	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-60-00-117	DISCARD THE AILERON GEARED TAB HINGE PINS, PART NO. NAS6203, NON-SERIALIZED	MOS					28-JAN-2011		
LIFE LIMIT	REF: AMM 27 11 21 961 801	HRS/MSC AFL	7500				0 0		7500
57-60-00-118	DISCARD THE AILERON ROD LINK PINS, PART NO. NAS6204, NON-SERIALIZED	MOS					28-JAN-2011		
LIFE LIMIT	REF: AMM 27 11 17 961 801	HRS/MSC AFL	7500				0 0		7500
+ 57-60-00-119	DETAILED INSPECTION OF THE LH AILERON PUSHING ROD SUPPORT STRUCTURE	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 27 11 17 220 803	HRS/MSC AFL	7500				0 0		7500
+ 57-60-00-119	DETAILED INSPECTION OF THE RH AILERON PUSHING ROD SUPPORT STRUCTURE	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 27 11 17 220 803	HRS/MSC AFL	7500				0 0		7500
57-60-00-201-1 (s)	DETAILED INSPECTION LEFT AILERON SUPPORT FITTINGS AND BOLTS						PKG		
MRB	REF: AMM 57 60 00 220 801	PKG 5 MOS HRS/MSC AFL	96	+1m/-1m			23-DEC-2019 2630:03 1481		
57-60-00-201-2 (s)	DETAILED INSPECTION RIGHT AILERON SUPPORT FITTINGS AND BOLTS						PKG		
MRB	REF: AMM 57 60 00 220 801	PKG 5 MOS HRS/MSC AFL	96	+1m/-1m			23-DEC-2019 2630:03 1481		
57-71-00-101	SPECIAL DETAILED INSPECTION OF THE GROUND SPOILER HINGE FITTINGS AND BACKUP STRUCTURE INCLUDING LUGS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-71-002	HRS/MSC AFL	7500				0 0		7500

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-71-00-103	SPECIAL DETAILED INSPECTION OF THE GROUND SPOILER ACTUATOR FITTINGS AND BACKUP STRUCTURE INCLUDING LUGS	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: NDT ET-57-71-001	AFL	7500				0	7500	
57-71-00-104	GENERAL VISUAL INSPECTION GROUND SPOILER ACTUATOR FITTING FASTENERS	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 27 63 09 210 802	AFL	7500				0	7500	
57-71-00-105	GENERAL VISUAL INSPECTION GROUND SPOILER HINGE FITTING FASTENERS	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: AMM 27 63 09 210 801	AFL	7500				0	7500	
57-71-00-106	DISCARD THE GROUND SPOILER HINGE PINS, PART NO. NAS6305, NON-SERIALIZED	MOS HRS/MSC					28-JAN-2011 0		
LIFE LIMIT	REF: AMM 27 63 09 961 801	AFL	7500				0	7500	
57-71-00-108	SPECIAL DETAILED INSPECTION OF THE GROUND SPOILER ACTUATOR FITTING LUGS (SPOILER SIDE)	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: NDT ET-57-71-001	AFL	7500				0	7500	
57-71-00-201-1	SPECIAL DETAILED INSPECTION LEFT OUTBOARD EXTERNAL SURFACE OF THE GROUND SPOILER	MOS HRS/MSC					28-JAN-2011 0		
MRB	REF: AMM 57 71 00 280 801	AFL	3750	+40/-40			0	3750	3790
57-71-00-201-2	SPECIAL DETAILED INSPECTION RIGHT INBOARD EXTERNAL SURFACE OF THE GROUND SPOILER	MOS HRS/MSC					28-JAN-2011 0		
MRB	REF: AMM 57 71 00 280 801	AFL	3750	+40/-40			0	3750	3790
57-71-00-201-3	SPECIAL DETAILED INSPECTION LEFT INBOARD EXTERNAL SURFACE OF THE GROUND SPOILER	MOS HRS/MSC					28-JAN-2011 0		
MRB	REF: AMM 57 71 00 280 801	AFL	3750	+40/-40			0	3750	3790

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-71-00-201-4	SPECIAL DETAILED INSPECTION RIGHT OUTBOARD EXTERNAL SURFACE OF THE GROUND SPOILER	MOS HRS/MSC					28-JAN-2011 0		
MRB	REF: AMM 57 71 00 280 801	AFL	3750	+40/-40			0	3750	3790
57-71-00-202-1 (s)	DETAILED INSPECTION LEFT OUTBOARD SUPPORT FITTINGS AND BOLTS OF THE GROUND SPOILER	MOS HRS/MSC	48	+1m/-1m			23-DEC-2019 2630:03		
MRB	REF: AMM 57 71 00 220 801	AFL					1481		
57-71-00-202-2 (s)	DETAILED INSPECTION LEFT INBOARD SUPPORT FITTINGS AND BOLTS OF THE GROUND SPOILER	MOS HRS/MSC	48	+1m/-1m			23-DEC-2019 2630:03		
MRB	REF: AMM 57 71 00 220 801	AFL					1481		
57-71-00-202-3 (s)	DETAILED INSPECTION RIGHT INBOARD SUPPORT FITTINGS AND BOLTS OF THE GROUND SPOILER	MOS HRS/MSC	48	+1m/-1m			23-DEC-2019 2630:03		
MRB	REF: AMM 57 71 00 220 801	AFL					1481		
57-71-00-202-4 (s)	DETAILED INSPECTION RIGHT OUTBOARD SUPPORT FITTINGS AND BOLTS OF THE GROUND SPOILER	MOS HRS/MSC	48	+1m/-1m			23-DEC-2019 2630:03		
MRB	REF: AMM 57 71 00 220 801	AFL					1481		
57-72-00-101	SPECIAL DETAILED INSPECTION OF THE INBOARD MULTI-FUNCTION SPOILER HINGE FITTINGS AND BACKUP STRUCTURE INCLUDING LUGS	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: NDT ET-57-72-003	AFL	7500				0	7500	
57-72-00-102	SPECIAL DETAILED INSPECTION OF THE INBOARD MULTI-FUNCTION SPOILER ACTUATOR FITTINGS AND BACKUP STRUCTURE INCLUDING LUGS	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: NDT ET-57-72-001	AFL	7500				0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-72-00-103	GENERAL VISUAL INSPECTION INBOARD MULTI-FUNCTION AND GROUND SPOILER PANELS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 57 72 00 210 801	HRS/MSC AFL	7500				0 0		7500
57-72-00-104	SPECIAL DETAILED INSPECTION OF THE OUTBOARD MULTI-FUNCTION SPOILERS HINGE FITTINGS AND BACKUP STRUCTURE INCLUDING LUGS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: NDT ET-57-72-004	HRS/MSC AFL	7500				0 0		7500
57-72-00-105	SPECIAL DETAILED INSPECTION OF THE OUTBOARD MULTI-FUNCTION SPOILER ACTUATOR FITTINGS AND BACKUP STRUCTURE INCLUDING LUGS	MOS							
AIRWORTHINESS	REF: NDT ET-57-72-002	HRS/MSC AFL	7500						7500
57-72-00-106	GENERAL VISUAL INSPECTION INBOARD MULTI-FUNCTION SPOILER HINGE FITTING FASTENERS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 27 62 05 210 801	HRS/MSC AFL	7500				0 0		7500
57-72-00-108	GENERAL VISUAL INSPECTION INBOARD MULTI-FUNCTION SPOILER ACTUATOR FITTINGS FASTENERS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 27 62 01 210 801	HRS/MSC AFL	7500				0 0		7500
57-72-00-110	DETAILED INSPECTION OUTBOARD MULTI-FUNCTION SPOILER PANELS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 57 72 00 220 803	HRS/MSC AFL	7500				0 0		7500
57-72-00-111	GENERAL VISUAL INSPECTION OUTBOARD MULTI-FUNCTION SPOILER HINGE FITTINGS AND BACKUP STRUCTURE FASTENERS	MOS					28-JAN-2011		
AIRWORTHINESS	REF: AMM 57 72 00 210 803	HRS/MSC AFL	7500				0 0		7500

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-72-00-112	GENERAL VISUAL INSPECTION OUTBOARD MULTI-FUNCTION SPOILER ACTUATOR FITTING FASTENERS	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
AIRWORTHINESS	REF: AMM 57 72 00 210 802								
57-72-00-113	DISCARD THE INBOARD M/F SPOILER HINGE PINS	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
LIFE LIMIT	REF: AMM 27 62 05 961 805								
57-72-00-115	DISCARD THE OUTBOARD M/F SPOILER HINGE PINS	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
LIFE LIMIT	REF: AMM 27 62 05 961 803								
57-72-00-117	SPECIAL DETAILED INSPECTION OF THE INBOARD MULTI-FUNCTION SPOILER SIDE ACTUATOR FITTING LUG	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
AIRWORTHINESS	REF: NDT ET-57-72-001								
57-72-00-118	SPECIAL DETAILED INSPECTION OF THE OUTBOARD MULTI-FUNCTION SPOILER SIDE ACTUATOR FITTING LUG	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
AIRWORTHINESS	REF: NDT ET-57-72-002								
57-72-00-201	SPECIAL DETAILED INSPECTION EXTERNAL SURFACE OF THE INBOARD MULTI-FUNCTION SPOILER	MOS HRS/MSC AFL	3750	+40/-40			28-JAN-2011 0 0	3750	3790
MRB	REF: AMM 57 72 00 280 801								
57-72-00-202-1 (s)	DETAILED INSPECTION LEFT OUTBOARD SUPPORT FITTINGS AND BOLTS OF THE MULTI-FUNCTION SPOILER	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 57 72 00 220 801								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-72-00-202-2 (s)	DETAILED INSPECTION LEFT INBOARD SUPPORT FITTINGS AND BOLTS OF THE MULTI-FUNCTION SPOILER PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 57 72 00 220 801								
57-72-00-202-3 (s)	DETAILED INSPECTION RIGHT INBOARD SUPPORT FITTINGS AND BOLTS OF THE MULTI-FUNCTION SPOILER PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 57 72 00 220 801								
57-72-00-202-4 (s)	DETAILED INSPECTION RIGHT OUTBOARD SUPPORT FITTINGS AND BOLTS OF THE MULTI-FUNCTION SPOILER PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 57 72 00 220 801								
57-72-00-210 (s)	DETAILED INSPECTION EXTERNAL SURFACE OF THE OUTBOARD MULTI-FUNCTION SPOILER PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 57 72 00 220 802								
57-ZL-00-202 (s)	GENERAL VISUAL INSPECTION LEFT/RIGHT AILERON - EXTERNAL PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
57-ZL-00-204 (s)	GENERAL VISUAL INSPECTION SURFACE OF THE LEFT/RIGHT WING LEADING EDGE-EXTERNAL PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
57-ZL-00-206 (s)	GENERAL VISUAL INSPECTION UPPER SURFACE OF THE LEFT/RIGHT WING FROM WS35.596 TO WS370.000-EXTERNAL PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-ZL-00-207 (s)	GENERAL VISUAL INSPECTION LOWER SURFACE OF THE LEFT/RIGHT WING FROM WS35.596 TO WS370.00-EXTERNAL PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
57-ZL-00-209 (s)	GENERAL VISUAL INSPECTION LEFT/RIGHT INTERNAL SECTION OF THE WING INCLUDING ALL OF THE INSTALLED COMPONENTS, ATTACHMENTS, AND FITTINGS FROM WS342.698 TO WS370.00 PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
57-ZL-00-210 (s)	GENERAL VISUAL INSPECTION OF THE LEFT/RIGHT WINGLET - EXTERNAL PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
57-ZL-00-211 (s)	GENERAL VISUAL INSPECTION LOWER INBOARD TRAILING EDGE OF THE LEFT/RIGHT WING FROM WS35.596 TO WS80.281-EXTERNAL PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
57-ZL-00-215 (s)	GENERAL VISUAL INSPECTION LEFT/RIGHT AILERON INTERNAL STRUCTURE AND WING TRAILING EDGE FROM WS298.155 TO WS370.00 PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
57-ZL-00-216 (s)	GENERAL VISUAL INSPECTION INBOARD TRAILING EDGE OF THE LEFT/RIGHT WING FROM WS35.596 TO WS80.281 - EXTERNAL PKG 3	MOS HRS/MSC AFL	36	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
57-ZL-00-301 (s)	GENERAL VISUAL INSPECTION WING CENTER SECTION FROM LEFT WS35.596 TO RIGHT WS35.596-EXTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-ZL-00-303 (s)	GENERAL VISUAL INSPECTION WING CENTER SECTION FROM LEFT WS35.596 TO RIGHT WS35.596-INTERNAL PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
57-ZL-00-305 (s)	GENERAL VISUAL INSPECTION LEFT/RIGHT WING LEADING EDGE AS VISIBLE THROUGH THE REMOVED ACCESS PANELS-INTERNAL PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
57-ZL-00-308 (s)	GENERAL VISUAL INSPECTION LEFT/RIGHT INTERNAL SECTION OF THE WING INCLUDING ALL OF THE INSTALLED COMPONENTS, ATTACHMENTS, AND FITTINGS FROM WS35.596 TO WS342.698 PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
57-ZL-00-312 (s)	GENERAL VISUAL INSPECTION INBOARD TRAILING EDGE OF THE LEFT/RIGHT WING FROM WS35.596 TO WS80.281-INTERNAL PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
57-ZL-00-314 (s)	GENERAL VISUAL INSPECTION TRAILING EDGE OF THE LEFT/RIGHT WING FROM WS80.281 TO WS298.155-INTERNAL PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
57-ZL-00-315 (s)	GENERAL VISUAL INSPECTION TRAILING EDGE OF THE LEFT/RIGHT WING FROM WS80.281 TO WS298.155-EXTERNAL PKG 4	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: See Workcard								
570000-0101	WING COMPLETE ASSEMBLY 1005701001-001 20317 REF: GENERIC NO REF	MOS HRS/MSC AFL					N:0 N:0 N:0 28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
570000-0102	WING REAR SPAR LINK ASSEMBLY 1005701015-001 585 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
570000-0103	WING REAR SPAR LINK ASSEMBLY 1005701015-001 586 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
570000-0104	WING REAR SPAR BOLT ASSEMBLY 1005701035-001 391 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
573101-0101	LH WINGLET STRUCTURE ASSEMBLY 1005731002-001 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
573101-0102	RH WINGLET STRUCTURE ASSEMBLY 1005731002-002 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
573101-0201	LH WING-TO-WINGLET REAR BOLT 1005731115-001 KS0256 REF: AMM 57 31 01 961 801	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0		7500
573101-0202	LH WING-TO-WINGLET REAR BOLT 1005731115-001 KS0244 REF: AMM 57 31 01 961 801	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0		7500
573101-0203	RH WING-TO-WINGLET REAR BOLT 1005731115-001 KS0230 REF: AMM 57 31 01 961 801	MOS HRS/MSC AFL	7500	N:0 N:0 N:0			28-JAN-2011 0 0		7500

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
573101-0204	RH WING-TO-WINGLET REAR BOLT 1005731115-001 KS0253	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 57 31 01 961 801	AFL	7500	N:0			0	7500	
573101-0205	LH WING-TO-WINGLET FWD BOLT 1005731115-003 KS0225	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 57 31 01 961 801	AFL	7500	N:0			0	7500	
573101-0206	LH WING-TO-WINGLET FWD BOLT 1005731115-003 KS0235	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 57 31 01 961 801	AFL	7500	N:0			0	7500	
573101-0207	RH WING-TO-WINGLET FWD BOLT 1005731115-003 KS0248	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 57 31 01 961 801	AFL	7500	N:0			0	7500	
573101-0208	RH WING-TO-WINGLET FWD BOLT 1005731115-003 KS0275	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 57 31 01 961 801	AFL	7500	N:0			0	7500	
573301-0101	LEFT WINGLET WINGTIP LENS 9EL455213-01 M50706	MOS HRS/MSC	O/C	N:0 N:0			23-DEC-2019 2630:03		
	REF: See Workcard	AFL		N:0			1481		
573301-0102	RIGHT WINGLET WINGTIP LENS 9EL455213-02 M60748	MOS HRS/MSC	O/C	N:0 N:0			23-DEC-2019 2630:03		
	REF: See Workcard	AFL		N:0			1481		
575100-0101	LEFT OUTBOARD SUPPORT-LINK ASSEMBLY OF THE FLAP 1005751392-011 DCM-68	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
575100-0102	RIGHT OUTBOARD SUPPORT-LINK ASSEMBLY OF THE FLAP 1005751392-011 DCM-66	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
575100-0103	LEFT CENTER SUPPORT-LINK ASSEMBLY OF THE FLAP 1005751391-005 D-111	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
575100-0104	RIGHT CENTER SUPPORT-LINK ASSEMBLY OF THE FLAP 1005751391-005 D-104	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
575100-0105	LEFT INBOARD SUPPORT-LINK ASSEMBLY OF THE FLAP 1005751390-007 DCM-83	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
575100-0106	RIGHT INBOARD SUPPORT-LINK ASSEMBLY OF THE FLAP 1005751390-007 DCM-84	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
575100-0201	LEFT INBOARD FLAP ASSEMBLY 1005751051-003 09CAM0127	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
575100-0202	RIGHT INBOARD FLAP ASSEMBLY 1005751051-004 09CAM0134	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		
575100-0203	LEFT OUTBOARD FLAP ASSEMBLY 1005751551-003 20317	MOS HRS/MSC	O/C	N:0 N:0			28-JAN-2011 0		
	REF: See Workcard	AFL		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
575100-0204	RIGHT OUTBOARD FLAP ASSEMBLY 1005751551-004 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0205	OUTBOARD FLAP SUPPORT CARRIAGE ASSEMBLY 1005751053-003 09CAM0142 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0206	OUTBOARD FLAP SUPPORT CARRIAGE ASSEMBLY 1005751053-004 09CAM0122 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0207	INBD LH FLAP SUPPORT ASSEMBLY 1005751065N500501 20318 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0208	INBD RH FLAP SUPPORT ASSEMBLY 1005751065N500502 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0209	MID LH FLAP SUPPORT ASSEMBLY 1005751066N500401 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0210	MID RH FLAP SUPPORT ASSEMBLY 1005751066N500402 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0211	OUTBD LH FLAP SUPPORT ASSEMBLY 1005751067N500501 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
575100-0212	OUTBD RH FLAP SUPPORT ASSEMBLY 1005751067N500502 20317 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0213	LH INBD FLAP FWD FAIRING ASSEMBLY 1005751081-005 F984432 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0214	RH INBD FLAP FWD FAIRING ASSEMBLY 1005751081-006 F931568 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0215	LH MID FLAP FWD FAIRING ASSEMBLY 1005751082-005 F931574 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0216	RH MID FLAP FWD FAIRING ASSEMBLY 1005751082-006 F931580 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0217	RH OUTBD FLAP FWD FAIRING ASSEMBLY 1005751083-006 F931588 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0218	LH INBD FLAP AFT FAIRING ASSEMBLY 1005751085-009 F980133 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0219	RH INBD FLAP AFT FAIRING ASSEMBLY 1005751085-010 F980123 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
575100-0220	LH MID FLAP AFT FAIRING ASSEMBLY 1005751086-007 F979894 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0221	RH MID FLAP AFT FAIRING ASSEMBLY 1005751086-008 F979905 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0222	LH OUTBD FLAP AFT FAIRING ASSEMBLY 1005751087-005 F979882 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0223	RH OUTBD FLAP AFT FAIRING ASSEMBLY 1005751087-006 F980108 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0224	LH OUTBD FLAP FWD FAIRING ASSEMBLY 1005751083-005 F984699 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0301	MID FLAP SUPPORT CARRIAGE ASSEMBLY 1005751052-001 10CAM0132 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0302	MID FLAP SUPPORT CARRIAGE ASSEMBLY 1005751052-002 08CAM0110 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
575100-0401	LEFT HAND FLAP OUTBOARD AFT LINK UPPER BOLT 1005751393-007 TRI0322 REF: AMM 57 51 03 961 807	MOS HRS/MSC AFL		N:0 N:0 N:0			28-JAN-2011 0 0		
LIFE LIMIT			7500					7500	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
575100-0402	RIGHT HAND FLAP OUTBOARD AFT LINK UPPER BOLT 1005751393-007 TRI0331	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 57 51 03 961 807	AFL	7500	N:0			0	7500	
575100-0403	LEFT HAND FLAP OUTBOARD AFT LINK LOWER BOLT 1005751393-009 TRI0063	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 57 51 03 961 807	AFL	7500	N:0			0	7500	
575100-0404	RIGHT HAND FLAP OUTBOARD AFT LINK LOWER BOLT 1005751393-009 TRI0061	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 57 51 03 961 807	AFL	7500	N:0			0	7500	
575100-0501	LH INBOARD FLAP AFT LINK UPPER BOLT NAS6206-30DH NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 57 51 03 961 807	AFL	7500	N:0			0	7500	
575100-0502	RH INBOARD FLAP AFT LINK UPPER BOLT NAS6206-30DH NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 57 51 03 961 807	AFL	7500	N:0			0	7500	
575100-0503	LH MID FLAP AFT LINK UPPER BOLT NAS6206-30DH NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 57 51 03 961 807	AFL	7500	N:0			0	7500	
575100-0504	RH MID FLAP AFT LINK UPPER BOLT NAS6206-30DH NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 57 51 03 961 807	AFL	7500	N:0			0	7500	
575100-0601	LH INBOARD FLAP AFT LINK LOWER BOLT NAS6206-34D NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 57 51 03 961 807	AFL	7500	N:0			0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
575100-0602	RH INBOARD FLAP AFT LINK LOWER BOLT NAS6206-34D NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 57 51 03 961 807	AFL	7500	N:0			0	7500	
575100-0603	LH MID FLAP AFT LINK LOWER BOLT NAS6206-34D NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 57 51 03 961 807	AFL	7500	N:0			0	7500	
575100-0604	RH MID FLAP AFT LINK LOWER BOLT NAS6206-34D NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 57 51 03 961 807	AFL	7500	N:0			0	7500	
575100-0701	LH INBOARD FLAP (CARRIAGE TO FLAP FITTING) BOLT NAS6309C52DH NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: GENERIC NO REF	AFL	7500	N:0			0	7500	
575100-0702	RH INBOARD FLAP (CARRIAGE TO FLAP FITTING) BOLT NAS6309C52DH NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: GENERIC NO REF	AFL	7500	N:0			0	7500	
575100-0703	LH MID FLAP (CARRIAGE TO FLAP FITTING) BOLT NAS6309C52DH NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: GENERIC NO REF	AFL	7500	N:0			0	7500	
575100-0704	RH MID FLAP (CARRIAGE TO FLAP FITTING) BOLT NAS6309C52DH NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: GENERIC NO REF	AFL	7500	N:0			0	7500	
575100-0801	LH OUTBOARD FLAP (CARRIAGE TO FLAP FITTING) BOLT NAS6310C48DH NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: GENERIC NO REF	AFL	7500	N:0			0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
575100-0802	RH OUTBOARD FLAP (CARRIAGE TO FLAP FITTING) BOLT NAS6310C48DH NON-SERIALIZED	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: GENERIC NO REF	AFL	7500	N:0			0	7500	
575103-0101	LH INBOARD FLAP SUPPORT SPIGOT 1005751419-005 BR1219	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	4832	N:0			0	4832	
575103-0102	RH INBOARD FLAP SUPPORT SPIGOT 1005751419-005 BR1214	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	4832	N:0			0	4832	
575103-0201	LH MIDDLE FLAP SUPPORT SPIGOT 1005751429-005 B1	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	4832	N:0			0	4832	
575103-0202	RH MIDDLE FLAP SUPPORT SPIGOT 1005751429-005 B5	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	4832	N:0			0	4832	
575103-0301	LH OUTBOARD FLAP SUPPORT SPIGOT 1005751439-005 D2	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	4832	N:0			0	4832	
575103-0302	RH OUTBOARD FLAP SUPPORT SPIGOT 1005751439-005 D16	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	4832	N:0			0	4832	
577100-0101	LH INBOARD GROUND SPOILER BOLT 1005771409-001 STR0021	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
577100-0102	LH OUTBOARD GROUND SPOILER BOLT 1005771409-001 STR0002	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
577100-0103	RH INBOARD GROUND SPOILER BOLT 1005771409-001 STR0015	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
577100-0104	RH OUTBOARD GROUND SPOILER BOLT 1005771409-001 STR0020	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
577200-0101	LH INBOARD M/F SPOILER ACTUATOR HINGE BOLT 1005771410-001 10CAM0033	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
577200-0102	LH OUTBOARD M/F SPOILER ACTUATOR HINGE BOLT 1005771410-001 10CAM0032	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
577200-0103	RH INBOARD M/F SPOILER ACTUATOR HINGE BOLT 1005771410-001 10CAM0025	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	
577200-0104	RH OUTBOARD M/F SPOILER ACTUATOR HINGE BOLT 1005771410-001 10CAM0027	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: See Workcard	AFL	7500	N:0			0	7500	

CHAPTER 71 POWER PLANT

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00-00-201-1 (s)	DETAILED INSPECTION NO. 1 ENGINE FAN-COWL-DOORS, ACCESS PANELS AND ATTACHED HARDWARE PKG 12	MOS HRS/MSC AFL	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 71 00 00 220 802								
71-00-00-201-2 (s)	DETAILED INSPECTION NO. 2 ENGINE FAN-COWL-DOORS, ACCESS PANELS AND ATTACHED HARDWARE PKG 12	MOS HRS/MSC AFL	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 71 00 00 220 802								
71-00-00-202-1 (s)	GENERAL VISUAL INSPECTION NO. 1 ENGINE FAN-COWL-DOOR INLET-SCOOPS AND VENTILATION GRILLS PKG 9	MOS HRS/MSC AFL	800	+40/-40			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 71 00 00 210 802								
71-00-00-202-2 (s)	GENERAL VISUAL INSPECTION NO. 2 ENGINE FAN-COWL-DOOR INLET-SCOOPS AND VENTILATION GRILLS PKG 9	MOS HRS/MSC AFL	800	+40/-40			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 71 00 00 210 802								
71-00-00-203-1 (s)	DETAILED INSPECTION NO. 1 ENGINE FAN-COWL DOOR SEALS PKG 12	MOS HRS/MSC AFL	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 71 00 00 220 803								
71-00-00-203-2 (s)	DETAILED INSPECTION NO. 2 ENGINE FAN-COWL DOOR SEALS PKG 12	MOS HRS/MSC AFL	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 71 00 00 220 803								
71-20-00-201-1 (s)	SPECIAL DETAILED INSPECTION NO. 1 ENGINE SUPPORT STRUCTURE AND BOLTS PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 71 20 00 280 801								
71-20-00-201-2 (s)	SPECIAL DETAILED INSPECTION NO. 2 ENGINE SUPPORT STRUCTURE AND BOLTS PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 71 20 00 280 801								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-20-00-203-1 (s)	DETAILED INSPECTION NO. 1 ENGINE REAR ENGINE MOUNTS, STRUTS, AND BOLTS PKG 5	MOS HRS/MSC	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 71 20 00 220 803	AFL							
71-20-00-203-2 (s)	DETAILED INSPECTION NO. 2 ENGINE REAR ENGINE MOUNTS, STRUTS, AND BOLTS PKG 5	MOS HRS/MSC	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 71 20 00 220 803	AFL							
71-21-00-102-1	SPECIAL DETAILED INSPECTION NO. 1 ENGINE FORWARD MOUNT YOKE - VERTICAL LINK PLATES AND ENGINE ATTACHMENT FITTINGS	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: See Workcard	AFL	7500				0	7500	
71-21-00-102-2	SPECIAL DETAILED INSPECTION NO. 2 ENGINE FORWARD MOUNT YOKE - VERTICAL LINK PLATES AND ENGINE ATTACHMENT FITTINGS	MOS HRS/MSC					28-JAN-2011 0		
AIRWORTHINESS	REF: See Workcard	AFL	7500				0	7500	
71-21-00-108-1	DISCARD NO. 1 ENGINE BOLTS OF THE ENGINE MOUNT FITTING, PART NO. NAS6707HU7, NON-SERIALIZED (IPC 71-21-00 FIGURE 1, ITEMS 15 &35)	MOS HRS/MSC					28-JAN-2011 0		
LIFE LIMIT	REF: AMM 71 20 01 961 804	AFL	7500				0	7500	
71-21-00-108-2	DISCARD NO. 2 ENGINE BOLTS OF THE ENGINE MOUNT FITTING, PART NO. NAS6707HU7, NON-SERIALIZED (IPC 71-21-00 FIGURE 1, ITEMS 15 &35)	MOS HRS/MSC					28-JAN-2011 0		
LIFE LIMIT	REF: AMM 71 20 01 961 804	AFL	7500				0	7500	
71-21-00-201-1 (s)	DETAILED INSPECTION NO. 1 ENGINE FORWARD ENGINE MOUNT, YOKE, LINK, FITTINGS, AND BOLTS PKG 5	MOS HRS/MSC	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 71 20 00 220 803	AFL							

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-21-00-201-2 (s)	DETAILED INSPECTION NO. 2 ENGINE FORWARD ENGINE MOUNT, YOKE, LINK, FITTINGS, AND BOLTS PKG 5	MOS HRS/MSC AFL	96	+1m/-1m			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 71 20 00 220 803								
71-22-00-102-1	SPECIAL DETAILED INSPECTION NO. 1 ENGINE AFT MOUNT LINKS	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
AIRWORTHINESS	REF: NDT ET-71-22-001								
71-22-00-102-2	SPECIAL DETAILED INSPECTION NO. 2 ENGINE AFT MOUNT LINKS	MOS HRS/MSC AFL	7500				28-JAN-2011 0 0	7500	
AIRWORTHINESS	REF: NDT ET-71-22-001								
71-60-01-201-1 (s)	GENERAL VISUAL INSPECTION NO. 1 ENGINE NACELLE INLET PKG 9	MOS HRS/MSC AFL	800	+40/-40			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 71 60 01 210 801								
71-60-01-201-2 (s)	GENERAL VISUAL INSPECTION NO. 2 ENGINE NACELLE INLET PKG 9	MOS HRS/MSC AFL	800	+40/-40			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 71 60 01 210 801								
71-60-01-202-1 (s)	DETAILED INSPECTION NO. 1 ENGINE NACELLE INLET PKG 11	MOS HRS/MSC AFL	1600	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 71 60 01 220 801								
71-60-01-202-2 (s)	DETAILED INSPECTION NO. 2 ENGINE NACELLE INLET PKG 11	MOS HRS/MSC AFL	1600	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 71 60 01 220 801								
71-60-01-203-1 (s)	GENERAL VISUAL INSPECTION NO. 1 ENGINE GENERATOR COOLING INLET PKG 9	MOS HRS/MSC AFL	800	+40/-40			PKG 23-DEC-2019 2630:03 1481		
MRB	REF: AMM 71 60 01 210 802								

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-60-01-203-2 (s)	GENERAL VISUAL INSPECTION NO. 2 ENGINE GENERATOR COOLING INLET PKG 9	MOS	800	+40/-40			PKG	23-DEC-2019	
MRB	REF: AMM 71 60 01 210 802	AFL					2630:03	1481	
71-ZL-00-202 (s)	GENERAL VISUAL INSPECTION LEFT/RIGHT NOSE COWL PKG 4	MOS	48	+1m/-1m			PKG	23-DEC-2019	
MRB	REF: See Workcard	AFL					2630:03	1481	
71-ZL-00-203 (s)	GENERAL VISUAL INSPECTION ENGINE (COWLINGS REMOVED) LH/RH PKG 4	MOS	48	+1m/-1m			PKG	23-DEC-2019	
MRB	REF: See Workcard	AFL					2630:03	1481	
71-ZL-00-301 (s)	GENERAL VISUAL INSPECTION EXTERNAL NACELLE LH/RH PKG 4	MOS	48	+1m/-1m			PKG	23-DEC-2019	
MRB	REF: See Workcard	AFL					2630:03	1481	
711005-0101	LEFT UPPER FAN COWL DOOR ASSEMBLY WBA7111E301-053 PZL281	MOS						28-JAN-2011	
	REF: See Workcard	HRS/MSC	O/C		N:0			0	
		AFL			N:0			0	
711005-0102	RIGHT UPPER FAN COWL DOOR ASSEMBLY WBA7112E301-053 PZL282	MOS						28-JAN-2011	
	REF: See Workcard	HRS/MSC	O/C		N:0			0	
		AFL			N:0			0	
711009-0101	LEFT LOWER FAN COWL DOOR ASSEMBLY WBA7113E301-059 PZL282	MOS						28-JAN-2011	
	REF: See Workcard	HRS/MSC	O/C		N:0			0	
		AFL			N:0			0	
711009-0102	RIGHT LOWER FAN COWL DOOR ASSEMBLY WBA7114E301-059 PZL284	MOS						28-JAN-2011	
	REF: See Workcard	HRS/MSC	O/C		N:0			0	
		AFL			N:0			0	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
712100-0101	LEFT YOKE ASSEMBLY WBA7121E001-049 SAM31801L REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
712100-0102	RIGHT YOKE ASSEMBLY WBA7121E001-050 SAM30401R REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
712100-0103	FORWARD MID ENGINE MOUNT WBA7121E009-047 SAM05906 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
712100-0104	FORWARD MID ENGINE MOUNT WBA7121E009-047 SAM05904 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
712100-0105	NO.1 ENGINE LOWER FORWARD ENGINE MOUNT WBA7121E011-045 SAM12006 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
712100-0106	NO.2 ENGINE LOWER FORWARD ENGINE MOUNT WBA7121E011-045 SAM12003 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
712100-0107	NO.1 ENGINE UPPER FORWARD ENGINE MOUNT WBA7121E011-045 SAM12001 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
712100-0108	NO.2 ENGINE UPPER FORWARD ENGINE MOUNT WBA7121E011-045 SAM11704 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
712100-0201	FORWARD ENGINE MOUNT FS724L LWR BOLT 1005451660-003 3092	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 71 20 01 961 805	AFL	7500	N:0			0	7500	
712100-0202	FORWARD ENGINE MOUNT FS724R LWR BOLT 1005451660-003 1047	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 71 20 01 961 805	AFL	7500	N:0			0	7500	
712100-0203	FORWARD ENGINE MOUNT FS724L UPR BOLT 1005451660-003 3159	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 71 20 01 961 805	AFL	7500	N:0			0	7500	
712100-0204	FORWARD ENGINE MOUNT FS724R UPR BOLT 1005451660-003 1048	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 71 20 01 961 805	AFL	7500	N:0			0	7500	
712100-0205	NO. 1 ENGINE - YOKE BOLT OF FWD ENGINE MOUNT FITTING, PART NO. WBA7121E014, SERIALIZED WBA7121E014-107 4563	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 71 20 01 961 803	AFL	7500	N:0			0	7500	
712100-0206	NO. 2 ENGINE - YOKE BOLT OF FWD ENGINE MOUNT FITTING, PART NO. WBA7121E014, SERIALIZED WBA7121E014-107 4560	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 71 20 01 961 803	AFL	7500	N:0			0	7500	
712100-0207	NO. 1 ENGINE - YOKE BOLTS OF FWD ENGINE MOUNT FITTING, PART NO. WBA7121E015, SERIALIZED (UPPER) WBA7121E015-109 4940	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 71 20 01 961 801	AFL	7500	N:0			0	7500	
712100-0208	NO. 1 ENGINE - YOKE BOLTS OF FWD ENGINE MOUNT FITTING, PART NO. WBA7121E015, SERIALIZED (LOWER) WBA7121E015-109 4943	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 71 20 01 961 801	AFL	7500	N:0			0	7500	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
712100-0209	NO. 2 ENGINE - YOKE BOLTS OF FWD ENGINE MOUNT FITTING, PART NO. WBA7121E015, SERIALIZED (UPPER) WBA7121E015-109 4942	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 71 20 01 961 801	AFL	7500	N:0			0	7500	
712100-0210	NO. 2 ENGINE - YOKE BOLTS OF FWD ENGINE MOUNT FITTING, PART NO. WBA7121E015, SERIALIZED (LOWER) WBA7121E015-109 4944	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 71 20 01 961 801	AFL	7500	N:0			0	7500	
712100-0211	NO. 1 ENGINE - YOKE BOLT OF FWD ENGINE MOUNT FITTING, PART NO. WBA7121E016, SERIALIZED WBA7121E016-105 3906	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 71 20 01 961 802	AFL	7500	N:0			0	7500	
712100-0212	NO. 2 ENGINE - YOKE BOLT OF FWD ENGINE MOUNT FITTING, PART NO. WBA7121E016, SERIALIZED WBA7121E016-105 3914	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 71 20 01 961 802	AFL	7500	N:0			0	7500	
712100-0213	NO. 1 ENGINE - BOLT OF THE AFT ENGINE MOUNT, PART NO. WBA7122E014, SERIALIZED (UPPER) WBA7122E014-101 4771	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 71 20 05 961 801	AFL	7500	N:0			0	7500	
712100-0214	NO. 1 ENGINE - BOLT OF THE AFT ENGINE MOUNT, PART NO. WBA7122E014, SERIALIZED (LOWER) WBA7122E014-101 4757	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 71 20 05 961 801	AFL	7500	N:0			0	7500	
712100-0215	NO. 2 ENGINE - BOLT OF THE AFT ENGINE MOUNT, PART NO. WBA7122E014, SERIALIZED (UPPER) WBA7122E014-101 4772	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 71 20 05 961 801	AFL	7500	N:0			0	7500	
712100-0216	NO. 2 ENGINE - BOLT OF THE AFT ENGINE MOUNT, PART NO. WBA7122E014, SERIALIZED (LOWER) WBA7122E014-101 4755	MOS HRS/MSC		N:0 N:0			28-JAN-2011 0		
LIFE LIMIT	REF: AMM 71 20 05 961 801	AFL	7500	N:0			0	7500	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
712100-0301	STRUT ASSEMBLY WBA7122E101-041 SAM06406 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
712100-0302	STRUT ASSEMBLY WBA7122E101-041 SAM06608 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
712100-0303	STRUT ASSEMBLY WBA7122E101-041 SAM06605 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
712100-0304	STRUT ASSEMBLY WBA7122E101-041 SAM06609 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
712100-0401	FORWARD MOUNT LINK ASSEMBLY WBA7121E006-049 SAM16508 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
712100-0402	FORWARD MOUNT LINK ASSEMBLY WBA7121E006-049 SAM16802 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
712100-0403	FORWARD MOUNT LINK ASSEMBLY WBA7121E006-049 SAM16709 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
712100-0404	FORWARD MOUNT LINK ASSEMBLY WBA7121E006-049 SAM16801 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
716001-0101	LEFT ENGINE INLET WBA7160E101-051 PZL611 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:107 O:0 N:2630:03 O:0 N:1481 O:0			23-DEC-2019 2630:03 1481		
716001-0102	RIGHT ENGINE INLET WBA7160E101-051 PZL610 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:107 O:0 N:2630:03 O:0 N:1481 O:0			23-DEC-2019 2630:03 1481		
71EN1 71.EN1	NO. 1 AS907-1-1A ENGINE 3030001-4 P118773 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			12-JAN-2011 0 0		
71EN2 71.EN2	NO. 2 AS907-1-1A ENGINE 3030001-4 P118771 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			12-JAN-2011 0 0		
ENGINE NO. 1 Model : AS907-1-1A Serial # P118773 Part # 3030001-4									
71-20-00-202 (s)	NO. 1 ENGINE - DETAILED INSPECTION ENGINE MOUNT POINTS PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
71-50-00-201 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE WIRING HARNESS PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
71-70-00-202 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE FUEL MANIFOLD SPLASH/DRIP-SHIELD PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-70-00-203 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE DRAIN SYSTEM ATTACHMENT FITTINGS PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
ENGINE NO. 2 Model : AS907-1-1A Serial # P118771 Part # 3030001-4									
71-20-00-202 (s)	NO. 2 ENGINE - DETAILED INSPECTION ENGINE MOUNT POINTS PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
71-50-00-201 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE WIRING HARNESS PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
71-70-00-202 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE FUEL MANIFOLD SPLASH/DRIP-SHIELD PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
71-70-00-203 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE DRAIN SYSTEM ATTACHMENT FITTINGS PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
CHAPTER 72	ENGINE								
+ 72-00-00-101	INSPECT SPECIFIED ENGINE COMPONENTS AT PIECE PART OPPORTUNITY REF: GENERIC NO REF	MOS HRS/MSC AFL	C/R				28-JAN-2011 0 0		
+ 72-00-00-102	DISCARD SPECIFIED ENGINE COMPONENTS AT DEFINED INTERVALS REF: GENERIC NO REF	MOS HRS/MSC AFL	C/R				28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-71-00-204-1 (s)	GENERAL VISUAL INSPECTION LEFT ENGINE REAR-MOUNT STRUT SEAL						PKG		
72.010	PKG 12	MOS					06-DEC-2018		
MRB	REF: AMM 72 71 00 210 804	HRS/MSC	2400	+40/-40			2236:21		
		AFL					1275		
72-71-00-204-2 (s)	GENERAL VISUAL INSPECTION RIGHT ENGINE REAR-MOUNT STRUT SEAL						PKG		
72.010	PKG 12	MOS					06-DEC-2018		
MRB	REF: AMM 72 71 00 210 804	HRS/MSC	2400	+40/-40			2236:21		
		AFL					1275		
720000-7101	LIST, EQUIPMENT								
	7030100-1	MOS					28-JAN-2011		
	P0633	HRS/MSC	O/C				0		
	REF:	AFL					0		
720000-7102	LIST EQUIPMENT								
	7030100-2	MOS					28-JAN-2011		
	P0634	HRS/MSC	O/C				0		
	REF:	AFL					0		
ENGINE NO. 1 Model : AS907-1-1A Serial # P118773 Part # 3030001-4									
72-00-10-907	NO. 1 ENGINE - PERFORM ENGINE HOT SECTION INSPECTION								
		MOS							
	REF: LMM 72-00-00	HRS/MSC	O/C						
		ENC							
72-00-50-907	NO. 1 ENGINE - PERFORM ENGINE CORE ZONE INSPECTION								
		MOS							
	REF:	HRS/MSC	O/C						
		ENC							
72-20-01-200	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE FAN CONTAINMENT HOUSING								
72.600	PKG 6	MOS					31-DEC-2010		
	REF:	HRS/MSC	4000	+45			0	(4000) 3988:27	4045
		ENC					0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-21-01-201 (s)	NO. 1 ENGINE - DETAILED INSPECTION ENGINE FAN BLADES PKG 8 REF: See Workcard	MOS HRS/MSC ENC	600	+40/-40			PKG 23-DEC-2019 2641:36 1492		
72-21-01-202 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE FAN INLET PKG 8 REF: See Workcard	MOS HRS/MSC ENC	600	+40/-40			PKG 23-DEC-2019 2641:36 1492		
72-21-01-203 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE FRONT FRAME ASSEMBLY PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
72-21-01-204 (s)	NO. 1 ENGINE - DETAILED INSPECTION ENGINE FAN STATOR ASSEMBLY PKG 8 REF: See Workcard	MOS HRS/MSC ENC	600	+40/-40			PKG 23-DEC-2019 2641:36 1492		
72-21-01-205 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE FAN MODULE PKG 9 REF: AMM 72 21 01 210 803	MOS HRS/MSC ENC	800	+40/-40			PKG 23-DEC-2019 2641:36 1492		
72-21-01-206 (s)	NO. 1 ENGINE - FUNCTIONAL TEST ENGINE FAN STUB SHAFT AND FAN RETENTION HARDWARE PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
72-21-01-208 (s)	NO. 1 ENGINE - DETAILED INSPECTION ENGINE FAN ROTOR ASSEMBLY PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
72-30-00-201	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION ENGINE COMPRESSOR SECTION REF: See Workcard	MOS HRS/MSC ENC	8000	+100			31-DEC-2010 0 0	(8000) 7988:27	8100



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-30-00-206 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION HP/LP BLEED AIR DUCTS PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
72-30-00-207 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE COMPRESSOR CASE PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
72-40-00-201 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE COMBUSTOR CASE PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
72-40-00-202 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION ENGINE COMBUSTOR MODULE PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
72-50-00-201 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION ENGINE HP TURBINE MODULE PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
72-50-00-205	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION ENGINE LP TURBINE MODULE MRB REF: See Workcard	MOS HRS/MSC ENC	4200	+40/-40			31-DEC-2010 0 0	(4200) 4188:27	4240
72-50-00-206 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE LP TURBINE CASE PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
72-50-00-208	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION ENGINE HP TURBINE SHROUD-SUPPORT ASSEMBLY REF: See Workcard	MOS HRS/MSC ENC	25000	+40/-40			31-DEC-2010 0 0	(25000) 24988:27	25040



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-50-00-210 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE EXIT GUIDE VANE (EGV) ASSEMBLY PKG 17	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
	REF: See Workcard								
72-50-00-211 (s)	NO. 1 ENGINE - DETAILED INSPECTION ENGINE EXIT GUIDE VANE AFT MOUNT LUGS PKG 17	MOS HRS/MSC ENC	4800	+40/-40			PKG 31-DEC-2010 0 0		
	MRB REF: AMM 72 50 00 220 801								
72-50-00-212	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION ENGINE LP TURBINE CASE	MOS HRS/MSC ENC	25000	+40/-40			31-DEC-2010 0 0	(25000) 24988:27	25040
	REF: See Workcard								
72-50-00-213 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE EXHAUST MIXER-NOZZLE AREA PKG 8	MOS HRS/MSC ENC	600	+40/-40			PKG 23-DEC-2019 2641:36 1492		
	REF: See Workcard								
72-50-00-218	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION EXIT GUIDE VANE (EGV) ASSEMBLY	MOS HRS/MSC ENC	25000	+40/-40			31-DEC-2010 0 0	(25000) 24988:27	25040
	REF: See Workcard								
72-60-00-201 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ACCESSORY GEARBOX (AGB) ASSEMBLY PKG 8	MOS HRS/MSC ENC	600	+40/-40			PKG 23-DEC-2019 2641:36 1492		
	REF: See Workcard								
72-71-00-201 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE OUTER FAN-BYPASS-DUCT AND SYSTEMS (LRU) ATTACHMENTS (EXTERIOR) PKG 17	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
	REF: See Workcard								
72-71-00-202 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE INNER FAN AND OUTER BYPASS DUCTS PKG 17	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
	REF: See Workcard								



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-71-00-203 (s)	NO. 1 ENGINE - DETAILED INSPECTION OUTER FAN-BYPASS DUCT REAR-FLANGE AND THRUST REVERSER ATTACHMENT HARDWARE						PKG		
	PKG 17	MOS						31-DEC-2010	
		HRS/MSC	4800	+40/-40				0	
MRB	REF: AMM 72 71 00 220 801	ENC						0	
72-71-00-205	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION ENGINE FAN BLADES								
		MOS						31-DEC-2010	
		HRS/MSC						0	
	REF: See Workcard	ENC	15000	+100				0	(15000) 14989 15100
72-71-00-206 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION FAN CONTAINMENT HOUSING ASSEMBLY ON THE ENGINE						PKG		
	PKG 17	MOS						31-DEC-2010	
		HRS/MSC	4800	+100				0	
	REF: See Workcard	ENC						0	
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.1 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR								
	3035602-1	MOS						31-DEC-2010	
	10-1201-00435	HRS/MSC	7525	+525/-525				0	(7525) 7513:27 8050
	REF: GENERIC NO REF	ENC						0	
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.10 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR								
	3035602-1	MOS						31-DEC-2010	
	10-150283-57603	HRS/MSC	7525	+525/-525				0	(7525) 7513:27 8050
	REF: GENERIC NO REF	ENC						0	
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.11 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR								
	3035602-1	MOS						31-DEC-2010	
	10-150283-57604	HRS/MSC	7525	+525/-525				0	(7525) 7513:27 8050
	REF: GENERIC NO REF	ENC						0	
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.12 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR								
	3035602-1	MOS						31-DEC-2010	
	10-2101-00123	HRS/MSC	7525	+525/-525				0	(7525) 7513:27 8050
	REF: GENERIC NO REF	ENC						0	
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.13 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR								
	3035602-1	MOS						31-DEC-2010	
	10-2101-00221	HRS/MSC	7525	+525/-525				0	(7525) 7513:27 8050
	REF: GENERIC NO REF	ENC						0	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.14 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00222 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.15 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00223 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.16 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00224 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.17 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00225 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.18 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00226 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.19 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00227 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.2 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-150283-56889 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.20 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00228 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.21 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00229 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.22 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00230 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.23 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00231 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.24 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00232 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.25 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00233 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.26 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00234 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.27 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00235 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.28 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00236 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.29 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00237 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.3 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-150283-56891 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.30 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00293 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.31 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00294 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.32 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00295 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.33 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00296 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.34 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00297 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.35 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00298 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.36 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00299 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.37 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00300 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.38 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00301 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.39 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00302 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.4 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-150283-56895 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.40 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00303 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.41 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00304 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.42 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00305 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.43 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00306 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.44 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00307 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.45 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00308 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.46 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00309 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.47 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00310 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.48 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00408 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.49 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00411 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.5 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-150283-56898 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-71-00-900	NO. 1 ENGINE - INSPECT NO.50 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00414 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.51 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00415 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.52 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00416 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.53 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00417 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.54 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00419 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.55 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00420 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.56 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00421 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.57 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00422 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.58 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00423 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.59 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00429 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.6 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-150283-56906 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.60 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00431 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.61 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00432 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.62 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00436 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.7 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-150283-57591 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.8 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-150283-57594 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-71-00-900	NO. 1 ENGINE - INSPECT NO.9 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-150283-57601 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
723001-0101	NO. 1 ENGINE - BALL BEARING 3033024-4 16-162255-16850 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0			10-DEC-2016 1703:13 1014		
723010-0101	NO. 1 ENGINE - COMPRESSOR ROTOR (SPACER, 2-3) ROTATING SEAL 3033069-3 08-13336-16692 REF: AMM 72 30 00 961 801	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14989	
723010-0201	NO. 1 ENGINE - COMPRESSOR STAGE 3 BLISK ASSEMBLY 3033108-8 1618244920054 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0			10-DEC-2016 1703:13 1014		
723010-0301	NO. 1 ENGINE - STAGE 1 COMPRESSOR BLISK 3033053-7 1618244919960 REF: AMM 72 30 00 961 802	MOS HRS/MSC ENC	15000	N:0 N:0			10-DEC-2016 1703:13 1014	(16014) 16003	
723010-0401	NO. 1 ENGINE - STAGE 2 COMPRESSOR BLISK 3033063-4 12-162246-03706 REF: AMM 72 30 00 961 802	MOS HRS/MSC ENC	15000	N:774:18 N:508			10-DEC-2016 1703:13 1014	(15506) 15495	
723010-0501	NO. 1 ENGINE - STAGE 4 COMPRESSOR BLISK 3033072-4 12-182449-06564 REF: AMM 72 30 00 961 802	MOS HRS/MSC ENC	15000	N:774:18 N:508			10-DEC-2016 1703:13 1014	(15506) 15495	
723010-0601	NO. 1 ENGINE - HP SHAFT 3033084-4 10-102045-00021 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14989	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723010-0701	NO. 1 ENGINE - VORTEX SPOILER ASSEMBLY 3033118-3 1016204501428	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0	(15000) 14989	
723010-0801	NO. 1 ENGINE - STAGE 3 COMPRESSOR BLISK 3033067-9 0918244900746	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 30 00 961 802	ENC	15000	N:0			0	(15000) 14989	
723010-0901	NO. 1 ENGINE - COMPRESSOR ROTOR (SPACER, 3-4) ROTATING SEAL 3033070-3 08-13336-16513	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 30 00 961 801	ENC	15000	N:0			0	(15000) 14989	
723010-1001	NO. 1 ENGINE - VORTEX SPOILER 3033074-3 1016204501428	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0	(15000) 14989	
723010-1101	NO. 1 ENGINE - VORTEX SLEEVE 3033117-2 10-2101-05713	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0	(15000) 14989	
723010-1201	NO. 1 ENGINE - ENGINE HP TURBINE FORWARD COUPLING 3033133-2 10-2101-05626	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 809	ENC	15000	N:0			0	(15000) 14989	
723010-1301	NO. 1 ENGINE - ENGINE CENTRIFUGAL COMPRESSOR IMPELLER 3033182-2 16-162246-02146	MOS HRS/MSC		N:0 N:0			10-DEC-2016 1703:13		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			1014	(16014) 16003	
723010-2000	NO. 1 ENGINE - DIFFUSER CASE 3033174-3 10-156138-02786	MOS HRS/MSC	O/C	N:0 N:0			31-DEC-2010 0		
	REF: GENERIC NO REF	ENC		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724010-0301	NO. 1 ENGINE - COMBUSTION CHAMBER CASE 3034063-3 10-150609-00024 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
724010-0401	NO. 1 ENGINE - COMBUSTION CHAMBER ASSEMBLY 3034088-5 16-3300-05222 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0			10-DEC-2016 1703:13 1014		
725101-0101	NO. 1 ENGINE - HPT-STAGE 1 SEAL ASSEMBLY 3035092-3 10-162246-01067 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
725101-0201	NO. 1 ENGINE - HPT-STAGE 2 SEAL ASSEMBLY 3035093-3 16-162246-00825 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0			10-DEC-2016 1703:13 1014		
725101-0301	NO. 1 ENGINE - HPT-STAGE 2 ROTOR ASSEMBLY 3035135-5 1016224604672 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
725101-0401	NO. 1 ENGINE - HPT-STAGE 1 ROTOR ASSEMBLY 3035137-4 1016224603269 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
725101-0501	NO. 1 ENGINE - HPT STAGE 1 SEAL PLATE (DRIVE ARM) COUPLER 3035030-3 09-162246-01903 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14989	
725101-0601	NO. 1 ENGINE - STAGE 1 HP TURBINE SEAL PLATE 3035124-1 10-162246-01067 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14989	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725101-0701	NO. 1 ENGINE - HPT STAGE 2 COUPLER 3035053-2 SN10P28769	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0	(15000) 14989	
725101-0801	NO. 1 ENGINE - STAGE 2 HP TURBINE SEAL PLATE 3035109-1 1016224602026	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0	(15000) 14989	
725103-0101	NO. 1 ENGINE - NO.1 HPT 1 STAGE BLADE 3035114-6 10M10983	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0102	NO. 1 ENGINE - NO.2 HPT 1 STAGE BLADE 3035114-6 10M18768	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0103	NO. 1 ENGINE - NO.3 HPT 1 STAGE BLADE 3035114-6 10M18924	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0104	NO. 1 ENGINE - NO.4 HPT 1 STAGE BLADE 3035114-6 10M18948	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0105	NO. 1 ENGINE - NO.5 HPT 1 STAGE BLADE 3035114-6 10M18951	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0106	NO. 1 ENGINE - NO.6 HPT 1 STAGE BLADE 3035114-6 10M18956	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725103-0107	NO. 1 ENGINE - NO.7 HPT 1 STAGE BLADE 3035114-6 10M18958	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0108	NO. 1 ENGINE - NO.8 HPT 1 STAGE BLADE 3035114-6 10M18960	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0109	NO. 1 ENGINE - NO.9 HPT 1 STAGE BLADE 3035114-6 10M18970	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0110	NO. 1 ENGINE - NO.10 HPT 1 STAGE BLADE 3035114-6 10M18971	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0111	NO. 1 ENGINE - NO.11 HPT 1 STAGE BLADE 3035114-6 10M18973	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0112	NO. 1 ENGINE - NO.12 HPT 1 STAGE BLADE 3035114-6 10M18976	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0113	NO. 1 ENGINE - NO.13 HPT 1 STAGE BLADE 3035114-6 10M18978	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0114	NO. 1 ENGINE - NO.14 HPT 1 STAGE BLADE 3035114-6 10M18988	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725103-0115	NO. 1 ENGINE - NO.15 HPT 1 STAGE BLADE								
	3035114-6	MOS		N:0			31-DEC-2010		
	10M19006	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0		
725103-0116	NO. 1 ENGINE - NO.16 HPT 1 STAGE BLADE								
	3035114-6	MOS		N:0			31-DEC-2010		
	10M19026	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0		
725103-0117	NO. 1 ENGINE - NO.17 HPT 1 STAGE BLADE								
	3035114-6	MOS		N:0			31-DEC-2010		
	10M19027	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0		
725103-0118	NO. 1 ENGINE - NO.18 HPT 1 STAGE BLADE								
	3035114-6	MOS		N:0			31-DEC-2010		
	10M19030	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0		
725103-0119	NO. 1 ENGINE - NO.19 HPT 1 STAGE BLADE								
	3035114-6	MOS		N:0			31-DEC-2010		
	10M19031	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0		
725103-0120	NO. 1 ENGINE - NO.20 HPT 1 STAGE BLADE								
	3035114-6	MOS		N:0			31-DEC-2010		
	10M19032	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0		
725103-0121	NO. 1 ENGINE - NO.21 HPT 1 STAGE BLADE								
	3035114-6	MOS		N:0			31-DEC-2010		
	10M19033	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0		
725103-0122	NO. 1 ENGINE - NO.22 HPT 1 STAGE BLADE								
	3035114-6	MOS		N:0			31-DEC-2010		
	10M19034	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725103-0123	NO. 1 ENGINE - NO.23 HPT 1 STAGE BLADE 3035114-6 10M19035	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0124	NO. 1 ENGINE - NO.24 HPT 1 STAGE BLADE 3035114-6 10M19038	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0125	NO. 1 ENGINE - NO.25 HPT 1 STAGE BLADE 3035114-6 10M19039	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0126	NO. 1 ENGINE - NO.26 HPT 1 STAGE BLADE 3035114-6 10M19054	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0127	NO. 1 ENGINE - NO.27 HPT 1 STAGE BLADE 3035114-6 10M19072	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0128	NO. 1 ENGINE - NO.28 HPT 1 STAGE BLADE 3035114-6 10M19082	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0129	NO. 1 ENGINE - NO.29 HPT 1 STAGE BLADE 3035114-6 10M19083	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0130	NO. 1 ENGINE - NO.30 HPT 1 STAGE BLADE 3035114-6 10M19766	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725103-0131	NO. 1 ENGINE - NO.31 HPT 1 STAGE BLADE 3035114-6 10M19767	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0132	NO. 1 ENGINE - NO.32 HPT 1 STAGE BLADE 3035114-6 10M19772	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0133	NO. 1 ENGINE - NO.33 HPT 1 STAGE BLADE 3035114-6 10M19773	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0134	NO. 1 ENGINE - NO.34 HPT 1 STAGE BLADE 3035114-6 10M19774	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0135	NO. 1 ENGINE - NO.35 HPT 1 STAGE BLADE 3035114-6 10M19776	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0136	NO. 1 ENGINE - NO.36 HPT 1 STAGE BLADE 3035114-6 10M22118	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0137	NO. 1 ENGINE - NO.37 HPT 1 STAGE BLADE 3035114-6 10M22177	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0138	NO. 1 ENGINE - NO.38 HPT 1 STAGE BLADE 3035114-6 10M22200	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725103-0201	NO. 1 ENGINE - NO.1 HPT 2 STAGE BLADE 3035049-5 10M42950	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0202	NO. 1 ENGINE - NO.2 HPT 2 STAGE BLADE 3035049-5 10M42951	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0203	NO. 1 ENGINE - NO.3 HPT 2 STAGE BLADE 3035049-5 10M42953	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0204	NO. 1 ENGINE - NO.4 HPT 2 STAGE BLADE 3035049-5 10M42954	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0205	NO. 1 ENGINE - NO.5 HPT 2 STAGE BLADE 3035049-5 10M42957	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0206	NO. 1 ENGINE - NO.6 HPT 2 STAGE BLADE 3035049-5 10M42959	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0207	NO. 1 ENGINE - NO.7 HPT 2 STAGE BLADE 3035049-5 10M42960	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0208	NO. 1 ENGINE - NO.8 HPT 2 STAGE BLADE 3035049-5 10M42964	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725103-0209	NO. 1 ENGINE - NO.9 HPT 2 STAGE BLADE 3035049-5 10M42967	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0210	NO. 1 ENGINE - NO.10 HPT 2 STAGE BLADE 3035049-5 10M43128	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0211	NO. 1 ENGINE - NO.11 HPT 2 STAGE BLADE 3035049-5 10M43129	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0212	NO. 1 ENGINE - NO.12 HPT 2 STAGE BLADE 3035049-5 10M43132	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0213	NO. 1 ENGINE - NO.13 HPT 2 STAGE BLADE 3035049-5 10M43133	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0214	NO. 1 ENGINE - NO.14 HPT 2 STAGE BLADE 3035049-5 10M43135	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0215	NO. 1 ENGINE - NO.15 HPT 2 STAGE BLADE 3035049-5 10M43136	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0216	NO. 1 ENGINE - NO.16 HPT 2 STAGE BLADE 3035049-5 10M43137	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725103-0217	NO. 1 ENGINE - NO.17 HPT 2 STAGE BLADE 3035049-5 10M43138	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0218	NO. 1 ENGINE - NO.18 HPT 2 STAGE BLADE 3035049-5 10M43139	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0219	NO. 1 ENGINE - NO.19 HPT 2 STAGE BLADE 3035049-5 10M43140	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0220	NO. 1 ENGINE - NO.20 HPT 2 STAGE BLADE 3035049-5 10M43141	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0221	NO. 1 ENGINE - NO.21 HPT 2 STAGE BLADE 3035049-5 10M43142	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0222	NO. 1 ENGINE - NO.22 HPT 2 STAGE BLADE 3035049-5 10M43143	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0223	NO. 1 ENGINE - NO.23 HPT 2 STAGE BLADE 3035049-5 10M43148	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0224	NO. 1 ENGINE - NO.24 HPT 2 STAGE BLADE 3035049-5 10M43149	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725103-0225	NO. 1 ENGINE - NO.25 HPT 2 STAGE BLADE 3035049-5 10M43152	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0226	NO. 1 ENGINE - NO.26 HPT 2 STAGE BLADE 3035049-5 10M47312	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0227	NO. 1 ENGINE - NO.27 HPT 2 STAGE BLADE 3035049-5 10M47315	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0228	NO. 1 ENGINE - NO.28 HPT 2 STAGE BLADE 3035049-5 10M47316	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0229	NO. 1 ENGINE - NO.29 HPT 2 STAGE BLADE 3035049-5 10M47325	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0230	NO. 1 ENGINE - NO.30 HPT 2 STAGE BLADE 3035049-5 10M47344	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0231	NO. 1 ENGINE - NO.31 HPT 2 STAGE BLADE 3035049-5 10M47348	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0232	NO. 1 ENGINE - NO.32 HPT 2 STAGE BLADE 3035049-5 10M47349	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725103-0233	NO. 1 ENGINE - NO.33 HPT 2 STAGE BLADE 3035049-5 10M47356	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0		
725103-0234	NO. 1 ENGINE - NO.34 HPT 2 STAGE BLADE 3035049-5 10M50760	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0		
725103-0301	NO. 1 ENGINE - STAGE 2 HP TURBINE DISK 3035123-1 1016224604672	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14989	
LIFE LIMIT	REF: AMM 72 50 00 961 801	ENC		N:0			0		
725103-0401	NO. 1 ENGINE - ENGINE HP TURBINE INTERSTAGE ROTATING SEAL 3035134-1 0916204501344	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14989	
LIFE LIMIT	REF: AMM 72 50 00 961 804	ENC		N:0			0		
725103-0501	NO. 1 ENGINE - STAGE 1 HP TURBINE DISK 3035136-2 1016224603269	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14989	
LIFE LIMIT	REF: AMM 72 50 00 961 801	ENC		N:0			0		
725104-7101	NO. 1 ENGINE - HPT NOZZLE SUPPORT 3035056-5 SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725502-0101	NO. 1 ENGINE - LPT-STAGE 2 ROTOR ASSEMBLY 3035660-1 1016224604924	MOS HRS/MSC	O/C	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725502-0201	NO. 1 ENGINE - LPT-STAGE 3 ROTOR ASSEMBLY 3035662-1 1016224604639	MOS HRS/MSC	O/C	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725502-0301	NO. 1 ENGINE - LPT-STAGE 1 ROTOR ASSEMBLY 3035692-1 1016224604740 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
725502-0401	NO. 1 ENGINE - LPT1 NOZZLE ASSEMBLY 3035658-9 08-14995-00445 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
725502-0501	NO. 1 ENGINE - ENGINE LP TURBINE INTERSTAGE ROTATING SEAL 3035595-1 10-162246-03719 REF: AMM 72 50 00 961 806	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14989	
725502-0601	NO. 1 ENGINE - ENGINE LP TURBINE DRIVE ARM 3035610-2 09-162246-01636 REF: AMM 72 50 00 961 808	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14989	
725502-0701	NO. 1 ENGINE - LPT STUB SHAFT 3035691-1 10-162684-07083 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14989	
725502-0801	NO. 1 ENGINE - LPT SHAFT 3035689-1 09-169163-00819 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14989	
725503-0101	NO. 1 ENGINE - NO.1 LPT 2 STAGE BLADE 3035602-1 10-1201-00435 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14988:27	
725503-0102	NO. 1 ENGINE - NO.2 LPT 2 STAGE BLADE 3035602-1 10-150283-56889 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0103	NO. 1 ENGINE - NO.3 LPT 2 STAGE BLADE 3035602-1 10-150283-56891	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0104	NO. 1 ENGINE - NO.4 LPT 2 STAGE BLADE 3035602-1 10-150283-56895	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0105	NO. 1 ENGINE - NO.5 LPT 2 STAGE BLADE 3035602-1 10-150283-56898	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0106	NO. 1 ENGINE - NO.6 LPT 2 STAGE BLADE 3035602-1 10-150283-56906	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0107	NO. 1 ENGINE - NO.7 LPT 2 STAGE BLADE 3035602-1 10-150283-57591	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0108	NO. 1 ENGINE - NO.8 LPT 2 STAGE BLADE 3035602-1 10-150283-57594	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0109	NO. 1 ENGINE - NO.9 LPT 2 STAGE BLADE 3035602-1 10-150283-57601	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0110	NO. 1 ENGINE - NO.10 LPT 2 STAGE BLADE 3035602-1 10-150283-57603	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0111	NO. 1 ENGINE - NO.11 LPT 2 STAGE BLADE 3035602-1 10-150283-57604	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0112	NO. 1 ENGINE - NO.12 LPT 2 STAGE BLADE 3035602-1 10-2101-00123	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0113	NO. 1 ENGINE - NO.13 LPT 2 STAGE BLADE 3035602-1 10-2101-00221	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0114	NO. 1 ENGINE - NO.14 LPT 2 STAGE BLADE 3035602-1 10-2101-00222	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0115	NO. 1 ENGINE - NO.15 LPT 2 STAGE BLADE 3035602-1 10-2101-00223	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0116	NO. 1 ENGINE - NO.16 LPT 2 STAGE BLADE 3035602-1 10-2101-00224	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0117	NO. 1 ENGINE - NO.17 LPT 2 STAGE BLADE 3035602-1 10-2101-00225	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0118	NO. 1 ENGINE - NO.18 LPT 2 STAGE BLADE 3035602-1 10-2101-00226	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0119	NO. 1 ENGINE - NO.19 LPT 2 STAGE BLADE 3035602-1 10-2101-00227	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0120	NO. 1 ENGINE - NO.20 LPT 2 STAGE BLADE 3035602-1 10-2101-00228	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0121	NO. 1 ENGINE - NO.21 LPT 2 STAGE BLADE 3035602-1 10-2101-00229	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0122	NO. 1 ENGINE - NO.22 LPT 2 STAGE BLADE 3035602-1 10-2101-00230	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0123	NO. 1 ENGINE - NO.23 LPT 2 STAGE BLADE 3035602-1 10-2101-00231	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0124	NO. 1 ENGINE - NO.24 LPT 2 STAGE BLADE 3035602-1 10-2101-00232	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0125	NO. 1 ENGINE - NO.25 LPT 2 STAGE BLADE 3035602-1 10-2101-00233	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0126	NO. 1 ENGINE - NO.26 LPT 2 STAGE BLADE 3035602-1 10-2101-00234	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0127	NO. 1 ENGINE - NO.27 LPT 2 STAGE BLADE 3035602-1 10-2101-00235	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0128	NO. 1 ENGINE - NO.28 LPT 2 STAGE BLADE 3035602-1 10-2101-00236	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0129	NO. 1 ENGINE - NO.29 LPT 2 STAGE BLADE 3035602-1 10-2101-00237	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0130	NO. 1 ENGINE - NO.30 LPT 2 STAGE BLADE 3035602-1 10-2101-00293	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0131	NO. 1 ENGINE - NO.31 LPT 2 STAGE BLADE 3035602-1 10-2101-00294	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0132	NO. 1 ENGINE - NO.32 LPT 2 STAGE BLADE 3035602-1 10-2101-00295	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0133	NO. 1 ENGINE - NO.33 LPT 2 STAGE BLADE 3035602-1 10-2101-00296	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0134	NO. 1 ENGINE - NO.34 LPT 2 STAGE BLADE 3035602-1 10-2101-00297	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0135	NO. 1 ENGINE - NO.35 LPT 2 STAGE BLADE 3035602-1 10-2101-00298	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0136	NO. 1 ENGINE - NO.36 LPT 2 STAGE BLADE 3035602-1 10-2101-00299	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0137	NO. 1 ENGINE - NO.37 LPT 2 STAGE BLADE 3035602-1 10-2101-00300	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0138	NO. 1 ENGINE - NO.38 LPT 2 STAGE BLADE 3035602-1 10-2101-00301	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0139	NO. 1 ENGINE - NO.39 LPT 2 STAGE BLADE 3035602-1 10-2101-00302	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0140	NO. 1 ENGINE - NO.40 LPT 2 STAGE BLADE 3035602-1 10-2101-00303	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0141	NO. 1 ENGINE - NO.41 LPT 2 STAGE BLADE 3035602-1 10-2101-00304	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0142	NO. 1 ENGINE - NO.42 LPT 2 STAGE BLADE 3035602-1 10-2101-00305	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0143	NO. 1 ENGINE - NO.43 LPT 2 STAGE BLADE 3035602-1 10-2101-00306	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0144	NO. 1 ENGINE - NO.44 LPT 2 STAGE BLADE 3035602-1 10-2101-00307	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0145	NO. 1 ENGINE - NO.45 LPT 2 STAGE BLADE 3035602-1 10-2101-00308	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0146	NO. 1 ENGINE - NO.46 LPT 2 STAGE BLADE 3035602-1 10-2101-00309	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0147	NO. 1 ENGINE - NO.47 LPT 2 STAGE BLADE 3035602-1 10-2101-00310	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0148	NO. 1 ENGINE - NO.48 LPT 2 STAGE BLADE 3035602-1 10-2101-00408	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0149	NO. 1 ENGINE - NO.49 LPT 2 STAGE BLADE 3035602-1 10-2101-00411	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0150	NO. 1 ENGINE - NO.50 LPT 2 STAGE BLADE 3035602-1 10-2101-00414	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0151	NO. 1 ENGINE - NO.51 LPT 2 STAGE BLADE 3035602-1 10-2101-00415	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0152	NO. 1 ENGINE - NO.52 LPT 2 STAGE BLADE 3035602-1 10-2101-00416	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0153	NO. 1 ENGINE - NO.53 LPT 2 STAGE BLADE 3035602-1 10-2101-00417	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0154	NO. 1 ENGINE - NO.54 LPT 2 STAGE BLADE 3035602-1 10-2101-00419	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0155	NO. 1 ENGINE - NO.55 LPT 2 STAGE BLADE 3035602-1 10-2101-00420	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0156	NO. 1 ENGINE - NO.56 LPT 2 STAGE BLADE 3035602-1 10-2101-00421	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0157	NO. 1 ENGINE - NO.57 LPT 2 STAGE BLADE 3035602-1 10-2101-00422	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0158	NO. 1 ENGINE - NO.58 LPT 2 STAGE BLADE 3035602-1 10-2101-00423	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0159	NO. 1 ENGINE - NO.59 LPT 2 STAGE BLADE 3035602-1 10-2101-00429	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0160	NO. 1 ENGINE - NO.60 LPT 2 STAGE BLADE 3035602-1 10-2101-00431	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0161	NO. 1 ENGINE - NO.61 LPT 2 STAGE BLADE 3035602-1 10-2101-00432	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0162	NO. 1 ENGINE - NO.62 LPT 2 STAGE BLADE 3035602-1 10-2101-00436	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0201	NO. 1 ENGINE - NO.1 LPT 3 STAGE BLADE 3035609-1 10-2101-01130	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0202	NO. 1 ENGINE - NO.2 LPT 3 STAGE BLADE 3035609-1 10-2101-01142	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0203	NO. 1 ENGINE - NO.3 LPT 3 STAGE BLADE 3035609-1 10-2101-01144	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0204	NO. 1 ENGINE - NO.4 LPT 3 STAGE BLADE 3035609-1 10-2101-01146	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0205	NO. 1 ENGINE - NO.5 LPT 3 STAGE BLADE 3035609-1 10-2101-01147	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0206	NO. 1 ENGINE - NO.6 LPT 3 STAGE BLADE 3035609-1 10-2101-01149	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0207	NO. 1 ENGINE - NO.7 LPT 3 STAGE BLADE 3035609-1 10-2101-01152	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0208	NO. 1 ENGINE - NO.8 LPT 3 STAGE BLADE 3035609-1 10-2101-01157	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0209	NO. 1 ENGINE - NO.9 LPT 3 STAGE BLADE 3035609-1 10-2101-01158	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0210	NO. 1 ENGINE - NO.10 LPT 3 STAGE BLADE 3035609-1 10-2101-01161	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0211	NO. 1 ENGINE - NO.11 LPT 3 STAGE BLADE 3035609-1 10-2101-01162	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0212	NO. 1 ENGINE - NO.12 LPT 3 STAGE BLADE 3035609-1 10-2101-01163	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0213	NO. 1 ENGINE - NO.13 LPT 3 STAGE BLADE 3035609-1 10-2101-01164	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0214	NO. 1 ENGINE - NO.14 LPT 3 STAGE BLADE 3035609-1 10-2101-01165	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0215	NO. 1 ENGINE - NO.15 LPT 3 STAGE BLADE 3035609-1 10-2101-01166	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0216	NO. 1 ENGINE - NO.16 LPT 3 STAGE BLADE 3035609-1 10-2101-01167	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0217	NO. 1 ENGINE - NO.17 LPT 3 STAGE BLADE 3035609-1 10-2101-01168	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0218	NO. 1 ENGINE - NO.18 LPT 3 STAGE BLADE 3035609-1 10-2101-01169	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0219	NO. 1 ENGINE - NO.19 LPT 3 STAGE BLADE 3035609-1 10-2101-01170	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0220	NO. 1 ENGINE - NO.20 LPT 3 STAGE BLADE 3035609-1 10-2101-01171	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0221	NO. 1 ENGINE - NO.21 LPT 3 STAGE BLADE 3035609-1 10-2101-01172	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0222	NO. 1 ENGINE - NO.22 LPT 3 STAGE BLADE 3035609-1 10-2101-01173	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0223	NO. 1 ENGINE - NO.23 LPT 3 STAGE BLADE 3035609-1 10-2101-01174	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0224	NO. 1 ENGINE - NO.24 LPT 3 STAGE BLADE 3035609-1 10-2101-01175	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0225	NO. 1 ENGINE - NO.25 LPT 3 STAGE BLADE 3035609-1 10-2101-01176	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0226	NO. 1 ENGINE - NO.26 LPT 3 STAGE BLADE 3035609-1 10-2101-01177	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0227	NO. 1 ENGINE - NO.27 LPT 3 STAGE BLADE 3035609-1 10-2101-01178	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0228	NO. 1 ENGINE - NO.28 LPT 3 STAGE BLADE 3035609-1 10-2101-01179	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0229	NO. 1 ENGINE - NO.29 LPT 3 STAGE BLADE 3035609-1 10-2101-01180	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0230	NO. 1 ENGINE - NO.30 LPT 3 STAGE BLADE 3035609-1 10-2101-01182	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0231	NO. 1 ENGINE - NO.31 LPT 3 STAGE BLADE 3035609-1 10-2101-01184	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0232	NO. 1 ENGINE - NO.32 LPT 3 STAGE BLADE 3035609-1 10-2101-01185	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0233	NO. 1 ENGINE - NO.33 LPT 3 STAGE BLADE 3035609-1 10-2101-01186	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0234	NO. 1 ENGINE - NO.34 LPT 3 STAGE BLADE 3035609-1 10-2101-01187	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0235	NO. 1 ENGINE - NO.35 LPT 3 STAGE BLADE 3035609-1 10-2101-01188	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0236	NO. 1 ENGINE - NO.36 LPT 3 STAGE BLADE 3035609-1 10-2101-01189	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0237	NO. 1 ENGINE - NO.37 LPT 3 STAGE BLADE 3035609-1 10-2101-01191	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0238	NO. 1 ENGINE - NO.38 LPT 3 STAGE BLADE 3035609-1 10-2101-01192	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0239	NO. 1 ENGINE - NO.39 LPT 3 STAGE BLADE 3035609-1 10-2101-01193	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0240	NO. 1 ENGINE - NO.40 LPT 3 STAGE BLADE 3035609-1 10-2101-01194	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0241	NO. 1 ENGINE - NO.41 LPT 3 STAGE BLADE 3035609-1 10-2101-01195	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0242	NO. 1 ENGINE - NO.42 LPT 3 STAGE BLADE 3035609-1 10-2101-01197	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0243	NO. 1 ENGINE - NO.43 LPT 3 STAGE BLADE 3035609-1 10-2101-01198	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0244	NO. 1 ENGINE - NO.44 LPT 3 STAGE BLADE 3035609-1 10-2101-01199	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0245	NO. 1 ENGINE - NO.45 LPT 3 STAGE BLADE 3035609-1	MOS		N:0			31-DEC-2010		
	10-2101-01200	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0246	NO. 1 ENGINE - NO.46 LPT 3 STAGE BLADE 3035609-1	MOS		N:0			31-DEC-2010		
	10-2101-01201	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0247	NO. 1 ENGINE - NO.47 LPT 3 STAGE BLADE 3035609-1	MOS		N:0			31-DEC-2010		
	10-2101-01202	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0248	NO. 1 ENGINE - NO.48 LPT 3 STAGE BLADE 3035609-1	MOS		N:0			31-DEC-2010		
	10-2101-01203	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0249	NO. 1 ENGINE - NO.49 LPT 3 STAGE BLADE 3035609-1	MOS		N:0			31-DEC-2010		
	10-2101-01204	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0250	NO. 1 ENGINE - NO.50 LPT 3 STAGE BLADE 3035609-1	MOS		N:0			31-DEC-2010		
	10-2101-01205	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0251	NO. 1 ENGINE - NO.51 LPT 3 STAGE BLADE 3035609-1	MOS		N:0			31-DEC-2010		
	10-2101-01206	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0252	NO. 1 ENGINE - NO.52 LPT 3 STAGE BLADE 3035609-1	MOS		N:0			31-DEC-2010		
	10-2101-01207	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0253	NO. 1 ENGINE - NO.53 LPT 3 STAGE BLADE 3035609-1 10-2101-01208	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0254	NO. 1 ENGINE - NO.54 LPT 3 STAGE BLADE 3035609-1 10-2101-01209	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0255	NO. 1 ENGINE - NO.55 LPT 3 STAGE BLADE 3035609-1 10-2101-01210	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0256	NO. 1 ENGINE - NO.56 LPT 3 STAGE BLADE 3035609-1 10-2101-01211	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0257	NO. 1 ENGINE - NO.57 LPT 3 STAGE BLADE 3035609-1 10-2101-01212	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0258	NO. 1 ENGINE - NO.58 LPT 3 STAGE BLADE 3035609-1 10-2101-01213	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0259	NO. 1 ENGINE - NO.59 LPT 3 STAGE BLADE 3035609-1 10-2101-01214	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0260	NO. 1 ENGINE - NO.60 LPT 3 STAGE BLADE 3035609-1 10-2101-01215	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0261	NO. 1 ENGINE - NO.61 LPT 3 STAGE BLADE								
	3035609-1	MOS		N:0			31-DEC-2010		
	10-2101-01216	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0262	NO. 1 ENGINE - NO.62 LPT 3 STAGE BLADE								
	3035609-1	MOS		N:0			31-DEC-2010		
	10-2101-01217	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0263	NO. 1 ENGINE - NO.63 LPT 3 STAGE BLADE								
	3035609-1	MOS		N:0			31-DEC-2010		
	10-2101-01221	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0264	NO. 1 ENGINE - NO.64 LPT 3 STAGE BLADE								
	3035609-1	MOS		N:0			31-DEC-2010		
	10-2101-01222	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0265	NO. 1 ENGINE - NO.65 LPT 3 STAGE BLADE								
	3035609-1	MOS		N:0			31-DEC-2010		
	10-2101-01223	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0266	NO. 1 ENGINE - NO.66 LPT 3 STAGE BLADE								
	3035609-1	MOS		N:0			31-DEC-2010		
	10-2101-01224	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0267	NO. 1 ENGINE - NO.67 LPT 3 STAGE BLADE								
	3035609-1	MOS		N:0			31-DEC-2010		
	10-2101-01225	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0268	NO. 1 ENGINE - NO.68 LPT 3 STAGE BLADE								
	3035609-1	MOS		N:0			31-DEC-2010		
	10-2101-01226	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0269	NO. 1 ENGINE - NO.69 LPT 3 STAGE BLADE 3035609-1 10-2101-01230	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0270	NO. 1 ENGINE - NO.70 LPT 3 STAGE BLADE 3035609-1 10-2101-01233	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0271	NO. 1 ENGINE - NO.71 LPT 3 STAGE BLADE 3035609-1 10-2101-01235	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0272	NO. 1 ENGINE - NO.72 LPT 3 STAGE BLADE 3035609-1 10-2101-01236	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0273	NO. 1 ENGINE - NO.73 LPT 3 STAGE BLADE 3035609-1 10-2101-01493	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0274	NO. 1 ENGINE - NO.74 LPT 3 STAGE BLADE 3035609-1 10-2101-01496	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0301	NO. 1 ENGINE - NO.1 LPT 1 STAGE BLADE 3035693-1 10-150283-54078	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0302	NO. 1 ENGINE - NO.2 LPT 1 STAGE BLADE 3035693-1 10-150283-54081	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0303	NO. 1 ENGINE - NO.3 LPT 1 STAGE BLADE 3035693-1 10-150283-54086	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0304	NO. 1 ENGINE - NO.4 LPT 1 STAGE BLADE 3035693-1 10-150283-54087	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0305	NO. 1 ENGINE - NO.5 LPT 1 STAGE BLADE 3035693-1 10-150283-54099	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0306	NO. 1 ENGINE - NO.6 LPT 1 STAGE BLADE 3035693-1 10-150283-54102	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0307	NO. 1 ENGINE - NO.7 LPT 1 STAGE BLADE 3035693-1 10-150283-54104	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0308	NO. 1 ENGINE - NO.8 LPT 1 STAGE BLADE 3035693-1 10-150283-54120	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0309	NO. 1 ENGINE - NO.9 LPT 1 STAGE BLADE 3035693-1 10-150283-54160	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0310	NO. 1 ENGINE - NO.10 LPT 1 STAGE BLADE 3035693-1 10-150283-54173	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0311	NO. 1 ENGINE - NO.11 LPT 1 STAGE BLADE 3035693-1 10-150283-54179	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0312	NO. 1 ENGINE - NO.12 LPT 1 STAGE BLADE 3035693-1 10-150283-54184	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0313	NO. 1 ENGINE - NO.13 LPT 1 STAGE BLADE 3035693-1 10-150283-54192	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0314	NO. 1 ENGINE - NO.14 LPT 1 STAGE BLADE 3035693-1 10-150283-54197	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0315	NO. 1 ENGINE - NO.15 LPT 1 STAGE BLADE 3035693-1 10-150283-54199	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0316	NO. 1 ENGINE - NO.16 LPT 1 STAGE BLADE 3035693-1 10-150283-54204	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0317	NO. 1 ENGINE - NO.17 LPT 1 STAGE BLADE 3035693-1 10-150283-54569	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0318	NO. 1 ENGINE - NO.18 LPT 1 STAGE BLADE 3035693-1 10-150283-54579	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0319	NO. 1 ENGINE - NO.19 LPT 1 STAGE BLADE 3035693-1 10-150283-54580	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0320	NO. 1 ENGINE - NO.20 LPT 1 STAGE BLADE 3035693-1 10-150283-54582	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0321	NO. 1 ENGINE - NO.21 LPT 1 STAGE BLADE 3035693-1 10-150283-54583	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0322	NO. 1 ENGINE - NO.22 LPT 1 STAGE BLADE 3035693-1 10-150283-54584	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0323	NO. 1 ENGINE - NO.23 LPT 1 STAGE BLADE 3035693-1 10-150283-54587	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0324	NO. 1 ENGINE - NO.24 LPT 1 STAGE BLADE 3035693-1 10-150283-54589	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0325	NO. 1 ENGINE - NO.25 LPT 1 STAGE BLADE 3035693-1 10-150283-54590	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0326	NO. 1 ENGINE - NO.26 LPT 1 STAGE BLADE 3035693-1 10-150283-54591	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0327	NO. 1 ENGINE - NO.27 LPT 1 STAGE BLADE 3035693-1 10-150283-54592	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0328	NO. 1 ENGINE - NO.28 LPT 1 STAGE BLADE 3035693-1 10-150283-54593	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0329	NO. 1 ENGINE - NO.29 LPT 1 STAGE BLADE 3035693-1 10-150283-54594	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0330	NO. 1 ENGINE - NO.30 LPT 1 STAGE BLADE 3035693-1 10-150283-54595	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0331	NO. 1 ENGINE - NO.31 LPT 1 STAGE BLADE 3035693-1 10-150283-54596	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0332	NO. 1 ENGINE - NO.32 LPT 1 STAGE BLADE 3035693-1 10-150283-54597	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0333	NO. 1 ENGINE - NO.33 LPT 1 STAGE BLADE 3035693-1 10-150283-54598	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0334	NO. 1 ENGINE - NO.34 LPT 1 STAGE BLADE 3035693-1 10-150283-54599	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0335	NO. 1 ENGINE - NO.35 LPT 1 STAGE BLADE 3035693-1 10-150283-54600	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0336	NO. 1 ENGINE - NO.36 LPT 1 STAGE BLADE 3035693-1 10-150283-54601	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0337	NO. 1 ENGINE - NO.37 LPT 1 STAGE BLADE 3035693-1 10-150283-54602	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0338	NO. 1 ENGINE - NO.38 LPT 1 STAGE BLADE 3035693-1 10-150283-54603	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0339	NO. 1 ENGINE - NO.39 LPT 1 STAGE BLADE 3035693-1 10-150283-54604	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0340	NO. 1 ENGINE - NO.40 LPT 1 STAGE BLADE 3035693-1 10-150283-54605	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0341	NO. 1 ENGINE - NO.41 LPT 1 STAGE BLADE 3035693-1 10-150283-54606	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0342	NO. 1 ENGINE - NO.42 LPT 1 STAGE BLADE 3035693-1 10-150283-54607	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0343	NO. 1 ENGINE - NO.43 LPT 1 STAGE BLADE 3035693-1 10-150283-54608	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0344	NO. 1 ENGINE - NO.44 LPT 1 STAGE BLADE 3035693-1 10-150283-54752	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0345	NO. 1 ENGINE - NO.45 LPT 1 STAGE BLADE 3035693-1 10-150283-54759	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0346	NO. 1 ENGINE - NO.46 LPT 1 STAGE BLADE 3035693-1 10-150283-54760	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0347	NO. 1 ENGINE - NO.47 LPT 1 STAGE BLADE 3035693-1 10-150283-54767	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0348	NO. 1 ENGINE - NO.48 LPT 1 STAGE BLADE 3035693-1 10-150283-54769	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0349	NO. 1 ENGINE - NO.49 LPT 1 STAGE BLADE 3035693-1 10-150283-54772	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0350	NO. 1 ENGINE - NO.50 LPT 1 STAGE BLADE 3035693-1 10-150283-54985	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0351	NO. 1 ENGINE - NO.51 LPT 1 STAGE BLADE 3035693-1 10-150283-55016	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0352	NO. 1 ENGINE - NO.52 LPT 1 STAGE BLADE 3035693-1 10-150283-55021	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0353	NO. 1 ENGINE - NO.53 LPT 1 STAGE BLADE 3035693-1 10-150283-55022	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0354	NO. 1 ENGINE - NO.54 LPT 1 STAGE BLADE 3035693-1 10-150283-55025	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0355	NO. 1 ENGINE - NO.55 LPT 1 STAGE BLADE 3035693-1 10-150283-55027	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0356	NO. 1 ENGINE - NO.56 LPT 1 STAGE BLADE 3035693-1 10-150283-55028	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0401	NO. 1 ENGINE - LPT STAGE 2 DISK 3035661-1 10162244604924	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 807	ENC		N:0			0	(15000) 14989	
725503-0501	NO. 1 ENGINE - LPT STAGE 3 DISK 3035663-1 1016224604639	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 807	ENC		N:0			0	(15000) 14989	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0601	NO. 1 ENGINE - LPT STAGE 1 DISK 3035593-1 1016224604740	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 807	ENC	15000	N:0			0	(15000) 14989	
726001-0101	NO. 1 ENGINE - ACCESSORY GEARBOX ASSEMBLY 3036004-2 10-169019-02019	MOS HRS/MSC	O/C	N:0 N:0			31-DEC-2010 0		
	REF: GENERIC NO REF	ENC		N:0			0		
726001-0301	NO. 1 ENGINE - OIL TEMPERATURE TRANSDUCER 3038701-1 1016901725816	MOS HRS/MSC	O/C	N:0 N:0			31-DEC-2010 0		
	REF: See Workcard	ENC		N:0			0		
726101-0101	NO. 1 ENGINE - OIL PUMP 3038704-3 10-162407-00020	MOS HRS/MSC	O/C	N:0 N:0			31-DEC-2010 0		
	REF: See Workcard	ENC		N:0			0		
727001-0101	NO. 1 ENGINE - SPINNER INNER RING 3037063-3 10-156138-01411	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: See Workcard	ENC	15000	N:0			0	(15000) 14989	
727001-0201	NO. 1 ENGINE - SPINNER COVER RING 3037101-2 10-156138-01282	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: See Workcard	ENC	15000	N:0			0	(15000) 14989	
727002-0101	NO. 1 ENGINE - ENGINE FAN DISK 3037077-2 09-162246-00883	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: See Workcard	ENC	15000	N:0			0	(15000) 14989	
727002-0201	NO. 1 ENGINE - FAN ROTOR ASSEMBLY 3037086-5 09-162246-00883	MOS HRS/MSC	O/C	N:0 N:0			31-DEC-2010 0		
	REF: See Workcard	ENC		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727002-0301	NO. 1 ENGINE - FAN SEAL PLATE 3037079-1 10-156138-01743	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: See Workcard	ENC	15000	N:0			0	(15000) 14989	
727010-0101	NO. 1 ENGINE - FAN STUB SHAFT 3037099-1 09-102045-00392	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0	(15000) 14989	
731010-0101	NO. 1 ENGINE - FUEL PUMP 2688676C 10ANL0880	MOS HRS/MSC	O/C	N:0 N:0			25-OCT-2011 5:48		
	REF: See Workcard	ENC		N:0					
ENGINE NO. 2 Model : AS907-1-1A Serial # P118771 Part # 3030001-4									
72-00-10-907	NO. 2 ENGINE - PERFORM ENGINE HOT SECTION INSPECTION	MOS HRS/MSC	O/C						
	REF: LMM 72-00-00	ENC							
72-00-50-907	NO. 2 ENGINE - PERFORM ENGINE CORE ZONE INSPECTION	MOS HRS/MSC	O/C						
	REF:	ENC							
72-20-01-200	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE FAN CONTAINMENT HOUSING PKG 6	MOS HRS/MSC	4000	+45			31-DEC-2010 0		
72.600	REF:	ENC					0	(4000) 3988:27	4045
72-21-01-201 (s)	NO. 2 ENGINE - DETAILED INSPECTION ENGINE FAN BLADES PKG 8	MOS HRS/MSC	600	+40/-40			PKG 23-DEC-2019 2641:36		
	REF: See Workcard	ENC					1491		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-21-01-202 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE FAN INLET PKG 8 REF: See Workcard	MOS HRS/MSC ENC	600	+40/-40			PKG 23-DEC-2019 2641:36 1491		
72-21-01-203 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE FRONT FRAME ASSEMBLY PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
72-21-01-204 (s)	NO. 2 ENGINE - DETAILED INSPECTION ENGINE FAN STATOR ASSEMBLY PKG 8 REF: See Workcard	MOS HRS/MSC ENC	600	+40/-40			PKG 23-DEC-2019 2641:36 1491		
72-21-01-205 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE FAN MODULE PKG 9 REF: AMM 72 21 01 210 803	MOS HRS/MSC ENC	800	+40/-40			PKG 23-DEC-2019 2641:36 1491		
72-21-01-206 (s)	NO. 2 ENGINE - FUNCTIONAL TEST ENGINE FAN STUB SHAFT AND FAN RETENTION HARDWARE PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
72-21-01-208 (s)	NO. 2 ENGINE - DETAILED INSPECTION ENGINE FAN ROTOR ASSEMBLY PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
72-30-00-201	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION ENGINE COMPRESSOR SECTION REF: See Workcard	MOS HRS/MSC ENC	8000	+100			31-DEC-2010 0 0	(8000) 7988:27	8100
72-30-00-206 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION HP/LP BLEED AIR DUCTS PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-30-00-207 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE COMPRESSOR CASE PKG 17	MOS	4800	+100			PKG 31-DEC-2010 0 0		
	REF: See Workcard	ENC							
72-40-00-201 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE COMBUSTOR CASE PKG 17	MOS	4800	+100			PKG 31-DEC-2010 0 0		
	REF: See Workcard	ENC							
72-40-00-202 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION ENGINE COMBUSTOR MODULE PKG 17	MOS	4800	+100			PKG 31-DEC-2010 0 0		
	REF: See Workcard	ENC							
72-50-00-201 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION ENGINE HP TURBINE MODULE PKG 17	MOS	4800	+100			PKG 31-DEC-2010 0 0		
	REF: See Workcard	ENC							
72-50-00-205	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION ENGINE LP TURBINE MODULE	MOS	4200	+40/-40			31-DEC-2010 0 0	(4200) 4188:27	4240
MRB	REF: See Workcard	ENC							
72-50-00-206 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE LP TURBINE CASE PKG 17	MOS	4800	+100			PKG 31-DEC-2010 0 0		
	REF: See Workcard	ENC							
72-50-00-208	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION ENGINE HP TURBINE SHROUD-SUPPORT ASSEMBLY	MOS	25000	+40/-40			31-DEC-2010 0 0	(25000) 24988:27	25040
	REF: See Workcard	ENC							
72-50-00-210 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE EXIT GUIDE VANE (EGV) ASSEMBLY PKG 17	MOS	4800	+100			PKG 31-DEC-2010 0 0		
	REF: See Workcard	ENC							



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-50-00-211 (s)	NO. 2 ENGINE - DETAILED INSPECTION ENGINE EXIT GUIDE VANE AFT MOUNT LUGS PKG 17	MOS HRS/MSC	4800	+40/-40			PKG 31-DEC-2010 0		
MRB	REF: AMM 72 50 00 220 801	ENC					0		
72-50-00-212	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION ENGINE LP TURBINE CASE REF: See Workcard	MOS HRS/MSC ENC	25000	+40/-40			31-DEC-2010 0 0	(25000) 24988:27	25040
72-50-00-213 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE EXHAUST MIXER-NOZZLE AREA PKG 8	MOS HRS/MSC	600	+40/-40			PKG 23-DEC-2019 2641:36 1491		
	REF: See Workcard	ENC							
72-50-00-218	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION EXIT GUIDE VANE (EGV) ASSEMBLY REF: See Workcard	MOS HRS/MSC ENC	25000	+40/-40			31-DEC-2010 0 0	(25000) 24988:27	25040
72-60-00-201 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ACCESSORY GEARBOX (AGB) ASSEMBLY PKG 8	MOS HRS/MSC	600	+40/-40			PKG 23-DEC-2019 2641:36 1491		
	REF: See Workcard	ENC							
72-71-00-201 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE OUTER FAN-BYPASS-DUCT AND SYSTEMS (LRU) ATTACHMENTS (EXTERIOR) PKG 17	MOS HRS/MSC	4800	+40/-40			PKG 31-DEC-2010 0		
MRB	REF: See Workcard	ENC					0		
72-71-00-202 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE INNER FAN AND OUTER BYPASS DUCTS PKG 17	MOS HRS/MSC	4800	+100			PKG 31-DEC-2010 0		
	REF: See Workcard	ENC					0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-71-00-203 (s)	NO. 2 ENGINE - DETAILED INSPECTION OUTER FAN-BYPASS DUCT REAR-FLANGE AND THRUST REVERSER ATTACHMENT HARDWARE						PKG		
	PKG 17	MOS						31-DEC-2010	
		HRS/MSC	4800	+40/-40				0	
MRB	REF: AMM 72 71 00 220 801	ENC						0	
72-71-00-205	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION ENGINE FAN BLADES								
		MOS						31-DEC-2010	
		HRS/MSC						0	
	REF: See Workcard	ENC	15000	+100				0	(15000) 14990 15100
72-71-00-206 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION FAN CONTAINMENT HOUSING ASSEMBLY ON THE ENGINE						PKG		
	PKG 17	MOS						31-DEC-2010	
		HRS/MSC	4800	+100				0	
	REF: See Workcard	ENC						0	
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.1 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR								
	3035602-1	MOS						31-DEC-2010	
	10-2101-00203	HRS/MSC	7525	+525/-525				0	(7525) 7513:27 8050
	REF: GENERIC NO REF	ENC						0	
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.10 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR								
	3035602-1	MOS						31-DEC-2010	
	10-2101-00213	HRS/MSC	7525	+525/-525				0	(7525) 7513:27 8050
	REF: GENERIC NO REF	ENC						0	
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.11 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR								
	3035602-1	MOS						31-DEC-2010	
	10-2101-00214	HRS/MSC	7525	+525/-525				0	(7525) 7513:27 8050
	REF: GENERIC NO REF	ENC						0	
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.12 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR								
	3035602-1	MOS						31-DEC-2010	
	10-2101-00215	HRS/MSC	7525	+525/-525				0	(7525) 7513:27 8050
	REF: GENERIC NO REF	ENC						0	
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.13 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR								
	3035602-1	MOS						31-DEC-2010	
	10-2101-00216	HRS/MSC	7525	+525/-525				0	(7525) 7513:27 8050
	REF: GENERIC NO REF	ENC						0	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.14 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00217 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.15 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00218 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.16 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00219 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.17 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00220 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.18 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00243 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.19 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00251 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.2 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00204 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.20 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00257 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.21 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00258 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.22 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00259 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.23 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00260 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.24 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00261 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.25 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00262 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.26 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00263 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.27 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00264 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.28 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00265 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.29 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00266 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.3 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00205 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.30 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00267 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.31 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00268 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.32 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00269 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.33 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00270 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.34 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00271 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.35 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00272 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.36 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00273 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.37 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00274 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.38 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00275 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.39 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00276 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.4 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00206 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.40 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00277 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.41 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00278 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.42 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00279 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.43 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00280 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.44 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00281 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.45 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00282 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.46 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00283 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.47 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00284 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.48 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00285 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.49 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00286 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.5 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00207 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-71-00-900	NO. 2 ENGINE - INSPECT NO.50 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00287 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.51 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00288 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.52 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00289 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.53 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00290 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.54 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00291 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.55 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00292 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.56 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00332 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.57 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00334 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.58 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00335 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.59 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00336 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.6 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00209 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.60 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00337 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.61 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00338 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.62 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00339 REF:	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.7 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00210 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.8 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00211 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-71-00-900	NO. 2 ENGINE - INSPECT NO.9 LPT 2 STAGE BLADE Z GAP CONTACT SURFACES FOR WEAR 3035602-1 10-2101-00212 REF: GENERIC NO REF	MOS HRS/MSC ENC	7525	+525/-525			31-DEC-2010 0 0	(7525) 7513:27	8050
723001-0101	NO. 2 ENGINE - BALL BEARING 3033024-6 18-162255-25399 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-NOV-2018 2236:21 1275		
723010-0101	NO. 2 ENGINE - COMPRESSOR ROTOR (SPACER, 2-3) ROTATING SEAL 3033069-3 08-13336-16956 REF: AMM 72 30 00 961 801	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14990	
723010-0201	NO. 2 ENGINE - COMPRESSOR STAGE 3 BLISK ASSEMBLY 3033108-8 10162246000839 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
723010-0301	NO. 2 ENGINE - STAGE 1 COMPRESSOR BLISK 3033053-7 0918244901004 REF: AMM 72 30 00 961 802	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14990	
723010-0401	NO. 2 ENGINE - STAGE 2 COMPRESSOR BLISK 3033063-4 1018244901238 REF: AMM 72 30 00 961 802	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14990	
723010-0501	NO. 2 ENGINE - STAGE 4 COMPRESSOR BLISK 3033072-4 1018019282449 REF: AMM 72 30 00 961 802	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14990	
723010-0601	NO. 2 ENGINE - HP SHAFT 3033084-4 10-102045-00005 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14990	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723010-0701	NO. 2 ENGINE - VORTEX SPOILER ASSEMBLY 3033118-3 1016204500913	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0	(15000) 14990	
723010-0801	NO. 2 ENGINE - STAGE 3 COMPRESSOR BLISK 3033067-9 10162246000839	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 30 00 961 802	ENC	15000	N:0			0	(15000) 14990	
723010-0901	NO. 2 ENGINE - COMPRESSOR ROTOR (SPACER, 3-4) ROTATING SEAL 3033070-3 08-13336-16308	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 30 00 961 801	ENC	15000	N:0			0	(15000) 14990	
723010-1001	NO. 2 ENGINE - VORTEX SPOILER 3033074-3 1016204500913	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0	(15000) 14990	
723010-1101	NO. 2 ENGINE - VORTEX SLEEVE 3033117-2 10210104744	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0	(15000) 14990	
723010-1201	NO. 2 ENGINE - ENGINE HP TURBINE FORWARD COUPLING 3033133-2 10P25363	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 809	ENC	15000	N:0			0	(15000) 14990	
723010-1301	NO. 2 ENGINE - ENGINE CENTRIFUGAL COMPRESSOR IMPELLER 3033182-2 08-13651-05984	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0	(15000) 14990	
723010-2000	NO. 2 ENGINE - DIFFUSER CASE 3033174-3 10-156138-02785	MOS HRS/MSC	O/C	N:0 N:0			31-DEC-2010 0		
	REF: GENERIC NO REF	ENC		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724010-0301	NO. 2 ENGINE - COMBUSTION CHAMBER CASE 3034063-3 10-150609-00042 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
724010-0401	NO. 2 ENGINE - COMBUSTION CHAMBER ASSEMBLY 3034088-5 18-3300-05818 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-NOV-2018 2236:21 1275		
725101-0101	NO. 2 ENGINE - HPT-STAGE 1 SEAL ASSEMBLY 3035092-3 10-162246-01081 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
725101-0201	NO. 2 ENGINE - HPT-STAGE 2 SEAL ASSEMBLY 3035093-2 1016224602044 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
725101-0301	NO. 2 ENGINE - HPT-STAGE 2 ROTOR ASSEMBLY 3035135-5 1016224604664 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
725101-0401	NO. 2 ENGINE - HPT-STAGE 1 ROTOR ASSEMBLY 3035137-4 1016224605942 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
725101-0501	NO. 2 ENGINE - HPT STAGE 1 SEAL PLATE (DRIVE ARM) COUPLER 3035030-3 08-13651-00339 REF: GENERIC NO REF	MOS HRS/MSC ENC		N:0 N:0 N:0			31-DEC-2010 0 0		(15000) 14990
LIFE LIMIT			15000						
725101-0601	NO. 2 ENGINE - STAGE 1 HP TURBINE SEAL PLATE 3035124-1 10-162246-01081 REF: GENERIC NO REF	MOS HRS/MSC ENC		N:0 N:0 N:0			31-DEC-2010 0 0		(15000) 14990
LIFE LIMIT			15000						

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725101-0701	NO. 2 ENGINE - HPT STAGE 2 COUPLER 3035053-2 10P28570	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0	(15000) 14990	
725101-0801	NO. 2 ENGINE - STAGE 2 HP TURBINE SEAL PLATE 3035109-1 1016224602044	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0	(15000) 14990	
725103-0101	NO. 2 ENGINE - NO.1 HPT 1 STAGE BLADE 3035114-6 09M16872	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0102	NO. 2 ENGINE - NO.2 HPT 1 STAGE BLADE 3035114-6 09M16909	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0103	NO. 2 ENGINE - NO.3 HPT 1 STAGE BLADE 3035114-6 09M16910	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0104	NO. 2 ENGINE - NO.4 HPT 1 STAGE BLADE 3035114-6 09M18117	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0105	NO. 2 ENGINE - NO.5 HPT 1 STAGE BLADE 3035114-6 09M18130	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0106	NO. 2 ENGINE - NO.6 HPT 1 STAGE BLADE 3035114-6 09M18131	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725103-0107	NO. 2 ENGINE - NO.7 HPT 1 STAGE BLADE 3035114-6 09M18132	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0108	NO. 2 ENGINE - NO.8 HPT 1 STAGE BLADE 3035114-6 09M18135	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0109	NO. 2 ENGINE - NO.9 HPT 1 STAGE BLADE 3035114-6 09M18138	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0110	NO. 2 ENGINE - NO.10 HPT 1 STAGE BLADE 3035114-6 09M18141	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0111	NO. 2 ENGINE - NO.11 HPT 1 STAGE BLADE 3035114-6 09M22580	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0112	NO. 2 ENGINE - NO.12 HPT 1 STAGE BLADE 3035114-6 09M22582	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0113	NO. 2 ENGINE - NO.13 HPT 1 STAGE BLADE 3035114-6 09M22592	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0114	NO. 2 ENGINE - NO.14 HPT 1 STAGE BLADE 3035114-6 09M23854	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725103-0115	NO. 2 ENGINE - NO.15 HPT 1 STAGE BLADE 3035114-6 09M23862	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0116	NO. 2 ENGINE - NO.16 HPT 1 STAGE BLADE 3035114-6 09M23866	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0117	NO. 2 ENGINE - NO.17 HPT 1 STAGE BLADE 3035114-6 09M23873	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0118	NO. 2 ENGINE - NO.18 HPT 1 STAGE BLADE 3035114-6 09M23878	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0119	NO. 2 ENGINE - NO.19 HPT 1 STAGE BLADE 3035114-6 09M23881	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0120	NO. 2 ENGINE - NO.20 HPT 1 STAGE BLADE 3035114-6 09M23884	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0121	NO. 2 ENGINE - NO.21 HPT 1 STAGE BLADE 3035114-6 09M23886	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0122	NO. 2 ENGINE - NO.22 HPT 1 STAGE BLADE 3035114-6 09M23888	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725103-0123	NO. 2 ENGINE - NO.23 HPT 1 STAGE BLADE 3035114-6 09M23890	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0124	NO. 2 ENGINE - NO.24 HPT 1 STAGE BLADE 3035114-6 09M23891	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0125	NO. 2 ENGINE - NO.25 HPT 1 STAGE BLADE 3035114-6 09M23892	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0126	NO. 2 ENGINE - NO.26 HPT 1 STAGE BLADE 3035114-6 09M23893	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0127	NO. 2 ENGINE - NO.27 HPT 1 STAGE BLADE 3035114-6 09M23895	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0128	NO. 2 ENGINE - NO.28 HPT 1 STAGE BLADE 3035114-6 09M23896	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0129	NO. 2 ENGINE - NO.29 HPT 1 STAGE BLADE 3035114-6 09M23897	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0130	NO. 2 ENGINE - NO.30 HPT 1 STAGE BLADE 3035114-6 09M23898	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725103-0131	NO. 2 ENGINE - NO.31 HPT 1 STAGE BLADE 3035114-6 09M23901	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0132	NO. 2 ENGINE - NO.32 HPT 1 STAGE BLADE 3035114-6 09M23903	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0133	NO. 2 ENGINE - NO.33 HPT 1 STAGE BLADE 3035114-6 09M23908	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0134	NO. 2 ENGINE - NO.34 HPT 1 STAGE BLADE 3035114-6 09M23910	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0135	NO. 2 ENGINE - NO.35 HPT 1 STAGE BLADE 3035114-6 09M23911	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0136	NO. 2 ENGINE - NO.36 HPT 1 STAGE BLADE 3035114-6 09M23914	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0137	NO. 2 ENGINE - NO.37 HPT 1 STAGE BLADE 3035114-6 09M23919	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0138	NO. 2 ENGINE - NO.38 HPT 1 STAGE BLADE 3035114-6 09M23920	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725103-0201	NO. 2 ENGINE - NO.1 HPT 2 STAGE BLADE 3035049-5 10M47245	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0202	NO. 2 ENGINE - NO.2 HPT 2 STAGE BLADE 3035049-5 10M47246	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0203	NO. 2 ENGINE - NO.3 HPT 2 STAGE BLADE 3035049-5 10M47248	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0204	NO. 2 ENGINE - NO.4 HPT 2 STAGE BLADE 3035049-5 10M47249	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0205	NO. 2 ENGINE - NO.5 HPT 2 STAGE BLADE 3035049-5 10M47250	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0206	NO. 2 ENGINE - NO.6 HPT 2 STAGE BLADE 3035049-5 10M47252	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0207	NO. 2 ENGINE - NO.7 HPT 2 STAGE BLADE 3035049-5 10M47253	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0208	NO. 2 ENGINE - NO.8 HPT 2 STAGE BLADE 3035049-5 10M47256	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725103-0209	NO. 2 ENGINE - NO.9 HPT 2 STAGE BLADE 3035049-5 10M47257	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0210	NO. 2 ENGINE - NO.10 HPT 2 STAGE BLADE 3035049-5 10M47258	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0211	NO. 2 ENGINE - NO.11 HPT 2 STAGE BLADE 3035049-5 10M47259	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0212	NO. 2 ENGINE - NO.12 HPT 2 STAGE BLADE 3035049-5 10M47260	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0213	NO. 2 ENGINE - NO.13 HPT 2 STAGE BLADE 3035049-5 10M47268	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0214	NO. 2 ENGINE - NO.14 HPT 2 STAGE BLADE 3035049-5 10M47270	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0215	NO. 2 ENGINE - NO.15 HPT 2 STAGE BLADE 3035049-5 10M47273	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0216	NO. 2 ENGINE - NO.16 HPT 2 STAGE BLADE 3035049-5 10M47279	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725103-0217	NO. 2 ENGINE - NO.17 HPT 2 STAGE BLADE 3035049-5 10M47291	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0218	NO. 2 ENGINE - NO.18 HPT 2 STAGE BLADE 3035049-5 10M47311	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0219	NO. 2 ENGINE - NO.19 HPT 2 STAGE BLADE 3035049-5 10M47324	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0220	NO. 2 ENGINE - NO.20 HPT 2 STAGE BLADE 3035049-5 10M47330	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0221	NO. 2 ENGINE - NO.21 HPT 2 STAGE BLADE 3035049-5 10M47331	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0222	NO. 2 ENGINE - NO.22 HPT 2 STAGE BLADE 3035049-5 10M47332	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0223	NO. 2 ENGINE - NO.23 HPT 2 STAGE BLADE 3035049-5 10M47333	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0224	NO. 2 ENGINE - NO.24 HPT 2 STAGE BLADE 3035049-5 10M47334	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725103-0225	NO. 2 ENGINE - NO.25 HPT 2 STAGE BLADE 3035049-5 10M47341	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0226	NO. 2 ENGINE - NO.26 HPT 2 STAGE BLADE 3035049-5 10M47347	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0227	NO. 2 ENGINE - NO.27 HPT 2 STAGE BLADE 3035049-5 10M47350	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0228	NO. 2 ENGINE - NO.28 HPT 2 STAGE BLADE 3035049-5 10M47351	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0229	NO. 2 ENGINE - NO.29 HPT 2 STAGE BLADE 3035049-5 10M47355	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0230	NO. 2 ENGINE - NO.30 HPT 2 STAGE BLADE 3035049-5 10M47357	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0231	NO. 2 ENGINE - NO.31 HPT 2 STAGE BLADE 3035049-5 10M47633	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	
725103-0232	NO. 2 ENGINE - NO.32 HPT 2 STAGE BLADE 3035049-5 10M47634	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725103-0233	NO. 2 ENGINE - NO.33 HPT 2 STAGE BLADE 3035049-5 10M47635	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0		
725103-0234	NO. 2 ENGINE - NO.34 HPT 2 STAGE BLADE 3035049-5 10M47641	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: AMM 72 50 00 961 803	ENC		N:0			0		
725103-0301	NO. 2 ENGINE - STAGE 2 HP TURBINE DISK 3035123-1 1016224604664	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14990	
LIFE LIMIT	REF: AMM 72 50 00 961 801	ENC		N:0			0		
725103-0401	NO. 2 ENGINE - ENGINE HP TURBINE INTERSTAGE ROTATING SEAL 3035134-1 0916204501347	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14990	
LIFE LIMIT	REF: AMM 72 50 00 961 804	ENC		N:0			0		
725103-0501	NO. 2 ENGINE - STAGE 1 HP TURBINE DISK 3035136-2 1016224605942	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14990	
LIFE LIMIT	REF: AMM 72 50 00 961 801	ENC		N:0			0		
725104-7101	NO. 2 ENGINE - HPT NOZZLE SUPPORT 3035056-5 SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725502-0101	NO. 2 ENGINE - LPT-STAGE 2 ROTOR ASSEMBLY 3035660-1 1016224603232	MOS HRS/MSC	O/C	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725502-0201	NO. 2 ENGINE - LPT-STAGE 3 ROTOR ASSEMBLY 3035662-1 1016224604637	MOS HRS/MSC	O/C	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725502-0301	NO. 2 ENGINE - LPT-STAGE 1 ROTOR ASSEMBLY 3035692-1 1016224602300 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
725502-0401	NO. 2 ENGINE - LPT1 NOZZLE ASSEMBLY 3035658-9 10-3300-01623 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
725502-0501	NO. 2 ENGINE - ENGINE LP TURBINE INTERSTAGE ROTATING SEAL 3035595-1 10-162246-03684 REF: AMM 72 50 00 961 806	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14990	
725502-0601	NO. 2 ENGINE - ENGINE LP TURBINE DRIVE ARM 3035610-2 09-162246-00663 REF: AMM 72 50 00 961 808	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14990	
725502-0701	NO. 2 ENGINE - LPT STUB SHAFT 3035691-1 10-162684-07079 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14990	
725502-0801	NO. 2 ENGINE - LPT SHAFT 3035689-1 090473300779 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14990	
725503-0101	NO. 2 ENGINE - NO.1 LPT 2 STAGE BLADE 3035602-1 10-2101-00203 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14988:27	
725503-0102	NO. 2 ENGINE - NO.2 LPT 2 STAGE BLADE 3035602-1 10-2101-00204 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			31-DEC-2010 0 0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0103	NO. 2 ENGINE - NO.3 LPT 2 STAGE BLADE 3035602-1 10-2101-00205	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0104	NO. 2 ENGINE - NO.4 LPT 2 STAGE BLADE 3035602-1 10-2101-00206	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0105	NO. 2 ENGINE - NO.5 LPT 2 STAGE BLADE 3035602-1 10-2101-00207	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0106	NO. 2 ENGINE - NO.6 LPT 2 STAGE BLADE 3035602-1 10-2101-00209	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0107	NO. 2 ENGINE - NO.7 LPT 2 STAGE BLADE 3035602-1 10-2101-00210	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0108	NO. 2 ENGINE - NO.8 LPT 2 STAGE BLADE 3035602-1 10-2101-00211	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0109	NO. 2 ENGINE - NO.9 LPT 2 STAGE BLADE 3035602-1 10-2101-00212	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0110	NO. 2 ENGINE - NO.10 LPT 2 STAGE BLADE 3035602-1 10-2101-00213	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0111	NO. 2 ENGINE - NO.11 LPT 2 STAGE BLADE 3035602-1 10-2101-00214	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0112	NO. 2 ENGINE - NO.12 LPT 2 STAGE BLADE 3035602-1 10-2101-00215	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0113	NO. 2 ENGINE - NO.13 LPT 2 STAGE BLADE 3035602-1 10-2101-00216	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0114	NO. 2 ENGINE - NO.14 LPT 2 STAGE BLADE 3035602-1 10-2101-00217	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0115	NO. 2 ENGINE - NO.15 LPT 2 STAGE BLADE 3035602-1 10-2101-00218	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0116	NO. 2 ENGINE - NO.16 LPT 2 STAGE BLADE 3035602-1 10-2101-00219	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0117	NO. 2 ENGINE - NO.17 LPT 2 STAGE BLADE 3035602-1 10-2101-00220	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0118	NO. 2 ENGINE - NO.18 LPT 2 STAGE BLADE 3035602-1 10-2101-00243	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0119	NO. 2 ENGINE - NO.19 LPT 2 STAGE BLADE 3035602-1 10-2101-00251	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0120	NO. 2 ENGINE - NO.20 LPT 2 STAGE BLADE 3035602-1 10-2101-00257	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0121	NO. 2 ENGINE - NO.21 LPT 2 STAGE BLADE 3035602-1 10-2101-00258	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0122	NO. 2 ENGINE - NO.22 LPT 2 STAGE BLADE 3035602-1 10-2101-00259	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0123	NO. 2 ENGINE - NO.23 LPT 2 STAGE BLADE 3035602-1 10-2101-00260	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0124	NO. 2 ENGINE - NO.24 LPT 2 STAGE BLADE 3035602-1 10-2101-00261	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0125	NO. 2 ENGINE - NO.25 LPT 2 STAGE BLADE 3035602-1 10-2101-00262	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0126	NO. 2 ENGINE - NO.26 LPT 2 STAGE BLADE 3035602-1 10-2101-00263	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0127	NO. 2 ENGINE - NO.27 LPT 2 STAGE BLADE 3035602-1 10-2101-00264	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0128	NO. 2 ENGINE - NO.28 LPT 2 STAGE BLADE 3035602-1 10-2101-00265	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0129	NO. 2 ENGINE - NO.29 LPT 2 STAGE BLADE 3035602-1 10-2101-00266	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0130	NO. 2 ENGINE - NO.30 LPT 2 STAGE BLADE 3035602-1 10-2101-00267	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0131	NO. 2 ENGINE - NO.31 LPT 2 STAGE BLADE 3035602-1 10-2101-00268	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0132	NO. 2 ENGINE - NO.32 LPT 2 STAGE BLADE 3035602-1 10-2101-00269	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0133	NO. 2 ENGINE - NO.33 LPT 2 STAGE BLADE 3035602-1 10-2101-00270	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0134	NO. 2 ENGINE - NO.34 LPT 2 STAGE BLADE 3035602-1 10-2101-00271	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		(15000) 14988:27
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0135	NO. 2 ENGINE - NO.35 LPT 2 STAGE BLADE 3035602-1 10-2101-00272	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0136	NO. 2 ENGINE - NO.36 LPT 2 STAGE BLADE 3035602-1 10-2101-00273	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0137	NO. 2 ENGINE - NO.37 LPT 2 STAGE BLADE 3035602-1 10-2101-00274	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0138	NO. 2 ENGINE - NO.38 LPT 2 STAGE BLADE 3035602-1 10-2101-00275	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0139	NO. 2 ENGINE - NO.39 LPT 2 STAGE BLADE 3035602-1 10-2101-00276	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0140	NO. 2 ENGINE - NO.40 LPT 2 STAGE BLADE 3035602-1 10-2101-00277	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0141	NO. 2 ENGINE - NO.41 LPT 2 STAGE BLADE 3035602-1 10-2101-00278	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0142	NO. 2 ENGINE - NO.42 LPT 2 STAGE BLADE 3035602-1 10-2101-00279	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0143	NO. 2 ENGINE - NO.43 LPT 2 STAGE BLADE 3035602-1 10-2101-00280	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0144	NO. 2 ENGINE - NO.44 LPT 2 STAGE BLADE 3035602-1 10-2101-00281	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0145	NO. 2 ENGINE - NO.45 LPT 2 STAGE BLADE 3035602-1 10-2101-00282	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0146	NO. 2 ENGINE - NO.46 LPT 2 STAGE BLADE 3035602-1 10-2101-00283	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0147	NO. 2 ENGINE - NO.47 LPT 2 STAGE BLADE 3035602-1 10-2101-00284	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0148	NO. 2 ENGINE - NO.48 LPT 2 STAGE BLADE 3035602-1 10-2101-00285	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0149	NO. 2 ENGINE - NO.49 LPT 2 STAGE BLADE 3035602-1 10-2101-00286	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0150	NO. 2 ENGINE - NO.50 LPT 2 STAGE BLADE 3035602-1 10-2101-00287	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0151	NO. 2 ENGINE - NO.51 LPT 2 STAGE BLADE 3035602-1 10-2101-00288	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0152	NO. 2 ENGINE - NO.52 LPT 2 STAGE BLADE 3035602-1 10-2101-00289	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0153	NO. 2 ENGINE - NO.53 LPT 2 STAGE BLADE 3035602-1 10-2101-00290	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0154	NO. 2 ENGINE - NO.54 LPT 2 STAGE BLADE 3035602-1 10-2101-00291	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0155	NO. 2 ENGINE - NO.55 LPT 2 STAGE BLADE 3035602-1 10-2101-00292	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0156	NO. 2 ENGINE - NO.56 LPT 2 STAGE BLADE 3035602-1 10-2101-00332	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0157	NO. 2 ENGINE - NO.57 LPT 2 STAGE BLADE 3035602-1 10-2101-00334	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0158	NO. 2 ENGINE - NO.58 LPT 2 STAGE BLADE 3035602-1 10-2101-00335	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0159	NO. 2 ENGINE - NO.59 LPT 2 STAGE BLADE 3035602-1 10-2101-00336	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0160	NO. 2 ENGINE - NO.60 LPT 2 STAGE BLADE 3035602-1 10-2101-00337	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0161	NO. 2 ENGINE - NO.61 LPT 2 STAGE BLADE 3035602-1 10-2101-00338	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0162	NO. 2 ENGINE - NO.62 LPT 2 STAGE BLADE 3035602-1 10-2101-00339	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0201	NO. 2 ENGINE - NO.1 LPT 3 STAGE BLADE 3035609-1 10-2101-01457	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0202	NO. 2 ENGINE - NO.2 LPT 3 STAGE BLADE 3035609-1 10-2101-01458	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0203	NO. 2 ENGINE - NO.3 LPT 3 STAGE BLADE 3035609-1 10-2101-01459	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0204	NO. 2 ENGINE - NO.4 LPT 3 STAGE BLADE 3035609-1 10-2101-01460	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0205	NO. 2 ENGINE - NO.5 LPT 3 STAGE BLADE 3035609-1 10-2101-01461	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0206	NO. 2 ENGINE - NO.6 LPT 3 STAGE BLADE 3035609-1 10-2101-01462	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0207	NO. 2 ENGINE - NO.7 LPT 3 STAGE BLADE 3035609-1 10-2101-01463	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0208	NO. 2 ENGINE - NO.8 LPT 3 STAGE BLADE 3035609-1 10-2101-01464	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0209	NO. 2 ENGINE - NO.9 LPT 3 STAGE BLADE 3035609-1 10-2101-01465	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0210	NO. 2 ENGINE - NO.10 LPT 3 STAGE BLADE 3035609-1 10-2101-01466	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0211	NO. 2 ENGINE - NO.11 LPT 3 STAGE BLADE 3035609-1 10-2101-01467	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0212	NO. 2 ENGINE - NO.12 LPT 3 STAGE BLADE 3035609-1 10-2101-01468	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0213	NO. 2 ENGINE - NO.13 LPT 3 STAGE BLADE 3035609-1 10-2101-01469	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0214	NO. 2 ENGINE - NO.14 LPT 3 STAGE BLADE 3035609-1 10-2101-01470	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0215	NO. 2 ENGINE - NO.15 LPT 3 STAGE BLADE 3035609-1 10-2101-01471	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0216	NO. 2 ENGINE - NO.16 LPT 3 STAGE BLADE 3035609-1 10-2101-01472	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0217	NO. 2 ENGINE - NO.17 LPT 3 STAGE BLADE 3035609-1 10-2101-01473	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0218	NO. 2 ENGINE - NO.18 LPT 3 STAGE BLADE 3035609-1 10-2101-01474	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0219	NO. 2 ENGINE - NO.19 LPT 3 STAGE BLADE 3035609-1 10-2101-01475	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0220	NO. 2 ENGINE - NO.20 LPT 3 STAGE BLADE 3035609-1 10-2101-01476	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0221	NO. 2 ENGINE - NO.21 LPT 3 STAGE BLADE 3035609-1 10-2101-01477	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0222	NO. 2 ENGINE - NO.22 LPT 3 STAGE BLADE 3035609-1 10-2101-01478	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0223	NO. 2 ENGINE - NO.23 LPT 3 STAGE BLADE 3035609-1 10-2101-01479	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0224	NO. 2 ENGINE - NO.24 LPT 3 STAGE BLADE 3035609-1 10-2101-01480	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0225	NO. 2 ENGINE - NO.25 LPT 3 STAGE BLADE 3035609-1 10-2101-01481	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0226	NO. 2 ENGINE - NO.26 LPT 3 STAGE BLADE 3035609-1 10-2101-01482	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0227	NO. 2 ENGINE - NO.27 LPT 3 STAGE BLADE 3035609-1 10-2101-01483	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0228	NO. 2 ENGINE - NO.28 LPT 3 STAGE BLADE 3035609-1 10-2101-01484	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0229	NO. 2 ENGINE - NO.29 LPT 3 STAGE BLADE 3035609-1 10-2101-01485	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0230	NO. 2 ENGINE - NO.30 LPT 3 STAGE BLADE 3035609-1 10-2101-01486	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0231	NO. 2 ENGINE - NO.31 LPT 3 STAGE BLADE 3035609-1 10-2101-01487	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0232	NO. 2 ENGINE - NO.32 LPT 3 STAGE BLADE 3035609-1 10-2101-01488	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0233	NO. 2 ENGINE - NO.33 LPT 3 STAGE BLADE 3035609-1 10-2101-01489	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0234	NO. 2 ENGINE - NO.34 LPT 3 STAGE BLADE 3035609-1 10-2101-01490	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0235	NO. 2 ENGINE - NO.35 LPT 3 STAGE BLADE 3035609-1 10-2101-01491	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0236	NO. 2 ENGINE - NO.36 LPT 3 STAGE BLADE 3035609-1 10-2101-01492	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0237	NO. 2 ENGINE - NO.37 LPT 3 STAGE BLADE 3035609-1 10-2101-01494	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0238	NO. 2 ENGINE - NO.38 LPT 3 STAGE BLADE 3035609-1 10-2101-01495	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0239	NO. 2 ENGINE - NO.39 LPT 3 STAGE BLADE 3035609-1 10-2101-01499	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0240	NO. 2 ENGINE - NO.40 LPT 3 STAGE BLADE 3035609-1 10-2101-01500	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0241	NO. 2 ENGINE - NO.41 LPT 3 STAGE BLADE 3035609-1 10-2101-01503	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0242	NO. 2 ENGINE - NO.42 LPT 3 STAGE BLADE 3035609-1 10-2101-01504	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0243	NO. 2 ENGINE - NO.43 LPT 3 STAGE BLADE 3035609-1 10-2101-01506	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0244	NO. 2 ENGINE - NO.44 LPT 3 STAGE BLADE 3035609-1 10-2101-01510	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0245	NO. 2 ENGINE - NO.45 LPT 3 STAGE BLADE 3035609-1 10-2101-01511	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0246	NO. 2 ENGINE - NO.46 LPT 3 STAGE BLADE 3035609-1 10-2101-01512	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0247	NO. 2 ENGINE - NO.47 LPT 3 STAGE BLADE 3035609-1 10-2101-01513	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0248	NO. 2 ENGINE - NO.48 LPT 3 STAGE BLADE 3035609-1 10-2101-01514	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0249	NO. 2 ENGINE - NO.49 LPT 3 STAGE BLADE 3035609-1 10-2101-01515	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0250	NO. 2 ENGINE - NO.50 LPT 3 STAGE BLADE 3035609-1 10-2101-01516	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0251	NO. 2 ENGINE - NO.51 LPT 3 STAGE BLADE 3035609-1 10-2101-01517	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0252	NO. 2 ENGINE - NO.52 LPT 3 STAGE BLADE 3035609-1 10-2101-01518	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0253	NO. 2 ENGINE - NO.53 LPT 3 STAGE BLADE 3035609-1 10-2101-01519	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0254	NO. 2 ENGINE - NO.54 LPT 3 STAGE BLADE 3035609-1 10-2101-01520	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0255	NO. 2 ENGINE - NO.55 LPT 3 STAGE BLADE 3035609-1 10-2101-01521	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0256	NO. 2 ENGINE - NO.56 LPT 3 STAGE BLADE 3035609-1 10-2101-01522	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0257	NO. 2 ENGINE - NO.57 LPT 3 STAGE BLADE 3035609-1 10-2101-01523	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0258	NO. 2 ENGINE - NO.58 LPT 3 STAGE BLADE 3035609-1 10-2101-01524	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0259	NO. 2 ENGINE - NO.59 LPT 3 STAGE BLADE 3035609-1 10-2101-01525	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0260	NO. 2 ENGINE - NO.60 LPT 3 STAGE BLADE 3035609-1 10-2101-01526	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0261	NO. 2 ENGINE - NO.61 LPT 3 STAGE BLADE 3035609-1 10-2101-01527	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0262	NO. 2 ENGINE - NO.62 LPT 3 STAGE BLADE 3035609-1 10-2101-01528	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0263	NO. 2 ENGINE - NO.63 LPT 3 STAGE BLADE 3035609-1 10-2101-01529	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0264	NO. 2 ENGINE - NO.64 LPT 3 STAGE BLADE 3035609-1 10-2101-01530	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0265	NO. 2 ENGINE - NO.65 LPT 3 STAGE BLADE 3035609-1 10-2101-01542	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0266	NO. 2 ENGINE - NO.66 LPT 3 STAGE BLADE 3035609-1 10-2101-01544	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0267	NO. 2 ENGINE - NO.67 LPT 3 STAGE BLADE 3035609-1 10-2101-01547	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0268	NO. 2 ENGINE - NO.68 LPT 3 STAGE BLADE 3035609-1 10-2101-01550	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0269	NO. 2 ENGINE - NO.69 LPT 3 STAGE BLADE 3035609-1 10-2101-01555	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0270	NO. 2 ENGINE - NO.70 LPT 3 STAGE BLADE 3035609-1 10-2101-01564	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0271	NO. 2 ENGINE - NO.71 LPT 3 STAGE BLADE 3035609-1 10-2101-01565	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0272	NO. 2 ENGINE - NO.72 LPT 3 STAGE BLADE 3035609-1 10-2101-01834	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0273	NO. 2 ENGINE - NO.73 LPT 3 STAGE BLADE 3035609-1 10-2101-01836	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0274	NO. 2 ENGINE - NO.74 LPT 3 STAGE BLADE 3035609-1 10-2101-01840	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0301	NO. 2 ENGINE - NO.1 LPT 1 STAGE BLADE 3035693-1 10-150283-54148	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0302	NO. 2 ENGINE - NO.2 LPT 1 STAGE BLADE 3035693-1 10-150283-54244	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0303	NO. 2 ENGINE - NO.3 LPT 1 STAGE BLADE 3035693-1 10-150283-54251	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0304	NO. 2 ENGINE - NO.4 LPT 1 STAGE BLADE 3035693-1 10-150283-54252	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0305	NO. 2 ENGINE - NO.5 LPT 1 STAGE BLADE 3035693-1 10-150283-54253	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0306	NO. 2 ENGINE - NO.6 LPT 1 STAGE BLADE 3035693-1 10-150283-54254	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0307	NO. 2 ENGINE - NO.7 LPT 1 STAGE BLADE 3035693-1 10-150283-54255	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0308	NO. 2 ENGINE - NO.8 LPT 1 STAGE BLADE 3035693-1 10-150283-54256	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0309	NO. 2 ENGINE - NO.9 LPT 1 STAGE BLADE 3035693-1 10-150283-54259	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0310	NO. 2 ENGINE - NO.10 LPT 1 STAGE BLADE 3035693-1 10-150283-54260	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0311	NO. 2 ENGINE - NO.11 LPT 1 STAGE BLADE 3035693-1 10-150283-54261	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0312	NO. 2 ENGINE - NO.12 LPT 1 STAGE BLADE 3035693-1 10-150283-54262	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0313	NO. 2 ENGINE - NO.13 LPT 1 STAGE BLADE 3035693-1 10-150283-54263	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0314	NO. 2 ENGINE - NO.14 LPT 1 STAGE BLADE 3035693-1 10-150283-54264	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0315	NO. 2 ENGINE - NO.15 LPT 1 STAGE BLADE 3035693-1 10-150283-54265	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0316	NO. 2 ENGINE - NO.16 LPT 1 STAGE BLADE 3035693-1 10-150283-54266	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0317	NO. 2 ENGINE - NO.17 LPT 1 STAGE BLADE 3035693-1 10-150283-54267	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0318	NO. 2 ENGINE - NO.18 LPT 1 STAGE BLADE 3035693-1 10-150283-54268	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0319	NO. 2 ENGINE - NO.19 LPT 1 STAGE BLADE 3035693-1 10-150283-54269	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0320	NO. 2 ENGINE - NO.20 LPT 1 STAGE BLADE 3035693-1 10-150283-54271	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0321	NO. 2 ENGINE - NO.21 LPT 1 STAGE BLADE 3035693-1 10-150283-54274	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0322	NO. 2 ENGINE - NO.22 LPT 1 STAGE BLADE 3035693-1 10-150283-54275	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0323	NO. 2 ENGINE - NO.23 LPT 1 STAGE BLADE 3035693-1 10-150283-54276	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0324	NO. 2 ENGINE - NO.24 LPT 1 STAGE BLADE 3035693-1 10-150283-54277	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0325	NO. 2 ENGINE - NO.25 LPT 1 STAGE BLADE 3035693-1 10-150283-54278	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0326	NO. 2 ENGINE - NO.26 LPT 1 STAGE BLADE 3035693-1 10-150283-54279	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0327	NO. 2 ENGINE - NO.27 LPT 1 STAGE BLADE 3035693-1 10-150283-54280	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0328	NO. 2 ENGINE - NO.28 LPT 1 STAGE BLADE 3035693-1 10-150283-54282	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0329	NO. 2 ENGINE - NO.29 LPT 1 STAGE BLADE 3035693-1 10-150283-54285	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0330	NO. 2 ENGINE - NO.30 LPT 1 STAGE BLADE 3035693-1 10-150283-54286	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0331	NO. 2 ENGINE - NO.31 LPT 1 STAGE BLADE 3035693-1 10-150283-54287	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0332	NO. 2 ENGINE - NO.32 LPT 1 STAGE BLADE 3035693-1 10-150283-54288	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0333	NO. 2 ENGINE - NO.33 LPT 1 STAGE BLADE 3035693-1 10-150283-54289	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0334	NO. 2 ENGINE - NO.34 LPT 1 STAGE BLADE 3035693-1 10-150283-54290	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0335	NO. 2 ENGINE - NO.35 LPT 1 STAGE BLADE 3035693-1 10-150283-54291	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0336	NO. 2 ENGINE - NO.36 LPT 1 STAGE BLADE 3035693-1 10-150283-54292	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0337	NO. 2 ENGINE - NO.37 LPT 1 STAGE BLADE 3035693-1 10-150283-54293	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0338	NO. 2 ENGINE - NO.38 LPT 1 STAGE BLADE 3035693-1 10-150283-54294	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0339	NO. 2 ENGINE - NO.39 LPT 1 STAGE BLADE 3035693-1 10-150283-54295	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0340	NO. 2 ENGINE - NO.40 LPT 1 STAGE BLADE 3035693-1 10-150283-54296	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0341	NO. 2 ENGINE - NO.41 LPT 1 STAGE BLADE 3035693-1 10-150283-54297	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0342	NO. 2 ENGINE - NO.42 LPT 1 STAGE BLADE 3035693-1 10-150283-54298	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0343	NO. 2 ENGINE - NO.43 LPT 1 STAGE BLADE								
	3035693-1	MOS		N:0			31-DEC-2010		
	10-150283-54299	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0344	NO. 2 ENGINE - NO.44 LPT 1 STAGE BLADE								
	3035693-1	MOS		N:0			31-DEC-2010		
	10-150283-54300	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0345	NO. 2 ENGINE - NO.45 LPT 1 STAGE BLADE								
	3035693-1	MOS		N:0			31-DEC-2010		
	10-150283-54301	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0346	NO. 2 ENGINE - NO.46 LPT 1 STAGE BLADE								
	3035693-1	MOS		N:0			31-DEC-2010		
	10-150283-54302	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0347	NO. 2 ENGINE - NO.47 LPT 1 STAGE BLADE								
	3035693-1	MOS		N:0			31-DEC-2010		
	10-150283-54303	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0348	NO. 2 ENGINE - NO.48 LPT 1 STAGE BLADE								
	3035693-1	MOS		N:0			31-DEC-2010		
	10-150283-54304	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0349	NO. 2 ENGINE - NO.49 LPT 1 STAGE BLADE								
	3035693-1	MOS		N:0			31-DEC-2010		
	10-150283-54305	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		
725503-0350	NO. 2 ENGINE - NO.50 LPT 1 STAGE BLADE								
	3035693-1	MOS		N:0			31-DEC-2010		
	10-150283-54306	HRS/MSC	15000	N:0			0	(15000) 14988:27	
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0351	NO. 2 ENGINE - NO.51 LPT 1 STAGE BLADE 3035693-1 10-150283-54307	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0352	NO. 2 ENGINE - NO.52 LPT 1 STAGE BLADE 3035693-1 10-150283-54308	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0353	NO. 2 ENGINE - NO.53 LPT 1 STAGE BLADE 3035693-1 10-150283-54309	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0354	NO. 2 ENGINE - NO.54 LPT 1 STAGE BLADE 3035693-1 10-150283-54312	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0355	NO. 2 ENGINE - NO.55 LPT 1 STAGE BLADE 3035693-1 10-150283-54313	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0356	NO. 2 ENGINE - NO.56 LPT 1 STAGE BLADE 3035693-1 10-150283-54314	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC		N:0			0	(15000) 14988:27	
725503-0401	NO. 2 ENGINE - LPT STAGE 2 DISK 3035661-1 1016224603232	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 807	ENC		N:0			0	(15000) 14990	
725503-0501	NO. 2 ENGINE - LPT STAGE 3 DISK 3035663-1 1016224604637	MOS HRS/MSC	15000	N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 807	ENC		N:0			0	(15000) 14990	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725503-0601	NO. 2 ENGINE - LPT STAGE 1 DISK 3035593-1 1016224602300	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: AMM 72 50 00 961 807	ENC	15000	N:0			0	(15000) 14990	
726001-0101	NO. 2 ENGINE - ACCESSORY GEARBOX ASSEMBLY 3036004-2 10-169019-02014	MOS HRS/MSC	O/C	N:0 N:0			31-DEC-2010 0		
	REF: GENERIC NO REF	ENC		N:0			0		
726001-0301	NO. 2 ENGINE - OIL TEMPERATURE TRANSDUCER 3038701-1 1016901725795	MOS HRS/MSC	O/C	N:0 N:0			31-DEC-2010 0		
	REF: See Workcard	ENC		N:0			0		
726101-0101	NO. 2 ENGINE - OIL PUMP 3038704-3 10-162407-00023	MOS HRS/MSC	O/C	N:0 N:0			31-DEC-2010 0		
	REF: See Workcard	ENC		N:0			0		
727001-0101	NO. 2 ENGINE - SPINNER INNER RING 3037063-3 10-156138-02130	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: See Workcard	ENC	15000	N:0			0	(15000) 14990	
727001-0201	NO. 2 ENGINE - SPINNER COVER RING 3037101-2 10-156138-02315	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: See Workcard	ENC	15000	N:0			0	(15000) 14990	
727002-0101	NO. 2 ENGINE - ENGINE FAN DISK 3037077-2 09-162246-00889	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: See Workcard	ENC	15000	N:0			0	(15000) 14990	
727002-0201	NO. 2 ENGINE - FAN ROTOR ASSEMBLY 3037086-5 09-162246-00889	MOS HRS/MSC	O/C	N:0 N:0			31-DEC-2010 0		
	REF: See Workcard	ENC		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727002-0301	NO. 2 ENGINE - FAN SEAL PLATE 3037079-1 10-156138-02475	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: See Workcard	ENC	15000	N:0			0	(15000) 14990	
727010-0101	NO. 2 ENGINE - FAN STUB SHAFT 3037099-1 08-102045-00696	MOS HRS/MSC		N:0 N:0			31-DEC-2010 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	15000	N:0			0	(15000) 14990	
731010-0101	NO. 2 ENGINE - FUEL PUMP 2688676C 10ANL0867	MOS HRS/MSC	O/C	N:0 N:0			25-OCT-2011 5:48		
	REF: See Workcard	ENC		N:0					
CHAPTER 73 ENGINE FUEL AND CONTROL									
73-00-00-101	REPAIR #1 ENGINE LONG TIME FADEC FAULTS	MOS HRS/MSC	A/R				19-JAN-2017 1703:13		
CMR	REF: AMM 45 76 00 280 801	AFL					1002		
73-00-00-101	REPAIR #2 ENGINE LONG TIME FADEC FAULTS	MOS HRS/MSC	A/R				19-JAN-2017 1703:13		
CMR	REF: AMM 45 76 00 280 801	AFL					1002		
ENGINE NO. 1 Model : AS907-1-1A Serial # P118773 Part # 3030001-4									
73-00-80-907	NO. 1 ENGINE - PERFORM FUEL CONTROL UNIT COMPONENT INSPECTION (HMU/FUEL PUMP) 442324 FHC0820	MOS HRS/MSC	7000	+100			31-DEC-2010 0	(7000) 6988:27	7100
	REF: LMM 72-00-00	ENC					0		
73-10-00-201 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE FUEL SYSTEM COMPONENTS AND TUBING PKG 17	MOS HRS/MSC	4800	+100			31-DEC-2010 0		
	REF: See Workcard	ENC					0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-10-05-201 (s)	NO. 1 ENGINE - DISCARD ENGINE FUEL-FILTER ELEMENT PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
73-10-05-202 (s)	NO. 1 ENGINE - VISUAL CHECK ENGINE FUEL-FILTER MECHANICAL DIFFERENTIAL-PRESSURE INDICATOR (DPI) PKG 8 REF: See Workcard	MOS HRS/MSC ENC	600	+40/-40			PKG 23-DEC-2019 2641:36 1492		
73-10-13-202	NO. 1 ENGINE - RESTORATION NO. 1 START FUEL NOZZLE OR REPLACEMENT 3034073-1 12-169016-07289 REF: AMM 73 10 13 615 802	MOS HRS/MSC ENC	2000	+40/-40			07-DEC-2017 1913:50 1132	(3913:50) 3902:17	3953:50
73-10-13-202	NO. 1 ENGINE - RESTORATION NO. 2 START FUEL NOZZLE OR REPLACEMENT 3034073-1 14-169016-04830 REF: AMM 73 10 13 615 802	MOS HRS/MSC ENC	2000	+40/-40			07-DEC-2017 1913:50 1132	(3913:50) 3902:17	3953:50
73-10-13-202	NO. 1 ENGINE - RESTORATION NO. 3 START FUEL NOZZLE OR REPLACEMENT 3034073-1 14-169016-05137 REF: AMM 73 10 13 615 802	MOS HRS/MSC ENC	2000	+40/-40			07-DEC-2017 1913:50 1132	(3913:50) 3902:17	3953:50
73-10-13-202	NO. 1 ENGINE - RESTORATION NO. 4 START FUEL NOZZLE OR REPLACEMENT 3034073-1 090416801058 REF: AMM 73 10 13 615 802	MOS HRS/MSC ENC	2000	+40/-40			07-DEC-2017 1913:50 1132	(3913:50) 3902:17	3953:50
73-20-00-201 (s)	NO. 1 ENGINE - OPERATIONAL TEST ENGINE EXHAUST GAS TEMPERATURE (EGT) RAKES (PROBES) PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
73-20-00-202 (s)	NO. 1 ENGINE - DETAILED INSPECTION ENGINE P3 SENSOR LINE PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732010-0101	NO. 1 ENGINE - FUEL CONTROL UNIT 442324 FHC0820 REF: See Workcard	MOS HRS/MSC ENC	O/C	R:0 R:0 R:0			17-MAY-2011 5:48 16		
733002-7101	NO. 1 ENGINE - FUEL FLOW METER 3038040-6 10-152330-00165 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0101	NO. 1 ENGINE - NO. 1 START FUEL NOZZLE 3034073-1 12-169016-07289 REF: See Workcard	MOS HRS/MSC ENC	O/C	O:1 O:0 O:0			07-DEC-2017 1913:50 1121		
734010-0102	NO. 1 ENGINE - NO. 2 START FUEL NOZZLE 3034073-1 14-169016-04830 REF: See Workcard	MOS HRS/MSC ENC	O/C	O:1 O:0 O:0			07-DEC-2017 1913:50 1121		
734010-0103	NO. 1 ENGINE - NO. 3 START FUEL NOZZLE 3034073-1 14-169016-05137 REF: See Workcard	MOS HRS/MSC ENC	O/C	O:1 O:0 O:0			07-DEC-2017 1913:50 1121		
734010-0104	NO. 1 ENGINE - NO. 4 START FUEL NOZZLE 3034073-1 090416801058 REF: See Workcard	MOS HRS/MSC ENC	O/C	O:2 O:0 O:0			07-DEC-2017 1913:50 1121		
734010-0201	NO. 1 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-07529 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0201A	NO. 1 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-07529 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
734010-0202	NO. 1 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-07590 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0202A	NO. 1 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-07590 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0203	NO. 1 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-07592 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0203A	NO. 1 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-07592 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0204	NO. 1 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-07594 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0204A	NO. 1 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-07594 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0205	NO. 1 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-07596 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0205A	NO. 1 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-07596 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
734010-0206	NO. 1 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-07624 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0206A	NO. 1 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-07624 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0207	NO. 1 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-07631 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0207A	NO. 1 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-07631 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0208	NO. 1 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-07817 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0208A	NO. 1 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-07817 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0209	NO. 1 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-07821 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0209A	NO. 1 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-07821 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
734010-0210	NO. 1 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-08063 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0210A	NO. 1 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-08063 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0211	NO. 1 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-08070 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0211A	NO. 1 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-08070 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0212	NO. 1 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-08077 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0212A	NO. 1 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-08077 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
ENGINE NO. 2 Model : AS907-1-1A Serial # P118771 Part # 3030001-4									
73-00-80-907	NO. 2 ENGINE - PERFORM FUEL CONTROL UNIT COMPONENT INSPECTION (HMU/FUEL PUMP) 442324 FHC0802 REF: LMM 72-00-00	MOS HRS/MSC ENC	7000	+100			31-DEC-2010 0 0	(7000) 6988:27	7100



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-10-00-201 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE FUEL SYSTEM COMPONENTS AND TUBING PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
73-10-05-201 (s)	NO. 2 ENGINE - DISCARD ENGINE FUEL-FILTER ELEMENT PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
73-10-05-202 (s)	NO. 2 ENGINE - VISUAL CHECK ENGINE FUEL-FILTER MECHANICAL DIFFERENTIAL-PRESSURE INDICATOR (DPI) PKG 8 REF: See Workcard	MOS HRS/MSC ENC	600	+40/-40			PKG 23-DEC-2019 2641:36 1491		
73-10-13-202	NO. 2 ENGINE - RESTORATION NO. 1 START FUEL NOZZLE OR REPLACEMENT 3034073-1 13-169016-00276 REF: AMM 73 10 13 615 802	MOS HRS/MSC ENC	2000	+40/-40			07-DEC-2017 1913:50 1131	(3913:50) 3902:17	3953:50
73-10-13-202	NO. 2 ENGINE - RESTORATION NO. 2 START FUEL NOZZLE OR REPLACEMENT 3034073-1 14-169016-05492 REF: AMM 73 10 13 615 802	MOS HRS/MSC ENC	2000	+40/-40			07-DEC-2017 1913:50 1131	(3913:50) 3902:17	3953:50
73-10-13-202	NO. 2 ENGINE - RESTORATION NO. 3 START FUEL NOZZLE OR REPLACEMENT 3034073-1 12-169016-08799 REF: AMM 73 10 13 615 802	MOS HRS/MSC ENC	2000	+40/-40			07-DEC-2017 1913:50 1131	(3913:50) 3902:17	3953:50
73-10-13-202	NO. 2 ENGINE - RESTORATION NO. 4 START FUEL NOZZLE OR REPLACEMENT 3034073-1 11-169016-01081 REF: AMM 73 10 13 615 802	MOS HRS/MSC ENC	2000	+40/-40			07-DEC-2017 1913:50 1131	(3913:50) 3902:17	3953:50
73-20-00-201 (s)	NO. 2 ENGINE - OPERATIONAL TEST ENGINE EXHAUST GAS TEMPERATURE (EGT) RAKES (PROBES) PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-20-00-202 (s)	NO. 2 ENGINE - DETAILED INSPECTION ENGINE P3 SENSOR LINE PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
732010-0101	NO. 2 ENGINE - FUEL CONTROL UNIT 442324 FHC0802 REF: See Workcard	MOS HRS/MSC ENC	O/C	R:0 R:0 R:0			17-MAY-2011 5:48 15		
733002-7101	NO. 2 ENGINE - FUEL FLOW METER 3038040-6 10-152330-00161 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0101	NO. 2 ENGINE - NO. 1 START FUEL NOZZLE 3034073-1 13-169016-00276 REF: See Workcard	MOS HRS/MSC ENC	O/C	O:2 O:0 O:0			07-DEC-2017 1913:50 1121		
734010-0102	NO. 2 ENGINE - NO. 2 START FUEL NOZZLE 3034073-1 14-169016-05492 REF: See Workcard	MOS HRS/MSC ENC	O/C	O:1 O:0 O:0			07-DEC-2017 1913:50 1121		
734010-0103	NO. 2 ENGINE - NO. 3 START FUEL NOZZLE 3034073-1 12-169016-08799 REF: See Workcard	MOS HRS/MSC ENC	O/C	O:1 O:0 O:0			07-DEC-2017 1913:50 1121		
734010-0104	NO. 2 ENGINE - NO. 4 START FUEL NOZZLE 3034073-1 11-169016-01081 REF: See Workcard	MOS HRS/MSC ENC	O/C	O:1 O:0 O:0			07-DEC-2017 1913:50 1121		
734010-0201	NO. 2 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-08005 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
734010-0201A	NO. 2 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-08005 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0202	NO. 2 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-08009 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0202A	NO. 2 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-08009 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0203	NO. 2 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-08058 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0203A	NO. 2 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-08058 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0204	NO. 2 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-08059 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0204A	NO. 2 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-08059 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0205	NO. 2 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-08062 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
734010-0205A	NO. 2 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-08062 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0206	NO. 2 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-08072 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0206A	NO. 2 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-08072 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0207	NO. 2 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-08073 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0207A	NO. 2 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-08073 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0208	NO. 2 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-08075 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0208A	NO. 2 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-08075 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0209	NO. 2 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-08415 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
734010-0209A	NO. 2 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-08415 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0210	NO. 2 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-08416 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0210A	NO. 2 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-08416 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0211	NO. 2 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-08418 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0211A	NO. 2 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-08418 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	
734010-0212	NO. 2 ENGINE - MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 10-169016-08419 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
734010-0212A	NO. 2 ENGINE - RESTORATION (CLEANING) OF MAIN HI TEMPERATURE FUEL INJECTION NOZZLE 3034056-5 PKG 17 10-169016-08419 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			31-DEC-2010 0 0	(4000) 3988:27 M 4040	

CHAPTER 74 IGNITION



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
741001	IGNITION UNIT								
	PN	MOS		N:0			28-JAN-2011		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF:	AFL		N:0			0		
ENGINE NO. 1 Model : AS907-1-1A Serial # P118773 Part # 3030001-4									
74-20-00-201 (s)	NO. 1 ENGINE - DETAILED INSPECTION ENGINE IGNITION LEAD ASSEMBLY						PKG		
	PKG 17	MOS					31-DEC-2010		
	REF: See Workcard	HRS/MSC	4800	+100			0		
		ENC					0		
741001-0101	NO. 1 ENGINE - IGNITION UNIT								
	3038100-6	MOS		N:0			31-DEC-2010		
	1016250401436	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	ENC		N:0			0		
742001-0101	NO. 1 ENGINE - INBOARD IGNITER PLUG								
	PN	MOS		N:0			31-DEC-2010		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	ENC		N:0			0		
742001-0102	NO. 1 ENGINE - OUTBOARD IGNITER PLUG								
	PN	MOS		N:0			31-DEC-2010		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	ENC		N:0			0		
742002-0101	NO. 1 ENGINE - INBOARD IGNITER LEAD								
	PN	MOS		N:0			31-DEC-2010		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	ENC		N:0			0		
742002-0102	NO. 1 ENGINE - OUTBOARD IGNITER LEAD								
	PN	MOS		N:0			31-DEC-2010		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	ENC		N:0			0		

ENGINE NO. 2 Model : AS907-1-1A Serial # P118771 Part # 3030001-4

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
74-20-00-201 (s)	NO. 2 ENGINE - DETAILED INSPECTION ENGINE IGNITION LEAD ASSEMBLY PKG 17	MOS	4800	+100			PKG 31-DEC-2010 0 0		
	REF: See Workcard	ENC					0		
741001-0101	NO. 2 ENGINE - IGNITION UNIT 3038100-6	MOS		N:0			31-DEC-2010 0 0		
	1016250402162	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	ENC		N:0			0		
742001-0101	NO. 2 ENGINE - INBOARD IGNITER PLUG 3038110-6	MOS		N:0			28-NOV-2018 2236:21 1275		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			2236:21		
	REF: See Workcard	ENC		N:0			1275		
742001-0102	NO. 2 ENGINE - OUTBOARD IGNITER PLUG 3038110-6	MOS		N:0			28-NOV-2018 2236:21 1275		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			2236:21		
	REF: See Workcard	ENC		N:0			1275		
742002-0101	NO. 2 ENGINE - INBOARD IGNITER LEAD PN	MOS		N:0			31-DEC-2010 0 0		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	ENC		N:0			0		
742002-0102	NO. 2 ENGINE - OUTBOARD IGNITER LEAD PN	MOS		N:0			31-DEC-2010 0 0		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	ENC		N:0			0		

CHAPTER 75

AIR

ENGINE NO. 1 Model : AS907-1-1A Serial # P118773 Part # 3030001-4

75-20-00-201 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE BUFFER AIR TUBES PKG 17	MOS	4800	+100			PKG 31-DEC-2010 0 0		
	REF: See Workcard	ENC					0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
75-20-00-202 (s)	NO. 1 ENGINE - FUNCTIONAL TEST OF THE COOLING TUBE CHECK VALVES PKG 14	MOS					PKG		
MRB	REF: See Workcard	HRS/MSC 4200 ENC					31-DEC-2010 0 0		
75-20-00-203	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE LP TURBINE COOLING TUBES AND ATTACHMENT HARDWARE	MOS					PKG		
	REF: AMM 75 20 00 210 802	HRS/MSC 2000 ENC	+40/-40				07-DEC-2017 1913:50 1121	(3913:50) 3902:17	3953:50
75-31-09-201 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE COMPRESSOR GUIDE-VANE ACTUATOR SYSTEM PKG 17	MOS					PKG		
	REF: See Workcard	HRS/MSC 4800 ENC	+100				31-DEC-2010 0 0		
755391	NO. 1 ENGINE - T2 SENSOR 3038200-6 1016901731969	MOS					PKG		
	REF: See Workcard	HRS/MSC O/C ENC		N:0 N:0 N:0			31-DEC-2010 0 0		
ENGINE NO. 2 Model : AS907-1-1A Serial # P118771 Part # 3030001-4									
75-20-00-201 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE BUFFER AIR TUBES PKG 17	MOS					PKG		
	REF: See Workcard	HRS/MSC 4800 ENC	+100				31-DEC-2010 0 0		
75-20-00-202 (s)	NO. 2 ENGINE - FUNCTIONAL TEST OF THE COOLING TUBE CHECK VALVES PKG 14	MOS					PKG		
MRB	REF: See Workcard	HRS/MSC 4200 ENC					31-DEC-2010 0 0		
75-20-00-203	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE LP TURBINE COOLING TUBES AND ATTACHMENT HARDWARE	MOS					PKG		
	REF: AMM 75 20 00 210 802	HRS/MSC 2000 ENC	+40/-40				07-DEC-2017 1913:50 1121	(3913:50) 3902:17	3953:50



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
75-31-09-201 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE COMPRESSOR GUIDE-VANE ACTUATOR SYSTEM PKG 17	MOS					PKG	31-DEC-2010	
	REF: See Workcard	HRS/MSC ENC	4800	+100				0	0
755391	NO. 2 ENGINE - T2 SENSOR 3038200-6	MOS						31-DEC-2010	
	1016901731972	HRS/MSC ENC	O/C					0	0
	REF: See Workcard							0	0
CHAPTER 76 ENGINE CONTROLS									
76-10-01-201 (s)	OPERATIONAL TEST OF THE FULL THROTTLE RANGE PKG 9	MOS					PKG	23-DEC-2019	
76.010	REF: AMM 76 10 01 710 802	HRS/MSC AFL	800	+40/-40				2630:03	1481
MRB									
761001	CENTER PEDESTAL A51 THROTTLE QUADRANT ASSEMBLY 1007610001-017	MOS						28-JAN-2011	
	FR0354	HRS/MSC AFL	O/C					0	0
	REF: See Workcard							0	0
761005-0101	NO. 1 ENGINE ECU A ELECTRONIC ENGINE CONTROL UNIT 2119576-1011	MOS						28-JAN-2011	
	100-AA1153	HRS/MSC AFL	O/C					0	0
	REF:							0	0
761005-0102	NO. 1 ENGINE ECU B ELECTRONIC ENGINE CONTROL UNIT 2119576-1011	MOS						24-MAY-2018	
	93-T0068	HRS/MSC AFL	O/C					2023:09	1171
	REF:								
761005-0103	NO. 2 ENGINE ECU A ELECTRONIC ENGINE CONTROL UNIT 2119576-1011	MOS						28-JAN-2011	
	88-AA0804	HRS/MSC AFL	O/C					0	0
	REF:							0	0



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761005-0104	NO. 2 ENGINE ECU B ELECTRONIC ENGINE CONTROL UNIT 2119576-1011 110-AA1176 REF:	MOS HRS/MSC AFL	O/C				24-MAY-2018 2023:09 1171		
ENGINE NO. 1 Model : AS907-1-1A Serial # P118773 Part # 3030001-4									
76-10-05-200	NO. 1 ENGINE - DETAILED INSPECTION OF THE ECU PN 2119576-1010 AND 2119576-1011 REF:	MOS HRS/MSC ENC	4000	+100			31-DEC-2010 0 0	(4000) 3988:27	4100
76-10-10-200	NO. 1 ENGINE - GENERAL VISUAL INSPECTION PERMANENT MAGNET ALTERNATOR (PMA) PKG 6 REF: LMM 72-00-00	MOS HRS/MSC ENC	4000	+100			31-DEC-2010 0 0	(4000) 3988:27	4100
762001-0101	NO. 1 ENGINE - N1 OVERSPEED SHUT-OFF DETECTOR 3034256-5 17-162151-00570 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	15000		N:1 N:0 N:0		06-APR-2018 1974:15 1160	(16974:15) 16962:42	
ENGINE NO. 2 Model : AS907-1-1A Serial # P118771 Part # 3030001-4									
76-10-05-200	NO. 2 ENGINE - DETAILED INSPECTION OF THE ECU PN 2119576-1010 AND 2119576-1011 REF:	MOS HRS/MSC ENC	4000	+100			31-DEC-2010 0 0	(4000) 3988:27	4100
76-10-10-200	NO. 2 ENGINE - GENERAL VISUAL INSPECTION PERMANENT MAGNET ALTERNATOR (PMA) PKG 6 REF: LMM 72-00-00	MOS HRS/MSC ENC	4000	+100			31-DEC-2010 0 0	(4000) 3988:27	4100
762001-0101	NO. 2 ENGINE - N1 OVERSPEED SHUT-OFF DETECTOR 3034256-4 14-162151-01558 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	15000		N:10 N:0 N:0		06-APR-2018 1974:15 1159	(16974:15) 16962:42	

CHAPTER 77 ENGINE INDICATING

ENGINE NO. 1 Model : AS907-1-1A Serial # P118773 Part # 3030001-4

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
77-10-05-200	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE N2 SPEED SENSOR PN PKG 6 SN-UNKNOWN REF: LMM 72-00-00	MOS HRS/MSC ENC	4000	+100			31-DEC-2010 0 0	(4000) 3988:27	4100
771005-0101	NO. 1 ENGINE - N2 SPEED SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
773001-0101	NO. 1 ENGINE - VIBRATION SENSOR TRANSDUCER 3038503-2 1016328720761 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		

ENGINE NO. 2 Model : AS907-1-1A Serial # P118771 Part # 3030001-4

77-10-05-200	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE N2 SPEED SENSOR PN PKG 6 SN-UNKNOWN REF: LMM 72-00-00	MOS HRS/MSC ENC	4000	+100			31-DEC-2010 0 0	(4000) 3988:27	4100
771005-0101	NO. 2 ENGINE - N2 SPEED SENSOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
773001-0101	NO. 2 ENGINE - VIBRATION SENSOR TRANSDUCER 3038503-2 1016328720759 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		

CHAPTER 78 EXHAUST

78-30-00-201-1 (s)	DETAILED INSPECTION LEFT THRUST REVERSER SEALS PKG 14	MOS HRS/MSC	4200	+40/-40			PKG 28-JAN-2011 0		
MRB	REF: AMM 78 30 00 220 802	AFL					0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-30-00-201-2 (s)	DETAILED INSPECTION RIGHT THRUST REVERSER SEALS PKG 14	MOS HRS/MSC	4200	+40/-40			PKG 28-JAN-2011 0		
MRB	REF: AMM 78 30 00 220 802	AFL					0		
78-30-00-202-1 (s)	GENERAL VISUAL INSPECTION LEFT THRUST REVERSER PKG 14	MOS HRS/MSC	4200	+40/-40			PKG 28-JAN-2011 0		
MRB	REF: AMM 78 30 00 210 802	AFL					0		
78-30-00-202-2 (s)	GENERAL VISUAL INSPECTION RIGHT THRUST REVERSER PKG 14	MOS HRS/MSC	4200	+40/-40			PKG 28-JAN-2011 0		
MRB	REF: AMM 78 30 00 210 802	AFL					0		
78-30-00-203-1 (s)	DETAILED INSPECTION LEFT THRUST REVERSER FIREWALL PKG 12	MOS HRS/MSC	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 78 30 00 220 801	AFL							
78-30-00-203-2 (s)	DETAILED INSPECTION RIGHT THRUST REVERSER FIREWALL PKG 12	MOS HRS/MSC	2400	+40/-40			PKG 06-DEC-2018 2236:21 1275		
MRB	REF: AMM 78 30 00 220 801	AFL							
78-31-00-201-1 (s)	DETAILED INSPECTION LEFT THRUST REVERSER PIVOT DOOR MOUNTING-BEAMS PKG 14	MOS HRS/MSC	4200	+40/-40			PKG 28-JAN-2011 0		
MRB	REF: AMM 78 31 00 220 801	AFL					0		
78-31-00-201-2 (s)	DETAILED INSPECTION RIGHT THRUST REVERSER PIVOT DOOR MOUNTING-BEAMS PKG 14	MOS HRS/MSC	4200	+40/-40			PKG 28-JAN-2011 0		
MRB	REF: AMM 78 31 00 220 801	AFL					0		
78-31-00-202 (s)	DETAILED INSPECTION PIVOT DOORS PKG 14	MOS HRS/MSC	4200	+40/-40			PKG 28-JAN-2011 0		
MRB	REF: AMM 78 31 00 220 802	AFL					0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-32-00-201 (s)	DETAILED INSPECTION S HOOK ASSEMBLIES PKG 14	MOS HRS/MSC	4200	+40/-40			PKG 28-JAN-2011 0		
MRB	REF: AMM 78 32 00 220 801	AFL					0		
78-32-00-202 (s)	DETAILED INSPECTION PIVOT DOOR HOOKS PKG 14	MOS HRS/MSC	4200	+40/-40			PKG 28-JAN-2011 0		
MRB	REF: AMM 78 32 00 220 802	AFL					0		
78-32-00-203 (s)	DETAILED INSPECTION PIVOT DOOR ACTUATORS AND ATTACHMENT HARDWARE PKG 14	MOS HRS/MSC	4200	+40/-40			PKG 28-JAN-2011 0		
MRB	REF: AMM 78 32 00 220 803	AFL					0		
78-32-00-204 (s)	DETAILED INSPECTION ELECTRO-HYDRAULIC LOCK ASSEMBLY PKG 14	MOS HRS/MSC	4200	+40/-40			PKG 28-JAN-2011 0		
MRB	REF: AMM 78 32 00 220 804	AFL					0		
78-32-00-205 (s)	DETAILED INSPECTION HYDRAULIC LOCK ASSEMBLY PKG 14	MOS HRS/MSC	4200	+40/-40			PKG 28-JAN-2011 0		
MRB	REF: AMM 78 32 00 220 805	AFL					0		
78-32-00-306 (s)	OPERATIONAL TEST PIVOT-DOOR ACTUATOR INTERNAL-LOCK PKG 11	MOS HRS/MSC	1600	+40/-40			PKG 20-MAY-2016 1581:47		
MRB	REF: AMM 78 32 00 710 801	AFL					936		
78-32-00-307 (s)	OPERATIONAL TEST ELECTRO-HYDRAULIC LOCK ASSEMBLY PKG 14	MOS HRS/MSC	4200	+40/-40			PKG 28-JAN-2011 0		
MRB	REF: AMM 78 32 00 710 802	AFL					0		
78-33-00-201-1 (s)	GENERAL VISUAL INSPECTION LEFT THRUST-REVERSER WIRING HARNESS PKG 14	MOS HRS/MSC	4200	+40/-40			PKG 28-JAN-2011 0		
MRB	REF: AMM 78 33 00 210 801	AFL					0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-33-00-201-2 (s)	GENERAL VISUAL INSPECTION RIGHT THRUST-REVERSER WIRING HARNESS PKG 14	MOS HRS/MSC	4200	+40/-40			PKG 28-JAN-2011 0		
MRB	REF: AMM 78 33 00 210 801	AFL					0		
78-33-00-202 (s)	DETAILED INSPECTION PIVOT-DOOR STOW-SWITCH STRIKER BRACKETS PKG 14	MOS HRS/MSC	4200	+40/-40			PKG 28-JAN-2011 0		
MRB	REF: AMM 78 33 00 220 801	AFL					0		
78-ZL-00-201 (s)	GENERAL VISUAL INSPECTION LEFT/RIGHT THRUST REVERSER (THRUST REVERSER DEPLOYED) PKG 4	MOS HRS/MSC	48	+1m/-1m			PKG 23-DEC-2019 2630:03		
MRB	REF: AMM 78 30 00 210 801	AFL					1481		
783002-0101	THRUST REVERSER 13A012-01-0G TR657	MOS HRS/MSC	O/C				06-APR-2018 1974:15		
	REF: See Workcard	AFL					1149		
783002-0102	THRUST REVERSER 13A013-01-0G TR658	MOS HRS/MSC	O/C				06-APR-2018 1974:15		
	REF: See Workcard	AFL					1149		
783101-0101	LEFT UPPER THRUST REVERSER DOOR ASSEMBLY 13E117-01-6U	MOS		N:0			28-JAN-2011		
	AS1326	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
783101-0102	RIGHT UPPER THRUST REVERSER DOOR ASSEMBLY 13E118-01-6U	MOS		N:0			28-JAN-2011		
	AS1328	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
783105-0101	LEFT LOWER THRUST REVERSER DOOR ASSEMBLY 13E103-06-6U	MOS		N:0			28-JAN-2011		
	AS1327	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783105-0102	RIGHT LOWER THRUST REVERSER DOOR ASSEMBLY 13E103-06-6U AS1329 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783201-0101	DIRECTION CONTROL UNIT P519A0001-01 A0093108 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783201-0102	DIRECTION CONTROL UNIT P519A0001-01 A0091122 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783202-0101	LEFT UPPER THRUST REVERSER PIVOT DOOR ACTUATOR P517A0001-05 A0094203 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783202-0102	RIGHT UPPER THRUST REVERSER PIVOT DOOR ACTUATOR P517A0001-05 A0094206 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783202-0103	LEFT LOWER THRUST REVERSER PIVOT DOOR ACTUATOR P517A0001-05 A0094289 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783202-0104	RIGHT LOWER THRUST REVERSER PIVOT DOOR ACTUATOR P517A0001-05 A0094207 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783205-0101	RIGHT THRUST REVERSER PRIMARY LOCK P520A0001-00 A0093706 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783205-0102	LEFT THRUST REVERSER PRIMARY LOCK P520A0001-00 A0093704 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783205-0201	LEFT THRUST REVERSER ELECTRO-HYDRAULIC PRIMARY LOCK P521A0001-01 A0093795 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783205-0202	RIGHT THRUST REVERSER ELECTRO-HYDRAULIC PRIMARY LOCK P521A0001-01 A0093797 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783207-0101	THRUST REVERSER ISOLATION CONTROL UNIT P518A0001-00 AAA624P518 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783207-0102	THRUST REVERSER ISOLATION CONTROL UNIT P518A0001-00 AAA625P518 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783301-0101	LH THRUST-REVERSER DOOR STOW SWITCH ASSEMBLY 83-990-168 15085 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783301-0102	LH THRUST-REVERSER DOOR STOW SWITCH ASSEMBLY 83-990-168 15087 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783301-0103	LH THRUST-REVERSER DOOR STOW SWITCH ASSEMBLY 83-990-168 15090 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783301-0104	LH THRUST-REVERSER DOOR STOW SWITCH ASSEMBLY 83-990-168 15091 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783301-0105	RH THRUST-REVERSER DOOR STOW SWITCH ASSEMBLY 83-990-168 15084 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783301-0106	RH THRUST-REVERSER DOOR STOW SWITCH ASSEMBLY 83-990-168 15086 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783301-0107	RH THRUST-REVERSER DOOR STOW SWITCH ASSEMBLY 83-990-168 15088 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783301-0108	RH THRUST-REVERSER DOOR STOW SWITCH ASSEMBLY 83-990-168 15089 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783301-0201	LH THRUST-REVERSER DOOR DEPLOY SWITCH ASSEMBLY 83-990-140 1399 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783301-0202	LH THRUST-REVERSER DOOR DEPLOY SWITCH ASSEMBLY 83-990-140 1398 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783301-0203	RH THRUST-REVERSER DOOR DEPLOY SWITCH ASSEMBLY 83-990-140 1400 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783301-0204	RH THRUST-REVERSER DOOR DEPLOY SWITCH ASSEMBLY 83-990-140 1401 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
783306-0101	MULTIPLEXER HARNESS ASSEMBLY 13W007-04-0U 366 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:63 N:1557:51 N:926			13-APR-2016 1557:51 926		
783306-0102	MULTIPLEXER HARNESS ASSEMBLY 13W007-04-0U 362 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:63 N:1557:51 N:926			13-APR-2016 1557:51 926		

ENGINE NO. 1 Model : AS907-1-1A Serial # P118773 Part # 3030001-4

78-11-00-201 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE MIXER NOZZLE AND CENTER BODY PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
783001-0101	NO. 1 ENGINE - THRUST REVERSER MAINTENANCE SWITCH ASSEMBLY 3038459-4 1015154500700 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		

ENGINE NO. 2 Model : AS907-1-1A Serial # P118771 Part # 3030001-4

78-11-00-201 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE MIXER NOZZLE AND CENTER BODY PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
783001-0101	NO. 2 ENGINE - THRUST REVERSER MAINTENANCE SWITCH ASSEMBLY 3038459-4 100824600661 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		

CHAPTER 79 OIL

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793013-0101	LEFT ENGINE GEARBOX - REMOTE OIL LEVEL INDICATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
793013-0102	RIGHT ENGINE GEARBOX - REMOTE OIL LEVEL INDICATOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			28-JAN-2011 0 0		
ENGINE NO. 1 Model : AS907-1-1A Serial # P118773 Part # 3030001-4									
79-20-00-201 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE EXTERNAL PLUMBING OF THE OIL SYSTEM PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
79-20-00-202 (s)	NO. 1 ENGINE - DISCARD ENGINE OIL PKG 11 DISCARD REF: AMM 79 10 00 961 801	MOS HRS/MSC ENC	1600	+40/-40			PKG 20-MAY-2016 1581:47 947		
79-20-05-201 (s)	NO. 1 ENGINE - DISCARD ENGINE OIL FILTER ELEMENT PKG 9 DISCARD REF: See Workcard	MOS HRS/MSC ENC	800	+40/-40			PKG 23-DEC-2019 2641:36 1492		
793009-0101	NO. 1 ENGINE - OIL PRESSURE TRANSDUCER 3038700-3 1016206700119 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			31-DEC-2010 0 0		
ENGINE NO. 2 Model : AS907-1-1A Serial # P118771 Part # 3030001-4									
79-20-00-201 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE EXTERNAL PLUMBING OF THE OIL SYSTEM PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		

Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-20-00-202 (s)	NO. 2 ENGINE - DISCARD ENGINE OIL PKG 11	MOS					PKG		
DISCARD	REF: AMM 79 10 00 961 801	HRS/MSC ENC	1600	+40/-40			20-MAY-2016 1581:47 946		
79-20-05-201 (s)	NO. 2 ENGINE - DISCARD ENGINE OIL FILTER ELEMENT PKG 9	MOS					PKG		
DISCARD	REF: See Workcard	HRS/MSC ENC	800	+40/-40			23-DEC-2019 2641:36 1491		
793009-0101	NO. 2 ENGINE - OIL PRESSURE TRANSDUCER 3038700-3 1016206700043	MOS							
	REF: See Workcard	HRS/MSC ENC	O/C		N:0 N:0 N:0		31-DEC-2010 0 0		
CHAPTER 80 STARTING									
801101-0101	LH ENGINE AIR TURBINE STARTER 3506000-4 853	MOS							
	REF: See Workcard	HRS/MSC AFL	O/C		N:0 N:0 N:0		28-JAN-2011 0 0		
801101-0102	RH ENGINE AIR TURBINE STARTER 3506000-4 846	MOS							
	REF: See Workcard	HRS/MSC AFL	O/C		N:0 N:0 N:0		28-JAN-2011 0 0		
ENGINE NO. 1 Model : AS907-1-1A Serial # P118773 Part # 3030001-4									
80-11-00-202 (s)	NO. 1 ENGINE - CHANGE ENGINE AIR TURBINE STARTER OIL DISCARD PKG 8	MOS					PKG		
DISCARD	REF: See Workcard	HRS/MSC ENC	600	+40/-40			23-DEC-2019 2641:36 1492		
80-11-00-203 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE AIR TURBINE STARTER PKG 8	MOS					PKG		
	REF: See Workcard	HRS/MSC ENC	600	+40/-40			23-DEC-2019 2641:36 1492		



Status Report

CH 300 S/N 20317 (RA-67250): 2765:48 HRS, 1553 AFL as of 27-Jul-2020

Owner/Operator: AVIATIS LLC

Report Date: 28-JUL-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
80-11-00-204 (s)	NO. 1 ENGINE - DETAILED INSPECTION ENGINE AIR TURBINE STARTER PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
80-11-00-205 (s)	NO. 1 ENGINE - DETAILED INSPECTION ENGINE AIR TURBINE STARTER MAGNETIC DRAIN PLUG PKG 10 REF: AMM 80 11 00 220 802	MOS HRS/MSC ENC	1200	+40/-40			PKG 06-DEC-2018 2236:21 1286		
ENGINE NO. 2 Model : AS907-1-1A Serial # P118771 Part # 3030001-4									
80-11-00-202 (s)	NO. 2 ENGINE - CHANGE ENGINE AIR TURBINE STARTER OIL DISCARD PKG 8 DISCARD REF: See Workcard	MOS HRS/MSC ENC	600	+40/-40			PKG 23-DEC-2019 2641:36 1491		
80-11-00-203 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE AIR TURBINE STARTER PKG 8 REF: See Workcard	MOS HRS/MSC ENC	600	+40/-40			PKG 23-DEC-2019 2641:36 1491		
80-11-00-204 (s)	NO. 2 ENGINE - DETAILED INSPECTION ENGINE AIR TURBINE STARTER PKG 17 REF: See Workcard	MOS HRS/MSC ENC	4800	+100			PKG 31-DEC-2010 0 0		
80-11-00-205 (s)	NO. 2 ENGINE - DETAILED INSPECTION ENGINE AIR TURBINE STARTER MAGNETIC DRAIN PLUG PKG 10 REF: AMM 80 11 00 220 802	MOS HRS/MSC ENC	1200	+40/-40			PKG 06-DEC-2018 2236:21 1285		