



NASA TM-81586

NASA Technical Memorandum 81586

NASA-TM-81586 19800024596

Nonanalytic Function Generation Routines for 16-Bit Microprocessors


James F. Soeder and Maryrita Shauffl
Lewis Research Center
Cleveland, Ohio

September 1980

LIBRARY COPY

DEC 8 1980

CLEVELAND RESEARCH CENTER
LIBRARY, NASA
CLEVELAND, OHIO



NONANALYTIC FUNCTION GENERATION ROUTINES

FOR 16-BIT MICROPROCESSORS

by James F. Soeder and Maryrita Shauf1

Lewis Research Center

SUMMARY

This report describes various interpolation techniques for three types of nonanalytic functions: univariate, bivariate, and map. These interpolation techniques are then implemented in scaled-fraction arithmetic on a representative 16-bit microprocessor. This work was done on an Intel 8086; however, the programs can be modified for use with any 16-bit microprocessor. A Fortran program is described that facilitates the scaling, documentation, and organization of data for use by these routines. Listings of all these programs are included in an appendix to the report.

INTRODUCTION

As microprocessors become more sophisticated, they will be used in increasingly complex applications. Specifically, advanced third-generation microprocessors such as the Zilog 8000, the Motorola 68000, and the Intel 8086 look more like minicomputers than like the programmable digital controllers that were characteristic of their predecessors. Therefore these third-generation microprocessors will be called on to control and simulate systems that require increasingly complex calculations in less and less time. One common type of calculation that is required in the simulation and control of a system such as a gas turbine engine is high-speed nonanalytic function generation. A nonanalytic function is taken here to mean any function of one or two variables that can be described by a table of values.

This function generation is accomplished by a program that can interpolate univariate, bivariate, and map functions rapidly enough to provide stable operation of the system. In many cases the generation of nonanalytic functions must be done as fast as possible. The current third-generation microprocessors can do this most economically by using assembly language and scaled-fraction arithmetic. Although the time required to write and debug these assembly language programs is somewhat greater than that required for high-level language programs, the resulting programs will be faster. In addition, if their calling sequences are general enough, they can be used in other applications, even those including high-level languages. The drawback of using scaled-fraction arithmetic can be overcome very easily by using a Fortran program to scale data. The program can accept the function data in engineering unit form, scale the data, and output them to a file that can be directly assembled by an assembler. By processing data in this automatic manner manual transcription and scaling errors can be virtually eliminated.

E-565

N80-33104#

This report describes three general function types: univariate, bivariate, and map. It then characterizes the interpolation techniques for each type of function. These interpolation techniques are similar to the techniques discussed in reference 1. Next, assembly language routines for function generation, which were written for the Intel 8086, are examined. Although the routines are specific to this 16-bit microprocessor, it is merely used as a demonstration vehicle. The ideas and concepts can be applied to any microprocessor with a 16-bit architecture and fixed-point-hardware, multiply-and-divide capability. Finally, the Fortran program that takes data in engineering units and converts them to scaled-fraction form is described. Listings of all these programs are included in the appendix.

DESCRIPTION OF NONANALYTIC FUNCTION TYPES

There are three basic types of functions that are considered in advanced microprocessor applications: Univariate, bivariate, and map. Descriptions of each function and their various interpolation techniques follow.

Univariate Function

A univariate function is the simplest type of nonlinear relationship. Figure 1 shows an example of a univariate function. It merely consists of a set of output values y , corresponding to a set of input values x . The computation of an intermediate y value corresponding to a particular x is done simply by using the linear interpolation equation

$$y_V = \left(\frac{x_V - x_L}{x_H - x_L} \right) (y_H - y_L) + y_L \quad (1)$$

where the definitions of the x 's and y 's are shown in figure 1. This simple interpolation equation can be implemented in one of two ways. First, one can store a set of scaled x and y points and compute equation (1) directly. Second, one can rewrite equation (1) in the following form:

$$y_V = m(x_V) + b \quad (2)$$

where

$$m = \left(\frac{y_H - y_L}{x_H - x_L} \right)$$

and

$$b = y \text{ intercept}$$

In other words, for each function segment that is defined by two breakpoints, a linear equation can be written. The slope of the segment is computed in a straightforward manner, and the y intercept is the point where the extension of the segment under consideration would intersect the y axis. Once the m 's and b 's are computed off line, they are stored along with the x 's and then used with equation (2) to generate the function. For simplicity of reference the first method is called FUN1 and the second NEFG.

FUN1 has the advantages of being straightforward, being easy to scale, and using a smaller amount of memory storage than NEFG. NEFG has the advantage of being faster because the divide operation necessary to compute the slope has been eliminated. However, NEFG does require considerably more storage per function and more off-line computation to determine the correct m's and b's. The tedium of this computation can be eliminated by using the Fortran program described later, in the section FORTRAN DATA PROCESSING.

Bivariate Function

An example of a specialized bivariate function is presented in figure 2. In this nonlinear function the output value y is dependent on two inputs, x and z . The curves, each of which has a particular value of z , have the same number of breakpoints. However, breakpoints occur at the same values of x . This simplifies the interpolation of this bivariate function. Therefore one only needs to perform a FUN1 type of univariate function routine on each of the z curves in order to find new y values for the input x and then to interpolate the two y values by using the z input. This procedure can be summarized by the following equations and reference to figure 3:

$$y_V = f(x_V, z_V)$$

$$y_L = \left(\frac{x_V - x_L}{x_H - x_L} \right) (y_B - y_A) + y_A \quad (3)$$

$$y_H = \left(\frac{x_V - x_L}{x_H - x_L} \right) (y_D - y_C) + y_C \quad (4)$$

$$y_V = \left(\frac{z_V - z_L}{z_H - z_L} \right) (y_H - y_L) + y_L \quad (5)$$

where all the x 's, y 's, and z 's are defined in figure 3. These equations can be manipulated in a straightforward manner to produce the output of the specialized bivariate function. Implementation of this method is called FUN2. A method could be devised that uses an NEFG interpolation technique to generate y_L and y_H . However, the scaling and storage requirements become quite cumbersome. This negates the time advantage gained by eliminating the divide operation required in equations (3) and (4).

Map Function

An example of a map function is shown in figure 4. These functions are similar to the bivariate ones because they have the same number of points for every z curve. However, in map functions each curve can have a unique set of x and y breakpoints. Because of this, one cannot use the simple interpolation technique that worked for the bivariate function; that is, since the x -coordinate did not change from curve to curve, one only had to compute two new y values and interpolate on z . However, for a map function, one must

compute the position that a curve would have if it had the desired value of z . This is done by implementing the following series of five equations with reference to figure 5:

$$y_V = f(x_V, z_V)$$

$$x_F = x_C + \left(\frac{z_V - z_L}{z_H - z_L} \right) (x_B - x_C) \quad (6)$$

$$x_G = x_D + \left(\frac{z_V - z_L}{z_H - z_L} \right) (x_E - x_D) \quad (7)$$

$$y_F = y_C + \left(\frac{z_V - z_L}{z_H - z_L} \right) (y_B - y_C) \quad (8)$$

$$y_G = y_D + \left(\frac{z_V - z_L}{z_H - z_L} \right) (y_E - y_D) \quad (9)$$

$$y_V = y_F + \left(\frac{x_V - x_F}{x_G - x_F} \right) (y_G - y_F) \quad (10)$$

where all the x 's, y 's, and z 's are as defined in figure 5. These equations can then be implemented directly. This interpolation technique is referred to as FUN3.

DESCRIPTION OF ROUTINE IMPLEMENTATION

The assembly language implementation of the four interpolation techniques is done in a straightforward manner. These routines can be called either from an assembly language program or from a high-level language program written in Intel's PL/M-86 (refs. 2 and 3). In the former case, parameters are passed back and forth by using registers. In the latter, parameters are passed to the routine on the stack and returned to the calling program by the AX register (the accumulator). These routines were written for the Intel 8086 implementations, which use up to 64K of memory. Some changes would be necessary if the programs are to be used in the full 1-megabyte memory environment. Complete listings of the programs are given in the appendix and individual details are covered below.

Univariate Functions (FUN1)

The FUN1 routine is the implementation of the first method of univariate function lookup. Several features of the program are worth mentioning. The first feature is the format used to store the data, an example of which is shown in figure 6. By having minus and plus full scale at each end of the data there is no need to selectively limit the x input. However, a maximum

check is made to make sure the input x value is not equal to 32767 and, if it is, to decrease the value by 1 bit. This prevents the routine from getting lost looking for a value that is greater than or equal to 32767. (See FUN1 label point in program listing.)

The second feature is that the routine has three entry points: PFUN1, FUN1, and FUN1A. PFUN1 is used to pass parameters by using the stack. This is the method that would be used from a call by a PL/M-86 program. FUN1 is used when parameters are passed through the registers, as would be done in an assembly language call. FUN1A should be used as an entry point to look up another function that has the same x breakpoints but different y breakpoints (as shown by the example format of fig. 7), and the x input values for both the functions are the same. With the FUN1A call the next function can be looked up by using the index values and slope factors that have already been passed to, or computed by, the program. This is useful because, once one computes the interpolation factor of equation (1), much of the computation is done.

The third feature is that this routine passes a new table pointer to the calling program along with the interpolated value. By passing a new table pointer to the calling program, on the next call of this particular function the FUN1 program will not have to search from the beginning of the table for the upper and lower bound of the interpolation. This makes the overall interpolation time less since the present interpolation interval will probably be within the same interval or one interval away from the last interpolation interval. The passing of a table's x index value is done indirectly from within the routine. This is the violation of the PL/M-86 compiler's block structure rules governing the change of formal calling parameters by an external procedure (ref. 3). However, if one is aware that this updating is being done, it should pose no particular problem, and a good deal of computation time will be saved.

Finally, shifts are made in the program at strategic places to assure that when dealing with fixed-point numbers no overflows will occur and produce erroneous results. This can happen in two different cases. First, if the most significant half of the dividend is greater than, or equal to, half the divisor, an overflow will occur. Second, if two adjacent x breakpoints are present that have an absolute distance greater than 32767 (i.e., -18000 and 17000), a subtract overflow will occur. The first overflow problem can be eliminated by right-arithmetic shifting the dividend an appropriate number of places before the divide. The second can be eliminated by noting that the interpolation factor must always be positive. Therefore, if the interpolation factor is computed by using an unsigned divide, subtract overflows make no difference.

Univariate Functions (NEFG)

The other univariate function routine, NEFG, has many of the same features as the FUN1 routine. It has a calling sequence for a PL/M-86 transfer, PNEFG, and one for an assembly language transfer, NEFG. In addition, it has the capability to pass back the table index value that points to the current interpolation interval in much the same manner as FUN1. Like the index in FUN1, this provides for speedup the next time the function is called.

The data storage method in this routine, however, is quite different from that in FUN1. Figure 8 presents an example of the NFG data storage format. The x and y values are single precision. However, the b values are double precision and therefore take up two word locations. The reason for the double-precision storage can be seen from the scaling that must be done:

$$y \left(\frac{A}{C} \right) = m \left(\frac{D}{E} \right) x \left(\frac{F}{G} \right) + b \left(\frac{A}{C} \right) \quad (11)$$

where (A/C) , (D/E) , and (F/G) are the scale factors of the respective variables. Reflecting on this relationship, since

$$-32768 \leq y \left(\frac{A}{C} \right) \leq 32767 \quad \text{for all } y \quad (12)$$

$$-32768 \leq x \left(\frac{F}{G} \right) \leq 32767 \quad \text{for all } x \quad (13)$$

then

$$-32768 \leq m \left(\frac{D}{E} \right) \leq 32767 \quad \text{for all } m \quad (14)$$

$$-32768 \leq b \left(\frac{A}{C} \right) \leq 32767 \quad \text{for all } b \quad (15)$$

must be true. However, it cannot always be guaranteed that conditions (14) and (15) can be met. Therefore the scale factors must be adjusted by a factor k :

$$-32768 \leq m \left(\frac{D}{E} \right) \frac{1}{k} \leq 32767$$

$$-32768 \leq b \left(\frac{A}{C} \right) \frac{1}{k} \leq 32767$$

The k factor can be made anything, but making it a power of 2 allows simple shifting to implement it. The exact calculation sequence for computing the k 's for each function is described in the section Scaling Section; but if the sequence yields a k other than 1, the final answer must be left-shifted that many times outside the routine. This will not yield an overflow since by definition the final answer y must lie between -32768 and 32767 . Therefore it is necessary to make the b values double precision because sometimes the number of shifts becomes as large as five or six. Making this many shifts in single precision could cause an intolerable reduction in accuracy. In an assembly language call the required double-word left shifts can be implemented directly in the calling program. For a PL/M-86 call subroutine SHFT is provided to do the shifts the appropriate number of times. A listing of this routine is given in the appendix. Finally, note that there is no economy associated with computing two functions in the piggyback style of FUN1 and FUN1A. This is because of the complexity involved in computing the new m and b entry points.

Bivariate Function (FUN2)

The FUN2 routine is a straightforward implementation of equations (3) to (5). This routine, like FUN1, has three entry points - FUN2, PFUN2, and FUN2A. The PFUN2 call uses the stack to pass all calling parameters. However, the FUN2 call uses the registers and the stack to pass parameters and thereby reduce calling overhead. Since the routine uses two FUN1 lookups, it implements logical shifts and unsigned divides in the same critical places as FUN1 to avoid overflow problems. Figure 9 presents an example of the FUN2 data storage format. In this format each row of y's corresponds to the respective x's at a particular z. The first and last rows of y data are the same as the row that follows or precedes them, respectively. This allows implicit limiting of the z input in the same manner as the x input. The routine also employs both an x and z index value that is passed to the calling program. These index values allow the routine to be close to the area where the function interpolation will take place on the next call. Finally, a FUN2A call sequence is provided, which allows the computation of a new y if the input x and z values, and hence the interpolation factors, are the same as those for the previous curve.

Map Function (FUN3)

The FUN3 routine, like FUN2, is a straightforward implementation of equations (6) to (10). This routine, also like FUN2, has two entry points, PFUN3 and FUN3, for various parameter passing options. However, it passes back only the interpolated output and the z index pointer. Since the x index pointer could be different depending on the two z curve values used in the interpolation, it was decided that passing two pointers back to the calling program would be too cumbersome for any advantage it might provide.

An example of the data format for FUN3 is shown in figure 10. The data in this figure describe a map that has four z curves with three (x,y) break-points for each curve. Note that in this data storage format the curves are limited in the x direction by putting in the x value maximum and minimum limits (32767 and -32768). However, for the z values the limits must be imposed outside the routine. Otherwise, when the z search commences, the z pointer would be lost if the z value were above or below the maximum or minimum z boundary point. This technique is used to contain the pointer since replicating the high and low curves as is done in FUN2 could result in unpredictable overflows. Finally, since map functions tend to be complex and difficult to handle, most of the time one would want to start computing from the beginning. Therefore no provision has been made for an entry point that uses interpolation factors already computed (i.e., FUN1A or FUN2A).

FORTRAN DATA PROCESSING

The use of Fortran programs to process the data needed for the function generation routines makes that job much easier and quicker. Three programs are used to limit, scale, and format the data. They are a main (or calling) program, a scaling routine, and an output routine. Since the scaling and output routines are general routines, any user-written main program containing data in engineering units can call them. The data for one curve are

passed to the scaling routine for each call. In the scaling routine the data and user options (other calling arguments) are analyzed, and the data are scaled and then output in both self-documenting tabular and Intel 8086 assembleable form. Even though the second output format was written for the Intel 8086, by changing a few format statements the user can easily adapt this output to any microprocessor, thus enhancing the flexibility of the routine.

The user can choose several options. Curves can have "flats" added (where x values of -32768 and/or 32767 are added and y values from the low or high end, respectively, are duplicated), or they can be extrapolated on either or both ends. The type of function routine (NEFG, FUN1, FUN1A, FUN2, or FUN3) that a curve represents can be specified. Also, the relocatable or absolute format for assembly code generation can now be chosen.

Main Program Data Format

The main program, as mentioned, contains the curve data and calls to the scaling routine INTSCL. The data are arranged in separate arrays by curve and contain seven pieces of information (fig. 11). These are (in order) x border specification (XB), x breakpoint specification (XBRKP), the number of x's per z curve, the number of z curves, x values, z values (if any), and y values. The x border specification indicates whether flats are to be added or the curve extrapolated: 0.0 for flats on both ends of the curve and no extrapolation, 1.0 for a flat on the low end and extrapolation of the high end, 2.0 for a flat on the high end and extrapolation of the low end, and 3.0 for no flats but extrapolation of both ends. The x breakpoint specification can have two values: 0.0 if the x breakpoint is the same for every z curve (i.e., NEFG, FUN1, and FUN2 functions) or 1.0 if the breakpoints are different (FUN3 function). The number of x's per z curve is specified by a real number, as is the number of z curves. In the latter parameter provision is made for either 0.0 or 1.0 to represent one z curve.

For NEFG and FUN1 curves the x, y, and z values are in a condensed format. The x values are listed and then the corresponding y values. No z values are required for the univariate function. A specific example of the data input format of figure 11 for a univariate curve with three points and a flat on each end is shown in figure 12. The formats for functions FUN2 and FUN3 are a little more complex. For FUN2, x values are as before listed first. Next the z values are listed and then the y's. However, the first row of y's corresponds to the first y value for each z curve. For FUN3 this same pattern is followed for z and y. The x's in this case are listed in the same manner as the y's. Figures 13 and 14 represent FUN2 and FUN3 data input formats for three z values and four x values. In these figures the first subscripts correspond to the x values and the second to the z values.

Calling Sequence

Referring to the Fortran listing, data array INFO is the first parameter in the call to the scaling program. The other parameters, listed in order by their variable names, in the INTSCL subroutine are TITLE, XNUM, XDNOM, YNUM,

YDNOM, ZNUM, ZDNOM, FUNC, FRMT, and ORG. TITLE, the eight-character title of the curve, is formulated in the main program. XNUM and XDNOM, the numerator and denominator of the scale factor for the x values, are specified as if machine units were being converted to engineering units. That is, XNUM = 150.0 and XDNOM = 32000.0 will give the correct scale factor (213.333) for the conversion of -153.600 engineering units into -32768 machine units. YNUM, YDNOM and ANUM, ZDNOM, the y and z scaling factors, respectively, are similarly specified. FUNC indicates which function routine the data array belongs to: 0 for NEFG, 1 for FUN1, 11 for FUN1A, 2 for FUN2, and 3 for FUN3. FRMT indicates the format of the assemblable output dataset. A zero represents a relocatable format and a 1, an absolute format. If 1 is specified, a value for the parameter ORG must also be specified, where ORG is the hexadecimal starting address of the data.

Scaling Subroutine INTSCL

When control is passed from the main program to the subroutine INTSCL, the actual scaling computation begins. Here the options specified by the user in the calling sequence are analyzed, data are scaled, and scaled data are output in two forms. The routine can be examined by looking at the parts of the program that perform the three main functions (analysis, scaling, and output) as three discrete sections. A functional flowchart of this program is shown in figure 15.

Analysis of Calling Parameters

The first of these program sections, the analysis section, begins by forming the data name arrays used on output. It then breaks the input data array into its several components and rearranges the x and y data. This rearrangement is done so that the type of curve being processed does not affect the routine's treatment of the data. Finally, flats are added and extrapolations performed as necessary. (For FUN2 only, z automatically has flats added to limit the z curve values.)

Scaling Section

In the scaling section, scale factors are computed and z, x, and y values scaled. The unscaled values are saved for later use in calculation and output, and all scaled values are checked against the minimum and maximum values of -32768 and 32767. No attempt is made to adjust the scale factors, but out-of-range values are set to either -32768 or 32767 and the appropriate warning message is written to notify the user.

The slope m and the y-intercept b values for NEFG are also calculated and scaled in this section. The maximum and minimum scaled values for both m and b are tested against the minimum and maximum of -32768 and 32767, but here an attempt is made to adjust the calculated scale factors by shifting and retesting. Thus the shift factor k mentioned in conjunction with the NEFG routine itself is produced. If right-shifting the original values by eight (dividing by 256) still does not bring the values into range, the attempt is

considered complete and a warning message is written to the user. Next, b values are separated into their most significant bits (MSB) and least significant bits (LSB) by taking their integer and fractional portions and scaling them separately. The integer part multiplied by the b scale factor is considered the most significant portion, and the fractional part multiplied by 65536 is considered the least significant portion.

Output Section

The output portion of the program writes the data out in two different formats. The first, self-documenting, format is a series of tables that include the curve type and name; any warning messages; scaling factors (both computed values and components); and x , y , m , and b values in both engineering units and machine units. Examples of FUN1 and NEFG tables are shown in figure 16. In figure 17 only the first page of the FUN2 and FUN3 tables is given. These require an additional page for each z value. These tables give at a glance all the information necessary to characterize a curve and to provide documentation for permanent storage.

The second format, shown in figure 18, is the scaled-data output in either relocatable or absolute format. (The absolute format differs from the relocatable format only in that an ORG statement with the specified hexadecimal address is the first line output for a curve.) The data name - consisting of an x , y , z , m , or b followed by the first six characters of the curve name (five for FUN1A curves) and a blank - is written on the first line, along with a "DW" and corresponding data. The next line written has a "DW" followed by more data, a format that is repeated until the data for that array are exhausted. The data output for each of the curves is written to the dataset in the particular formats discussed earlier.

Subroutine WRTDTA

Subroutine WRTDTA is called to write all the x and y arrays for the Intel 8086 assemblable format. Its calling sequence has five parameters: FUNARY, XPTS, DNAME, FNTN, and ZPTS. FUNARY is the array of scaled data to be written, XPTS the number of x points in the curve, and DNAME the data name associated with the array. FNTN is the parameter that differentiates function types (0 indicates NEFG, FUN1, or FUN1A; 1 indicates FUN2 or FUN3) and is used primarily as a check for the number of z points, specified by ZPTS.

Special-Purpose Routine

One other routine is called from both the main program and INTSCL. This routine, F4MVC, is a character manipulation routine resident on the IBM 360. Its calling sequence parameters are SSTRNG, L1, DSTRNG, L2, and NBYTES. SSTRNG is the source string, L1 the index of the first byte to be copied, DSTRNG the destination string, L2 the first byte to be replaced, and NBYTE the number of bytes to be copied. This routine simply moves characters, byte by byte, from one string to another and can therefore be replaced by a user-written Fortran program.

CONCLUDING REMARKS

This report has described several common nonanalytic function types and interpolation techniques that can be used on them. In addition, a fixed-point arithmetic, assembly language implementation of the routines was demonstrated by using the Intel 8086 microprocessor. The fixed-point arithmetic was used for the speed and hardware minimization it currently provides. Furthermore the routines were written in such a way as to provide high-speed lookup while freeing the user from being concerned by scaling overflows. Although these routines were written for the Intel 8086, the overflow and scaling techniques are general enough concepts to be used with any 16-bit microprocessor. Finally, a Fortran program was discussed that can be used in conjunction with these assembly language routines. This program can take data that are currently in a simulation deck or any engineering unit form and scale them into the proper integer values that can be used by the microprocessor. The program then scales all the necessary function data and outputs them to a dataset that can be processed by the assembler. In addition, the program outputs listings to document all the scaled data. Therefore by using these routines one can realize error-free translation of function curves from engineering unit data to scaled-fraction data that can be used by the microprocessor for real-time control or simulation.

REFERENCES

1. Hart, Clint E.: Function Generation Subprograms For Use In Digital Simulations. NASA TM X-71526, 1974.
2. Intel Corporation: MCS-86 Assembly Language Reference Manual. #9800640A.
3. Intel Corporation: PL/M-86 Programming Manual. #9800466A.

APPENDIX - NONANALYTIC FUNCTION GENERATION ROUTINES
AND FORTRAN SCALING PROGRAM

ISIS-II MCS-86 MACRO ASSEMBLER V2.1 ASSEMBLY OF MODULE FUN1
 OBJECT MODULE PLACED IN :F1:PFUN1.OBJ
 ASSEMBLER INVOKED BY: ASM86 :F1:PFUN1.SRC XREF DATE(3 SEPT 80)

```

LOC OBJ          LINE    SOURCE
                1      ;
                2      ;
                3      ;   SUBROUTINE FUN1 AND FUN1A FOR UNIVARIATE
                4      ;   FUNCTIONS LOOK-UP OF NON-EQUAL INCREMENT FUNCTIONS
                5      ;
                6      ;   CALL SEQUENCES FUN1
                7      ;
                8      ;   SI REGISTER CONTAINS THE NUMBER OF
                9      ;     POINTS IN THE TABLE
               10      ;   BX REGISTER CONTAINS THE X TABLE BASE ADDRESS
               11      ;   DI REGISTER CONTAINS THE X TABLE INDEX VALUE ADDRESS
               12      ;   AX REGISTER CONTAINS THE X VALUE
               13      ;   CALL FUN1
               14      ;
               15      ;
               16      ;
               17      ;   FOR FUN1A CALL DO NOT DESTROY BX,BP,SI,DI REGISTERS
               18      ;
               19      ;   THE Y VALUE OF THE CURVE IS RETURNED IN THE AX REGISTER
               20      ;
               21      ;   ***** BEWARE *****
               22      ;
               23      ;   THE X TABLE INDEX LOCATION IS AUTOMATICALLY UPDATED BY
               24      ;   BY THE ROUTINE AND THEREFORE DOESN'T FOLLOW THE PL/M-86
               25      ;   BLOCK STRUCTURE
               26      ;
               27      ;   *****
               28      ;
               29      ;   CALLING SEQUENCE FOR PL/M-86 CALL
               30      ;   RSLT = PFUN1(X,XBS,XINDX,NOPTS)
               31      ;
               32      ;   X= VALUE OF FUNCTION
               33      ;   XBS= X TABLE BASE ADDRESS
               34      ;   XINDX = ADDRESS OF X TABLE INDEX VALUE
               35      ;   NOPTS = NUMBER OF POINTS IN TABLE
               36      ;
               37      ;
               38      ;
               39      ;   *****
               40      ;
               41      ;       NAME    FUN1
               42      ;   CGROUP GROUP CODE
               43      ;       ASSUME CS:CGROUP
               44      ;       PUBLIC FUN1,FUN1A,PFUN1
               45      ;
               46      ;
               47      ;   CODE SEGMENT FOR ROUTINE
               48      ;
               49      ;   CODE SEGMENT PUBLIC 'CODE'
               50      ;   PROGRAM ENTRY IF ENTERED BY PL/M-86 CALL ROUTINE

```



```

LOC OBJ          LINE    SOURCE
                    51      ;
0000 5A          52      PFUN1:POP  DX      ; TEMP SAVE OF PC
0001 5E          53          POP  SI      ; NUMBER OF POINTS IN TABLE
0002 5F          54          POP  DI      ; ADDRESS OF TABLE INDEX
0003 5B          55          POP  BX      ; X TABLE BASE LOCATION
0004 58          56          POP  AX      ; X TABLE VALUE TO BE LOOK-UP
0005 52          57          PUSH DX      ; RESTORE PC TO THE STACK
                    58      ;
                    59      ;
                    60      ; PROGRAM ENTRY IF CALLED BY ASSEMBLY
                    61      ; LANGUAGE ROUTINE
                    62      ;
0006 8B15        63      FUN1: MOV  DX,[DI] ; MOVE ACTUAL INDEX VALUE TO DX
0008 87D7        64          XCHG DX,DI    ; EXCHANGE TO ENABLE INDEXING
                    65      ;
                    66      ; BEGIN COMPARISON OF TABLE VALUES
000A 3DFF7F      67          CMP  AX,32767 ; CHECK IF X VALUE EQUAL TO PLUS FULL SCALE
000D 7501        68          JNZ  CFUN ; JUMP TO ROUTINE TO START CHECKING
000F 48          69          DEC  AX      ; DECREMENT X VALUE--MAKE IT =32766
0010 3B01        70      CFUN: CMP  AX,[BX+DI] ; COMPARE VALUE IN AX WITH TABLE LOCATION
                    71          ; POINTED TO BY BX REGISTER
0012 7D09        72          JGE  ILOP ; JUMP TO INTERPOLATION ROUTINE
                    73      ; DECREMENT LOOP
0014 83EF02      74      DLOP: SUB  DI,2 ; SUBTRACT 2 FROM TABLE POINTER
0017 3B01        75          CMP  AX,[BX+DI] ; COMPARE AX REGISTER VALUE TO TABLE LOCATION
0019 7D0C        76          JGE  INTA ; JUMP TO INTERPOLATION ROUTINE
001B EBF7        77          JMP  DLOP ; JUMP TO DECREMENT LOOP
                    78      ; INCREMENT LOOP
001D 83C702      79      ILOP: ADD  DI,2 ; ADD 2 TO TABLE POINTER
0020 3B01        80          CMP  AX,[BX+DI] ; COMPARE AX REGISTER VALUE TO TABLE LOCATION
0022 7DF9        81          JGE  ILOP ; JUMP TO INCREMENT LOOP
0024 EB0490      82          JMP  INTR ; JUMP TO INTERPOLATION ROUTINE
                    83      ;
                    84      ; INTERPOLATION LOOP
                    85      ; DI CONTAINS ADDRESS OF THE X LOWER LIMIT VALUE
                    86      ; BX CONTAINS ADDRESS OF THE X UPPER LIMIT VALUE
                    87      ; BP IS THE TEMPORARY SAVE REGISTER FOR THE INTERPOLATION FACTOR
                    88      ;
0027 83C702      89      INTA: ADD  DI,2 ; ADD 2 TO TABLE POINTER FOR EQUALIZATION
                    90          ; IF COMING FROM DECREMENT LOOP
002A 87D7        91      INTR: XCHG DX,DI ; MOVE INDEX AND POINTER FOR WRITING OUT
002C 8915        92          MOV  [DI],DX ; UPDATE INDEX VALUE OUTSIDE LOOP
002E 03DA        93          ADD  BX,DX ; ADD INDEX AND BASE POINTER
0030 8BFB        94          MOV  DI,BX ; MOVE UPPER LIMIT POINTER TO DI REGISTER
0032 8BD0        95          MOV  DX,AX ; SAVE LOOK-UP VALUE IN DX REGISTER
0034 83EF02      96          SUB  DI,2 ; DECREMENT DI AND MAKE LOWER LIMIT POINTER
0037 8B07        97          MOV  AX,[BX] ; MOVE UPPER LIMIT TABLE VALUE TO AX
0039 2B05        98          SUB  AX,[DI] ; SUBTRACT LOWER LIMIT VALUE
003B 8BE8        99          MOV  BP,AX ; SAVE RESULT IN BP REGISTER
003D 2B15       100          SUB  DX,[DI] ; COMPUTE NUMERATOR OF INTERPOLATION FACTOR
003F B80000     101          MOV  AX,0 ; CLEAR THE LEAST SIGNIFICANT BITS IN
                    102          ; DOUBLE PRECISION ACCUMULATOR TO
                    103          ; PREPARE FOR DIVIDE
0042 D1EA       104          SHR  DX,1 ; SHIFT RIGHT 1 PLACE IN DOUBLE PRECISION
0044 D1D8     105          RCR  AX,1 ; TO AVOID A DIVIDE OVERFLOW IN NEXT OPERATION

```

LOC	OBJ	LINE	SOURCE
0046	D1EA	106	SHR DX,1 ; SHIFT RIGHT 1 PLACE IN DOUBLE PRECISION
0048	D1D8	107	ROR AX,1 ; TO AVOID A DIVIDE OVERFLOW IN NEXT OPERATION
004A	F7F5	108	DIV BP ; DIVIDE TO COMPUTE POSITIVE
		109	; INTERPOLATION FACTOR
004C	8BC8	110	MOV CX,AX ; SAVE INTERPOLATION FACTOR IN CX REGISTER
		111	;
		112	; SI REGISTER INCREASED BY A FACTOR OF 2*(SI+2)
		113	; THIS ALLOWS ADDRESSING OF THE Y'S IN THE CURRENT
		114	; FUN1 TABLE OR THE NEXT FUN1A TABLE
		115	;
		116	;
004E	8BEF	117	MOV BP,DI ; SAVE LOW POINTER IN BP
0050	83C602	118	ADD SI,2 ; ADD 2 TO NUMBER OF POINTS TO COMPENSATE
		119	; FOR END POINTS ADDED TO DATA
0053	D1E6	120	SAL SI,1 ; MULTIPLY SI BY 2
0055	8BFE	121	MOV DI,SI ; SAVE NO. OF POINTS IN DI REGISTER
0057	8B00	122	FUN1A:MOV AX,[BX+SI] ; MOVE UPPER Y BREAKPOINT TO AX
0059	D1F8	123	SAR AX,1 ; SHIFT TO AVOID SUBTRACT OVERFLOW
		124	; PERFORM Y INCREMENT SUBTRACTION
005B	8E8B12	125	MOV DX,DS:[BP+SI] ; MOVE LOWER Y VALUE INTO DX REG.
005E	D1FA	126	SAR DX,1 ; RIGHT SHIFT 1 TO AVOID OVERFLOW IF
		127	; BREAKPOINT SPREAD IS > 32767
0060	2BC2	128	SUB AX,DX ; COMPUTE DENOMINATOR OR INTERPOLATION FACTOR
0062	F7E9	129	IMUL CX ; MULTIPLY BY X INTERPOLATION FACTOR
		130	; SHIFT LEFT 2 TO CORRECT THE
		131	; PREVIOUS DIVIDE SHIFT
		132	; AND SUBTRACT SHIFTS
0064	D1E0	133	SHL AX,1 ; DOUBLE PRECISION LEFT SHIFT TO CORRECT
0066	D1D2	134	RCL DX,1 ; FOR SUBTRACT OVERFLOW SHIFTS
		135	;
0068	D1E0	136	SHL AX,1 ; DOUBLE PRECISION LEFT SHIFT TO CORRECT
006A	D1D2	137	RCL DX,1 ; FOR DIVIDE OVERFLOW PREVENTION SHIFT
006C	D1E0	138	SHL AX,1 ; DOUBLE PRECISION LEFT SHIFT TO CORRECT
006E	D1D2	139	RCL DX,1 ; FOR DIVIDE OVERFLOW PREVENTION SHIFT
0070	3E0312	140	ADD DX,DS:[BP+SI] ;ADD Y LOW VALUE TO COMPLETE INTERPOLATION
0073	03F7	141	ADD SI,DI ; ADD NO. OF POINTS TO INDEX VALUE TO BE
		142	; READY FOR FUN1A CALL
0075	8BC2	143	MOV AX,DX ; MOVE RESULT TO AX REGISTER FOR PL/M-86
		144	; PROGRAM OUTPUT
0077	C3	145	RET ; RETURN TO CALLING PROGRAM
----		146	CODE ENDS
		147	END

XREF SYMBOL TABLE LISTING

NAME	TYPE	VALUE	ATTRIBUTES, XREFS
??SEG	. SEGMENT		SIZE=0000H PARA PUBLIC
CFUN.	. L NEAR	0010H	CODE 68 70#
CGROUP.	. GROUP		CODE 42# 43
CODE.	. SEGMENT		SIZE=0078H PARA PUBLIC 'CODE' 42# 49 146
DL0P.	. L NEAR	0014H	CODE 74# 77
FUN1.	. L NEAR	0006H	CODE PUBLIC 44 63#
FUN1A	. L NEAR	0057H	CODE PUBLIC 44 122#
ILOP.	. L NEAR	001DH	CODE 72 79# 81
INTA.	. L NEAR	0027H	CODE 76 89#
INTR.	. L NEAR	002AH	CODE 82 91#
PFUN1	. L NEAR	0000H	CODE PUBLIC 44 52#

ASSEMBLY COMPLETE, NO ERRORS FOUND


```

LOC OBJ          LINE    SOURCE
                51      ; NOTE: THE Y VALUES ARE ASSUMED TO
                52      ; NOT HAVE A DIFFERENCE OF GREATER THAN 32767
                53      ;
                54      ;
                55      ;
                56      ; FUN2A CALLING SEQUENCE:
                57      ;
                58      ; Y TABLE BASE VALUE
                59      ; CALL FUN2A
                60      ;
                61      ; NOTE: X AND Z VALUES ARE THE SAME, Y IS DIFFERENT
                62      ; THE CX, DX AND SI REGISTERS MUST NOT BE CHANGED BEFORE THE CALL
                63      ;
                64      ; AX REGISTER CONTAINS THE RETURNED RESULT
                65      ;
                66      ;
                67      ; *****
                68      ;
                69      NAME FUN2
                70      PUBLIC FUN2,FUN2A,PFUN2
                71      CGROUP GROUP CODE
                72      DGROUP GROUP CONST,DATA,STACK,MEMORY
                73      ASSUME CS:CGROUP,DS:DGROUP
                74      ;
                75      ; DATA SEGMENT FOR THE ROUTINE RESIDES IN
                76      ; TEMPORARY STORAGE
                77      ;
                78      DATA SEGMENT PUBLIC 'DATA'
-----
0000 0100      79      SPC DW 1 ; STORAGE FOR PROGRAM COUNTER
0002 0100      80      SSI DW 1 ; STORAGE FOR SI REGISTER (Z INDEX)
0004 0100      81      YPTI DW 1 ; STORAGE FOR Y TABLE OFFSET VALUE
0006 0100      82      DDX DW 1 ; STORAGE FOR Z INTERPOLATION FACTOR
-----
                83      DATA ENDS
                84      ;
                85      ; BEGIN CODE SEGMENT FOR THE ROUTINE
                86      ;
-----
                87      CODE SEGMENT PUBLIC 'CODE'
                88      ; UNPOP STACK TO STORE PROGRAM COUNTER
                89      ; AND GET THE Z VARIABLES FROM THE STACK
                90      ;
0000 8F060000  R    91      PFUN2:POP SPC ; STORE PROGRAM COUNTER
0004 58      92      POP AX ; Z LOOK-UP VALUE
0005 5B      93      POP BX ; Z TABLE BASE VALUE
0006 5F      94      POP DI ; Z TABLE INDEX POINTER LOCATION
0007 EB0590   95      JMP BEG ; JUMP AROUND ASSEMBLY CALL
000A 8F060000  R    96      FUN2: POP SPC ; SAVE PROGRAM COUNTER
000E 8B35     97      BEG: MOV SI,[DI] ; MOVE ACTUAL INDEX VALUE INTO SI
                98      ;
                99      ; BEGIN COMPARISONS TO DETERMINE Z LOCATION
                100     ;
0010 3DFF7F   101     CMP AX,32767 ; CHECK IF Z VALUE IS EQUAL TO FULL SCALE
0013 7501     102     JNZ NCHGZ ; JUMP TO CONTINUE SEARCH LOOP
0015 48      103     DEC AX ; DECREMENT BY ONE BIT TO PREVENT
                104     ; Z POINTER FROM BEING LOST
0016 3B00     105     NCHGZ: CMP AX,[BX+SI] ; COMPARE Z LOOK-UP VALUE WITH VALUE

```

LOC	OBJ	LINE	SOURCE
		106	; IN Z TABLE POINTED TO BY BX+SI
0018	7D09	107	JGE ILOP ; JUMP TO INCREMENTING LOOP
		108	; DECREMENTING LOOP
001A	83EE02	109	DLOP: SUB SI,2 ; SUBTRACT 2 FROM TABLE INDEX
001D	3B00	110	CMP AX,[BX+SI] ; COMPARE Z LOOK-UP VALUE WITH TABLE LOC
001F	7D0C	111	JGE CLZA ; JUMP TO INTERPOLATION FACTOR COMP.
0021	EBF7	112	JMP DLOP ; JUMP TO BEGINNING OF DECREMENT LOOP
		113	; INCREMENTING LOOP
0023	83C602	114	ILOP: ADD SI,2 ; ADD 2 TO TABLE INDEX VALUE
0026	3B00	115	CMP AX,[BX+SI] ; COMPARE Z LOOK-UP VALUE WITH TABLE LOC
0028	7DF9	116	JGE ILOP ; JUMP TO BEGINNING OF INCREMENT LOOP
002A	EB0490	117	JMP CLZ ; JUMP TO INTERPOLATION FACTOR CALCULATION
		118	; CLOSE Z SEARCH AND COMPUTE Z INTERPOLATION FACTOR
002D	83C602	119	CLZA: ADD SI,2 ; ADD 2 TO TABLE POINTER FOR EQUALIZATION
		120	; IF COMING FROM DECREMENT LOOP
0030	03DE	121	CLZ: ADD BX,SI ; ADD INDEX AND BASE Z POINTER VALUES TOGETHER
0032	8935	122	MOV [DI],SI ; SAVE Z INDEX VALUE FOR NEXT CALL
0034	8BFB	123	MOV DI,BX ; SAVE RESULT IN DI REGISTER
0036	83EF02	124	SUB DI,2 ; DECREMENT POINTER FOR LOWER Z TABLE VALUE
		125	; COMPUTE Z INTERPOLATION FACTOR
0039	2B05	126	SUB AX,[DI] ; SUBTRACT Z LOW FROM Z INPUT VALUE
003B	8B00	127	MOV DX,AX ; SAVE RESULT IN DX
003D	8B07	128	MOV AX,[BX] ; PUT Z HIGH IN AX REGISTER
003F	2B05	129	SUB AX,[DI] ; SUBTRACT Z LOW FROM Z HIGH VALUE
0041	8BC8	130	MOV CX,AX ; TEMPORARILY SAVE VALUE IN CX
0043	8B0000	131	MOV AX,0 ; CLEAR LEAST SIG PORTION OF DIVIDEND
0046	D1EA	132	SHR DX,1 ; RIGHT SHIFT 1 TO PREVENT DIVIDE OVERFLOW
0048	D1D8	133	ROR AX,1 ; ON NEXT OPERATION
004A	D1EA	134	SHR DX,1 ; RIGHT SHIFT 1 TO PREVENT DIVIDE OVERFLOW
004C	D1D8	135	ROR AX,1 ; ON NEXT OPERATION
004E	F7F1	136	DIV CX ; COMPUTE Z INTERPOLATION FACTOR
0050	A30600	R 137	MOV DDX,AX ; DDX NOW CONTAINS THE Z INTERPOLATION FACTOR/2
		138	; SI, SSI CONTAIN THE Z INDEX VALUE
0053	89360200	R 139	MOV SSI,SI ; SAVE THE Z INDEX VALUE
		140	; POP STACK FOR VARIABLES NECESSARY FOR X SEARCH
0057	58	141	POP AX ; X VALUE
0058	5B	142	POP BX ; X TABLE BASE VALUE
0059	5F	143	POP DI ; X TABLE INDEX VALUE POINTER
005A	8B35	144	MOV SI,[DI] ; MOVE ACTUAL INDEX VALUE INTO SI
		145	;
		146	; COMMENCE X TABLE SEARCH
005C	3DFF7F	147	CMP AX,32767 ; CHECK IF X VALUE IF EQUAL TO FULL SCALE
005F	7501	148	JNZ CFUN2 ; JUMP TO CONTINUE SEARCH LOOP
0061	48	149	DEC AX ; DECREMENT BY 1 BIT TO PREVENT
		150	; X POINTER FROM BEING LOST
0062	3B00	151	CFUN2: CMP AX,[BX+SI] ; COMPARE X LOOK-UP VALUE WITH VALUE
		152	; IN X TABLE POINTED TO BY BX+SI
0064	7D09	153	JGE ILOP ; JUMP TO INCREMENTING LOOP
		154	; DECREMENTING LOOP
0066	83EE02	155	DDLOP: SUB SI,2 ; SUBTRACT 2 FROM TABLE INDEX
0069	3B00	156	CMP AX,[BX+SI] ; COMPARE X LOOK-UP VALUE WITH TABLE LOC
006B	7D0C	157	JGE CMPA ; JUMP TO INTERPOLATION FACTOR COMP.
006D	EBF7	158	JMP DDLOP ; JUMP TO BEGINNING OF DECREMENTING LOOP
		159	; INCREMENTING LOOP
006F	83C602	160	ILOP: ADD SI,2 ; ADD 2 TO TABLE INDEX VALUE

LOC	OBJ	LINE	SOURCE
0072	3B00	161	CMP AX,[BX+SI] ; COMPARE X LOOK-UP VALUE WITH TABLE LOC.
0074	7DF9	162	JGE IIL0P ; JUMP TO INCREMENTING LOOP
0076	EB0490	163	JMP CMPP ; JUMP TO INTERPOLATION FACTOR CALCULATION
		164	; CLOSE X SEARCH AND PREPARE TO COMPUTE X INTRP FACTOR
0079	83C602	165	CMFA: ADD SI,2 ; ADD 2 TO TABLE POINTER FOR EQUALIZATION
		166	; IF COMING FROM DECREMENT LOOP
007C	03DE	167	CMFP: ADD BX,SI ; ADD INDEX AND TABLE POINTER BASE VALUES
007E	8935	168	MOV [DI],SI ; SAVE INDEX POINTER VALUE IN SPEC. LOC.
0080	8BFB	169	MOV DI,BX ; SAVE RESULT IN DI REGISTER
0082	83EF02	170	SUB DI,2 ; DECREMENT POINTER FOR LOWER X TABLE VALUE
		171	; COMPUTE X INTERPOLATION FACTOR
0085	2B05	172	SUB AX,[DI] ; SUBTRACT X LOW FROM X INPUT VALUE
0087	8BD0	173	MOV DX,AX ; SAVE RESULT IN DI
0089	8B07	174	MOV AX,[BX] ; PUT X HIGH IN AX REGISTER
008B	2B05	175	SUB AX,[DI] ; SUBTRACT Z LOW FROM Z INPUT VALUE
008D	8BC8	176	MOV CX,AX ; SAVE VALUE IN CX
008F	880000	177	MOV AX,0 ; CLEAR LEAST SIGNIFICANT PORTION OF DIVIDEND
0092	D1EA	178	SHR DX,1 ; SHIFT RIGHT 1 PLACE IN DOUBLE PRECISION
0094	D1D8	179	RCR AX,1 ; TO AVOID A DIVIDE OVERFLOW IN NEXT OPERATION
0096	D1EA	180	SHR DX,1 ; SHIFT RIGHT 1 PLACE IN DOUBLE PRECISION
0098	D1D8	181	RCR AX,1 ; TO AVOID A DIVIDE OVERFLOW IN NEXT OPERATION
009A	F7F1	182	DIV CX ; DIVIDE TO COMPUTE INTERPOLATION FACTOR
009C	8BC8	183	MOV CX,AX ; SAVE RESULT IN CX REGISTER
		184	;
		185	; CX CONTAINS THE X INTERPOLATION FACTOR/2
		186	; DDX CONTAINS THE Z INTERPOLATION FACTOR/2
		187	;
		188	; SAVE THE INDEX REGISTER VALUES SO
		189	; SO THAT THEY CAN BE RECALLED LATER FOR
		190	; PERMANENT STORAGE OUTSIDE ROUTINE
		191	;
		192	;
		193	; COMPUTE THE Y TABLE OFFSETS FROM THE
		194	; START OF THE Y TABLE
009E	58	195	POP AX ; AX CONTAINS THE NUMBER OF X PTS.
009F	050200	196	ADD AX,2 ; ADD 2 TO NO. OF X POINTS FOR END POINTS
00A2	8BE8	197	MOV BP,AX ; SAVE RESULT IN BP
00A4	D1E5	198	SHL BP,1 ; MULTIPLY RESULT BY 2
00A6	F7260200	199	MUL SSI ; MULTIPLY BY Z INDEX VALUE
00AA	03C6	200	ADD AX,SI ; ADD X INDEX VALUE
		201	;
		202	; AX CONTAINS THE OFFSET OF THE HIGH
		203	; Y WORD FROM THE START OF THE Y TABLE
		204	; OFFSET (BYTES) = Z OFFSET * (X POINTS + 2) + X OFFSET
		205	;
		206	; STORE TOTAL NUMBER OF X POINTS + 2 IN BYTES
00AC	8BF5	207	MOV SI,BP
		208	; STORE Y TABLE OFFSET FOR POSSIBLE FUN2A CALL
00AE	A30400	209	MOV YPTI,AX
00B1	EB0890	210	JMP CFUN ; JUMP TO CONTINUE FUNN2 ROUTINE
		211	;
		212	; ENTRY POINT FOR THE FUN2A CALL
		213	;
00B4	58	214	FUN2A: POP AX
00B5	A30000	215	MOV SPC,AX ; POP AND STORE PROGRAM COUNTER

LOC	OBJ	LINE	SOURCE
00B8	A10400	R 216	MOV AX,YPTI ; RESTORE Y TABLE OFFSET TO AX
		217	;
		218	; COMPUTE BASE POINTER VALUES USING Y LOACTION
		219	; AND THE COMPUTED OFFSET
		220	;
00B8	5D	221	CFUN: POP BP ; BP CONTAINS Y TABLE BASE VALUE
00BC	8BF3	222	MOV DI,AX ; MOVE Y TABLE OFFSET TO DI
00BE	03FD	223	ADD DI,BP ; ADD Y TABLE BASE VALUE
00C0	8BDF	224	MOV BX,DI ; MOVE RESULT TO BX REGISTER
00C2	83EB02	225	SUB BX,2 ; SUBTRACT 2 FROM RESULT
		226	;
		227	; DI AND BX CONTAIN THE HIGH AND LOW TABLE
		228	; LOCATION VALUES FOR INTERPOLATION
		229	; SI CONTAINS NUMBER OF X POINTS
		230	;
		231	; COMPUTE THE Y HIGH INTERPOLATED VALUE
00C5	8B05	232	MOV AX,[DI] ; MOVE Y HIGH PRIMITIVE VALUE
00C7	D1F8	233	SAR AX,1 ; SHIFT VALUE TO AVOID OVERFLOW
		234	; IF BREAKPOINT SPREAD >32768
00C9	8B2F	235	MOV BP,[BX] ; MOVE Y LOW PRIMITIVE VALUE
00CB	D1FD	236	SAR BP,1 ; SHIFT VALUE TO AVOID OVERFLOW
00CD	2BC5	237	SUB AX,BP ; SUBTRACT Y LOW PRIMITIVE VALUE
00CF	F7E9	238	IMUL CX ; MULTIPLY X INTERPOLATION FACTOR
00D1	D1E0	239	SHL AX,1 ; SHIFT RESULT TO CORRECT FOR
00D3	D1D2	240	RCL DX,1 ; SUBTRACTION OVERFLOW SHIFT
00D5	D1E0	241	SHL AX,1 ; MULTIPLY RESULT BY 2 TO CORRECT FOR
00D7	D1D2	242	RCL DX,1 ; A PREVIOUS DIVIDE SHIFT
00D9	D1E0	243	SHL AX,1 ; MULTIPLY RESULT BY 2 TO CORRECT FOR
00DB	D1D2	244	RCL DX,1 ; A PREVIOUS DIVIDE SHIFT
00DD	0317	245	ADD DX,[BX] ; ADD Y LOW PRIMITIVE VALUE
00DF	8BEA	246	MOV BP,DX ; BP NOW CONTAINS THE Y HIGH INTERPOLATED VALUE
		247	;
		248	; COMPUTE THE NEW INDEX VALUES FOR Y LOW
		249	; INTERPOLATED VALUE COMPUTATION
00E1	2BFE	250	SUB DI,SI ; COMPUTE NEW Y HIGH PRIMITIVE VALUE LOCATION
00E3	2BDE	251	SUB BX,SI ; COMPUTE NEW Y LOW PRIMITIVE VALUE LOCATION
		252	; COMPUTE THE Y LOW INTERPOLATED VALUE
00E5	8B05	253	MOV AX,[DI] ; MOVE Y HIGH PRIMITIVE VALUE
00E7	D1F8	254	SAR AX,1 ; SHIFT VALUE TO AVOID OVERFLOW
		255	; IF BREADPOINT SPREAD I > 32767
00E9	8B37	256	MOV SI,[BX] ; MOVE Y LOW PRIMITIVE VALUE
00EB	D1FE	257	SAR SI,1 ; SHIFT VALUE TO AVOID OVERFLOW
00ED	2BC6	258	SUB AX,SI ; SUBTRACT Y LOW PRIMITIVE VALUE
00EF	F7E9	259	IMUL CX ; MULTIPLY X INTERPOLATION FACTOR
00F1	D1E0	260	SHL AX,1 ; SHIFT RESULT TO CORRECT FOR
00F3	D1D2	261	RCL DX,1 ; SUBTRACTION OVERFLOW SHIFT
00F5	D1E0	262	SHL AX,1 ; MULTIPLY RESULT BY 2 TO CORRECT FOR
00F7	D1D2	263	RCL DX,1 ; A PREVIOUS DIVIDE SHIFT
00F9	D1E0	264	SHL AX,1 ; MULTIPLY RESULT BY 2 TO CORRECT FOR
00FB	D1D2	265	RCL DX,1 ; A PREVIOUS DIVIDE SHIFT
00FD	0317	266	ADD DX,[BX] ; ADD Y LOW PRIMITIVE VALUE
00FF	8BF2	267	MOV SI,DX ; SI CONTAINS Y LOW INTERPOLATED VALUE
		268	;
		269	; COMPUTE THE FINAL INTERPOLATED Y VALUE
0101	8B05	270	MOV AX,BP ; MOVE Y HIGH INTERPOLATED VALUE

LOC	OBJ	LINE	SOURCE
0103	D1F8	271	SAR AX,1 ; SHIFT TO AVOID SUBTRACT OVERFLOW
0105	D1FA	272	SAR DX,1 ; SHIFT TO AVOID SUBTRACT OVERFLOW
0107	2BC2	273	SUB AX,DX ; SUBTRACT Y LOW INTERPOLATED VALUE
0109	F72E0600	274	IMUL DD ; MULTIPLY BY Z INTERPOLATION FACTOR
010D	D1E0	275	SHL AX,1 ; SHIFT RESULT TO CORRECT FOR
010F	D1D2	276	RCL DX,1 ; SUBTRACTION OVERFLOW SHIFT
0111	D1E0	277	SHL AX,1 ; MULTIPLY BY 2 TO CORRECT FOR
0113	D1D2	278	RCL DX,1 ; A PREVIOUS DIVIDE SHIFT
0115	D1E0	279	SHL AX,1 ; MULTIPLY BY 2 TO CORRECT FOR
0117	D1D2	280	RCL DX,1 ; A PREVIOUS DIVIDE SHIFT
0119	03D6	281	ADD DX,SI ; ADD Y LOW INTERPOLATED VALUE
		282	; PREPARE TO RETURN TO THE MAIN PROGRAM
		283	; PUT PROGRAM COUNTER BACK ON STACK
011B	882E0000	284	MOV BP,SPC
011F	55	285	PUSH BP
		286	; PUT RESULT IN AX REGISTER FOR PROPER TRANSFER
0120	8BC2	287	MOV AX,DX
0122	C3	288	RET
----		289	CODE ENDS
		290	END

XREF SYMBOL TABLE LISTING

NAME	TYPE	VALUE	ATTRIBUTES, XREFS
PPSEG	. SEGMENT		SIZE=0000H PARA PUBLIC
BEG	. L NEAR	000EH	CODE 95 97#
CFUN	. L NEAR	00BBH	CODE 210 221#
CFUN2	. L NEAR	0062H	CODE 148 151#
CGROUP	. GROUP		CODE 71# 73
CLZ	. L NEAR	0030H	CODE 117 121#
CLZA	. L NEAR	002DH	CODE 111 119#
CMFA	. L NEAR	0079H	CODE 157 165#
CMFP	. L NEAR	007CH	CODE 163 167#
CODE	. SEGMENT		SIZE=0123H PARA PUBLIC 'CODE' 71# 87 889
CONST	. SEGMENT		SIZE=0000H --UNDEFINED-- 72#
DATA	. SEGMENT		SIZE=0008H PARA PUBLIC 'DATA' 72# 78 83
DDLOP	. L NEAR	0066H	CODE 155# 158
DDX	. V WORD	0006H	DATA 82# 137 274
DGROUP	. GROUP		CONST DATA STACK MEMORY 72# 73
DLOP	. L NEAR	001AH	CODE 109# 112
FUN2	. L NEAR	000AH	CODE PUBLIC 70 96#
FUN2A	. L NEAR	00B4H	CODE PUBLIC 70 214#
ILOP	. L NEAR	006FH	CODE 153 160# 162
ILOP	. L NEAR	0023H	CODE 107 114# 116
MEMORY	. SEGMENT		SIZE=0000H --UNDEFINED--
NCHGZ	. L NEAR	0016H	CODE 102 105#
FFUN2	. L NEAR	0000H	CODE PUBLIC 70 91#
SPC	. V WORD	0000H	DATA 79# 91 96 215 234
SSI	. V WORD	0002H	DATA 80# 139 199
STACK	. SEGMENT		SIZE=0000H --UNDEFINED--
YPTI	. V WORD	0004H	DATA 81# 209 216

ASSEMBLY COMPLETE, NO ERRORS FOUND


```

LOC  OBJ          LINE    SOURCE
                                51      ;
                                52      NAME    FUN3
                                53      PUBLIC FUN3,PFUN3
                                54      CGROUP GROUP CODE
                                55      DGROUP GROUP DATA,CONST,STACK,MEMORY
                                56      ASSUME CS:CGROUP,DS:DGROUP
                                57      ;
                                58      ; DATA SEGMENT
-----
                                59      DATA SEGMENT PUBLIC 'DATA'
0000 0100          60      SPC3  DW    1          ; STORE PROGRAM COUNTER
0002 0100          61      DDZ  DW    1          ; Z INTERPOLATION FACTOR
0004 0100          62      NBYT DW    1          ; NUMBER OF X BYTES PER Z VALUE
0006 0100          63      XSAV DW    1          ; X LOOK-UP VALUE
0008 0100          64      HXOFF DW    1          ; HIGH X OFFSET
000A 0100          65      LXOFF DW    1          ; LOW X OFFSET
000C 0100          66      DDX  DW    1          ; X INTERPOLATION FACTOR
000E 0100          67      XB   DW    1          ; BREAKPOINT COORDINATE
0010 0100          68      XC   DW    1          ; BREAKPOINT COORDINATE
0012 0100          69      XE   DW    1          ; BREAKPOINT COORDINATE
0014 0100          70      YB   DW    1          ; BREAKPOINT COORDINATE
0016 0100          71      YC   DW    1          ; BREAKPOINT COORDINATE
0018 0100          72      YE   DW    1          ; BREAKPOINT COORDINATE
-----
                                73      DATA  ENDS
                                74      ;
                                75      ; CODE SEGMENT
-----
                                76      CODE SEGMENT PUBLIC 'CODE'
                                77      ;
                                78      ; START FUNCTION ROUTINE
                                79      ;
0000 8F060000      R    80      PFUN3: POP    SPC3          ; STORE PROGRAM COUNTER
0004 58            81              POP    AX          ; Z LOOK-UP VALUE
0005 5B            82              POP    BX          ; Z TABLE BASE VALUE
0006 5F            83              POP    DI          ; Z TABLE INDEX VALUE ADDRESS
0007 EB0590        84              JMP    BEG          ; JUMP ASSEMBLY LANGUAGE CALL
000A 8F060000      R    85      FUN3:  POP    SPC3          ; SAVE PC FOR ASSEMBLY CALL
000E 8B35          86      BEG:  MOV    SI,[DI]        ; LOAD Z TABLE INDEX VALUE POINTER
                                87      ;
                                88      ; DETERMINE Z LOCATION
                                89      ;
0010 3B00          90              CMP    AX,[BX+SI]        ; COMPARE Z LOOK-UP VALUE WITH VALUE IN
                                91              ; Z TABLE POINTED TO BY BX+SI
0012 7D09          92              JGE    ILOP3        ; JUMP TO INCREMENTING LOOP
                                93      ;
                                94      ; DECREMENTING LOOP
                                95      ;
0014 83EE02        96      DLOP3: SUB    SI,2          ; SUBTRACT FROM TABLE INDEX
0017 3B00          97              CMP    AX,[BX+SI]        ; COMPARE Z LOOK-UP VALUE WITH TABLE LOC.
0019 7D0C          98              JGE    CLZA3        ; JUMP TO INTERPOLATION FACTOR CALC
001B EBF7          99              JMP    DLOP3        ; JUMP TO BEGINNING OF DECREMENT LOOP
                                100     ;
                                101     ; INCREMENTING LOOP
                                102     ;
001D 83C602        103     ILOP3: ADD    SI,2          ; ADD 2 TO THE INDEX POINTER
0020 3B00          104     CMP    AX,[BX+SI]        ; COMPARE Z LOOK-UP VALUE WITH TABLE LOC.
0022 7DF9          105     JGE    ILOP3        ; JUMP TO BEGINNING OF INCREMENT LOOP

```

LOC	OBJ	LINE	SOURCE
0024	ER0490	106	JMP CLZ3 ; JUMP TO INTERPOLATION LOOP
		107	;
		108	; CLOSE Z SEARCH AND COMPUTE Z INTERPOLATION FACTOR
		109	;
0027	83C602	110	CLZA3: ADD SI,2 ; ADD 2 TO TABLE INDEZ FOR EQUALIZATION
		111	; IF COMING FROM DECREMENT LOOP
002A	03DE	112	CLZ3: ADD BX,SI ; ADD INDEX AND BASE Z POINTER VALUES
002C	8935	113	MOV [DI],SI ; SAVE Z INDEX VALUE IN PROPER ADDRESS
002E	8BFB	114	MOV DI,BX ; SAVE RESULT IN DI REGISTER
0030	83EF02	115	SUB DI,2 ; DECREMENT POINTER FOR LOWER Z TABLE VALUE
0033	2B05	116	SUB AX,[DI] ; SUBTRACT Z LOW FROM Z INPUT VALUE
0035	8BD0	117	MOV DX,AX ; SAVE RESULT IN DX
0037	8B07	118	MOV AX,[BX] ; PUT Z HIGH IN AX REGISTER
0039	2B05	119	SUB AX,[DI] ; SUBTRACT Z LOW FROM Z HIGH VALUE
003B	8BC3	120	MOV CX,AX ; TEMPORARILY SAVED VALUE IN CX
003D	B90000	121	MOV AX,0 ; CLEAR LEAST SIG. PORTION OF DIVIDEND
0040	D1EA	122	SHR DX,1 ; FULL RIGHT SHIFT TO PREVENT OVERFLOW
0042	D1D8	123	RCR AX,1 ; ON THE NEXT DIVIDE
0044	D1EA	124	SHR DX,1 ; FULL RIGHT SHIFT TO PREVENT OVERFLOW
0046	D1D8	125	RCR AX,1 ; ON THE NEXT DIVIDE
0048	F7F1	126	DIV CX ; DIVIDE TO COMPUTE Z INTERPOLATION FACTOR
004A	A30200	R 127	MOV DDZ,AX ; DDZ CONTAINS THE Z INTERPOLATION FACTOR
		128	;
		129	; COMPUTE OFFSET AND ABSOLUTE LOCATION OF START OF X HIGH VECTOR
		130	; X OFFSET = (# OF X POINTS +2)*ZINDEX
		131	; NBYT = (# OF XPOINTS+2)*2
004D	58	132	POP AX ; AX CONTAINS THE NUMBER OF X POINTS
004E	050200	133	ADD AX,2 ; ADD 2 TO ACCOUNT FOR END POINTS
0051	8BE8	134	MOV BP,AX ; SHIFT TO BP REG.
0053	D1E5	135	SHL BP,1 ; MUL BY 2 TO GET BYTES/Z VALUE
0055	F7E6	136	MUL SI ; MUL BY Z INDEX TO GET TOTAL OFFSET
0057	8BF0	137	MOV SI,AX ; SI CONTAINS THE HIGH X OFFSET
0059	892E0400	R 138	MOV NBYT,BP ; NBYT CONTAINS THE NUMBER OF X BYTES
		139	; PER Z VALUE (VECTOR)
		140	;
		141	; COMPUTE X LOCATION FOR THE HIGH VALUE OF Z
005D	5F	142	POP DI ; DI CONTAINS X TABLE BASE VALUE
005E	8BD8	143	MOV BX,AX ; BX CONTAINS THE HIGH X OFFSET
0060	58	144	POP AX ; X LOOK-UP VALUE
		145	;
		146	; AX CONTAINS THE X LOOK-UP VALUE
		147	; BP CONTAINS THE NUMBER OF X BYTES PER VECTOR
		148	; DI CONTAINS THE X TABLE BASE VALUE
		149	;
		150	; DETERMINE X OFFSET FROM BEGINNING OF X HIGH VECTOR
0061	3DFF7F	151	CMP AX,32767 ; CHECK IF X VALUE IS PLUS FULL SCALE
0064	7501	152	JNZ CFUN3 ; JUMP TO CONTINUE SEARCH ROUTINE
0066	48	153	DEC AX ; DECREMENT X VALUE TO PREVENT POINTER
		154	; FROM GETTING LOST
0067	A30600	R 155	CFUN3: MOV XSAV,AX ; SAVE X LOOK-UP VALUE
006A	3B01	156	CMP AX,[DI+BX] ; COMPARE X LOOK-UP VALUE WITH VALUE
		157	; IN TABLE POINTED TO BY DI+BX
006C	7D09	158	JGE ILPXH3 ; JUMP TO INCREMENTING LOOP
		159	;
		160	; DECREMENTING LOOP

LOC	OBJ	LINE	SOURCE
006E	83EB02	161	DLPXH3:SUB BX,2 ; SUBTRACT 2 FROM INDEX VALUE
0071	3B01	162	CMP AX,[DI+BX] ; COMPARE X LOOK-UP VALUE TO TABLE
0073	7DOC	163	JGE CLXA3 ; JUMP TO INTERPOLATION LOOP
0075	EBF7	164	JMP DLPXH3 ; JUMP TO BEGINNING OF DECREMENT LOOP
		165	;
		166	; INCREMENTING LOOP
0077	83C302	167	ILPXH3:ADD BX,2 ; ADD 2 TO INDEX POINTER
007A	3B01	168	CMP AX,[DI+BX] ; COMPARE X LOOK-UP VALUE TO TABLE
007C	7DF9	169	JGE ILPXH3 ; JUMP TO INTERPOLATION LOOP
007E	EB0490	170	JMP CLX3 ; JUMP TO BEGINNING OF INCREMENTING LOOP
		171	;
		172	; FINAL COMPUTATION OF FINAL X LOCATIONS FOR Z HIGH VALUE
		173	;
0081	83C302	174	CLXA3: ADD BX,2 ; INCREMENT POINTER BY 2 IF
		175	; COMING FROM DECREMENT LOOP
0084	8BEF	176	CLX3: MOV BP,DI ; BP CONTAINS X TABLE BASE VALUE
0086	891E0800	R 177	MOV HXOFF,BX ; HXOFF CONTAINS THE X HIGH OFFSET (XE)
008A	03FB	178	ADD DI,BX
008C	8BDF	179	MOV BX,DI ; DI HAS LOCATION OF HIGH X (XE) FOR Z HIGH
008E	83EB02	180	SUB BX,2 ; BX HAS LOCATION OF LOW X (XB) FOR Z HIGH
0091	893E1200	R 181	MOV XE,DI ; SAVE LOCATION IN XE
0095	891E0E00	R 182	MOV XB,BX ; SAVE LOCATION IN XB
		183	;
		184	; COMPUTE LOW X LOCATIONS FOR LOW VALUE OF Z
		185	;
		186	; COMPUTE LOW X LOCATION
		187	; X OFFSET = (X OFFSET - NBYT)
0099	2B360400	R 188	SUB SI,NBYT ; SI CONTAINS LOW X VECTOR OFFSET
009D	8BDE	189	MOV BX,SI ; BX CONTAINS X VECTOR OFFSET FOR Z LOW
009F	8BFD	190	MOV DI,BP ; SI CONTAINS X TABLE BASE VALUE
		191	; DETERMINE X LOCATION
00A1	A10600	R 192	MOV AX,XSAV ; AX CONTAINS X LOOK-UP VALUE
00A4	3B01	193	CMP AX,[DI+BX] ; COMPARE X LOOK-UP VALUE WITH VALUE
		194	; IN X TABLE POINTED TO BY DI+BX
00A6	7D09	195	JGE ILPXL3 ; JUMP TO INCREMENTING LOOP
		196	; DECREMENTING LOOP
00A8	83EB02	197	DLPXL3:SUB BX,2 ; DECREMENT INDEX POINTER
00AB	3B01	198	CMP AX,[DI+BX] ; COMPARE X LOOK-UP VALUE WITH TABLE LOC.
00AD	7DOC	199	JGE CLXLA3 ; JUMP TO FINAL X LOW CALC.
00AF	EBF7	200	JMP DLPXL3 ; JUMP TO DECREMENT LOOP
		201	;
		202	; INCREMENTING LOOP
00B1	83C302	203	ILPXL3:ADD BX,2 ; INCREMENT INDEX POINTER
00B4	3B01	204	CMP AX,[DI+BX] ; COMPARE X LOOK-UP VALUE WITH TABLE LOC.
00B6	7DF9	205	JGE ILPXL3 ; JUMP TO INCREMENT LOOP
00B8	EB0490	206	JMP CLXL3 ; JUMP TO FINAL X LOW CALC.
		207	;
		208	; COMPUTE X LOW LOCATIONS FOR LOW VALUE OF Z
		209	; X OFFSET = (X OFFSET-NBYT)
00BB	83C302	210	CLXLA3:ADD BX,2 ; ADD 2 TO INDEX POINTER FOR EQUALIZATION
		211	; IF COMING FROM DECREMENT LOOP
00BE	03FB	212	CLXL3: ADD DI,BX ; ADD OFFSET AND BASE POINTERS
00C0	891E0A00	R 213	MOV LXOFF,BX ; LXOFF CONTAINS THE LOW X OFFSET (XD)
00C4	8BDF	214	MOV BX,DI ; DI CONTAINS LOCATION OF HIGH X (XD) FOR Z LOW
00C6	83EB02	215	SUB BX,2 ; BX CONTAINS LOCATION OF LOW X (XC) FOR Z LOW

LOC	OBJ		LINE	SOURCE	
00C9	891E1000	R	216	MOV XC,BX	; SAVE LOCATION IN XC
			217	;	
			218	; COMPUTE XG = XD+DDXZ(XE-XD)	
			219	;	
00CD	8B1E1200	R	220	MOV BX,XE	; BX CONTAINS HIGH X LOCATION
00D1	8B07		221	MOV AX,[BX]	; MOVE XE TO AX
00D3	D1F8		222	SAR AX,1	; RIGHT SHIFT 1 IN CASE POINT
			223		; DELTA IS GREATER THAN 32767
00D5	8B15		224	MOV DX,[DI]	; MOVE XD
00D7	D1FA		225	SAR DX,1	; SHIFT TO AVOID SUBTRACT OVERFLOW
00D9	2BC2		226	SUB AX,DX	; SUBTRACT XD
00DB	F72E0200	R	227	IMUL DDXZ	; MULTIPLY BY INTERPOLATION FACTOR
00DF	D1E0		228	SHL AX,1	; SHIFT TO CORRECT FOR
00E1	D1D2		229	RCL DX,1	; SUBTRACT OVERFLOW SHIFT
00E3	D1E0		230	SHL AX,1	; MULTIPLY RESULT BY 2
00E5	D1D2		231	RCL DX,1	; TO MAKE UP FOR SHIFT BEFORE DIVIDE
00E7	D1E0		232	SHL AX,1	; FULL LEFT SHIFT TO CORRECT
00E9	D1D2		233	RCL DX,1	; PREVIOUS SHIFT
00EB	0315		234	ADD DX,[DI]	; ADD XD TO RESULT
00ED	8BEA		235	MOV BP,DX	; BP CONTAINS XG
			236	;	
			237	; COMPUTE XF=XC+DDXZ(XB-XC)	
			238	;	
00EF	8B1E0E00	R	239	MOV BX,XB	; BX CONTAINS X HIGH LOCATION
00F3	8B3E1000	R	240	MOV DI,XC	; DI CONTAINS X LOW LOCATION
00F7	8B07		241	MOV AX,[BX]	; MOVE XB TO AX REGISTER
00F9	D1F8		242	SAR AX,1	; RIGHT SHIFT 1 IN CASE POINT
			243		; SPREAD IS GREATER THAN 32767
00FB	8B15		244	MOV DX,[DI]	; MOVE XC TO DX REG.
00FD	D1FA		245	SAR DX,1	; SHIFT TO AVOID SUBTRACT OVERFLOW
00FF	2BC2		246	SUB AX,DX	; SUBTRACT XC
0101	F72E0200	R	247	IMUL DDXZ	; MULTIPLY BY INTERPOLATION FACTOR
0105	D1E0		248	SHL AX,1	; SHIFT TO CORRECT FOR
0107	D1D2		249	RCL DX,1	; SUBTRACT OVERFLOW SHIFTS
0109	D1E0		250	SHL AX,1	; MULTIPLY BY 2 TO MAKE UP FOR
010B	D1D2		251	RCL DX,1	; PREVIOUS SHIFT BEFORE DIVIDE
010D	D1E0		252	SHL AX,1	; FULL LEFT SHIFT TO CORRECT
010F	D1D2		253	RCL DX,1	; PREVIOUS SHIFT
0111	0315		254	ADD DX,[DI]	; DX CONTAINS XF
			255	;	
			256	; COMPUTE X INTERPOLATION FACTOR	
			257	;	
0113	A10600	R	258	MOV AX,XSAV	; AX CONTAINS X LOOK-UP VALUE
0116	2BC2		259	SUB AX,DX	; SUBTRACT XF
0118	8BDA		260	MOV BX,DX	; MOVE XF TO BX REGISTER
011A	8BD0		261	MOV DX,AX	; MOVE (XA-XF) TO DX
011C	8BC5		262	MOV AX,BP	; MOVE XG TO AX REGISTER
011E	2BC3		263	SUB AX,BX	; SUBTRACT XF
0120	8BC8		264	MOV CX,AX	; STORE RESULT IN CX
0122	B80000		265	MOV AX,0	; CLEAR LEAST SIG. PORTION OF DIVIDEND
0125	D1EA		266	SHR DX,1	; RIGHT SHIFT 2 TO AVOID DIVIDE OVERFLOW
0127	D1D8		267	RCR AX,1	
0129	D1EA		268	SHR DX,1	
012B	D1D8		269	RCR AX,1	
012D	F7F1		270	DIV CX	; DIVIDE BY INTERPOLATION FACTOR

LOC	OBJ	LINE	SOURCE
012F	A30C00	R 271	MOV DDX,AX ; DDX CONTAINS X INTERPOLATION FACTOR
		272	;
		273	; HXOFF CONTAINS THE HIGH X OFFSET IN THE HIGH X VECTOR (Z HIGH VALUE)
		274	; LXOFF CONTAINS THE HIGH X OFFSET IN THE LOW X VECTOR (Z LOW VALUE)
		275	; DDXZ CONTAINS THE Z INTERPOLATION FACTOR
		276	; DDX CONTAINS THE X INTERPOLATION FACTOR
		277	;
		278	;
		279	; COMPUTE Y HIGH LOCATIONS Y OFFSET = YBASE+X HIGH OFFSET
		280	;
0132	5B	281	POP BX ; BX CONTAINS THE Y TABLE BASE VALUE
0133	8BF3	282	MOV SI,BX ; SAVE Y TABLE BASE VALUE
0135	8B3E0800	R 283	MOV DI,HXOFF ; MOVE OFFSET TO DI REGISTER
0139	03DF	284	ADD BX,DI ; ADD OFFSET Y BASE
013B	8BFB	285	MOV DI,BX ; BX CONTAINS HIGH Y LOCATION (YE)
013D	83EF02	286	SUB DI,2 ; DI CONTAINS LOW Y LOCATION (YB)
0140	891E1800	R 287	MOV YE,BX ; SAVE VALUE IN YE
0144	893E1400	R 288	MOV YB,DI ; SAVE VALUE IN YB
		289	;
		290	; COMPUTE Y LOW LOCATIONS Y OFFSET = YBASE + X LOW OFFSET
		291	;
0148	8BDE	292	MOV BX,SI ; BX CONTAINS THE Y TABLE BASE
014A	8B3E0A00	R 293	MOV DI,LXOFF ; MOVE X LOW OFFSET TO DI
014E	03DF	294	ADD BX,DI ; ADD YBASE AND X LOW OFFSET
0150	8BFB	295	MOV DI,BX ; BX CONTAINS HIGH Y LOCATION (YD)
0152	83EF02	296	SUB DI,2 ; DI CONTAINS LOW Y LOCATION (YC)
0155	893E1600	R 297	MOV YC,DI ; SAVE VALUE IN YC
		298	;
		299	; COMPUTE YG = YD+DDXZ(YE-YD)
		300	;
0159	8B3E1800	R 301	MOV DI,YE ; DI CONTAINS HIGH Y LOCATION YE
015D	8B05	302	MOV AX,[DI] ; AX CONTAINS HIGH Y LOCATION YD
015F	D1F8	303	SAR AX,1 ; RIGHT SHIFT 1 IN CASE POINT
		304	; DELTA IS GREATER THAN 32767
0161	8B17	305	MOV DX,[BX] ; MOVE YD INTO DX REG
0163	D1FA	306	SAR DX,1 ; RIGHT SHIFT TO AVOID SUBTRACT OVERFLOW
0165	2BC2	307	SUB AX,DX ; SUBTRACT (YE-YD)
0167	F72E0200	R 308	IMUL DDXZ ; MULTIPLY BY Z INTERPOLATION FACTOR
016B	D1E0	309	SHL AX,1 ; SHIFT TO CORRECT FOR PREVIOUS
016D	D1D2	310	RCL DX,1 ; SUBTRACT OVERFLOW SHIFTS
016F	D1E0	311	SHL AX,1 ; LEFT SHIFT 1 TO CORRECT FOR DIVIDE SHIFT
0171	D1D2	312	RCL DX,1
0173	D1E0	313	SHL AX,1 ; FULL LEFT SHIFT TO CORRECT
0175	D1D2	314	RCL DX,1 ; PREVIOUS DIVIDE SHIFT
0177	0317	315	ADD DX,[BX] ; ADD YD VALUE TO RESULT
0179	8BCA	316	MOV CX,DX ; CX CONTAINS YG
		317	;
		318	; COMPUTE YF = YC + DDXZ(YB - YC)
		319	;
017B	8B3E1400	R 320	MOV DI,YB ; DI CONTAINS HIGH Y LOCATION
017F	8B1E1600	R 321	MOV BX,YC ; BX CONTAINS LOW Y LOCATION
0183	8B05	322	MOV AX,[DI] ; MOVE YB TO AX REGISTER
0185	D1F8	323	SAR AX,1 ; RIGHT SHIFT 1 IN CASE
		324	; POINT DELTA IS > 32767
0187	8B17	325	MOV DX,[BX] ; MOVE YG INTO DX REG.

LOC	OBJ	LINE	SOURCE
0189	D1FA	326	SAR DX,1 ; SHIFT TO AVOID SUBTRACT OVERFLOW
018B	2BC2	327	SUB AX,DX ; SUBTRACT YC
018D	F72E0200	328	IMUL DDZX ; MULTIPLY BY INTERPOLATION FACTOR
0191	D1E0	329	SHL AX,1 ; SHIFT TO CORRECT FOR
0193	D1D2	330	RCL DX,1 ; PREVIOUS SUBTRACT SHIFTS
0195	D1E0	331	SHL AX,1 ; SHIFT LEFT ONE TO CORRECT FOR DIVIDE SHIFT
0197	D1D2	332	RCL DX,1
0199	D1E0	333	SHL AX,1 ; FULL LEFT SHIFT TO CORRECT
019B	D1D2	334	RCL DX,1 ; PREVIOUS DIVIDE SHIFT
019D	0317	335	ADD DX,[BX] ; ADD YC TO RESULT
019F	8BEA	336	MOV BP,DX ; BP CONTAINS YF
		337	;
		338	; COMPUTE FINAL YV = YF + DDZ(YG - YF)
		339	;
01A1	8BC1	340	MOV AX,CX ; AX CONTAINS YG
01A3	D1F8	341	SAR AX,1 ; SHIFT TO AVOID OVERFLOW
01A5	D1FA	342	SAR DX,1 ; IF POINT DELTA >32767
01A7	2BC2	343	SUB AX,DX ; SUBTRACT YF
01A9	F72E0C00	344	IMUL DDZ ; MULTIPLY BY INTERPOLATION FACTOR
01AD	D1E0	345	SHL AX,1 ; SHIFT TO CORRECT FOR PREVIOUS
01AF	D1D2	346	RCL DX,1 ; SUBTRACTION SHIFT
01B1	D1E0	347	SHL AX,1 ; LEFT SHIFT TO CORRECT FOR PREVIOUS
01B3	D1D2	348	RCL DX,1 ; DIVIDE OVERFLOW SHIFTS
01B5	D1E0	349	SHL AX,1
01B7	D1D2	350	RCL DX,1
01B9	03D5	351	ADD DX,BP ; DX CONTAINS FINAL Y
		352	;
		353	; RETURN TO MAIN PROGRAM
		354	;
		355	; PUSH PROGRAM COUNTER BACK ON STACK
01BB	882E0000	356	MOV BP,SPC3
01BF	55	357	PUSH BP
01C0	8BC2	358	MOV AX,DX ; MOVE RESULT TO AX REGISTER FOR
		359	; RETURN TO PL/M PROGRAM
		360	;
01C2	C3	361	RET
----		362	CODE ENDS
		363	END

XREF SYMBOL TABLE LISTING

```

NAME      TYPE      VALUE  ATTRIBUTES, XREFS
-----
??SEG . SEGMENT          SIZE=0000H PARA PUBLIC
BEG . . L NEAR  000EH  CODE  84 86#
CFUN3 . L NEAR  0067H  CODE 152 155#
CGROUP. GROUP          CODE  54# 56
CLX3. . L NEAR  0084H  CODE 170 176#
CLXA3 . L NEAR  0081H  CODE 163 174#
CLXL3 . L NEAR  00BEH  CODE 206 212#
CLXA3. L NEAR  00BBH  CODE 199 210#
CLZ3. . L NEAR  002AH  CODE 106 112#
CLZA3 . L NEAR  0027H  CODE  98 110#
CODE. . SEGMENT          SIZE=01C3H PARA PUBLIC 'CODE' 54# 76 362
CONST . SEGMENT          SIZE=0000H --UNDEFINED-- 55#
DATA. . SEGMENT          SIZE=001AH PARA PUBLIC 'DATA' 55# 59 73
DDX . . V WORD  000CH  DATA 66# 271 344
DDXZ. . V WORD  0002H  DATA 61# 127 227 247 308 328
DGROUP. GROUP          DATA CONST STACK MEMORY 55# 56
ILOP3 . L NEAR  0014H  CODE  96# 99
DLPXH3. L NEAR  006EH  CODE 161# 164
DLPXL3. L NEAR  00A8H  CODE 197# 200
FUN3. . L NEAR  000AH  CODE PUBLIC 53 85#
HXOFF . V WORD  0008H  DATA 64# 177 283
ILOP3 . L NEAR  001DH  CODE  92 103# 105
ILPXH3. L NEAR  0077H  CODE 158 167# 169
ILPXL3. L NEAR  00B1H  CODE 195 203# 205
LXOFF . V WORD  000AH  DATA 65# 213 293
MEMORY. SEGMENT          SIZE=0000H --UNDEFINED--
NBYT. . V WORD  0004H  DATA 62# 138 188
PFUN3 . L NEAR  0000H  CODE PUBLIC 53 80#
SPC3. . V WORD  0000H  DATA 60# 80 85 356
STACK . SEGMENT          SIZE=0000H --UNDEFINED--
XB. . . V WORD  000EH  DATA 67# 182 239
XC. . . V WORD  0010H  DATA 68# 216 240
XE. . . V WORD  0012H  DATA 69# 181 220
XSAV. . V WORD  0006H  DATA 63# 155 192 258
YB. . . V WORD  0014H  DATA 70# 288 320
YC. . . V WORD  0016H  DATA 71# 297 321
YE. . . V WORD  0018H  DATA 72# 287 301

```

ASSEMBLY COMPLETE, NO ERRORS FOUND


```

LOC OBJ          LINE    SOURCE
                    51    ;*****
                    52    ;
                    53    ;
                    54    ;   NOTE: DATA STORAGE FORMAT
                    55    ;       X VALUES--(-32768 TO 32767)
                    56    ;       M VALUES--(-32768 TO 32767)
                    57    ;       B VALUES--(DOUBLE PRECISION VALUES
                    58    ;           LEAST SIGNIFICANT 2 BYTES
                    59    ;           MOST SIGNIFICANT 2 BYTES)
                    60    ;
                    61    ;
                    62    ;
                    63    ;   *****
                    64    ;
                    65    ;       NAME NEFG
                    66    ;       PUBLIC PNEFG,NEFG
                    67    ; CGROUP GROUP CODE
                    68    ;       ASSUME CS:CGROUP
                    69    ;
                    70    ;
                    71    ;   CODE SEGMENT FOR ROUTINE
                    72    ;
                    73    ; CODE SEGMENT PUBLIC 'CODE'
                    74    ;   PROGRAM ENTRY IF ENTERED BY PL/M-86 CALL ROUTINE
                    75    ;
0000 5A          76    PNEFG:POP  DX   ; TEMP SAVE OF PC
0001 58          77    POP  AX   ; X VALUE
0002 5B          78    POP  BX   ; X TABLE FLOATING POINTER ADDRESS
0003 5F          79    POP  DI   ; X TABLE BASE VALUE
0004 5E          80    POP  SI   ; NUMBER OF POINTS IN TABLE
0005 5D          81    POP  BP   ; STARTING LOCATION OF B VALUES
0006 52          82    PUSH DX   ; RESTORE PC TO THE STACK
                    83    ;
                    84    ;   PROGRAM ENTRY IF CALLED BY ASSEMBLY
                    85    ;   LANGUAGE ROUTINE
                    86    ;
0007 B90200     87    NEFG: MOV  CX,2   ; PUT VALUE OF 2 IN CX REGISTER FOR INCREMENTING
000A 8B17     88    MOV  DX,[BX]  ; MOVE POINTER VALUE TO DX REGISTER
000C 87DA     89    XCHG BX,DX   ; SAVE POINTER LOC IN DX REGISTER
000E 03F1     90    ADD  SI,CX   ; ADD 2 TO THE NUMBER OF X POINTS
                    91    ;
0010 3DFF7F   92    CMP  AX,32767 ; CHECK IF X VALUE IS EQUAL TO FULL SCALE
0013 7501     93    JNZ  CNEFG   ; JUMP TO CONTINUE FUNCTION LOOK-UP
0015 48       94    DEC  AX     ; DECREMENT BY ONE BIT TO AVOID POINTER
                    95    ; BEING LOST
                    96    ;   BEGIN COMPARISON OF TABLE VALUES
                    97    ;
0016 3B01     98    CNEFG:CMP AX,[BX+DI] ; COMPARE X VALUE WITH TABLE LOCATION
0018 7D08     99    JGE  ILOP   ; JUMP TO INCREMENT LOOP
                    100   ;   DECREMENT LOOP
001A 2B09    101   DLOP: SUB  BX,CX   ; SUBTRACT 2 FROM X TABLE POINTER
001C 3B01    102   CMP  AX,[BX+DI]  ; COMPARE X VALUE WITH TABLE LOCATION
001E 7D0B    103   JGE  INTRA   ; JUMP TO INTERPOLATION ROUTINE
0020 EBF8    104   JMP  DLOP   ; JUMP TO BEGINNING OF DECREMENT LOOP
                    105   ;   INCREMENT LOOP

```

```

LOC OBJ          LINE    SOURCE
0022 03D9        106    ILOP: ADD  BX,CX      ; ADD 2 TO TABLE POINTER
0024 3B01        107          CMP  AX,[BX+DI]     ; COMPARE X VALUE WITH TABLE LOCATION
0025 7DFA        108          JGE  ILOP          ; JUMP TO BEGINNING OF INCREMENT LOOP
0028 EB0390      109          JMP  INTR          ; JUMP TO INTERPOLATION ROUTINE
110             ;
111             ;   BX CONTAINS THE LOCATION OF THE X TABLE VALUE
112             ;   WHICH IS HIGHER THAN THE X LOOK-UP VALUE
113             ;
114             ;   COMPUTE LOCATION OF THE M SLOPE VALUE
115             ;   M LOCATION = ((X POINTER -(2 * #X POINTS))-2
116             ;
002B 03D9        117    INTRA:ADD  BX,CX      ; ADD 2 TO TABLE POINTER FOR EQUIVALENCE
118             ;   IF COMING FROM DECREMENT LOOP
002D 87DA        119    INTR: XCHG  BX,DX     ; PUT ADDRESS OF POINTER IN BX REGISTER
002F 8917        120          MOV  [BX],DX       ; SAVE CURRENT VALUE OF INDEX POINTER
0031 03D7        121          ADD  DX,DI        ; ADD X INDEX AND BASE VALUE
0033 8BDA        122          MOV  BX,DX        ; MOVE TOTAL POINTER TO BX REG
0035 D1E6        123          SAL  SI,1        ; MULTIPLY NO. OF X POINTS BY 2
0037 03DE        124          ADD  BX,SI        ; ADD ABOVE TO CURRENT X TABLE POINTER
0039 2BD9        125          SUB  BX,CX        ; DECREMENT POINTER BY TWO
126             ;   BX CONTAINS THE ADDRESS OF THE SLOPE M
003B F72F        127          IMUL WORD PTR [BX] ; MULTIPLY CURRENT X VALUE BY THE SLOPE
003D D1E0        128          SHL  AX,1        ; FULL LEFT ARITHMETIC SHIFT TO
003F D1D2        129          RCL  DX,1        ; BRING MULTIPLY SCALING INTO LINE
130             ;
131             ;   AX AND DX CONTAIN THE VALUE OF SLOPE TIMES VALUE--M*X
132             ;
133             ;
134             ;   COMPUTE THE LOCATION OF THE B'S
135             ;   USING THE RELATION (M ADDR - X BASE - X BYTES)*2 + (B BASE)
0041 2BDF        135          SUB  BX,DI        ; SUBTRACT X BASE FROM M ADDR
0043 2BDE        136          SUB  BX,SI        ; SUBTRACT X # OF BYTES
0045 D1E3        137          SAL  BX,1        ; MULTIPLY RESULT BY 2
0047 03DD        138          ADD  BX,BP        ; ADD BP TO GIVE ADDRESS OF MSB B VALUE
0049 8BFB        139          MOV  DI,BX        ; MOVE VALUE TO DI REGISTER
004B 03F9        140          ADD  DI,CX        ; DECREMENT BY 2 AND DI CONTAINS ADDRESS OF
141             ;   LSB B VALUE
142             ;
143             ;   NOW FOR DOUBLE PRECISION ADD
004D 0305        143          ADD  AX,[DI]      ; ADD LSB B VALUE TO RESULT
004F 1317        144          ADC  DX,[BX]    ; ADD MSB B VALUE TO RESULT
0051 8B08        145          MOV  BX,AX        ; MOVE CX TO AX TO ALLOW FOR THE
146             ;   SHFT FUNCTION CALL IN PLM PROGRAM
0053 C3          147          RET
----          148    CODE ENDS
149          END

```

XREF SYMBOL TABLE LISTING

NAME	TYPE	VALUE	ATTRIBUTES, XREFS
??SEG	. SEGMENT		SIZE=0000H PARA PUBLIC
CGROUP	. GROUP		CODE 67# 68
CNEFG	. L NEAR	0016H	CODE 93 98#
CODE	. SEGMENT		SIZE=0054H PARA PUBLIC 'CODE' 67# 73 148
DLOGP	. L NEAR	001AH	CODE 101# 104
ILOGP	. L NEAR	0022H	CODE 99 106# 108
INTR	. L NEAR	002DH	CODE 109 119#
INTRA	. L NEAR	002BH	CODE 103 117#
NEFG	. L NEAR	0007H	CODE PUBLIC 66 87#
FNEFG	. L NEAR	0000H	CODE PUBLIC 66 76#

ASSEMBLY COMPLETE, NO ERRORS FOUND

IGIS-II MCS-86 MACRO ASSEMBLER V2.1 ASSEMBLY OF MODULE SHFT
 OBJECT MODULE PLACED IN :F1:NSHFT.OBJ
 ASSEMBLER INVOKED BY: ASM86 :F1:NSHFT.SRC XREF DATE(3 SEPT 80)

LOC	OBJ	LINE	SOURCE
		1	;
		2	;
		3	;
		4	;
		5	;
		6	THIS PROCEDURE IS USED TO SHIFT THE BX AND DX DOUBLE
		7	PRECISION ACCUMULATORS A SPECIFIED NUMBER OF TIMES
		8	;
		9	THE PROCEDURE IS USED AFTER CALLING THE NEFG FUNCTION
		10	ROUTINE FROM A PL/M-86 PROGRAM
		11	;
		12	CALL SEQUENCE:
		13	;
		14	RSLT = SHFT(NO.)
		15	WHERE NO. IS THE NUMBER OF FULL LEFT
		16	ARITHMETIC SHIFTS THAT MUST BE MADE
		17	;
		18	;
		19	;*****
		20	;
		21	NAME SHFT
		22	PUBLIC SHFT
		23	CGROUP GROUP CODE
		24	ASSUME CS:CGROUP
		25	;
		26	;
----		27	CODE SEGMENT PUBLIC 'CODE'
		28	;
0000	8BEC	29	SHFT: MOV BP,SP
0002	8B4E02	30	MOV CX,[BP]+2
0005	D1E3	31	NXT: SHL BX,1
0007	D1D2	32	RCL DX,1
0009	E2FA	33	LOOP NXT
000B	8BC2	34	MOV AX,DX
000D	C20200	35	RET 02H
----		36	CODE ENDS
		37	END

XREF SYMBOL TABLE LISTING

NAME	TYPE	VALUE	ATTRIBUTES, XREFS
00SEG	. SEGMENT		SIZE=0000H PARA PUBLIC
CGROUP	. GROUP		CODE 23# 24
CODE	. SEGMENT		SIZE=0010H PARA PUBLIC 'CODE' 23# 27 36
NXT	. L NEAR	0005H	CODE 31# 33
SHFT	. L NEAR	0000H	CODE PUBLIC 22 29#

ASSEMBLY COMPLETE, NO ERRORS FOUND


```

100      SUBROUTINE INTSCL(INFO,TITLE,XNUM,XDNOM,YNUM,YDNOM,ZNUM,ZDNOM,FUNC,FRMT,ORG)
200      C
300      C SUBROUTINE INTSCL ACCEPTS DATA IN ENGINEERING UNITS FOR NEFG,FUN1,FUNIA,FUN2, AND FUN3 TYPE CURVES,
400      C COMPUTES M AND B FOR NEFG, AND SCALES ALL DATA. OUTPUT IS IN TWO FORMS:
500      C 1) A TABULAR LIST DATASET, AND
600      C 2) EITHER AN ABSOLUTE OR RELOCATABLE DATASET SUITABLE FOR THE 8086 ASSEMBLER.
700      C
800      C CALLING VARIABLES:
900      C
1000     C INFO      -- ARRAY WHICH CONTAINS (IN THIS ORDER)
1100     C          1) X BORDER SPECIFICATION
1200     C             0.0 = ADD BOTH FLATS      -- NO EXTRAPOLATION
1300     C             1.0 = ADD LOW X FLAT     -- EXTRAPOLATE HIGH END
1400     C             2.0 = ADD HIGH X FLAT    -- EXTRAPOLATE LOW END
1500     C             3.0 = NO FLATS          -- EXTRAPOLATE BOTH ENDS
1600     C          2) X BREAKPOINT SPECIFICATION
1700     C             0.0 = SAME X BREAKPOINT (FUN1, FUN2 TYPE)
1800     C             1.0 = DIFFERENT X BREAKPOINT (FUN3 TYPE)
1900     C          3) NUMBER OF X'S PER Z CURVE
2000     C          4) NUMBER OF Z CURVES (0.0 OR 1.0 = 1 Z CURVE)
2100     C          5) FIRST X VALUE FOR ALL Z CURVES
2200     C          6) SECOND X VALUE FOR ALL Z
2300     C          7) ETC.
2400     C          8) Z VALUES
2500     C          9) FIRST Y VALUE FOR ALL Z CURVES
2600     C         10)ETC.
2700     C TITLE     -- NAME OF CURVE
2800     C XNUM      -- X NUMERATOR VALUE FOR SCALING
2900     C XDNOM     -- X DENOMINATOR VALUE FOR SCALING
3000     C YNUM      -- Y NUMERATOR
3100     C YDNOM     -- Y DENOMINATOR
3200     C ZNUM      -- Z NUMERATOR
3300     C ZDNOM     -- Z DENOMINATOR
3400     C FUNC      -- INDICATES FUNCTION ROUTINE DATA BELONGS TO
3500     C             0 = NEFG
3600     C             1 = FUN1
3700     C             11= FUNIA
3800     C             2 = FUN2
3900     C             3 = FUN3
4000     C FRMT      -- FORMAT CHOICE FOR OUTPUT DATASET
4100     C             0 = RELOCATABLE
4200     C             1 = ABSOLUTE
4300     C ORG       -- HEXADECIMAL STARTING ADDRESS OF DATA FOR ABSOLUTE FORMAT
4400     C           DIMENSION XVAL(100,100),ZVAL(100),YVAL(100,100),MVAL(100),BVAL(100)
4500     C           DIMENSION XSCLD(100,100),ZSCLD(100),YSCLD(100,100),MSCLD(100),BMSB(100),BLSB(100)
4600     C           DIMENSION TITLE(2),INFO(500),ZNAME(2),XNAME(2),YNAME(2),YINAME(2),MNAME(2),BNAME(2)
4700     C           INTEGER XNO,ZNO,XSUB,ZSUB,YSUB,ZSCLD,XSCLD,YSCLD,BMSB,BLSB
4800     C           INTEGER FUNC,ORG,FRMT,XLNS,BLNS,YLNS,ZLNS,STMTNO
4900     C           INTEGER TITLE,SHFT,Y1,Y2,EXTRAP,SFTR,WARN
5000     C           REAL MBIG,MSMAL,MVAL,MSF
5100     C           REAL LSB,INFO,MNAME
5200     C           WARN=0
5300     C

```

```

5400 C   FILL NAME ARRAYS FOR OUTPUT DATASETS
5500 C
5600     DATA DATAZ,DATAX,DATAY,DATAY1,DATAM,DATAB,BLANK/'Z  ','X  ','Y  ','Y1  ','M  ','B  ','  '/'
5700 C
5800     IF (FUNC.NE.2.AND.FUNC.NE.3) GO TO 80
5900     CALL F4MVC(DATAZ,1,ZNAME,1,1)
6000     CALL F4MVC(TITLE,1,ZNAME,2,6)
6100     CALL F4MVC(BLANK,1,ZNAME,8,1)
6200 C
6300 80 CONTINUE
6400     CALL F4MVC(DATAX,1,XNAME,1,1)
6500     CALL F4MVC(TITLE,1,XNAME,2,6)
6600     CALL F4MVC(BLANK,1,XNAME,8,1)
6700 C
6800     CALL F4MVC(DATAY,1,YNAME,1,1)
6900     CALL F4MVC(TITLE,1,YNAME,2,6)
7000     CALL F4MVC(BLANK,1,YNAME,8,1)
7100 C
7200     IF (FUNC.NE.0) GO TO 85
7300     CALL F4MVC(DATAM,1,MNAME,1,1)
7400     CALL F4MVC(TITLE,1,MNAME,2,6)
7500     CALL F4MVC(BLANK,1,MNAME,8,1)
7600 C
7700     CALL F4MVC(DATAB,1,BNAME,1,1)
7800     CALL F4MVC(TITLE,1,BNAME,2,6)
7900     CALL F4MVC(BLANK,1,BNAME,8,1)
8000 C
8100 85 CONTINUE
8200     IF (FUNC.NE.11) GO TO 90
8300     CALL F4MVC(DATAY1,1,Y1NAME,1,2)
8400     CALL F4MVC(TITLE,1,Y1NAME,3,5)
8500     CALL F4MVC(BLANK,1,Y1NAME,8,1)
8600 C
8700 90 CONTINUE
8800 C
8900 C
9000 C   BREAK UP INFO ARRAY
9100 C
9200     CVEND=INFO(1)
9300     BRKPT=INFO(2)
9400     XNO=INFO(3)
9500 C
9600 C   DETERMINE FLAT AND EXTRAPOLATION OPTIONS
9700 C
9800     FLAT=CVEND
9900 C
10000     IF (CVEND.EQ.0.0) EXTRAP=0
10100     IF (CVEND.EQ.1.0) EXTRAP=2
10200     IF (CVEND.EQ.2.0) EXTRAP=3
10300     IF (CVEND.EQ.3.0) EXTRAP=1
10400     ZNO=INFO(4)
10500 C
10600 C   TEST FOR Z VALUES

```

```
10700 C
10800     IF (ZNO.EQ.0) ZNO=1
10900     JJ=ZNO
11000     IF (BRKPT.EQ.0.0) JJ=1
11100 C
11200 C     GET X VALUES INTO ORDER BY CURVE
11300 C
11400     II=0
11500     DO 100 I=1,XNO
11600     DO 100 J=1,JJ
11700     II=II+1
11800     XSUB=4+II
11900     XVAL(J,I)=INFO(XSUB)
12000 100 CONTINUE
12100 C
12200 C     FILL ZVAL ARRAY IF NECESSARY
12300 C
12400     IF (ZNO.EQ.1) GO TO 300
12500     DO 200 I=1,ZNO
12600     ZSUB=5+XNO*JJ+(I-1)
12700     ZVAL(I)=INFO(ZSUB)
12800 200 CONTINUE
12900 C
13000     IF (FUNC.NE.2) GO TO 300
13100 C
13200 C     SHIFT Z VALUES AND INSERT LOW AND HIGH ENDPOINTS
13300 C
13400     II=ZNO+1
13500     III=ZNO
13600     DO 210 I=1,ZNO
13700     ZVAL(II)=ZVAL(III)
13800     II=II-1
13900     III=III-1
14000 210 CONTINUE
14100 C
14200     ZVAL(1)=-32768*ZNUM/ZDNOM
14300     JZNO=ZNO+2
14400     ZVAL(JZNO)=32767*ZNUM/ZDNOM
14500 C
14600 C
14700 C     FILL Y ARRAY
14800 C
14900 300 IF (ZNO.EQ.1) GO TO 310
15000     ZZNO=ZNO
15100     GO TO 320
15200 310 ZZNO=0
15300 C
15400 320 II=0
15500     DO 350 I=1,XNO
15600     DO 350 J=1,ZNO
15700     YSUB=5+(XNO*JJ+ZZNO)+II
15800     YVAL(J,I)=INFO(YSUB)
15900     II=II+1
```

```
16000 350 CONTINUE
16100 C
16200 C
16300 C EXTRAPOLATE AND ADD FLATS IF NECESSARY
16400 C
16500 C
16600 C TEST FOR TYPE OF EXTRAPOLATION AND PERFORM IT
16700 C
16800 IF (EXTRAP.EQ.0) GO TO 3000
16900 IF (EXTRAP.EQ.2) GO TO 2000
17000 C
17100 C EXTRAPOLATE LOW END OF CURVES
17200 C
17300 C
17400 C SHIFT X VALUES AND INSERT LOW VALUE
17500 C
17600 1000 DO 1110 J=1,ZNO
17700 II=XNO+1
17800 III=XNO
17900 DO 1100 I=1,XNO
18000 XVAL(J,II)=XVAL(J,III)
18100 II=II-1
18200 III=III-1
18300 1100 CONTINUE
18400 XVAL(J,1)=-32768*XNUM/XDNOM
18500 1110 CONTINUE
18600 C
18700 C SHIFT Y VECTOR VALUES
18800 C
18900 DO 1210 J=1,ZNO
19000 II=XNO+1
19100 III=XNO
19200 DO 1200 I=1,XNO
19300 YVAL(J,II)=YVAL(J,III)
19400 II=II-1
19500 III=III-1
19600 1200 CONTINUE
19700 C
19800 C COMPUTE EXTRAPOLATED Y VALUE AND PUT IN ARRAY
19900 C
20000 YLOEXT=-(((XVAL(J,3)-XVAL(J,1))*(YVAL(J,3)-YVAL(J,2)))/(XVAL(J,3)-XVAL(J,2)))-YVAL(J,3)
20100 YVAL(J,1)=YLOEXT
20200 1210 CONTINUE
20300 C
20400 C INCREMENT XNO TO REFLECT CHANGE
20500 C
20600 XNO=XNO+1
20700 C
20800 IF (EXTRAP.EQ.3) GO TO 3000
20900 C
21000 C EXTRAPOLATE HIGH END OF CURVES
21100 C
21200 C
```

```

21300 C ADD X VALUE TO HIGH END
21400 C
21500 2000 XNO=XNO+1
21600 C
21700 DO 2010 J=1,ZNO
21800 XVAL(J,XNO)=32767*XNUM/XDNOM
21900 2010 CONTINUE
22000 C
22100 C COMPUTE Y HIGH EXTRAPOLATION AND PUT IN ARRAY
22200 C
22300 I=XNO-1
22400 II=XNO-2
22500 DO 2020 J=1,ZNO
22600 YHIEXT=(XVAL(J,XNO)-XVAL(J,II))*(YVAL(J,I)-YVAL(J,II))/(XVAL(J,I)-XVAL(J,II))+YVAL(J,II)
22700 YVAL(J,XNO)=YHIEXT
22800 2020 CONTINUE
22900 C
23000 C IF BOTH ENDS EXTRAPOLATED, SKIP FLATS.
23100 C
23200 IF (EXTRAP.EQ.1) GO TO 4500
23300 C
23400 3000 IF (FLAT.EQ.3.0) GO TO 4500
23500 IF (FLAT.EQ.2.0) GO TO 4000
23600 C
23700 C SHIFT X AND Y VALUES AND ADD FLATS
23800 C
23900 DO 3020 J=1,ZNO
24000 II=XNO+1
24100 III=XNO
24200 DO 3010 I=1,XNO
24300 XVAL(J,II)=XVAL(J,III)
24400 YVAL(J,II)=YVAL(J,III)
24500 II=II-1
24600 III=III-1
24700 3010 CONTINUE
24800 XVAL(J,1)=-32768*XNUM/XDNOM
24900 YVAL(J,1)=YVAL(J,2)
25000 3020 CONTINUE
25100 C
25200 C INCREMENT XNO
25300 C
25400 XNO=XNO+1
25500 C
25600 IF (FLAT.EQ.1.0) GO TO 4500
25700 C
25800 C ADD UPPER FLATS TO X AND Y CURVES
25900 C
26000 4000 XNO=XNO+1
26100 C
26200 I=XNO-1
26300 DO 4010 J=1,ZNO
26400 XVAL(J,XNO)=32767*XNUM/XDNOM
26500 YVAL(J,XNO)=YVAL(J,I)

```

```
26600 4010 CONTINUE
26700 C
26800 4500 IF (FUNC.NE.2) GO TO 5000
26900 C
27000 C SHIFT Y VALUES AND ADD ENDPOINTS
27100 C
27200 ZNO=ZNO+2
27300 C
27400 JZNO=ZNO-2
27500 JJ=ZNO-1
27600 JJJ=JZNO
27700 DO 370 J=1,JZNO
27800 DO 360 I=1,XNO
27900 YVAL(JJ,I)=YVAL(JJJ,I)
28000 360 CONTINUE
28100 JJ=JJ-1
28200 JJJ=JJJ-1
28300 370 CONTINUE
28400 C
28500 DO 380 I=1,XNO
28600 YVAL(1,I)=YVAL(2,I)
28700 380 CONTINUE
28800 C
28900 J=ZNO-1
29000 DO 390 I=1,XNO
29100 YVAL(ZNO,I)=YVAL(J,I)
29200 390 CONTINUE
29300 C
29400 C
29500 C DONE WITH EXTRAPOLATION AND FLATS.
29600 C
29700 C*****
29800 C
29900 C SCALING SECTION
30000 C
30100 C*****
30200 C
30300 C COMPUTE SCALE FACTORS AND MAX/MIN VALUES
30400 C
30500 5000 CONTINUE
30600 C
30700 XSF=XDNOM/XNUM
30800 YSF=YDNOM/YNUM
30900 IF (ZNUM.EQ.0.0) ZNUM=1.0
31000 ZSF=ZDNOM/ZNUM
31100 C
31200 XMAX=32767*XSF
31300 XMIN=-32768*XSF
31400 YMAX=32767*YSF
31500 YMIN=-32768*YSF
31600 ZMAX=32767*ZSF
31700 ZMIN=-32768*ZSF
31800 C
```

```

31900 C SCALE Z VALUES IF NECESSARY
32000 C
32100 IF (ZNO.EQ.1) GO TO 5100
32200 C
32300 DO 5010 J=1,ZNO
32400 C
32500 C ROUND Z VALUES
32600 IF (ZVAL(J).LT.0.0) GO TO 5001
32700 ZSCLD(J)=ZVAL(J)*ZSF+0.5
32800 GO TO 5005
32900 5001 ZSCLD(J)=ZVAL(J)*ZSF-0.5
33000 C
33100 5005 CONTINUE
33200 IF (ZSCLD(J).LE.ZMAX.OR.ZSCLD(J).GE.ZMIN) GO TO 5006
33300 IF (WARN.EQ.0) WRITE(10,1)
33400 1 FORMAT(1H1)
33500 WARN=1
33600 WRITE(10,5)ZVAL(J),ZSCLD(J),(TITLE(N),N=1,2)
33700 5 FORMAT(1X,'***** THE Z VALUE ',F13.7,' AS SCALED TO ',I6,' IS OUT OF RANGE IN-
33800 * CURVE ',2A4,'. *****')
33900 C
34000 5006 IF (ZSCLD(J).LE.32767) GO TO 5007
34100 IF (WARN.EQ.0) WRITE(10,1)
34200 WARN=1
34300 WRITE(10,6)ZSCLD(J),(TITLE(N),N=1,2)
34400 6: FORMAT(1X,'***** WARNING: THE Z VALUE ',I6,' FOR CURVE ',2A4,' HAS BEEN SET TO 32767.*****')
34500 ZSCLD(J)=32767
34600 C
34700 5007 IF (ZSCLD(J).GE.-32768) GO TO 5010
34800 IF (WARN.EQ.0) WRITE(10,1)
34900 WARN=1
35000 WRITE(10,7)ZSCLD(J),(TITLE(N),N=1,2)
35100 7 FORMAT(1X,'***** WARNING: THE Z VALUE ',I6,' FOR CURVE ',2A4,' HAS BEEN SET TO -32768.*****')
35200 ZSCLD(J)=-32768
35300 C
35400 5010 CONTINUE
35500 C
35600 C SCALE X AND Y VALUES
35700 C
35800 5100 DO 5200 J=1,ZNO
35900 DO 5200 I=1,XNO
36000 C
36100 C ROUND AND SCALE X VALUES
36200 IF (XVAL(J,I).LT.0.0) GO TO 5101
36300 XSCLD(J,I)=XVAL(J,I)*XSF+0.5
36400 GO TO 5102
36500 5101 XSCLD(J,I)=XVAL(J,I)*XSF-0.5
36600 C
36700 C ROUND AND SCALE Y VALUES
36800 5102 IF (YVAL(J,I).LT.0.0) GO TO 5103
36900 YSCLD(J,I)=YVAL(J,I)*YSF+0.5
37000 GO TO 5105
37100 5103 YSCLD(J,I)=YVAL(J,I)*YSF-0.5

```

```

37200 C
37300 5105 CONTINUE
37400 IF (XSCLD(J,I).LE.XMAX.OR.XSCLD(J,I).GE.XMIN) GO TO 5110
37500 IF (WARN.EQ.0) WRITE(10,1)
37600 WARN=1
37700 WRITE(10,10)XVAL(J,I),XSCLD(J,I),(TITLE(N),N=1,2)
37800 10 FORMAT(1X,'***** THE X VALUE ',F13.7,' AS SCALED TO ',I6,' IS OUT OF RANGE IN-
37900 * CURVE ',2A4,'. *****')
38000 5110 IF (YSCLD(J,I).LE.YMAX.OR.YSCLD(J,I).GE.YMIN) GO TO 5120
38100 IF (WARN.EQ.0) WRITE(10,1)
38200 WARN=1
38300 WRITE(10,15)YVAL(J,I),YSCLD(J,I),(TITLE(N),N=1,2)
38400 15 FORMAT(1X,'***** THE Y VALUE ',F13.7,' AS SCALED TO ',I6,' IS OUT OF RANGE IN-
38500 * CURVE ',2A4,'. *****')
38600 C
38700 5120 IF (XSCLD(J,I).LE.32767) GO TO 5125
38800 IF (WARN.EQ.0) WRITE(10,1)
38900 WARN=1
39000 WRITE(10,16)XSCLD(J,I),(TITLE(N),N=1,2)
39100 16 FORMAT(1X,'***** WARNING: THE X VALUE ',I6,' FOR CURVE ',2A4,' HAS BEEN SET TO 32767.*****')
39200 XSCLD(J,I)=32767
39300 C
39400 5125 IF (XSCLD(J,I).GE.-32768) GO TO 5130
39500 IF (WARN.EQ.0) WRITE(10,1)
39600 WARN=1
39700 WRITE(10,17)XSCLD(J,I),(TITLE(N),N=1,2)
39800 17 FORMAT(1X,'***** WARNING: THE X VALUE ',I6,' FOR CURVE ',2A4,' HAS BEEN SET TO -32768.*****')
39900 XSCLD(J,I)=-32768
40000 C
40100 5130 IF (YSCLD(J,I).LE.32767) GO TO 5135
40200 IF (WARN.EQ.0) WRITE(10,1)
40300 WARN=1
40400 WRITE(10,18)YSCLD(J,I),(TITLE(N),N=1,2)
40500 18 FORMAT(1X,'***** WARNING: THE Y VALUE ',I6,' FOR CURVE ',2A4,' HAS BEEN SET TO 32767.*****')
40600 YSCLD(J,I)=32767
40700 C
40800 5135 IF (YSCLD(J,I).GE.-32768) GO TO 5200
40900 IF (WARN.EQ.0) WRITE(10,1)
41000 WARN=1
41100 WRITE(10,19)YSCLD(J,I),(TITLE(N),N=1,2)
41200 19 FORMAT(1X,'***** WARNING: THE Y VALUE ',I6,' FOR CURVE ',2A4,' HAS BEEN SET TO -32768.*****')
41300 YSCLD(J,I)=-32768
41400 C
41500 5200 CONTINUE
41600 C
41700 C COMPUTE M AND B VALUES FOR NEFG AND SCALE
41800 C
41900 IF (FUNC.NE.0) GO TO 6000
42000 C
42100 MBNO=XNO-1
42200 DO 5510 I=1,MBNO
42300 II=I+1
42400 MVAL(I)=(YVAL(1,II)-YVAL(1,I))/(XVAL(1,II)-XVAL(1,I))

```



```

42500      BVAL(I)=YVAL(1,I)-MVAL(I)*XVAL(1,I)
42600 5510 CONTINUE
42700 C
42800 C COMPUTE PROPER SHIFT VALUE FOR M AND B SCALE FACTORS
42900 C
43000      MBIG=-32768
43100      BBIG=-32768
43200      MSMAL=32767
43300      BSMAL=32767
43400 C
43500      DO 5520 I=1,MBNO
43600      IF (MVAL(I).GT.MBIG) MBIG=MVAL(I)
43700      IF (BVAL(I).GT.BBIG) BBIG=BVAL(I)
43800      IF (MVAL(I).LT.MSMAL) MSMAL=MVAL(I)
43900      IF (BVAL(I).LT.BSMAL) BSMAL=BVAL(I)
44000 5520 CONTINUE
44100 C
44200      MSF=32768*YSF/XSF
44300      BSF=YSF
44400 C
44500      DO 5535 I=1,9
44600      SHFT=2**(I-1)
44700      SFTR=I-1
44800      MTST1=MBIG*MSF/SHFT
44900      MTST2=MSMAL*MSF/SHFT
45000      BTST1=BBIG*BSF/SHFT
45100      BTST2=BSMAL*BSF/SHFT
45200 C
45300      IF (MTST1.LE.32767.AND.MTST2.GE.-32768) GO TO 5530
45400      GO TO 5535
45500 C
45600 5530 IF (BTST1.LE.32767.AND.BTST2.GE.-32768) GO TO 5536
45700 C
45800 5535 CONTINUE
45900 C
46000 C IF SHIFTING 8 DOESN'T PUT THE SCALED VALUES WITHIN RANGE,
46100 C OUTPUT ERROR MESSAGE AND CONTINUE
46200 C
46300      IF (WARN.EQ.0) WRITE(10,1)
46400      WRITE(10,20)(TITLE(N),N=1,2)
46500 20 FORMAT(1X,'***** WARNING: THE M AND B SCALE FACTORS HAVE BEEN SHIFTED 8 (DIVIDED BY 256),'/'-
46600 *1X,' AND ONE OR BOTH ARE STILL OUT OF RANGE IN CURVE ',2A4,'. *****')
46700 C
46800 C
46900 5536 MSF=MSF/SHFT
47000      BSF=BSF/SHFT
47100 C
47200 C SEPARATE B INTO MSB AND LSB
47300 C
47400      DO 5545 I=1,MBNO
47500 C
47600 C
47700 C

```

```

47800 C ROUND AND SCALE B VALUES
47900 C
48000 IF (BMSB(I).LT.0) GO TO 5537
48100 BSCLD=BVAL(I)*BSF
48200 BMSB(I)=INT(BSCLD)
48300 LSB=BSCLD-BMSB(I)
48400 GO TO 5538
48500 5537 BSCLD=BVAL(I)*BSF
48600 BMSB(I)=INT(BSCLD)
48700 LSB=BSCLD-BMSB(I)
48800 5538 BLSB(I)=LSB*65536
48900 C
49000 C
49100 C ROUND AND SCALE M VALUES
49200 IF (MVAL(I).LT.0.0) GO TO 5539
49300 MSCLD(I)=MVAL(I)*MSF+0.5
49400 GO TO 5545
49500 5539 MSCLD(I)=MVAL(I)*MSF-0.5
49600 C
49700 5545 CONTINUE
49800 C
49900 C*****
50000 C
50100 C OUTPUT SECTION
50200 C
50300 C*****
50400 C
50500 C OUTPUT NEFG TABLE AND DATASET
50600 C
50700 IF (WARN.EQ.0) WRITE(10,1)
50800 WRITE(10,5550)(TITLE(I),I=1,2)
50900 5550 FORMAT(/,1X,'NEFG CURVE ',2A4,/)
51000 C
51100 WRITE(10,5551)XSF,XDNOM,XNUM,YSF,YDNOM,YNUM,MSF,SFTR,BSF,SFTR
51200 5551 FORMAT(5X,'X SCALE FACTOR: ',G12.6,' ('',G12.6,'/',G12.6,')',',',/,/,',-
51300 *5X,'Y SCALE FACTOR: ',G12.6,' ('',G12.6,'/',G12.6,')',',',/,/,',-
51400 *5X,'M SCALE FACTOR: ',G12.6,5X,'M SHIFT FACTOR: ',I1,/,/,',-
51500 *5X,'B SCALE FACTOR: ',G12.6,5X,'B SHIFT FACTOR: ',I1,/,/,')
51600 WRITE(10,5552)
51700 5552 FORMAT(14X,'X',13X,'SCALED X',13X,'Y',13X,'SCALED Y'//)
51800 C
51900 DO 5553 I=1,XNO
52000 5553 WRITE(10,5554)XVAL(1,I),XSCLD(1,I),YVAL(1,I),YSCLD(1,I)
52100 5554 FORMAT(2(8X,G13.6,8X,I6))
52200 WRITE(10,5555)
52300 5555 FORMAT(/,9X,'M',9X,'SCALED M',9X,'B',9X,'SCALED B (MSB)',3X,'SCALED B (LSB)')
52400 DO 5556 I=1,MBNO
52500 5556 WRITE(10,5557)MVAL(I),MSCLD(I),BVAL(I),BMSB(I),BLSB(I)
52600 5557 FORMAT(3X,G13.6,4X,I6,4X,G13.6,7X,I6,11X,I6)
52700 C
52800 C TABLE DONE. NOW FOR DATASET.
52900 C
53000 WRITE(20,5573)(TITLE(I),I=1,2)

```

```

53100 5573 FORMAT(1H1,'; DATA FOR NEFG CURVE ',2A4)
53200 C
53300 C RELOCATABLE OR ABSOLUTE?
53400 C
53500 IF (FRMT.EQ.0) GO TO 5575
53600 WRITE(20,5574)ORG
53700 5574 FORMAT(1H ,8X,'ORG',5X,I4,'H')
53800 C
53900 C WRITE X
54000 C
54100 5575 CONTINUE
54200 CALL WRTDTA(XSCLD,XNO,XNAME,0,1)
54300 C
54400 C WRITE M
54500 C
54600 5700 MLNS=MBNO/5
54700 IF (MLNS*5.NE.MBNO) MLNS=MLNS+1
54800 IF (MBNO.LT.5) GO TO 5730
54900 WRITE(20,5705)(MNAME(N),N=1,2),(MSCLD(I),I=1,5)
55000 5705 FORMAT(1H ,2A4,'DW',6X,4(I6,','),I6)
55100 IF (MLNS.EQ.1) GO TO 5800
55200 KK=6
55300 KKK=10
55400 II=XNO
55500 DO 5725 I=2,MLNS
55600 II=II-5
55700 IF (II.LT.5) GO TO 5715
55800 WRITE(20,5710)(MSCLD(K),K=KK,KKK)
55900 5710 FORMAT(1H ,8X,'DW',6X,4(I6,','),I6)
56000 KK=KK+5
56100 KKK=KKK+5
56200 GO TO 5725
56300 C
56400 5715 III=II-1
56500 KKK=KK+III
56600 IF (II.EQ.4) WRITE(20,5720)(MSCLD(K),K=KK,KKK)
56700 5720 FORMAT(1H ,8X,'DW',6X,3(I6,','),I6)
56800 IF (II.EQ.3) WRITE(20,5721)(MSCLD(K),K=KK,KKK)
56900 5721 FORMAT(1H ,8X,'DW',6X,2(I6,','),I6)
57000 IF (II.EQ.2) WRITE(20,5722)(MSCLD(K),K=KK,KKK)
57100 5722 FORMAT(1H ,8X,'DW',6X,I6,',',I6)
57200 IF (II.EQ.1) WRITE(20,5723)(MSCLD(K),K=KK,KKK)
57300 5723 FORMAT(1H ,8X,'DW',6X,I6)
57400 C
57500 5725 CONTINUE
57600 C
57700 GO TO 5800
57800 C
57900 5730 CONTINUE
58000 IF (MBNO.EQ.4) WRITE(20,5035)(MNAME(N),N=1,2),(MSCLD(I),I=1,4)
58100 5035 FORMAT(1H ,2A4,'DW',6X,3(I6,','),I6)
58200 IF (MBNO.EQ.3) WRITE(20,5036)(MNAME(N),N=1,2),(MSCLD(I),I=1,3)
58300 5036 FORMAT(1H ,2A4,'DW',6X,2(I6,','),I6)

```

```

58400      IF (MBNO.EQ.2) WRITE(20,5037)(MNAME(N),N=1,2),(MSCLD(I),I=1,2)
58500      5037 FORMAT(1H ,2A4,'DW',6X,I6,',',',I6)
58600      IF (MBNO.EQ.1) WRITE(20,5038)MSCLD(1)
58700      5038 FORMAT(1H ,2A4,'DW',6X,I6)
58800      C
58900      C   WRITE B
59000      C
59100      5800 BLNS=MBNO/3
59200      IF (BLNS*3.NE.MBNO) BLNS=BLNS+1
59300      IF (MBNO.LT.3) GO TO 5840
59400      WRITE(20,5805)(BNAME(N),N=1,2),BMSB(1),BLSB(1),BMSB(2),BLSB(2),BMSB(3),BLSB(3)
59500      5805 FORMAT(1H ,2A4,'DW',6X,5(I6,',','),I6)
59600      IF (BLNS.EQ.1) GO TO 9999
59700      KK=4
59800      II=MBNO
59900      C
60000      DO 5835 I=2,BLNS
60100      II=II-3
60200      IF (II.LT.3) GO TO 5815
60300      WRITE(20,5810)BMSB(KK),BLSB(KK),BMSB(KK+1),BLSB(KK+1),BMSB(KK+2),BLSB(KK+2)
60400      5810 FORMAT(1H ,8X,'DW',6X,5(I6,',','),I6)
60500      KK=KK+3
60600      GO TO 5835
60700      C
60800      5815 III=II-1
60900      IF (II.NE.1) GO TO 5825
61000      WRITE(20,5820)BMSB(KK),BLSB(KK)
61100      5820 FORMAT(1H ,8X,'DW',6X,I6,',',',I6)
61200      GO TO 9999
61300      C
61400      5825 WRITE(20,5830)BMSB(KK),BLSB(KK),BMSB(KK+1),BLSB(KK+1)
61500      5830 FORMAT(1H ,8X,'DW',6X,3(I6,',','),I6)
61600      C
61700      5835 CONTINUE
61800      GO TO 9999
61900      C
62000      C
62100      5840 IF (MBNO.NE.1) GO TO 5850
62200      WRITE(20,5845)(BNAME(N),N=1,2),BMSB(1),BLSB(1)
62300      5845 FORMAT(1H ,2A4,'DW',6X,I6,',',',I6)
62400      GO TO 9999
62500      C
62600      5850 WRITE(20,5855)(BNAME(N),N=1,2),BMSB(1),BLSB(1),BMSB(2),BLSB(2)
62700      5855 FORMAT(1H ,2A4,3(I6,',','),I6)
62800      GO TO 9999
62900      C
63000      C   END NEFG TABLE AND DATASET. STOP.
63100      C
63200      C
63300      C   FUN1 TABLE AND DATASET
63400      C
63500      6000 IF (FUNC.NE.1) GO TO 7000
63600      C

```

```

63700      IF (WARN.EQ.0) WRITE(10,1)
63800      WRITE(10,6005)(TITLE(I),I=1,2),XSF,XDNOM,XNUM,YSF,YDNOM,YNUM
63900      6005 FORMAT(/,1X,4X,'FUN1 CURVE ',2A4,///-
64000      *5X,'X SCALE FACTOR: ',G12.6,' ('',G12.6,'/',',G12.6,')',///,-
64100      *5X,'Y SCALE FACTOR: ',G12.6,' ('',G12.6,'/',',G12.6,')',///)
64200      C
64300      WRITE(10,6010)
64400      6010 FORMAT(14X,'X',13X,'SCALED X',13X,'Y',13X,'SCALED Y'///)
64500      DO 6015 I=1,XNO
64600      6015 WRITE(10,6020)XVAL(1,I),XSCLD(1,I),YVAL(1,I),YSCLD(1,I)
64700      6020 FORMAT(2(8X,G13.6,8X,I6))
64800      C
64900      C   TABLE DONE. NOW FOR DATASET.
65000      C
65100      WRITE(20,6025)(TITLE(I),I=1,2)
65200      6025 FORMAT(1H1,';   DATA FOR FUN1 CURVE ',2A4)
65300      C
65400      C   RELOCATABLE OR ABSOLUTE?
65500      C
65600      IF (FRMT.EQ.0) GO TO 6035
65700      WRITE(20,6030)ORG
65800      6030 FORMAT(1H ,8X,'ORG',5X,I4,'H')
65900      C
66000      C   WRITE X AND Y
66100      C
66200      6035 CONTINUE
66300      CALL WRDTA(XSCLD,XNO,XNAME,0,1)
66400      C
66500      CALL WRDTA(YSCLD,XNO,YNAME,0,1)
66600      C
66700      C   END FUN1 TABLE AND DATASET. STOP.
66800      C
66900      GO TO 9999
67000      C
67100      C   FUN1A TABLE AND DATASET.
67200      C
67300      7000 IF (FUNC.NE.11) GO TO 8000
67400      C
67500      IF (WARN.EQ.0) WRITE(10,1)
67600      WRITE(10,7005)(TITLE(I),I=1,2),XSF,XDNOM,XNUM,YSF,YDNOM,YNUM
67700      7005 FORMAT(/,1X,4X,'FUN1A CURVE ',2A4,///,-
67800      *5X,'X SCALE FACTOR: ',G12.6,' ('',G12.6,'/',',G12.6,')',///,-
67900      *5X,'Y SCALE FACTOR: ',G12.6,' ('',G12.6,'/',',G12.6,')',///)
68000      WRITE(10,6010)
68100      DO 7010 I=1,XNO
68200      7010 WRITE(10,6020)XVAL(1,I),XSCLD(1,I),YVAL(1,I),YSCLD(1,I)
68300      C
68400      C   TABLE DONE. NOW FOR DATASET.
68500      C
68600      WRITE(20,7015)(TITLE(N),N=1,2)
68700      7015 FORMAT(1H1,';   DATA FOR FUN1A CURVE ',2A4)
68800      C
68900      C   RELOCATABLE OR ABSOLUTE?

```

```

69000 C
69100 IF (FRMT.EQ.0) GO TO 7020
69200 WRITE(20,6030)ORG
69300 C
69400 7020 CONTINUE
69500 CALL WRTDTA(YSCLD,XNO,Y1NAME,0,1)
69600 C
69700 C END FUN1A TABLE AND DATASET. STOP.
69800 C
69900 GO TO 9999
70000 C
70100 C FUN2 TABLE AND DATASET.
70200 C
70300 8000 IF (FUNC.NE.2) GO TO 9000
70400 C
70500 DO 8047 J=1,ZNO
70600 IF (J.NE.1) GO TO 8010
70700 IF (WARN.EQ.0) WRITE(10,1)
70800 WRITE(10,8001)(TITLE(N),N=1,2)
70900 8001 FORMAT(/,1X,'FUN2 CURVE ',2A4,/)
71000 WRITE(10,8005)XSF,XDNOM,XNUM,YSF,YDNOM,YNUM,ZSF,ZDNOM,ZNUM
71100 8005 FORMAT(-
71200 *5X,'X SCALE FACTOR: ',G12.6,' ('',G12.6,'/',G12.6,'')',//,-
71300 *5X,'Y SCALE FACTOR: ',G12.6,' ('',G12.6,'/',G12.6,'')',//,-
71400 *5X,'Z SCALE FACTOR: ',G12.6,' ('',G12.6,'/',G12.6,'')',///)
71500 C
71600 8010 IF (J.NE.1) GO TO 8016
71700 WRITE(10,8015)ZVAL(J),ZSCLD(J)
71800 8015 FORMAT(14X,'Z = ',G13.6,13X,'SCALED Z = ',I6,///)
71900 GO TO 8021
72000 8016 WRITE(10,8020)(TITLE(N),N=1,2),ZVAL(J),ZSCLD(J)
72100 8020 FORMAT(1H1,/,1X,'FUN2 CURVE ',2A4,///,13X,'Z = ',G13.6,13X,'SCALED Z = ',I6,///)
72200 C
72300 C X AND Y TABLES
72400 C
72500 8021 WRITE(10,8025)
72600 8025 FORMAT(8X,'X',8X,'SCALED X',8X,'Y',8X,'SCALED Y')
72700 C
72800 DO 8046 I=1,XNO
72900 WRITE(10,8030)XVAL(1,I),XSCLD(1,I),YVAL(J,I),YSCLD(J,I)
73000 8030 FORMAT(2(3X,G13.6,3X,I6))
73100 C
73200 8046 CONTINUE
73300 8047 CONTINUE
73400 C
73500 C DONE WITH Z TABLE. NOW FOR Z DATASET.
73600 C
73700 C
73800 C RELOCATABLE OR ABSOLUTE?
73900 C
74000 WRITE(20,8099)(TITLE(N),N=1,2)
74100 8099 FORMAT(1H1,'; DATA FOR FUN2 CURVE ',2A4)
74200 8100 IF (FRMT.EQ.0) GO TO 8102

```

```

74300      WRITE(20,8101)ORG
74400      8101 FORMAT(1H ,8X,'ORG',5X,I4,'H')
74500      C
74600      C   Z VECTOR
74700      C
74800      8102 ZLNS=ZNO/5
74900          IF (ZLNS*5.NE.ZNO) ZLNS=ZLNS+1
75000          IF (ZNO.LT.5) GO TO 8125
75100          IF (FUNC.EQ.3) GO TO 8106
75200          WRITE(20,8105)(ZNAME(N),N=1,2),(ZSCLD(I),I=1,5)
75300      8105 FORMAT(1H ,2A4,'DW',6X,4(I6,' '),I6)
75400          GO TO 8108
75500      8106 WRITE(20,8107)(ZNAME(N),N=1,2),(ZSCLD(I),I=1,5)
75600      8107 FORMAT(1H ,2A4,'DW',6X,4(I6,' '),I6)
75700          IF (ZLNS.EQ.1) GO TO 8199
75800      C
75900      8108 KK=6
76000          KKK=10
76100          II=ZNO
76200      C
76300          DO 8120 I=2,ZLNS
76400          II=II-5
76500          IF (II.LT.5) GO TO 8115
76600          WRITE(20,8110)(ZSCLD(K),K=KK,KKK)
76700      8110 FORMAT(1H ,8X,'DW',6X,4(I6,' '),I6)
76800          KK=KK+5
76900          KKK=KKK+5
77000          GO TO 8120
77100      C
77200      8115 III=II-1
77300          KKK=KK+III
77400          IF (II.EQ.4) WRITE(20,5720)(ZSCLD(K),K=KK,KKK)
77500          IF (II.EQ.3) WRITE(20,5721)(ZSCLD(K),K=KK,KKK)
77600          IF (II.EQ.2) WRITE(20,5722)(ZSCLD(K),K=KK,KKK)
77700          IF (II.EQ.1) WRITE(20,5723)(ZSCLD(K),K=KK,KKK)
77800      C
77900      8120 CONTINUE
78000          GO TO 8199
78100      C
78200      8125 CONTINUE
78300      C
78400          IF (ZNO.EQ.4) WRITE(20,8130)(ZNAME(N),N=1,2),(ZSCLD(I),I=1,4)
78500      8130 FORMAT(1H ,2A4,'DW',6X,3(I6,' '),I6)
78600          IF (ZNO.EQ.3) WRITE(20,8131)(ZNAME(N),N=1,2),(ZSCLD(I),I=1,3)
78700      8131 FORMAT(1H ,2A4,'DW',6X,2(I6,' '),I6)
78800          IF (ZNO.EQ.2) WRITE(20,8132)(ZNAME(N),N=1,2),(ZSCLD(I),I=1,2)
78900      8132 FORMAT(1H ,2A4,'DW',6X,I6,' ',I6)
79000          IF (ZNO.EQ.1) WRITE(20,8133)ZSCLD(1)
79100      8133 FORMAT(1H ,2A4,'DW',6X,I6)
79200      C
79300      8199 IF (FUNC.EQ.3) GO TO 9100
79400      C
79500      C   WRITE X AND Y

```

```

79600 C
79700 8200 CONTINUE
79800     CALL WRDTA(XSCLD,XNO,XNAME,1,1)
79900 C
80000     CALL WRDTA(YSCLD,XNO,YNAME,1,ZNO)
80100 C
80200 C     DONE WITH FUN2. STOP.
80300 C
80400     GO TO 9999
80500 C
80600 C     NOW FOR FUN3 TABLES.
80700 C
80800 C
80900 9000 CONTINUE
81000 C
81100     DO 9047 J=1,ZNO
81200     IF (J.NE.1) GO TO 9010
81300     IF (WARN.EQ.0) WRITE(10,1)
81400     WRITE(10,9001)(TITLE(N),N=1,2)
81500 9001 FORMAT(/,1X,'FUN3 CURVE ',2A4,/)
81600     WRITE(10,9005)XSF,XDNOM,XNUM,YSF,YDNOM,YNUM,ZSF,ZDNOM,ZNUM
81700 9005 FORMAT(-
81800     *5X,'X SCALE FACTOR: ',G12.6,' ('',G12.6,'/',G12.6,'')',//,-
81900     *5X,'Y SCALE FACTOR: ',G12.6,' ('',G12.6,'/',G12.6,'')',//,-
82000     *5X,'Z SCALE FACTOR: ',G12.6,' ('',G12.6,'/',G12.6,'')',//)
82100 C
82200 9010 IF (J.NE.1) GO TO 9016
82300     WRITE(10,9015)ZVAL(J),ZSCLD(J)
82400 9015 FORMAT(14X,'Z = ',G13.6,13X,'SCALED Z = ',I6//)
82500     GO TO 9021
82600 9016 WRITE(10,9020)(TITLE(N),N=1,2),ZVAL(J),ZSCLD(J)
82700 9020 FORMAT(1H1,/,1X,'FUN3 CURVE ',2A4,13X,'Z = ',G13.6,13X,'SCALED Z = ',I6//)
82800 C
82900 C     X AND Y TABLES
83000 C
83100 9021 WRITE(10,9025)
83200 9025 FORMAT(8X,'X',8X,'SCALED X',8X,'Y',8X,'SCALED Y'//)
83300 C
83400     DO 9046 I=1,XNO
83500     WRITE(10,9030)XVAL(J,I),XSCLD(J,I),YVAL(J,I),YSCLD(J,I)
83600 9030 FORMAT(3X,G13.6,3X,I6,3X,G13.6,3X,I6)
83700 C
83800 9046 CONTINUE
83900 9047 CONTINUE
84000 C
84100 C     DONE WITH Z TABLE; NOW FOR Z DATASET.
84200 C
84300 C     Z VECTOR
84400 C
84500     WRITE(20,9050)(TITLE(N),N=1,2)
84600 9050 FORMAT(1H1,';     DATA FOR FUN3 CURVE ',2A4)
84700     GO TO 8100
84800 C

```


INTELSCL,07/29/80 08:30:46

PAGE 018

```
84900 C X AND Y VECTORS
85000 C
85100 9100 CONTINUE
85200 CALL WRTDTA(XSCLD,XNO,XNAME,1,ZNO)
85300 C
85400 CALL WRTDTA(YSCLD,XNO,YNAME,1,ZNO)
85500 C
85600 C END OF ROUTINE
85700 C
85800 9999 RETURN
85900 END
```

```

100      SUBROUTINE WRDTA(FUNARY,XPTS,DNAME,FNTN,ZPTS)
200      C
300      C THIS SUBROUTINE WRITES DATA VECTORS FOR DATA PROCESSED IN ROUTINE INTSCL.
400      C
500      C CALLING SEQUENCE:
600      C
700      C FUNARY  -- TWO-DIMENSIONAL ARRAY FOR X AND Y VECTORS IN NEFG,FUN1,FUNIA,FUN2, AND FUN3
800      C XPTS   -- NUMBER OF X POINTS IN VECTOR
900      C DNAME  -- VARIABLE NAME TO BE PLACED TO START OF DATA
1000     C FNTN   -- INDICATES FUNCTION TABLE IS FOR
1100     C         0 = NEFG,FUN1,FUNIA
1200     C         1 = FUN2,FUN3
1300     C ZPTS   -- NUMBER OF Z POINTS IN VECTOR
1400     C
1500     C DIMENSION FUNARY(100,100),DNAME(2)
1600     C INTEGER FUNARY,XPTS,FNTN,ZPTS,ZZPTS
1700     C
1800     C ZZPTS=ZPTS
1900     C IF (FNTN.EQ.0) ZZPTS=1
2000     C
2100     C
2200     C
2300     C DO 2000 J=1,ZZPTS
2400     C
2450     C 100 CONTINUE
2500     C LNS=XPTS/5
2600     C IF (LNS*5.NE.XPTS) LNS=LNS+1
2700     C IF (XPTS.LT.5) GO TO 1030
2800     C
2900     C WRITE FIRST LINE
3000     C
3100     C IF (J.NE.1) GO TO 1006
3200     C WRITE(20,1005)(DNAME(N),N=1,2),(FUNARY(J,I),I=1,5)
3300     C 1005 FORMAT(1H ,2A4,'DW',6X,4(I6,', '),I6)
3400     C GO TO 1009
3500     C
3600     C 1006 WRITE(20,1010)(FUNARY(J,I),I=1,5)
3700     C
3800     C 1009 IF (LNS.EQ.1) GO TO 2000
3900     C KK=6
4000     C KKK=10
4100     C II=XPTS
4200     C
4300     C WRITE SUBSEQUENT LINES
4400     C
4500     C DO 1025 I=2,LNS
4600     C II=II-5
4700     C IF (II.LT.5) GO TO 1015
4800     C WRITE(20,1010)(FUNARY(J,K),K=KK,KKK)
4900     C 1010 FORMAT(1H ,8X,'DW',6X,4(I6,', '),I6)
5000     C KK=KK+5
5100     C KKK=KKK+5
5200     C GO TO 1025

```

```
5300 C
5400 C   IF LAST LINE HAS < 5 POINTS:
5500 C
5600   1015 III=II-1
5700       KKK=KK+III
5800       IF (II.EQ.4) WRITE(20,1045)(FUNARY(J,K),K=KK,KKK)
5900       IF (II.EQ.3) WRITE(20,1046)(FUNARY(J,K),K=KK,KKK)
6000       IF (II.EQ.2) WRITE(20,1047)(FUNARY(J,K),K=KK,KKK)
6100       IF (II.EQ.1) WRITE(20,1048)(FUNARY(J,K),K=KK,KKK)
6200 C
6300   1025 CONTINUE
6400 C
6500       GO TO 2000
6600 C
6700 C   IF VECTOR HAS < 5 TOTAL POINTS
6800 C
6900   1030 CONTINUE
7000       IF (J.NE.1) GO TO 1040
7100 C
7200       IF (XPTS.EQ.4) WRITE(20,1035)(DNAME(N),N=1,2),(FUNARY(J,I),I=1,4)
7300   1035 FORMAT(1H ,2A4,'DW',6X,3(I6,' '),I6)
7400       IF (XPTS.EQ.3) WRITE(20,1036)(DNAME(N),N=1,2),(FUNARY(J,I),I=1,3)
7500   1036 FORMAT(1H ,2A4,'DW',6X,2(I6,' '),I6)
7600       IF (XPTS.EQ.2) WRITE(20,1037)(DNAME(N),N=1,2),(FUNARY(J,I),I=1,2)
7700   1037 FORMAT(1H ,2A4,'DW',6X,I6,' ',I6)
7800       IF (XPTS.EQ.1) WRITE(20,1038)(DNAME(N),N=1,2),FUNARY(J,1)
7900   1038 FORMAT(1H ,2A4,'DW',6X,I6)
8000 C
8100       GO TO 2000
8200 C
8300   1040 CONTINUE
8400 C
8500       IF (XPTS.EQ.4) WRITE(20,1045)(FUNARY(J,I),I=1,4)
8600   1045 FORMAT(1H ,8X,'DW',6X,3(I6,' '),I6)
8700       IF (XPTS.EQ.3) WRITE(20,1046)(FUNARY(J,I),I=1,3)
8800   1046 FORMAT(1H ,8X,'DW',6X,2(I6,' '),I6)
8900       IF (XPTS.EQ.2) WRITE(20,1047)(FUNARY(J,I),I=1,2)
9000   1047 FORMAT(1H ,8X,'DW',6X,I6,' ',I6)
9100       IF (XPTS.EQ.1) WRITE(20,1048)FUNARY(J,1)
9200   1048 FORMAT(1H ,8X,'DW',6X,I6)
9300 C
9400 C
9500   2000 CONTINUE
9600   9999 RETURN
9700       END
```






Figure 1. - Univariate function.




Figure 2. - Bivariate function.




Figure 3. - Bivariate function interpolation diagram.




Figure 4. - Map function.




Figure 5. - Map function interpolation diagram.

```

-32768  x1  x2  x3  x4  32767
        y1  y1  y2  y3  y4  y4

```

Figure 6. - Example of FUN1 data storage format.

```

x value   -32768  x1  x2  x3  x4  32768
y value    y1  y1  y2  y3  y4  y4
y value prime  y1' y1' y2' y3' y4' y4'

```

Figure 7. - Example of FUN1 and FUN1A data storage format.

```

x value -32768  x1  x2  x3  x4  32768
m value  m1  m2  m3  m4  m5
b value  b1b1L b2b2L b3b3L b4b4L b5b5L

```

Figure 8. - Example of NEFG data storage format.

z values	-32768	z_1	z_2	z_3		32767
x values	-32768	x_1	x_2	x_3	x_4	32767
y values	y_{11}	y_{11}	y_{12}	y_{13}	y_{14}	y_{14}
	y_{11}	y_{11}	y_{12}	y_{13}	y_{14}	y_{14}
	y_{21}	y_{21}	y_{22}	y_{23}	y_{24}	y_{24}
	y_{31}	y_{31}	y_{32}	y_{33}	y_{34}	y_{34}
	y_{31}	y_{31}	y_{32}	y_{33}	y_{34}	y_{34}

Figure 9. - Example of FUN2 data storage format. (Note y_{ij} form, where i corresponds to z value and j corresponds to x value.)

z value	z_1	z_2	z_3	z_4	
x value	-32768	x_{11}	x_{12}	x_{13}	32767
	-32768	x_{21}	x_{22}	x_{23}	32767
	-32768	x_{31}	x_{32}	x_{33}	32767
	-32768	x_{41}	x_{42}	x_{43}	32767
y value	y_{11}	y_{11}	y_{12}	y_{13}	y_{13}
	y_{21}	y_{21}	y_{22}	y_{23}	y_{23}
	y_{31}	y_{31}	y_{32}	y_{33}	y_{33}
	y_{41}	y_{41}	y_{42}	y_{43}	y_{44}

Figure 10. - Example of FUN3 data storage format. (Note that x_{ij} and y_{ij} form, where i corresponds to z value and j corresponds to x value.)

Data/function type/XB, XBRKP, #x's, #z's
 x values
 z values
 y values

Figure 11. - Generalized data input.

Data/FUN1/0.0, 0.0, 3.0, 0.0

x_1, x_2, x_3

y_1, y_2, y_3

Figure 12. - Example of FUN1 data input for Fortran program.

Data/FUN2/0.0, 0.0, 4.0, 3.0

x_1, x_2, x_3, x_4

z_1, z_2, z_3

y_{11}, y_{12}, y_{13}

y_{21}, y_{22}, y_{23}

y_{31}, y_{32}, y_{33}

y_{41}, y_{42}, y_{43}

Figure 13. - Example of FUN2 data input for Fortran program. (Note y_{ij} form, where i corresponds to x value and j corresponds to z value.)

Data/FUN3/0.0, 1.0, 4.0, 3.0

x_{11}, x_{12}, x_{13}

x_{21}, x_{22}, x_{23}

x_{31}, x_{32}, x_{33}

x_{41}, x_{42}, x_{43}

z_1, z_2, z_3

y_{11}, y_{12}, y_{13}

y_{21}, y_{22}, y_{23}

y_{31}, y_{32}, y_{33}

y_{41}, y_{42}, y_{43}

Figure 14. - Example of FUN3 data input for Fortran program. (Note y_{ij} form, where i corresponds to x value and j corresponds to z value.)




Figure 15. - Fortran program functional flowchart.

FUN1 CURVE DP255H
 X SCALE FACTOR: 81.9200 (32768.0 / 400.000)
 Y SCALE FACTOR: 204800. (32768.0 / 0.160000)

X	SCALED X	Y	SCALED Y
-400.000	-32768	0.740000E-01	15565
73.0000	6029	0.740000E-01	15565
118.000	9748	0.108000	22118
123.000	10142	0.109350	22395
146.000	11960	0.115600	23663
152.000	12452	0.115940	23675
180.400	14776	0.115240	23601
203.000	16430	0.115010	23554
204.800	16712	0.115000	23552
218.000	17859	0.111450	22825
221.700	18326	0.110000	22528
232.500	19046	0.102000	20890
399.988	32767	0.102000	20890

(a) FUN1.

NEFG CURVE M1P2CV
 X SCALE FACTOR: 800.000 (32000.0 / 40.0000)
 Y SCALE FACTOR: 2.18453 (32768.0 / 15000.0)
 M SCALE FACTOR: 89.4784 M SHIFT FACTOR: 0
 B SCALE FACTOR: 2.18453 B SHIFT FACTOR: 0

X	SCALED X	Y	SCALED Y
-40.9600	-32768	0.000000	0
25.0000	22000	0.000000	0
30.0000	24000	482.500	1054
35.0000	000	1158.00	2530
40.9587	767	1158.00	2530

M	SCALED M	B	SCALED B (MSB)	SCALED B (LSB)
0.000000	0	0.000000	0	0
96.5000	8635	-2412.50	-5270	-12032
135.100	12008	-5370.50	-7799	-57078
0.000000	0	1158.00	2529	45168

(b) NEFG.

Figure 16. - Examples of scaling program output for FUN1 and NEFG curves.

FUN2 CURVE PT6SCH
 X SCALE FACTOR: 81.9200 (32768.0 / 400.000)
 Y SCALE FACTOR: 320.000 (32000.0 / 100.000)
 Z SCALE FACTOR: 800.000 (32000.0 / 40.0000)

Z = -40.9600 SCALED Z = -32768

X	SCALED X	Y	SCALED Y
-400.000	-32768	1.80000	576
111.000	9093	1.80000	576
165.000	13517	1.90000	608
199.000	16302	2.00000	640
234.000	19169	4.10000	1312
399.988	32767	4.10000	1312

(a) FUN2.

***** WARNING: THE Y VALUE 44262 FOR CURVE H7 HAS BEEN SET TO 32767.*****
 ***** WARNING: THE Y VALUE 53800 FOR CURVE H7 HAS BEEN SET TO 32767.*****
 ***** WARNING: THE Y VALUE 47143 FOR CURVE H7 HAS BEEN SET TO 32767.*****
 ***** WARNING: THE Y VALUE 42386 FOR CURVE H7 HAS BEEN SET TO 32767.*****
 ***** WARNING: THE Y VALUE 33167 FOR CURVE H7 HAS BEEN SET TO 32767.*****

FUN3 CURVE H7
 X SCALE FACTOR: 2.13333 (32000.0 / 15000.0)
 Y SCALE FACTOR: 727.273 (32000.0 / 44.0000)
 Z SCALE FACTOR: 32.0000 (32000.0 / 1000.00)

Z = -100.000 SCALED Z = -3200

X	SCALED X	Y	SCALED Y
-15360.0	-32768	-40.0000	-29091
7016.00	14967	-40.0000	-29091
8447.00	18020	-2.00000	-1455
9059.00	19326	6.00000	4364
15359.5	32767	88.3598	32767

(b) FUN3.

Figure 17. - Example of scaling program output for FUN2 and FUN3 curves.

```

: DATA FOR FUN2 CURVE WACCRV
ZMACCRV DW -32768. -269. 806. 2517. 4339
          DW 8933. 11831. 17741. 32767
XMACCRV DW -32768. 4287. 5973. 7689. 11093
          DW 14293. 17707. 32767
YMACCRV DW 9773. 9773. 10789. 13009. 16769
          DW 18326. 19169. 19169
          DW 9773. 9773. 10789. 13009. 16769
          DW 18326. 19169. 19169
          DW 8413. 8413. 10789. 13009. 16056
          DW 17883. 19048. 19048
          DW 7741. 7741. 10789. 12435. 14778
          DW 14640. 18842. 18842
          DW 7741. 7741. 10789. 11969. 13656
          DW 13319. 18104. 18104
          DW 7741. 7741. 12789. 11428. 12747
          DW 13918. 14957. 14957
          DW 7741. 7741. 10789. 10789. 10789
          DW 11428. 14868. 14868
          DW 7741. 7741. 10789. 10409. 10409
          DW 10609. 11510. 11510
          DW 7741. 7741. 10789. 10409. 10409
          DW 10609. 11510. 11510

```

Figure 18. - Example of scaling program code output for FUN2 curve.

1. Report No. NASA TM-81586	2. Government Accession No.	3. Recipient's Catalog No.	
4. Title and Subtitle NONANALYTIC FUNCTION GENERATION ROUTINES FOR 16-BIT MICROPROCESSORS		5. Report Date September 1980	6. Performing Organization Code
		8. Performing Organization Report No. E-565	
7. Author(s) James F. Soeder and Maryrita Shauf		10. Work Unit No.	11. Contract or Grant No.
9. Performing Organization Name and Address National Aeronautics and Space Administration Lewis Research Center Cleveland, Ohio 44135		13. Type of Report and Period Covered Technical Memorandum	
		14. Sponsoring Agency Code	
12. Sponsoring Agency Name and Address National Aeronautics and Space Administration Washington, D. C. 20546		15. Supplementary Notes	
16. Abstract <p>This report describes various interpolation techniques for three types of nonanalytic functions: univariate, bivariate, and map. These interpolation techniques are then implemented in scaled-fraction arithmetic on a representative 16-bit microprocessor. This work was done on an Intel 8086; however, the programs can be modified for use with any 16-bit microprocessor. A Fortran program is described that facilitates the scaling, documentation, and organization of data for use by these routines. Listings of all these programs are included in an appendix to the report.</p>			
17. Key Words (Suggested by Author(s)) Computer programs Microprocessors Digital control		18. Distribution Statement Unclassified - unlimited STAR Category 61	
19. Security Classif. (of this report) Unclassified	20. Security Classif. (of this page) Unclassified	21. No. of Pages	22. Price*



National Aeronautics and
Space Administration

Washington, D.C.
20546

Official Business
Penalty for Private Use, \$300

SPECIAL FOURTH CLASS MAIL
BOOK

Postage and Fees Paid
National Aeronautics and
Space Administration
NASA-451



NASA

POSTMASTER: If Undeliverable (Section 158
Postal Manual) Do Not Return
