

## **Product Discontinuation Statement**

This document outlines Axis products that have been discontinued or will be discontinued, and indicates the relevant replacement products.

The following products are covered by this statement:

- AXIS S9201
- AXIS S9002

## **Final Order Date**

The reason for this discontinuation is that the products will be upgraded to Mk II versions. Since this regards an upgrade, a final order date is not applicable. The old models will continue to be sold until they are out of stock, at which time all orders shall be transferred to the new Mk II versions.

## **Discontinued Products**

Discontinued Product	Replacement Product
AXIS S9201	
EUR [01174-002]	AXIS S9201 Mk II
UK [01174-003]	EUR [01691-002]
US [01174-004]	UK [01691-003]
JP [01174-005]	US [01691-004]
AUS [01174-006]	JP [01691-005]
BR [01174-012]	AUS [01691-006]
CN [01174-002]	BR [01691-012]
KOR [01174-007]	TW [01691-013]
TW [01174-013]	
	AXIS S9002 Mk II
	EUR [01619-002]
AXIS S9002	UK [01619-003]
EUR/US/US [0202-860]	US [01619-004]
APAC [0202-890]	JP [01619-005]
	AUS [01619-006]
	BR [01619-012]
	TW [01619-013]

## **Support Policy**

Axis will continue to give world-class support for the discontinued products and they will follow the support policy of the above listed replacements products.

Lund, Sweden, December 17, 2018

Per Sten

Global Product Manager, Axis Communications