

B.3 EAC/AA Control Report

Metering System	From	To	Details
Run Time: 10/06/1997 13:48:53			
Organisation: An Electricity Company			
Estimated Annual Consumption/Annualised Advance Control Report			
User: OPSSUPER			
Input File : EEVC0103.dat			
Output File: DSEC53			
1	01/01/1997	10/01/1997	No DPC for GSP G2 PC 1 SSC SSC1 TP TPR02 Sett Date 01/01/1997
1	01/01/1997	10/01/1997	No DPC for GSP G2 PC 1 SSC SSC1 TP TPR03 Sett Date 01/01/1997
2	01/01/1997	11/01/1997	No DPC values for Sett Date 11/01/1997
3	01/01/1997	10/01/1997	Negative EAC -4346655923.5 for TP TPR01 Negative EAC -4346655923.5 for TP TPR01
3	01/01/1997	10/01/1997	Negative AA -11515214.8 for TP TPR01
3	01/01/1997	10/01/1997	Negative Meter Advance -6789012.3 for TP TPR01
3	01/01/1997	10/01/1997	Negative DPC -0.0521753037605 for GSP G5 PC 1 SSC SSC1 TP TPR02 Sett 01/01/1997
3	01/01/1997	10/01/1997	Negative EAC -17286087132.0 replaced by 5678.9 for TP TPR02 Negative EAC -17286087132.0 for TP TPR02
3	01/01/1997	10/01/1997	Negative AA -19574053.1 for TP TPR02
3	01/01/1997	10/01/1997	Negative Meter Advance -8901234.5 for TP TPR02
3	01/01/1997	10/01/1997	Negative EAC -22712729382.1 replaced by 15678.9 for TP TPR03 Negative EAC -22712729382.1 for TP TPR03
3	01/01/1997	10/01/1997	Negative AA -226317.3 for TP TPR03
3	01/01/1997	10/01/1997	Negative Meter Advance -123456.7 for TP TPR03
3	01/01/1997	10/01/1997	Negative DPC -0.0521075489287 for GSP G5 PC 1 SSC SSC1 TP TPR04 Sett 01/01/1997
3	01/01/1997	10/01/1997	Negative EAC -45062203624.3 replaced by 65678.9 for TP TPR04 egative EAC -45062203624.3 for TP TPR04
3	01/01/1997	10/01/1997	Negative AA -6015808.6 for TP TPR04
3	01/01/1997	10/01/1997	Negative Meter Advance -2345678.9 for TP TPR04
4	01/01/1997	10/01/1997	AA Exceeds Tolerance - MA 12345678, AA 123456, PC 01, SSC SSC1, TP TPR01, Tolerance 500000, -1000

Page: 1

Run Time: 10/06/1997 13:48:53		Organisation: An Electricity Company	
Estimated Annual Consumption/Annualised Advance Control Report			
Processing Details:			
No. of Metering Systems Read	:	4	
No. of Metering Systems Processed Successfully	:	2	
No. of Metering Systems Processed Unsuccessfully:	:	2	
<u>No. of MS for which a negative EAC was replaced :</u>	:	<u>1</u>	
End of Report			

Page: 2

B.4 EAC/AA Exception Report (Human-Readable)

Metering System	Reason Code	From	To	Details
1	NDP	01/01/1997	10/01/1997	No DPC for GSP G2 PC 1 SSC SSC1 TP TPR02 Sett Date 01/01/1997
1	NDP	01/01/1997	10/01/1997	No DPC for GSP G2 PC 1 SSC SSC1 TP TPR03 Sett Date 01/01/1997
2	NDD	01/01/1997	11/01/1997	No DPC values for Sett Date 11/01/1997
3	NDD	01/01/1997	10/01/1997	Negative EAC -4346655923.5 replaced by 45678.9 for TP TPR01
3	NDD	01/01/1997	10/01/1997	Negative EAC -17286087132.0 replaced by 5678.9 for TP TPR02
3	NDD	01/01/1997	10/01/1997	Negative EAC -22712729382.1 replaced by 15678.9 for TP TPR03
3	NDD	01/01/1997	10/01/1997	Negative EAC -45062203624.3 replaced by 65678.9 for TP TPR04

No. of Metering Systems Processed Unsuccessfully: 2

Page: 1

B.10 Load Standard Settlement Configuration Exception Report

Run Time: 12/06/1997 12:02:19

Organisation: An Electricity Company

Load Standard Settlement Configuration Exception Report

User: EACAA

File Name: SSC1004319.dat

Settlement Date: 12/04/1997

Standard Settlement Configuration	Reason for Rejection
-----------------------------------	----------------------

28	SSC Description in database can't be changed, record: 12
<u>30</u>	<u>Record Rejected - Invalid AFYC -900, value found in record: 15</u>

Page: 1

Run Time: 12/06/1997 12:02:19

Organisation: An Electricity Company

Load Standard Settlement Configuration Exception Report

No. of Standard Settlement Configurations not loaded: ~~2~~

End of Report

Page: 2