

Replacement Fan Clutch Repair Kits for KYSOR® K26RA, K30RA and K32RA

Benefit from Horton's industry-leading customer service and quality, even if you are running its competitors' fan drives in your fleet.

- **Dual pilot for reduced inventory and complete application coverage**
- **Two-piece liner design for quick repairs**
- **Superior liner material for longer life and reliability**

Count on Horton to not only provide the reliable, durable products you need, but to deliver them on time



ENGINEERED FOR:





Rear-Air Fan Clutch

Horton # 9908504

Replaces #

1090-09650-01

1090-09750-01

8801X

8801N



Rear-Air Major Kit

Horton # 9908408

Replaces #

1033-40600-02

8800SKL



Rear-Air Seal Kit

Horton # 9908409

Replaces #

1033-08233-01

8500SK



Lining Kit

(fit's both rear-air and front-air fan clutches)

Horton # 9908407

Replaces #

1033-40600-01

8800L



Hub Bearing Kits

Horton # 9908300

Replaces #

1033-07781-01

8581-01

Horton # 9908301

Replaces #

1033-07782-01

8582-01

Horton # 9908302

Replaces #

1033-07782-02

8582-02

Horton # 9908303

Replaces #

1033-07782-03

8582-03

Horton # 9908304

Replaces #

1033-07782-04

8582-04

Visit catalog.hortonww.com

to view full list of part number cross references!

Committed to Your Ideal Airflow Solution

Horton® is the premium provider of engine cooling solutions worldwide. Our culture of innovation delivers high-performance products that last and services that help you meet your commitments. Trust Horton to help your products last longer, run quieter and consume less fuel.

Horton is IATF 16949, ISO 14001 and ISO 9001 certified.