







SCALE: -



TOO TIGHT

TOO LOOSE



ASSEMBLY GUIDELINE: T-MAX DRINKER

PART NR.:

DATE: 07-29-11

REVISION: 2

GL1073