

Inspection Carried Out By: Hessle Plant Ltd

Carrwood Road Castleford West Yorkshire WF10 4PT Tel: 01977 550557 E-Mail: mail@hessle.co.uk Web Site: www.hessle.co.uk

Conducted in accordance with CFTS Publication GN28, Regulation 9 of the 'Lifting Operations and Lifting Equipment Regulations 1998' and the 'Provision and Use of Work Equipment Regulations 1998'

Site: NORTH WEST MEWPS LTD

C/O WATES CONSTRUCTION GATE 1

INTERNATIONAL DRIVE

EAST BOLDON SUNDERLAND SR5 3FH

Regular Thorough Examination

Equip No:	16779	Inspect No:	8969	
Make/Model:	SKYJACK / 8841 - 07	Job No:	125612	
Serial No:	40001121	Contact:		
Last Inspection:		Inspected:	10/10/2023	
Meter:		Printed:	11/10/2023	Page: 1 of 1

Items to Inspect	Result	Comments
RTE		
Reason For RTE?	Within 6 Month Interval	
Safe Working Load	Yes (Detail)	680kg
Date Of Manufacture	Yes (Detail)	Unknown
Is this the first examination after installation or assembly at new site/ location?	No	
If Yes to above, has the equipment been installed correctly?	Not Applicable	
A Defects	None	
Timescale For A Defect Repairs	Not Applicable	
B Defects	None	
Timescale For B Defect Repairs	Not Applicable	
C Observations	None	
Timesclae For Observation Repairs	Not Applicable	
Particulars of any tests carried out as part of examination	No	
I hereby declare that the equipment described in this report was thoroughly examined in accordance with GN28	No Faults Have Been Detected	
Is Machine Safe to use?	Yes	
Date Of Next Inspection	Yes (Detail)	10/04/2024

DECLARATION BY COMPETENT PERSON

I hereby declare that the equipment described in this report was thoroughly examined in accordance with GN28

Engineer Name: Stephen Brown

Customer Name: Customer Not Present

Signature:



Signature

Name and address of Company responsible for this Thorough Examination Hessle Fork Trucks - Head Office, Carrwood Road, Castleford, WF10 4PT