

Analysis of Response to Emergency Steam Report

Month: April-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
202207152	MS22000640	04-XST-0077	PARK AVE E 63 ST	WM	04/02/2022	09:15	09:19	09:31	16:00	16-30	Yes
202207156	MS22000641	09-XST-0341	SEVENTH AVE SOUTH GROVE ST	SK	04/02/2022	16:50	16:52	17:11	21:00	16-30	Yes
202207168	MS22000642	09-XST-0234	SEVENTH AVE SOUTH W 10 ST	C2	04/02/2022	21:48	21:49	22:00	12:00	0-15	Yes
202207264	MS22000652	13-SVC-2010	SERVICE - 2010 AT 88-92 TRINITY PLACE	D1	04/04/2022	14:40	14:45	15:00	20:00	16-30	Yes
202207288	MS22000658	07-MH-8811	MANHOLE - 8811: 345 33 ST W/O FIRST AVE	ECS	04/05/2022	06:16	06:25	06:36	20:00	16-30	Yes
202207302	MS22000660	04-ST-0072	E 56 ST BTW FIRST AVE & YORK AVE	SK	04/05/2022	10:17	10:28	10:45	28:00	16-30	Yes
202207307	MS22000661	02-MH-15085	MANHOLE - 15085: 123 75 ST W/O LEXINGTON AVE	SK	04/05/2022	10:40	10:50	11:32	52:00	46-60	Yes
202207315	MS22000665	03-XST-0058	FIFTH AVE E 73 ST	SK	04/05/2022	17:49	17:52	18:00	11:00	0-15	Yes
202207424	MS22000676	12-SV2-1101	SV2BOX - 1101: 31 DUANE ST	M	04/07/2022	08:03	08:10	08:37	34:00	31-45	Yes
202207463	MS22000685	06-ST-0064	E 36 ST BTW THIRD AVE & SECOND AVE	CR	04/07/2022	18:33	18:36	18:50	17:00	16-30	Yes
202207468	MS22000686	04-ST-0297	W 56 ST BTW NINTH AVE & EIGHTH AVE	ECS	04/07/2022	19:51	19:55	20:27	36:00	31-45	Yes
202207469	MS22000687	07-ST-0096	E 33 ST BTW PARK AVE & LEXINGTON AVE	ECS	04/07/2022	23:19	23:20	23:21	02:00	0-15	Yes
202207510	MS22000689	07-ST-0097	E 33 ST BTW SECOND AVE & FIRST AVE	ECS	04/08/2022	09:43	09:55	10:15	32:00	31-45	Yes
202207515	MS22000698	06-SVC-970	SERVICE - 970 AT 274 MADISON AVE	SK	04/08/2022	12:54	13:03	13:30	36:00	31-45	Yes

Analysis of Response to Emergency Steam Report

Month: April-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
202207544	MS22000707	07-ST-0097	E 33 ST BTW SECOND AVE & FIRST AVE	ECS	04/09/2022	08:11	08:15	08:41	30:00	16-30	Yes
202207684	MS22000711	09-XST-0089	GROVE ST W 4 ST	WM	04/11/2022	11:43	11:49	12:30	47:00	46-60	Yes
202207743	MS22000716	05-ST-0356	W 53 ST BTW SIXTH AVE & FIFTH AVE	ECS	04/12/2022	09:10	09:13	09:50	40:00	31-45	Yes
202207757	MS22000722	08-XST-0041	GRAMERCY PARK SOUTH GRAMERCY PARK WEST	PP	04/12/2022	13:00	13:03	13:22	22:00	16-30	Yes
202207758	MS22000723	08-SVC-3759	SERVICE - 3759 AT 240 S PARK AVE	L	04/12/2022	14:08	14:10	14:17	09:00	0-15	Yes
202207818	MS22000727	07-ST-0097	E 33 ST BTW SECOND AVE & FIRST AVE	ECS	04/13/2022	07:35	07:45	08:22	47:00	46-60	Yes
202207833	MS22000731	04-MH-6561	MANHOLE - 6561: 130 58 ST W/O LEXINGTON AVE	N	04/13/2022	10:39	10:48	10:57	18:00	16-30	Yes
202207914	MS22000741	11-ST-0068	CHERRY ST BTW RUTGERS ST & CLINTON ST	N	04/14/2022	10:43	10:45	10:57	14:00	0-15	Yes
202207925	MS22000747	02-ST-0232	PARK AVE BTW E 75 ST & E 76 ST	ECS	04/14/2022	16:03	16:07	16:19	16:00	16-30	Yes
202207927	MS22000749	08-ST-0050	E 14 ST BTW AVE B & AVE C	SK	04/14/2022	16:56	16:58	17:21	25:00	16-30	Yes
202207939	MS22000750	05-MH-8775	MANHOLE - 8775: 217 51 ST E/O EIGHTH AVE	L	04/14/2022	19:29	19:31	20:00	31:00	31-45	Yes
202207971	MS22000752	04-MH-15005	MANHOLE - 15005: WEST END AVE N/O 62 ST	FM	04/15/2022	08:22	08:30	08:48	26:00	16-30	Yes
17710533	17710533	08-ST-0329	SEVENTH AVE BTW W 14 ST & W 15 ST	ER	04/24/2022	09:44	09:46	10:05	21:00	16-30	Yes

No. of Records: 27



Consolidated Edison Company
of New York, Inc.
750 East 16th Street
New York NY 10009
www.conEd.com

June 17, 2022

Mr. Kevin Speicher
Chief, Gas & Petroleum Safety
Office of Electric, Gas & Water
New York State Dept. of Public Service
Three Empire State Plaza
Albany, NY 12223

Mr. Speicher,

Pursuant to section 420.12 (f) of the Public Service Commission's regulations, Consolidated Edison Company of New York, Inc. ("Con Edison" or "the Company") hereby submits the attached Unscheduled Interruption of Service Report. There were no unscheduled interruptions for the month of May 2022.

In addition, pursuant to section 420.13 (c) of the Commission's regulations, the Company hereby submits the attached Analysis of Response to Emergency Steam Reports for the month of May 2022. The Company responded to ninety five percent of emergency calls within 60 minutes.

Sincerely,

06/17/2022

Theresa Kong
General Manager
Steam Distribution

PV/File

Attachments



Analysis of Response to Emergency Steam Report

Month: May-2022

Emergency Calls

	Weekdays During Normal Business Hours		Weekdays After Business Hours		Weekends		Total		Leak or Vapor Complaints	
									Current Month	
Response Time*(Minut	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls
0-15	6	40%			2	66.67%	8	38.1%	7	35%
16-30	4	26.67%	1	33.33%			5	23.81%	5	25%
31-45	3	20%	1	33.33%	1	33.33%	5	23.81%	5	25%
46-60	1	6.67%	1	33.33%			2	9.52%	2	10%
>60	1	6.67%					1	4.76%	1	5%
Totals	15	100	3	100	3	100	21	100	20	100

* Total elapsed time from receipt of report to time of arrival.

 06/17/22

Signature of General Manager



Analysis of Response to Emergency Steam Report

Month: May-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
17720806	17720806	08-MH-7671	MANHOLE - 7671: 244 15 ST W/O SECOND AVE	ER	05/01/2022	00:15	00:30	00:53	38:00	31-45	Yes
17732362	17732362	10-ST-0107	GRAND ST BTW BOWERY & CHRYSTIE ST	ER	05/04/2022	13:30	13:30	14:00	30:00	16-30	Yes
17733520	17733520	08-ST-0085	E 20 ST BTW GRAMERCY PARK EAST & THIRD AVE	ER	05/05/2022	10:15	10:15	10:30	15:00	0-15	Yes
17734522	17734522	07-ST-0097	E 33 ST BTW SECOND AVE & FIRST AVE	ER	05/06/2022	09:30	09:30	10:00	30:00	16-30	Yes
17734684	17734684	03-ST-0230	PARK AVE BTW E 70 ST & E 71 ST	ER	05/06/2022	14:15	14:15	14:30	15:00	0-15	Yes
17735237	17735237	07-MH-6435	MANHOLE - 6435: 95 MADISON AVE S/O 29 ST	ER	05/06/2022	15:00	15:00	15:30	30:00	16-30	Yes
17740754	17740754	04-MH-15405	MANHOLE - 15405: 446 W 58 ST E/O TENTH AVE	ER	05/09/2022	11:45	11:50	12:17	32:00	31-45	Yes
17741682	17741682	05-ST-0265	W 45 ST BTW EIGHTH AVE & SEVENTH AVE	ER	05/10/2022	18:00	18:15	19:00	60:00	46-60	Yes
17744783	17744783	12-ST-0078	READE ST BTW CHURCH ST & REPUBLICAN ALLEY	ER	05/13/2022	08:15	08:15	09:00	45:00	31-45	Yes
17744800	17744800	12-SVC-187	SERVICE - 187 AT 150-52 DUANE ST	ER	05/13/2022	09:15	09:15	09:30	15:00	0-15	Yes
17744901	17744901	03-ST-0229	PARK AVE BTW E 69 ST & E 70 ST	ER	05/13/2022	11:00	11:15	11:15	15:00	0-15	Yes
17744952	17744952	11-ST-0132	HENRY ST BTW CATHERINE ST & MARKET ST	ER	05/13/2022	11:45	11:45	12:15	30:00	16-30	Yes
17745257	17745257	12-XST-0043	CHERRY ST PIKE ST	SK	05/13/2022	17:00	17:00	17:30	30:00	16-30	Yes
17745293	17745293	03-ST-0229	PARK AVE BTW E 69 ST & E 70 ST	SK	05/13/2022	19:11	19:15	19:55	44:00	31-45	Yes



Analysis of Response to Emergency Steam Report

Month: May-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
17751387	17751387	03-ST-0109	E 69 ST BTW FIRST AVE & YORK AVE	ER	05/16/2022	08:30	08:30	09:15	45:00	31-45	Yes
17751412	17751412	10-MH-5670	MANHOLE - 5670: COLUMBIA ST AND DELANCEY ST	P	05/16/2022	09:00	09:00	09:15	15:00	0-15	Yes
17751388	17751388	03-ST-0141	E 71 ST BTW THIRD AVE & SECOND AVE	ER	05/16/2022	09:00	09:00	09:15	15:00	0-15	Yes
17751427	17751427	12-ST-0078	READE ST BTW CHURCH ST & REPUBLICAN ALLEY	ER	05/16/2022	09:30	09:30	10:30	60:00	46-60	Yes
17753807	17753807	14-XST-0067	WASHINGTON ST RECTOR ST	ER	05/17/2022	12:15	12:30	13:30	75:00	>60	Yes
17773458	17773458	06-ST-0183	MADISON AVE BTW E 40 ST & E 41 ST	WM	05/28/2022	05:55	05:58	06:02	07:00	0-15	No
17775455	17775455	02-ST-0115	E 76 ST BTW MADISON AVE & PARK AVE	ER	05/28/2022	23:05	23:09	23:15	10:00	0-15	Yes

No. of Records: 21



Consolidated Edison Company
of New York, Inc.
750 East 16th Street
New York NY 10009
www.conEd.com

July 15, 2022

Mr. Kevin Speicher
Chief, Gas & Petroleum Safety
Office of Electric, Gas & Water
New York State Dept. of Public Service
Three Empire State Plaza
Albany, NY 12223

Mr. Speicher,

Pursuant to section 420.12 (f) of the Public Service Commission's regulations, Consolidated Edison Company of New York, Inc. ("Con Edison" or "the Company") hereby submits the attached Unscheduled Interruption of Service Report. There were no unscheduled interruptions for the month of June 2022.

In addition, pursuant to section 420.13 (c) of the Commission's regulations, the Company hereby submits the attached Analysis of Response to Emergency Steam Reports for the month of June 2022. The Company responded to 91.67 percent of emergency calls within 60 minutes.

Sincerely,

Theresa Kong
General Manager
Steam Distribution

PV/File

Attachments



Analysis of Response to Emergency Steam Report

Month: June-2022

Emergency Calls

	Weekdays During Normal Business Hours		Weekdays After Business Hours		Weekends		Total		Leak or Vapor Complaints	
									Current Month	
Response Time*(Minut	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls
0-15	1	6.67%	1	20%			2	7.69%	2	8.33%
16-30	7	46.67%	3	60%	4	66.67%	14	53.85%	13	54.17%
31-45	5	33.33%	1	20%	1	16.67%	7	26.92%	7	29.17%
46-60					1	16.67%	1	3.85%		
>60	2	13.33%					2	7.69%	2	8.33%
Totals	15	100	5	100	6	100	26	100	24	100

* Total elapsed time from receipt of report to time of arrival.


Signature of General Manager



Analysis of Response to Emergency Steam Report

Month: June-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
17783776		04-XST-0077	PARK AVE E 63 ST	ER	06/01/2022	07:59	08:02	08:25	26:00	16-30	Yes
17783933		04-SV2-2068	SV2BOX - 2068: 940 THIRD AVE. N/O 56 ST.	ER	06/01/2022	10:22	10:35	11:04	42:00	31-45	Yes
17791947		07-ST-0276	W 31 ST BTW TENTH AVE & NINTH AVE	ER	06/03/2022	09:09	09:14	09:40	31:00	31-45	Yes
17792060		05-ST-0040	BROADWAY BTW W 50 ST & W 51 ST	ER	06/03/2022	10:43	11:15	12:00	76:00	>60	Yes
17800039		02-SVC-2079	SERVICE - 2079 AT 35 E 75 ST	ER	06/06/2022	23:28	23:39	23:54	26:00	16-30	Yes
17802796		04-ST-0231	PARK AVE BTW E 63 ST & E 64 ST	ER	06/09/2022	08:30	08:30	09:15	45:00	31-45	Yes
17804367		02-ST-0146	E 79 ST BTW THIRD AVE & SECOND AVE	SK	06/10/2022	09:15	09:15	09:30	15:00	0-15	Yes
17804527		07-ST-0285	W 33 ST BTW SEVENTH AVE & SIXTH AVE	SK	06/10/2022	13:45	01:45	14:15	30:00	16-30	Yes
17865870		10-ST-0246	COLUMBIA ST BTW GRAND ST & BROOME ST	ER	06/12/2022	07:56	08:04	08:20	24:00	16-30	Yes
17865872		04-ST-0231	PARK AVE BTW E 63 ST & E 64 ST	ER	06/12/2022	08:36	08:45	09:10	34:00	31-45	Yes
17865943		03-ST-0097	E 67 ST BTW SECOND AVE & FIRST AVE	ER	06/12/2022	17:04	17:10	17:32	28:00	16-30	Yes
17867862		12-XST-0135	CHURCH ST PARK PL	SK	06/14/2022	16:26	16:30	16:52	26:00	16-30	No
17870439		10-ST-0132	HUDSON ST BTW SPRING ST & VANDAM ST	ER	06/16/2022	11:45	11:45	12:30	45:00	31-45	Yes
17874014		12-ST-0068	PARK PL BTW CHURCH ST & BROADWAY	ER	06/18/2022	08:15	08:15	09:10	55:00	46-60	No
17874032		07-XST-0060	LEXINGTON AVE E 34 ST	ER	06/18/2022	11:12	11:15	11:30	18:00	16-30	Yes



Analysis of Response to Emergency Steam Report

Month: June-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
17874057		06-ST-0098	E 39 ST BTW LEXINGTON AVE & THIRD AVE	ER	06/18/2022	14:30	14:30	15:00	30:00	16-30	Yes
17876609		05-TMH-8445	TRAP MANHOLE- 8445: MADISON AVE S/O 49 ST	ER	06/20/2022	07:15	07:30	08:00	45:00	31-45	Yes
17877623		05-MH-6116	MANHOLE - 6116: 538 LEXINGTON AVE N/O 49 ST	ER	06/21/2022	01:34	01:40	01:50	16:00	16-30	Yes
17877748		04-ST-0309	W 57 ST BTW SIXTH AVE & FIFTH AVE	ER	06/21/2022	08:30	08:30	09:00	30:00	16-30	Yes
17877784		07-ST-0090	E 32 ST BTW MADISON AVE & PARK AVE	ER	06/21/2022	09:45	10:00	10:15	30:00	16-30	Yes
17877807		03-ST-0144	E 72 ST BTW FIFTH AVE & MADISON AVE	ER	06/21/2022	10:13	10:15	11:15	62:00	>60	Yes
17877801		06-ST-0098	E 39 ST BTW LEXINGTON AVE & THIRD AVE	ER	06/21/2022	10:15	10:15	10:45	30:00	16-30	Yes
17877869		10-MH-10541	MANHOLE - 10541: HENRY ST W/O MONTGOMERY ST	ER	06/21/2022	12:30	13:45	13:00	30:00	16-30	Yes
17877946		06-ST-0098	E 39 ST BTW LEXINGTON AVE & THIRD AVE	ER	06/21/2022	14:15	14:15	14:45	30:00	16-30	Yes
17877977		04-SVC-196	SERVICE - 196 AT 116-20 E 56 ST	ER	06/21/2022	17:00	17:00	17:15	15:00	0-15	Yes
17892237		03-ST-0102	E 68 ST BTW LEXINGTON AVE & THIRD AVE	ER	06/30/2022	00:01	00:08	00:32	31:00	31-45	Yes

No. of Records: 26



Consolidated Edison Company
of New York, Inc.
750 East 16th Street
New York NY 10009
www.conEd.com

August 15, 2022

Mr. Kevin Speicher
Chief, Gas & Petroleum Safety
Office of Electric, Gas & Water
New York State Dept. of Public Service
Three Empire State Plaza
Albany, NY 12223

Mr. Speicher,

Pursuant to section 420.12 (f) of the Public Service Commission's regulations, Consolidated Edison Company of New York, Inc. ("Con Edison" or "the Company") hereby submits the attached Unscheduled Interruption of Service Report. There were no unscheduled interruptions for the month of July 2022.

In addition, pursuant to section 420.13 (c) of the Commission's regulations, the Company hereby submits the attached Analysis of Response to Emergency Steam Reports for the month of July 2022. The Company responded to 100 percent of emergency calls within 60 minutes.

Sincerely,

Theresa Kong
General Manager
Steam Distribution

PV/File

Attachments


Analysis of Response to Emergency Steam Report

Month: July-2022

Emergency Calls

Response Time*(Minut	Weekdays During Normal Business Hours		Weekdays After Business Hours		Weekends		Total		Leak or Vapor Complaints			
	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls	Current Month		Year To Date	
									# of calls	% of calls	# of calls	% of calls
0-15	3	10.34%					3	7.5%	3	7.69%	36	15.06%
16-30	9	31.03%	8	88.89%	1	50%	18	45%	18	46.15%	107	44.77%
31-45	16	55.17%	1	11.11%	1	50%	18	45%	17	43.59%	77	32.22%
46-60	1	3.45%					1	2.5%	1	2.56%	14	5.86%
>60											5	2.09%
Totals	29	100	9	100	2	100	40	100	39	100	239	100

* Total elapsed time from receipt of report to time of arrival.


Signature of General Manager



Analysis of Response to Emergency Steam Report

Month: July-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
17906150		05-ST-0096	E 49 ST BTW FIFTH AVE & MADISON AVE	ER	07/06/2022	10:18	10:24	10:50	32:00	31-45	Yes
17907184		04-ST-0074	E 56 ST BTW MADISON AVE & PARK AVE	ER	07/07/2022	11:08	11:11	11:25	17:00	16-30	Yes
17908566		03-ST-0111	E 69 ST BTW MADISON AVE & PARK AVE	ER	07/08/2022	10:53	10:58	11:15	22:00	16-30	Yes
17908662		04-ST-0133	E 61 ST BTW MADISON AVE & PARK AVE	ER	07/08/2022	17:04	17:05	17:21	17:00	16-30	Yes
17909811		13-ST-0058	WATER ST BTW FULTON ST & JOHN ST	ER	07/08/2022	22:30	22:30	23:00	30:00	16-30	Yes
17914147		09-ST-0502	VARICK ST BTW KING ST & W HOUSTON ST	ER	07/11/2022	16:22	16:27	17:03	41:00	31-45	Yes
17914196		10-MH-5426	MANHOLE - 5426: 384 CANAL ST AND WEST BROADWAY	ER	07/11/2022	17:02	17:04	17:25	23:00	16-30	Yes
17915358		10-ST-0051	GRAND ST BTW JACKSON ST & LEWIS ST	ER	07/12/2022	11:18	11:20	11:45	27:00	16-30	Yes
17916089		14-SVC-1979	SERVICE - 1979 AT 85 BROAD ST	ER	07/13/2022	07:52	07:52	07:55	03:00	0-15	Yes
17916161		13-ST-0071	VESEY ST BTW WEST ST & WEST BROADWAY	ER	07/13/2022	09:15	09:15	09:45	30:00	16-30	Yes
17916246		03-ST-0144	E 72 ST BTW FIFTH AVE & MADISON AVE	ER	07/13/2022	10:45	11:00	11:30	45:00	31-45	Yes
17916353		05-XST-0108	EIGHTH AVE W 51 ST	ER	07/13/2022	14:15	14:15	14:30	15:00	0-15	Yes
17916404		MVMH6781	35TH STREET W/ O FIRST AVE	ER	07/13/2022	17:15	17:15	17:45	30:00	16-30	Yes
17917536		01-96-84	DISTRICT 01 - 96 ST TO 84 ST	ER	07/14/2022	07:45	07:45	08:30	45:00	31-45	Yes



Analysis of Response to Emergency Steam Report

Month: July-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
17917682		14-SVC-2073	SERVICE - 2073 AT 95 WALL ST	ER	07/14/2022	11:00	11:00	11:45	45:00	31-45	Yes
17918824		03-ST-0147	E 72 ST BTW MADISON AVE & PARK AVE	ER	07/15/2022	08:30	08:30	09:00	30:00	16-30	Yes
17918925		13-ST-0055	WATER ST BTW BEEKMAN ST & FULTON ST	ER	07/15/2022	12:30	12:45	13:00	30:00	16-30	Yes
17924435		04-ST-0297	W 56 ST BTW NINTH AVE & EIGHTH AVE	ER	07/18/2022	12:16	12:20	13:10	54:00	46-60	Yes
17924707		13-XST-0040	GREENWICH ST LIBERTY ST	ER	07/18/2022	20:30	20:30	21:00	30:00	16-30	Yes
17925472		03-ST-0092	E 67 ST BTW FIFTH AVE & MADISON AVE	ER	07/19/2022	09:44	09:50	10:05	21:00	16-30	Yes
17925614		02-ST-0050	CENTRAL PARK WEST BTW W 82 ST & W 83 ST	ER	07/19/2022	12:34	12:35	13:05	31:00	31-45	No
17927748		03-ST-0092	E 67 ST BTW FIFTH AVE & MADISON AVE	ER	07/21/2022	08:15	08:15	09:00	45:00	31-45	Yes
17934567		12-ST-0077	READE ST BTW CENTRE ST & CHURCH ST	ER	07/25/2022	10:45	11:00	11:30	45:00	31-45	Yes
17934602		08-ST-0206	W 15 ST BTW SEVENTH AVE & SIXTH AVE	ER	07/25/2022	12:00	12:00	12:45	45:00	31-45	Yes
17934601		08-ST-0206	W 15 ST BTW SEVENTH AVE & SIXTH AVE	ER	07/25/2022	12:00	12:00	12:45	45:00	31-45	Yes
17935954		04-SV2-TW57S58	SV2BOX - TW57S58: 57TH ST. E/O 6TH AVENUE	ER	07/26/2022	13:45	14:00	14:25	40:00	31-45	Yes
17936300		04-XST-0187	PARK AVE E 58 ST	ER	07/26/2022	22:55	23:03	23:20	25:00	16-30	Yes
17936301		05-XST-0186	FIFTH AVE E 53 ST	ER	07/27/2022	00:33	00:40	00:58	25:00	16-30	Yes

8/4/22 3:14 PM



Analysis of Response to Emergency Steam Report

Month: July-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
17936706		06-ST-0297	W 37 ST BTW SEVENTH AVE & BROADWAY	ER	07/27/2022	08:05	08:11	08:44	39:00	31-45	Yes
17936898		08-ST-0292	W 22 ST BTW SEVENTH AVE & SIXTH AVE	ER	07/27/2022	11:24	11:27	11:57	33:00	31-45	Yes
17936916		08-ST-0109	E 22 ST BTW THIRD AVE & SECOND AVE	ER	07/27/2022	11:42	11:47	11:56	14:00	0-15	Yes
17937060		07-ST-0300	SEVENTH AVE BTW W 24 ST & W 25 ST	ER	07/27/2022	12:31	12:47	13:02	31:00	31-45	Yes
17938156		02-MH-15346	MANHOLE - 15346: 225 CPW S/O 83 ST	ER	07/28/2022	11:28	11:30	11:44	16:00	16-30	Yes
17938260		05-ST-0138	LEXINGTON AVE BTW E 47 ST & E 48 ST	ER	07/28/2022	15:21	15:25	15:51	30:00	16-30	Yes
17938779		08-XST-0131	SEVENTH AVE W 16 ST	ER	07/29/2022	03:42	03:45	04:00	18:00	16-30	Yes
17939074		08-ST-0065	E 15 ST BTW SECOND AVE & NATHAN D PERLMAN PL	ER	07/29/2022	09:34	09:37	10:05	31:00	31-45	Yes
17939112		07-ST-0300	SEVENTH AVE BTW W 24 ST & W 25 ST	ER	07/29/2022	11:59	12:04	12:36	37:00	31-45	Yes
17939143		04-SVC-3676	SERVICE: SVC-3676 345 E 59 ST	ER	07/29/2022	13:17	13:25	13:48	31:00	31-45	Yes
17944804		10-ST-0107	GRAND ST BTW BOWERY & CHRYSTIE ST	ER	07/31/2022	17:34	17:38	17:54	20:00	16-30	Yes
17945097		04-XST-0030	SIXTH AVE W 59 ST	ER	07/31/2022	21:24	21:25	22:00	36:00	31-45	Yes

No. of Records: 40

8/4/22 3:14 PM

4 / 4



Consolidated Edison Company
of New York, Inc.
750 East 16th Street
New York NY 10009
www.conEd.com

September 15, 2022

Mr. Kevin Speicher
Chief, Gas & Petroleum Safety
Office of Electric, Gas & Water
New York State Dept. of Public Service
Three Empire State Plaza
Albany, NY 12223

Mr. Speicher,

Pursuant to section 420.12 (f) of the Public Service Commission's regulations, Consolidated Edison Company of New York, Inc. ("Con Edison" or "the Company") hereby submits the attached Unscheduled Interruption of Service Report. There were no unscheduled interruptions for the month of August 2022.

In addition, pursuant to section 420.13 (c) of the Commission's regulations, the Company hereby submits the attached Analysis of Response to Emergency Steam Reports for the month of August 2022. The Company responded to 97.5 percent of emergency calls within 60 minutes.

Sincerely,



Theresa Kong
General Manager
Steam Distribution

PV/File

Attachments



Analysis of Response to Emergency Steam Report

Month: August-2022

Emergency Calls

	Weekdays During Normal Business Hours		Weekdays After Business Hours		Weekends		Total		Leak or Vapor Complaints	
									Current Month	
Response Time*(Minut	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls
0-15	5	17.86%	2	15.38%	2	40%	9	19.57%	9	22.5%
16-30	10	35.71%	8	61.54%	3	60%	21	45.65%	17	42.5%
31-45	11	39.29%	3	23.08%			14	30.43%	12	30%
46-60	1	3.57%					1	2.17%	1	2.5%
>60	1	3.57%					1	2.17%	1	2.5%
Totals	28	100	13	100	5	100	46	100	40	100

* Total elapsed time from receipt of report to time of arrival.

Signature of General Manager



Analysis of Response to Emergency Steam Report

Month: August-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
17945857		01-ST-1285	W 94 ST BTW COLUMBUS AVE & CENTRAL PARK WEST	SK	08/01/2022	18:36	18:37	19:00	24:00	16-30	No
17947034		05-ST-0365	W 54 ST BTW SIXTH AVE & FIFTH AVE	ER	08/02/2022	12:56	13:05	13:50	54:00	46-60	Yes
17953177		06-ST-0035	BROADWAY BTW W 36 ST & W 37 ST	ER	08/03/2022	09:55	09:57	10:18	23:00	16-30	Yes
17953217		12-ST-0071	PARK ROW BTW BEEKMAN ST & ANN ST	ER	08/03/2022	11:47	11:49	12:14	27:00	16-30	No
17954567		05-ST-0138	LEXINGTON AVE BTW E 47 ST & E 48 ST	ER	08/04/2022	07:47	07:51	08:30	43:00	31-45	Yes
17956009		10-MH-10540	MANHOLE - 10540: 360 CANAL ST W/O CHURCH ST	ER	08/05/2022	17:54	17:55	18:08	14:00	0-15	Yes
17956979		09-TMH-5472	TRAP MANHOLE- 5472: VARICK ST N/O CARMINE ST	ER	08/06/2022	18:41	18:42	19:09	28:00	16-30	Yes
17959853		08-XST-0051	SEVENTH AVE W 23 ST	ER	08/07/2022	23:38	23:40	00:03	25:00	16-30	Yes
17960144		04-ST-0214	W 62 ST BTW BROADWAY & CENTRAL PARK WEST	ER	08/08/2022	11:58	12:01	12:22	24:00	16-30	Yes
17960245		03-XST-0110	YORK AVE E 70 ST	ER	08/08/2022	14:03	14:07	14:38	35:00	31-45	Yes
17960253		08-ST-0176	FIFTH AVE BTW E 20 ST & W 21 ST	ER	08/08/2022	15:20	15:25	15:59	39:00	31-45	Yes
17960948		06-MH-8301	MANHOLE - 8301: 1369 BROADWAY S/O 37 ST	ER	08/09/2022	10:21	10:26	10:50	29:00	16-30	Yes
17962047		05-MH-15360	MANHOLE - 15360: 500 LEXINGTON AVE N/O 47 ST	ER	08/10/2022	08:30	08:44	09:12	42:00	31-45	No



Analysis of Response to Emergency Steam Report

Month: August-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
17962199		06-MH-15510	MANHOLE - 15510: FIRST AVE S/O 38 ST	ER	08/10/2022	14:14	14:15	14:25	11:00	0-15	Yes
17963085		12-XST-0091	BARCLAY ST CHURCH ST	ER	08/11/2022	10:49	10:53	11:05	16:00	16-30	Yes
17963182		13-MH-5173	MANHOLE - 5173: 26 PLATT ST W/O GOLD ST	ER	08/11/2022	13:09	13:12	13:25	16:00	16-30	No
17964122		03-ST-0147	E 72 ST BTW MADISON AVE & PARK AVE	ER	08/12/2022	12:15	12:20	12:55	40:00	31-45	Yes
17964232		07-ST-0300	SEVENTH AVE BTW W 24 ST & W 25 ST	ER	08/12/2022	17:33	17:35	17:55	22:00	16-30	Yes
17964985		02-ST-0003	AMSTERDAM AVE BTW W 76 ST & W 77 ST	ER	08/12/2022	21:30	21:30	21:45	15:00	0-15	Yes
17965125		03-SVC	SERVICE	ER	08/12/2022	23:30	23:30	00:15	45:00	31-45	Yes
17965128		13-SV2-TCHSFLS	SV2BOX - TCHSFLS: S/INT. CHURCH & FULTON STS.	ER	08/13/2022	02:00	02:00	02:15	15:00	0-15	Yes
17965254		07-XST-0133	NINTH AVE W 33 ST	ER	08/13/2022	20:00	20:00	20:15	15:00	0-15	Yes
17968145		06-SVC-638	SERVICE: SVC-638 1-3 E 42 ST	SFS	08/15/2022	01:11	01:15	01:35	24:00	16-30	Yes
17968225		12-XST-0091	BARCLAY ST CHURCH ST	ER	08/15/2022	07:12	07:17	07:54	42:00	31-45	Yes
17968399		10-ST-0045	GRAND ST BTW ELIZABETH ST & BOWERY	ER	08/15/2022	14:36	14:39	14:51	15:00	0-15	Yes
17968506		03-ST-0095	E 67 ST BTW MADISON AVE & PARK AVE	ER	08/15/2022	19:50	19:55	20:20	30:00	16-30	No
17968636		03-ST-0109	E 69 ST BTW FIRST AVE & YORK AVE	ER	08/16/2022	08:32	08:37	09:05	33:00	31-45	Yes
17968669		03-ST-0153	E 73 ST BTW FIFTH AVE & MADISON AVE	ER	08/16/2022	09:47	09:49	10:27	40:00	31-45	Yes



Analysis of Response to Emergency Steam Report

Month: August-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
17968707		04-ST-0319	SIXTH AVE BTW W 58 ST & CENTRAL PARK SOUTH	ER	08/16/2022	10:27	10:28	10:47	20:00	16-30	Yes
17968909		09-ST-0507	W 13 ST BTW SIXTH AVE & FIFTH AVE	ER	08/16/2022	16:35	16:38	17:14	39:00	31-45	Yes
17968916		04-ST-0248	THIRD AVE BTW E 62 ST & E 63 ST	ER	08/16/2022	17:08	17:09	17:33	25:00	16-30	Yes
17968953		07-ST-0009	FIRST AVE BTW E 24 ST & E 25 ST	ER	08/16/2022	18:30	18:30	18:55	25:00	16-30	Yes
17971231		04-ST-0308	W 57 ST BTW SEVENTH AVE & SIXTH AVE	ER	08/17/2022	17:45	17:45	18:17	32:00	31-45	No
17971243		09-XST-0511	SIXTH AVE W 13 ST	ER	08/17/2022	18:57	19:00	19:24	27:00	16-30	Yes
17977031		04-ST-0221	W 64 ST BTW COLUMBUS AVE & BROADWAY	ER	08/21/2022	10:55	11:01	11:12	17:00	16-30	Yes
17978134		03-ST-0153	E 73 ST BTW FIFTH AVE & MADISON AVE	ER	08/22/2022	09:22	09:24	09:50	28:00	16-30	Yes
17978135		06-ST-0375	SIXTH AVE BTW W 43 ST & W 44 ST	ER	08/22/2022	09:25	09:29	09:50	25:00	16-30	Yes
17978211		05-ST-0365	W 54 ST BTW SIXTH AVE & FIFTH AVE	ER	08/22/2022	11:11	11:11	11:45	34:00	31-45	Yes
17978233		07-ST-0274	W 31 ST BTW SEVENTH AVE & SIXTH AVE	ER	08/22/2022	12:28	12:29	12:42	14:00	0-15	Yes
17978234		14-ST-0073	RECTOR ST BTW WEST ST & WASHINGTON ST	ER	08/22/2022	12:35	12:35	12:38	03:00	0-15	Yes
17978316		04-ST-0308	W 57 ST BTW SEVENTH AVE & SIXTH AVE	ER	08/22/2022	16:03	16:09	16:29	26:00	16-30	Yes
17979227		07-ST-0287	W 33 ST BTW TENTH AVE & NINTH AVE	ER	08/23/2022	08:32	09:00	09:08	36:00	31-45	Yes

**Analysis of Response to Emergency Steam Report**

Month: August-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
17980233		02-ST-0231	PARK AVE BTW E 74 ST & E 75 ST	ER	08/24/2022	11:17	11:24	11:45	28:00	16-30	Yes
17989392		03-MH-16053	MANHOLE - 16053: 68 ST E/O FIFTH AVE	ER	08/31/2022	07:30	07:37	08:46	76:00	>60	Yes
17989394		03-ST-0103	E 68 ST BTW MADISON AVE & PARK AVE	ER	08/31/2022	07:37	07:48	08:13	36:00	31-45	Yes
17989553		06-ST-0345	W 43 ST BTW SIXTH AVE & FIFTH AVE	ER	08/31/2022	14:26	14:27	14:28	02:00	0-15	Yes

No. of Records: 46



Analysis of Response to Emergency Steam Report

Month: August-2022

Emergency Calls

	Weekdays During Normal Business Hours		Weekdays After Business Hours		Weekends		Total		Leak or Vapor Complaints	
									Current Month	
Response Time*(Minut	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls
0-15	5	17.86%	2	15.38%	2	40%	9	19.57%	9	22.5%
16-30	10	35.71%	8	61.54%	3	60%	21	45.65%	17	42.5%
31-45	11	39.29%	3	23.08%			14	30.43%	12	30%
46-60	1	3.57%					1	2.17%	1	2.5%
>60	1	3.57%					1	2.17%	1	2.5%
Totals	28	100	13	100	5	100	46	100	40	100

* Total elapsed time from receipt of report to time of arrival.

Signature of General Manager



Analysis of Response to Emergency Steam Report

Month: August-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
17945857		01-ST-1285	W 94 ST BTW COLUMBUS AVE & CENTRAL PARK WEST	SK	08/01/2022	18:36	18:37	19:00	24:00	16-30	No
17947034		05-ST-0365	W 54 ST BTW SIXTH AVE & FIFTH AVE	ER	08/02/2022	12:56	13:05	13:50	54:00	46-60	Yes
17953177		06-ST-0035	BROADWAY BTW W 36 ST & W 37 ST	ER	08/03/2022	09:55	09:57	10:18	23:00	16-30	Yes
17953217		12-ST-0071	PARK ROW BTW BEEKMAN ST & ANN ST	ER	08/03/2022	11:47	11:49	12:14	27:00	16-30	No
17954567		05-ST-0138	LEXINGTON AVE BTW E 47 ST & E 48 ST	ER	08/04/2022	07:47	07:51	08:30	43:00	31-45	Yes
17956009		10-MH-10540	MANHOLE - 10540: 360 CANAL ST W/O CHURCH ST	ER	08/05/2022	17:54	17:55	18:08	14:00	0-15	Yes
17956979		09-TMH-5472	TRAP MANHOLE- 5472: VARICK ST N/O CARMINE ST	ER	08/06/2022	18:41	18:42	19:09	28:00	16-30	Yes
17959853		08-XST-0051	SEVENTH AVE W 23 ST	ER	08/07/2022	23:38	23:40	00:03	25:00	16-30	Yes
17960144		04-ST-0214	W 62 ST BTW BROADWAY & CENTRAL PARK WEST	ER	08/08/2022	11:58	12:01	12:22	24:00	16-30	Yes
17960245		03-XST-0110	YORK AVE E 70 ST	ER	08/08/2022	14:03	14:07	14:38	35:00	31-45	Yes
17960253		08-ST-0176	FIFTH AVE BTW E 20 ST & W 21 ST	ER	08/08/2022	15:20	15:25	15:59	39:00	31-45	Yes
17960948		06-MH-8301	MANHOLE - 8301: 1369 BROADWAY S/O 37 ST	ER	08/09/2022	10:21	10:26	10:50	29:00	16-30	Yes
17962047		05-MH-15360	MANHOLE - 15360: 500 LEXINGTON AVE N/O 47 ST	ER	08/10/2022	08:30	08:44	09:12	42:00	31-45	No



Analysis of Response to Emergency Steam Report

Month: August-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
17962199		06-MH-15510	MANHOLE - 15510: FIRST AVE S/O 38 ST	ER	08/10/2022	14:14	14:15	14:25	11:00	0-15	Yes
17963085		12-XST-0091	BARCLAY ST CHURCH ST	ER	08/11/2022	10:49	10:53	11:05	16:00	16-30	Yes
17963182		13-MH-5173	MANHOLE - 5173: 26 PLATT ST W/O GOLD ST	ER	08/11/2022	13:09	13:12	13:25	16:00	16-30	No
17964122		03-ST-0147	E 72 ST BTW MADISON AVE & PARK AVE	ER	08/12/2022	12:15	12:20	12:55	40:00	31-45	Yes
17964232		07-ST-0300	SEVENTH AVE BTW W 24 ST & W 25 ST	ER	08/12/2022	17:33	17:35	17:55	22:00	16-30	Yes
17964985		02-ST-0003	AMSTERDAM AVE BTW W 76 ST & W 77 ST	ER	08/12/2022	21:30	21:30	21:45	15:00	0-15	Yes
17965125		03-SVC	SERVICE	ER	08/12/2022	23:30	23:30	00:15	45:00	31-45	Yes
17965128		13-SV2-TCHSFLS	SV2BOX - TCHSFLS: S/INT. CHURCH & FULTON STS.	ER	08/13/2022	02:00	02:00	02:15	15:00	0-15	Yes
17965254		07-XST-0133	NINTH AVE W 33 ST	ER	08/13/2022	20:00	20:00	20:15	15:00	0-15	Yes
17968145		06-SVC-638	SERVICE: SVC-638 1-3 E 42 ST	SFS	08/15/2022	01:11	01:15	01:35	24:00	16-30	Yes
17968225		12-XST-0091	BARCLAY ST CHURCH ST	ER	08/15/2022	07:12	07:17	07:54	42:00	31-45	Yes
17968399		10-ST-0045	GRAND ST BTW ELIZABETH ST & BOWERY	ER	08/15/2022	14:36	14:39	14:51	15:00	0-15	Yes
17968506		03-ST-0095	E 67 ST BTW MADISON AVE & PARK AVE	ER	08/15/2022	19:50	19:55	20:20	30:00	16-30	No
17968636		03-ST-0109	E 69 ST BTW FIRST AVE & YORK AVE	ER	08/16/2022	08:32	08:37	09:05	33:00	31-45	Yes
17968669		03-ST-0153	E 73 ST BTW FIFTH AVE & MADISON AVE	ER	08/16/2022	09:47	09:49	10:27	40:00	31-45	Yes



Analysis of Response to Emergency Steam Report

Month: August-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
17968707		04-ST-0319	SIXTH AVE BTW W 58 ST & CENTRAL PARK SOUTH	ER	08/16/2022	10:27	10:28	10:47	20:00	16-30	Yes
17968909		09-ST-0507	W 13 ST BTW SIXTH AVE & FIFTH AVE	ER	08/16/2022	16:35	16:38	17:14	39:00	31-45	Yes
17968916		04-ST-0248	THIRD AVE BTW E 62 ST & E 63 ST	ER	08/16/2022	17:08	17:09	17:33	25:00	16-30	Yes
17968953		07-ST-0009	FIRST AVE BTW E 24 ST & E 25 ST	ER	08/16/2022	18:30	18:30	18:55	25:00	16-30	Yes
17971231		04-ST-0308	W 57 ST BTW SEVENTH AVE & SIXTH AVE	ER	08/17/2022	17:45	17:45	18:17	32:00	31-45	No
17971243		09-XST-0511	SIXTH AVE W 13 ST	ER	08/17/2022	18:57	19:00	19:24	27:00	16-30	Yes
17977031		04-ST-0221	W 64 ST BTW COLUMBUS AVE & BROADWAY	ER	08/21/2022	10:55	11:01	11:12	17:00	16-30	Yes
17978134		03-ST-0153	E 73 ST BTW FIFTH AVE & MADISON AVE	ER	08/22/2022	09:22	09:24	09:50	28:00	16-30	Yes
17978135		06-ST-0375	SIXTH AVE BTW W 43 ST & W 44 ST	ER	08/22/2022	09:25	09:29	09:50	25:00	16-30	Yes
17978211		05-ST-0365	W 54 ST BTW SIXTH AVE & FIFTH AVE	ER	08/22/2022	11:11	11:11	11:45	34:00	31-45	Yes
17978233		07-ST-0274	W 31 ST BTW SEVENTH AVE & SIXTH AVE	ER	08/22/2022	12:28	12:29	12:42	14:00	0-15	Yes
17978234		14-ST-0073	RECTOR ST BTW WEST ST & WASHINGTON ST	ER	08/22/2022	12:35	12:35	12:38	03:00	0-15	Yes
17978316		04-ST-0308	W 57 ST BTW SEVENTH AVE & SIXTH AVE	ER	08/22/2022	16:03	16:09	16:29	26:00	16-30	Yes
17979227		07-ST-0287	W 33 ST BTW TENTH AVE & NINTH AVE	ER	08/23/2022	08:32	09:00	09:08	36:00	31-45	Yes

**Analysis of Response to Emergency Steam Report**

Month: August-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
17980233		02-ST-0231	PARK AVE BTW E 74 ST & E 75 ST	ER	08/24/2022	11:17	11:24	11:45	28:00	16-30	Yes
17989392		03-MH-16053	MANHOLE - 16053: 68 ST E/O FIFTH AVE	ER	08/31/2022	07:30	07:37	08:46	76:00	>60	Yes
17989394		03-ST-0103	E 68 ST BTW MADISON AVE & PARK AVE	ER	08/31/2022	07:37	07:48	08:13	36:00	31-45	Yes
17989553		06-ST-0345	W 43 ST BTW SIXTH AVE & FIFTH AVE	ER	08/31/2022	14:26	14:27	14:28	02:00	0-15	Yes

No. of Records: 46



Consolidated Edison Company
of New York, Inc.
750 East 16th Street
New York NY 10009
www.conEd.com

October 14, 2022

Mr. Kevin Speicher
Chief, Gas & Petroleum Safety
Office of Electric, Gas & Water
New York State Dept. of Public Service
Three Empire State Plaza
Albany, NY 12223

Mr. Speicher,

Pursuant to section 420.12 (f) of the Public Service Commission's regulations, Consolidated Edison Company of New York, Inc. ("Con Edison" or "the Company") hereby submits the attached Unscheduled Interruption of Service Report. There were no unscheduled interruptions for the month of September 2022.

In addition, pursuant to section 420.13 (c) of the Commission's regulations, the Company hereby submits the attached Analysis of Response to Emergency Steam Reports for the month of September 2022. The Company responded to 97.01 percent of emergency calls within 60 minutes.

Sincerely,

Theresa Kong
General Manager
Steam Distribution

PV/File

Attachments

Analysis of Response to Emergency Steam Report

Month: September-2022

Emergency Calls

	Weekdays During Normal Business Hours		Weekdays After Business Hours		Weekends		Total		Leak or Vapor Complaints	
									Current Month	
Response Time*(Minut	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls
0-15	5	11.63%	3	20%	2	16.67%	10	14.29%	10	14.93%
16-30	16	37.21%	9	60%	4	33.33%	29	41.43%	26	38.81%
31-45	18	41.86%	3	20%	5	41.67%	26	37.14%	26	38.81%
46-60	2	4.65%			1	8.33%	3	4.29%	3	4.48%
>60	2	4.65%					2	2.86%	2	2.99%
Totals	43	100	15	100	12	100	70	100	67	100

* Total elapsed time from receipt of report to time of arrival.

 10/14/2022
Signature of General Manager

Analysis of Response to Emergency Steam Report

Month: September-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
17990576		06-ST-0354	W 44 ST BTW SIXTH AVE & FIFTH AVE	ER	09/01/2022	16:00	16:06	16:33	33:00	31-45	Yes
17991054		07-XST-0075	FIFTH AVE E 33 ST	ER	09/01/2022	21:58	22:02	22:25	27:00	16-30	Yes
17991206		14-XST-0046	GREENWICH ST MORRIS ST	ER	09/02/2022	09:12	09:17	09:52	40:00	31-45	Yes
17991252		14-ST-0078	WHITEHALL ST BTW BRIDGE ST & PEARL ST	ER	09/02/2022	11:25	11:30	11:44	19:00	16-30	Yes
17998103		03-ST-0147	E 72 ST BTW MADISON AVE & PARK AVE	ER	09/03/2022	10:00	10:10	10:17	17:00	16-30	No
17999140		09-ST-0060	BARUCH DR BTW DELANCEY ST & E HOUSTON ST	ER	09/03/2022	23:36	23:38	00:11	35:00	31-45	Yes
18000968		05-SV2-3082	SV2BOX - 3082: 226-36 WEST 46 ST. E/O 8 AVE.	ER	09/04/2022	09:10	09:15	10:00	50:00	46-60	Yes
18000967		01-ST-0814	COLUMBUS AVE BTW W 86 ST & W 87 ST	ER	09/04/2022	11:15	11:20	11:30	15:00	0-15	Yes
18001642		02-ST-0235	PARK AVE BTW E 78 ST & E 79 ST	ER	09/05/2022	13:20	13:22	14:20	60:00	46-60	Yes
18001654		08-ST-0131	IRVING PL BTW E 17 ST & E 18 ST	ER	09/05/2022	18:33	18:39	19:00	27:00	16-30	Yes
18002129		04-XST-0188	COLUMBUS AVE W 59 ST	SK	09/06/2022	09:25	09:28	09:58	33:00	31-45	Yes
18002119		06-ST-0098	E 39 ST BTW LEXINGTON AVE & THIRD AVE	ER	09/06/2022	09:29	09:33	09:48	19:00	16-30	Yes
18002180		07-ST-0229	W 27 ST BTW EIGHTH AVE & SEVENTH AVE	ER	09/06/2022	12:13	12:20	12:41	28:00	16-30	Yes
18002261		06-ST-0375	SIXTH AVE BTW W 43 ST & W 44 ST	ER	09/06/2022	14:15	14:20	14:50	35:00	31-45	Yes
18002503		03-ST-0147	E 72 ST BTW MADISON AVE & PARK AVE	ER	09/07/2022	09:32	09:36	10:14	42:00	31-45	Yes

Analysis of Response to Emergency Steam Report

Month: September-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
18002633		13-SVC-229	SERVICE - 229 AT 120 BROADWAY	ER	09/07/2022	12:15	12:17	12:57	42:00	31-45	Yes
18002710		09-ST-0108	E 9 ST BTW FOURTH AVE & THIRD AVE	ER	09/07/2022	15:00	15:02	15:15	15:00	0-15	Yes
18002718		04-ST-0125	E 60 ST BTW PARK AVE & LEXINGTON AVE	ER	09/07/2022	15:26	15:43	16:29	63:00	>60	Yes
18003807		03-ST-0119	MADISON AVE BTW E 68 ST & E 69 ST	ER	09/08/2022	12:48	13:34	13:50	62:00	>60	Yes
18004008		03-ST-0091	E 66 ST BTW THIRD AVE & SECOND AVE	ER	09/08/2022	20:27	20:31	20:50	23:00	16-30	Yes
18005016		13-ST-0056	WATER ST BTW DOVER ST & PECK SLIP	ER	09/09/2022	16:29	16:33	17:02	33:00	31-45	Yes
18006874		08-SVC-3058	SERVICE - 3058 AT 447-55 E 14 ST	ER	09/11/2022	00:01	00:07	00:41	40:00	31-45	Yes
18008626		08-ST-0049	E 14 ST BTW AVE A & AVE B	ER	09/11/2022	17:55	17:58	18:02	07:00	0-15	Yes
18009169		04-MH-15432	MANHOLE - 15432: 63 ST I/S LEXINGTON AVE	ER	09/11/2022	22:52	22:57	23:15	23:00	16-30	Yes
18009561		10-MH-10541	MANHOLE - 10541: HENRY ST W/O MONTGOMERY ST	ER	09/12/2022	12:42	12:44	13:07	25:00	16-30	Yes
18009555		04-ST-0225	PARK AVE BTW E 57 ST & E 58 ST	ER	09/12/2022	12:46	12:52	13:08	22:00	16-30	Yes
18010048		13-ST-0011	GREENWICH ST BTW RECTOR ST & LIBERTY ST	ER	09/13/2022	07:48	07:51	08:15	27:00	16-30	Yes
18010957		03-MH-15932	MANHOLE - 15932: 72 ST W/O MADISON AVE	ER	09/14/2022	07:15	07:20	07:55	40:00	31-45	Yes
18012053		03-ST-0119	MADISON AVE BTW E 68 ST & E 69 ST	ER	09/15/2022	11:13	11:18	11:45	32:00	31-45	Yes

Analysis of Response to Emergency Steam Report

Month: September-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
18012803		13-XST-0095	NASSAU ST CEDAR ST	SK	09/16/2022	02:00	02:00	02:30	30:00	16-30	Yes
18012980		06-ST-0157	LEXINGTON AVE BTW E 43 ST & E 44 ST	ER	09/16/2022	08:36	08:42	09:18	42:00	31-45	Yes
18013190		05-ST-0285	W 47 ST BTW EIGHTH AVE & BROADWAY	ER	09/16/2022	13:49	13:56	14:33	44:00	31-45	Yes
18013214		04-ST-0308	W 57 ST BTW SEVENTH AVE & SIXTH AVE	ER	09/16/2022	15:35	15:38	15:50	15:00	0-15	Yes
18014961		09-XST-0515	COLUMBIA ST E HOUSTON ST	ER	09/17/2022	18:14	18:14	18:36	22:00	16-30	Yes
18017850		07-XST-0133	NINTH AVE W 33 ST	ER	09/18/2022	21:28	21:35	21:45	17:00	16-30	Yes
18018006		07-ST-0090	E 32 ST BTW MADISON AVE & PARK AVE	ER	09/19/2022	09:05	09:11	09:50	45:00	31-45	Yes
18018077		05-ST-0185	FIFTH AVE BTW E 45 ST & E 46 ST	ER	09/19/2022	10:52	10:55	11:03	11:00	0-15	Yes
18018868		08-ST-0087	E 20 ST BTW THIRD AVE & SECOND AVE	ER	09/20/2022	12:11	12:16	12:41	30:00	16-30	Yes
18018903		12-XST-0130	JAMES ST MADISON ST	ER	09/20/2022	13:02	13:06	13:40	38:00	31-45	Yes
18018932		01-XST-0470	FIRST AVE E 86 ST	ER	09/20/2022	14:01	14:04	14:38	37:00	31-45	Yes
18019968		11-ST-0074	CHURCH ST BTW WHITE ST & WALKER ST	SK	09/21/2022	13:45	14:00	14:15	30:00	16-30	Yes
18021272		01-ST-0817	COLUMBUS AVE BTW W 89 ST & W 90 ST	SK	09/22/2022	05:15	05:20	05:40	25:00	16-30	Yes
18021648		07-SVC-330	SERVICE - 330 AT 130-32 W 34 ST	ER	09/23/2022	02:42	02:50	03:08	26:00	16-30	Yes
18021833		06-ST-0374	SIXTH AVE BTW W 42 ST & W 43 ST	ER	09/23/2022	09:45	10:00	10:15	30:00	16-30	Yes

Analysis of Response to Emergency Steam Report

Month: September-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
18021878		07-ST-0090	E 32 ST BTW MADISON AVE & PARK AVE	ER	09/23/2022	10:45	11:00	11:15	30:00	16-30	Yes
18021912		03-ST-0080	E 65 ST BTW LEXINGTON AVE & THIRD AVE	ER	09/23/2022	12:00	12:00	12:30	30:00	16-30	Yes
18021947		04-ST-0227	PARK AVE BTW E 59 ST & E 60 ST	ER	09/23/2022	13:00	13:15	13:45	45:00	31-45	Yes
18021968		05-ST-0188	FIFTH AVE BTW E 48 ST & W 49 ST	ER	09/23/2022	14:15	14:30	15:00	45:00	31-45	Yes
18022093		05-XST-0068	SECOND AVE E 52 ST	ER	09/23/2022	17:00	17:00	17:15	15:00	0-15	Yes
18022124		08-SV2-TE15S353	SV2BOX - TE15S353: 15 ST. W/O FIRST AVE.	ER	09/23/2022	18:36	18:46	18:59	23:00	16-30	Yes

Analysis of Response to Emergency Steam Report

Month: September-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
18023310		08-ST-0299	W 23 ST BTW NINTH AVE & EIGHTH AVE	ER	09/24/2022	09:44	09:47	10:16	32:00	31-45	Yes
18023331		04-XST-0121	SECOND AVE E 58 ST	ER	09/24/2022	12:38	12:45	13:19	41:00	31-45	Yes
18027115		14-ST-0015	BROAD ST BTW WILLIAM ST & STONE ST	ER	09/25/2022	12:51	12:53	13:30	39:00	31-45	Yes
18028067		10-MH-10541	MANHOLE - 10541: HENRY ST W/O MONTGOMERY ST	ER	09/26/2022	10:46	11:00	11:15	29:00	16-30	Yes
18028102		05-ST-0075	E 48 ST BTW LEXINGTON AVE & THIRD AVE	ER	09/26/2022	12:06	12:15	12:21	15:00	0-15	Yes
18028235		04-ST-0226	PARK AVE BTW E 58 ST & E 59 ST	ER	09/26/2022	14:13	14:15	14:20	07:00	0-15	Yes
18028962		07-ST-0263	W 31 ST BTW NINTH AVE & EIGHTH AVE	ER	09/27/2022	07:14	07:25	07:50	36:00	31-45	Yes
18028993		03-ST-0113	E 69 ST BTW SECOND AVE & FIRST AVE	ER	09/27/2022	08:48	09:00	09:40	52:00	46-60	Yes
18030220		07-ST-0300	SEVENTH AVE BTW W 24 ST & W 25 ST	ER	09/28/2022	08:21	08:25	08:44	23:00	16-30	Yes
18030417		03-ST-0132	E 70 ST BTW THIRD AVE & SECOND AVE	ER	09/28/2022	12:06	12:10	12:30	24:00	16-30	Yes
18031416		04-SVC-3835	SERVICE - 3835 AT 740 MADISON AVE	SFS	09/28/2022	23:36	23:42	23:50	14:00	0-15	Yes
18031646		03-ST-0150	E 72 ST BTW THIRD AVE & SECOND AVE	ER	09/29/2022	11:54	11:58	12:05	11:00	0-15	Yes
18031692		04-MH-15917	MANHOLE - 15917: FIFTH AVE N/O 61 ST	ER	09/29/2022	13:45	13:50	14:30	45:00	31-45	Yes
18033073		06-ST-0274	SECOND AVE BTW E 42 ST & E 43 ST	ER	09/30/2022	05:10	05:13	05:30	20:00	16-30	Yes

10/3/22 10:25 AM

6 / 7

Analysis of Response to Emergency Steam Report

Month: September-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
18033125		04-ST-0099	E 58 ST BTW SECOND AVE & APPR TO QUEENSBORO BRIDGE	ER	09/30/2022	08:02	08:06	08:33	31:00	31-45	Yes
18033202		07-ST-0024	NINTH AVE BTW W 30 ST & W 31 ST	ER	09/30/2022	08:39	08:45	09:02	23:00	16-30	Yes
18033214		09-TMH-8256	TRAP MANHOLE- 8256: 12 WEST 13 ST W/O FIFTH AVE	ER	09/30/2022	09:16	09:20	09:40	24:00	16-30	No
18033445		14-XST-0031	BROAD ST SOUTH ST	ER	09/30/2022	12:45	12:51	13:18	33:00	31-45	Yes
18033561		04-ST-0170	E 64 ST BTW MADISON AVE & PARK AVE	ER	09/30/2022	15:32	15:35	16:10	38:00	31-45	Yes
18033600		03-ST-0127	E 70 ST BTW FIRST AVE & YORK AVE	ER	09/30/2022	18:56	19:00	19:13	17:00	16-30	No

No. of Records: 70



Consolidated Edison Company
of New York, Inc.
750 East 16th Street
New York NY 10009
www.conEd.com

November 15, 2022

Mr. Kevin Speicher
Chief, Gas & Petroleum Safety
Office of Electric, Gas & Water
New York State Dept. of Public Service
Three Empire State Plaza
Albany, NY 12223

Mr. Speicher,

Pursuant to section 420.12 (f) of the Public Service Commission's regulations, Consolidated Edison Company of New York, Inc. ("Con Edison" or "the Company") hereby submits the attached Unscheduled Interruption of Service Report. There was one unscheduled interruption affecting one customer for the month of October 2022.

In addition, pursuant to section 420.13 (c) of the Commission's regulations, the Company hereby submits the attached Analysis of Response to Emergency Steam Reports for the month of October 2022. The Company responded to 100 percent of emergency calls within 60 minutes.

Sincerely,

Theresa Kong
General Manager
Steam Distribution

PV/File

Attachments

Consolidated Edison Company of New York, Inc.

Steam Distribution

SERVICE INTERRUPTION REPORT

District: Manhattan
 Month: October 2022

From: 10/01/2022 – 10/31/2022

Date	Time Received	Dispatch Time	Arrival Time	Time Off	Time On	Duration HR / Min.		Location	Number of Customers Affected	Cause of Interruption
10/02/2022	10:09	10:12	10:15	10:30	10:50	0	20	1 Liberty Plaza	1	Equipment Failure

Theresa Kong,


 General Manager / Steam Distribution

11/15/2022


Analysis of Response to Emergency Steam Report

Month: October-2022

Emergency Calls

	Weekdays During Normal Business Hours		Weekdays After Business Hours		Weekends		Total		Leak or Vapor Complaints	
									Current Month	
Response Time*(Minut	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls
0-15	5	15.15%	1	5.56%	2	22.22%	8	13.33%	8	13.79%
16-30	21	63.64%	9	50%	6	66.67%	36	60%	34	58.62%
31-45	7	21.21%	8	44.44%	1	11.11%	16	26.67%	16	27.59%
46-60										
>60										
Totals	33	100	18	100	9	100	60	100	58	100

* Total elapsed time from receipt of report to time of arrival.


Signature of General Manager

Analysis of Response to Emergency Steam Report

Month: October-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
18034648		03-ST-0127	E 70 ST BTW FIRST AVE & YORK AVE	ER	10/01/2022	07:45	07:45	08:00	15:00	0-15	Yes
18034805		05-ST-0275	W 46 ST BTW EIGHTH AVE & BROADWAY	ER	10/01/2022	13:30	13:30	14:00	30:00	16-30	Yes
18034811		05-ST-0265	W 45 ST BTW EIGHTH AVE & SEVENTH AVE	ER	10/01/2022	15:00	15:00	15:30	30:00	16-30	Yes
18043576		06-ST-0048	E 35 ST BTW MADISON AVE & PARK AVE	ER	10/03/2022	08:30	08:30	08:45	15:00	0-15	Yes
18043672		03-ST-0150	E 72 ST BTW THIRD AVE & SECOND AVE	ER	10/03/2022	10:00	10:00	10:30	30:00	16-30	Yes
18044404		05-ST-0084	EIGHTH AVE BTW W 45 ST & W 44 ST	ER	10/04/2022	01:12	01:15	01:30	18:00	16-30	Yes
18046212		04-XST-0071	FIFTH AVE E 61 ST	ER	10/05/2022	06:15	06:21	07:00	45:00	31-45	Yes
18046318		05-ST-0265	W 45 ST BTW EIGHTH AVE & SEVENTH AVE	ER	10/05/2022	08:43	08:45	09:23	40:00	31-45	Yes
18047791		10-SVC-3791	SERVICE - 3791 AT HUDSON STREET	ER	10/05/2022	21:42	21:48	22:18	36:00	31-45	Yes
18047861		01-XST-0604	COLUMBUS AVE W 87 ST	SK	10/05/2022	23:25	23:30	23:48	23:00	16-30	Yes
18047897		11-ST-0131	HENRY ST BTW MARKET ST & FORSYTH ST	ER	10/06/2022	04:47	04:52	05:07	20:00	16-30	Yes
18048089		03-ST-0127	E 70 ST BTW FIRST AVE & YORK AVE	ER	10/06/2022	09:19	09:23	09:45	26:00	16-30	Yes
18048179		14-XST-0051	STONE ST BROAD ST	ER	10/06/2022	10:49	10:54	11:17	28:00	16-30	Yes
18048244		04-ST-0207	W 59 ST BTW AMSTERDAM AVE & COLUMBUS AVE	ER	10/06/2022	13:04	13:06	13:10	06:00	0-15	Yes

Analysis of Response to Emergency Steam Report

Month: October-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
18048279		01-ST-2071	SEVENTH AVE BTW W 150 ST & W 151 ST	ER	10/06/2022	14:30	14:34	15:13	43:00	31-45	Yes
18048352		08-ST-0300	W 23 ST BTW SEVENTH AVE & SIXTH AVE	ER	10/06/2022	17:20	17:22	17:37	17:00	16-30	Yes
18048354		09-ST-0302	E 6 ST BTW AVE C & AVE D	ER	10/06/2022	17:41	17:44	18:04	23:00	16-30	Yes
18049386		03-XST-0021	THIRD AVE E 70 ST	ER	10/07/2022	10:58	11:03	11:22	24:00	16-30	Yes
18049588		02-MH-15805	MANHOLE - 15805: 79 ST W/ O PARK AVE	ER	10/07/2022	17:12	17:19	17:44	32:00	31-45	Yes
18052980		03-MH-7248	MANHOLE - 7248: 212 72 ST E/O THIRD AVE	ER	10/09/2022	17:42	17:46	17:50	08:00	0-15	Yes
18054170		03-XST-0110	YORK AVE E 70 ST	ER	10/10/2022	15:03	15:06	15:25	22:00	16-30	No
18054362		06-XST-0157	SECOND AVE E 42 ST	ER	10/10/2022	20:47	20:52	21:15	28:00	16-30	Yes
18054726		03-ST-0131	E 70 ST BTW SECOND AVE & FIRST AVE	ER	10/11/2022	13:00	13:15	13:27	27:00	16-30	Yes
18054800		04-XST-0074	PARK AVE E 60 ST	SK	10/11/2022	15:26	15:40	15:54	28:00	16-30	Yes
18055682		03-ST-0150	E 72 ST BTW THIRD AVE & SECOND AVE	ER	10/12/2022	08:54	08:55	09:03	09:00	0-15	Yes
18055769		13-SVC-229	SERVICE - 229 AT 120 BROADWAY	ER	10/12/2022	11:39	11:42	12:07	28:00	16-30	Yes
18055876		03-ST-0168	E 74 ST BTW THIRD AVE & SECOND AVE	ER	10/12/2022	14:37	14:39	14:49	12:00	0-15	Yes
18055961		02-ST-0047	CENTRAL PARK WEST BTW W 76 ST & W 77 ST	ER	10/12/2022	17:11	17:14	17:50	39:00	31-45	Yes
18056212		12-XST-0005	ELK ST DUANE ST	ER	10/13/2022	11:30	11:32	12:01	31:00	31-45	Yes
18057947		03-XST-0110	YORK AVE E 70 ST	ER	10/14/2022	05:46	05:50	06:20	34:00	31-45	Yes

11/2/22 9:53 AM

3 / 6

Analysis of Response to Emergency Steam Report

Month: October-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
18058001		02-ST-0048	CENTRAL PARK WEST BTW W 77 ST & W 81 ST	ER	10/14/2022	08:13	08:15	08:52	39:00	31-45	Yes
18058013		04-ST-0304	W 57 ST BTW ELEVENTH AVE & TENTH AVE	ER	10/14/2022	09:15	09:18	09:36	21:00	16-30	Yes
18060368		04-SVC-196	SERVICE - 196 AT 116-20 E 56 ST	ER	10/15/2022	17:10	17:16	17:28	18:00	16-30	Yes
18063859		06-SVC	SERVICE	ER	10/17/2022	07:00	07:08	07:41	41:00	31-45	Yes
18063940		13-SV2-960	SV2BOX - 960: 27 CLIFF ST	ER	10/17/2022	11:10	11:12	11:29	19:00	16-30	Yes
18064147		08-ST-0241	THIRD AVE BTW E 19 ST & E 20 ST	ER	10/17/2022	18:15	18:18	18:39	24:00	16-30	Yes
18064808		02-ST-0235	PARK AVE BTW E 78 ST & E 79 ST	ER	10/18/2022	11:33	11:36	12:15	42:00	31-45	Yes
18064956		07-ST-0039	E 26 ST BTW FIRST AVE & EAST RIVER DR	ER	10/18/2022	15:35	15:38	16:15	40:00	31-45	Yes
18064996		04-XST-0074	PARK AVE E 60 ST	ER	10/18/2022	17:50	18:00	18:22	32:00	31-45	Yes
18065864		08-ST-0299	W 23 ST BTW NINTH AVE & EIGHTH AVE	ER	10/19/2022	08:23	08:25	08:50	27:00	16-30	No
18065918		05-ST-0041	BROADWAY BTW W 51 ST & W 52 ST	ER	10/19/2022	11:24	11:35	11:45	21:00	16-30	Yes
18065963		02-ST-0048	CENTRAL PARK WEST BTW W 77 ST & W 81 ST	ER	10/19/2022	12:33	12:45	12:50	17:00	16-30	Yes
18066024		02-XST-0031	SECOND AVE E 75 ST	ER	10/19/2022	15:29	15:39	15:50	21:00	16-30	Yes
18066048		04-MH-7381	MANHOLE - 7381: FIRST AVE N/O 59 ST	ER	10/19/2022	17:21	17:24	17:40	19:00	16-30	Yes
18068356		04-ST-0215	W 62 ST BTW COLUMBUS AVE & BROADWAY	ER	10/21/2022	12:12	12:20	12:29	17:00	16-30	Yes
18068523		08-ST-0266	W 19 ST BTW TENTH AVE & NINTH AVE	ER	10/21/2022	19:34	19:40	19:50	16:00	16-30	Yes

Analysis of Response to Emergency Steam Report

Month: October-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
18069814		12-XST-0091	BARCLAY ST CHURCH ST	ER	10/22/2022	08:04	08:07	08:40	36:00	31-45	Yes
18072310		03-ST-0258	YORK AVE BTW E 73 ST & E 74 ST	ER	10/23/2022	10:09	10:11	10:27	18:00	16-30	Yes
18072329		08-ST-0169	MADISON AVE BTW E 23 ST & E 24 ST	ER	10/23/2022	12:08	12:11	12:35	27:00	16-30	Yes
18072925		05-ST-0265	W 45 ST BTW EIGHTH AVE & SEVENTH AVE	ER	10/24/2022	11:30	11:33	11:49	19:00	16-30	Yes

Analysis of Response to Emergency Steam Report

Month: October-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
18073365		05-XST-0154	FIFTH AVE W 51 ST	ER	10/25/2022	04:25	04:28	04:33	08:00	0-15	Yes
18073424		04-ST-0133	E 61 ST BTW MADISON AVE & PARK AVE	ER	10/25/2022	07:45	07:46	08:30	45:00	31-45	Yes
18073460		08-ST-0177	FIFTH AVE BTW E 21 ST & W 22 ST	ER	10/25/2022	09:28	09:30	09:41	13:00	0-15	Yes
18073465		06-ST-0224	PARK AVE BTW E 37 ST & E 38 ST	ER	10/25/2022	09:42	09:44	10:04	22:00	16-30	Yes
18073618		13-ST-0030	JOHN ST BTW WILLIAM ST & DUTCH ST	ER	10/25/2022	13:56	14:02	14:26	30:00	16-30	Yes
18074173		05-ST-0069	E 47 ST BTW PARK AVE & LEXINGTON AVE	ER	10/26/2022	00:59	01:05	01:40	41:00	31-45	Yes
18077886		05-ST-0339	W 51 ST BTW TENTH AVE & NINTH AVE	ER	10/29/2022	12:14	12:15	12:32	17:00	16-30	Yes
18081698		04-ST-0074	E 56 ST BTW MADISON AVE & PARK AVE	ER	10/31/2022	09:22	09:30	09:50	28:00	16-30	Yes
18081829		02-ST-0108	E 75 ST BTW SECOND AVE & FIRST AVE	ER	10/31/2022	12:12	12:15	12:30	18:00	16-30	Yes
18081839		02-ST-0280	SECOND AVE BTW E 74 ST & E 75 ST	ER	10/31/2022	13:28	13:33	13:45	17:00	16-30	Yes

No. of Records: 60



Consolidated Edison Company
of New York, Inc.
750 East 16th Street
New York NY 10009
www.conEd.com

December 15, 2022

Mr. Kevin Speicher
Chief, Gas & Petroleum Safety
Office of Electric, Gas & Water
New York State Dept. of Public Service
Three Empire State Plaza
Albany, NY 12223

Mr. Speicher,

Pursuant to section 420.12 (f) of the Public Service Commission's regulations, Consolidated Edison Company of New York, Inc. ("Con Edison" or "the Company") hereby submits the attached Unscheduled Interruption of Service Report. There were no unscheduled interruptions for the month of November 2022.

In addition, pursuant to section 420.13 (c) of the Commission's regulations, the Company hereby submits the attached Analysis of Response to Emergency Steam Reports for the month of November 2022. The Company responded to 100 percent of emergency calls within 60 minutes.

Sincerely,



12/14/2022

Theresa Kong
General Manager
Steam Distribution

PV/File

Attachments

Analysis of Response to Emergency Steam Report

Month: November-2022

Emergency Calls

	Weekdays During Normal Business Hours		Weekdays After Business Hours		Weekends		Total		Leak or Vapor Complaints	
									Current Month	
Response Time*(Minut	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls
0-15	4	16%	2	22.22%	2	40%	8	20.51%	8	21.62%
16-30	9	36%	3	33.33%	3	60%	15	38.46%	14	37.84%
31-45	10	40%	4	44.44%			14	35.9%	13	35.14%
46-60	2	8%					2	5.13%	2	5.41%
>60										
Totals	25	100	9	100	5	100	39	100	37	100

* Total elapsed time from receipt of report to time of arrival.


 12/14/2022
 Signature of General Manager

Analysis of Response to Emergency Steam Report

Month: November-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
18082356		12-XST-0050	SPRUCE ST GOLD ST	ER	11/01/2022	10:55	11:00	11:30	35:00	31-45	Yes
18082441		04-ST-0308	W 57 ST BTW SEVENTH AVE & SIXTH AVE	ER	11/01/2022	13:18	13:25	13:30	12:00	0-15	Yes
18082466		04-SV2-TW57S200	SV2BOX - TW57S200: 57TH ST. W/O 7TH AVE	ER	11/01/2022	13:42	13:50	14:11	29:00	16-30	Yes
18082575		04-ST-0125	E 60 ST BTW PARK AVE & LEXINGTON AVE	ER	11/01/2022	18:08	18:12	18:18	10:00	0-15	Yes
18084280		14-ST-0084	NEW ST BTW BEAVER ST & EXCHANGE PL	ER	11/02/2022	17:50	17:52	18:15	25:00	16-30	Yes
18089971		12-XST-0103	ELK ST READE ST	ER	11/03/2022	09:08	09:12	09:30	22:00	16-30	Yes
18089982		04-ST-0302	W 57 ST BTW BROADWAY & SEVENTH AVE	ER	11/03/2022	10:04	10:10	10:42	38:00	31-45	Yes
18091588		05-SVC-972	SERVICE - 972 AT 277 PARK AVE	ER	11/04/2022	09:58	10:05	10:33	35:00	31-45	Yes
18091628		10-MH-16332	MANHOLE - 16332: GRAND ST W/O MULBERRY ST	ER	11/04/2022	11:44	23:50	12:21	37:00	31-45	Yes
18091801		10-ST-0264	DELANCEY ST NO BTW SHERIFF ST & COLUMBIA ST	ER	11/04/2022	17:13	17:25	17:43	30:00	16-30	Yes
18093491		08-ST-0029	FIRST AVE BTW E 16 ST & E 17 ST	ER	11/05/2022	21:31	21:32	21:45	14:00	0-15	Yes
18096148		02-ST-0261	YORK AVE BTW E 74 ST & E 75 ST	ER	11/07/2022	04:53	04:56	05:04	11:00	0-15	Yes
18098265		04-ST-0034	BROADWAY BTW W 61 ST & W 62 ST	ER	11/09/2022	12:05	12:07	12:27	22:00	16-30	Yes
18098349		06-ST-0122	E 41 ST BTW LEXINGTON AVE & THIRD AVE	ER	11/09/2022	14:57	15:00	15:15	18:00	16-30	Yes

Analysis of Response to Emergency Steam Report

Month: November-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
18098427		12-ST-0063	WEST BROADWAY BTW CHAMBERS ST & HUDSON ST	ER	11/09/2022	17:59	18:03	18:42	43:00	31-45	Yes
18099292		14-XST-0030	BROAD ST EXCHANGE PL	ER	11/10/2022	11:55	11:59	12:12	17:00	16-30	Yes
18100039		03-ST-0129	E 70 ST BTW MADISON AVE & PARK AVE	ER	11/11/2022	08:48	08:53	09:20	32:00	31-45	Yes
18100139		05-XST-0047	SEVENTH AVE W 49 ST	ER	11/11/2022	18:26	18:37	19:11	45:00	31-45	Yes
18101512		11-XST-0019	CENTRE ST HOGAN PL	ER	11/12/2022	13:37	13:42	13:55	18:00	16-30	No
18104359		13-ST-0034	CEDAR ST BTW TRINITY PL & BROADWAY	ER	11/14/2022	07:38	07:40	08:12	34:00	31-45	No
18104588		05-ST-0074	E 48 ST BTW FIFTH AVE & MADISON AVE	ER	11/14/2022	15:07	15:10	15:28	21:00	16-30	Yes
18105266		01-ST-0816	COLUMBUS AVE BTW W 88 ST & W 89 ST	ER	11/15/2022	09:09	09:13	10:00	51:00	46-60	Yes
18105303		05-ST-0157	E 54 ST BTW FIFTH AVE & MADISON AVE	ER	11/15/2022	10:34	10:36	11:06	32:00	31-45	Yes
18106123		06-ST-0156	LEXINGTON AVE BTW E 42 ST & E 43 ST	ER	11/16/2022	14:29	14:32	14:58	29:00	16-30	Yes
18106153		07-SVC-3843	SERVICE - 3843 AT 424-434 W 33 ST	ER	11/16/2022	14:49	14:52	15:04	15:00	0-15	Yes
18107377		12-SVC-1410	SERVICE - 1410 AT 43-51 CHAMBERS ST	ER	11/17/2022	11:52	11:52	12:15	23:00	16-30	Yes
18107511		07-ST-0025	NINTH AVE BTW W 31 ST & W 33 ST	ER	11/17/2022	15:59	16:02	16:38	39:00	31-45	Yes
18108583		05-ST-0131	E 53 ST BTW FIFTH AVE & MADISON AVE	ER	11/18/2022	15:25	15:29	16:08	43:00	31-45	Yes

Analysis of Response to Emergency Steam Report

Month: November-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
18110238		04-XST-0132	BROADWAY W 62 ST	ER	11/20/2022	03:26	03:30	03:49	23:00	16-30	Yes
18110311		10-XST-0146	VARICK ST CANAL ST	ER	11/20/2022	11:04	11:10	11:30	26:00	16-30	Yes
18113041		04-ST-0087	E 57 ST BTW PARK AVE & LEXINGTON AVE	ER	11/21/2022	11:10	11:12	11:54	44:00	31-45	Yes
18113073		04-ST-0308	W 57 ST BTW SEVENTH AVE & SIXTH AVE	ER	11/21/2022	11:52	11:55	12:00	08:00	0-15	Yes
18114804		04-XST-0112	E 55 ST PARK AVE	ER	11/22/2022	10:54	10:58	11:21	27:00	16-30	Yes
18115554		07-ST-0094	E 33 ST BTW LEXINGTON AVE & THIRD AVE	ER	11/23/2022	12:32	12:40	13:06	34:00	31-45	Yes
18116089		05-ST-0331	W 51 ST BTW EIGHTH AVE & BROADWAY	ER	11/24/2022	11:06	11:15	12:00	54:00	46-60	Yes
18116120		07-ST-0266	SECOND AVE BTW E 26 ST & E 27 ST	ER	11/24/2022	14:48	14:55	15:00	12:00	0-15	Yes
18116132		01-XST-0605	COLUMBUS AVE W 88 ST	ER	11/24/2022	18:39	18:40	19:07	28:00	16-30	Yes
18117858		01-XST-1224	CENTRAL PARK WEST W 86 ST	ER	11/26/2022	10:05	10:10	10:20	15:00	0-15	Yes
18127054		07-ST-0048	PARK AVE BTW E 33 ST & E 34 ST	ER	11/30/2022	17:06	17:10	17:45	39:00	31-45	Yes

No. of Records: 39



Consolidated Edison Company
of New York, Inc.
750 East 16th Street
New York NY 10009
www.conEd.com

January 13, 2023

Mr. Kevin Speicher
Chief, Gas & Petroleum Safety
Office of Electric, Gas & Water
New York State Dept. of Public Service
Three Empire State Plaza
Albany, NY 12223

Mr. Speicher,

Pursuant to section 420.12 (f) of the Public Service Commission's regulations, Consolidated Edison Company of New York, Inc. ("Con Edison" or "the Company") hereby submits the attached Unscheduled Interruption of Service Report. There was one unscheduled interruption affecting ten customers for the month of December 2022.

In addition, pursuant to section 420.13 (c) of the Commission's regulations, the Company hereby submits the attached Analysis of Response to Emergency Steam Reports for the month of December 2022. The Company responded to 97.30 percent of emergency calls within 60 minutes.

Sincerely,



Theresa Kong
General Manager
Steam Distribution

PV/File

Attachments

Analysis of Response to Emergency Steam Report

Month: December-2022

Emergency Calls

	Weekdays During Normal Business Hours		Weekdays After Business Hours		Weekends		Total		Leak or Vapor Complaints	
									Current Month	
Response Time*(Minut)	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls	# of calls	% of calls
0-15	6	26.09%	5	50%			11	28.95%	10	27.03%
16-30	7	30.43%	2	20%	3	60%	12	31.58%	12	32.43%
31-45	8	34.78%	3	30%	2	40%	13	34.21%	13	35.14%
46-60	1	4.35%					1	2.63%	1	2.7%
>60	1	4.35%					1	2.63%	1	2.7%
Totals	23	100	10	100	5	100	38	100	37	100

* Total elapsed time from receipt of report to time of arrival.



1/12/2023

Signature of General Manager



Analysis of Response to Emergency Steam Report

Month: December-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
18128688		03-ST-0102	E 68 ST BTW LEXINGTON AVE & THIRD AVE	ER	12/02/2022	00:04	00:10	00:17	13:00	0-15	Yes
18145613		08-XST-0125	FIRST AVE E 20 ST	SK	12/05/2022	19:54	19:57	20:30	36:00	31-45	Yes
18145911		04-ST-0034	BROADWAY BTW W 61 ST & W 62 ST	ER	12/06/2022	11:22	11:30	11:50	28:00	16-30	Yes
18146099		11-ST-0138	SOUTH ST BTW CLINTON ST & MONTGOMERY ST	SK	12/07/2022	02:16	02:19	02:45	29:00	16-30	Yes
18146134		04-ST-0197	FIFTH AVE BTW W 57 ST & E 57 ST	ER	12/07/2022	07:18	07:22	08:02	44:00	31-45	Yes
18146316		06-XST-0155	SECOND AVE E 36 ST	ER	12/07/2022	13:16	13:19	13:21	05:00	0-15	Yes
18147168		14-ST-0048	WALL ST BTW NASSAU ST & BROADWAY	ER	12/07/2022	22:06	22:13	22:21	15:00	0-15	Yes
18147286		05-SVC-1503	SERVICE: SVC-1503 AT 4-10 E 53 ST	ER	12/08/2022	08:48	09:00	09:30	42:00	31-45	Yes
18147357		08-ST-0072	E 17 ST BTW FIFTH AVE & BROADWAY	ER	12/08/2022	11:38	11:40	11:44	06:00	0-15	Yes
18147449		02-ST-0050	CENTRAL PARK WEST BTW W 82 ST & W 83 ST	ER	12/08/2022	14:11	14:12	14:48	37:00	31-45	Yes
18148200		08-XST-0081	E 15 ST AVE C	ER	12/08/2022	18:58	18:59	19:00	02:00	0-15	Yes
18148310		05-ST-0131	E 53 ST BTW FIFTH AVE & MADISON AVE	ER	12/09/2022	08:58	09:05	09:28	30:00	16-30	Yes
18148358		05-ST-0131	E 53 ST BTW FIFTH AVE & MADISON AVE	ER	12/09/2022	11:37	11:42	12:19	42:00	31-45	Yes
18149824		04-ST-0276	SEVENTH AVE BTW W 54 ST & W 55 ST	ER	12/10/2022	21:38	21:41	22:22	44:00	31-45	Yes
18151812		10-MH-5421	MANHOLE - 5421: 350 CANAL ST W/ O CHURCH ST	ER	12/11/2022	19:16	19:25	20:00	44:00	31-45	Yes

1/3/23 9:11 AM

2 / 4



Analysis of Response to Emergency Steam Report

Month: December-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
18152645		03-ST-0132	E 70 ST BTW THIRD AVE & SECOND AVE	ER	12/11/2022	22:55	23:05	23:20	25:00	16-30	Yes
18154581		12-SVC-3135	SERVICE - 3135 AT 25 MURRAY ST	ER	12/14/2022	09:13	09:25	10:25	72:00	>60	Yes
18154583		07-ST-0284	W 33 ST BTW NINTH AVE & EIGHTH AVE	ER	12/14/2022	09:21	09:22	09:35	14:00	0-15	Yes
18154613		08-ST-0010	BROADWAY BTW E 18 ST & E 19 ST	ER	12/14/2022	10:30	10:35	10:40	10:00	0-15	Yes
18154775		09-ST-0112	FIRST AVE BTW E 12 ST & E 13 ST	ER	12/14/2022	15:54	16:00	16:37	43:00	31-45	Yes
18156130		02-ST-0046	CENTRAL PARK WEST BTW W 75 ST & W 76 ST	ER	12/16/2022	09:36	09:45	09:55	18:00	16-30	Yes
18156148		04-ST-0098	E 58 ST BTW PARK AVE & LEXINGTON AVE	ER	12/16/2022	10:27	10:30	10:34	07:00	0-15	Yes
18156273		02-ST-0085	MADISON AVE BTW E 77 ST & E 78 ST	ER	12/16/2022	13:09	13:15	13:37	28:00	16-30	Yes
18156311		06-ST-0053	E 35 ST BTW TUNNEL EXIT & SECOND AVE	ER	12/16/2022	15:45	15:50	16:07	22:00	16-30	Yes
18156336		02-ST-0089	MADISON AVE BTW E 81 ST & E 82 ST	ER	12/16/2022	19:50	19:53	20:34	44:00	31-45	Yes
18161146		02-SVC-38	SERVICE - 38 AT 1002-4 MADISON AVE	ER	12/19/2022	07:52	07:56	08:25	33:00	31-45	Yes
18161190		12-SVC-3135	SERVICE - 3135 AT 25 MURRAY ST	ER	12/19/2022	09:20	09:22	09:47	27:00	16-30	Yes
18162764		12-MH-15615	MANHOLE - 15615: CENTRE ST I/S DUANE ST	ER	12/21/2022	12:09	12:11	12:29	20:00	16-30	Yes
18162769		04-ST-0303	W 57 ST BTW EIGHTH AVE & BROADWAY	ER	12/21/2022	12:27	12:34	12:34	07:00	0-15	Yes



Analysis of Response to Emergency Steam Report

Month: December-2022

Work Order	Ticket Number	Location	Location Description	Jobcode/Task Type	Code Date	Rec Time	Disp Time	Arrival Time	Resp Time	Range	Leak or Vapor Complaint
18162801		04-SVC-646	SERVICE: SVC-646 AT 2-12 E 55 ST	ER	12/21/2022	13:29	13:33	14:10	41:00	31-45	Yes
18163479		08-ST-0056	E 14 ST BTW FIRST AVE & AVE A	ER	12/22/2022	20:21	20:23	20:25	04:00	0-15	Yes
18164631		14-MH-5519	MANHOLE - 5519: 130 WATER ST S/ O PINE ST	ER	12/23/2022	07:05	07:08	07:47	42:00	31-45	Yes
18166538		03-ST-0195	W 68 ST BTW COLUMBUS AVE & CENTRAL PARK WEST	ER	12/24/2022	20:55	21:00	21:18	23:00	16-30	Yes
18170490		12-ST-0056	ST JAMES PL BTW PEARL ST & ST JAMES PL	ER	12/27/2022	17:53	17:54	18:04	11:00	0-15	No
18171252		03-ST-0078	E 65 ST BTW FIFTH AVE & MADISON AVE	ER	12/28/2022	09:52	09:57	10:13	20:00	16-30	Yes
18171377		06-SVC-358	SERVICE: SVC-358 AT 1367-69 BROADWAY	ER	12/28/2022	15:15	15:20	16:00	45:00	31-45	Yes
18173637		04-XST-0031	SEVENTH AVE W 56 ST	ER	12/30/2022	07:04	07:09	07:50	46:00	46-60	Yes
18175195		02-ST-0119	E 76 ST BTW YORK AVE & EAST RIVER DR	ER	12/31/2022	11:16	11:21	11:32	16:00	16-30	Yes

No. of Records: 38

Consolidated Edison Company of New York, Inc.

Steam Distribution

SERVICE INTERRUPTION REPORT


District: Manhattan
Month: December 2022

From: 12/01/2022 – 12/31/2022

Date	Time Received	Dispatch Time	Arrival Time	Time Off	Time On	Duration HR / Min.		Location	Number of Customers Affected	Cause of Interruption
12/23/2022	5:34 AM	5:34 AM	5:34 AM	7:00 AM	1:26 PM	6 Hr	26 Min	East 65th Street, between Park Avenue and Madison Avenue	10*	Equipment failure

*Note: One of the ten customer was restored on 12/24/2022 at 12:48 AM due to the failed equipment being on their service line which required repair prior to turn on.

Theresa Kong,

 1/13/2023
General Manager / Steam Distribution

Company Name: Con Edison
Case Description: Con Edison Steam Rate Filing with NYS PSC
Case: 22-S-0659

Response to DPS Interrogatories – Set DPS-19
Date of Response: February 21, 2023
Responding Witness: Steam Infrastructure and Operations Panel

Question No. :229

Subject: Leak Management

1. Fully explain how the average month-end steam leak backlog is calculated and indicate whether the average is a rolling average from month-to-month. Provide all applicable procedures and a sample calculation.
2. Provide the Company's definition of a "steam leak."
 - a. Indicate whether all steam vapor conditions considered a steam leak.
 - b. If all steam vapor conditions are not considered a steam leak, indicate when a steam vapor condition is considered a steam leak.
3. Does the steam leak backlog include all steam vapor conditions? If not, indicate which steam vapor conditions are excluded from the steam leak backlog.
4. How and when are newly determined steam leaks added to the steam leak backlog? Provide all applicable procedures.
5. For each month (January, February, March, April, May, June, July, August, September, October, November, and December) in 2018, 2019, 2020, 2021, and 2022, provide the following:
 - a. number of newly determined steam leaks;
 - b. average duration of investigations of newly determined steam leaks;
 - c. number of repaired steam leaks;
 - d. average cost for repaired steam leaks;
 - e. average duration for repairs of steam leaks;
 - f. number of backlogged steam leaks; and
 - g. average month-end steam leak backlog.

Response

1. The average month-end steam leak backlog is calculated on the first business day of each month. It is a formula that identifies all confirmed leaks identified in the current reporting month plus the previous month backlog minus previous months leaks

cleared. Con Edison does not have a formal procedure for calculating the leak backlog, please see below for the formula and an example calculation.

$$\begin{aligned}
 \text{Leak Backlog} = & \\
 & \text{leaks identified current month} \\
 & + (\text{previous months leak backlog} \\
 & - \text{previous months leaks cleared})
 \end{aligned}$$

It is a rolling average of the leak backlog calculated from January to December of the given year (January being the first month the average is the month end backlog number).

Sample Calculation of the leak backlog for December 2022:

$$\begin{aligned}
 \text{Leak Backlog} = & \\
 & 32 \text{ leaks identified current month} \\
 & + (15 \text{ previous months leak backlog} \\
 & - 30 \text{ previous months leaks cleared}) \\
 & \textbf{Leak Backlog} = 17
 \end{aligned}$$

2. A steam leak is pressurized steam unintentionally released through a breach in the pressure boundary of the steam system piping.
 - a. See response to question 3
 - b. A steam vapor condition is considered a leak when it is identified that pressurized steam was unintentionally released through a breach in the pressure boundary of the steam system piping.
3. No, steam leak backlog does not include all steam vapor conditions. Vapor conditions must be first investigated and confirmed as leaks.
4. Newly determined steam leaks are added to the leak backlog when they are confirmed as a leak after the leak investigation is completed. They are tracked back to the original complaint date and managed according to code. Con Edison does not have a formal procedure for when newly determined steam leaks added to the steam leak backlog.
5. See below table containing the information requested in question 5 above.

Year and Month	a (number)	c (number)	d (\$000)	e (days)	f (number)	g (number)
----------------	---------------	---------------	--------------	-------------	---------------	---------------

2018	January	35	33	687	*	20	20.00
	February	41	41	912		20	20.00
	March	37	31	1,517		26	22.00
	April	29	45	2,523		10	19.00
	May	45	38	1,641		17	18.60
	June	38	38	1,800		17	18.30
	July	40	37	1,098		20	18.60
	August	39	42	1,962		17	18.30
	September	32	30	1,106		19	18.40
	October	50	55	1,995		14	18.00
	November	44	40	1,470		18	18.00
	December	37	30	1,199		25	18.58
2019	January	31	28	2,198	34.74	28	28.00
	February	33	43	1,504	21.28	18	23.00
	March	37	37	1,635	29.18	18	21.33
	April	45	42	1,011	39.48	21	21.25
	May	48	51	1,139	30.49	18	20.60
	June	34	35	954	27.30	17	20.00
	July	35	37	1,187	23.88	15	19.29
	August	35	39	1,889	17.53	11	18.25
	September	36	26	1,401	26.42	21	18.56
	October	45	47	1,332	33.84	19	18.60
	November	33	18	1,077	38.11	34	20.00
	December	24	36	1,222	31.57	22	20.17
2020	January	34	38	994	18.84	18	18.00
	February	47	46	1,922	19.51	19	18.50
	March	30	31	2,042	36.38	18	18.33
	April	25	24	1,570	21.46	19	18.50
	May	32	36	1,167	25.90	15	17.80
	June	20	22	1,135	19.24	13	17.00
	July	23	25	1,409	25.86	11	16.14
	August	35	30	1,457	35.97	16	16.13
	September	28	29	1,196	34.48	15	16.00
	October	27	18	1,339	46.53	24	16.80
	November	44	40	1,574	30.12	28	17.81
	December	31	39	1,217	53.94	20	18.00

Year and Month	a (number)	c (number)	d (\$000)	e (days)	f (number)	g (number)
----------------	---------------	---------------	--------------	-------------	---------------	---------------

2021	January	31	31	1,464	32.39	20	20.00
	February	29	33	1,724	40.62	16	18.00
	March	27	27	2,139	17.30	16	17.30
	April	31	36	2,090	24.82	11	15.75
	May	37	31	1,172	22.45	17	16.00
	June	28	31	1,693	17.47	14	15.66
	July	36	27	1,688	22.71	23	16.71
	August	33	40	1,288	18.83	16	16.62
	September	34	34	1,468	33.45	16	16.55
	October	58	54	1,663	23.66	20	16.90
	November	31	33	1,589	20.37	18	17.00
	December	35	32	2,170	29.09	21	17.33
2022	January	33	26	1,507	23.52	28	28.00
	February	33	37	1,817	13.50	24	26.00
	March	34	37	1,665	13.65	21	24.33
	April	32	38	1,654	28.70	15	22.00
	May	42	44	1,968	31.03	13	20.20
	June	40	36	2,175	25.61	17	19.67
	July	41	40	1,312	16.92	18	19.43
	August	55	47	1,503	24.99	26	20.25
	September	37	46	1,665	12.96	17	19.88
	October	36	40	1,071	11.24	13	19.20
	November	42	40	1,708	13.60	15	18.82
	December	32	30	2,675	13.58	17	18.67

Please note:

- Item b is not provided for any of the years requested as the Company's work management system does not break out leak investigation duration, as it tracks the leak identification date and then the leak repair date.
- For item d the value provided includes O&M, Capital and Retirement cost and is for expenditures associated with the Leaks and Excavations Program which addresses issues that arise from both leaks and additional work that requires excavation and repair.
- For year 2018* our legacy work management system data quality does not allow us to extract information requested for item e and therefore it is not provided with the response.

Company Name: Con Edison
Case Description: Con Edison Steam Rate Filing with NYS PSC
Case: 22-S-0659

Response to DPS Interrogatories – Set DPS-19
Date of Response: February 21, 2023
Responding Witness: Steam Infrastructure and Operations Panel

Question No. :231

Subject: Remote Monitoring System (RMS)

1. Provide the definition of a steam RMS “critical location.” How does the Company determine if an RMS location is a critical location?
2. Provide the number of steam RMS that the Company has installed in critical locations broken down by remote-terminal unit (RTU), steam trap temperature sensor location, and float water level detector (float).
3. Explain how the Company calculates the percent reliability of the steam RMS. Provide a sample calculation and all applicable procedures.
4. For each month (January, February, March, April, May, June, July, August, September, October, November, and December) in 2020, 2021, and 2022, provide the percent reliability of steam RMS in critical locations.
5. Provide the number of non-critical steam RMS locations.
6. Provide the number of steam RMS that the Company has installed in non-critical locations broken down by RTU, steam trap temperature sensor location, and float.
7. For each month (January, February, March, April, May, June, July, August, September, October, November, and December) in 2020, 2021, and 2022, provide the percent reliability of steam RMS in non-critical locations.
8. For the “Remote Monitoring System RTU Box Replacement” program, will the 940 RTUs primarily be used to replace RTU’s in critical or non-critical RMS locations?
 - a. Provide the number of RTUs that will be used in each critical and non-critical RMS locations.
9. For the “Remote Monitoring System RTU Box Replacement” program, will any of the 940 RTUs be used to expand the steam RMS system?

- a. If yes, provide the number of RTUs that will be used for new steam RMS locations.

10. Fully explain how the Company will ensure the reliability of its steam RMS in both critical and non-critical locations. Include any Company goals for percent reliability for its steam RMS in non-critical locations.

Response

1. Con Edison defines a critical steam structure to be one of the following four conditions:
 - A category 1 deep structure where the depth of the steam main is 15 feet or deeper and has a water impingement issue.
 - A category 2 deep structure where the depth of the steam main is between 12 and 15 feet and has a water impingement issue.
 - A structure with at least one permanent pump installed. A pump structure could also be a category 1 or category 2 deep structure.
 - A steam structure that was removed from the priority list based on a remediation condition that remote monitoring or a water float sensor is to be installed.
2. As of February 1, 2023 Con Edison has:
 - 124 Remote Terminal Units
 - 124 Trap Temp Sensing Locations
 - 188 Locations with Float level sensors
3. The Company does not have a procedure for calculating reliability. The Company calculates reliability dividing the reporting and functioning sensor locations by the all the locations as detailed below:

$$\left(\frac{\text{Reporting and functioning sensors in critical RTU locations}}{\text{Total sensors in critical RTU locations}} \right) \times 100$$

Sample Calculation for December 2022:

$$\frac{(118 \text{ reliable traps} + 166 \text{ reliable floats})}{(124 \text{ total traps} + 188 \text{ total floats})} \times 100$$

$$\frac{(284 \text{ reliable sensors})}{(312 \text{ total sensors})} \times 100$$

$$0.910 \times 100$$

91.0 %

4.

	2020	2021	2022
January	85.5	86.2	79.4
February	85.5	81.9	89.3
March	83.8	81.88	90.3
April	85.5	79.2	87.7
May	87.3	89.6	77.7
June	84.9	75.8	74.7
July	60.7	84.2	72.4
August	66.4	77.5	81.7
September	69.5	78.9	82.7
October	80	80.2	89.4
November	90.3	88.6	91.3
December	88.9	89.6	91.0

5. Con Edison has a total of 816 non-critical RMS locations.
6. In an effort to focus on the critical locations and enhance the reliability of the critical RMS locations the Company has not maintained the non-critical RMS locations since 2019 as they contain obsolete equipment. Therefore, we do not have an accurate number for installed equipment at noncritical locations to provide.
7. As stated above in the response to question 6, since 2019 the Company has not maintained non-critical RMS locations and shifted its focus to critical locations, thereafter reliability data is not available for non-critical locations.
8. Yes, the 940 RTUs will be primarily used to expand the RMS to non-critical locations. 124 RTUs will be used in critical locations and the remaining 816 will be in non-critical locations.
9. At this moment there is no plans for new locations.
10. The Company has:
 - Invested in the development and testing of technologies that have higher rating and higher probability of surviving in the steam environment.
 - Continued to research and test new technologies.

- Established a new and higher progression union title of Mechanic Technician which required specialized training for those field employees maintaining and repairing the RMS equipment.
- The Company has an internal goal of maintaining critical RMS reliability at 80% or higher.
- Implemented a new work management system for tracking RMS repair work.

The Company does not have an internal metric for non-critical RMS locations but will monitor non-critical reliability as we expand the program.