
#### **Instructions for Using This Digital Survey**

This architectural survey has images that may appear as small tiles that are difficult to read. In order to enhance the size and appearance of the photos in this document perform the following actions:

- 1) Download PDF to desktop.
- 2) Open the document in Adobe Reader.
  - 3) Open on the View Tab.
- 4) Go to Page Display in the drop down menu.
  - 5) Change to Single Page View

#### **INDEX MAP**

HISTORIC ARCHITECTURAL SURVEY



Springfield " Survey Boundary 1984

### Missouri Historic Architectural Inventory for 63 5550 Division of Parks and Historic Preservation Department of Natural Resources

•		
38) Ownership — private *	1) inventory number	11-94
- public	2) name (cont)	<u> </u>
39) Owners — name	3) name - historial	
	· ·	
— address	4) street address	South ave.
40) Local contact	5) town or vicinity	Suringfield
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county	
43) Other survey	8) category	Greene
45) Other survey	_	
	(site, structure,	building
	building, object)	
44) History	9) significance	
built ca. 1880 (present by 1884)	10) date	ca. 1880
erá used as a drug store for over fifty	11) style	04. 1000
; ears	1	
	12) architect	
	13) builder	
	14) original use	connercial
	15) present use	
45) Additional description (a)		vacant
45) Additional description The press netal cornice has been		2
removed. Only detail visible is the four bay	17) plan shape	rectangle
second story level with round arched window	18) basement	-
openings.	19) foundation	stone
obeurno	20) wall construction	brick
	21) roof type -	
	• • • • • • • • • • • • • • • • • • • •	flat
	material	_
	22) contact print	
	35mm	
		-
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings		
47) Information sources		cornice removed and
47) Information sources Sanborn 1884		
47) Information sources	24) changes - additions/alter-	cornice removed and
47) Information sources Sanborn 1884 1902	24) changes - additions/alter- ations/moved	cornice removed and
47) Information sources Sanborn 1884	24) changes - additions/alter- ations/moved 25) condition	cornice removed and storefront altered
47) Information sources Sanborn 1884 1902	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	cornice removed and storefront altered
47) Information sources Sanborn 1884 1902	24) changes - additions/alter- ations/moved 25) condition	cornice removed and storefront altered
47) Information sources Sanborn 1884 1902	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	cornice removed and storefront altered
47) Information sources Sanborn 1884 1902 1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	cornice removed and storefront altered
47) Information sources Sanborn 1884 1902	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	cornice removed and storefront altered
47) Information sources Sanborn 1884 1902 1933 48) Location of negatives roll 101 #35	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	cornice removed and storefront altered
47) Information sources Sanborn 1884 1902 1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	cornice removed and storefront altered
47) Information sources Sanborn 1884 1902 1933 48) Location of negatives roll 101 #35 49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	cornice removed and storefront altered
47) Information sources Sanborn 1884 1902 1933 48) Location of negatives roll 101 #35	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	cornice removed and storefront altered
47) Information sources Sanborn 1884 1902 1933 48) Location of negatives roll 101 #35 49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	cornice removed and storefront altered
47) Information sources Sanborn 1884 1902 1933 48) Location of negatives roll 101 #35 49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	cornice removed and storefront altered
47) Information sources Sanborn 1884 1902 1933 48) Location of negatives roll 101 #35 49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	cornice removed and storefront altered
47) Information sources  Sanborn 1884 1902 1933  48) Location of negatives roll 101 #35  49) Prepared by DDD  50) Organization NTT	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	cornice removed and storefront altered
47) Information sources Sanborn 1884 1902 1933 48) Location of negatives roll 101 #35 49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica	cornice removed and storefront altered
47) Information sources  Sanborn 1884 1902 1933  48) Location of negatives roll 101 #35  49) Prepared by DDD  50) Organization NTT	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district	cornice removed and storefront altered
47) Information sources Sanborn 1884 1902 1933  48) Location of negatives roll 101 #35  49) Prepared by DDD  50) Organization PT  If add  Separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica	cornice removed and storefront altered
47) Information sources  Sanborn 1884 1902 1933  48) Location of negatives roll 101 #35  49) Prepared by DDD  50) Organization NTT	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	no no
47) Information sources Sanborn 1884 1902 1933  48) Location of negatives roll 101 #35  49) Prepared by DDD  50) Organization PT  If add  Separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	no no yes
47) Information sources  Sanborn 1884 1902 1933  48) Location of negatives roll 101 #35  49) Prepared by DDD  50) Organization PTT  Separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	no no
47) Information sources  Sanoorn 1884 1902 1933  48) Location of negatives roll 101 #35  49) Prepared by DDD  50) Organization NTT  Separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	no no yes
47) Information sources  Sanoorn 1884 1902 1933  48) Location of negatives roll 101 #35  49) Prepared by DDD  50) Organization NTT  Separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	no no yes
47) Information sources  Sanoorn 1884 1902 1933  48) Location of negatives roll 101 #35  49) Prepared by DDD  50) Organization NTT  Separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	no no yes



2) r 3) r 4) s 5) t 6) l 17) c 6 11) s 12) a 14) c 15) r 16) r 17) r 18) l 19) t 19)	style architect builder original use present use number of stories plan shape	m-100,104,105,106 South ave. Springfield  Greene building  commercial
3) r 4) s 5 t 4 s 5 t 5 t 6 l l 7 c 6 l l 7 c 6 l l 1 2 l 2 2 1 2 1 2 1 2 1 2 1 2 1 2 1	name - historial street address town or vicinity legal description county category (site, structure, building, object) significance date style architect builder original use present use number of stories plan shape	Greene building  Commercial
4) s 5) t 6) I 7) c 8) c ( t 10) c 11) s 12) a 14) c 15) r 16) r 17) r 18) I	street address town or vicinity legal description county category (site, structure, building, object) significance date style architect builder original use present use number of stories plan shape	Greene building  Commercial
5) t 6) I 7) c 8) c (t 10) c 11) s 12) a 13) t 14) c 15) r 16) r 17) r 18) I	town or vicinity legal description county category (site, structure, building, object) significance date style architect builder original use present use number of stories plan shape	Greene building  Commercial
6)     7)   6   8   6   (   1   1   1   1   1   1   1   1   1	legal description county category (site, structure, building, object) significance date style architect builder original use present use number of stories plan shape	Greene building  commercial
7) ( 8) ( 10) ( 11) ( 12) ( 13) ( 14) ( 15) ( 16) ( 17) ( 18) ( 19) (	county category (site, structure, building, object) significance date style architect builder original use present use number of stories plan shape	building  commercial
8) ( () () () () () () () () () (	category (site, structure, building, object) significance date style architect builder original use present use number of stories plan shape	building  commercial
9) \$ 10) \$ 11) \$ 12) \$ 13) \$ 14) \$ 15) \$ 16) \$ 17) \$ 18) \$ 18) \$ 19) \$ 19	(site, structure, building, object) significance date style architect builder original use present use number of stories plan shape	Commercial
9) 5 10) 6 11) 5 12) 2 13) 1 14) 6 15) 1 16) 1 17) 1 18) 1	building, object) significance date style architect builder original use present use number of stories plan shape	Commercial
9) s 10) c 11) s 12) a 13) t 14) c 15) p 16) r 17) p 18) t	significance date style architect builder original use present use number of stories plan shape	
10) c 11) s 12) a 13) t 14) c 15) p 16) r 17) p 18) t	date style architect builder original use present use number of stories plan shape	
11) s 12) a 13) t 14) c 15) p 16) r 17) p 18) t	style architect builder original use present use number of stories plan shape	
13) t 14) c 15) p 16) r 17) p 18) t	builder original use present use number of stories plan shape	
14) ( 15) ( 16) ( 17) ( 18) ( 19) (	original use present use number of stories plan shape	
15) ( 16) ( 17) ( 18) ( 19) (	present use number of stories plan shape	
16) ( 17) ( 18) ( 19) (	number of stories plan shape	
17) ( 18) ( 19) (	plan shape	
18) ( 19) (		
19) 1	hacamant	
_	(	
	foundation	
-	wall construction	bri elt
	roof type -	
	material	
23) :	site plan:	
1++	+++++	<del>-                                     </del>
-+-		
++	+++++	<del>╶┧┊╏╂</del> ┋╃╏╃
	<u> </u>	
1	-	see description
ļ		
}		
{ <i>r</i>		
1 '		
1	-	
ì	-	
1	•	
1	<del>-</del>	
		no
1	-	
1	established	
	historical district	:10
33)	name of historical	
1	district	
ł		no
i	· ·	
1 '		1:/18/84
37)	revision	
<del> </del>		
		l .
	23) 24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35) 36)	23) site plan  23) site plan  24) changes -    additions/alter-    ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation    underway?  30) endangered?  31) on National    Register?  32) part of    established    historical district  33) name of historical



# Missouri Historic Architectural Inventory for Galacter Services Division of Parks and Historic Preservation Department of Natural Resources

DIVISION OF LARKS AND INSCORE LIESCHARION DI	cpartitions of Hatural Nesources
38) Ownership — private	* 1) inventory number II-109
public	2) name (cont) •
39) Owners — name	3) name - historial
— address	4) street addressSouth ave.
40) Local contact	5) town or vicinity Soring field
41) Coordinates (UTM)	6) legal description
42) Quad	7)
	1 (11 6 6 11 6
43) Other survey	8) category
	(site, structure, building
	building, object)
44) History	9) significance
· · · · · · · · · · · · · · · · · · ·	
	10) date
	11) style
	12) architect
	13) builder
	14) original use
	15) present use
45) Additional description facade is completely obscured	, 16) number of stories 2 2 2
	17) plan shape rectangle
	19) foundation
	20) wall construction brick
	21) roof type-
	material _
	22) contact print
	35mm
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
47) Information sources	
47) Information sources	24) changes - storefront altered
	24) changes - storefront altered and facade covered
47) Information sources	24) changes - storefront altered and facade covered ations/moved codern siding
47) Information sources	24) changes - storefront altered and facade covered
47) Information sources	24) changes - storefront altered and facade covered ations/moved codern siding
47) Information sources	24) changes- additions/alter- ations/moved ations/moved 25) condition 26) visible from road?
47) Information sources	24) changes - storefront altered and facade covered modern siding 25) condition 26) visible from road? 27) distance/frontage
47) Information sources Sanborn1933	24) changes - storefront altered and facade covered modern siding 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
47) Information sources Sanborn1933	24) changes - storefront altered and facade covered modern siding 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources  Sanborn1933  48) Location of negatives roll 101 #34	24) changes - storefront altered and facade covered modern siding 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
47) Information sources Sanborn1933	24) changes - storefront altered and facade covered modern siding 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources  Sanborn1933  48) Location of negatives roll 101 #34	24) changes- additions/alter- ations/moved ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
47) Information sources  Sanborn1933  48) Location of negatives roll 101 #34  49) Prepared by DDD	24) changes- additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  Sanborn1933  48) Location of negatives roll 101 #34	24) changes- additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?
47) Information sources  Sanborn1933  48) Location of negatives roll 101 #34  49) Prepared by DDD	24) changes - storefront altered and facade covered modern siding 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of
47) Information sources  Sanborn1933  48) Location of negatives roll 101 #34  49) Prepared by DDD	24) changes- additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established
47) Information sources  Sanborn1933  48) Location of negatives roll 101 #34  49) Prepared by DDD	24) changes - storefront altered and facade covered modern siding 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of
47) Information sources  Sanborn1933  48) Location of negatives roll 101 #34  49) Prepared by DDD  50) Organization	24) changes - storefront altered and facade covered modern siding 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district
47) Information sources  Sanborn1933  48) Location of negatives roll 101 #34  49) Prepared by DDD	24) changes- additions/alter- ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National Register?  32) part of established historical district  33) name of historical
47) Information sources  Sanborn1933  48) Location of negatives roll 101 #34  49) Prepared by DDD  50) Organization	24) changes- additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district
47) Information sources  Sanborn1933  48) Location of negatives roll 101 #34  49) Prepared by DDD  50) Organization	24) changes- additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?  no  store front altered and facade covered modern siding  no no no no no no
47) Information sources  Sanborn1933  48) Location of negatives roll 101 #34  49) Prepared by DDD  50) Organization	24) changes- additions/alter- ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National Register?  32) part of established historical district  33) name of historical district  34) is site eligible? 35) district potential?
47) Information sources  Sanborn1933  48) Location of negatives roll 101 #34  49) Prepared by DDD  50) Organization	24) changes- additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?  no  store front altered and facade covered modern siding  no no no no no no
47) Information sources  Sanborn1933  48) Location of negatives roll 101 #34  49) Prepared by DDD  50) Organization INIT  ched separate sheets.	24) changes- additions/alter- ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National Register?  32) part of established historical district  33) name of historical district  34) is site eligible? 35) district potential?
47) Information sources  Sanborn1933  48) Location of negatives roll 101 #34  49) Prepared by DDD  50) Organization INT  ched separate sheets.	24) changes- additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  store front altered and facade covered modern siding  no modern siding
47) Information sources  Sanborn1933  48) Location of negatives roll 101 #34  49) Prepared by DDD  50) Organization INT  ched separate sheets.	24) changes- additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  store front altered and facade covered modern siding  no modern siding



Missouri Historic Architectural Inventory for Communication Division of Parks and Historic Preservation Denartment of Natural Persurance


Division of Parks and Historic Preservation Department	u		
38) Ownership — private *	1)	inventory number	N-92
— public	2)	name (cont)	1.00
39) Owners — name	3)	name - historial	-
address	4)	street address	217 South ave.
(40) Local contact	5)	town or vicinity	Springfield
41) Coordinates (UTM)	ı	legal description	<u> </u>
42) Quad		county	
43) Other survey		category	Greene
Top while during	",	(site, structure,	
			building
XXV 11-1		building, object)	
44) History	1	significance	1000
		date	ca. 1920
•		style	
		architect	
		builder	
	14)	original use	commercial
	15)	present use	vacant
45) Additional description Fatterned parapet with geometric *	16)	number of stories	2
stone coping below which is a patterned geometri	(17)	plan shape	rectangle
motif surrounding a stone panel with "Altschul"	18)	basement	-
	1	foundation	_
carved on it. There is a continous stone lintel		wall construction	
and sill.	- 1	roof type -	brick veneer
	[21]	material	flat
	201	contact print	
	221	35mm	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings  47) Information sources		changes -	storefront altered
		changes - additions/alter-	storefront altered
	24)	changes - additions/alter- ations/moved	storefront altered
	24)	changes - additions/alter- ations/moved condition	
	24)	changes - additions/alter- ations/moved condition visible from road?	
	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road? distance/frontage	
47) Information sources	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	
47) Information sources	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	
47) Information sources	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	
47) Information sources  48) Location of negatives roll 17 734	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	
47) Information sources  48) Location of negatives roll 17 734  49) Prepared by DDD	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	
47) Information sources  48) Location of negatives roll 17 734	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	
47) Information sources  48) Location of negatives roll 17 .734  49) Prepared by DDD LIFE	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	
47) Information sources  48) Location of negatives roll 17 .734  49) Prepared by DDD LUCC	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	
47) Information sources  48) Location of negatives roll 17 .734  49) Prepared by DDD LIFE	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	no
48) Location of negatives roll 17 734  49) Prepared by DDD 1.117  50) Organization	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	no
47) Information sources  48) Location of negatives roll 17 .734  49) Prepared by DDD LIFE	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	no
48) Location of negatives roll 17 734  49) Prepared by DDD LHT  50) Organization	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district	no
48) Location of negatives roll 17 .734  49) Prepared by DDD 1.HT  attached separate sheets.	24) 25) 26) 27) 28) 29) 30) 31) 32) 33,	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible?	no no
48) Location of negatives roll 17 .734  49) Prepared by DDD 1.11T  attached separate sheets.	24) 25) 26) 27) 28) 29) 30) 31) 32) 34, 35,	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible? ) district potential	no no no yes
48) Location of negatives roll 17 234  49) Prepared by DDD LHT	24) 25) 26) 27) 28) 29) 30) 31) 32) 34, 35, 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential? date	no no
48) Location of negatives roll 17 .734  49) Prepared by DDD 1.11T  attached separate sheets.	24) 25) 26) 27) 28) 29) 30) 31) 32) 34, 35, 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible? ) district potential	no no no yes
48) Location of negatives roll 1734  49) Prepared by DUD 1	24) 25) 26) 27) 28) 29) 30) 31) 32) 34, 35, 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential? date	no no no yes
48) Location of negatives roll 17 .734  49) Prepared by DDD 1.HT  attached separate sheets.	24) 25) 26) 27) 28) 29) 30) 31) 32) 34, 35, 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential? date	no no no yes



Division of Fairs and instante reservation beha		
38) Ownership — private — public	<ol> <li>inventory numb</li> <li>name (cont)</li> </ol>	er 11-05
39) Owners — name	3) name - historial	
— address	4) street address	301 South avc.
(40) Local contact	5) town or vicinity	
41) Coordinates (UTM)	6) legal descriptio	n
42) Quad	7) county	Greene
43) Other survey	8) category	
	(site, structure,	1
	building, object	3)
44) History	9) significance	
	10) date	ca. 1915
	11) style 12) architect	
	13) builder	
	14) original use	
	15) present use	connercial
45) Additional description 77 to the state of the state o	16) number of stori	ies 2
fint paraget which a simple banded .	17) plan shape	rectangle
entablature beneath. Flat arch soldier coursed	18) basement	-
lintels above triple Grouped second story window	19) foundation	-
opening. Stone sills.	20) wall constructi	on brick
	21) roof type -	flit
	material	
	22) contact print	
	35mm	
46) Description of environment/outbuildings	23). site plan	
		<del></del>
	<del></del>	<del>┤</del> ┤╎┼╁┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼
	04)	
47) Information sources Samborn 1933	24) changes - additions/alter	storefront altered
	ations/moved	-
	25) condition	
	26) visible from ro	pad?
	27) distance/front	
	28) accessible?	
48) Location of negatives	29) preservation	
roll 98 416	underway?	
49) Prepared by	30) endangered?	
DDD	31) on National	
50) Organization	Register?	110
	32) part of	
	established	riet no
tached excepts cheats	historical dist	
tached separate sheets.	district	
	34) is site eligible	? no
	35) district potent	
	36) date	I <sub>1</sub> /11/84
	37) revision	
HISTORIC INVENTORY FORM  NISSOURI HERITAGE TRUST		



38) Ownership — private *	1) inventory number	7-96
public	2) name (cont)	
·	1	
39) Owners — name	3) name - historial	
— addres s	4) street address	305 South ave.
( 40) Local contact	5) town or vicinity	
	· I	Springfield
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county	~
		Craene
43) Other survey	8) category	
	(site, structure,	227.22
	building object)	building
	building, object)	
44) History	9) significance	
	10) date	
		ca. 1905
	11) style	
	12) architect	
	13) 50:140-	
	13) builder	
	14) original use	commercial
	15) present use	commercial
ACA A Julia Caral Daniel Caral		
45) Additional description Flat parapet beneath which is a	16) number of stories	2
TECO Participes porterior american to a	17) plan shape	rectangle
simple patt rued brick entablature. There are	المما	
seven window bays with round arched window open	14 18) basement	-
DEVENT WELLOW OR ON THE TOWN OF THE TAIL TO THE TAIL THE THE TAIL	19) foundation	
ings with two der two light window sash.	20) wall construction	1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1
The storefront on the left has cast iron	' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '	01 7 0 77
pilesters flunding the storefront. A remaint	21) roof type -	flat
plinstons limbing the Storellone. A formation	material	-
of a press potal entablature above the store-		
front on t e right survives.	22) contact print	
Tronc on the figure salvives.	35mm	
		i
$\bigcirc$		İ
O		
A6\ Decories in a few viscous and the side in the side	03)	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	+ + + + + + + + + + + + + + + + + + + +
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan:	
46) Description of environment/outbuildings	23) site plan:	
46) Description of environment/outbuildings		
46) Description of environment/outbuildings  47) Information sources		<u> </u>
	24) changes -	storefronts altered
	24) changes - additions/alter-	<u> </u>
	24) changes - additions/alterations/moved	<u> </u>
	24) changes - additions/alter-	<u> </u>
	24) changes - additions/alter- ations/moved 25) condition	storefronts altered
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road	storefronts altered
	24) changes - additions/alter- ations/moved 25) condition	storefronts altered
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road	storefronts altered
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible?	storefronts altered
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation	storefronts altered
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible?	storefronts altered
48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway?	storefronts altered
48) Location of negatives  2011 98 ://17  49) Prepared by	24) changes - additions/alterations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	storefronts altered
48) Location of negatives  #2011 98 #17  49) Prepared by  DDD  TT	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	storefronts altered
48) Location of negatives  #2011 98 #17  49) Prepared by  DDD  TT	24) changes - additions/alterations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	storefronts altered
48) Location of negatives  2011 98 ://17  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	storefronts altered
48) Location of negatives  ### ### ############################	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	storefronts altered
48) Location of negatives  ### ### ############################	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	storefronts altered
48) Location of negatives  ### ### ############################	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	storefronts altered
48) Location of negatives  #011 98 #17  49) Prepared by  DDD  1. T	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	storefronts altered
48) Location of negatives  ### ### ############################	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	storefronts altered
48) Location of negatives  #011 98 #17  49) Prepared by  DDD  1. T	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	storefronts altered
48) Location of negatives  #011 98 #17  49) Prepared by  DDD  1. T	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	storefronts altered
48) Location of negatives  roll 98 ://17  49) Prepared by  DDD  SO) Organization  attached separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	storefronts altered
48) Location of negatives  ##17  49) Prepared by  50) Organization  attached separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential	storefronts altered  no no no yes
48) Location of negatives  roll 98 ://17  49) Prepared by  DDD  1007  attached separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	storefronts altered
48) Location of negatives  roll 98 ://17  49) Prepared by  DDD  TT  50) Organization  attached separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential	storefronts altered  no no no yes
48) Location of negatives  roll 98 ://17  49) Prepared by  DDD  TT  50) Organization  attached separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential 36) date	storefronts altered  no no no yes
48) Location of negatives  # 17  # 17  # 17  # 19  # 17  # 1	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential 36) date	storefronts altered  no no no yes
48) Location of negatives  roll 98 ://17  49) Prepared by  DDD  TT  50) Organization  attached separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential 36) date	storefronts altered  no no no yes



38) Ownership — private *	1)	inventory number	11-100
public	21	name (cont)	
	1	· ·	
39) Owners — name	3)	name - historial	
address	4)	street address	306 South ave.
(140) Local contact	51	town or vicinity	
	1	- 1	Springfield
41) Coordinates (UTM)	6)	legal description	
42) Quad	7)	county	Cmaina
			Greene
43) Other survey	8)	category	
		(site, structure,	
	1	building, object)	
			building
44) History	9)	significance	
built between 1886 and 1891 with a	10)	date	
millinery on the first floor and printing	1,11	style	
on the pocond.	1	_	
on the bacond.	12)	architect	
	13)	builder	
		original use	corrercial
	15)	present use	
45) Additional description		number of stories	commurcial -
	1		2
Flat parapet with banded entab-	[17)	plan shape	rectangle
lature and brick coffered frieze with more	181	basement	
banding beneath. Three bay facade at the second	'		
	1 '	foundation	-
story with round headed window openings and	20)	wall construction	orick
two over two light window sash.	21)	roof type -	flat
	/	material	
			-
	22)	contact print	
		35mm	
	1		
	Ì		
			i
( )			
$\circ$			
O			
46) Description of environment/outbuildings	23)	site plant	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings			
46) Description of environment/outbuildings		site plan	
47) Information sources Sanborn 1886		changes -	store has been
		changes - additions/alter-	store has been
47) Information sources Sanborn 1886		changes -	
47) Information sources Sanborn 1886	24)	changes - additions/alter-	store has been
47) Information sources Sanborn 1886	24)	changes - additions/alter- ations/moved condition	store has been
47) Information sources Sanborn 1886	24)	changes - additions/alter- ations/moved condition visible from road?	store has been
47) Information sources Sanborn 1886	24)	changes - additions/alter- ations/moved condition	store has been
47) Information sources Sanborn 1886	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road?	store has been
47) Information sources Semborn 1886 1891	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	store has been
47) Information sources Sanborn 1886	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	store has been
47) Information sources Semborn 1886 1891  48) Location of negatives roll 17 727	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	store has been
47) Information sources Samborn 1886 1891  48) Location of negatives roll 17 7/27	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	store has been
47) Information sources Semborn 1886 1891	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	store has been
47) Information sources Semborn 1886 1891  48) Location of negatives roll 17 727 49) Prepared by DDD	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	store has been
47) Information sources Semborn 1886 1891  48) Location of negatives roll 17 727 49) Prepared by DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	store has been
47) Information sources Samborn 1886 1891  48) Location of negatives roll 17 //27	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	store has been extensively altered
47) Information sources Semborn 1886 1891  48) Location of negatives roll 17 727 49) Prepared by DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	store has been extensively altered
47) Information sources 3emborn 1886 1891  48) Location of negatives roll 17 #27 49) Prepared by DDD 50) Organization 1887	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	store has been extensively altered
47) Information sources  Semborn 1886 1891  48) Location of negatives roll 17 #27  49) Prepared by DDD  50) Organization THE	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	store has been extensively altered
47) Information sources 3emborn 1886 1891  48) Location of negatives roll 17 #27 49) Prepared by DDD 50) Organization 1887	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	store has been extensively altered
47) Information sources  Semborn 1886 1891  48) Location of negatives roll 17 #27  49) Prepared by DDD  50) Organization THE	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	store has been extensively altered
47) Information sources  Semborn 1886 1891  48) Location of negatives roll 17 #27  49) Prepared by DDD  50) Organization THE	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	store has been extensively altered
47) Information sources  Semborn 1886 1891  48) Location of negatives roll 17 #27  49) Prepared by DDD  50) Organization THE	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	no
47) Information sources  Semborn 1886 1891  48) Location of negatives roll 17 #27  49) Prepared by DDD  50) Organization THE	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	no
47) Information sources  Semborn 1886 1891  48) Location of negatives roll 17 #27  49) Prepared by DDD  50) Organization THE	24) 25) 26) 27) 28) 29) 30) 31) 32) 34) 35)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	no no no
47) Information sources Samborn 1886 1891  48) Location of negatives roll 17 #27  49) Prepared by DDD 50) Organization THIT  attached separate sheets.	24) 25) 26) 27) 28) 29) 30) 31) 32) 34) 35) 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	store has been extensively altered  no no
47) Information sources Samborn 1886 1891  48) Location of negatives roll 17 #27  49) Prepared by DDD 50) Organization THIT  attached separate sheets.	24) 25) 26) 27) 28) 29) 30) 31) 32) 34) 35) 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	no no no
47) Information sources Samborn 1886 1891  48) Location of negatives roll 17 #27  49) Prepared by DDD 50) Organization THIT  attached separate sheets.	24) 25) 26) 27) 28) 29) 30) 31) 32) 34) 35) 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	no no no
47) Information sources Samborn 1886 1891  48) Location of negatives roll 17 #27  49) Prepared by DDD 50) Organization THIT  attached separate sheets.	24) 25) 26) 27) 28) 29) 30) 31) 32) 34) 35) 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	no no no



38) Ownership — private	1) inventory number	M-107
public	2) name (cont)	
39) Owners — name	3) name - historial	
address	4) street address	700 0 ()
	5) town or vicinity	308 South ave.
40) Local contact	1	Springfield
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county	Greene
43) Other survey	8) category	
	(site, structure,	
	building, object)	building
AAV History	9) significance	2 512 178
44) History originally built to house a bank	1 *	2 7 0 7 0
	10) date	ca. 1930
	11) style	
	12) architect	
	13) builder	
	14) original use	commercial
	15) present use	
46) Additional description		commercial
45) Additional description Art Deco inspired concrete panel .		3
set in the center of the paraget. The first	17) plan shape	rectangle
story level is sheatheed with a stone veneer.	18) basement	-
en e	19) foundation	_
	20) wall construction	brick veneer
	21) roof type -	flot
	material	
	22) contact print	
	· ·	
	35mm	
	,	
,		
		<del></del>
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings .	23) site plan	
46) Description of environment/outbuildings .	23) site plan	
46) Description of environment/outbuildings .	23) site plan	
46) Description of environment/outbuildings .	23) site plan	
46) Description of environment/outbuildings		
47) Information sources	24) changes -	
	24) changes - additions/alter-	store front has been
47) Information sources	24) changes - additions/alter- ations/moved	
47) Information sources	24) changes - additions/alter-	store front has been
47) Information sources	24) changes - additions/alter- ations/moved	store front has been oltered
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	store front has been oltered
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	store front has been oltered
47) Information sources Sanborn 1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	store front has been oltered
47) Information sources Sanborn 1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	store front has been oltered
47) Information sources Sanborn 1933	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	store front has been oltered
47) Information sources Sanborn 1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	store front has been oltered
47) Information sources Sanborn 1933  48) Location of negatives roll 17 #28	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	store front has been oltered
47) Information sources Sanborn 1933  48) Location of negatives roll 17 #28  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	store front has been oltered
47) Information sources Sanborn 1933  48) Location of negatives roll 17 #28	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	store front has been sltered
47) Information sources Sanborn 1933  48) Location of negatives roll 17 #28  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	store front has been sltered
47) Information sources Sanborn 1933  48) Location of negatives roll 17 #28  49) Prepared by DDD  50) Organization NET	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	store front has been oltered
47) Information sources Sanborn 1933  48) Location of negatives roll 17 #28  49) Prepared by DDD  50) Organization NOT	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	store front has been oltered
47) Information sources Sanborn 1933  48) Location of negatives roll 17 #28  49) Prepared by DDD  50) Organization NET	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica	store front has been oltered
47) Information sources Sanborn 1933  48) Location of negatives roll 17 #28  49) Prepared by DDD  50) Organization NOT	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district	store front has been oltered
47) Information sources Samborn 1933  48) Location of negatives roll 17 #28  49) Prepared by DDD  50) Organization NOT	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica	store front has been oltered
47) Information sources Samborn 1933  48) Location of negatives roll 17 #28  49) Prepared by DDD  50) Organization INT  ittached separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible?	store front has been altered  no  no
47) Information sources Samborn 1933  48) Location of negatives roll 17 #28  49) Prepared by DDD  50) Organization  httached separate sheets.	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential?	no no yes
47) Information sources Sanborn 1933  48) Location of negatives roll 17 #28  49) Prepared by DDD  50) Organization NOT	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential: 36) date	store front has been altered  no  no
47) Information sources Sanborn 1933  48) Location of negatives roll 17 #28  49) Prepared by DDD  50) Organization  Attached separate sheets.	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential?	no no yes
47) Information sources Samborn 1933  48) Location of negatives roll 17 #28  49) Prepared by DDD  50) Organization  httached separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential: 36) date	no no yes




### Missouri Historic Architectural Inventory for (4) 45-45-58 Division of Parks and Historic Preservation Department of Natural Resources

Division of Larks and Historia Licotration Depa		
38) Ownership — private	1) inventory number	7;=08
— public	2) name (cont)	
39) Owners — name	3) name - historial	
— address	4) street address	-A.G. a
	·	30 South ave.
40) Local contact	5) town or vicinity	Springfield
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county	Greene —
43) Other survey Used as a wholesale dry goods outlet	8) category	
for much of the nineteenth century. The	(site, structure,	1
	building, object)	building
building was associated with the Keet-	9) significance	
44) History Rountree Hercantile co. for most of its		500
history, and was probably built by that firm.	10) date	ca. 1682
• •	11) style	
	12) architect	
	13) builder	
	14) original use	commercial
	_	
	15) present use	commercial
45) Additional description	16) number of stories	2
Elaborate baroque brick work on the	17) plan shape	rectangle
patterned parapet. So also are the arched brick	18) basement	-
lintels for ing hoods over the window openings.	19) foundation	_
There are six bays. The second and fifth are	20) wall construction	
paired window openings with variant brick hoods		brick
	21) roof type -	flat
There are four over four light window sash.	material	
	22) contact print	
	35mm	
46) Description of environment/outbuildings	23) site plan	! ! ! ! ! ! ! ! ! ! ! ! ! ! ! ! ! ! ! !
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings		
46) Description of environment/outbuildings	23) site plan	
47) Information sources		storefront altered
47) Information sources	24) changes -	
47) Information sources	24) changes - additions/alterations/moved	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition	storefront altered
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	storefront altered
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	storefront altered
47) Information sources Sanborn 1884	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	storefront altered
47) Information sources Sanborn 1884	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	storefront altered
47) Information sources Sanborn 1884	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	storefront altered
47) Information sources Sanborn 1984  48) Location of negatives roll 17 #33	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	storefront altered
47) Information sources Sanborn 1884	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	storefront altered
47) Information sources  Sanborn 1884  48) Location of negatives roll 17 #33  49) Prepared by DDD	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	storefront altered
47) Information sources Sanborn 1984  48) Location of negatives roll 17 #33	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	storefront altered
47) Information sources  Sanborn 1884  48) Location of negatives roll 17 #33  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	storefront altered
47) Information sources Sanborn 1984  48) Location of negatives roll 17 #33  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	no
47) Information sources Sanborn 1984  48) Location of negatives roll 17 #33  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	no
47) Information sources Sanborn 1984  48) Location of negatives roll 17 #33  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	no
47) Information sources  Sanborn 1984  48) Location of negatives roll 17 #33  49) Prepared by DDD  50) Organization DET	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	no
47) Information sources  Sanborn 1984  48) Location of negatives roll 17 #33  49) Prepared by DDD  50) Organization DET	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district	no
47) Information sources  Sanborn 1984  48) Location of negatives roll 17 #33  49) Prepared by DDD  50) Organization DET	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible?	no no
47) Information sources  Sanborn 1884  48) Location of negatives roll 17 #33  49) Prepared by DDD  50) Organization INTER  If add  d separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential?	no no yes
47) Information sources  Sanborn 1884  48) Location of negatives roll 17 #33  49) Prepared by DDD  50) Organization LET	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential? 36) date	no no
47) Information sources  Sanborn 1884  48) Location of negatives roll 17 #33  49) Prepared by DDD  50) Organization INTER  If add  d separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential?	no no yes
47) Information sources  3 anborn 1884  48) Location of negatives roll 17 #33  49) Prepared by DDD  50) Organization CHT  If add  d separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential? 36) date	no no yes
47) Information sources  Sanborn 1884  48) Location of negatives roll 17 #33  49) Prepared by DDD  50) Organization INT  If add  d separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential? 36) date	no no yes



#### missouri mistoric Architectural Inventory for GR-A0-003-585 Division of Parks and Historic Preservation Department of Natural Resources

50. A			ient of Italuia	
38) Ownership — private	•		inventory number	11-99
— public		- 1	name (cont)	
39) Owners — name		1	name - historial	Rojers &Baldwin Co.
— address		1	street address	315 South ave.
40) Local contact		- 1	town or vicinity	Syringfield
41) Coordinates (UT	M)		legal description	
42) Quad			county	Greene
43) Other survey		8)	category	
			(site, structure,	building
	5 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 -		building, object)	
44) History Proba	bly built ca. 1890 after the organizat	t: 109)	significance	
of the Roge	rs and Baldwin Hardware Co. which	110)	oate	1886-1891
occupied t	he building for a nuber of years		style	
(the name	of the company sur vives on the sout!	1	architect	
elevation	painted near the roof)	1 1	builder	
	-		original use	corercial
AE) Additional discussion			present use	comercial
+5) Auditional description	n The modern metal front stands out *		number of stories	<i>l</i> <sub>1</sub> .
about two fe	et from the original facade which		plan shape	rectangle
	act beneath (except the first story)		basement	_
	ress metal cornice and entablature	,	foundation	stole
	corefront. The lintels of the window	1 -	wall construction	hrick
	car to be metal hoods.	21)	roof type -	Cl.:t
		201	material	
		[22)	contact print	
			35mm	
		1		
$\bigcirc$				
$\mathbf{O}$				
		-		
46) Description of anxion	and Alas Marriadia and	021		
46) Description of enviro	nment/outbuildings	23)	site plant	<del>╶</del> <del>╶┼┼┼┼┼┼┼┼┼</del> ┼┼
46) Description of enviro	nment/outbuildings	23)	site plan	
46) Description of enviro	nment/outbuildings	23)	site plan	
46) Description of enviro	nment/outbuildings	23)	site plan	
46) Description of enviro	nment/outbuildings	23)	site plan	
46) Description of environment 47) Information sources	Sanborn 1854 1886		changes -	storefront altered
			changes - additions/alter-	facade covered with
	Sanborn 1854 1886	24)	changes - additions/alter- ations/moved	1
	Sanborn 1854 1886 1902 1891	24)	changes - additions/alter- ations/moved condition	facade covered with
	Sanborn 1854 1886 1902 1891	24)	changes - additions/alter- ations/moved condition visible from road?	facade covered with
	Sanborn 1854 1886 1902 1891	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road? distance/frontage	facade covered with
47) Information sources	Sanborn 1854 1886 1902 1891 1933	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	facade covered with
	Sanborn 1854 1886 1902 1891 1933	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	facade covered with
47) Information sources  48) Location of negatives	Sanborn 1854 1886 1902 1891 1933	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	facade covered with
47) Information sources	Sanborn 1804 1886 1902 1891 1933	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	facade covered with
47) Information sources  48) Location of negatives  49) Prepared by	Sanborn 1854 1886 1902 1891 1933	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	facade covered with
47) Information sources  48) Location of negatives	Sanborn 1804 1886 1902 1891 1933 roll 17 #32 DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	facade covered with
48) Location of negatives 49) Prepared by 50) Organization	Sanborn 1804 1886 1902 1891 1933 roll 17 #32 DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	facade covered with
47) Information sources  48) Location of negatives  49) Prepared by	Sanborn 1804 1886 1902 1891 1933 roll 17 #32 DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	facade covered with
48) Location of negatives 49) Prepared by 50) Organization	Sanborn 1804 1886 1902 1891 1933 roll 17 #32 DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	facade covered with a modern cover
48) Location of negatives 49) Prepared by 50) Organization	Sanborn 1854 1886 1902 1891 1933 roll 17 #52 DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	facade covered with a modern cover
48) Location of negatives 49) Prepared by 50) Organization	Sanborn 1854 1886 1902 1891 1933 roll 17 #52 DDD	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	facade covered with a modern cover
48) Location of negatives 49) Prepared by 50) Organization	Sanborn 1854 1886 1902 1891 1933 roll 17 #52 DDD	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	facade covered with a modern cover
48) Location of negatives 49) Prepared by 50) Organization	Sanborn 1804 1886 1902 1891 1933  roll 17 #32 DDD 1.HT	24) 25) 26) 27) 28) 29) 30) 31) 32) 33, 34, 35,	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district ) is site eligible?	no  yes yes
48) Location of negatives 49) Prepared by 50) Organization	Sanborn 1804 1886 1902 1891 1933  roll 17 #32 DDD 1.HT	24) 25) 26) 27) 28) 29) 30) 31) 32) 33, 34, 35, 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district ) is site eligible? ) district potential?	no
48) Location of negatives 49) Prepared by 50) Organization	Sanborn 1804 1886 1902 1891 1933  roll 17 #32 DDD 1.HT	24) 25) 26) 27) 28) 29) 30) 31) 32) 33, 34, 35, 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	no  yes yes
48) Location of negatives 49) Prepared by 50) Organization	Sanborn 1804 1886 1902 1891 1933  roll 17 1/52 DDD 1.HT	24) 25) 26) 27) 28) 29) 30) 31) 32) 33, 34, 35, 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	no  yes yes



#### Missouri Historic Architectural Inventory for GR-AS-663-590Division of Parks and Historic Preservation Department of Natural Resources

Division of Parks and Historic Preservation Depa		
38) Ownership — private *		-100
— public	2) name (cont)	
39) Owners — name	3) name - historial	
address	4) street address	17 South ave.
40) Local contact	5) town or vicinity S	mingfield.
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county	reone
43) Other survey	8) category	
	(site, structure,	ud I di no
		uilding
Appears to be the same building present on	9) significance 10) date	
the first Scalern ins. co. map of 1884. Probably	11) style	ca. 1834
built shortly before that date. This building he	12) architect	
been a hardware outlet from that date to the	13) builder	
present.	, , , , , , ,	ountercial
<del>-</del>	-	oratercial
45) Additional description	16) number of stories 3	
45) Additional description Press letal projecting cornice is	-/	ectangle
intact. Jast iron window hoods over window	1	
openings with one over one light sash. The first	19) foundation	<del></del>
story storefront has a cast iron pilastered facade with press notal details and entablature.	laa	rick
The interior of the building survives intact with	laa. ——	1: t
cast iron superting columns and a press metal	material _	
cieling.	22) contact print	
	35mm	
	*	
$\cap$		
$\cup$		
	102) -:	<del> </del>
46) Description of environment/outbuildings	23) site plan	<del></del> <del>┆╎╎╎╎╎╎</del> ┼┼┼┼┼┼┼┼
46) Description of environment/outbuildings		
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings		
46) Description of environment/outbuildings		
47) Information sources		
47) Information sources Sanborn 1884		
47) Information sources	24) changes -	
47) Information sources Sanborn 1884	24) changes - additions/alter-	
47) Information sources Sanborn 1884	24) changes - additions/alterations/moved	
47) Information sources Sanborn 1884	24) changes - additions/alter- ations/moved 25) condition	
47) Information sources Sanborn 1884	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	
47) Information sources Sanborn 1884 1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	
47) Information sources Sanborn 1884 1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	
47) Information sources Sanborn 1884 1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	
47) Information sources Sanborn 1884 1933  48) Location of negatives roll 17 31  49) Prepared by Dab	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
47) Information sources Samborn 1884 1933  48) Location of negatives roll 17 31  49) Prepared by Dab	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	no
47) Information sources Sanborn 1884 1933  48) Location of negatives roll 17 31  49) Prepared by Dub	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	no
47) Information sources Sanborn 1884 1933  48) Location of negatives roll 17 31  49) Prepared by Dab	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	
47) Information sources  Samborn 1884 1933  48) Location of negatives roll 17 731  49) Prepared by Dob  50) Organization LET	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	no
47) Information sources Sanbern 1884 1933  48) Location of negatives roll 17 31  49) Prepared by Dab	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	
47) Information sources  Samborn 1884 1933  48) Location of negatives roll 17 731  49) Prepared by Dob  50) Organization LET	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	no
47) Information sources  Sanborn 1884 1933  48) Location of negatives roll 17 731  49) Prepared by  50) Organization  Ad. attached separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	no yes
47) Information sources  Samborn 1884 1933  48) Location of negatives roll 17 731  49) Prepared by Deb  50) Organization MIT	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	no yes yes
47) Information sources  Sanborn 1884 1933  48) Location of negatives roll 17 731  49) Prepared by DDD  50) Organization Attached separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	no
47) Information sources  Sanborn 1884 1933  48) Location of negatives roll 17 31  49) Prepared by DDD  50) Organization CATT	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	no yes yes
47) Information sources  Sanborn 1884 1933  48) Location of negatives roll 17 731  49) Prepared by DDD  50) Organization Attached separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	no yes yes



38) Ownership — private				
	. •	1	inventory number	];-101
— public		2)	name (cont)	
39) Owners — name		3)	name - historial	
address		4)	street address	701 CLl
(40) Local contact		1 .	town or vicinity	321 South ave
41) Coordinates (UTM)			, ,	Springfield
			legal description	
42) Quad			county	Greene
43) Other survey		8)	category	
		1	(site, structure,	hud I dan m
		1	building, object)	building
44) History had the between 1086	1 1 CO2 1 11 Tr 4		significance	
pulle permeen Tooc	and $1891$ by the Keet-		date	7006 - 0
Rountree dercantile co.	wholesalers.			1886 <b>-1891</b>
			style	
		12)	architect	
		13)	builder	
		14)	original use	commercial
			present use	commercial
45) Additional description Tuitenesting			number of stories	4
THOST GO GETTE	use of pressed brick .	1/		
to curve the window surrow	unds at the second and	1	plan shape	rectangle
third storys.		'	basement	
Two cast iron coffered pr	ilesters frame the	19)	foundation	
store front with the com		20)	wall construction	brick
Foundry Spring field No.	1200000000	21)	roof type -	flat
	hara hamani One wayid		material	<del></del>
The cornice has probably	been changed. The would	4 1	contact print	
expect a letal cornice.		- 1		
			35mm	
		1		
		1		
$\circ$				
46) Description of environment/outbuildings				
		23)	site plan	
		23)	site plan	
		23)	site plan	
	•	23)	site plan	
	·	23)	site plan	
47) Information sources Sa	nborn 1886		changes -	Appears to have lost
47) Information sources Sai	nborn 1886 1891			Appears to have lost the original cornice
47) Information sources Sal	nborn 1886 1891		changes -	the original cornice
47) Information sources Sal	nborn 1886 1891	24)	changes - additions/alter-	
47) Information sources Sal	nborn 1886 1891	24)	changes - additions/alterations/moved condition	the original cornice
47) Information sources Sal	nborn 1886 1891	24)	changes - additions/alter-ations/moved condition visible from road?	the original cornice
47) Information sources Sat	nborn 1886 1891	24) 25) 26) 27)	changes - additions/alter-ations/moved condition visible from road? distance/frontage	the original cornice
521	nborn 1886 1891	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	the original cornice
Sel	nborn 1886 1891	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	the original cornice
521	nborn 1886 1891	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	the original cornice
48) Location of negatives roll 17 330	nborn 1886 1891	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	the original cornice
48) Location of negatives roll 17 370	nborn 1886 1891	24) 25) 26) 27) 28) 29) 30)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	the original cornice
48) Location of negatives roll 17 30 49) Prepared by DDD	nborn 1886 1891	24) 25) 26) 27) 28) 29) 30)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	the original cornice
48) Location of negatives roll 17 330	nborn 1886 1891	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	the original cornice
48) Location of negatives roll 17 30 49) Prepared by DDD	nborn 1886 1891	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	the original cornice first story altered
48) Location of negatives roll 17 30 49) Prepared by DDD	nborn 1886 1891	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	the original cornice first story altered
48) Location of negatives roll 17 30 49) Prepared by DDD	nborn 1886 1891	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	the original cornice first story altered
48) Location of negatives roll 17 30 49) Prepared by DDD	1891 .	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	the original cornice first story altered
48) Location of negatives roll 17 330 49) Prepared by DDD 50) Organization THIT	1891 .	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	the original cornice first story altered
48) Location of negatives roll 17 330 49) Prepared by DDD 50) Organization THIT	1891 .	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	the original cornice first story altered
48) Location of negatives roll 17 330 49) Prepared by DDD 50) Organization THIT	1891 .	24) 25) 26) 27) 28) 29) 30) 31) 32) 33)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	the original cornice first story altered  no no
48) Location of negatives roll 17 330 49) Prepared by DDD 50) Organization THIT	1891 .	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	no no yes
48) Location of negatives roll 17 430 49) Prepared by DDD 50) Organization LHT	1891 . ets.	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35) 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	the original cornice first story altered  no no
48) Location of negatives roll 17 330 49) Prepared by DDD 50) Organization THIT	1891 . ets.	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35) 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	no no yes
48) Location of negatives roll 17 430 49) Prepared by DDD 50) Organization THT	1891 . ets.	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35) 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	no no yes



# Missouri Historic Architectural Inventory for 1912 A 3-003-592. Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership—private - public 2 name (cont) 39) Owners — name - address 40) Local contact 41) Coordinates (UTM) 50 Local contact 41) Coordinates (UTM) 60 legal description 70 county 61 County 61 County 61 County 62) County 62) County 62) County 63) Other survey 63) Category (site, structure, building, object) 64) History 64) Local contact above and cigar factory on the second as a local above and cigar factory on the second 61 County 62 County 63 County 64) Additional description 62 County 64) Additional description 63 County 64 County 64 County 64 County 64 County 65 County 64 County 65
39) Owners—name —address —40) Local contact 41) Coordinates (UTM) 42) Quad 51) Other survey  44) History  built between 1036 and 1091 and used as a least abore and cigar factory on the second floor.  45) Additional description Simple patterned and banded brich entablature beneath the paraget. Round aroned window openings with two over two light window sash. A small portion of what light have been the original first story press letal facade survives below the second story wandow level.  325 South ave 327 South ave 327 South ave 327 South ave 328 South ave 327 South ave 328 South ave 328 South ave 329 South ave 329 South ave 320 South ave 321 South ave 321 South ave 325 South ave 327 South ave 328 South ave 327 South ave 328 South ave 328 South ave 329 South ave 320 South ave 321 South ave 3221 South ave 3221 South ave 323 South ave 323 South ave 325 South ave 321 South ave 321 South ave 321 South ave 3221 South ave 321 South ave 3221 South ave 3221 South ave 323 South ave 325 South ave 326 South ave 327 South
-address  40) Local contact  41) Coordinates (UTM)  42) Quad  77 county  43) Other survey  44) History  built between 1886 and 1891 and used as a least after and cigar factory on the second floor.  45) Additional description  Rounc arcaed window openings with two over two light window sach. A small portion of what light have been the original first story press setal facade survives below the second story wandow level.  47) Street address  55) town or vicinity  66 legal description  77 county  Graene  325 South eve 3 arringfield  326 South eve 3 arringfield  326 South eve 3 arringfield  327 contents  328 South eve 3 arringfield  329 arringfield  329 arringfield  320 category  (site, structure, building building, object)  9 significance  10) date  11) style  12) architect  13) builder  14) original use 15) present use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print 35mm
40) Local contact 41) Coordinates (UTM) 42) Quad 55) town or vicinity 66) legal description 77) county 88) category (site, structure, building, object) 44) History 44) History  44) History  44) History  45) Additional description  45) Additional description  45) Additional description  45) Additional description  46) Additional description  47) Additional description  48) Category (site, structure, building)  49) significance 10) date 11) style 12) architect 13) builder 14) original use 15) present use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print 35mm
44) Coordinates (UTM) 42) Quad 70 county 43) Other survey  44) History  built between 1000 and 1091 and used     as a sent store and cigar factory on the second floor.  45) Additional description  From the parapet.  Round absolute beneath the parapet.  Round absolute be
41) Coordinates (UTM) 12) Quad 13) Other survey  8) category (site, structure, building, object)  44) History  built between 1886 and 1891 and used as a seat store and cigar factory on the second floor.  45) Additional description Simple patterned and banded brick entablature beneath the parapet. Round anched window openings with two over two light window sach. A small portion of what hight have been the original first story press setal facade survives below the second story wandow level.  6) legal description 7; county 6; county 6; deep duilding building
43) Other survey  (site, structure, building, object)  built between 1886 and 1891 and used
3) Other survey  (3) Other survey  (3) Category (site, structure, building, object)  (4) History  (5) Significance (10) date (11) style (12) architect (13) builder (14) original use (15) present use (17) plan shape (17) plan shape (18) Sament (19) sament (19) sament (19) plan shape (19) rectangle (19) rectangle (19) rectangle (19) sament (19) plan shape (19) sament (19) plan shape (19) sament (19) plan shape (19) plan shape (19) sament (19) plan shape (19) plan shape (19) sament (19) plan shape (19) plan shape (19) sament (19) plan shape (10) sament (1
built between 1886 and 1891 and used as a leaf after and cigar factory on the second floor.    1886-1891
built between 1886 and 1891 and used as a seat store and cigar factory on the second floor.  10) date 11) style 12) architect 13) builder 14) original use 15) Additional description Simple patterned and banded brick entablature beneath the parapet. Round acceded window openings with two over two light window sash. A small portion of what might have been the original first story press metal facade survives below the second story window level.  16) Nadditional description Simple patterned and banded 17) plan shape 18) basement 19) foundation 20) wall construction 21) order of type-material 22) contact print 35mm
built between 1000 and 1091 and used as a leaf afore and cigar factory on the second floor.  10) date style 11) style 12) architect 13) builder 14) original use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 20) wall construction 21) roof type- material 22) contact print 35mm
built between 1000 and 1091 and used as a seat after and cigar factory on the second floor.  10) date 11) style 12) architect 13) builder 14) original use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 10) date 11) style 12) architect 13) builder 14) original use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 20) wall construction 21) roof type- material 22) contact print 35mm
as a seat after and digar factory on the second floor.
#5) Additional description Simple patterned and banded brich entablature beneath the parapet.  Round arched window openings with two over two light window sash. A small portion of what hight have been the original first story press setal facade survives below the second story window level.  12) architect 13) builder 14) original use 15) presentuse contercial 15) presentuse 15) presentuse 16) number of stories 2 17) plan shape 18) basement 19) foundation 20) wall construction 21) foundation 20) wall construction 21) roof type material 22) contact print 35mm
13) builder   14) original use   contact cial   15) present use   contact cial   15) present use   contact cial   16) number of stories   2   17) plan shape   18) basement   19) foundation   19) foundation   20) wall construction   20) wall construction   20) wall construction   21) roof type-material   22) contact print   35mm
Additional description Simple patterned and banded brich entablature beneath the parapet.  Round anched window openings with two over two light window sash. A small portion of what hight have been the original first story press metal facade survives below the second story wandow level.  16) number of stories 2 17) plan shape rectangle 18) basement 19) foundation 20) wall construction brick 21) roof typematerial 22) contact print 35mm
45) Additional description Simple patterned and banded brich entablature beneath the parapet. Round anched window openings with two over two light window sash. A small portion of what might have been the original first story press metal facade survives below the second story wandow level.  15) presentuse condercial  16) number of stories 2  17) plan shape 18) basement 19) foundation 20) wall construction brick 21) roof typematerial 22) contact print 35mm
brich entablature beneath the parapet. Round anched window openings with two over two light window sash. A small portion of what might have been the original first story press metal facade survives below the second story window level.  16) number of stories 2 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type material 22) contact print 35mm
brich entablature beneath the parapet. Round anched window openings with two over two light window sash. A small portion of what hight have been the original first story press metal facade survives below the second story window level.  17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type material 21) roof type material 22) contact print 35mm
Round anched window openings with two over two light window sash. A small portion of what might have been the original first story press metal facade survives below the second story window level.  18) basement 19) foundation 20) wall construction 21) roof type-material 22) contact print 35mm
two light window sash. A small portion of what hight have been the original first story press metal facade survives below the second story window level.    19
what hight have been the original first story press metal facade survives below the second story window level.  20) wall construction brick 21) roof type-material 22) contact print 35mm
press Letel facade survives below the second story window level.  21) roof type-material 22) contact print 35mm
story window level.    Title   Second
22) contact print 35mm
35mm
207 Steephan of environmendoutbandings
<del>╒╃┋╃┋┋┍┋╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒</del>
47) Information sources 24) changes -
Sanborn 1886 additions/alter-
1891 ations/moved extensively al
ations/moved
25) condition 26) visible from road?
26) Visible from road?
48) Location of negatives 22 and 23 (20) 29) preservation
roll 17 %29
underway?  49) Prepared by  30) endangered?
49) Prepared by DDD 30) endangered?
Of Organization 17th
32) part of
actablished
established historical district
historical district no
historical district attached separate sheets.  historical district 33) name of historical
historical district  attached separate sheets.  33) name of historical district
historical district  attached separate sheets.  33) name of historical district  district  34) is site eligible?
historical district  33) name of historical district  34) is site eligible?  35) district potential?
historical district  33) name of historical district  34) is site eligible?  35) district potential?  36) date
historical district  33) name of historical district  34) is site eligible?  35) district potential?




# Missouri Historic Architectural Inventory for Ge 3-003-593 Division of Parks and Historic Preservation Department of Natural Resources

## 10 inventory number   1.136   2.136	
39) Owners—name   3) name-historial	
-address	
40) Local contact 41) Coordinates (UTM)  42) Quad  7) county  8) category (site, structure, building, object)  44) History  9) significance 10) date 11) style 11) style 12) architect 13) builder 14) original use 15) present use	
41) Coordinates (UTM)  42) Quad  7) county  8) category (site, structure, building object)  44) History  9) significance 10) date 11) style 12) architect 13) builder 14) original use 15) present use  6) legal description  7 county  6 poole  7 county  7 county  6 poole  7 county  8 category (site, structure, building  9 significance 10) date 11) style 12) architect 13) builder 14) original use 15) present use	
42) Quad   7) county   Gracue	11.0
## 8) category  (site, structure, building building building object)  ### 44) History  ### 9 significance  10) date  11) style  12) architect  13) builder  14) original use  15) present use  #### 130 to the property of the	1,0
(site, structure, building building building building building building building building building 9) significance 10) date da. 1920 11) style 12) architect 13) builder 13) builder 14) original use convene 15) present use convene	1
building, object)	
Suilding, object)	
10) date	
10) date	
11) style 12) architect 13) builder 14) original use	
12) architect 13) builder 14) original use cannot e	
13) builder 14) original use converge 15) present use converge	
14) original use control of the cont	
15) present use <u>ຕະດາຕຸອ</u>	
AE) Additional description [16] number of stories [17]	
1.	
17) plan shape i poull or	
18) basement	
19) foundation concrete	
20) wall construction brills	
21) roof type-	
material	
22) contact print	
35mm	1
46) Description of environment/outbuildings  23) site plan	
47) Information sources 24) changes - this is only	a
jankown 1933 additions/after-	
ations/moved huilding	
25) condition	
26) visible from road?	
27) distance/frontage	
28) accessible?	
48) Location of negatives 29) preservation	
roll 86 #41	
49) Prepared by 30) endangered?	
31) on National	
50) Organization Register?	
32) part of	
32) part of established no	
32) part of established historical district	
32) part of established no	
32) part of established historical district	
If additional state of the sheets.  32) part of established historical district  33) name of historical district	
If additional set to the sheets.  32) part of established historical district  33) name of historical district  34) is site eligible?	
If additional state of the sheets.  32) part of established historical district  33) name of historical district  34) is site eligible?  35) district potential?	
If additional state of the sheets.  32) part of established historical district  33) name of historical district  34) is site eligible?  35) district potential?  36) date  4/18134	
If additional state of the sheets.  32) part of established historical district  33) name of historical district  34) is site eligible?  35) district potential?	
If additional setablished historical district  33) name of historical district  34) is site eligible?  35) district potential?  36) date  37) part of established historical district  33) name of historical district  34) is site eligible?  35) district potential?	



# Missouri Historic Architectural Inventory for GRASSOURCES - 594 Division of Parks and Historic Preservation Department of Natural Resources

	DIVISION OF LARKS AND THIS COIL FLESCIVATION DE	_	
38) Ownership — private		1) inventory number	11-165
— public		2) name (cont)	
39) Owners — name		3) name - historial	
— address		4) street address	525 E.Tanpa st.
(40) Local contact		5) town or vicinity	Springfield
41) Coordinates (UT!	M)	6) legal description	
42) Quad		7) county	Greene
43) Other survey		8) category	4100110
•		(site, structure,	book 1 24 mm
		\ \ \ \ \ \	building
AA) Water		building, object)	
44) History	et in the 1920s by the City Ice co.	9) significance	
U QL. I	to the the typos sy one off, for co.	10) date	<u>ca. 1915</u>
		11) style	
		12) architect	
		13) builder	
		14) original use	comercial
		15) present use	
45) Additional description	n	16) number of stories	_co_coroial
is, riadicional description	,		1
		17) plan shape	rectangle
		18) basement	
		19) foundation	_corote
		20) wall construction	concrete block
		21) roof type -	firt
	•	material	
		22) contact print	
		35mm	
		·	
$\bigcirc$		(	
$\bigcirc$			
46) Description of enviro	nment/outbuildings	23) site plan	
			<del>┤┊┆┊┧┧</del> ╁ <del>╏╏</del> ╁╂╁╂╂
		\ <del>-\-\-\-\-\-\-\-\-\-\-\-\-\-\-\-\-\-\-</del>	<del>·</del> ┆ <del>╎╎╎╽</del> ┪ <del>┆┆┥┩╏</del> ┆
			<del>╶╎╶╎╎╎╎╎</del> ┪ <del>╡╏</del> ┪╇╇╇╇╇╇╇
47) Information sources		24) changes -	
477 Injoination sources	Sanborn 1933	_	
	Denoorn roof	additions/alter-	
		ations/moved	
		25) condition	
		26) visible from road?	
		27) distance/frontage	
		28) accessible?	
48) Location of negatives	37.06.00	29) preservation	
· ·	roll 86 #2-3	underway?	
49) Prepared by		30) endangered?	<del></del>
,pa	DDD	31) on National	
50) Organization	• ***( <b>n</b>		
50) Organization	1.11T	Register?	110
		32) part of	
	· ·	established	no
with the second		historical district	
If additional s	and realized	33) name of historical	
	1200	district	
		34) is site eligible?	no
		<ul><li>34) is site eligible?</li><li>35) district potential?</li></ul>	no
		_	no
		35) district potential?	
		35) district potential? 36) date	no





# Missouri Historic Architectural Inventory for Gradule 595 Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private •	1)	inventory number	11-162
— public	1	name (cont)	L-106
•	1		salle
39) Owners — name	3)	name - historial	
— address	1		Gibson Pres. Chapel
_	4)	street address	536 E. Tampa st.
40) Local contact	5)	town or vicinity	
41) Coordinates (UTM)	1	~	Springfield
41) Coordinates (UTM)	6)	legal description	
42) Quad	7)	county	
43) Other survey			Greene
Sorin field local historic site	B)	category	
- Control of the Cont		(site, structure,	
ite has been desi nated as being elected in the land of the land register.	l		
all home for nebboral regulator.		building, object)	building
44) History built by one of the first black congregation	5 9)	significance	
		date	1005
in Springfield	110)	date	1891
	11)	style	church gothic
	121	architect	
	1		
	13)	builder	
·	141	original use	
	1	-	church
	15)	present use	church
45) Additional description			
45) Additional description Right pitch gable roof with limestone	1.07		
coping. There are stone caps on engaged wall	17)	plan shape	rectangle
		basement	
buttresses on the side ellivations. Between the	1		full
buttresses are othic point arched window opening	Ų9)	foundation	stone
	. [ 1	wall construction	
with one over one light sash. On the main	1 '		brick
facade is a large window opening with a gothic	[21]	roof type -	able
		material	
point arch Tilled with laced muntins. Entrance	221		asphalt
projects all htly with arched entry area. Tower	(22)	contact print	
		35mm	
on the morthe st commer has round arched window			-
openings. Ord inally the tower had a tall	1		
•	1		
steeple which was lost in a fire.			
( )			
46) Description of environment/outbuildings	23)	site plan!	1
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan!	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings			
46) Description of environment/outbuildings  47) Information sources information from historic site board			building has gone
47) Information sources information from historic site board		changes -	building has gone
		changes - additions/alter-	building has gone through many
47) Information sources information from historic site board		changes -	building has gone
47) Information sources information from historic site board	24)	changes - additions/alter-	building has gone through many changes
47) Information sources information from historic site board	24)	changes - additions/alter- ations/moved condition	building has gone through many changes
47) Information sources information from historic site board	24)	changes - additions/alter- ations/moved condition visible from road?	building has gone through many changes
47) Information sources information from historic site board	24)	changes - additions/alter- ations/moved condition	building has gone through many changes
47) Information sources information from historic site board	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road? distance/frontage	building has gone through many changes
47) Information sources in Cormation from historic site board files.	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	building has gone through many changes
47) Information sources information from historic site board	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage	building has gone through many changes
47) Information sources in Cormation from historic site board files.	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	building has gone through many changes
47) Information sources information from historic site board files.  48) Location of negatives roll 5 #10-10	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	building has gone through many changes
47) Information sources in Cormation from historic site board files.	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	building has gone through many changes
47) Information sources information from historic site board files.  48) Location of negatives roll 5 #10-10	24) 25) 26) 27) 28) 29) 30)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	building has gone through many changes good
<ul> <li>47) Information sources in formation from historic site board files.</li> <li>48) Location of negatives roll 5 #10-18</li> <li>49) Prepared by DDD</li> </ul>	24) 25) 26) 27) 28) 29) 30)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	building has gone through many changes rood
47) Information sources information from historic site board files.  48) Location of negatives roll 5 #10-10	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	building has gone through many changes good
<ul> <li>47) Information sources in formation from historic site board files.</li> <li>48) Location of negatives roll 5 #10-18</li> <li>49) Prepared by DDD</li> </ul>	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	building has gone through many changes rood
<ul> <li>47) Information sources in formation from historic site board files.</li> <li>48) Location of negatives roll 5 #10-18</li> <li>49) Prepared by DDD</li> </ul>	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	building has gone through many changes rood
<ul> <li>47) Information sources in Formation from historic site board files.</li> <li>48) Location of negatives roll 5 #10-18</li> <li>49) Prepared by DDD</li> </ul>	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	ouilding has gone through many changes rood no
47) Information sources information from historic site board files.  48) Location of negatives roll 5 #16-16  49) Prepared by DDD  50) Organization NAT	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	building has gone through many changes rood
<ul> <li>47) Information sources in Formation from historic site board files.</li> <li>48) Location of negatives roll 5 #10-18</li> <li>49) Prepared by DDD</li> </ul>	25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	no no
47) Information sources information from historic site board files.  48) Location of negatives roll 5 #16-16  49) Prepared by DDD  50) Organization NAT	25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	no no
47) Information sources information from historic site board files.  48) Location of negatives roll 5 #16-16  49) Prepared by DDD  50) Organization NAT	24) 25) 26) 27) 28) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	no no
47) Information sources information from historic site board files.  48) Location of negatives roll 5 #16-16  49) Prepared by DDD  50) Organization NAT	24) 25) 26) 27) 28) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	no
47) Information sources information from historic site board files.  48) Location of negatives roll 5 #16-16  49) Prepared by DDD  50) Organization NAT	24) 25) 26) 27) 28) 29) 30) 31) 32) 33,	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district ) is site eligible?	no no yes
47) Information sources in Formation from historic site board files.  48) Location of negatives roll 5 #16-16  49) Prepared by DDD  50) Organization NLT	24) 25) 26) 27) 28) 29) 30) 31) 32) 34, 35,	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	no no yes no
47) Information sources in Formation from historic site board files.  48) Location of negatives roll 5 #10-10  49) Prepared by DDD  50) Organization NAT	24) 25) 26) 27) 28) 29) 30) 31) 32) 34, 35, 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	no no yes
47) Information sources in Formation from historic site board files.  48) Location of negatives roll 5 #10-10  49) Prepared by DDD  50) Organization NAT	24) 25) 26) 27) 28) 29) 30) 31) 32) 34, 35, 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	no no yes no
47) Information sources information from historic site board files.  48) Location of negatives roll 5 #10-10  49) Prepared by DDD  50) Organization NLT	24) 25) 26) 27) 28) 29) 30) 31) 32) 34, 35, 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	no no yes no
47) Information sources information from historic site board files.  48) Location of negatives roll 5 #10-10  49) Prepared by DDD  50) Organization NAT	24) 25) 26) 27) 28) 29) 30) 31) 32) 34, 35, 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	no no yes no
47) Information sources information from historic site board files.  48) Location of negatives roll 5 #10-10  49) Prepared by DDD  50) Organization NLT	24) 25) 26) 27) 28) 29) 30) 31) 32) 34, 35, 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	no no yes no





### Missouri Historic Architectural Inventory for State Control of Parks and Historic Preservation Department of Natural Resources

			<u> </u>	
38) Ownership — private			inventory number	N=3
— public		1	name (cont)	
39) Owners — name		3)	name - historial	
— address		4)	street address	E. Walnut st.
40) Local contact		5)	town or vicinity	Springfield
41) Coordinates (UTA	4)		legal description	1 - 10 - 1
42) Quad	,,		county	Creene
-				
43) Other survey		87	category	
			(site, structure,	building
		1	building, object)	
44) History		9)	significance	
		10)	date	ca. 1915
		11)	style	
			architect	
			builder	
		- 1	original use	commercial
			present use	commercial
45) Additional description	Simple banded brick entablature	- 1	number of stories	2
halow the f	let sapapet. There are brick	17)	plan shape	rectangle
	roles above the flat window openings.	18)	basement	
relleving a	Lower from the true will and the Lucian obedings.	19)	foundation	
	plant to be of stone. One large	1	wall construction	1
	supports the second story facade	1 '	roof type -	bric'
above the	storefront. This may be original	(21)		27.4t
			material	
		22)	contact print 35mm	
Ο.				
46) Description of enviro	oment/outhuildings	231	site plan	
40) Description of chimo	minerit/outpunumgs	20,	Site plan	<del>┡</del> ╶┞ <del>╸╽</del> ╶ <del>╏╶╽╶╽</del> ╶╂ <del>╸┨</del> ╾╂ <del>╸╏╸╏╸╏╸╏╸</del> ┼
		1.1	1 1 1 1 1 1 1 1	
		+		
47) Information sources	·			
47) Information sources	· · · · · · · · · · · · · · · · · · ·			storefront altered
47) Information sources			changes -	
47) Information sources	· · · · · · · · · · · · · · · · · · ·	24)	changes - additions/alter-ations/moved	
47) Information sources	·	24)	changes - additions/alter- ations/moved condition	storefront altered
47) Information sources	·	24) 25) 26)	changes - additions/alter- ations/moved condition visible from road?	storefront altered
47) Information sources		24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road? distance/frontage	storefront altered
	<u>.</u>	25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	storefront altered
47) Information sources  48) Location of negatives	roll 1 ½27	25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	storefront altered
48) Location of negatives	roll 1 #27	25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	storefront altered
	roll 1 #27	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	storefront altered
48) Location of negatives	roll 1 #27 DuD	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	storefront altered
48) Location of negatives	roll 1 #27	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	storefront altered
48) Location of negatives 49) Prepared by	DUD .	24) 25) 26) 27) 28) 29) 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	storefront altered
48) Location of negatives 49) Prepared by	DUD .	24) 25) 26) 27) 28) 29) 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	storefront altered
48) Location of negatives 49) Prepared by	DUD .	24) 25) 26) 27) 28) 29) 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	storefront altered
48) Location of negatives 49) Prepared by	DDD MHT	25) 26) 27) 28) 29) 30) 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	storefront altered
48) Location of negatives 49) Prepared by	DUD .	25) 26) 27) 28) 29) 30) 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica	storefront altered
48) Location of negatives 49) Prepared by	DDD MHT	24) 25) 26) 27) 28) 30 31 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district oname of historical district	storefront altered
48) Location of negatives 49) Prepared by	DDD MHT	24) 25) 26) 27) 28) 30 31 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible?	storefront altered
48) Location of negatives 49) Prepared by	DDD MHT	24) 25) 26) 27) 28 29) 30 31 32 33 344 35	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible? ) district potential	storefront altered
48) Location of negatives 49) Prepared by	DDD MHT	24) 25) 26) 27) 28 29) 30 31 32 33 34 35 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential: date	storefront altered
48) Location of negatives 49) Prepared by	DDD PHT ttached separate sheets.	24) 25) 26) 27) 28 29) 30 31 32 33 34 35 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible? ) district potential	storefront altered
48) Location of negatives 49) Prepared by	DDD PHT ttached separate sheets.	24) 25) 26) 27) 28 29) 30 31 32 33 34 35 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential: date	storefront altered
48) Location of negatives 49) Prepared by	DDD PHT ttached separate sheets.	24) 25) 26) 27) 28 29) 30 31 32 33 34 35 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential: date	storefront altered



Missouri Historic Architectural Inventory for Communication Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private *	1)	inventory number	1:-103
— public	2)	name (cont)	
39) Owners — name	3)	name - historial	
— address	4)	street address	209-11 E.Walnut st.
40) Local contact	5)	town or vicinity	
41) Coordinates (UTM)	1	legal description	Oprinefield
42) Quad	1	county	_
43) Other survey		category	Greene
ray outer adverg	",	(site, structure,	
		building, object)	building
44) History	91	significance	
77, (113tory	1	date	ca. 1910
		style	5d 1910
		-	
		architect	
		builder	
	1	original use	connercial
		present use	co.mercial
45) Additional description Flat paraget with a simple patterne	(16)	number of stories	
entablature. There appear to be stone lintels	17)	plan shape	rectangle
and sills at the second story window openings.	1 1	basement	
	1 .	foundation	-
		wall construction	brick
	21)	roof type -	flat
•		material	
	22)	contact print	
		35mm	<b> </b>
( )			
46) Description of environment/outbuildings	23	site plan	
46) Description of environment/outbuildings	23	) site plan	
46) Description of environment/outbuildings	23	site plan	
46) Description of environment/outbuildings	23	) site plan	
46) Description of environment/outbuildings	23)	) site plan	
46) Description of environment/outbuildings	23)		
46) Description of environment/outbuildings  47) Information sources Sanborn 1933		) changes -	store front altered
		changes - additions/alter-	store front altered
	24	changes - additions/alter- ations/moved	store front altered
	24	) changes - additions/alter- ations/moved ) condition	
	24	changes - additions/alter- ations/moved ) condition ) visible from road?	
	24 25 26 27	changes - additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage	
47) Information sources Sanborn 1933	24 25 26 27 28	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	
	24 25 26 27 28	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	
47) Information sources Samborn 1933  48) Location of negatives roll 101 #23	24 25 26 27 28 29	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	
47) Information sources Samborn 1933  48) Location of negatives roll 101 #23  49) Prepared by DDD	24 25 26 27 28 29 30	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	
47) Information sources Samborn 1933  48) Location of negatives roll 101 #23  49) Prepared by DDD  11 T	24 25 26 27 28 29 30	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	
47) Information sources Samborn 1933  48) Location of negatives roll 101 #23  49) Prepared by DDD	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? underway? on National Register?	
47) Information sources Samborn 1933  48) Location of negatives roll 101 #23  49) Prepared by DDD  11 T	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	
47) Information sources Samborn 1933  48) Location of negatives roll 101 #23  49) Prepared by DDD  1117  50) Organization	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	n:
48) Location of negatives roll 101 #23  49) Prepared by DDD  11 T	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	n:)
47) Information sources Samborn 1933  48) Location of negatives roll 101 #23  49) Prepared by DDD  1117  50) Organization	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? endangered? ) on National Register? part of established historical district name of historica	n:)
48) Location of negatives roll 101 #23  49) Prepared by DDD  11 T	24 25 26 27 28 29 30 31 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district	no no
48) Location of negatives roll 101 #23  49) Prepared by DDD  117  50) Organization	24 25 26 27 28 29 30 31 32 33	changes - additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? !) part of established historical district so name of historical district is site eligible?	no no
47) Information sources Sanborn 1933  48) Location of negatives roll 101 #23  49) Prepared by DDD  11 T  50) Organization	24 25 26 27 28 29 30 31 32 33 34 35	changes - additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established historical district name of historica district is site eligible? district potential	no no no yes
48) Location of negatives roll 101 #23  49) Prepared by DDD  111  50) Organization  3ched separate sheets.	24 25 26 27 28 29 30 31 32 33 34 35 36	changes - additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? endangered? ) on National Register? part of established historical district name of historica district is site eligible? district potential	no no
47) Information sources  Sanborn 1933  48) Location of negatives roll 101 #23  49) Prepared by DDD  11 T  3ched separate sheets.	24 25 26 27 28 29 30 31 32 33 34 35 36	changes - additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established historical district name of historica district is site eligible? district potential	no no no yes
47) Information sources Sanborn 1933  48) Location of negatives roll 101 #23  49) Prepared by DDD  11 T  50) Organization	24 25 26 27 28 29 30 31 32 33 34 35 36	changes - additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? endangered? ) on National Register? part of established historical district name of historica district is site eligible? district potential	no no no yes



### Missouri Historic Architectural Inventory for $G_R \approx 598$ Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — privat	e	* 1)	inventory number	N-184
— pubii		2)	name (cont)	
39) Owners — name		3)	name - historial	
- address		4)	street address	24 12 11 2 4
40) Local contact				21 E. Walnut st.
( ) '	T. 41		town or vicinity	Springfield
41) Coordinates (U	im)		legal description	
42) Quad		7)	county	Greene
43) Other survey	<del></del>	8)	category	
•			(site, structure,	
				building
	<u> </u>		building, object)	
44) History		(9)	significance	1
		10)	date	-cc- 1910
		111)	style	
			architect	
			builder	
		14)	original use	comercial
		15)	present use	vacant
45) Additional descript	on	• 16)	number of stories	2
	flat parapet. Probably this buildi	n [ 1.7)	nlan chang	1
had a rotal	l cornice as the area beneath the			rectangle
			basement	<u>-</u>
	s totally unadorned. The lintels ove	<sup>1</sup>  19)	foundation	_
	d story window openings appear to be	20)	wall construction	brick
stone as	are the sills.	- 1	roof type -	flat
		,	material	
		201		-
		(22)	contact print	
			35mm	
		1	•	
		ļ		
$\bigcirc$		-		
,				
46) Description of envi	20 m a a 4/a . 4 h i I d i m a a			<del></del>
	ronnent/outpulidings	23)	site plan	
, 50001.p.	ronnengoutbundings	23)	site plan	<del>╎┦┪┩╏╏┩</del>
	ronment/outbuttaings	23)	site plan	
	ronment/outbuttaings	23)	site plan	
	ronment/outbuttaings	23)	site plan	
·	ronment/outbuttaings	23)	site plan	
·	ronment/outbuttaings			
				T
47) Information source	s		changes -	storefront altered
			changes - additions/alter-	T
	s	24)	changes - additions/alterations/moved	storefront altered
	s	24)	changes - additions/alter-	storefront altered
	s	24)	changes - additions/alterations/moved	storefront altered windows blocked in
	s	24)	changes - additions/alter- ations/moved condition visible from road	storefront altered windows blocked in
	S	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road: distance/frontage	storefront altered windows blocked in
47) Information source	s Sanborn 1933	24) 25) 26) 27) 28	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	storefront altered windows blocked in
	s Sanborn 1933	24) 25) 26) 27) 28	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	storefront altered windows blocked in
47) Information source 48) Location of negative	s Sanborn 1933	24) 25) 26, 27, 28	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	storefront altered windows blocked in
47) Information source	s Sanborn 1933 es roll 101 #24	24) 25) 26, 27, 28	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	storefront altered windows blocked in
47) Information source 48) Location of negative	s Sanborn 1933	24) 25) 26) 27) 28 29	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	storefront altered windows blocked in
47) Information source 48) Location of negative 49) Prepared by	s Sanborn 1933  es roll 101 #24  DDD	24) 25) 26) 27) 28 29	changes - additions/alter- ations/moved condition visible from road: distance/frontage accessible? preservation underway? endangered? on National	storefront altered windows blocked in
47) Information source 48) Location of negative	s Sanborn 1933 es roll 101 #24	24) 25) 26) 27) 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	storefront altered windows blocked in
47) Information source 48) Location of negative 49) Prepared by	s Sanborn 1933  es roll 101 #24  DDD	24) 25) 26) 27) 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	storefront altered windows blocked in
47) Information source 48) Location of negative 49) Prepared by	s Sanborn 1933  es roll 101 #24  DDD	24) 25) 26) 27) 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	storefront altered windows blocked in no no
47) Information source 48) Location of negative 49) Prepared by	s Sanborn 1933  es roll 101 #24  DDD	24) 25) 26) 27) 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	storefront altered windows blocked in no no
47) Information source 48) Location of negative 49) Prepared by	s Sanborn 1933  es roll 101 #24  DDD	24) 25) 26) 27) 28 29 30 31 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	storefront altered windows blocked in no no
47) Information source 48) Location of negative 49) Prepared by	s Sanborn 1933  es roll 101 #24  DDD T	24) 25) 26) 27) 28 29 30 31 32	changes - additions/alter- ations/moved condition visible from road: distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica	storefront altered windows blocked in no no
47) Information source 48) Location of negative 49) Prepared by	s Sanborn 1933  es roll 101 #24  DDD T	24) 25) 26) 27) 28 29 30 31 32	changes - additions/alter- ations/moved condition visible from road: distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district district	storefront altered windows blocked in no no
47) Information source 48) Location of negative 49) Prepared by	s Sanborn 1933  es roll 101 #24  DDD T	24) 25) 26) 27) 28 29 30 31 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible?	storefront altered windows blocked in no no no
47) Information source 48) Location of negative 49) Prepared by	s Sanborn 1933  es roll 101 #24  DDD T	24) 25) 26) 27) 28 29 30 31 32 33 34 35	changes - additions/alter- ations/moved condition visible from road: distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible?	storefront altered windows blocked in no no yes
47) Information source 48) Location of negative 49) Prepared by	s Sanborn 1933  es roll 101 #24  DDD T	24) 25) 26) 27) 28 29 30 31 32 33 34 35	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible?	storefront altered windows blocked in no no no
47) Information source 48) Location of negative 49) Prepared by	s Sanborn 1933  es roll 101 #24  DDD T	24) 25) 26) 27) 28 29 30 31 32 33 34 35 36	changes - additions/alter- ations/moved condition visible from road: distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible?	storefront altered windows blocked in no no yes
47) Information source 48) Location of negative 49) Prepared by	s Sanborn 1933  es roll 101 #24  DDD T	24) 25) 26) 27) 28 29 30 31 32 33 34 35 36	changes - additions/alter- ations/moved condition visible from road: distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential date	storefront altered windows blocked in no no yes
47) Information source 48) Location of negative 49) Prepared by	s Sanborn 1933  es roll 101 #24  DDD T	24) 25) 26) 27) 28 29 30 31 32 33 34 35 36	changes - additions/alter- ations/moved condition visible from road: distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential date	storefront altered windows blocked in no no yes



# Missouri Historic Architectural Inventory for Carlo Ca

38) Ownership — private	* 1) inventory number \ \ \frac{1}{2}
public	2) name (acat)
·	5a. C
39) Owners — name	3) name-historial linconic Temple
— address	A\ . A   1   1
40) Local contact	201-0/ La Walnut St
	5) town or vicinity Springfield
41) Coordinates (UTM)	6) legal description
42) Quad	7) county
	intene
43) Other survey	8) category
	(site, structure, but I do no
	I DULIGINO
	building, object)
44) History	9) significance
Between the third and fourth story there	
is a centered panel of terra-cotta-bright	
	11) style
brick red-with the words: Masonic Temple.	12) architect
	13) builder
	14) original use lodge and commercia
	15) present use same
45) Additional description Flat parapet with stone coping.	* 16) number of stories 4
And the second s	
Projecting cornice below the parapet made of	
press-metal with dentil pattern beneath.	18) basement
— · · · · · · · · · · · · · · · · · · ·	19) foundation
Broad pilasters seperate the facade into three	
primary bays. Window openings have their	20) wall construction brick
	one 21) roof type- flat
original one over one light sash and have st	011G
lintels and sills. Between the first and se	cond material -
storys there is a broad band of metalwork	22) contact print
	25
upon which rests the pilasters of the top th	ree
storys. The first story store bays are sepe	
· · · · · · · · · · · · · · · · · · ·	
by pilasters with stone capitals and plinths	• •
The lodge entrance (south east corner) has a	
hexagonal tile floor before a recessed entra	ncol
( )	noca
	nee a
The center bey-with four window openines)	nee.
The center bey-with four window openines)	
The center boy-with four window openines)	23) site plan
The center bey-with four window openines)	
The center bey-with four window openines)	
The center bey-with four window openines)	
The center bey-with four window openines)	
The center bey-with four window openines)	
The center bey-with four window openines)	23) site plan
The center bey-with four window openines)  46) Description of environment/outbuildings	23) site plan
The center bey-with four window openines)	23) site plan  24) changes - minor storefront
The center bey-with four window openines)  46) Description of environment/outbuildings	23) site plan
The center bey-with four window openines)  46) Description of environment/outbuildings	23) site plan:  24) changes- additions/alter- alteration
The center bey-with four window openines)  46) Description of environment/outbuildings	23) site plan:  24) changes -    additions/alter-    ations/moved  alteration
The center bey-with four window openines)  46) Description of environment/outbuildings	23) site plan:  24) changes- additions/alter- alteration
The center bey-with four window openines)  46) Description of environment/outbuildings	23) site plan:  24) changes- additions/alter- ations/moved 25) condition
The center bey-with four window openines)  46) Description of environment/outbuildings	23) site plan  24) changes- additions/alter- ations/moved 25) condition 26) visible from road?
The center bey-with four window openines)  46) Description of environment/outbuildings	23) site plan:  24) changes- additions/alter- ations/moved 25) condition
The center bey-with four window openines)  46) Description of environment/outbuildings	23) site plan  24) changes- additions/alter- ations/moved 25) condition 26) visible from road?
The centur boy-with four window openings)  46) Description of environment/outbuildings  47) Information sources	23) site plan  24) changes -    additions/alter-    ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?
The centur boy-with four window openings)  46) Description of environment/outbuildings  47) Information sources	23) site plan  24) changes- additions/alter- ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation
The centur boy-with four window openings)  46) Description of environment/outbuildings  47) Information sources	23) site plan  24) changes -    additions/alter-    ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?
The centur boy-with four window opening)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prepared by	24) changes- additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
The centur boy-with four window openings)  46) Description of environment/outbuildings  47) Information sources	23) site plan:  24) changes- additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
The centur boy-with four window openings)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prepared by  DDD	23) site plan:  24) changes- additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  29) preservation underway? 30) endangered? 31) on National
The center boy-with four window openines)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prenared by	23) site plan  24) changes- additions/alter- ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National
The center boy-with four window openines)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prepared by  DDD	23) site plan  24) changes - minor storefront additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?
The center boy-with four window openines)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prepared by  DDD	23) site plan  24) changes -    additions/alter-    ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation    underway?  30) endangered?  31) on National    Register?  32) part of
The center boy-with four window openines)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prepared by  DDD	23) site plan:  24) changes- additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established
The centur boy-with four window openings)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prepared by  DDD	23) site plan  24) changes -
The centur boy-with four window openincs)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prepared by  DDD  50) Organization  HT	23) site plan  24) changes -    additions/alter-    ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation    underway?  30) endangered?  31) on National    Register?  32) part of    established    historical district
The centur boy-with four window openings)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prepared by  DDD	23) site plan  24) changes -
The centur bay-with four window opening)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prepared by  DDD  50) Organization  HT	23) site plan  24) changes -    additions/alter-    ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation    underway?  30) endangered?  31) on National    Register?  32) part of    established    historical district
The centur bay-with four window opening)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prepared by  DDD  50) Organization  HT	23) site plan  24) changes- additions/alter- ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National Register?  32) part of established historical district  33) name of historical district
The centur bay-with four window opening)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prepared by  DDD  50) Organization  HT	23) site plan  24) changes- additions/alter- ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National Register?  32) part of established historical district  33) name of historical district  34) is site eligible?  yes
The centur boy-with four window openincs)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prepared by  DDD  50) Organization  HT	23) site plan  24) changes - minor storefront alteration  25) condition 26) visible from road? 27) distance/frontage 28) accessible?  29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?  yes
The centur boy-with four window openincs)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prepared by  DDD  50) Organization  HT	23) site plan  24) changes - minor storefront alteration  25) condition 26) visible from road? 27) distance/frontage 28) accessible?  29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?  yes
The centur boy-with four window openincs)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prepared by  DDD  50) Organization  HT	23) site plan  24) changes - minor storefront additions/alteration  25) condition 26) visible from road? 27) distance/frontage 28) accessible?  29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  minor storefront alteration  no  alteration
The center boy-with four window openincs)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prepared by  DDD  50) Organization  HT	23) site plan  24) changes - minor storefront alteration  25) condition 26) visible from road? 27) distance/frontage 28) accessible?  29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?  yes
The center boy-with four window openincs)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prepared by  DDD  50) Organization  1 HT	23) site plan  24) changes - minor storefront additions/alteration  25) condition 26) visible from road? 27) distance/frontage 28) accessible?  29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  minor storefront alteration  no  alteration
The center boy-with four window openincs)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prepared by  DDD  50) Organization  1 HT	23) site plan  24) changes - minor storefront additions/alteration  25) condition 26) visible from road? 27) distance/frontage 28) accessible?  29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  minor storefront alteration  no  alteration  no  yes  yes  yes  yes  yes  yes  yes
The centur bay-with four window opening)  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives roll 1 #28-29  49) Prepared by  DDD  50) Organization  HT	23) site plan  24) changes - minor storefront additions/alteration  25) condition 26) visible from road? 27) distance/frontage 28) accessible?  29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  minor storefront alteration  no  alteration  no  yes  yes  yes  yes  yes  yes  yes



#### Missouri Historic Architectural Inventory for Company (Company) Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private *	1) i	nventory number	7-5
public	2) 1	name (cont)	Little theatre
39) Owners — name		name - historial	Lander'd theatre
address	1 '		
		street address	309-313 E. Walnut st
40) Local contact	5) t	town or vicinity	Springlield
41) Coordinates (UTM)	6) 1	legal description	
42) Quad	1	county	Greene
43) Other survey		category	OT COME
45) Other Survey			
		(site, structure,	building
		building, object)	
44) History	9) :	significance	
	10)		
	11)		
	1 .	architect	
	]13)	builder	
	14)	original use	
		present use	
AE\ Additional description			
45) Additional description		number of stories	
This building has been placed on	,	plan shape	
the National Register of Historic places.	18)	basement	
Consult the nomination form for information on	19)	foundation	
history and leacription	1 -	wall construction	
mrgooth end coorthoron			
		roof type -	
·		material	
	22)	contact print	
		35mm	
	Ì		
	ļ		
	}		
	-		
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings			
46) Description of environment/outbuildings		site plan	
46) Description of environment/outbuildings  47) Information sources			
	24)	changes -	
	24)	changes - additions/alter-	
	24)	changes - additions/alter-ations/moved	
	24)	changes - additions/alterations/moved condition	
	24) 25) 26)	changes - additions/alter- ations/moved condition visible from road?	
	24) 25) 26)	changes - additions/alterations/moved condition	
	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road? distance/frontage	
47) Information sources	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	
	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	
47) Information sources  48) Location of negatives	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	
47) Information sources	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	
47) Information sources  48) Location of negatives	24) 25) 26) 27) 28) 29) 30)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	
47) Information sources  48) Location of negatives  49) Prepared by	24) 25) 26) 27) 28) 29) 30)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	
47) Information sources  48) Location of negatives	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	
47) Information sources  48) Location of negatives  49) Prepared by	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	
47) Information sources  48) Location of negatives  49) Prepared by	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	yes
47) Information sources  48) Location of negatives  49) Prepared by	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	yes
47) Information sources  48) Location of negatives  49) Prepared by	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	yes
47) Information sources  48) Location of negatives  49) Prepared by  50) Organization	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica	yes
47) Information sources  48) Location of negatives  49) Prepared by  50) Organization	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district	yes
47) Information sources  48) Location of negatives  49) Prepared by  50) Organization	24) 25) 26) 27) 28) 29) 30) 31) 32) 33)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible?	yes
47) Information sources  48) Location of negatives  49) Prepared by  50) Organization	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential?	yes
47) Information sources  48) Location of negatives  49) Prepared by  50) Organization	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible?	yes
47) Information sources  48) Location of negatives  49) Prepared by  50) Organization  ed, attached separate sheets.	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35) 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential?	yes
48) Location of negatives 49) Prepared by 50) Organization  ed, attached separate sheets.	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35) 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential? date	yes
48) Location of negatives 49) Prepared by 50) Organization  ed, attached separate sheets.	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35) 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential? date	yes



# Missouri Historic Architectural Inventory for General Color Division of Parks and Historic Preservation Department of Natural Resources

Bivision of Farks and Thistory and Department			
38) Ownership — private *	1) in	nventory number	II-6
— public	2) na	ame (cont)	
39) Owners — name		ame - historial	
— address		treet address	315 E. Walnut st.
40) Local contact	5) to	own or vicinity	Sprincfield
41) Coordinates (UTM)	6) le	egal description	Label of the Label Control of
42) Quad		ounty	
	1		Greene
43) Other survey	8) ca	ategory	
	(s	site, structure,	building
	Ь	uilding, object)	Datt griff
M) Westons		ignificance	
44) History		-	
	10) d		ca. 1915
	11) st	tyle	
	12) a	rchitect	
	1		
		ouilder	
	14) o	original use	commercial and hotel
	15) p	resent use	conterdial
45) Additional description	161 =	bar of starios	2
The modern metal front obscures the	d.=:	מיווטבי טו פנטוופט	
THE LOUGH MEANT TIONS OBSERTED ON			rectangle
original facede but it does survive. Nothing can	18) b	pasement	
be seen of the cormice but there is a return of	19) fe	oundation	
the stonework entable are which is above the stone	1 600	wall construction	
	1		brios
-front.	21) r	oof type -	flat
	n	material	**
	22) 0	contact print	<del></del>
	1	35mm	
46) Description of environment/outbuildings	23) s	site plan	
46) Description of environment/outbuildings	23) s	site plan	
46) Description of environment/outbuildings	23) s	site plan	
46) Description of environment/outbuildings	23) s	site plan	
46) Description of environment/outbuildings	23) s	site plan	
46) Description of environment/outbuildings			
47) Information sources			storefront altered
	24)		
47) Information sources	24) (	changes -	storefront altered whole facade covere
47) Information sources	24) (	changes - additions/alter- ations/moved	storefront altered whole facade covere with modern metal
47) Information sources	24) (25) (3	changes - additions/alter- ations/moved condition	storefront altered whole facade covere with modern metal
47) Information sources	24) (25) (26) (26)	changes - additions/alter- ations/moved condition visible from road?	storefront altered whole facade covere with modern metal
47) Information sources	24) (25) (26) (27) (3	changes - additions/alter- ations/moved condition visible from road? distance/frontage	storefront altered whole facade covere with modern metal
47) Information sources	24) (25) (26) (27) (3	changes - additions/alter- ations/moved condition visible from road?	storefront altered whole facade covere with modern metal
47) Information sources Sanborn 1333	24) (25) (26) (27) (28) (28) (27)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	storefront altered whole facade covere with modern metal
47) Information sources	24) (25) (26) (27) (28) (29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	storefront altered whole facade covere with modern metal
47) Information sources  Samborn 1933  48) Location of negatives roll 101 #21	24) (25) (26) (27) (28) (29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	storefront altered whole facade covere with modern metal
47) Information sources Sanborn 1333	24) (25) (26) (27) (28) (29) (30) (40)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	storefront altered whole facade covere with modern metal
47) Information sources  Sanborn 1333  48) Location of negatives roll 101 #21  49) Prepared by  DDD	24) (25) (26) (27) (28) (29) (30) (31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	storefront altered whole facade covere with modern metal
47) Information sources  Samborn 1933  48) Location of negatives roll 101 #21  49) Prepared by  DDD	24) (25) (26) (27) (28) (29) (30) (31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	storefront altered whole facade covere with modern metal
47) Information sources  Sanborn 1333  48) Location of negatives roll 101 #21  49) Prepared by  DDD	24) (25) (26) (27) (28) (29) (30) (31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	storefront altered whole facade covere with modern metal
47) Information sources  Samborn 1933  48) Location of negatives roll 101 #21  49) Prepared by  DDD	24) (25) (26) (27) (28) (29) (30) (31) (32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	storefront altered whole facade covere with modern metal good
47) Information sources  Samborn 1333  48) Location of negatives roll 101 #21  49) Prepared by  DDD	24) (25) (26) (27) (28) (31) (32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	storefront altered whole facade covere with modern metal good
47) Information sources  Samborn 1933  48) Location of negatives roll 101 #21  49) Prepared by DDD  50) Organization	24) (25) (26) (27) (28) (31) (32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	storefront altered whole facade covere with modern metal good  no
47) Information sources  Samborn 1933  48) Location of negatives roll 101 #21  49) Prepared by  DDD	24) (25) (26) (27) (28) (31) (32) (33)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica	storefront altered whole facade covere with modern metal good  no
47) Information sources  Samborn 1933  48) Location of negatives roll 101 #21  49) Prepared by  DDD  50) Organization	24) (25) (26) (27) (28) (29) (31) (32) (33)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	storefront altered whole facade covere with modern metal good  no
47) Information sources  Samborn 1933  48) Location of negatives roll 101 #21  49) Prepared by DDD  50) Organization	24) (25) (26) (27) (28) (29) (31) (32) (33)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica	storefront altered whole facade covere with modern metal good  no
47) Information sources  Samborn 1333  48) Location of negatives roll 101 #21  49) Prepared by DDD  50) Organization roll  ittached separate sheets.	24) (25) (26) (27) (28) (29) (30) (31) (32) (34)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible?	storefront altered whole facade covere with modern metal good  no no no
47) Information sources  Samborn 1933  48) Location of negatives roll 101 #21  49) Prepared by  DDD  50) Organization	24) (25) (26) (27) (28) (29) (30) (31) (32) (33) (34) (35)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential	storefront altered whole facade covere with modern metal good  no no no yes
47) Information sources  Samborn 1933  48) Location of negatives roll 101 #21  49) Prepared by DDD  50) Organization  Ittached separate sheets.	24) (25) (26) (27) (28) (32) (33) (34) (35) (36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential date	storefront altered whole facade covere with modern metal good  no no no
47) Information sources  Samborn 1333  48) Location of negatives roll 101 #21  49) Prepared by DDD  50) Organization roll  ittached separate sheets.	24) (25) (26) (27) (28) (32) (33) (34) (35) (36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential	storefront altered whole facade covere with modern metal good  no no no yes
47) Information sources  Samborn 1933  48) Location of negatives roll 101 #21  49) Prepared by DDD  50) Organization roll  Ittached separate sheets.	24) (25) (26) (27) (28) (32) (33) (34) (35) (36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential date	storefront altered whole facade covere with modern metal good  no no no yes
47) Information sources  Samborn 1933  48) Location of negatives roll 101 #21  49) Prepared by DDD  50) Organization  Ittached separate sheets.	24) (25) (26) (27) (28) (32) (33) (34) (35) (36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential date	storefront altered whole facade covere with modern metal good  no no no yes



## 

•			
38) Ownership — private *	1) inventory number	N-8	-
— public	2) name (cont)	1,(,	
·	1		
39) Owners — name	3) name - historial		
— address	4) street address	319 E. Welnut st.	
40) Local contact	5) town or vicinity		
41) Coordinates (UTM)	1	Springfield	
	6) legal description		
42) Quad	7) county	Groone	
43) Other survey	8) category		-
·	(site, structure,		•
	1	building	
	building, object)		
44) History	9) significance		
	10) date	ca. 1910	
		020 1710	
	11) style		
	12) architect		
	13) builder		
	14) original use	201 11 20 20 20 20 20 20 20 20 20 20 20 20 20	
	_	commercial	
	15) present use	commercial	
45) Additional description	16) number of stories	3	
Flat paraget with stone coping	17) plan shape	rectangle	
beneath which is a bare brick area which may have	18) basement		
been covered with a metal cornice. Below the	1	·-	
	19) foundation	1-	
cornice there is an entablature with brick	20) wall construction	brick	
corbelling and decorative stone and brick	21) roof type -	27.40	
patterning. The building is framed by corner	material		
pilasters with stone capitals. Window openings			
	22) contact print		(
are paired with a continous lintel and sill of	35mm		
stone.			
	}	·	
			ì
( )			
		i	
			L
46) Description of environment/outbuildings	23) site plan		ادا
46) Description of environment/outbuildings	23) site plan		٤٠
46) Description of environment/outbuildings	23) site plan		10.0
46) Description of environment/outbuildings	23) site plan		رد
46) Description of environment/outbuildings	23) site plan		100
46) Description of environment/outbuildings			101
			100
46) Description of environment/outbuildings  47) Information sources			131
	24) changes -	storefront altered	101
	24) changes - additions/alter-		101
	24) changes - additions/alterations/moved	storefront altered	131
	24) changes - additions/alter- ations/moved 25) condition	storefront altered cornice missing	101
	24) changes - additions/alterations/moved	storefront altered cornice missing	151
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road	storefront altered cornice Hissing	131
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage	storefront altered cornice Hissing	10
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road: 27) distance/frontage 28) accessible?	storefront altered cornice Hissing	(0)
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation	storefront altered cornice Hissing	(0)
47) Information sources  48) Location of negatives roll 1 #31	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway?	storefront altered cornice Hissing	(0)
47) Information sources  48) Location of negatives  roll 1 #31  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation	storefront altered cornice Hissing	(0)
47) Information sources  48) Location of negatives roll 1 #31	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	storefront altered cornice Hissing	(0)
48) Location of negatives roll 1 #31 49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	storefront altered cornice Hissing	(0)
48) Location of negatives roll 1 #31 49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	storefront altered cornice Hissing	(0)
48) Location of negatives roll 1 #31 49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	storefront altered cornice Hissing	(u) (l)
48) Location of negatives roll 1 #31 49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	storefront altered cornice Hissing	(1)
48) Location of negatives roll 1 #31 49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	storefront altered cornice Hissing	(0)
48) Location of negatives roll 1 #31 49) Prepared by DDD 250) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road: 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	storefront altered cornice Hissing	(v) (l)
48) Location of negatives roll 1 #31 49) Prepared by 50) Organization  ded, attached separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica	storefront altered cornice Hissing	(0)
48) Location of negatives roll 1 #31 49) Prepared by DDD 250) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road: 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	storefront altered cornice Hissing  no	(0)
48) Location of negatives roll 1 #31 49) Prepared by 50) Organization  ded, attached separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible?	no no	
48) Location of negatives  roll 1 #31  49) Prepared by  50) Organization  Add attached separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road: 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential	no n	
48) Location of negatives  roll 1 #31  49) Prepared by  50) Organization  Add attached separate sheets.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible?	no no	
48) Location of negatives roll 1 #31 49) Prepared by 50) Organization LET	24) changes - additions/alter- ations/moved 25) condition 26) visible from road: 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential	no n	(c) (c) (d) (d)
48) Location of negatives roll 1 #31 49) Prepared by 50) Organization LET	24) changes - additions/alter- ations/moved 25) condition 26) visible from road: 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential 36) date	no n	
48) Location of negatives roll 1 #31 49) Prepared by 50) Organization LET	24) changes - additions/alter- ations/moved 25) condition 26) visible from road: 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential 36) date	no n	



## Missouri Historic Architectural Inventory for Architectural Enventory for Architectura

			<del></del>
38) Ownership — private		inventory number	<u> </u>
— public	2)	name (cont)	
39) Owners — name	3)	name - historial	
	l	street address	
— address			321 E. Walnut st.
40) Local contact	5)	town or vicinity	Soringfield
41) Coordinates (UTM)	6)	legal description	
42) Quad	l .	county	
	J		Greene
43) Other survey	8)	category	ļ
		(site, structure,	hudlding
		building, object)	building
AN U.S.	01	significance	
44) History	1		
	10)	date	ca. 1910
	11)	style	
	121	architect	
	1		
•	1	builder	
	14)	original use	commerci <u>al</u>
	15)	present use	consercial
45) Additional description		number of stories	
To at a company with a city of a contract			2
Flat parapet with a simple patterned	1		rectangle
brick entablacure. Second story window openings	18)	basement	
have segmental arch lintels. The openings	191	foundation	
have been closed off.		wall construction	
nave been closed off.	1 '		brick
	(21)	roof type -	flat
·		material	
	22)	contact print	
	ļ	35mm	
46) Description of environment/outbuildings	23	site plan	
	1	111111	<del>                                      </del>
	14	++++	
	-+	<del>┤╸┤╶┤╶┤╶</del> ┼	<del>┞╎┊┊┼╡┋</del> ╫╅╋
	1	<del></del>	
	1+	+++++	
47) Information sources	24	) changes -	storefront altered
		additions/alter-	
	1	ations/moved	
	25	) condition	
	26	) visible from road:	?
	27	) distance/frontage	
		) accessible?	
	- 1	) preservation	
48) Location of negatives roll 101 #20	29		
1011 1011		underway?	
49) Prepared by	30	) endangered?	_
DDD *	31	.) on National	
50) Organization	l	Register?	12.0
I.E.F	20	2) part of	10
	32		
	Ì	established	no
		historical distric	t [
attached separate sheets.	33	3) name of historica	al
		district	
	2	is site eligible?	70
			no
		b) district potential	
	- 1	5) date	4/10/84
	37	7) revision	
I A SAN TORM	$\top$		



#### Missouri Historic Architectural Inventory for Grand Grand Grand Color Division of Parks and Historic Preservation Department of Natural Resources

·			
38) Ownership — private	1)	inventory number	M-10
— public	2)	name (cont)	
39) Owners — name	1	name - historial	
— address			
	1	street address	323-331 E. Walnut st.
40) Local contact		town or vicinity	Springfield
41) Coordinates (UTM)	6)	legal description	
42) Quad	7)	county	Greene
43) Other survey	8)	category	Create
		(site, structure,	
			building
		building, object)	
44) History		significance	
	10)	date	ca. 1910
	11)	style	
	12)	architect	
		builder	
	1		
		original use	co mercial
		present use	comporcial
45) Additional description		number of stories	O TIMO TO TOWN
Flat parapet with stone coping below		plan shape	frectangle rectangle
which is a brack patterned and corbelled entabla-		basement	
ture. There are six primary bays set off with	19)	foundation	
pilasters. There are continous lintels and sills	127	wall sanctured:	
principle indicate and an annual and an annual and an annual and an			brick
	21)	roof type -	ilat
•		material	
	22)	contact print	<u> </u>
		35mm	
		····	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings	23)	site plan	
46) Description of environment/outbuildings			
47) Information sources		changes -	
		changes - additions/alter-	storefronts have bee
47) Information sources	24)	changes - additions/alter- ations/moved	T-'
47) Information sources	24)	changes - additions/alter-	storefronts have bee
47) Information sources	24)	changes - additions/alter- ations/moved	storefronts have bee
47) Information sources	24)	changes - additions/alter- ations/moved condition visible from road?	storefronts have bee
47) Information sources	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road? distance/frontage	storefronts have bee
47) Information sources Sanborn 1933	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	storefronts have bee
47) Information sources	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	altered
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #32	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	storefronts have bee
47) Information sources Sanborn 1933	25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	storefronts have bee
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #32  49) Prepared by DDD	25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	storefronts have bee
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #32	25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	storefronts have bee
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #32  49) Prepared by DDD	24) 25) 26) 27) 28) 29) 30)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	storefronts have bee
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #32  49) Prepared by DDD	24) 25) 26) 27) 28) 29) 30)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	storefronts have bee
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #32  49) Prepared by DDD	24) 25) 26) 27) 28) 29) 30)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	storefronts have bee altered
47) Information sources  Sanborn 1.933  48) Location of negatives roll 1 #32  49) Prepared by DDD  50) Organization LET	24) 25) 26) 27) 28] 29] 30) 31) 32]	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	storefronts have bee altered  no
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #32  49) Prepared by DDD	24) 25) 26) 27) 28] 29] 30) 31) 32]	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica	storefronts have bee altered  no
47) Information sources  Sanborn 1.933  48) Location of negatives roll 1 #32  49) Prepared by DDD  50) Organization 1.ET	24) 25) 26) 27) 28) 29) 30) 31) 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district	storefronts have bee altered  no no
47) Information sources  Sanborn 1.933  48) Location of negatives roll 1 #32  49) Prepared by DDD  50) Organization 1.ET	24) 25) 26) 27) 28) 29) 30) 31) 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible?	storefronts have bee altered  no no
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #32  49) Prepared by DDD  50) Organization LET	24) 25) 26) 27) 28) 30) 31, 32, 33 34, 35	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible? ) district potential:	no no no To
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #32  49) Prepared by DDD  50) Organization LET	24) 25) 26) 27) 28) 30) 31, 32, 33 34, 35	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible?	storefronts have bee altered  no no
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #32  49) Prepared by DDD  50) Organization LET	24) 25) 26) 27) 28) 30) 31) 32, 33 34 35 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible? ) district potential:	no no no To
47) Information sources  Samborn 1933  48) Location of negatives roll 1 #32  49) Prepared by DDD  50) Organization  If add descent sheets.	24) 25) 26) 27) 28) 30) 31) 32, 33 34 35 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible? ) district potential? ) date	no no no no
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #32  49) Prepared by DDD  50) Organization LET	24) 25) 26) 27) 28) 30) 31) 32, 33 34 35 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible? ) district potential? ) date	no no no no



Missouri Historic Architectural Inventory for

Division of Parks and Historic Preservation Department of Natural Resources

3) Ownership - private	e X	• 1) inventory number	9 ].
— public			State Hotel
19) Owners — name	John F. O'Reilly	3' name historial	
— address	Box 231 Lebanon, MO.	· · · · · · · · · · · · · · · · · · ·	100 E. Walnut
Local contact		I F	Springfield
`= →1) Coordinates (U`	TM.·		[reg. Survey 178 Lot A
2) Quad			Greene
3) Other survey		8) category	1
		(site, structure,	
			Building
14) History	Built year 1905 as the Springfield	9) significance	
Business Colle	ege continuing as such until 1926. By 193	33 10) date	a 1905
the original o	college rooms had become separate business	111 style	Commercial with classical
locations. Th	ne hotel was first called the Marquette	12) architect	details
Hotel.	and the first of the first que to	13) builder	
		14) original use	Business College & Hotel
			Hotel & commercial
15) Additional descripti	Of Those stony being the same to the same	16) number of stories	3
Eivo bassa 4	on Three story brick commercial building.	17) plan shape	rectangle
	the north side separated by brick pilaster	S 18: hasament	full
	tructure. Pilasters "support" entablatur	e 191 foundation	concrete
which is a low	parapet wall to the roof. Smooth dresse		prick
stone coping o	n parapet wall with a second band of stor	1e	
work below whi	on there is corbelled brick work. The	material	flat
pilasters have	stone capitals and plinths. The first	100	
and second bay	s have only one window opeining. The sec	cond and	
fourth have tw	o as does the center bay though it is muc	:h	
	two flanking bays. The window openings		
have smooth dr	essed limestone lintels and sills. The		:
	lves are one over one light double hung		
Ches. A dou	ble belt of smooth dressed limestone pro-	-	:
. Jes a base t	o the pilasters of the second and third		
	<u>fectually separates the first story from</u> ronment/outbuildings	1000	
46) Description of envi	ronment/outbuildings	23) site plan	
			,
			,
			(
			in the second of the second
47) Information source	City Directory 1900-1933	24) changes	Several of the first
¢.	Sanborn 1902-1910	additions alter-	story bays have been
	29HD0LH 1305-1310	ations/moved	altered
		25) condition	Good
		26) visible from road?	_
		27) distance/frontage	
		28) accessible?	
48) Location of negative	ves Roll 70 #18-21	29) preservation	
	Roll 70 #18-21	underway?	No
49) Prepared by	DDD	301 endangered?	No
75) Tropared by		31) on National	LLY.
50) Organization	Missouri Heritage Trust	Register?	No
50) Olganization	missouri neritaye irust	32) part of	1132
		established	No
		historical district	INU
	the state of the s	33) name of historical	
If additional space is ne	eeded, attached separate sheets	district	
			N -
(		34) is site eligible?	No
		35) district potential?	
		36) date	January 25, 1984
		37) revision	

the two above. The pilasters are picked up again with stone capitals now framing a wide open bay which originally were glassed openings for storefronts. All presently appear modified. The first bay is filled now with glass brick.

West elevation--four bays. The only real difference from the front is that there are three openings in the 2nd and 4rd floor bays with larger window openings flanking a small window (bathroom?). The first story bay in the northwest corner is the entrance to the "State Hotel" lobby and is a corner entrance. There is one remaining cast iron pilaster which breaks the large first story opening into two equal sections both glass filled.

The small store fronts on the west side appear original and unaltered with stone stoops and encaustic tile covered the recessed entry ways. Large plate glass windiws fill the bay openings.

GRANDOUS LOS



					_
38) Ownership — priva	ite X	1)	inventory number	8	=
publ		(2)	name (cont)		1
39) Owners — name	Emogene Posoar	(3)	name - historial	,	1
— address	<b>▼</b>	4)	street address	400 5 11.3	1
40) Local contact	400 L. Walliut	1	town or vicinity	408 E. Walnut	┥
•	III'RA)	1	legal description	Springfield	┥
41) Coordinates (	U : M;	ı		Ireg. Survey 178 Lot B	4
42) Quad		1	county	Greene	<u> </u>
43) Other survey		8)	category		2/3)
		İ	(site, structure,		ω
		1	building, object)	Building	Ì
44) History		9)	significance	<u> </u>	1
7 17 THISTON	Built ca. 1910 and became part with		date		┥
Springfield Bu	siness College in 1922. By 1933 building	1 '	style	ca 1910	┥
called College	Anartments	1	-	Commercial with classic	<del>d</del> 1
	The street of th	1 '	architect	details	
		1 .	builder	4004773	<u>'</u>
		14)	original use	Commercial	7
		15)	present use	Apartments	7
45) Additional descrip	fion The Cartes of Tables	16)	number of stories	Aper chiencs	4
1	tion Three story brick. Flat roof. Two	1	plan shape	No. + +	<b>⊣</b>
	ith pilasters executed in the same fashion		basement	rectangle	$\dashv$
	or to the west. East wall is seven bays	1		full	4
window openin	gs have brick relieving arches which at	1	foundation	concrete	_
	ry are lintels to doubled window openings		wall construction	brick	
	one lite double hung sashes. The second	21)	roof type -	flat	
		1	material		7
	s also have brick relieving arches but with	22)	contact print	<del></del>	5
single window	s with a transom above.	/	35mm		
					1.0
46) Description of env	rironment/outbuildings	23)	site plan		9)
46) Description of en	rironment/outbuildings	23)	site plan		9)
46) Description of en	rironment/outbuildings	23)	site plan		9)
46) Description of en	rironment/outbuildings	23)	site plan		9)
46) Description of en	rironment/outbuildings	23)	site plan		9)
46) Description of en	rironment/outbuildings	23)	site plan		9)
46) Description of end 47) Information source			changes -		9) 5)
	res		changes - additions/alter-		
		24	changes - additions/alter- ations/moved		
	res	24	changes - additions/alter- ations/moved condition	- Good	
	res	24	changes - additions/alter- ations/moved		
	res	24 25 26	changes - additions/alter- ations/moved condition	2	
47) Information source	City Directory 1910-1933	24 25 26 27	changes - additions/alter- ations/moved condition visible from road	-	
47) Information source	City Directory 1910-1933	24 25 26 27 28	changes - additions/alter- ations/moved condition visible from road distance/frontage	2	5)
47) Information source	City Directory 1910-1933	24 25 26 27 28	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible?	-	5)
47) Information source 48) Location of negat	City Directory 1910-1933	25 26 27 28 29	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	- No	5)
47) Information source	City Directory 1910-1933  Ves Roll 70 #22	24 25 26 27 28 29 30	changes - additions/alter- ations/moved condition visible from road; distance/frontage accessible? preservation underway? endangered?	-	5)
47) Information source 48) Location of negat	City Directory 1910-1933	24 25 26 27 28 29 30	changes - additions/alter- ations/moved condition visible from road: distance/frontage accessible? preservation underway? endangered?	No No	5)
47) Information source 48) Location of negat	City Directory 1910-1933  Ves Roll 70 #22  DDD	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road: distance/frontage accessible? preservation underway? endangered? on National Register?	- No	5)
47) Information source 48) Location of negate 49) Prepared by	City Directory 1910-1933  Ves Roll 70 #22	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road: distance/frontage accessible? preservation underway? endangered?	No No	5) 6)
47) Information source 48) Location of negate 49) Prepared by	City Directory 1910-1933  Ves Roll 70 #22  DDD	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road: distance/frontage accessible? preservation underway? endangered? on National Register?	No No No	5) 6)
47) Information source 48) Location of negate 49) Prepared by	City Directory 1910-1933  Ves Roll 70 #22  DDD	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road: distance/frontage accessible? preservation underway? endangered? on National Register?	No No No	5) 6)
48) Location of negat 49) Prepared by 50) Organization	City Directory 1910-1933  Ves Roll 70 #22  DDD  Missouri Heritage Trust	25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established		5) 6)
48) Location of negat 49) Prepared by 50) Organization	City Directory 1910-1933  Ves Roll 70 #22  DDD	25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district		5) 6)
48) Location of negat 49) Prepared by 50) Organization	City Directory 1910-1933  Ves Roll 70 #22  DDD  Missouri Heritage Trust	24 25 26 27 28 29 30 31 32	changes - additions/alter- ations/moved condition visible from road: distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district district		5) 6)
48) Location of negat 49) Prepared by 50) Organization	City Directory 1910-1933  Ves Roll 70 #22  DDD  Missouri Heritage Trust	24 25 26 27 28 29 30 31 32 33	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible?		5) 6) 7)
48) Location of negat 49) Prepared by 50) Organization	City Directory 1910-1933  Ves Roll 70 #22  DDD  Missouri Heritage Trust	24 25 26 27 28 29 30 31 32 33 34 35	changes - additions/alter- ations/moved condition visible from road: distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible?		5) 6)
48) Location of negat 49) Prepared by 50) Organization	City Directory 1910-1933  Ves Roll 70 #22  DDD  Missouri Heritage Trust	24 25 26 27 28 29 30 31 32 33 34 35 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible?		5) 6) 7)



Missouri Historic Architectural Inventory for GRAP - CCE GA 1977 - Division of Parks and Historic Preservation Department of Natural Page 1997

		miston of ranks and mistoric rieservation pepa	II LIT	ient of Natura	Resources
38)	Ownership — private	₹ <del>*</del>	Į.	inventory number	
307	— public		1	name (cont)	
39)	Owners — name		3)	name - historial	St. Paul's Methodist (
	— address		1	street address	413 E. Walnut
	40) Local contact		l	town or vicinity	Springfield
	41) Coordinates (UTM)		1	legal description	Ireg. 175 Lot E
	Quad	to the second control of the control	1	county	Greene
43)	Other survey		8)	category	
				(site, structure,	Building
A A \	History	The state of the s		building, object)	
+4;	History	Built 1902-1903 by present congregation	1	significance	Architectural-Social
		Work began in 1902. Cornerstone laid	1	date	1903
		June 26, 1903. Total cost was	1	style	Baroque Revival
		\$50,000.	I	architect builder	
				original use	C)
			İ	present use	Church
15)	Additional description		1	number of stories	Church
,		The facade is classically derived with		plan shape	2+
	a stone parapet	with a centered gable pediment. The	í		Irregular
	eaves are wide	with modillions beneath within the pedi	19)	foundation	Full
		ter of the pediment has an elaborate	1	wall construction	Smooth Ashlar Limeston Brick
	J)	ted face. There is a full cornice con-		roof type -	Gable/Flat
		the pediment across the facade with	/	material	Asphalt Shingle
		e and modillions. Beneath the cornice	221	contact print	Aspira to shring te
		e area of brick banding. Under the		35mm	
		icade is recessed at the second story			
		partially free standing terra cotta			
		with Ionic capitals also of terra cotta	1		
		/ entrance at the base of the columns			
		tta entablature above connecting the ither side of the entrance there are	İ		
			+		
46)	Description of environment	vindows with stone surrounds. On the we rent/outbuildings side is a connected tower	23)	site plan	
		covered dome executed in a decidedly	1		
		style. Also on the west are three			
		operings with elaborate stained glass			
	windows.	per mgs with cluborate stained grass			
	Williadws.				and the second s
17)	Information sources	The state of the s	24)	changes -	Additions to the season
		St Paul Official Directory 1939.	-	additions/alter-	Additions to the rear
				ations/moved	
			25)	condition	Goud
			26)	visible from road?	-
			27)	distance/frontage	
atres.			1	accessible?	
18)	Location of negatives	Roll A #30-31	29)	preservation	
		17 #35-37		underway?	No
49)	Prepared by	DDD		endangered?	No
			(31)	on National	
50)	Organization	Missouri Heritage Trust		Register?	No
			32)	part of	1
				established	N.
				historical district	No
if ac	dditional space is needed.	attached separate sheets	(33)	name of historical	
<i>(</i>				district	
<u> </u>			(	is site eligible?	Yes
			- I	district potential?	No 5-1- C 1094
			J	date	Feb. 6, 1984
			3/)	revision	







Missouri Historic Architectural Inventory for

Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership - private	X *	1)	inventory number	2	1
— public	•		name (cont)	-	<b>⊣</b> =
39) Owners — name	St. Paul's Methodist Church	3)	name - historial		-
— address		4)	street address	415 E. Walnut	4
( )40) Local contact		5)	town or vicinity	Springfield	┪
41) Coordinates (UTA	<b>1</b> );	6)	legal description	Ireg. Survey 175 Lot A	7
42) Quad		7)	county	Greene	7
43) Other survey			category	dieene	12
			(site, structure,		2/3)
		1	building, object)	Building	
44) History	Built 1910-1913 as parsonage for	9)	significance	Architectural-Social	7
	St. Paul's Methodist Church	10)	date	1910-1913	-
		11)	style	Colonial Revival	7
		12)	architect	COTONIAL NEVIVO	7
		13)	builder		7
		14)	original use	Residence/parsonage	7
		15)	present use	Residence/parsonage	7
45) Additional description	Two front dormers gabled with pilastere	(16)	number of stories	2	4
aumaunda daubla	hung windows in arched opening. Upper	17)	plan shape	Rectangle	7
	over six pane sash. Moulded cornice	18)	basement	Full	7
	under the eaves. Three bay facade.	19)	foundation	Rough, faced, coursed	7
Cmosth dwassed 1	imestone lintels and sills. Eight over	20)	wall construction	Brick ashlar Limeston	ne ne
Smooth dressed i	low sashes. Portico at entry with flat	21)	roof type -	Gable Gable	<u> </u>
eight light wind	ed cornice and entablature. Doubled	ļ	material	Asphalt shingle	7
		22)	contact print	Triplia L. Jilligir	5
	t the corners of portico with Tuscan		35mm		
capitais. West	gable-pedimented gable with continuous er stucco in face of gable pediment with	}			Ì
ornice. Plaste	indow in pediment. Cornice moulded with	1			1
dillions. Eas	st gable identical with a full open porch				
ullilons. Eas	identical to front portico. Doubled				}
columns at ea	ach location. Wooden balustrade with	1			1
moulded_handrail	and turned halusters.				
46) Description of environ	and turned balusters. ment/outbuildings	23)	site plan		9)
					}
		-			· [
47) Information sources		24)	changes -		5
	St. Paul's Church Directory 1939	Ì	additions/alter-	None wieible	
			ations/moved	None visible	_
			condition	Good	_
			visible from road?		_
			distance/frontage		
40)			accessible?		၂၅
48) Location of negatives	R 70 #23-24	[29)	preservation		
40) 5		20)	underway?	No	4
49) Prepared by	DDD		endangered?	No	_
<b>50.</b> 0		31)	on National		
50) Organization	Missouri Heritage Trust	321	Register?	No	_3
		32)	part of established		
			historical district	No	
If additional coace to meed a	d attached conarate cheets	331	name of historical		4
и auumonai space is neede	d attached separate sheets.	33)	district		
( )		34	is site eligible?	<del></del>	$\dashv$
$\bigcirc$			district potential?	Yes	30
		1	date	Yes	-19
		- 1	revision	Jan. 31, 1984	$\dashv$
		ا آ			

All I want

GR ASH Waller



Missouri Historic Architectural Inventory for
Division of Parks and Historic Preservation Department of Natural Resources


		<del></del>		
38) Ownership — private X		inventory number	7	Ξ
— public		name (cont)		ļ
39) Owners — name Herman Lohmeyer		name - historial		
-address 500 E. Walnut	1 1	street address	500 E. Walnut	
40) Local contact 41) Coordinates (UTM)		town or vicinity	Springfield	
		legal description	Ireq. Survey 177 Lot A	4
42) Quad  43) Other survey	I _	county	Greene	↓
43) Other survey	8)	category		2/3)
		(site, structure,		
My Water of English	0	building, object)	Building	1
44) History From ca. 1905-1921 home of Francis		significance	Architectural-Commerce	┨
Xavier Heer, Pres. Heer Dept. Store Co.		date	ca. 1885	1
	ı	style	<u> Italianate</u>	4
		architect		4
	1	builder	Residence	4
	í	original use		4
		present use	Funeral Home	<del> </del>
45) Additional description There are several gabled dormers which		number of stories	2	4
act as attic vents. The eaves hold built in gutters.	1	plan shape	Iregular	1
Jigsaw cut brackets support the cornice. Where soffit	1	basement	Full	1
and frieze board meet there is a cove moulding. Below		foundation	Rough, faced, coursed	4
the brackets is a band with a geometric design. The	1 1	wall construction	Frame/Lan ciding	je
frieze itself is heavily coffered. The corner boards	1	roof type -	Lap Stattig	1
are treated with mouldings so as to appear as a capitale		material	Hip Press metal roof	ļ
pilaster. Door and window surrounds have moulded heads	[22]	contact print		5)
(see photo). In the southeast corner is a two story		35mm		1
porch which has been enclosed. It may be that this				
porch began life as a "sun" porch added around the turn				
of the century. The front porch and the ports cochere	}			
also appear to date from the turn of the century	}			
rather than from original construction. A photo				
taken in 1925 (Daily Leader Oct. 27, 1925) shows the	1			
46) 6	000			1.0
46) Description of environment/outbuildings	23)	site plan		9
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now	23)	site plan	in the second se	99
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once be-	23)	site plan		9)
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is	23)	site plan		9)
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays		site plan		9)
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormes	rs			
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormed to the formation sources.	rs	changes -	Rear wing added	9) 5)
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormer 1902 & 1910 Sanborn (see attached)	rs	changes - additions/alter-	Front porch & PC are	
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormed to the property of	24)	changes - additions/alter- ations/moved	Front porch & PC are ca. 1920	
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormer 1902 & 1910 Sanborn (see attached)	24) 25)	changes - additions/alter- ations/moved condition	Front porch & PC are ca. 1920 Good	
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormer 1902 & 1910 Sanborn (see attached)	24) 25) 26)	changes - additions/alter- ations/moved condition visible from road?	Front porch & PC are ca. 1920 Good	
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormer 1902 & 1910 Sanborn (see attached)	25) 26) 27)	changes - additions/alter- ations/moved condition visible from road? distance/frontage	Front porch & PC are ca. 1920 Good	5)
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormed the local sources (see attached)  1902 & 1910 Sanborn City Directory 1903-1933	25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	Front porch & PC are ca. 1920 Good	
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormer 1902 & 1910 Sanborn (see attached)	25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	Front porch & PC are _ca. 1920 _Good	5)
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormer (see attached)  1902 & 1910 Sanborn City Directory 1903-1933	25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	Front porch & PC are ca. 1920 Good	5)
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormed the light of the local state of the loc	25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	Front porch & PC are _ca. 1920 _Good	5)
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormer (see attached)  1902 & 1910 Sanborn City Directory 1903-1933  48) Location of negatives  49) Prepared by DDD	25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	Front porch & PC are _ca. 1920 _Good NoNo	5)
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormer (see attached)  1902 & 1910 Sanborn City Directory 1903-1933	25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	Front porch & PC are ca. 1920 Good	5)
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormer (see attached)  1902 & 1910 Sanborn City Directory 1903-1933  48) Location of negatives  49) Prepared by DDD	25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	Front porch & PC are _ca. 1920 _Good NoNo	5)
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormer (see attached)  1902 & 1910 Sanborn City Directory 1903-1933  48) Location of negatives  49) Prepared by DDD	25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	Front porch & PC are ca. 1920 Good No No No	5)
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormer (see attached)  1902 & 1910 Sanborn City Directory 1903-1933  48) Location of negatives  49) Prepared by DDD  Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	Front porch & PC are ca. 1920 Good No No No No	5)
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormer (see attached)  1902 & 1910 Sanborn City Directory 1903-1933  48) Location of negatives  49) Prepared by DDD	25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	Front porch & PC are ca. 1920 Good No No No	5)
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormer (see attached)  1902 & 1910 Sanborn City Directory 1903-1933  48) Location of negatives  49) Prepared by DDD  Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	Front porch & PC are ca. 1920 Good  No No No No	5)
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormer (see attached)  1902 & 1910 Sanborn City Directory 1903-1933  48) Location of negatives  49) Prepared by DDD  Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	Front porch & PC are ca. 1920 Good  No No No No No Yes	5) 6) 7)
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormer (see attached)  1902 & 1910 Sanborn City Directory 1903-1933  48) Location of negatives  49) Prepared by DDD  Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	Front porch & PC are ca. 1920 Good  No No No No Ves No	5)
46) Description of environment/outbuildings Behind the house, actually on an adjoining property now part of the funeral home is a carriage house once belonging to a house since demolished. The building is one and one half stories-frame construction. Two bays on the west elevation. There are two large hipped dormer (see attached)  1902 & 1910 Sanborn City Directory 1903-1933  48) Location of negatives  49) Prepared by DDD  Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35) 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	Front porch & PC are ca. 1920 Good  No No No No No Yes	5) 6) 7)

#### 500 E. Walnut

porch open. It is now completely enclosed. To the rear on the south elevation a one story addition has been made very recently of concrete block construction. The building has been used as a Funeral Home since ca. 1925.

(Continuation from 46) with one over one light sash on a pyramid hipped roof plan. There is an cupula vent at the apex of the roof with a pyramid roof sharply tapering. Roof is covered with asphalt shingles.

CPALL AND



G12-412003-11-61




Missouri Historic Architectural Inventory for

Division of Parks and Historic Preservation Department of Natural Resources

W				
38) Ownership — private X	1)	inventory number	4	]=
— public	2)	name (cont)		1
39) Owners—name W. A. Bonar et al	3)	name - historial		1
— address 519 E. Walnut	-	street address	519 E. Walnut	
40) Local contact		town or vicinity	Springfield	]
41) Coordinates (UTM)		legal description	Ireg. Survey 177 Lot L	]
42) Quad		county	Greene	<u> </u>
43) Other survey	8)	category		2/3)
		(site, structure,		<u> </u>
		building, object)	Building	
44) History		significance	Architectural-Commerce	1
		date	ca. 1885	
		style	Italianate	
	-	architect		1
		builder		1
		original use	Residence	j
ACC ALIGN		present use	Apts.	<u> </u>
45) Additional description Vermiculated limestone coursed ashlar	-	number of stories	2	4
limestone-in out of the way places the stone is rough		plan shape	L-shape	
faced. There are two later additions made to the north		basement	Full	]
elevation of the house. The first is of frame two storie	<u></u> § 9)	foundation	Coursed ashlar Limesto	he
with a rough coursed ashlar foundation. The window	20)	wall construction	Frame/ vermiculated	1
surrounds have simple cut decoration on their faces. The	21)	roof type -	Aspesto Staing	4
last addition is also frame two stories with a hip roof.	001	material	Formcated Hip Asphalt	<u> </u>
It has a concrete foundation (see drawing). The front	22)	contact print	shingles	5
elevation of the older portion is three bays wide with a		35mm		
side entrance. The windows have elaborate hoods (see				
photo). The entrance has been extensively altered. Ther	e			
3 now a porticoed entrance set with Tuscan columns				
) flanking the entrance. The portico roof is flat with				
a balustrade with square balusters surrounding the				
roof. The original entryway may be seen as it was merely 46) Description of environment/outbuildings	231	site plan		9)
filled in rather than obliterated. It was arched with	23;	site plan	e de la companya della companya della companya de la companya dell	٦
flanking decorative brackets which may only partly be				
seen. The cornice is highly decorative under the pro-			The state of the s	
jecting eaves with a dentil pattern under a cove moulded		gen eiger er eine ein ∰ gen eiger ein ein gen		
angle with applied moulding set so as to create the im-		we w	e de la composição de l	
47) Information sources	24)	changes -	Front porch removed.	5
pression of recessed panels on a wide frieze. The "panel	l .	_	fully altered, rear	
are flanked by a double set of scrolled brackets. The		ations/moved	addition	
pattern carries around the entire house.	25)	condition	Good	-
partiern carries around one enorre mouse.	1	visible from road?		-
	1	distance/frontage	•	1
		accessible?	-	0
48) Location of negatives R 40 #40-44, 1-4, 9	201	preservation		-
ν το πτο-ττ, 1-τ, 3	231			
49) Prepared by DDD	[29]	underway?	No.	
		•	No No	
opp	30)	underway?	No No	7
	30)	underway? endangered? on National	No	
50) Organization Missouri Heritage Trust	30) 31)	underway? endangered?		7)
	30) 31)	underway? endangered? on National Register?	No	7)
	30) 31)	underway? endangered? on National Register? part of	No No	7)
	30) 31) 32)	underway? endangered? on National Register? part of established	No	7)
50) Organization Missouri Heritage Trust	30) 31) 32)	underway? endangered? on National Register? part of established historical district	No No	7)
50) Organization Missouri Heritage Trust	30) 31) 32)	underway? endangered? on National Register? part of established historical district name of historical	No No	
50) Organization Missouri Heritage Trust	30) 31) 32) 33) 34) 35)	underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	No No No	7) 30)
50) Organization Missouri Heritage Trust	30) 31) 32) 33) 34) 35) 36)	underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	No No No Yes	

process to be desired



NT

60 N 1021 1



Missouri Historic Architectural Inventory for GR (2003 - Cold Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — priva	ate X	*		inventory number	5	_]=
publ			1	name (cont)	Lorraine Apts.	
39) Owners — name	Gerald Messenger		3)	name - historial	Same	
address	s 1249 S. Airwood		1 .	street address	527 E. Walnut	╛
40) Local contact	:			town or vicinity	Springfield	
41) Coordinates (	(MTU)		6)	legal description	Ireq. Survey 155 Lot	<u>:</u>   L
42) Quad			7)	county	Greene	
43) Other survey			8)	category		2/3)
				(site, structure,		۳
			1	building, object)	Building	Ì
44) History			9)	significance		٦
			10)	date	1919-1920	
	Built 1919-1920		11)	style	Commercial with classic	al
			12)	architect	detai	
			13)	builder		7
			14)	original use	Apartments	7
			1	present use	Apartments	٦
45) Additional descrip	otion Three shares	dale complementation of the		number of stories	3	4
,	inree stories, br	rick construction with a	17)	plan shape	rectangle	7
	idation. There are t		1,00	basement	Full	$\dashv$
apartment hou	se - both priginal.	The first is the front	191	foundation	Concrete	$\dashv$
		It is of buff colored	20)	wall construction	Brick	-
		els. The window sur-		roof type -	Flat	$\dashv$
rounds are of	cast concrete left	its original off white	- 1			-
color. The f	ront entrance is the	e center bay of the thre	9221	contact print	<u> </u>	5
Day Tacade.	Tr 12 combosed of ca	ist contrete elements	/	35mm		
		with small flanking		33		
windows or si	delights.		-			
Lighter color	ed brick is used to	accent columns on the	}			
open porch be	fore the entrance ar	nd above the third story	·			
		attic story windows.				
here is a si	mple straight cornic	ce picked out in brick				
and above the	cornice is a parape	et gable made up entirel	Year			- 19
46) Description of en	vironment/outbuildings '	,	23)	site plan	والمناب والمنافي والمنافية والمنافية والمنافية والمنافية والمنافية والمنافية والمنافية والمنافية والمنافية والم	
						5
			- [			1
						,
						<u> </u>
47) Information source	ces		24	changes -		5)
	Cit. Divertony 10	1		additions/alter-		
	City Directory 19	15-1933		ations/moved	None visible	
			25	) condition	Good	
			26	visible from road?		
			27	) distance/frontage	-	
			28	accessible?		9
48) Location of negat	tives		29	) preservation		
Location of negati	ROII /U #5-8			underway?	No	
49) Prepared by	DDD Roll 54	7-4 #11-12	30	) endangered?		$\neg$
73) Fiepaled by	000		1	) on National	No	$\dashv$
EO) Organization				Register?	No	
50) Organization	Missouri Heritage	Trust	32	) part of	110	
	•			established		
				historical district	: No	
16 11:			33	name of historica		$\dashv$
If additional space is r	needed, attached separate sheets.		33	district		
$\overline{}$			24	) is site eligible?	No	$\dashv$
1			1	<ul><li>is site eligible:</li><li>district potential</li></ul>	, No	30
			1	=		<b> </b> 의
			- }	i) date	January 25, 1984	$\dashv$
			[3/	') revision		

#### 527 E. Walnut

of the lighter buff brick with a brick center panel also made of different colored brick. There is a cast concrete coping on the brick parapet.

The roof appears to be flat.

The second portion of the building is of the usual red brick with brick relieving arches at the windows and doors. Brick piers frame the bays on the side elevations. The rear elevation (north) has an exterior wooden staircase leading to each floor. There is an open frame service elevator in current operation on the north elevation as well.

Behind the building is a low one story brick parking garage of multiple bays which appears to be of the same date as the apartment building.

CRACE - 611



38) Ownership - priva e	Y	Topaction of Hata	Tal Nesources
— public	A.	* 1) inventory number	
39) Owners — name		2) name (cont)	Grace Episcopal Church
address		3) name - historial	
(40) Local contact		4) street address	601 E. Walnut
41) Coordinates (U.)	5 Y	5) town or vicinity	Springfield
· Quad	54	6) legal description	
43) Other survey	the control of the second control of the control of	7) county	Greene
43) Other survey	H storic Site Board	8) category	
		(site, structure,	Building
order of the contract of the c		building, object)	
44) History		9) significance	Architectural-Social
		10) date	1869
		11) style	Gothic Revival
		12) architect	and the state of t
		13) builder	
		14) original use	Church
		15) present use	Church
45) Additional description	The same 2 a a 4 a section 2 a c	16) number of storie	S 1
	There is a tower with a flat roof	Which   17) plan shape	
• •	There are louvered gothic arche	d 18) basement	Rectangle
	Il taces of the tower. Each vertica	19) foundation	No
	wall surfaces has a trefoil cutout	20) wall construction	Stone
	e board reaches the roof eaves. The	eaves 21) roof type	Board Abatten
overhang the v	vall surfaces with exposed rafter er	ds. material	High Gable
In the front	gable there are exposed purlins. Ea	ch 221 contact print	Asphalt Shingle
window opening	has an elaborately moulded gothic	arch 35mm	
window hood.	There are stepped wooden buttresses	3311111	i
	side bay. On the facade is a gabled		
	n details like those on the main str		
	is a doubled door in an arched openi		
with heavily		9	
( ). 1 on 11 da 1 1 1 J	- Company of the comp		
46) Description of enviro	and other than the control of the co	02)	
40) Description of enviro	a neacoutounaings	23) site plan	
47) Information sources	Historic Site Board File.	24) changes -	Numerous additions to
	The state st	additions/alter-	the rear
		ations/moved	
		25) condition	Good
		26) visible from road	1?
		27) distance/frontag	e
		28) accessible?	
48) Location of negatives	Doll 16 #26 20	29) preservation	
	Roll 16 #26-28	underway?	No
49) Prepared by	B.D.C.	30) endangered?	No
	DD0	31) on National	J.J.X.
50) Organization		Register?	No
	Missouri Heritage Trust	32) part of	
		established	
	•	historical distric	et No
If additional space is neede	ad, attached separate sheets	33) name of historic	
		district	_
		34) is site eligible?	Yes
		35) district potentia	The state of the s
		36) date	Feb. 6, 1984
		37) revision	. 60. 0, 1304
	•	377 (37.3101)	



Missouri Historic Architectural Inventory for

Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership - private	V *	1)	inventory number	20	L.:
• •	^		name (cont)		=
public	II als Davids		1	Englenook Apts	1
	Hugh Parks		name - historial	Same	1
— address	810 South Ave.	1	street address	700 E. Walnut	1
( 40) Local contact			town or vicinity	Springfield	_
41) Coordinates (UTM	å	6)	legal description	H. Shepard's 1st add.	'
42) Quad		7)	county	Greene Lot 1	
43) Other survey		8)	category		2/3)
,			(site, structure,		ω
			building, object)	Building	
44) History		9)	significance	<u> </u>	1
44) History	D. 214 1016 1017	1	date	1916-1917	1
	Build 1916-1917.	1	style	Commercial with Classic	1 2
			*		4°'
			architect	detail	1
		)	builder		1
		1	original use	Apt. House	J
		15)	present use	Apt. House	
45) Additional description	Three story brick construction with a	16)	number of stories	3	4
concrete foundat	ion. Flat roof with parapet gable at the	17)	plan shape	rectangle	1
front. Two sact	ions to the building finet as at the	'	basement	full	1
Innaine Ante	ions to the building (just as at the		foundation		1
built of buff	The front section is basically square	'	wall construction	concrete	4
DUTIT OF DUTT CO	lored brick (though the front elevation			brick	4
is painted white	). There are cast concrete window sills	21)	roof type -	flat	4
and surrounds.			material		<del> </del>
The front elevat	ion is broken into three basic bays with	4	contact print		5
center entrance.	The front entrance is a single door wit	Ţ	35mm		
sidelights and a	transom. Above the main entrance is a	T			
large namel with	fixed multipaned windows to sive list				
on the stainwell	fixed multi-paned windows to give light				1
on the stairweit.	Above the smaller double hung windows				
flank the er	ntrance and stairwell window. Entrance				
is a cantele	evered metal hood which may be original.	1			
Each bay is picke	ed out with cast concrete banding in				<del> </del>
46) Description of environ	ment/outbuildings	23)	site plan		9)
				organization of the state of th	
				Andrew Street	
		} .		• • • • • • • • • • • • • • • • • • •	
			the second second		
			2 . m . m	والمنافذ أمكان والمتاسب والمالي	
		24	changes -		5
47) Information sources		24	•		
			additions/alter-		
	City Directory 1915-1933		ations/moved	Porch altered in front	_
	•	25	) condition	Good	
		26	visible from road?	4000	$\neg$
		27	) distance/frontage		╗
			) accessible?		6
				-	$\dashv$
48) Location of negatives	Roll 40 #13-14	29	) preservation		
		1.	underway?	No	$\dashv$
49) Prepared by	DDD Roll 547-4 #13-14		) endangered?	No No	$\dashv$
		31	) on National	No	
50) Organization	Missouri Heritage Trust	ĺ	Register?		
oo, organization	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	32	) part of		$\neg$
			established		
			historical district	No	
	and the state of t	22	name of historica		-
If additional space is neede	ed. attached separate sheets.	33	•	'	
			district	-	-
		- 1	) is site eligible?	No	4.
		35	) district potential?	? No	30
		36	) date	January 25, 1984	
		37	') revision	- Vallage J Line	
		1			_

vertical and horizontal strips. Each horizontal band of concrete also acts as lintle or sill to the windows within each bay.

An additional band of cast concrete sets off the cornice in a horizontal line interacting the vertical lines separating the bays. At the point of intersection is a concrete block in accent. The gable is a simple flat parapet with concrete coping. There is an open porch at the front of the building with concrete steps leading up to it.

The larger rectangular portion of the building is of red brick with brick relieving arches at the windows and doors. Each side bay is framed by brick piers. There is a side exterior stairway on the east elevation.

Ce de Maria





Missouri Historic Architectural Inventory for GP FOR Division of Parks and Historic Preservation Department of Natural Resources


38) Ownership — private	X ,		inventory number	19	۳
— public			name (cont)		
39) Owners — name	Hugh Parks	4	name - historial		_
— address	810 South Ave.	1	street address	708 E. Walnut	4
40) Local contact			town or vicinity	Springfield	_
41) Coordinates (UT	M:		legal description county	H. Sheppard's Add. Lo	틱
42) Quad			category	Greene 2	+
43) Other survey		8,	(site, structure,		2/3)
		Ì	building, object)	Duilding	Ì
44) History		9)	significance	Building Architectural-Commerc	_
	Built 1910-1911 by Wm. Gottfried, co-	1	date	1910-1911	=
owner of Gottfr	ied Furniture & Carpet Co.		style	Catalogue/Builder wit	h
			architect	Classical detail	
		13)	builder	CTUSSICUT GCCUTT	-4
		14)	original use	Residence	7
		15)	present use	Apts.	
45) Additional description	The Limestone lintles and sills at the win-	16)	number of stories	2	4
	the east, west and north elevations.	17)	plan shape	Irregular	_
	ion has brick relieving arches at the	18)	basement	Full	
	openings. Double hung single pane sashe	el 1	foundation	Rough, faced, coursed	
	opening. Each gable is fully pedimented	20)	wall construction	Brick ashlar Limest	one
	us cornice, and wide overhanging eaves.	21)	roof type -	Dr ICK	
	simple modillions at the cornice and a		material	Hip Gable combination	<del></del>
	oard with a dentiled pattern applied.	22)	contact print	Asphalt shingle	5)
	ves, and frieze are continuous around the		35mm		
	d are carried onto the front porch as				ļ
	le has a recessed pediment with a single				
	d a plastered exterior covering. The				
nediment ab	ove the front porch has a half circle				Ì
window with	radiating muntins in a fan pattern.				
46) Description of enviro	enment/outhuildings	23)	site plan		9
46) Description of enviro	onment/outbuildings	23,	Site plan		
		-		and the second s	.
					Í
		1		y and the second of the second	,
47) Information sources		24)	changes -		5)
		Ì	additions/alter-		
	City Directory 1909-1933		ations/moved	None visible	
	Sanborn 1910	25	condition	Good but needs mainte	nanc
		26	visible from road?		
		27	distance/frontage	-	
		28	accessible?	-	
48) Location of negative	s Roll 40 #15-18	29	) preservation		
	KOTT 40 #13-16		underway?	No	_
49) Prepared by	DDD	- 1	endangered?	No No	_
		31	on National		
50) Organization	Missouri Heritage Trust	1	Register?	No	
	THIS SOUTH NEW YOUNGE THE GOVERNMENT OF THE PROPERTY OF THE PR	32	) part of		
		}	established		
		22	historical district ) name of historical	<u> </u>	_
If additional space is need	ded, attached separate sheets	33	district	'  <u>-</u>	
		34	) is site eligible?	Voc	$\dashv$
•			) district potential?	Yes	3
		- 1	) date	Jan. 31, 1984	<b>⊣</b> ≝
		- 1	) revision		

The two story front porch covers the entire front facade. The corners are curved rather than ruare. Porch posts are wooden shafts with plaster capitals done in the Ionic style. The inths are limestone blocks smooth dressed at the first floor, and wood at the second. The porch steps are smooth dressed limestone and the foundation for the porch is a continuous coursed rough faced ashlar limestone. Balustrades are of wood with turned balasters.

There is a fragment of a hitching post used to prop up the gutter in the southwest corner of the house. It is a square shaped shaft with a brass ring set into the limestone.

Granica and

706 1 calment



N

CRABARELLARIA



# Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources

	-				
38) Ownership — private	X . *	1)	inventory number	18	=
public	·	2)	name (cont)		7
39) Owners — name	Charles Chapell	(3)	name - historial		٦
— address	3553 E. Linwood	4)	street address	716 E. Walnut	
40) Local contact		5)	town or vicinity	Springfield	
41) Coordinates (UT)	M)	6)	legal description	H. Sheppard's 1st Add	
42) Quad		7)	county	Greene Lot 3	
43) Other survey		8)	category		2/3)
		}	(site, structure,		$ \omega $
		Ì	building, object)	Building	1
44) History		9)	significance	Architectural-Commerc	
	Built 1907-1908 by Henry Clay Tompkins,	10)	date	1907-1908	-5-
	idence. Adjacent property probably	11)	style	Catalogue/Builder wit	· h
	owned by Tomphins and maintained as	12)	architect	Classical o	
rental (720 E. )	Walnut) identical to this house.	13)	builder	LIBSSICAL_C	اقاما
		14)	original use	Residence	
		1	present use	Apts.	_
45) Additional descriptio	N The second house	- 1	number of stories	Apres.	4
i di il i i i i	There are two houses considered here-	1	plan shape	Do ntong? -	~
	n every observable detail except that		basement	Rectangle	$\dashv$
the interior pla	an has been "turned over" one from the	1	foundation	Full	
other so that th	ne stairwells face each other across the		wall construction	Rough, coursed, ashlar	_
intervening space	ce. Three bay facade with an off center	1 .	roof type -	Brick Cast Stone	
entryway. Door	and window lintels of smooth dressed		material		
	the window sills. Foundation is of cas	t	contact print	LHip Asphalt single	5
	to imitate rough faced coursed ashlar	(22)	35mm		۳
	ion. Windows are double hung with single		33mm		
pane sashes. Th	ne dormer has a hipped roof with paired	ļ			
double hung wind	dows separated by a fluted wooden pilaste	rļ.			
There is a dent	iled cornice. The gutters are built in	-			
at the eaves	with a simple dentiled cornice with a na	rrou	ı		
eze board.	The brick is a dark brown color rather		•		
than the brick	red commonly found. There is a one-story nment/outbuildings	ļ			
46) Description of enviro	nment/outbuildings	23)	site plan	· 100 - 100	9)
				and the second of the second o	
The drive leads	to a two bay garage at the rear of the				
property which	is of <b>brick and one story.</b>				
			4	and the second s	
			· · · · · · · · · · · · · · · · · · ·		
47) Information sources	0: 0:	24)	changes -		5)
	City Directory 1900-1933		additions/alter-		
	Sanborn 1910	- (	ations/moved	None visible	
		25)	condition	Good	
		26)	visible from road?		
		27)	distance/frontage	_	
		28)	accessible?	_	9
48) Location of negatives	Roll 547-2 #16	29)	preservation		
<b>5</b>	Roll 65 #2, 7-8	}	underway?	No.	
49) Prepared by	NOTE 03 #29 / 0	30	endangered?	No No	$\neg$
·, · · · · · · · · · · · · · · · · · ·	DDD		on National	No	
50) Organization	Missouri Heritage Trust	1	Register?	No	
oo, organization	MISSOURT HELLLage Trust	32	) part of	No No	
			established		
			historical district	No	
			name of historical		
If add to a section is a section of the section of	log attached congrate cheets	133			- 1
lf additional space is need	led, attached separate sheets.	33		-	
If additional space is need	led, attached separate sheets.		district	-	
If additional space is need	led, attached separate sheets.	34	district ) is site eligible?	Yes	ω
If additional space is need	led. attached separate sheets.	34 35	district ) is site eligible? ) district potential?	Yes No	30)
If additional space is need	led. attached separate sheets.	34 35 36	district ) is site eligible?	Yes	30)


rch which extends across the front for most of the width of the facade. It is covered ally over the entryway with a hipped roof. The square columns are of the brick used in the construction of the house with cast concrete capitals in the Ionic order. The dentiled cornice matches that found on the cornice of the house itself and on the dormer window. Porch walls are of brick with a smoothed limestone coping. The floor of the porch is made up of blue and white hexagonal encaustic tile set in a geometric design and border. The threshold of the front entryway and the steps leading up to the porch are of smoothed limestone.

There is a diamond patterned leaded glass window set at the landing in the stairwell of each house. On the east elevation on 716 and on the west elevation on 720 E. Walnut. Brick relieving arches form the lintels for window and door opening on the south, east and west elevations of both houses.

A single poured concrete drive ca. 1920 serves both houses and passes between.

In front of 718 there is a limestone stoop at the street which is smooth dressed. Presumably this acted as a step from horse driven carriages.

REAL ON Lotte





GRACIOSIO



Missouri Historic Architectural Inventory for Grand Communication of Parks and Historic Preservation Department of Natural Resources

	Division of Farms and Chesterio Freedom Paper				
38) Ownership — private	* ·	1)	inventory number		=
— public		2)	name (cont)	_	
39) Owners — name	Jessie Lloyd	3)	name - historial		
— address	719 E. Walnut	1 1	street address	719 E. Walnut	
40) Local contact			town or vicinity	Springfield	1
41) Coordinates (UT	<sup>*</sup> M;		legal description	H. Shepard's 2nd Addl.	
42) Quad			county	Greene Lot 3	
43) Other survey		8)	category		2/3)
			(site, structure,		=
			building, object)	Building	]
44) History	Build 1900-1901 by Moses W. Coolbaugh	1	significance		
	General Mgr. of Springfield Furniture	l	date	1900-1901	
	Co.		style	Catalogue/builder with	
	60.		architect	shingle style de	tai
		1 '	builder		
		I	original use	residence	_
		1	present use	office	
45) Additional description	On The roof is covered with a modern cedar	1 .	number of stories	2	<u>4</u>
shake. The wa	lls are covered with the original butt	1	plan shape	irregular	
	e second floor level and a modern covering	1	basement	full	
	eathing made to imitate board and batten	,	foundation	Rough faced coursed Ast	n
	ront gable has a continuous cornice creat-		wall construction	Frame limestor	ne
•	The shingling is used as a decorative	21)	roof type -	hip & gable combination	<u> </u>
	g the frieze itself. There is a pent roof		material	wood shingle shale	
	There are shaped corner brackets set at	22)	contact print		5)
•	thexe too are covered with shingles.		35mm		
	projection on the front elevation which				
-	the cornice and is given its own hipped				
	as a dormer (see drawing and photos).				
	y (square) projects from the west elevatio	n			
	story with an ogee curved roof of metal				
	copper). The east and west gables are				<b>↓</b>
46) Description of envir	onment/outbuildings	23)	site plan		9)
	pyramid hipped roof one story frame out-			•	
building is at	the rear of the property used as a garage.	-			
The wall surfac	es are lap sided.	۸.			
		1			(n
47) Information sources		24	) changes -	Entire 1st story level	5)
		-	additions/alter-	extensively altered	
	City Directory 1899-1933		ations/moved		4
		1	) condition	Good	_
			) visible from road?		-
			) distance/frontage	-	6
			) accessible?		اقع
48) Location of negative	es Roll 65 #1, 41-44 Roll 40 #19-21	29	) preservation		
	•	20	underway?	No	4
49) Prepared by	DOD		) endangered?	No	_
		31	) on National		
50) Organization	Missouri Heritage Trust	20	Register?	No	—\ <u>&gt;</u>
	•	32	established		
			established	A.1	
		22	historical district	No	_
If additional space is nee	ded, attached separate sheets.	33	<ul><li>name of historica district</li></ul>		
į		24	) is site eligible?	-	$\dashv$
1			<ol> <li>is site eligible:</li> <li>district potential?</li> </ol>	, No	30
			6) district potential:	-NO	e
		Ų	7) revision	Jan. 25, 1984	$\dashv$
		15,	,		

identical with continuous cornice and shingling used to face the pediment. There are double recessed attic windows with curved openings into which the shingles are carried (photo).

l windows are double hung single pane sashes. In the east gable projection the first story window has a single fixed leaded glass sash done in a diamond pattern.


There is an exterior chimney located on the west elevation with decorative brick patterning done to imitate a pedimented opening.

The porch and port cochere have been very reently remodeled to their present false appearance. It is possible that the original porch and port cochers exist under the later additions though it is difficult to tell.

The rear elevation has a two story porch and stairway on the exterior leading into a half story servants' hall (?) above the rear projecting gable. The rear gable has a large dormer with a shed roof projecting to the westward to accommodate more space in the attic rooms.

There is a modern addition of one story to the rear of the house.

GRAS-CO LOW





# Missouri Historic Architectural Inventory for GR 1990 - 697 7 Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private X		ory number	17	<u> </u>
— public	2) name (			
39) Owners — name Duard Baldwin	3) name			
— address 1441 Summit	4) street		720 E. Walnut	
40) Local contact	5) town o	, i	Springfield	
41) Coordinates (UTM)	_	lescription	H. Sheppard's 1st Add.	
42) Quad	7) county		Greene Lot 3	
43) Other survey	8) catego			2/3)
		structure,		=
		ng, object)	Building	_
44) History Probably built 1907-1908 as a matching	9) signifi	cance	Architectural-Commerce	<u>.</u>
house to 716 E. Walnut. Built by H. C. Tompkins.	10) date		1907-1908	_
	11) style		Catalogue/Builder	╣
	12) archite		with Classical de	tail
	13) builde			
	14) origina	<b>I</b>	Residence	
	15) preser		Apts.	
45) Additional description  There are two houses considered here -	1	er of stories	2	
both identical in every observable detail except that	17) plan si	· .	Rectangle	
the interior plan has been "turned over" one from the	18) basem		Full	_
other so that the stairwells face each other across the	19) founda		Rough, faced, coursed	
intervening space. Three bay facade with an off center		onstruction	ashlar cast	ston
entryway. Door and window lintels of smooth dressed	21) roof ty		Brick ashiai Last	
limestone as are the window sills. Foundation is of cast	materi	ial	Hip Asphalt shingle	<u> </u>
concrete shaped to imitate rough faced coursed ashlar				5)
stone construction. Windows are double hung with single	35mm	1		
pane sashes. The dormer has a hipped roof with paired				
double hung windows separated by a fluted wooden pilaster				
There is a dentiled cornice. The gutters are built in				
	row			
at the eaves with a simple dentiled cornice with a nar	row			
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather				10
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather	row 23) site pl	an		9)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather		an		9)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather		an		9)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather		an		9)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather than the brick red commonly found. There is a one-story 46) Description of environment/outbuildings		an <sub>.</sub>		9)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather than the brick red commonly found. There is a one-story 46) Description of environment/outbuildings  The drive leads to a two bay garage at the rear of the property which is of brick and one story.	23) site pl			5
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather than the brick red commonly found. There is a one-story do Description of environment/outbuildings  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources	23) site pl	es -		9) 5)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather than the brick red commonly found. There is a one-story 46) Description of environment/outbuildings  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources  City Directory 1900-1933	23) site pl	es - ons/alter-		5
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather than the brick red commonly found. There is a one-story do Description of environment/outbuildings  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources	23) site pl  24) chang additi-	es - ons/alter - s/moved	None visible	5
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather than the brick red commonly found. There is a one-story 46) Description of environment/outbuildings  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources  City Directory 1900-1933	23) site pl  24) chang additions 25) conditions	es - ons/alter- s/moved tion		5
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather than the brick red commonly found. There is a one-story 46) Description of environment/outbuildings  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources  City Directory 1900-1933	24) chang additinations 25) conditions 26) visible	es - ons/alter- s/moved tion e from road?	None visible	5
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather than the brick red commonly found. There is a one-story 46) Description of environment/outbuildings  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources  City Directory 1900-1933	24) chang additi- ations 25) condit 26) visible 27) distan	es - ons/alter- s/moved tion e from road? nce/frontage	None visible	5)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather than the brick red commonly found. There is a one-story 46) Description of environment/outbuildings  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources  City Directory 1900-1933 1910 Sanborn	24) chang additions 25) conditions 26) visible 27) distant 28) access	es - ons/alter- s/moved tion e from road? nce/frontage sible?	None visible	5
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather than the brick red commonly found. There is a one-story 46) Description of environment/outbuildings  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources  City Directory 1900-1933 1910 Sanborn	24) chang additions 25) conditions 26) visible 27) distant 28) access 29) preserving	es - ons/alter- s/moved tion e from road? nce/frontage sible? rvation	None visible Good	5)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather than the brick red commonly found. There is a one-story 46) Description of environment/outbuildings  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources  City Directory 1900-1933 1910 Sanborn  48) Location of negatives Roll 547 - 2 #17 Roll 65 #3-7	24) chang additions 25) conditions 26) visible 27) distant 28) access 29) preser under	es - ons/alter- s/moved tion e from road? nce/frontage sible? rvation way?	None visible Good No	5)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather than the brick red commonly found. There is a one-story 46) Description of environment/outbuildings  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources  City Directory 1900-1933 1910 Sanborn  48) Location of negatives Roll 547 - 2 #17 Roll 65 #3-7	24) chang additinations (25) conditions (27) distant (28) access (29) preserunder (30) endant	es - ons/alter- s/moved tion e from road? nce/frontage sible? rvation way? ngered?	None visible Good	5)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather than the brick red commonly found. There is a one-story 46) Description of environment/outbuildings  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources  City Directory 1900-1933 1910 Sanborn  48) Location of negatives Roll 547 - 2 #17 Roll 65 #3-7	24) chang additions 25) conditions 25) conditions 27) distant 28) access under 30) endant 31) on Na	es - ons/alter- s/moved tion e from road? nce/frontage sible? rvation way? ngered?	None visible Good No No	5) 6)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather than the brick red commonly found. There is a one-story 46) Description of environment/outbuildings  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources  City Directory 1900-1933 1910 Sanborn  48) Location of negatives Roll 547 - 2 #17 Roll 65 #3-7	24) chang additions 25) conditions 26) visible 27) distant 28) access 29) preser under 30) endant 31) on Na Regist	es - ons/alter- s/moved tion e from road? nce/frontage sible? rvation way? ngered? tional ter?	None visible Good No	5)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather than the brick red commonly found. There is a one-story 46) Description of environment/outbuildings  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources  City Directory 1900-1933 1910 Sanborn  48) Location of negatives Roll 547 - 2 #17 Roll 65 #3-7	24) chang additions 25) conditions 25) conditions 27) distant 28) access under 30) endant 31) on Na	es - ons/alter- s/moved tion e from road? nce/frontage sible? rvation way? ngered? tional ter?	None visible Good No No No	5) 6)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather than the brick red commonly found. There is a one-story 46) Description of environment/outbuildings  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources  City Directory 1900-1933 1910 Sanborn  48) Location of negatives Roll 547 - 2 #17 Roll 65 #3-7	24) chang additions 25) conditions 25) conditions 27) distant 28) access 29) preser under 30) endant 31) on Na Regist 32) part of establications 230 establications 240 establications 250 establications 2	es - ons/alter- s/moved tion e from road? nce/frontage sible? rvation way? ngered? tional ter?	None visible Good No No	5) 6)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather to the brick red commonly found. There is a one-story found. There is a one-story the brick and one story.  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources  City Directory 1900-1933 1910 Sanborn  48) Location of negatives Roll 547 - 2 #17 Roll 65 #3-7  49) Prepared by  DDD  Missouri Heritage Trust	24) chang additinations 25) conditions 26) visible 27) distant 28) access 29) preser under 30) endant 31) on Na Regist 32) part of establic histor	es - ons/alter- s/moved tion e from road? nce/frontage sible? rvation way? ngered? tional ter? of lished	None visible Good No No No	5) 6)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather than the brick red commonly found. There is a one-story 46) Description of environment/outbuildings  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources  City Directory 1900-1933 1910 Sanborn  48) Location of negatives Roll 547 - 2 #17 Roll 65 #3-7	24) chang additinations 25) conditions 26) visible 27) distant 28) access 29) preser under 30) endant 31) on Na Regist 32) part of establic histor	es - ons/alter- s/moved tion e from road? nce/frontage sible? rvation way? ngered? tional ter? f lished rical district of historical	None visible Good No No No	5) 6)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather to the brick red commonly found. There is a one-story found. There is a one-story the brick and one story.  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources  City Directory 1900-1933 1910 Sanborn  48) Location of negatives Roll 547 - 2 #17 Roll 65 #3-7  49) Prepared by  DDD  Missouri Heritage Trust	24) chang additications 25) conditications 25) conditications 26) visible 27) distant 28) access 29) presecunder 30) endant 31) on Na Regist 32) part of estable histor 33) name district	es - ons/alter- s/moved tion e from road? nce/frontage sible? rvation way? ngered? tional ter? f lished rical district of historical ct	None visible Good	5) 6)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather to the brick red commonly found. There is a one-story found. There is a one-story the brick and one story.  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources  City Directory 1900-1933 1910 Sanborn  48) Location of negatives Roll 547 - 2 #17 Roll 65 #3-7  49) Prepared by  DDD  Missouri Heritage Trust	24) chang additications 25) conditications 25) conditications 26) visible 27) distant 28) access 29) presecunder 30) endant 31) on Na Regist 32) part of establications 33) name district 34) is site	es - ons/alter- s/moved tion e from road? nce/frontage sible? rvation way? ngered? tional ter? f lished rical district of historical ct	None visible Good	5) 6) 7)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather to the brick red commonly found. There is a one-story found. There is a one-story the brick and one story.  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources  City Directory 1900-1933 1910 Sanborn  48) Location of negatives Roll 547 - 2 #17 Roll 65 #3-7  49) Prepared by  DDD  Missouri Heritage Trust	24) chang additications 25) conditications 25) conditications 26) visible 27) distant 28) access 29) presecunder 30) endant 31) on Na Regist 32) part of establications 33) name district 34) is site	es - ons/alter- s/moved tion e from road? nce/frontage sible? rvation way? ngered? tional ter? f lished rical district of historical ct e eligible?	None visible Good	5) 6)
at the eaves with a simple dentiled cornice with a nar frieze board. The brick is a dark brown color rather to the brick red commonly found. There is a one-story found. There is a one-story the brick and one story.  The drive leads to a two bay garage at the rear of the property which is of brick and one story.  47) Information sources  City Directory 1900-1933 1910 Sanborn  48) Location of negatives Roll 547 - 2 #17 Roll 65 #3-7  49) Prepared by  DDD  Missouri Heritage Trust	24) chang additions 25) conditions 25) conditions 26) visible 27) distant 28) access 29) preser under 30) endant 31) on Na Regist 32) part of establishistor 33) name district 34) is site 35) district 35)	es - ons/alter- s/moved tion e from road? nce/frontage sible? rvation way? ngered? tional ter? of lished rical district of historical ct e eligible? ct potential?	None visible Good	5) 6) 7)

porch which extends across the front for most of the width of the facade. It is covered c y over the entryway with a hipped roof. The square columns are of the brick used in the construction of the house with cast concrete capitals in the Ionic order. The dentiled cornice matches that found on the cornice of the house itself and on the dormer window. Porch walls are of brick with a smoothed limestone coping. The floor of the porch is made up of blue and white hexagonal encaustic tile set in a geometric design and border. The threshold of the front entryway and the steps leading up to the porch are of smoothed limestone.


There is a diamond patterned leaded glass window set at the landing in the stairwell of each house. On the east elevation on 716 and on the west elevation on 720 E. Walnut. Brick relieving arches form the lintels for window and door opening on the south, east and west elevations of both houses.

A single poured concrete drive ca. 1920 serves both houses and passes beneath.

In front of 718 there is a limestone stoop at the street which is smooth dressed. Presumably this acted as a step from horse driven carriages.

Critical lord

A A Company of the Co



NV



Missouri Historic Architectural Inventory for  $CR_{1}$   $CR_{2}$   $CR_{3}$   $CR_{3}$  Division of Parks and Historic Preservation Department of Natural Resources

		partment of Natura	i Kesonices
38) Ownership — privat		* 1) inventory number	16
public 39) Owners name	Dillon Investment Co.	2) name (cont) 3) name - historial	-
- address	Wilhoit Building	4) street address	738 E. Walnut
40) Local contact	without barraing	5) town or vicinity	<u></u>
41) Coordinates (U	[34]	6) legal description	Springfield
42) Quad		7) county	H. Shepard's Add. Lot 5 Greene
43) Other survey		8) category	Building
43) Other 30/40)		(site, structure,	Building
		building, object)	
14) History	and the second s	9) significance	Architectural
Lived	in from 1910-1933+ Richard Ricketts	10) data	ca. 1885
	Owner, President of Springfield Seed C	.0. 11) style	Italianate
		12) architect	La Fanate
		13) builder	
		14) original use	Docidoneo
		15) present use	Residence
15) Additional descript	ur	16) number of stories	Apartments
•	The front elevation presents an L shap	De 17) plan shape	Irreqular
	rance in the long side. There is a small	18) basement	Full?
	r on the front_elevation to give light to	19) foundation	Rough, faced, coursed
	Brackets are placed at regular intervals	20) wall construction	achlan Limostone
	ce. The brackets themselves are exu-	21) roof type :	Frame/Lap Siding
	ped with jigsaw cutouts. The frieze boar	nd material	Hip Asphalt Shingle
	ed sawtooth cutout pattern which continue	1227 COMMON DIME	THEP Aspirate sitting to
	ntire house. The corner boards are treat	35mm	
ed as pilast	ers with a fanciful cutout capital applie	ed	
flush to the	wall surface (photos). The window heads	5	
have a very	simple jigsaw cutout design at the corner	^S.	
_Moulding is	applied to the window head. Windows are		
	with si <mark>ngle pane sas</mark> hes. At the first fl	loor	
level there	are moulded wooden lugsills to further		
46) Description of envi	ronment/outbuildings	23) site plan	
47) 1-6		24) changes	Trankanaha altawad
47) Information source		additions/alter-	Front porches altered Rear porches filled in
		ations/moved	Rear porches illied ii
		25) condition	
		26) visible from road?	Good
		27) distance/frontage	
		i28) accessible?	
40\		29) preservation	
48) Location of negative	res Roll 65 #9-17	underway?	Ma
40) Day and by		30) endangered?	No.
49) Prepared by	DOD	31) on National	No.
50\ 0 · · · ·	· ·	Register?	N.o.
50) Organization	Missouri Heritage Trust	32) part of	NC
	•	established	
		historical district	No
ng a managara i i i i i i i	aded attached congrete cheets	33) name of historica	
it additional space is ne	eded-attached separate sheets	district	-
(		34) is site eligible?	Vos
`		35) district potential	? Yes
		36) date	The same of the sa
		37) revision	Feb. 6, 1984
		.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	approximate the state of the st

ccent the opening.

Front entrance has sidelights and transom both with beveled glass lights. The front porch boxes off the L shape of the facade. It has a single pitch roof with a sawtooth frieze identical to that found on the cornice of the house itself. The porch posts are modern replacements.


The foundation is of rough faced coursed ashlar limestone. On the east elevation is a two story bay window of five sides. To the right is a leaded glass window (photo) set at what must be the landing in the stairhall.

The west facace has two exterior entrances to either side of a projecting wing. Each opening has a porch similar to that found on the front porch. However the porch in the southwest corner supports its original chamfered porch posts with a mansard porch roof.

The rear elevation supports a two story once open porch which has been filled in more recently. The cornice and frieze continue around the porch in a continuous pattern. The porch roof is only slightly pitched.

There are two small gabled attic vents on the east and west roof faces. The chimneys are of brick with corbelled belts to give shape.

CRA, 063 (0)



GRASICE-618



Missouri Historic Architectural Inventory for Grand Control Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership private					
ээ, эммэж риман	X	1)	inventory number	15	]=
public		2)	name (cont)		] _
39) Owners — name	Clarence McElroy	3)	name - historial		1
address	3357 Waddell	4)	street address	800 E. Walnut	1
( 10) Local contact		5)	town or vicinity		1
+1) Coordinates (UTM	<b>(</b> )	1 '	legal description	Springfield Add	-
42) Quad	·		county	E.T. Robberson's Add.	4
43) Other survey			category	Greene Lot ]	<del>  -</del>
43) Other survey		87			2/3
			(site, structure,		
			building, object)	Building	_
44) History	Built in 1915 by Harry Cooper, Pres. of	9)	significance	Architectural-Commerce	
	•	10)	date	1915	}
Harry Cooper Sup	ply Co. (wholesale plumbing supplies)	11)	style	Catalogue/Builder with	7
		12)	architect	Craftsman inspired de	1
		13)	builder	Liaitsiian inspired de	Lai
		14)	original use	Desidence	-{
			present use	Residence	┥
AE) Additional description			number of stories	Residence	<del> </del>
45) Additional description	Overhanging eaves with a very narrow	/		2	4
	ze board. Each gable has a "stick"		plan shape	Irregular	1
bracket (photo)	at the gable cornice ends each with a	1 .	basement	Full-Rough, faced.	
four sided taper	ing pendant of wood. The fascia board	19)	foundation	coursed ashlar Limesto	he
	he gable has a suspended pendant. The	20)	wall construction	Frame/Asbestos Siding	1
front elevation	presents an Lshape to the street with the	21)	roof type -	Multi-Gable Asphalt	1
ashle just doser	ribed projecting and a long side entrance.	1	material	Shingle	1
		22)	contact print		5
	d dormer on the long side of the front		35mm		
	mimics the larger gable pediment in every				
	ve a textured plaster pediment face with				
flush narrow boa	rding to give the false impression of				
half timbering.	The gable has two fixed single light				
) attic windows	while the dormer has a small double				Ì
'hung window.					
corporated into	the half-timbered effect. At the first ment/outbuildings				
46) Description of environ	ment/outbuildings	23)	site plan		9)
There is a one-s	story frame building at the rear of the	1.			
	acts as a garage and storage building.			e de la company	1
					1
The dable 15 10	the front and has corner brackets match-				
	the front and has corner brackets match-		• • • • •	en er en en en en en en en en en en en en en	
ing those found	on the house and also sports a pendant				
ing those found as found on the		24)	changes.		5
ing those found	on the house and also sports a pendant	24)	changes -		5)
ing those found as found on the	on the house and also sports a pendant rest of the house.  Sanborn 1910	24)	additions/alter-		5)
ing those found as found on the	on the house and also sports a pendant rest of the house.		additions/alter- ations/moved		5)
ing those found as found on the	on the house and also sports a pendant rest of the house.  Sanborn 1910	25)	additions/alter- ations/moved condition	Good	5)
ing those found as found on the	on the house and also sports a pendant rest of the house.  Sanborn 1910	25)	additions/alter- ations/moved	Good	5)
ing those found as found on the	on the house and also sports a pendant rest of the house.  Sanborn 1910	25) 26)	additions/alter- ations/moved condition	Good -	_
ing those found as found on the	on the house and also sports a pendant rest of the house.  Sanborn 1910	25) 26) 27)	additions/alter- ations/moved condition visible from road?	Good - -	5) 6)
ing those found as found on the	on the house and also sports a pendant rest of the house.  Sanborn 1910 City Directories 1914-1916	25) 26) 27) 28)	additions/alter- ations/moved condition visible from road? distance/frontage	Good - -	_
ing those found as found on the 47) Information sources	on the house and also sports a pendant rest of the house.  Sanborn 1910	25) 26) 27) 28)	additions/alter- ations/moved condition visible from road? distance/frontage accessible?	-	_
ing those found as found on the 47) Information sources	on the house and also sports a pendant rest of the house.  Sanborn 1910 City Directories 1914-1916  Roll 65 #18-26	25) 26) 27) 28) 29)	additions/alter- ations/moved condition visible from road? distance/frontage accessible?		_
ing those found as found on the 47) Information sources	on the house and also sports a pendant rest of the house.  Sanborn 1910 City Directories 1914-1916	25) 26) 27) 28) 29)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	-	_
ing those found as found on the 47) Information sources  48) Location of negatives 49) Prepared by	on the house and also sports a pendant rest of the house.  Sanborn 1910 City Directories 1914-1916  Roll 65 #18-26	25) 26) 27) 28) 29)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	- - - No No	6)
ing those found as found on the 47) Information sources	on the house and also sports a pendant rest of the house.  Sanborn 1910 City Directories 1914-1916  Roll 65 #18-26 DDD	25) 26) 27) 28) 29) 30) 31)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?		_
ing those found as found on the 47) Information sources  48) Location of negatives 49) Prepared by	on the house and also sports a pendant rest of the house.  Sanborn 1910 City Directories 1914-1916  Roll 65 #18-26	25) 26) 27) 28) 29) 30) 31)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	- - - No No	6)
ing those found as found on the 47) Information sources  48) Location of negatives 49) Prepared by	on the house and also sports a pendant rest of the house.  Sanborn 1910 City Directories 1914-1916  Roll 65 #18-26 DDD	25) 26) 27) 28) 29) 30) 31)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	- - - No No No	6)
ing those found as found on the 47) Information sources  48) Location of negatives  49) Prepared by  50) Organization	on the house and also sports a pendant rest of the house.  Sanborn 1910 City Directories 1914-1916  Roll 65 #18-26  DDD  Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	- - - No No No	6)
ing those found as found on the 47) Information sources  48) Location of negatives  49) Prepared by  50) Organization	on the house and also sports a pendant rest of the house.  Sanborn 1910 City Directories 1914-1916  Roll 65 #18-26 DDD	25) 26) 27) 28) 29) 30) 31)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	- - - No No No	6)
ing those found as found on the 47) Information sources  48) Location of negatives  49) Prepared by  50) Organization	on the house and also sports a pendant rest of the house.  Sanborn 1910 City Directories 1914-1916  Roll 65 #18-26  DDD  Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31) 32)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district oname of historical district		6)
ing those found as found on the 47) Information sources  48) Location of negatives  49) Prepared by  50) Organization	on the house and also sports a pendant rest of the house.  Sanborn 1910 City Directories 1914-1916  Roll 65 #18-26  DDD  Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31) 32) 33,	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?		6) 7)
ing those found as found on the 47) Information sources  48) Location of negatives  49) Prepared by  50) Organization	on the house and also sports a pendant rest of the house.  Sanborn 1910 City Directories 1914-1916  Roll 65 #18-26  DDD  Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31) 32) 34, 35,	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?		6)
ing those found as found on the 47) Information sources  48) Location of negatives  49) Prepared by  50) Organization	on the house and also sports a pendant rest of the house.  Sanborn 1910 City Directories 1914-1916  Roll 65 #18-26  DDD  Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31) 32) 33, 34, 35, 36,	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?		6) 7)
ing those found as found on the 47) Information sources  48) Location of negatives  49) Prepared by  50) Organization	on the house and also sports a pendant rest of the house.  Sanborn 1910 City Directories 1914-1916  Roll 65 #18-26  DDD  Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31) 32) 33, 34, 35, 36,	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?		6) 7)


#### 800 E. Walnut

story the gable projection has chamfered corners to form three sides instead of a flat surface. A porch projects from the front elevation starting at the angle of the gable corner cutout. Above the entry the porch is pedimented and throughout is only one story and of one roof pitch. The pediment picks up the textured plastered surface with vertical wooden members flush to the plaster. At the corners of the pediment are brackets with pendants and at the apex of the gable is also found a pendant.

The porch posts are of square wooden columns set in pairs and in sets of three at porch corners. Between the posts near the top are set "keyhole" cutout panels above four sided wooden horizontals (approx. 2 x 2 inches) which are through mortized into the posts. Above the horizontals is a diagonal four sided wooden member placed so as to appear as a bracket brace.

The porch continues around the east elevation and projects to form a port cochere extending flush to the projecting gable on the east elevation (photo). The porch motifs are continued on the port cochere. Porch walls are of painted brick with limestone coping. Simple wooden balustrade with square spindles. The east gable does not have the pediment details found on the front elevation though the asbestos siding may have been placed over it. The first story has the chamfered corners found on the front gabled projection. Porch steps are of limestone smoothed.

( 1 1 0 03 WA



EC- 2- 60-619



Missouri Historic Architectural Inventory for

Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	X .	1	inventory number	14	<b>」</b> =
public		1	name (cont)		
39) Owners — name	Bob Dedman	3)	name - historial	-	
— address	812 E. Walnut	4)	street address	812 E. Walnut	
( 40) Local contact		5)	town or vicinity	Springfield	
41) Coordinates (UT	M)	6)	legal description	E.T.Robberson's Add.	
42) Quad		7)	county	Greene Lot 2	
43) Other survey		8)	category	<u> </u>	2/3)
ŕ			(site, structure,		ω
		1	building, object)	Building	
44) History		9)	significance	Architectural-Commerce	7
,		ľ	date		-
		1 -	style	ca. 1905	$\dashv$
			architect	Catalogue/Builder with	
		1 "	builder	Craftsman inspired o	letai
			original use	Residence	
			present use	Commercial/residential	
45) Additional description	<sup>n</sup> Wide projecting eaves with angular	1	number of stories	2	4
hraces set to "	support" the eaves. The brackets are	1	plan shape	Square	
	ve accent to their presence. There is a		basement	Full	
		19)	foundation	Cast Stone	
	t the front elevation with two small attic	20).	wall construction	Cast Stone	
	hich are double hung. The second story	21)	roof type -	Hip	$\neg$
	tment is of smooth cast concrete blocks		material	Red Clay Ceramic Tile	
	smooth dressed ashlar stone construction.	22)	contact print	TIVE OF CEROMIC TITLE	5
	ouff brown. The lintels over the five		35mm		
	second story level form a continuous line				
	st concrete, but of a lighter color so as				
to imitate the	commonly found limestone lintels on neigh-	-			
	Note the two large double hung single par				
) sash windo					
•	ws with the three small fixed windows				
sandwiched betw	ws with the three small fixed windows een. The small windows are multipaned.				
•	ws with the three small fixed windows een. The small windows are multipaned.		site plan		9)
sandwiched betw	ws with the three small fixed windows een. The small windows are multipaned.		site plan		9)
sandwiched betw	ws with the three small fixed windows een. The small windows are multipaned.		site plan		9)
sandwiched betw	ws with the three small fixed windows een. The small windows are multipaned.		site plan		9)
sandwiched betw	ws with the three small fixed windows een. The small windows are multipaned.		site plan		9)
sandwiched betw	ws with the three small fixed windows een. The small windows are multipaned.		site plan		9)
sandwiched betw 46) Description of enviro	ws with the three small fixed windows een. The small windows are multipaned.	23)			9)
sandwiched betw	ws with the three small fixed windows een. The small windows are multipaned.	23)	site plan  changes - additions/alter-		
sandwiched betw 46) Description of enviro	ws with the three small fixed windows een. The small windows are multipaned.	23)	changes - additions/alter-		
sandwiched betw 46) Description of enviro	ws with the three small fixed windows een. The small windows are multipaned.	23)	changes - additions/alter- ations/moved		
sandwiched betw 46) Description of enviro	ws with the three small fixed windows een. The small windows are multipaned.	24)	changes - additions/alter- ations/moved condition	Good	
sandwiched betw 46) Description of enviro	ws with the three small fixed windows een. The small windows are multipaned.	24) 25) 26)	changes - additions/alter- ations/moved condition visible from road?		
sandwiched betw 46) Description of enviro	ws with the three small fixed windows een. The small windows are multipaned.	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road? distance/frontage		5)
sandwiched betw 46) Description of environ 47) Information sources	ws with the three small fixed windows een. The small windows are multipaned.  Inment/outbuildings  Sanborn 1910	23) 24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?		
sandwiched betw 46) Description of enviro	ws with the three small fixed windows een. The small windows are multipaned.  nment/outbuildings  Sanborn 1910	23) 24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?		5)
sandwiched betw 46) Description of environ 47) Information sources	ws with the three small fixed windows een. The small windows are multipaned.  Inment/outbuildings  Sanborn 1910	23) 24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?		5)
sandwiched betw 46) Description of environ 47) Information sources	ws with the three small fixed windows een. The small windows are multipaned.  Inment/outbuildings  Sanborn 1910	23) 24) 25) 26) 27) 28) 29; 30,	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	-	5)
46) Description of environment of the second	ws with the three small fixed windows een. The small windows are multipaned.  Inment/outbuildings  Sanborn 1910  Roll 65 #14-17 + 36	23) 24) 25) 26) 27) 28) 29; 30,	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	- - - - Yes	5)
46) Description of environment of the second	ws with the three small fixed windows een. The small windows are multipaned.  Inment/outbuildings  Sanborn 1910  Roll 65 #14-17 + 36  DDD	23) 24) 25) 26) 27) 28) 29; 30,	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	Yes No	5)
46) Description of environment of en	ws with the three small fixed windows een. The small windows are multipaned.  Inment/outbuildings  Sanborn 1910  Roll 65 #14-17 + 36	23) 24) 25) 26) 27) 28) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	- - - - Yes	5)
46) Description of environment of en	ws with the three small fixed windows een. The small windows are multipaned.  Inment/outbuildings  Sanborn 1910  Roll 65 #14-17 + 36  DDD	23) 24) 25) 26) 27) 28) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	YesNo	5)
46) Description of environment of en	ws with the three small fixed windows een. The small windows are multipaned.  Inment/outbuildings  Sanborn 1910  Roll 65 #14-17 + 36  DDD	23) 24) 25) 26) 27) 28) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	Yes No	5)
46) Description of environment of the second	ws with the three small fixed windows een. The small windows are multipaned.  Inment/outbuildings  Sanborn 1910  Roll 65 #14-17 + 36  DDD  Missouri Heritage Trust	23) 24) 25) 26) 27) 28) 30] 31] 32]	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	Yes No No No	5)
46) Description of environment of the second	ws with the three small fixed windows een. The small windows are multipaned.  Inment/outbuildings  Sanborn 1910  Roll 65 #14-17 + 36  DDD	23) 24) 25) 26) 27) 28) 30] 31] 32]	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica	Yes No No No	5)
46) Description of environment of the second	ws with the three small fixed windows een. The small windows are multipaned.  Inment/outbuildings  Sanborn 1910  Roll 65 #14-17 + 36  DDD  Missouri Heritage Trust	23) 24) 25) 26) 27) 28) 30 31 32	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district	Yes	5)
46) Description of environment of the second	ws with the three small fixed windows een. The small windows are multipaned.  Inment/outbuildings  Sanborn 1910  Roll 65 #14-17 + 36  DDD  Missouri Heritage Trust	23) 24) 25) 26) 27) 28) 30, 31, 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible?	Yes No No No Yes	5) 6) 7)
46) Description of environment of the second	ws with the three small fixed windows een. The small windows are multipaned.  Inment/outbuildings  Sanborn 1910  Roll 65 #14-17 + 36  DDD  Missouri Heritage Trust	23) 24) 25) 26) 27) 28) 30) 31 32 33 34 35	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible?	Yes No No Yes No Yes No No Yes	5)
46) Description of environment of the second	ws with the three small fixed windows een. The small windows are multipaned.  Inment/outbuildings  Sanborn 1910  Roll 65 #14-17 + 36  DDD  Missouri Heritage Trust	23) 24) 25) 26) 27) 28) 30) 31 32 33 34 35 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible?	Yes No No No Yes	5) 6) 7)

A narrow band of smooth cast concrete blocks separates the first story from the second. By the line the blocks are fashioned to imitate rough faced stone set in coursed ashlar pattern. There is a water table of smooth cast concrete ca. 6 inches wide with a slight pitch outward. Below the foundation is the same as the first story level wall treatment. The massive front porch with its single roof pitch of one story is carried on smooth cast concrete columns. The porch roof is covered with the same red ceramic tile. There are cornice braces identical to those found at the eaves of the house and there are diagonal braces between the posts. The porch walls are of rough faced cast concrete with the angled water table carried around the porch as well. The porch parapet wall is smooth cast concrete blocks with cast concrete coping.


There are small fixed windows giving into a front parlor in the northeast angle of the house with leaded glass windows set in a diamond pattern.

The porch carries around the east elevation to fill in the angle created by the projecting wing on that side, and actually projecing a few feet beyond to accommodate stepped entrance to the porch and a second entryway in the wall angle.

On the west elevation is a square bay window two stories in height fashioned so that the roof and eaves cover the bay. On the south elevation there was originally a two story open porch with a single pitch covered with the red ceramic tile roof found elsewhere on the house. The porch has since been filled in.

GRALL GOD

in I likelyet



41

GR 101 103



	division of Parks and Historic Preservation Dep		•	
38) Ownership — private — public	X	- 1	inventory number name (cont)	13
39) Owners — name	Elizabeth Rich		name (cont)	Grey Gables
— address	4141 Ridge Drive	1 .	street address	822 E. Walnut
40) Local contact	4141 Kluge Drive	'	town or vicinity	Springfield
41) Coordinates (UT)	1	i i	legal description	E.T.Robberson's Add.
42) Quad			county	Greene Lot 3
43) Other survey	A CONTRACTOR OF THE MARKET CONTRACTOR OF THE STATE OF THE		category	dreene Loc 3
•			(site, structure,	
			building, object)	Building
44) History		9)	significance	Architectural
			date	ca. 1895
		11)	style	Queen Anne
		12)	architect	
		13)	builder	particular and the control of the co
		14)	original use	Residence
			present use	Apt. House
45) Additional description	The entire front elevation is dominated	16)	number of stories	2-1/2
by a wide pedi:	mented gable. The pediment is recessed	17)	plan shape	Irregular
•	ly inward from the cornice. The sur-	1	basement	Full
	diment is shingled. A double window is		foundation	Rough, faced, coursed
	gable with a fan shaped window head	ì	wall construction	Frame/ ashlar limeston
	Ed. There is a second smaller cornice	[21)	roof type -	Lap Staing
	th the window head which brings the pedi	-	material	Mu ti-gable
	s recessed position. Wooden modillions	22)	contact print	Asphalt Shingle
are set at thi	s cornice line. Shingles cover the		35mm	
second pedimen	t to the apex of the gable. Window sur-			
	front elevation and throughout the house			
are simple una	dorned boards. At the second story leve	1		
jabove the ent	ryway is a fixed window with leaded glas	S		
set in a diam	ond pattern. Above the entryway is a			
pedimented po	rch roof whose surface is plastered in a ment/outbuildings continued page 2	337	site plan	
To the rear of	the house is a one story frame addition	(23)	Site plan	
	foundation and with simple gables. Over			
	e west elevation is an elaborate wooden	= 1		
	It is to the west of this building that			
	stern is located with a cast iron pump			and the second s
47) Information sources	still in place. Sometime in the early	. (24)	changes -	Wing added to the rear
•		<b>′</b>	additions/alter-	ca. 1910.
At the rear of	Continued page 2. the property is a gable roofed frame out		ations/moved	
building with h	card and batten walls, with shed roof	25)	condition	Good
wings, with mul	ti-bay garage openings. Probably ca.	26)	visible from road?	_
1930.	Janage openings. Hobubity ca.	27)	distance/frontage	_
· ·		1 .	accessible?	-
48) Location of negatives	Roll 69 #18-29	29)	preservation	
	NOTE 09 #10-29		underway?	No
49) Prepared by	DDD	30)	endangered?	No
		31)	on National	
50) Organization	Missouri Heritage Trust		Register?	No
	-	32)	part of	
			established	1
			historical district	No
If additional space is neede	attached separate sheets	33)	name of historical	
		24	district	
# *			is site eligible?	Yes
		1	district potential? date	110
		1	revision	Feb. 6, 1984
		37,	, 10131011	
HICTORIO INVESTOS.	17. A.S.			
HISTORIC INVENTORY FO	F 805			

## Continued from 45.

foliate pattern. The porch cornice has a dentiled pattern which is carried around the entire porch on the west elevation. Below the cornice is a plastered frieze also picked out in a floreate design motif. Porch posts are of wooden columns with cast plaster capitals (photo). Some of the porch posts may have been replaced at a later date with wooden Tuscan capitals which seem to occur at irregular intervals.


The porch is supported by the columns resting on stone pillars which rise up flush with the porch balustrade. The stonework is rough faced ashlar. The balustrade is of wood with simple delicate turned balusters. The porch floor and support structure are of wood. Underneath the porch floor is what may be the original jigsaw cutout latticework covering the spaces between stone pillars.

The porch curves around the house along the west elevation. The house itself goes through some unusual changes which are best seen in the drawings made of the roof plan (Ref#). There is a three story tower at the corner of the house giving definition to the curved space of the porch further accenting its presence. Window sashes are curved to accommodate the curved surfact of the tower. The tower roof is bell cast with a metal finial cap. At the eaves of the west elevation is found a built in gutter system with a wide projecting eave with modillions at the cornice. There is a dentil pattern found on a very narrow frieze board. The gable in the west elevation is shingled without the recessed area found on the front gable. There are corner scrolled brackets at the corniced gable ends (photo).

There is another primary entrance to the house at the west projecting wing. Part of the wing itself is cutout in order to accommodate more space at this second formal entrance. The porch takes a 90 degree turn and extends further westward to create an ample porte cochere. The porte cochere carries the same plaster worked frieze as does that found below the cornice on the front pedimented porch. The porch roof, however, is hipped over the porte cochere. The steps leading from the ground to the side entrance are of very rough faced ashlar coursed limestone with limestone steps.

### Continued from 46.

1930s? the house was converted to genteel apartments. At that time the entrance on the west facade received its present antechamber done in the rather heavy classical style popular at that time. The door surround is fluted with a pediment above the doorway. An intercom system operated from this location. Each apartment has a microphone on a cord and a broad grill over a speaker. The second floor apartment (front) has its original bathroom fixtures (1930s) of white porcelain. The walls of the bathroom are done in polychroned tile. Closets had veneered fallfront chests built in to them. The kitchen has its original cabinet work with the bright plastic handles common of the period. Original woodwork much in evidence. The hall and staircase are done in oak with an oak newel post. Door and window openings have fluted surrounds with bulls eye corner blocks.



GR H. 66568)



Missouri Historic Architectural Inventory for Color of Color of Color of Parks and Historic Preservation Department of Natural Resources


	ivision of Parks and Historic Preservation Depa			
38) Ownership — private	у.	[ I)	inventory number	12
— public		2)	name (cont)	Sorosis House
39) Owners — name		3)	name - historial	Massey House
— address		4)	street address	838 E. Walnut
40) Local contact		i	town or vicinity	Springfield
41) Coordinates (UTM	3	6)	legal description	
42) Quad		7)	county	Greene
43) Other survey	The second secon	8)	category	\$ 1 0.0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
		İ	(site, structure,	Building
		1	building, object)	
44) History	Built 1894-1895 by Frank R. Massey,		significance	Architectural-Social
	then Vice President of Keet-Rountree	1	date	1894-1895
	Shoe Co.	ì	style	Queen Anne
		i	architect	
		1	builder	
		1	original use	Residence
			present use	Empty
45) Additional description	At the northwest corner there is an eigh	16)	number of stories	2-1/2
sided tower wil	the flat roof and a heavily moulded			Irregular
	half story level of the tower (above the	1	basement	Full
	has single light fixed sash window		foundation	Rough, faced, coursed
	second story level has multi-paned upper		wall construction	Frame/ ashlar limeston
	light windows and the first story has one		roof type -	frame/vinyl siding
	sash. The eaves of the house project		material contact print	Gable Asphalt Shingle
	ard modillions beneath. There are two	(22)	·	
	onto the flat roof porch. Each door has		35mm	!
	panels. There is a gabled-slightly			!
	on the facade with a double window oper	1		
	ver line light sash. Cornice returns set			
. <b>če</b> . L				
orr the pearm	ent with very slight simple brackets with	۱		i,
	ent with very slight simple brackets with nackets <mark>at the corners of the eave</mark> s	1		,
accentuated b	mackets at the corners of the eaves		site plan	. ,
	mackets at the corners of the eaves		site plan	
accentuated b	mackets at the corners of the eaves		site plan	
accentuated b	mackets at the corners of the eaves		site plan	
accentuated b	mackets at the corners of the eaves		site plan	
accentuated b	mackets at the corners of the eaves		site plan	
accentuated b	mackets at the corners of the eaves	23)	site plan	
accentuated by 46) Description of environ	mackets at the corners of the eaves ment/outbuildings  Historic Site Board File	23)		
accentuated by 46) Description of environ	mackets at the corners of the eaves	23)	Changes -	Vinyl Siding added.
accentuated by 46) Description of environ	mackets at the corners of the eaves ment/outbuildings  Historic Site Board File	[24]	changes - additions/alter-	
accentuated by 46) Description of environ	mackets at the corners of the eaves ment/outbuildings  Historic Site Board File	[23) [24] [25]	changes - additions/alter- ations/moved	Vinyl Siding added.
accentuated by 46) Description of environ	mackets at the corners of the eaves ment/outbuildings  Historic Site Board File	23) 24) 25) 26)	changes - additions/alter- ations/moved condition	
accentuated by 46) Description of environ 47) Information sources	mackets at the corners of the eaves ment/outbuildings  Historic Site Board File	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	
accentuated by 46) Description of environ	Historic Site Board File City Directory 1894-1933	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	
accentuated by 46) Description of environ 47) Information sources	mackets at the corners of the eaves ment/outbuildings  Historic Site Board File	(25) (26) (27) (28) (29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	
accentuated by 46) Description of environ 47) Information sources	Historic Site Board File City Directory 1894-1933	(25) (26) (27) (28) (29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	Good
accentuated by 46) Description of environ 47) Information sources 48) Location of negatives	Historic Site Board File City Directory 1894-1933	(25) (26) (27) (28) (29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	Good - - No
accentuated by 46) Description of environ 47) Information sources 48) Location of negatives	Historic Site Board File City Directory 1894-1933  Roll 16 #19-25	23) 24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	Good - - No
accentuated by 46) Description of environ 47) Information sources 48) Location of negatives 49) Prepared by	Historic Site Board File City Directory 1894-1933	23) 24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	Good - - No Yes
accentuated by 46) Description of environ 47) Information sources 48) Location of negatives 49) Prepared by	Historic Site Board File City Directory 1894-1933  Roll 16 #19-25	23) 24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	Good  No Yes  No
accentuated by 46) Description of environ 47) Information sources 48) Location of negatives 49) Prepared by 50) Organization	Historic Site Board File City Directory 1894-1933  Roll 16 #19-25  DDC  Missouri Heritage Trust	(25) (26) (27) (28) (29) (30) (31) (32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	Good - - No Yes
accentuated by 46) Description of environ 47) Information sources 48) Location of negatives 49) Prepared by	Historic Site Board File City Directory 1894-1933  Roll 16 #19-25  DDC  Missouri Heritage Trust	(25) (26) (27) (28) (29) (30) (31) (32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	Good  No Yes  No
accentuated by 46) Description of environ 47) Information sources 48) Location of negatives 49) Prepared by 50) Organization	Historic Site Board File City Directory 1894-1933  Roll 16 #19-25  DDC  Missouri Heritage Trust	23) (24) (25) (26) (27) (28) (29) (30) (31) (32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	Good  No Yes  No No
accentuated by 46) Description of environ 47) Information sources 48) Location of negatives 49) Prepared by 50) Organization	Historic Site Board File City Directory 1894-1933  Roll 16 #19-25  DDC  Missouri Heritage Trust	24) 25) 26) 27) 28) 30) 31) 32) 33)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	Good  No Yes No No
accentuated by 46) Description of environ 47) Information sources 48) Location of negatives 49) Prepared by 50) Organization	Historic Site Board File City Directory 1894-1933  Roll 16 #19-25  DDC  Missouri Heritage Trust	23) 24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	Good  No Yes No No No
accentuated by 46) Description of environ 47) Information sources 48) Location of negatives 49) Prepared by 50) Organization	Historic Site Board File City Directory 1894-1933  Roll 16 #19-25  DDC  Missouri Heritage Trust	23) 24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35) 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	Good  No Yes No No
accentuated by 46) Description of environ 47) Information sources 48) Location of negatives 49) Prepared by 50) Organization	Historic Site Board File City Directory 1894-1933  Roll 16 #19-25  DDC  Missouri Heritage Trust	23) 24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35) 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	Good  No Yes No No No

obscured by the modern siding. At the second story level is a tripled window opening with multi-paned lights over one light. At the first story level the wing overhangs with simple brackets beneath. The first story window opening is large, fixed with simple leaded glass lights. The entry has a pair of leaded glass fixed window lights to the right side of the entry vestibule.

There is a full porch across the facade except in front of the tower. The porch continues around the east side of the house until it meets with a projecting wing. The porch is open at the angle of the house and in front of the facade wing. The two covered porch areas have flat roofs with broad eaves, dentiled cornice and wide entablature. At each porch corner is a square pillar of ashlar stone work while at either side of the pillars are limestone columns with tuscan capitals and limestone plinths. The whole rests on an ashlar stone parapet. The porch floor and steps are concrete.

On the east side elevation there is a projecting gable wing with a one-story bay with multi-window openings. Across the rear of the house is a glass filled two story shed roof sun porch. Above on the roof face is a shed roof dormer. The interior remains intact with two exceptions. The servants' stairs have been partially removed to provide a kitchen area on the second floor. The wall between the two front bedrooms on the second floor has been removed.

On the first floor large multi-light panel doors open the entire space with the exception of the kitchen area. There are carved wooden fireplace mentles with decorative tile work surrounds and hearths which may also be found on the second floor in the two front bedrooms. Moulded cornice work is found in all rooms on the first floor. The kitchen appears to be ca. 1915. The bathroom on the second floor appears to be original with all original interior fixtures.



GR-AS-6-23-6-20




	Division of Larks and Historic Liescivation Dep	artn	icht of Hature	ii iicouroco	
38) Ownership — private	X *	1)	inventory number	58	]=
— public		2)	name (cont)	McCann-Jewell House	7
39) Owners — name	Barbara Rosen	(3)	name - historial	TICOGITI OCWETT TIOUSE	1
— address	900 E. Walnut	1 '	street address	900 E. Walnut	
40) Local contact		1 .	town or vicinity	Springfield	
41) Coordinates (UT	M)	1	legal description	E.T. Robberson's Add.	
42) Quad			county	Greene Lot 6.	
43) Other survey		8)	category		2/3)
Historic Sites	Board.		(site, structure,		55
			building, object)	Building	
44) History			significance		
	Built 1896 By Charles McCann. While		date	ca. 1896?	_
	was president of Springfield Wagon Co.		style	Queen Anne	_
	ught_in 1917 owner of Springfield Leader	L	architect	Arch-Commercial	_
	3+. Two story with attic story frame con-		builder	Henry Kidd	_
	h faced ashlar coursed limestone foundati			Residence	
	n the front facade with pedimented gable		present use	Residence	<u> </u>
45) Additional description		1 '	number of stories	2	<u>4</u>
	ice. Doubled windows with nine over one		plan shape	Irregular	]
	Moulded cornice with narrow frieze board		basement	Full	_
	cting eaves. Lap siding covers the en-	1	foundation	Rough faced coursed	
	ojecting wing with gable on front eleva-	1 '	wall construction	Frame/ ashlar limesto	he
	r cut outs. Cornice returns with recesse	d21)	roof type -	1 lcp siding	
	setting off pediment. Modillions under			multi asphalt gable	ļ
	e gable. Nine light fixed sash in the		contact print	Shingle	5)
	ied moulding at window head. Butt shingl		35mm	•	
	of the pediment. Second story windows a	ηe	·	-	
	ht double hung. Between the first and			· .	
	ere is a "skirt" belt about four feet in				
	ed with butt shingles. There are narrow				
	ds defining the upper and lower limits of				
the skirt. Fir 46) Description of environment	st story windows of the front and west el		-ik		10
46) Description of enviror	ment/outbuildings	23)	site plan		9)
A large frame o	utbuilding survives behind house on the				
alley. Board a	nd batten walls gabled with jerkinheads	3	+		
at the apex. O	riginal use as carriage house and storage				
	ase as out rage house and storage				
47) Information sources		24)	changes -		5
		- ',	additions/alter-		
Sanborn 1910	C. L. D I		ations/moved	Rear deck modern	
	oric Site Board	25)	condition	04	-
City Directory	1916-1933		visible from road?	Good	1
	•	_	distance/frontage		1
			accessible?		9
48) Location of negatives	Roll 69 #30-33, 42-93-44,1	1 .	preservation	_	┨
	NOTE 09 #30-33, 42-93-44,1		underway?	No	
49) Prepared by	DDD	30)	endangered?	No	1
		31)	on National		1
50) Organization	Missouri Heritage Trust		Register?	No.	<u> </u>
	missouri heritage must	32)	part of		7
			established	No	
			historical district	110	
lf additional space is neede	d, attached separate sheets.	33)	name of historical		1
			district	_	1
		1	is site eligible?	Yes	ļ
			district potential?	Yes	30)
		36)	date	Jan. 25, 1984	

vations have diamond patterned leaded glass upper window sashes over one light. Sidelights and transom frame the entryway set in the angle of the L-shape front elevation.

A porch fills the front elevation. Shed roofed with a moulded cornice and plaster entableture set with "Swag" motif. Doubled sets of columns support the porch roof. Columns are cast iron fluted shafts with cast iron Corinthian capitals. Plinths are square wood paneled and continue to the foundation. Wooden balustrade with moulded hand rail and turned balusters. Wooden porch floor and support system.

On the west elevation is a porticoed entrance which echoes the front porch with entablature decoration cast iron columns, etc. There is a low retaining stone wall at the sidewalk on the north and west. Sides of the property. Rough coursed ashlar limestone with pecked stone coping. The wall curves and steps flanking at the street entry. Steps themselves are also limestone.





CR-AS CKNOW



### Missouri Historic Architectural Inventory for G (2 (2000) 2000) Division of Parks and Historic Preservation Department of Natural Resources

	т	· · · · · · · · · · · · · · · · · · ·		
38) Ownership — private X		inventory number	57	=
— public	1	name (cont)		
39) Owners—name E. C. Horner	1 '	name - historial		
—address 910 E. Walnut	1 '	street address	910 E. Walnut	
40) Local contact	1	town or vicinity	E. T. Robberson's Add.	1
41) Coordinates (UTM)		legal description	Springfield Lot 7	
42) Quad		county	Greene	
43) Other survey	(8)	category		2/3)
		(site, structure,		<u> </u>
		building, object)	Building	
44) History	9)	significance	Architectural-Medical	
Build ca 1885-1887 by Dr. Walter Camp	10)	date	ca. 1885-1887 history	l
physician/opthamologist). descendants still live in	11)	style	Queen Anne	1
house. Shed dormer on the front elevation appears to	12)	architect		1
be a later addition front projecting wing with gable	13)	builder		1
creating an L-shaped facade. Scolled brackets at the	14)	original use	Residence	
corner of the eaves in the gable. Gable is pedimented by	y15)	present use	Residence	1
45) Additional description		number of stories	2	4
two horizontal boards flush with thewall. Between the	17)	plan shape	irregular	1
boards are narrow vertical moulded boards. Above this	18)	basement	full	1
"frieze" five vertical boards rising to meet a narrow		foundation	Rough; faced; coursed;	1
board frieze under the eaves. The apex is filled with a	20)	wall construction		1
fan shaped wooden panel which serves as window head to		roof type -		ne
doubled window openings. The surrounds are the two		material	<u> Sidilid</u>	
center vertical boards which are continuous downward to	22)	contact print	Gable asphalt shingle	5
the foundation. The remaining area of the pediment as	,	35mm		
		3311111		
well as the rest of the house is covered with lap siding The vertical boards act as surround to the second story	1			
				1
window and the first story window as well. The "frieze"				
roken of before acts as the head of the window which is				
one over one light sash. Another horizontal board	.			
frames the window at the sill. Separating the first and		alka mtan		9
46) Description of environment/outbuildings	23)	site plan		=
There are two out buildings standing behind the house.	-			
Frist is a small gabled one-story building with formed				
concrete walls. The other is one-story frame walls				
covered with board and batten. Oriinally used as a				
carriage house and storage.	0.4	<del></del>		(J)
47) Information sources	24)	changes -		9:
Sanborn 1910		additions/alter-	additions at rear el.	1
∂wner	Í	ations/moved		_
Sity Directory 1884-1933	1	condition	in need of repair	
5 to 5 to 5 to 5 to 5 to 5 to 5 to 5 to	1 '	visible from road?		
		distance/frontage		
		accessible?	-	6)
48) Location of negatives	29)	preservation		
Roll 547-4 #19-20	1	underway?	No	╛
49) Prepared by Roll 69 #34-41	30)	endangered?	No	
DDD Roll 1 #31	31)	on National		
50) Organization Roll 27 #29-33		Register?	No	
1011 LI TLJ-33	32	part of		
Missouri Heritage Trust	1	established	N.	
	-	historical district	No	
If additional space is needed, attached separate sheets	33	name of historical		]
	-	district		
	34	) is site eligible?	Yes	1.
•	35	) district potential?		30)
	36	) date	1-25-84	_]
	37	) revision		]
	1			1

recond stories is another board below which the corners of the wing are chamtered to make tree faces to the facade of the wing. There are solid brackets at the corners with carved fan motifs (see photo). First story window one over one light sash framed in same fashion as the second story window.

There are windows in the corners of the wing with one over one light sash.

The entry is in the angle of the L-shaped facade with a later vestibule projecting from the entryway.

The eaves of the roof on the long side project slightly and are set off with scrolled brackets which are set on the frieze board which is the window head to two second story windows. The brackets are set above the vertical board window surrounds.


Shed roofed porch fills the facade and continues partially around the east elevation. It is shed roofed though with a pedimentimented gable above the entryway. There is a continuous cornice with scrolled brackets set even with the posts. The face of the pediment is covered with a wooden fan decoration matching the wing gable apex.


The porch has a turned spingle open establature. There are turned porch posts with half hemispherical spoked brackets.

Wooden balustrade with moulded handrail and turned balusters.

West elevation-

re is a slightly projecting wing with the same details as the front gabled wing. The well to the south, however, instead of being recessed is flush with the wing. The cut out or chamter at the first story becomes a pieslice V-shaped with windows at either face. A similar treatment is executed at the second story level to distinguish the wing from the wall of the house (see photo). The roof level of the wall has a panelled parapet with a decorative pressed tin face. There is a moulded cornice under the panels with spaced brackets. At the southwest corner of the house is an eight sided tower with eight sided roof. There are modillions at the cornice of the tower eave. The three west facing faces of the tower have windows. The third story has fixed six lite sashes while the others are double hung with one over one light sashes. There is a band or moulded cornice separating the first from the second story. Below the cornice are single panels on each face with applied plster decorations. East elevation—there is a hipped gable or jerkin head with scrolled brackets in the corners under the eaves. Four multi-paned fixed sash windows fill the gable.







#### Missouri Historic Architectural Inventory for Color Co


•					
38) Ownership — priva	te X	1)	inventory number	56	Ξ
publ	ic ·	2)	name (cont)		
39) Owners — name	Jack Hood	3)	name - historial		1
address	1140 S. Farway	4)	street address	916 E. Walnut	
40) Local contact		1	town or vicinity	Springfield	
41) Coordinates (	(MTL	1	legal description	E. T. Robberson's Add.	
42) Quad		7)	county	Greene Lot 8	
43) Other survey	And the state of t	8)	category		2/3)
			(site, structure,		ω
			building, object)	Building	
44) History		9)	significance	Architectural-contribut	ina
		10)	date	Ca 1905	פיין
		11)	style	Catalogue/builder with	1
		12)	architect	classical deta	110
		13)	builder		1 13
		14)	original use	Residence	
		15)	present use	Apts.	1
45) Additional descrip	tion Engate allowation and appropriate at	16)	number of stories	2	4
Drojostina	front elevation - presents L-shape to st			irregular	1
	with peaimented gable. Continuous cor-		basement	full	1
	ojecting eaves throughout on house.	19)	foundation	Rough, faced, coursed,	1
	small attic window fixed sash with simple	20)	wall construction	frame/ ashlar limes	tono
	the window head. The face of the pedi-	21)	roof type -	lap siding	Lone
ment is covered	with butt shingles. The frieze board is			gable & hip combination	1
the head of the	windows at the second story level. Simple	22)	contact print		5
one over one 11	ght sash thrughout house. Iransom over the	2	35mm	asphalt	
	of L on facade. First story windows have			shingle	
	g to the window heads. Porch fills the L-	ŀ			
	d continues around the east elevation.				
	e over the entry on the porch with a	1			
	cornice. Butt shingles in the pediment.				
Another pedimen	t looking eastward on the northeast corner	-			
of the porch, n	arrow establature with narrow round wooden ironment/outbuildings	221	-141		9
46) Description of env	ironment/outbuildings	23)	site plan		<b>S</b>
		-			
			<del></del> .		1.5
47) Information source	<b>e</b> s	24)	changes -		5
	Sanborn 1910		additions/alter-	dooming out in NE	İ.,
			ations/moved	doorway cut in NE corne	ar
	City Directory - 1933	25)	condition	of east gable wing	
		26)	visible from road?	Good	]
		27)	distance/frontage	_	
		28)	accessible?	-	6)
48) Location of negati	ves	29)	preservation		1
	Roll 27 #34-35		underway?	No	
49) Prepared by	DDD	30	endangered?		
	DDD	31)	on National	No	7
50) Organization		1	Register?	No	
, <b>-</b>	Missouri Heritage Trust	32	) part of		2
			established		
			historical district	No	
If additional space is ne	reded, attached separate sheets.	33	) name of historical		
add.tional apole is ne			district	_	
)		34	) is site eligible?	N	
/		1	) district potential?	No	30
			) date	<del>res</del>	75
		- 1	) revision	Jan. 25, 1984	+
		],	,		1

columns with tuscan capitals.

Wood balustrade with moulded handrail and turned balusters. Wood porch floor and support stem. A door has recently been cut at the northeast corner to admit into a second apartment.

East elevation - projecting wing has corner chamters at both stories.

NS.





Missouri Historic Architectural Inventory for Garage Color Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	x . *		inventory number	55	٥
public			name (cont)		]
39) Owners — name	Crystal Cron et al	1	name - historial		
address	920 E. Walnut	1 '	street address	920 E. Walnut	
40) Local contact 41) Coordinates (UT	M)		town or vicinity	Springfield	
42) Quad	( <b>V</b> 1)	1	legal description	E.T. Robberson's Add. Lot	1
43) Other survey			county	Greene 9	
45) Other survey		87	(site, structure,		2/3)
			building, object)	Building	
44) History	Built 1911-1912 by Gaylord Douglas -	9)	significance		
,,	maker of farm loans		date	Architectural-Contribu-	1
	maker of farm roams	1 .	style	1911-1912 ting Four Square	-
			architect	Tour Square	-
		13)	builder		1
		14)	original use	Residence	1
			present use	Apts.	1
45) Additional descriptio	Front claustion lauge mabled will down	16)	number of stories	23	4
dominatos tha f	Front elevationlarge gabled wall dorme			Square	1
	acade with broken cornice. Simple s at the eaves of the gable. The face	1 .	basement	Full	1
	is filled with modern steel siding.		foundation	Cast Stone	
There is a trin	led window centered in the gable. A narr	[20]	wall construction	Cast Stone	
dentiled and mo	1ded cornice defines the pediment on line	( <u>177</u> )	- ·	Hip	
	of the house. The eaves project widely		material	Asphalt Shingle	L
	th modillions and dentiled cornice all	22)	contact print 35mm	· ·	5)
around the hous			3311111		
	If is of case-stone blocks in imitation				
of smooth ashla	r stone construction. First there is a				
wide band of sm	mooth blocks then a very narrow bank of				
rough faced	blocks, followed by a thin moulded cast-				
scone band with	another course of wide smooth faced				
46) Description of enviro	nment/outbuildings	23)	site plan		9
	garage hasbeen in place for a number of		·		
	cult to tell how long. It is of frame				
	th a foundation of rough faced cast stone				
	•				1
					İ
47) Information sources		24)	changes -		5
HSB material Fi	le		additions/alter-		
Sanborn 1910			ations/moved	None visible	
City Directory	1910-1933.	1 .	condition	Good	1
•		1 .	visible from road?		-
		1	distance/frontage accessible?		_
48) Location of negatives		1 '	preservation	<del>-</del>	၅
40) Location of negatives	Roll 27 #36-42	23,	underway?	No	
49) Prepared by	DDD	30)	endangered?		1
43) Trepared by	פטט		on National	No	-
50) Organization	Missouri Heritage Trust	,	Register?	N -	
, <b>-</b>	missouri heritage frust	32)	part of	No	2
			established		1
		1	historical district	No	
If additional space is need	ed, attached separate sheets.	33)	name of historical		1
			district		
(			is site eligible?	Yes	<u> </u>
		- 1	district potential?	Yes	30)
			date	Jan. 25, 1984	4
		3/)	revision		1
		1		1	1

Que Free March

#### 10 E. Walnut

blocks. The wall surface at the second story level is of rough textured cast-stone ashlar and coursed.

The final frieze band of smooth blocks act as window heads to the second story windows. There are smooth limestone sills. The facade is three bays. The windows are one over one light sash. A hipped roof porch covers the entire facade with wide projecting eaves, and a very narrow entablature. Porch columns are round smooth limestone tapering upward. The capitals are square limestone blocks with rough outerfaces. The plinths are the same. The ceiling of theporch is of pressed metal in a floreate design. The porch floor is laid with encaustic tile in a black and white geometric pattern.

Between the first and second stories is a band of smooth cast-stone blocks with a narrow band of moulded cast stone above. The belt course is just visible under the porch on the front facade. Above the windows and door the lintles are legitimate dressed limestone. There are sidelights and transom surrunding the entrance with beveled glass.

Smooth dressed limestone coping stone on the porch parapet which is constructed of rough faced cast-stone.


Below the parapet is a band of smooth dressed limestone as a water table which is continuous around the entire house as well as the porch. Below this line the rough faced cast stone continues to the ground on the porch but on the house smooth cast stone is used to the ground level.

I re are gabled dormers in all three faces of the roof each withcontinuous cornices faced with steel siding, and with doubled windows.

An original two storyshed roofed sun porch exends across the rear of the house.

CV - 1103-076

51





## Missouri Historic Architectural Inventory for (-1)

Division of Parks and Historic Freservation Depa			
38) Ownership — private X	1) inventory number		۳
public	2) name (cont)	Reps House	4
39) Owners — name Wirt Development Co.	3) name - historial		
—address P. O. Box 4949	4) street address	935 E. Walnut	
40) Local contact	5) town or vicinity	Springfield	1
41) Coordinates (UTM)	6) legal description	Irregular Survey 169 Lo	<u>a</u> t
42) Quad	7) county	Greene L.	<u> </u>
43) Other survey	8) category		2/3)
Historic Site Board	(site, structure,		186
Springfield Historic Site	building, object)		
44) History	9) significance	Architectural-Commercia	1
Build 1903 by F. A. Sieberman, a St.	10) date	1903	٦.
Louis executive &Financier, for Wm. Reps of Reps	11) style	Queen Anne	_
Dry Goods Co.	12) architect	queen Anne	7
J =	13) builder		-
	14) original use	Residence	┪
	15) present use	empty	┨
45) Additional description West elevation - the gable which domi-	16) number of stories		4
	17) plan shape		٦
nates this elevation has a staggered butt shingle	18) basement	irregular	$\dashv$
covered face and continuous cornice. The eaves of the	19) foundation	full	4
gable project with modillions beneath. The gable has a	,	rough, faced, coursed,	4
noticeable bell-cast. Inside the gable is a single	20) wall construction	Frame/ dantal timestor	<u>1</u> e
window opening with one over one light sash. The cor-	21) roof type	st <u>eel siding</u>	_
nice frieze acts as the window head to the second story	material	Gable asphalt shingle	
window openings. All window openings on the house have	22) contact print	· omigic	5
one over one light sash.	35mm		-
Eight sided. The tower on the suthwest corner of the hou	se		
begins at the second story level and extends above the			
roofline with a bellcast eight sidied hip roof with a			
metal finial cap. There are modillions beneath the			}
eaves on the tower roof. The cornice frieze beneath			
acts as the window head to the attic story window opening			
46) Description of environment/outbuildings	23) site plan		و
TO) Description of entironmendoatounumgs		A STATE OF THE STA	
Behind the house is a one story bellcast hip roof carri-	Į.	e de la companya de la companya de la companya de la companya de la companya de la companya de la companya de La companya de la companya de la companya de la companya de la companya de la companya de la companya de la co	
age house and storage building of frame construction			1
with applied moulding to door and window by the All		•	
with applied moulding to door and window head. All			
window sash is one over one.	04) -1		(P
47) Information sources	24) changes -	Stool siding added	5)
"Done House of Oor Feet H. T	additions/alter-	Steel siding added	
"Reps House at 935 East Walnut in Springfield, Missouri,			_
Wm. Henson, Susan Ray 1981 on file Historic Site Board.	25) condition	Good	
	26) visible from road		
	27) distance/frontag	е п	
	28) accessible?	11	6
48) Location of negatives	29) preservation		
	underway?	No	
10) Prepared by DOD	30) endangered?	No.	$\dashv$
49) Prepared by DDD	31) on National	Yes	
<b>50</b> ) 0	Register?	1	
50) Organization Missouri Heritage Trust	1	No	7
	32) part of	No	
	established		
	historical distric		_
If additional space is needed, attached separate sheets.	33) name of historic	cal	1
	district	-	
	34) is site eligible?	Yes	
	35) district potentia	Yes Yes	30)
	36) date	Jan. 25, 1984	
	37) revision		

(see photo). The walls are covered with fishscale shingle below the attic story windows with a narrow skirt separating it from the second story window openings, and beneath the windows there is another area of fishscale shingle slightly flaring and abruptly ending 1 cut flat horizontally as the tower ends at the corner with modillions beneath (see photo).


Facade -- The front elevation is dominated by a gable wall dormer with a palladian window centered in it with applied moulding to the window head. The face of the pediment within the gable is covered with fishscale shingle and the continuous cornice has modillions beneath the eaves. The cornice frieze is the window head to the second story window openings.

On the southeast corner of the house is a small circular turret with a metal conicla roof with a metal finial cap. Beneath the roof eave is a moulded cornice with the frieze as window head to the second story window openings in the turret.


The turret eave line matches the eave line on the main house mass. The face of the turret is covered with fishscale shingle. The base of the turret disappears into the roof of the purch across the facade and east elevaions of the house, and does not reappear at the first story level.

The porch has a hip roof except over the entry area where there is a gable pediment which slightly projects beyond the porch cornice line. The nornice is however continuous across the pediment. The pediment face is plastered in decorative motif with the number of the house centered in the pediment. The porch is supported on round wooden columns with tuscan capitals. The balastrade has moulded handrail and turned balusters. The porch floor and structure is of wood.

GRA - 600-607



GR-43-002-627



Reps House 935 East Walnut First floor Scale: 1/8" = 1' N

CE-A: 000.624


Bath Bedroom Orginal Sleeping Porch Bedroom Bedroom Orginal Sewing Room

959 - 1000

Rep's House--Second Floor

68 1 1 6 2 6 6 2 V

Grant house



Rep's House--Third Floor

Carlotte Colored



## Missouri Historic Architectural Inventory for Grand Section 25

38) Ownership — private	X .	l	inventory number	54	5
— public		2)	name (cont)		
39) Owners — name	M. Comstock	3)	name - historial		
— address	938 E. Walnut	4)	street address	938 E. Walnut	
√40) Local contact		5)	town or vicinity	Springfield	
→41) Coordinates (UTA	1)	6)	legal description	Ireg. Survey 167 Lot A	
42) Quad		7)	county	Greene	1
43) Other survey		8)	category		2/3)
,			(site, structure,		3)
		1	building, object)	Building	
44) History		9)	significance		1,
44) History	Built 1899-1900 by Henry H. Smalley	1	date	Architectual-Commerc	aı
DD 4.5 - And Horse	* * * * * * * * * * * * * * * * * * * *	1	style	1899-1900	1
RR tie and supp	y contractor.		architect	Queen Anne	
			builder		
		1	original use		1
			=	Residence	-
		1	present use	Residence/photo studio	_
45) Additional description	Two story attic story construction, ir-	1	number of stories	2	4
rogular nlan ch	ape, multi-gable roof shape with asphalt	1	plan shape	. Irregular	1
	faced coursed ashlar limestone founda-		basement		4
-	Taced Coursed asirrar Timescone Tourida-	/	foundation	Rough, face, coursed	]
tion.		20)	wall construction	Frame/ ashlar limes	tone
	- projecting gabled wing with pediment.	21)	roof type -	lap siding	]
	ts at the eave ends at the gable. Thin	1	material	Gable asphalt shingle	1
	setting off the pediment with small	22)	contact print	· dable asphalt shingle	5)
	ting. Doubled window in the center of		35mm		
	pediment. The frieze board beneath the	1			
pediment in the	gable is the window head to the second				
story window.	Window is tripled at the second story				
with one over o	ne light sashes. The entire second story				1
	se is covered with imbricated shingles				
	separates the first from the second				
-		021	-:41		وا
46) Description of enviro	ment/outbuildings	23)	site plan	en jaron en en en en en en en en en en en en en	٦
		1			
				en en en en en en en en en en en en en e	
				on the second of the second o	
47) Information sources		24)	changes -		5)
47) Information sources		24)	changes - additions/alter-		
·		24)	J	Porch filled in NE cor	
Sanborn 1910	899-1953		additions/alter-	Porch filled in NE cor	
·	899-1953	25)	additions/alter- ations/moved	Porch filled in NE cor	
Sanborn 1910	899-1953	25) 26)	additions/alter- ations/moved condition	Porch filled in NE cor	
Sanborn 1910	899-1953	25) 26) 27)	additions/alter- ations/moved condition visible from road?	Porch filled in NE cor	
Sanborn 1910 City directory		25) 26) 27) 28)	additions/alter- ations/moved condition visible from road?	Porch filled in NE cor	ner
Sanborn 1910		25) 26) 27) 28)	additions/alter- ations/moved condition visible from road? distance/frontage accessible?	Porch filled in NE cor	ner
Sanborn 1910 City directory  48) Location of negatives	Roll 68 #9-11, 21°, Roll 27 #1, 4377	25) 26) 27) 28	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	Porch filled in NE cor	ner
Sanborn 1910 City directory		25; 26; 27; 28; 29; 30;	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	Porch filled in NE cor	ner
Sanborn 1910 City directory  48) Location of negatives  49) Prepared by	Roll 68 #9-11, 21°, Roll 27 #1, 4377 DDD	25; 26; 27; 28; 29; 30;	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	Porch filled in NE cor Good - - - No	ner
Sanborn 1910 City directory  48) Location of negatives	Roll 68 #9-11, 21°, Roll 27 #1, 4377	25; 26; 27; 28; 29; 30; 31;	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	Porch filled in NE cor Good No	ner
Sanborn 1910 City directory  48) Location of negatives  49) Prepared by	Roll 68 #9-11, 21°, Roll 27 #1, 4377 DDD	25; 26; 27; 28; 29; 30; 31;	additions/alterations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	Porch filled in NE cor Good - - - No	en er
Sanborn 1910 City directory  48) Location of negatives  49) Prepared by	Roll 68 #9-11, 21°, Roll 27 #1, 4377 DDD	25; 26; 27; 28; 29; 30; 31;	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	Porch filled in NE cor Good  No No	en er
Sanborn 1910 City directory  48) Location of negatives  49) Prepared by  50) Organization	Roll 68 #9-11, 21°, Roll 27 #1, 4377 DDD Missouri Heritage Trust	25, 26, 27, 28, 29, 30, 31, 32	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	Porch filled in NE cor Good  No No No	en er
Sanborn 1910 City directory  48) Location of negatives  49) Prepared by  50) Organization	Roll 68 #9-11, 21°, Roll 27 #1, 4377 DDD	25, 26, 27, 28, 29, 30, 31, 32	additions/alterations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica	Porch filled in NE cor Good  No No No	en er
Sanborn 1910 City directory  48) Location of negatives  49) Prepared by  50) Organization	Roll 68 #9-11, 21°, Roll 27 #1, 4377 DDD Missouri Heritage Trust	255, 266, 277, 288, 299, 300, 311, 322, 333	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district district	Porch filled in NE cor Good  No No No	en er
Sanborn 1910 City directory  48) Location of negatives  49) Prepared by  50) Organization	Roll 68 #9-11, 21°, Roll 27 #1, 4377 DDD Missouri Heritage Trust	25; 26, 27, 28, 29, 30, 31, 32, 33,	additions/alterations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible?	Porch filled in NE con Good No No No No Yes	6) 7)
Sanborn 1910 City directory  48) Location of negatives  49) Prepared by  50) Organization	Roll 68 #9-11, 21°, Roll 27 #1, 4377 DDD Missouri Heritage Trust	25; 26, 27, 28, 29, 30, 31, 32, 33,	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district district	Porch filled in NE con Good No No No No Yes	en er
Sanborn 1910 City directory  48) Location of negatives  49) Prepared by  50) Organization	Roll 68 #9-11, 21°, Roll 27 #1, 4377 DDD Missouri Heritage Trust	25; 26, 27, 28, 29, 30, 31, 32, 33, 34, 35,	additions/alterations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible?	Porch filled in NE cor Good No No No No Yes	6) 7)
Sanborn 1910 City directory  48) Location of negatives  49) Prepared by  50) Organization	Roll 68 #9-11, 21°, Roll 27 #1, 4377 DDD Missouri Heritage Trust	25; 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36,	additions/alterations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible?	Porch filled in NE con Good No No No No Yes Yes Yes	6) 7)

story. Below that line the first story is lap sided. First story window in the projecting wing is fixed in place with multiple panes set around a large center pane. There is a small window hood over the window. The facade of the west wing of the house contains the ntry. Above there is an eyebrow window on the roof face. The northwest corner of the wing is a projecting oriel which is gabled--fish scale shingles cover the face of the oriel. There is a window with a stained glass upper sash over one light sash. The surround matches that found on the center wing first story window with simple hood. Above the window is a thin moulded cornice creating a pediment with an oculus window with fixed sash centered in the pediment.

Below the oriel the wing has its first story northwest corner cut creating two wall faces. The corner of the west wing and the projectint front wing is filled with a porch of one story The roof is shed shaped but with a gabled pediment over the entry area. The cornice is continuous and the face of the pediment is plastered with the house number and a decorative plaster motif applied.


West elevation -- the entire second story of the projecting wing on this elevation is projected over that of the first story with simple brackets underneath.

East elevation - projecting gabled wing with a doubled pediment. The first is in the apex of the gable with a sningled face. The overhanding cornice has simple modillions. Below is a second pediment area which actually encompasses the former. The frieze board of the first cornice is the window head to the doubled windows. There is a wide overhanging cornice with large brackets set close together at the angle. The second story follows the front wing in detail except that it too projects over the first story level just under the "skirt" before described with an overhanging cornice and closely spaced brackets. The first story window has an elaborately stained glass window upper sash.

A two story sum porch fills the angle created by the rear wing and the east wing that has been tly filled in recently. In the south west corner a shed roofed one story wing fills the angled space. At the sidewalk there is a smooth dressed limestone set of steps with limestone flanking wall with a curved surface. The walkway to the house is of limestone slabs.

0- 30 18 21

5



GR-45-003-000



# Missouri Historic Architectural Inventory for Company

Division of Falls and Installed Population Population	• • • • •		n Rosouroco	
38) Ownership — private X	1)	inventory number	22	۳
public	2)	name (cont)		]
39) Owners — name Harry Rowe	3)	name - historial		
<pre> address 424 Charing</pre>		street address	943 E. Walnut	]
40) Local contact		town or vicinity	Springfield	
41) Coordinates (UTM)		legal description	ireg. Survey 169 Lot K	
42) Quad		county	Greene	
43) Other survey	8)	category		2/3)
		(site, structure,		=
		building, object)		_
44) History		significance	<u>Architectual-contributir</u>	фg
		date	ca 19 <u>05</u>	1
		style	Cataloque/builder with	_
		architect	classical	_
		builder	details	_
		original use	Residence	4
		present use	Apts.	ļ
45) Additional description On the front elevation and the east ele-		plan shape	Square with wing	4
vacion there are bell cast hip domiers with projecting		basement		
eaves and modillions beneath. The walls of the dormers		foundation	Full	4
are covered with alternating bands of lap siding and	,	wall construction	Concrete	-
rish scale shingle. In each dormer there are two window		roof type -	Frame/lap siding	4
openings with one over one right sash. The east dormer	21,	material	Bell cast hip asphalt	4
has a latticed muntin upper sash.	221	contact print	shingle	5
		35mm		٦
The eaves on the main house project beyond the wall				
planes with modillions beneath. The cornice frieze acts				1
as the window head to the second story window openings.				
There are four window openings grouped together as the				
first bay on the front elevation with fifteen over one				
light sash. The second bay on the second story level				
are double doors with multi-pane door lights. The doors 46) Description of environment/outbuildings	23)	site plan	· · · · · · · · · · · · · · · · · · ·	و
				1
		•	en de la composition de la composition de la composition de la composition de la composition de la composition La composition de la composition de la composition de la composition de la composition de la composition de la	1
			a see a see a see a see a see a see a see a see a see a see a see a see a see a see a see a see a see a see a	
		•		
47) Information sources	24)	changes -		5)
		additions/alter-	Daniel all	
1910 Sanborn		ations/moved	Porch altered	_
	'	condition	Good	_
		visible from road?	-	_
		distance/frontage		_
		accessible?	-	6
48) Location of negatives Roll 27 #7, 10; Roll 2A #13-14.	29)	preservation		
	201	underway?	No	4
49) Prepared by DDD	1	endangered? on National	No	4
50) Organization N	31)	Register?	No	
50) Organization Missouri Heritage Trust	321	part of	No	77
	J.,	established		
		historical district	No	
If additional space is needed, attached separate sheets.	33)	name of historical		+
		district	_	
	34)	is site eligible?	No	7
	1	district potential?		30
	1251	date	Jan. 25, 1984	
	130)	dute	Uall. 20, 1904	
	1 '	revision	0411. 23, 1904	


give onto a flat roof porch with a balcony surrounding the edge. The balcony has square balusters and hand rail. The eaves of the porch have a dentil decorated cornice supported on fluted round wooden columns with Ionic plaster capitals. The porch balustrade on the first ory has a moulded handrail and turned balusters. The porch floor and structure are of wood.

The first story level has a three bay facade with one over one light sash and applied moulding to the window heads at each of the window openings.

On the east elevation there is a three sided oriel on the first story which appears to have been added later.

GEA,003-627

NA





## Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources

	Division of Parks and Historic Preservation Dep	artn	ient of Matura	i kesouices	
38) Ownership — priva			inventory number	53	تا
publ			name (cont)		_
39) Owners — name	Michael Murrell	1 .	name - historial		-
— address	Jan E. Walliat	'	street address	944 E. Walnut	4
40) Local contact		1	town or vicinity	Springfield	_
41) Coordinates (	U 1 (M)	1 '	legal description	Ireg. Survey 167 Lot E	3
42) Quad			county	Greene	<u> </u>
43) Other survey	Distance City D. J. C. C. T. H.	- 1	category		2/3)
	Historic Site Board Springfield Histori	d	(site, structure, building, object)	Building	
44) History	Site	9)	significance		-
44) Mistory	Digit on 1007 by Enant Common Com	1	date	Architectural-Commerce	-
Tross Coming	Built ca. 1897 by Frank Curran, Sec	1	style	ca. 1897	-
	8 neighbor. Sold in 1910 to Charles		architect	Queen Anne	┨
	Springfield Paper Supply Co. Widow		builder		┧
living there			original use	D	1
riving there	900		present use	Residence	1
45) Additional descrip	tion _		number of stories	Apts.	4
63	Front elevationfront wing gable		plan shape	1 Innoquian	$\dashv$
Tlutea verge	ooard in gable with applied plaster(?)	- 1	basement	Irregular	1
	mple board modillions in the gable. The	- 1	£aa.da&ia	[Fu]]	┥
	able pediment is covered with shingles.	20)	wall construction	Rough, faced, coursed,	┨
	has been entirely removed recently and a	211	roof type -	frame/ ashlar lin	1
	inserted in its place. The pediment itself	f	material	lap siding stor	IE.
	th a narrow moulded cornice with a narrow	22)	contact print	Multi-gable asphalt	5
	which serves as the window head to the		35mm	shingle	
	window openings. The second story is				
	lap siding. There is a doubled window with	า			
	light sash which is set off center. To				
	a half round window with fixed sash which				
	landin <b>g window.</b>	1			
between the f	irst and second stories is a broad belted				
46) Description of env	ironment/outbuildings	23)	site plan		9
,			·		
				· ·	
				and the second s	
47) Information source	es .	24)	changes -	Entrance to Appt. on	5
	0   1010	1	additions/alter-	west el - added porch	
	Sanborn 1910		ations/moved	altered	
	City Directory 1900-1933	25	condition	Good	1
	Historic Site Board File	26	visible from road?		7
		27	distance/frontage		
		28	accessible?	-	6
48) Location of negati	ves		) preservation		7
	Roll 68 #12-18, 20,22		underway?	No	
49) Prepared by		30	endangered?	No	7
,	DDD	- 1	on National		7
50) Organization		-	Register?	NO	<u> </u>
O'Ballization	Missouri Heritage Trust	32	) part of	- 110	42
			established		
			historical district	No	
If additional space is no	reded, attached separate sheets.	33	) name of historical	110	$\dashv$
additional space is lie	issue, situating separate situate.		district	_	
(		34	) is site eligible?	Vac	$\dashv$
`			) district potential?	Yes	3
			) date		79
			) revision	Jan. 25, 1984	$\dashv$
		آ ا	,		-
		- 1		1	- 1

skirt covered with fishscale shingles with a moulded cornice at the lower end. A frieze board for the skirt acts as the window head to the first story window openings.

The first story window has a leaded glass upper sash in floreate design. Beneath the window is a double panel which meets with a board water table.

In the northeast corner of the house at the gable just described is a round corner turret. Only the conical roof of the turret extends above the house roof line. There is a metal finial cap on the roof of the turret. There are two window openings at the second story level of the main house portion. These have multi-paned upper sashes over one light sash. The window heads are the frieze board under a moulded cornice at the roof eaveline. The fishscale belt course with skirt carries around the turret as well. Beneath the skirt there is a metal turret base which rapidly tapers to a point midway on the first story level.

The facade presents an Lshape with a west wing slightly recessed from the front gable just described. There is a small projecting porch in the angle with a single pitch roof except over the entry area where there is a pediment which projects slightly from the porch cornice line. There is a broad verge board in the gable. Large brackets are found supporting the pediment. The face of the pediment is covered with a small coffered wooden motif with plaster (?) rosettes set in the coffered blocks.

Porch posts are simple turned wood, - the balustrade is also of wood with square balusters. The porch structure itself is of wood.

Above the porch is a modern addition filling the angle created by the house wings at the second story level. Probably a bathroom. At the very apex of the roof visible from the facade is a small gablet with an attic vent formed by the rear gabled roof line which is larger than the soler front gable.

East elevation—The eaves overhang with a simple cornice and narrow frieze which doubles as the head to second story window openings. The fishscale belt course with skirt continues around the entire house. A brick chimney is engaged to the wall visible to the ground. The shoulders at the second story level are of carved limestone. A small gable—with the chimney projecting at its center has flanking triangular windows with fixed sash and spoked muntins. The cornice is continuous across the small gable.


At the first story level is a parlor window with a half elliptical multipaned transom above double windows with simple leaded glass upper sashes. To the right of the chimney stack is a one story bay window which is square and has a hipped roof.

There is a small gabled porch above an entry in the west wing of the house. The pediment is filled with fishscale shingles. The porch has been filled in recently to make a vestibule to an apartment. There is a tripled window on the first story front which is likely in a front parlor with the center window larger than those flanking. The roof cants to provide more space at the half story at the rear of the house visible in the west elevation. Presumably this was to accommodate servant quarters. Now it is an apartment.

Between this house and 1000 East Walnut is a brick drive with limestone curbing.

CV-NGCC3-530

 $S^{\uparrow}$ 





## Missouri Historic Architectural Inventory for Gland Division of Parks and Historic Preservation Department of Natural Resources

	<b>2</b> (1)(1)(1)(1)(1)(1)(1)(1)(1)(1)(1)(1)(1)(				
38) Ownership — private	X		inventory number	23	]=
— public		1	name (cont)		
39) Owners — name	Bill Bass	l '	name - historial		_
— address	Rt 8, Box 71, Springfield	l '	street address town or vicinity	945-947 E. Walnut	4
( 10) Local contact 41) Coordinates (UT	M)	1 '	legal description	Springfield 160 Lot 1	1
42) Quad	···/		county	Treg. Survey 169 Lot J	1
43) Other survey			category	Greene	2
•			(site, structure,		2/3)
			building, object)	Building	
44) History			significance	Contribution	
	Built 1916-1917 by Harry Crone, dentist	1	date	1916-1917	_
		1	style	Four Square	4
			architect		_
		1 '	builder original use	Destilens	4
		1	present use	Residence	-
45) Additional description	n		number of stories	Apts.	4
43) Additional description	There are bellcast hip dormers on		plan shape	Square	$\dashv$
all roof faces	except the rear. The face and walls of		basement	Full	
	with butt shingle and each have two win-	19)	foundation	Rough, faced, coursed ash	lar
	th one over one light sash.	20)	wall construction	Frame/ limestone	
	ecting eaves on the house with board	21)	roof type -	lap siding	
• -	eath and with a cornice frieze as window		material	bell cast hip asphalt	
	cond story window openings. All window	22)	contact print	shingle	5)
	house have one over one light sash.		35mm		
	de there is a hip roof porch supported				
	columns with tuscan capitals. The				
	a moulded handrail and square balusters.				
	tone steps with a red brick flanking wall				
Which limestone	coping. Jindow openings on the facade at the secon	4			
46) Description of environment	nment/outbuildings	23)	site plan		9
-					
	$\epsilon$ is a one story, one bay, frame, hip roof		*		
garage with a sh	ed roof leadto.	1			
47)		24)	changes -		5
47) Information sources		24)	additions/alter-		
Sanborn 1910			ations/moved	None_visible	
City Directory	1910-1933	25)	condition	Good	7
		26)	visible from road		
		27)	distance/frontage		$\neg$
		28)	accessible?	-	6
48) Location of negative	S .	29)	) preservation		
	Roll #27 #8-9: R2A	1	underway?	No	
49) Prepared by	DDD		endangered?	No	_
		31)	on National		
50) Organization	Missouri Heritage Trust	22	Register?	No	_3
		32	) part of established	1	
			historical district	No.	
If additional snare is need	ded, attached separate sheets.	33	) name of historica	NO	$\dashv$
a additional space is fieel	socializada daparata arratar		district		
(		34	) is site eligible?	Yes	
N <sub>1980</sub>		35	) district potential		30)
		1	) date	Jan. 26, 1984	
		37	) revision		$\dashv$
		1		ĺ	1


ory level while on the first there are four openings total with a doubled entrance. All window openings on the first story have applied moulding to the window head.

On the west there is a square one story bay window with a hip roof and with a window opening in each face.

On the east there is a one story hip wing.

Also on the east elevation is a small portico porch with a hip roof leading to a side house entrance. The portico is supported on slender round wooden columns with tuscan capitals. The doorway has applied moulding to the head of the opening.

NT



GR-25-65-631



Missouri Historic Architectural Inventory for Communication of Parks and Historic Preservation Department of Natural Resources

	_			
38) Ownership — private $\chi$		inventory number	52	۳
— public	-	name (cont)	Fellow's House	]
39) Owners—name Anna Murrell		name - historial	same	
— address 1000 E. Walnut		street address	1000 E. Walnut	1
40) Local contact		town or vicinity	Springfield	ļ
41) Coordinates (UTM)	ĺ	legal description	Ireg. Survey Lot C	
42) Quad		county	Greene	
43) Other survey	8)	category		2/3)
Historic Site Board Springfield Historic Site		(site, structure,		٦
		building, object)	Building	
44) History		significance	Architectual-Contributi	ng
Built 1898 by Frank Fellows		date	1898	1
Owner & Mgr. Springfield Wagon Factory		style	Queen Anne	1
		architect		
		builder		
		original use	Residence	1
	l .	present use	Apts.	<u> </u>
45) Additional description  West elevation - dominated by a large	,	number of stories	2½	4
gabled wing with a double pediment. The first is at the	l	plan shape	irregular	1
apex with staggered butt shingles covering the face. A	}	basement	full	
small half round window is at the cornice line and ac-		foundation	Rough, faced, coursed	
tually is the top of the center window of a Palladian		wall construction	Frame/ ashlar limes	ton
· · · · · · · · · · · · · · · · · · ·	21)	roof type -	lap siding	]
style window found in the second pediment. There is an		material	multi-gable asphalt	
overhaning cornice with closely grouped modillions. Be-	22)	contact print	shingle	5
low is the "second" pediment which is also covered with		35mm	3	
staggered butt shingles. The center Palladian window				}
is actually an oriel projecting beyond the face of the				}
gable. The re eding base of the oriel window is of metal				}
Under the projecting eaves in the second pediment are the	1			
same closely spaced modillions found under the first	}			ĺ
pediment in the gable. Cornice returns are at the				
46) Description of environment/outbuildings	23)	site plan		9)
				}
				ļ
47) Information sources	24)	changes -	Part of porch filled in	ر ا اق
Sanborn 1910		additions/alter-	and altered. Rear wing	<b>,</b>
		ations/moved	added.	_
City Directory	25)	) condition	Good	_
"Fellows' House Field Survey with Personal Interpretation	26	visible from road?		
1981 Pat Bachler Lisa Holloway	27	) distance/frontage	-	
	28	accessible?	-	9
48) Location of negatives	29	) preservation		
Roll 68 #19, 23-32	1	underway?	No	
49) Prepared by DDD	30	) endangered?	No.	_
	31	) on National		
50) Organization Missouri Heritage Trust		Register?	No.	
mestuge must	32	) part of		
		established		
		historical district	No No	_
If additional space is needed attached separate sheets	33	) name of historica	1	
		district	_	_
	- 1	) is site eligible?	Yes	٠
	35	) district potential	Yes	30)
	1	) date	Jan. 26, 1984	4
	137	') revision	J	1

corners of the gable. At one time there was a cornice delimiting the second pediment however, its place is a metal belt course.

The frieze is an place and serves as the window head to the second story window openings. There is what must be a landing window spaced between the first and second stories with a half round fanlighted transom and wood "keystone" above a simple one over one light sash window. At the first story level is a round oculus window next to an altered entrance which may be recently added. To the left is a doubled window opening with slightly projecting window head with moulded and centiled entablature.

In the northwest corner of the house, actually on the front wing, but visible from the west elevation, is a corner tower with a bellcast roof and ornate metal finial cap. It is three stories with the third story above the roof eave level of the house itself. The tower is eight sided with projecting eaves and modillions like those over the house at cornice and gable. The window lights are one over one sash in the tower and elsewhere on the house unless otherwise noted. The walls of the third, and the area between the third and second stories (even with the line of the frieze board under the eaves), are covered with shingles set in an unusual undulating pattern.

The porch at the front of the house wraps around to the west with a porch entry with pedimented gable above. The cornice is continuous and the face of the pediment is set in shingles with a saw tooth pattern as belt course to butt shingles. The cornice is dentiled below which is an open work spindled entablature. The porch posts are tripled at the corners and are simple tapering wooden columns with wooden tuscan capitals. The pillars supporting the porch columns are of red brick with concrete coping probably much later than the rest of the structure. The porch itself is of wooden members with a wooden floor. There is a moulded handrail on a wooden ' lustrade with turned balusters.


Front elevation -- on the right is a gabled wing with cornice returns gable moddillions and the bellcast shape found on the west wing. The of the pediment is covered with staggered butt shingles. The corners are chamtered on the front and east elevations under the cornice of the projecting wings. Under the cornice are brackets set at the corners framing the window set in the corner cut out. The eaves project on the front elevation with cornice modillions like those founc elsewhere on the house. Below the eaves on the second story level and above the front porch in the corner left by the tower and the projecting wing is an open porch (impossible to photograph because of the foliage) which is framed by doubled columns like those described on the porch below supporting an arched entablature.

At the entry to the house there is a pediment gable on the porch which projects slightly from the rest of the porch. It is identical to the west porch gable except that there is a centered panel in the open spindle worked entablature and simple scroll brackets on the posts. Porch columns are doubled at the entrance.

The first story window in the front wing has a geometric leaded glass upper sash. All window and door surrounds on the front elevation have simple applied moulding to the heads of the openings. East elevation -- all of the first story window openings have moulded heads with dentil patterns. On the projecting east wing (identical to the front gable) the first story windows have narrow fixed upper sashes with diamond latticed leaded windows.

There is a modern sned dormer set on the east roof elevation. To the rear of the house is a centered pedimented gabled dormer. To the left is a modern gabled dormer.


51



C1 10 103-672


FELLONS HOUSE 1000 E. Walrut

North Sile




FIRST FLOOR

TOOD F THEY P



SECOND FLOOR

Ge ALLOW LE &



THIRD FLOOR

Constant a long



Missouri Historic Architectural Inventory for Grand Communication Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private X *	1) inventory number	24	
•	•		1=
public	2) name (cont)		_
39) Owners — name Harry Rowe	3) name - historial		
—address 1429 Charing	4) street address	1001 E. Walnut	
40) Local contact	5) town or vicinity	Springfield	7
41) Coordinates (UTM)	6) legal description	Ireg. Survey 169 Lot I	1
42) Quad	7) county	Greene	1
43) Other survey	8) category	dicette	+
43) Other survey	(site, structure,	   Budladaa	2/3)
	· · · · · ·	Building	
	building, object)		]
44) History Built by Benjamin Routt of Routt Bros,		Architectural-Contributi	ng
grocers. Lived at this property 1890	10) date	ca. 1905	
Probably built this house ca. 1905. Widow still there	11) style	Catalogue-Builder	7
1933.	12) architect		1
1333.	13) builder		┪
	14) original use	Residence	1
	_		-
	15) present use	Apts.	<del> </del>
45) Additional description On the front and rear elevations there	16) number of stories	2	_\ <b>4</b>
are bellcast hip dormers with wide eaves and covered	17) plan shape	Square Wing	
with butt shingle. The window openings in the dormers	18) basement	Full	
have lattice muntin upper sash in each of the double	19) foundation	Rough, faced, coursed	7
	20) wall construction	Frame/ ashlar Limeston	ne
openings. On the point of the pyramid roof there is a	21) roof type -	lap siding	7
metal finial cap. The eaves on the main house project	material	Bell cast hip	-
from the wall planes with simple board modillions be-	22) contact print		5
neath. The cornice frieze acts as the window head to		Asphalt shingle	9
the second story window openings. All window openings	35mm		
have one over one light sash unless noted otherwise.			
The house has three facade bays. On the second story			
· · · · · · · · · · · · · · · · · · ·			
level the center bay has three small window openings			
			l l
with fixed twelve light sash with a common project-			
ing lintel with brackets beneath separating the			
ing lintel with brackets beneath separating the	22) site plan		9
	23) site plan		9)
ing lintel with brackets beneath separating the	23) site plan		9)
ing lintel with brackets beneath separating the	23) site plan		9)
ing lintel with brackets beneath separating the	23) site plan		9)
ing lintel with brackets beneath separating the	23) site plan		9)
ing lintel with brackets beneath separating the	23) site plan		9)
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings			
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910.	24) changes -		9) 5)
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings	24) changes - additions/alter-		
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910.	24) changes - additions/alter- ations/moved	None visible	
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910.	24) changes - additions/alter- ations/moved 25) condition	None visible	
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	None visible	
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910.	24) changes - additions/alter- ations/moved 25) condition	None visible	
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	None visible	
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910.  City Directory 1900-1933.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	None visible	5)
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	None visible Good	5)
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910.  City Directory 1900-1933.  48) Location of negatives R #27 #11; R2A #10-12,15	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	None visible Good No	5)
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910.  City Directory 1900-1933.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	None visible Good	5)
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910.  City Directory 1900-1933.  48) Location of negatives R #27 #11; R2A #10-12,15	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	None visible Good No No	5)
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910. City Directory 1900-1933.  48) Location of negatives R #27 #11; R2A #10-12,15  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	None visible Good No	5)
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910. City Directory 1900-1933.  48) Location of negatives R #27 #11; R2A #10-12,15  49) Prepared by DDD	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	None visible Good No No	5) 6)
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910. City Directory 1900-1933.  48) Location of negatives R #27 #11; R2A #10-12,15  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	None visible Good No No	5) 6)
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910. City Directory 1900-1933.  48) Location of negatives R #27 #11; R2A #10-12,15  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	None visible Good No No	5) 6)
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910. City Directory 1900-1933.  48) Location of negatives R #27 #11; R2A #10-12,15  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	None visible  Good  No No No	5) 6)
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910. City Directory 1900-1933.  48) Location of negatives R #27 #11; R2A #10-12,15  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	None visible  Good  No No No	5) 6)
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910. City Directory 1900-1933.  48) Location of negatives R #27 #11; R2A #10-12,15  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	None visible  Good  No No No No	5) 6)
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910. City Directory 1900-1933.  48) Location of negatives R #27 #11; R2A #10-12,15  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	None visible  Good  No No No No Yes	5) 6) 7)
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910. City Directory 1900-1933.  48) Location of negatives R #27 #11; R2A #10-12,15  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	None visible  Good  No No No No  No Yes Yes	5) 6)
ing lintel with brackets beneath separating the openings from one another extending from the sill to the 46) Description of environment/outbuildings  47) Information sources Sanborn 1910. City Directory 1900-1933.  48) Location of negatives R #27 #11; R2A #10-12,15  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	None visible  Good  No No No No Yes	5) 6) 7)

1001 E. Walnut


he e soffit. Across the facade and extending around the east side is a hip roof porch when wide eaves. The porch is supported on round wooden columns with Tuscan capitals. The balustrade has a moulded handrail and truned balusters. The porch floor and structure are of wood. The first story level on the facade has one over one light sash in the window openings with applied moulding to the window head. The entrance has sidelights and a glass filled transom with frosted bevel glass.

On the east there is a hip roof projecting wing. The first story windows in the wing are tripled with diamond leaded glass upper sash. On the south corner of the wing there is an original entrance giving onto the porch. The entry hall window has a diamond leaded glass window in fixed sash.

At the rear of the house is a one-story latticed porch with a flat roof.

PRINT 18001222

NA






## Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — priva	te X *	1)	inventory number	51	۳
— publi		2)	name (cont)		
39) Owners — name	Martha Estep	3)	name - historial		1
— address	1010 E. Walnut	4)	street address	1008 E. Walnut	1
√40) Local contact		5)	town or vicinity	Springfield	1
41) Coordinates (l	TM)	6)	legal description	Ireg. Survey 167 Lot D	1
42) Quad		7)	county	Greene	1
43) Other survey			category	<u> dreene</u>	<u> </u>
•		'	(site, structure,		2/3)
		1	building, object)	Building	
44) History		9)	significance		┨
-	Built 1919-1920 by non-resident owner,		date	Contributing	┨
probably built	for rental.	l i	style	1919-1920	1
		1 '	architect	<u>Catalogue/Builder</u>	4
		1	builder		-
		1			1
			original use	Residence	
			present use	Apts	
45) Additional descript	tion Rough faced coursed ashlar limestone	1	number of stories	2	<b>4</b>
foundation onl	y on the front where visible and partly on	1 -	plan shape	Irregular	]
the side eleva	tions. In the rear the foundation appears	1	basement	Full.	_
to be of concr	ete. A one and a half story wing projects	19)	foundation	Rough, faced, coursed	1
to the west wi	th a gabled dormer set in the roof. A two		wall construction	achlar Limostone	į į
story gabled w	ing projects in front with heavy projecting	g 21)	roof type -	Frame/asbestos siding	1
eaves and corn	ice returns in the gable. The pediment		material	Gable Asphalt shingle	1
is set off wit	h a narrow moulded cornice with the frieze	22)	contact print	- wort aspinite surnger	5
	s the window head to the second story win-	l	35mm		
	Second story windows are doubled in the				
	over one light window sash. Below on the				
	ne windows are tripled of equal size. There	ام			
		-			
	w applied trim to the window heads of the				
	y. A porch fills the angle created by the				
front wing and	a narrow east projecting wing. The porch	231	site plan		ور
40) Description of envi	ironment/outbuildings posts are wooden, large squ	a re	site plais		٦
	boxed and tapering.		er en en en en en en en en en en en en en	And a series of the series of	
	10400\		المراق والخياسا السلجميد	والمحافظة والإنامان والمالية	
	se is a more recent (ca. 1940?) one story	:	ng pangangan di sang ng d		
	building with a concrete foundation		an en en en en en en en en en en en en en	in the second of	
<u>covered with t</u>	he same asbestos siding. At the rear of t		<del></del>	·	(7)
47) Information source	property to a measure and a		changes -	Asbestos Siding added.	5
	city Directory 1918-1933 addit	iþn.	additions/alter-	Modern Apt. house in	
		1	ations/moved	rear. Rear wing added	_
		25)	condition	Good	_
		26)	visible from road?	•••	
		27)	distance/frontage	_	
		28)	accessible?		9
48) Location of negative	ves p co 422 25	29	preservation		1
_	<sup>ves</sup> R 68 #33 <b>-3</b> 5		underway?	No	
49) Prepared by	non	30	endangered?	No No	٦
,,	DDD	- 1	on National	- IVU	7
50) Organization			Register?	No	
and a familiarion	Missouri Heritage Trust	32	) part of	No	2
			established		
			historical district	No	
16 malalikinan 1 m · · · · · i	and attached consents cheets	22	name of historical		4
ii auuitionai space is ne	eeded, attached separate sheets.	33	district	_	
		24			4
J		- 1	) is site eligible?	No	ω
		1	) district potential?	<del></del>	30)
			) date	Jan. 31, 1984	4
		3/	) revision		_
		1			

51




GR-AS-003-681



Missouri Historic Architectural Inventory for Glame - 2003 - Color Division of Parks and Historic Preservation Department of Natural Resources

				<b>,</b>
38) Ownership — private x		inventory number	50	נ
public		name (cont)		
39) Owners — name Mark Rowland		name - historial		
<pre>— address Rt. 3 Cassville, MO.</pre>		street address	1012 E. Walnut	Ì
40) Local contact		town or vicinity	Springfield	
41) Coordinates (UTM:		legal description	Ireg. Survey 167 Lot F	
42) Quad		county	Greene	<u> </u>
43) Other survey	8)	category		2/3)
		(site, structure,		
		building, object)	Building	
44) History		significance	Contributing	1
		date	ca. 1940	
		style	Colonial Revival	
		architect		
		builder		
		original use	Residence	<u> </u>
		present use	Apts.	
45) Additional description Three bay facade with doubled half		number of stories	1-1/2	4
story windows with six over one light sashes. The half	1	plan shape	Rectangular	_
story is actually a dormer with a shed roof projecting	/	basement	Full	]
from the gambrel. False window shutters made of "box-		foundation	Concrete	
car" siding are at each window. The center bay entry is	20)	wall construction	Frame	
flanked by sidelights. There is a small porticoed entry	21)	roof type -	Gambrel	
way with a gabled roof and square wood tapered posts		material	Asphalt Shingle	
set on brick pillars. The stoop and steps are of con-	22)	contact print	Asphart Shingle	5)
		35mm		
crete covered brick. Side porch on east side extends				
across most of the side elevation with a flat roof,				
square wooden tapering porch posts. Wooden balustrade				
with square balusters. Pillars are of brick with a				
brick foundation and concrete floor and steps on the				
porch itself.				
46) Description of environment/outbuildings	23)	site plan		9)
Modern apartment house detached in the rear of the				
property.				
				<u> </u>
47) Information sources	24)	changes -		5)
		additions/alter-		
City Directory 1920 - 1933		ations/moved	None	4
	1	condition	Good	_
		visible from road?		
	1	distance/frontage	-	1
	28	accessible?	<u>-</u>	၂၅
48) Location of negatives	29	) preservation		
Roll 68 #36-38		underway?	<u>No</u>	_
49) Prepared by DDD	30	endangered?	No	
	31	) on National	No	
50) Organization Missouri Heritage Trust		Register?		7
m soull her lage it ust	32	) part of		
		established		
		historical district		4
If additional space is needed, attached separate sheets	33	) name of historica	al l	
	_	district		4
		) is site eligible?	No	100
	- 1	) district potential		30)
	- 1	) date	Jan. 26, 1984	$\dashv$
	37	) revision		

31





Missouri Historic Architectural Inventory for Grand Division of Parks and Historic Preservation Department of Natural Resources


38) Ownership — private X	1)	inventory number	25	]=
— public		name (cont)		15
39) Owners — name Alpha Delta Pi Sorority		name - historial		1
— address 1021 E. Walnut		street address	1021 E. Walnut	1
40) Local contact		town or vicinity	Springfield	1
41) Coordinates (UTM)		legal description	Ireg. Survey 169 Lot F	-
		county	Greene	-
42) Quad		category	ureene	-
43) Other survey	l .	(site, structure,		2/3)
		building, object)	Dord I did no	
	l	significance	Building	-
44) History	l	•	Contributing	4
Built 1906-1907 by Moses Levy , President Levy-Wolf		date	1906-1907	-
Dry Goods Co.	-	style	Four Square	-
		architect		4
		builder		4
	1	original use	Residence	_
		present use	Sorority House	
45) Additional description Throop have facade on a hadia severe	1	number of stories	2	_4_
Three bay facade on a basic square	1	plan shape	Square	
structure with pyramid hipped roof covered with asphalt	18)	basement	Full	
shingles. Hipped dormers of all three faces of the		foundation	Rough, faced, Random A	
pyramid with doubled windows one over one sash. Wide pro	20)	wall construction	Frame/ Limestone	1
jecting eaves on house doubled windows with one over one	21)	roof type -	steel siding	7
sash at the second story level on first and third bays.	ļ	material	Hip Asphalt Shingle	
The center bay at second story level has a fixed sash	22)	contact print		5)
window with latticed muntins presumably at the landing		35mm		
of a stairhall. There is a simple moulding applied to al	Ŋ			
window heads. The porch across the front of the house				
has a flat roof with a wooden balustrade as parapet.				
There is an unadorned cornice and entablature with squat				
Mound oach chong columns with Turney cartiel 1				
round cast stone columns with Tuscan capitals also				
in cas stone supporting the porch. The parapet is	ļ			
in cas stone supporting the porch. The parapet is	23)	site plan		9)
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings	23)	site plan	· · · · · · · · · · · · · · · · · · ·	9)
in cas stone supporting the porch. The parapet is	23)	site plan		9)
in cas stone supporting the porch. The parapet is	23)	site plan		9)
in cas stone supporting the porch. The parapet is	23)	site plan		9)
in cas stone supporting the porch. The parapet is	23)	site plan		9)
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings			Poar addition	9) 5)
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources		changes -	Rear addition	
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources Sanborn 1910		changes - additions/alter-	Rear addition steel siding added	
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources	24)	changes - additions/alter- ations/moved	steel siding added	
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources Sanborn 1910	24)	changes - additions/alter- ations/moved condition	steel siding added Good	
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources Sanborn 1910	24) 25) 26)	changes - additions/alter- ations/moved condition visible from road?	steel siding added Good	
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources Sanborn 1910	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road? distance/frontage	steel siding added Good	5)
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources Sanborn 1910 City Directory 1905-1933.	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	steel siding added Good	
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources Sanborn 1910 City Directory 1905-1933.	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	Steel siding added  Good	5)
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources Sanborn 1910 City Directory 1905-1933.	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	Steel siding added  Good  No	5)
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources Sanborn 1910 City Directory 1905-1933.	25) 26) 27) 28) 29) 30)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	Steel siding added  Good	5)
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources Sanborn 1910 City Directory 1905-1933.  48) Location of negatives Roll 68 #39  49) Prepared by DDD	25) 26) 27) 28) 29) 30)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	steel siding added  Good  No No	5)
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources Sanborn 1910 City Directory 1905-1933.	25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	Steel siding added  Good  No	5)
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources Sanborn 1910 City Directory 1905-1933.  48) Location of negatives Roll 68 #39  49) Prepared by DDD	25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	steel siding added  Good  No No	5)
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources Sanborn 1910 City Directory 1905-1933.  48) Location of negatives Roll 68 #39  49) Prepared by DDD	25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	steel siding added  Good  No No No	5)
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources    Sanborn 1910    City Directory 1905-1933.  48) Location of negatives Roll 68 #39  49) Prepared by DDD  50) Organization Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	steel siding added  Good  No No No No	5)
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources Sanborn 1910 City Directory 1905-1933.  48) Location of negatives Roll 68 #39  49) Prepared by DDD	25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica	steel siding added  Good  No No No No	5)
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources    Sanborn 1910    City Directory 1905-1933.  48) Location of negatives Roll 68 #39  49) Prepared by DDD  50) Organization Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district	steel siding added  Good  No No No No No	5)
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources    Sanborn 1910    City Directory 1905-1933.  48) Location of negatives Roll 68 #39  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible?	steel siding added  Good  No No No No No	5) 6) 7)
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources     Sanborn 1910     City Directory 1905-1933.  48) Location of negatives Roll 68 #39  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 30) 31) 32) 34 35	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible? ) district potential?	steel siding added  Good  No No No No No No Yes	5)
in cas stone supporting the porch. The parapet is  46) Description of environment/outbuildings  47) Information sources    Sanborn 1910    City Directory 1905-1933.  48) Location of negatives Roll 68 #39  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 30) 31) 32) 344 35 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible?	steel siding added  Good  No No No No No	5) 6) 7)

of rough faced ashlar cast stone though the steps themselves are of limestone.

l. first story bays to either side of the center entry are tripled with a large window in the center with flanking smaller window openings all one over one light sash. There are sidelights and a transom surrounging the entryway.

GP 40003-601.





GP-180 (103-6036



Missouri Historic Architectural Inventory for

Division of Parks and Historic Preservation Department of Natural Resources

		T 7E	_
3( ) Ownership — private X	1) inventory number	26	ן=
— public	2) name (cont)		
39) Owners—name Sigma Chi House Corp.	3) name - historial		_
— address 1027 E. Walnut	4) street address	1027 E. Walnut	_
40) Local contact	5) town or vicinity	Springfield	
<b>´41)</b> Coordinates (UTM)	6) legal description	Springfield Treg. Survey 168 Lot A	
42) Quad	7) county	Greene	
43) Other survey	8) category		2/3)
	(site, structure,	Building	<b>=</b>
	building, object)	buriding	
44) History	9) significance	Architectual-Contribut	ilon
Built 1912 by Harry Durst, Lawyer	10) date	1912	
	11) style	Bungalow	
	12) architect		
	13) builder		
	14) original use	Besidence	
	15) present use	Fraternity House	
45) Additional description Low pitch roof with braod overhanging	16) number of stories	2	4
eaves with exposed rafter ends. In the front gable (and	17) plan shape	L-shape	7
all others) there are large simple knee braces. In the	18) basement	full	7
center of the gable, under the apex of the gable, is a	19) foundation	concrete	7
brace with geometric motif which rests on a carved panel	20) wall construction	1st S, brick 2nd, Fra	me
set at the apex of the gable. The entire second story	21) roof type -	Gable	
is covered with butt shingles. The second story front	material	Asphalt Shingle	7
gable has a set of French doors with multiple panes	22) contact print		5
opening onto a modern wooden porch which may replace a	35mm		
smaller earlier one. To the might is a tripled window			
smaller earlier one. To the right is a tripled window			
with multipaned lights in the sashes. Above the entry			
on the second story is a fixed sash window of multi-panes	5		
in what is presumably the stair hall.			
The second story projects slightly beyond the first			
46) Description of environment/outbuildings	23) site plan		9
Behind the house is a one-story gabled frame, 3 bay			
garage and storage building.			
garage and Storage burnaring.			
			Ì
47) Information sources	24) changes -	_	5)
	additions/alter-	Open porch with a facad	le
1910 Sanborn	ations/moved	added	
City Directory 1910-1933	25) condition	Good	7
City Directory 1910-1933	26) visible from road?		
	27) distance/frontage		
	28) accessible?	_	9
48) Location of negatives	29) preservation		
_	underway?	No	
Roll #1 #16-19, 40-41 Roll 597-5 #11-12	30) endangered?	No	
DDD	31) on National	- 110	
50) Organization	Register?	No	
Missouri Heritage Trust	32) part of	NU	73
	established		1
	historical district	t No	
If additional space is needed, attached separate sheets.	33) name of historica	ıl	_
	district	_	
	34) is site eligible?	Yes	
	35) district potential		30
	36) date	Jan. 26, 1984	
	37) revision		

story. Where they meet there is a narrow board. In the gable on the front elevation is a one story square bay window with five grouped windows. The walls of the bay are covered with butt shingles. The roof is obscured by the modern porch.


mere is a porch across the whole of the front facade though only that at the southeast corner has a roof. The porch extends around to the east side of the house in the angle created by the front gabled wing and a east side wing. The porch roof is gabled with the pediment to the front. There are projecting ends of the plates and purlins as well as the rafter ends under the eaves. The face of the pediment is wood set in a vertical geometric pattern. The porch posts are of field stone set into concrete. They are square and tapering. The chimney base on the west elevation is also of field stone sloping outward as it meets the ground.

At the second story level the chimney becomes brick. On the west elevation is a long oriel "sun porch" at the second story level placed inside the west gable.

East elevation - the east gable has a projecting ridge pole as well as the knee braces found in the other gables. There are doubled windows at the landing of the stair hall visible in the east gable with geometric motif stained glass upper sashes (photo). Other windows on the west and he east elevations are one over one sash.

C+ 20,000 2-6057

NA



COLAS-NATIONS



Missouri Historic Architectural Inventory for General Security Company of Parks and Historic Preservation Department of Natural Resources


38) Ownership — private X	T 1)	inventory number	27	T
— public		name (cont)		ן=
·				4
39) Owners — name George Everett		name - historial		_
— address 1033 E. Walnut	1 '	street address	1033 E. Walnut	
( 40) Local contact	5)	town or vicinity	Springfield	
41) Coordinates (UTM)	6)	legal description	Ireg. Survey 168 Lot B	7
42) Quad	7)	county	Greene	1
43) Other survey	8)	category		N
	1	(site, structure,		2/3)
	1	building, object)		
AAN IR.A.		significance		4
44) History	1	-	Contributing	4
Built 1924-1925 by Dr. James Fulbright, Physician	1	date	1924-1925	_
		style	Colonial Revival	
	1 '	architect		
	13)	builder		
	14)	original use	Residence	7
	15)	present use	Residence	7
45) Additional description	16)	number of stories	1-1/2	4
45) Additional description Five bay facade rectangular shape with g	ΙΦŽ¢	dawing.	Rectangle &wing	┪
gabled wing. Three dormers with six over six light		basement		4
sash in double hung windows. The walls of the dormers	1 /	foundation	Full	4
are covered with asbestos siding. Each of the first			Concrete	_
story windows are six over six light sash with flat		wall construction	Brick over tile	
arch lintels. False shutters are at each window. The	21)	roof type -	Gable	
conton have ontry has all intical wall downer flush with t		material	Asphalt Shingle	
center bay entry has elliptical wall dormer flush with t	(22)	contact print		5)
eaves above it. The present door hood is modern. The		35mm		
entry is framed with pilasters.	Ì			1
On the east elevation is a one-story sun parlor with				
grouped six over six light sash window openings. The				
parlor roof is flat with wooden pilasters set at the				
corners of the room under a moulded cornice. Beneath				
each of the sunparlor windows is a panel. On the rear	'			
46) Description of environment/outbuildings	23)	site plan		9)
				1
			Comment of the second of the s	
47) Information sources	24)	changes -		5
47) Tillormation sources	[24,	additions/alter-		
City Directory 1920-1933	ł	·	Door hood is modern.	1
		ations/moved		4
	1	condition	Good	
	26)	visible from road?		
	27)	distance/frontage	-	
	28)	accessible?	-	9
48) Location of negatives	29)	preservation		
Roll 1 #20-21, 27		underway?	No	
49) Prepared by DDC	301	endangered?	No No	
19) Prepared by DDD		on National		-
50. 0	31/		No	
50) Organization Missouri Heritage Trust	100	Register?		_3
	(32)	part of		
		established		
	1	historical district	No ·	_
If additional space is needed, attached separate sheets	33)	name of historical		1
		district	-	
<i>!</i>	34)	is site eligible?	Yes	
	lacy	district potential?		30
	35)	district potentiar.	1 162	
		date		7
	36)	•	Jan. 26, 1984	
	36)	date		

roof face is a long shed roofed dormer adding space to the half story.

there is a low one story brick over tile wing which houses the garage and part of the kitchen.

Each of the gables has more or less flush eaves with a half round window set near the apex.

NT



GR-A5-003-631





Missouri Historic Architectural Inventory for


Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership - private	X .	1)	inventory number	49	=
public		2)	name (cont)		]
39) Owners — name	Roma Hobercht et al	3)	name - historial		
— address	1040 E. Walnut	1	street address	1040 E. Walnut	
40) Local contact		1	town or vicinity	Springfield AD E. Smith's Add. Lot	
41) Coordinates (UT	M)		legal description	AD E. Smith's Add. Lot	12
42) Quad			county	Greene	<u> </u>
43) Other survey		8)	category		2/3)
		Ì	(site, structure,	Dudlata	
		+-	building, object)	Building	4
44) History		1	significance date	Contributing	-
			style	ca. 1905	4
			architect	<u>Catalogue/Builder</u>	-
			builder		-
		1 .	original use	Docidonas	1
			present use	Residence Residence	1
45) Additional description		- 1	number of stories	2	4
45) Additional description	"Hipped dormers on the west and fron	1 1	plan shape	Rectangle	1
elevations. Br	oad projecting eaves on dormers with doub	1e.8)	hasement	Full	-
hung one over o	ne light sash window. The eaves on the		foundation	Rough, forced, coursed	1
	e bradly projecting with cornice	l i	wall construction		1
modillions and	a plain frieze board and corner board.	1 .	roof type -		3
	les as the window heads to the second sto	ry	material	lap siding	1
windows. The f	acade is two bay with a one story hipped	22)	contact print	Bell cast hip asphalt	5
	e simple cornice and entablature with	/	35mm	shingle	
	rch columns with Tuscan capitals. Wooden				
balustrade with	turned balusters. The porch structure				
is of wood. We	st elevation a hipped roof one story				
three sided ori	el at the first story level. All windows				
	are one over one light sash. There is a				
rear wing which	has a concrete foundation. All details	Ì			
46) Description of enviro	nment/outbuildings	23)	site plan		9
		}		· · · · · · · · · · · · · · · · · · ·	
		1	,	والمستقدان	
				e e e e e e e e e e e e e e e e e e e	
			• • • •		
47) Information sources		24)	changes -		5)
	Sanborn 1910		additions/alter-	Rear wing added ca. 19	930
	City Directory 1900-1933		ations/moved		
	•	25)	condition	Good	
		26)	visible from road?		_]
		27)	distance/frontage		
		1 .	accessible?		6
48) Location of negative	S D 0 1 1 420 20	29)	preservation		
	Roll 1 #28-30		underway?	No	4
49) Prepared by	DDD		endangered?	No No	_
	000	31)	on National	NO TO THE PROPERTY OF THE PROP	
50) Organization	Missouri Heritage Trust		Register?	No	
	masouri nerrouge must	32	) part of		
			established		
			historical district		4
If additional space is need	ded, attached separate sheets.	33	) name of historical		
			district	-	4
		- 1	) is site eligible?	Yes	(1)
			) district potential?	Yes	30)
			) date	Jan. 26, 1984	$\dashv$
		3/	) revision		$\dashv$

conform with the main house leading one to believe it is original or built shortly after initial construction. The rear wing also has a hipped roof.

GENEROS 1039

 $S^{\uparrow}$ 






## Missouri Historic Architectural Inventory for Company Control

38) Ownership — private x	1)	inventory number	28	5
— public	2)	name (cont)		7
39) Owners — name Ethel Holland et al	3)	name - historial		1
— address 1041 E. Walnut	4)	street address	1041 E. Walnut	1
1041 E. Harriage	5)	town or vicinity	Springfield	1
41) Coordinates (UTM)	6)	legal description	Ireg. Survey 168 Lot I	1
42) Quad	7)	county	Greene	1
43) Other survey	8)	category		2/3)
,		(site, structure,		3
		building, object)	Building	
44) History	9)	significance	Contributing	1
Built 1909-1910 by Harry J. Upham, SecTreas. Upham	10)	date	1909-1910	7
Shoe Co.	11)	style	Four square	7
	12)	architect		7
	13)	builder		
	14)	original use	Residence	7
	15)	present use	Residence	
45) Additional description	16)	number of stories	2	4
Two bay facade. Gabled dormers on the		plan shape	Square	
east, west, and south faces of the roof. Each is	18)	basement	Full	
pedimented with continuous cornice at the broad pro-	19)	foundation	Rough, faced, coursed	
Jecint eave line. The window surround is pilastered		wall construction	Frame/ ashlar cast s	ton
with multi-paned sashes both above and below in the	21)	roof type -	asbestos siding	
double hung window. The eaves on the house also project		material	Hip asphalt shingle	
beyond the walls with simple cornice moulding and	22)	contact print		5)
board entablature. All windows are one over one sash		35mm		
unless other wise noted. There is a gabled portico at				
the entry with a continuous cornice. The porch columns				
are of wood with Tuscan capitals in groups of three at	4			
the corners of the portico. Wood balustrade with moulded				
) handrail and turned balusters. Multi-paned sidelights	>			1
and transom frame the doorway. There was originally a				٠,
46) Description of environment/outbuildings	23)	site plan		9
				-
	241	changes -		5
47) Information sources	24)	additions/alter-	Front porch altered	
Sanborn 1910		ations/moved	Rear wing added	
City Directory 1909-1933	25)	condition		$\dashv$
	1	visible from road?	Good	$\dashv$
	1	distance/frontage		7
		accessible?		6
		preservation	-	_
48) Location of negatives	23,	underway?	A1 -	
Roll 1 #22-26	30	endangered?	No.	7
49) Prepared by DDD		on National	No	-
EO) Organization		Register?	No.	-
50) Organization Missouri Heritage Trust	32	) part of	No	-5
		established		
		historical district	No	
If additional space is needed, attached separate sheets.	33	) name of historica		$\neg$
		district	No	
	34	) is site eligible?	No	
,	35	) district potential:		30)
	36	) date	Jan. 26, 1984	_
	37	) revision		_
	- 1		I	1

much larger porch which has been reduced to its present size. The porch stoop is of concrete as are the steps. The upper sashes in the first story windows on the front and east elevations leaded glass. A modern garage is attached to the rear of the house. A rear porch onestory with shed roof has been recently enlarged to its present size.

CHAS-OCK IN

Well builded



GP PS-04 3- 5-10








Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private				
- public	1)	inventory number	<b>4</b> 8	]=
— pasite	2) 1	name (cont)		1
39) Owners—name Richard Taylor	3) (	name - historial		1
- address Rt. 1, Box 397	4) 9	street address	1046 E. Walnut	1
40) Local contact	5) 1	town or vicinity	\$pringfield.	1
41) Coordinates (UTM	6)	legal description	Ad. E. Smith's Add. Lot	:1
42) Quad		county	Greene 11	7
43) Other survey	1	category	<u> dreene</u>	N
	- 1	(site, structure,		2/3)
	1	building, object)	D : 1 1 :	1
44) History	1	significance	Building	-
·		=	Contributing	4
Built 1908 for Willis G. Crane who owned			1908	4
a harness &saddlery business.	11)		Four Square	4
	(	architect		_
	1	builder		1
	1	original use	Residence	1
		present use	Residence	L
45) Additional description Hip dormers on the west and front ele-	16)	number of stories	2	4
vations with broad projecting eaves. Doubled windows	17)	plan shape	Rectangle	]
with one over one sash in double hung windows. The	18) 1	basement	Full	1
eaves on the house itself also project noticeably with	19) 1	foundation	Rough, faced, coursed	
simple frieze board which doubles as the window heads to	20) 1	wall construction	Frame/ ashlar Cast	
	21) (	roof type -	lap siding Stone	-
the second story window openings. All windows are one	١ .	material	Bell cast hip asphalt	4
over one sash with a narrow simple applied moulding to	22)	contact print	• •	5
the window head at the first story window openings.	- 1	35mm	shingle	
Three bay facade with center bay entrance. The doorway	}			
is flanked by sidelights and a transom.				
The front elevation is dominated by a one-story hipped	}			}
roof porch across the entire front. The cornice and	1			}
( entablature are unadorned on the porch-underneath	1			
are round wood columns with Tuscan capitals resting on				1
piers of rough faced cast stone. The balustrade is of 46) Description of environment/outbuildings	ļ			<u> </u>
	123)	cita nlan		
	120,	site plan		9
wood with turned balusters. The structure of the porch		site pian		3
itself and the steps leading up to it are of wood. At		site piari		9
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square		site pian		93
itself and the steps leading up to it are of wood. At		site plan		3
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square		site plan		
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square		changes -		5)
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.	24)			
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources	24)	changes -	None visible	
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources  Sanborn 191(	24)	changes - additions/alter-	None visible	
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources	24)	changes - additions/alter- ations/moved	None visible Good	
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources  Sanborn 191(	24) 25) 26)	changes - additions/alter- ations/moved condition visible from road?		
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources  Sanborn 191(	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road? distance/frontage		5)
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources  Sanborn 191( City Directory 1907-1910	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	Good	
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources  Sanborn 191( City Directory 1907-1910	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation		5)
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources  Sanborn 191( City Directory 1907-1910  R 1 #32-36	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	Good	5)
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources  Sanborn 191( City Directory 1907-1910	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	Good	5)
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources  Sanborn 191( City Directory 1907-1910  48) Location of negatives  R 1 #32-36  49) Prepared by DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	Good - - No	5)
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources  Sanborn 191( City Directory 1907-1910  R 1 #32-36	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	Good - - No	5) 6)
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources  Sanborn 191( City Directory 1907-1910  48) Location of negatives  R 1 #32-36  49) Prepared by DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	Good No No	5)
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources  Sanborn 191( City Directory 1907-1910  48) Location of negatives  R 1 #32-36  49) Prepared by DDD	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	Good No No	5) 6)
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources  Sanborn 191( City Directory 1907-1910  48) Location of negatives  R 1 #32-36  49) Prepared by DDD	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	Good No No	5) 6)
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources  Sanborn 191( City Directory 1907-1910  48) Location of negatives  R 1 #32-36  49) Prepared by DDD	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	Good No No No	5) 6)
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources  Sanborn 191( City Directory 1907-1910  48) Location of negatives R 1 #32-36  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	Good No No No	5) 6)
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources  Sanborn 191( City Directory 1907-1910  48) Location of negatives R 1 #32-36  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	Good No No No No	5) 6)
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources  Sanborn 191( City Directory 1907-1910  48) Location of negatives R 1 #32-36  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	Good No No No	5) 6) 7)
itself and the steps leading up to it are of wood. At the street is a cast stone hitching post which is square and tapering.  47) Information sources  Sanborn 191( City Directory 1907-1910  48) Location of negatives R 1 #32-36  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	Good No No No No	5) 6)

51










Missouri Historic Architectural Inventory for C

Division of Parks and Historic Preservation Department of Natural Resources

	•				
38) Ownership — private	* X	ı	inventory number	47	]=
— public		2)	name (cont)		
39) Owners — name	Alumni Delta Upsilon, Inc.	( )	name - historial		
— address	1050 E. Walnut	1	street address	1050 E. Walnut	
( 10) Local contact		1	town or vicinity	<u>Springfield</u>	4
41) Coordinates (U	TM)	1	legal description	AD E. Smith's Add. Lots	4
42) Quad		1 _	county	Greene 9 & 10	_
43) Other survey		8)	category		2/3)
			(site, structure,	Building	
			building, object)		4
44) History		1	significance	Architectural_Contribut	- <b>i</b> ng
	O by W. D. Tatlow lawyer. He lived in	1	date		4
•	at must have been intended as a "genteel"	1	style architect	Catalogue/builder with	_
apt. house.		1 .	builder	classical deta	ءاند
		1	original use		
			present use	Apt. House	
45\ 4444		1	number of stories	Faternity House	4
45) Additional descripti					<del>-</del> ح
	Hip dormers east, west and south roof the front elevation the dormer is gabled		plan shape basement	rectangle	$\dashv$
	demarcated by a continuous cornice line at	1 '		<u>Eull</u>	_
	ecting eaves. The wall surfaces are		wall construction	Concrete	-
	t shingles and the side walls are notice-			Birch veneer	_
		1	roof type - material	Hip	4
	ward. A single light window with latticed the face of the dormer. The eaves on the		contact print	Asphalt Shingle	5
		(22)	35mm	ū	9
	are broadly projecting with simple board	1	33111111		
modillions under					
	three bay facade. The second story center				
	two doors with geometric design lights				
	ted door hood over both with moulded en-				
	The windows are one over one light sash o visible lintel. The sills appear to be				
		221	site plan		9
46) Description of envir	onment/outbullaings	23)	site plan		
Hinned roof one	story buff colored brick veneered out-				
· ·	our pays appears to be original to the				
structure.	our says appears to be original to the				
scructure.					
47) Information source		24)	changes -		5
47) Information Source	5		additions/alter-		
City Dimont	Ani 1010 1022	Ì	ations/moved	None visible	
city birect	ory 1919-1933	251	condition		-
		1	visible from road?	Good	-
			distance/frontage		$\dashv$
		1	accessible?		6
40)		1	preservation	-	$\dashv$
40) Location of negativ	es Roll 1 #37-43	- ]	underway?	N	
40) Proposed by	DDD	30	endangered?	No.	$\dashv$
49) Prepared by	DDD		on National	No.	$\dashv$
EO) Oi	Military and Health and The Control	31	Register?	Ne	
50) Organization	Missouri Heritage Trust	32	) part of		-[3
			established		
			historical district	: N-	
If additional anna is as	eded. attached separate sheets	33	) name of historica		$\dashv$
it additional space is nee	cueu, attachicu separate sheetis		district		-
		34	) is site eligible?	V	$\dashv$
		- 1	) district potential	? <del>  Yes                                   </del>	30
			) date	Yes Jan. 26, 1984	$\dashv$ $\exists$
		- 1	) revision	Vuii. 705 1704	_
					_

limestone. The second story doors give onto a flat roofed porch with a wooden balustrade ich appears to date later than the house. There are modillions at the cornice of the coh roof with the wide projecting eaves found on the house. Square brick columns of buff colored brick support the porch corners with square limestone (?) capitals and banding. Flanking the entrance are smooth round tapering limestone columns with Tuscan capitals also of limestone. A brick parapet wall surrounds the porch with limestone coping.

Side elevation entrances have door hoods with knee brace supports. On the east elevation is a two story three sided oriel which is tucked under the projecting eaves. On the west elevation are two such oriels. Shed roofed frame sun porch on the rear partially filled in.



ST

C-8-25-063-6-12



Missouri Historic Architectural Inventory for Colored


W) Ownership — private X	1) inventory number	29	]=
— public	2) name (cont)		
39) Owners — name Ray Mitchell	3) name - historial		
— address 1122 E. Walnut	4) street address	1101 E. Walnut	
( 40) Local contact 41) Coordinates (UTM)	5) town or vicinity	Springfield	_
42) Quad	6) legal description	East Side Add. Lot 47	_
43) Other survey	7) county 8) category	Greene	+
45) Other survey	(site, structure,		2/3)
	building, object)	Building	
44) History Built in 1905-1906 by Charles McCann as	9) significance	Contributing	
a speculative venture and sold to Robert Carpenter - the	10) date	1905-1906	-
first resident - who was cashier for the Springfield Gas	11) style	Catalogue/builder with	┪
& Electric Co.	12) architect	classical det	ails
a Erceti ie co.	13) builder	31333,33, 430	7
	14) original use	Residence	
	15) present use	Apartments	
45) Additional description	16) number of stories	2	4
Red brick used in the construction.	17) plan shape	Irregular	_
Front elevation-two bay facade with gable entry. Pedi-	18) basement	Full	
ment in the gable with cornice returns and recessed gable	19) foundation	Rough, faced, coursed,	
cornice of simple mouldings. The face of the gable is	20) wall construction	Brick/ ashlar Limesto	ne
covered with butt shingles curving inward to the re-	21) roof type -	Gable	
cessed centered window opening of one over one light	material	Ashphalt shingle	
sash. Under the cornice is slightly projecting brick	22) contact print		5)
belt course. Brick double course relieving arches at the	35mm		
window openings with rusticated brick headers. The win-			
dows are one over one light sash. Rough faced limestone			
sills at all window openings. There is a double brick			
stretcher course to delimit the first and second			
stories. There is a one-story hipped roof porch			
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The	22) aito alon		10
stories. There is a one-story hipped roof porch	23) site plan		9)
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The	23) site plan		9)
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The			9)
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The 46) Description of environment/outbuildings			9)
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The 46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped			9)
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The 46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.			9) 5)
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The 46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910		Porch filled in-exter	5)
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The  46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910 City Directory 1906-1910	24) changes -	Porch filled in-exter stairway on west El a	5 ior
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The 46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910	24) changes - additions/alter-		5 ior
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The  46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910 City Directory 1906-1910	24) changes - additions/alter- ations/moved	stairway on west El a Good	5 ior
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The  46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910 City Directory 1906-1910	24) changes - additions/alter- ations/moved 25) condition	stairway on west El a Good	5 ior
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The  46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910 City Directory 1906-1910	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	stairway on west El a Good	5 ior
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The  46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910 City Directory 1906-1910	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	stairway on west El a Good	jor dded
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The 46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910 City Directory 1906-1910 Deed Record Book 233, page 463	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	stairway on west El a Good	jor dded
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The  46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910 City Directory 1906-1910 Deed Record Book 233, page 463	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	stairway on west El a Good	jor dded
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The  46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910 City Directory 1906-1910 Deed Record Book 233, page 463	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	stairway on west El a Good No	jor dded
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The  46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910 City Directory 1906-1910 Deed Record Book 233, page 463  48) Location of negatives  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	stairway on west El a Good No	ior dded
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The  46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910 City Directory 1906-1910 Deed Record Book 233, page 463  48) Location of negatives  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	stairway on west El a Good No No	jor dded
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The  46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910 City Directory 1906-1910 Deed Record Book 233, page 463  48) Location of negatives  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	stairway on west El a Good No No No	ior dded
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The  46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910 City Directory 1906-1910 Deed Record Book 233, page 463  48) Location of negatives  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	stairway on west El a Good No No No	ior dded
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The  46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910 City Directory 1906-1910 Deed Record Book 233, page 463  48) Location of negatives  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	stairway on west El a Good No No No	ior dded
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The  46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910 City Directory 1906-1910 Deed Record Book 233, page 463  48) Location of negatives  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	stairway on west El a Good No No No No	ior dded
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The  46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910 City Directory 1906-1910 Deed Record Book 233, page 463  48) Location of negatives  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	stairway on west El a Good No No No No Yes	ior dded 6) 7)
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The  46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910 City Directory 1906-1910 Deed Record Book 233, page 463  48) Location of negatives  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	stairway on west El a Good No No No No Yes Yes	ior dded
stories. There is a one-story hipped roof porch across the front of the house extending eastward. The  46) Description of environment/outbuildings  Behind the house is a one-story outbuilding with a hipped roof built of wood containing a one bay garage.  47) Information sources  Sanborn 1910 City Directory 1906-1910 Deed Record Book 233, page 463  48) Location of negatives  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	stairway on west El a Good No No No No Yes	ior dded 6) 7)

simple moulded cornice and entablature survive but the porch area has been filled in recelly.

On the east elevation is a projecting wing with pedimented gable. Butt shingles cover the face of the pediment with a continuous cornice setting off the pediment. Brackets are placed at the corners of the gable. Beneath the cornice the corners are chamfered on the wing with a window in each face.

On the west elevation is an oriel window of three sides at what must be the landing between the floors in the stairhall. There is a single bracket under the oriel. The roof is hipped. Presently the window has been turned into a doorway and a modern stair leads to a second story apartment. Hipped dormer covered with butt shingles positioned above oriel window.

General Con




NA

GR- NS-OCOMORE



## Missouri Historic Architectural Inventory for Ghamada Color Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private y	11	inventory number	4.0	Τ
public		name (cont)	46	=
·	- •	name - historial		-
39) Owners—name Emma Bissett & Marion Hablet				4
- address 1104 E. Walnut		street address	1104 E. Walnut	4
( 40) Local contact		town or vicinity	Springfield	_
41) Coordinates (UTM		legal description	Ad. F. Smith Add. Lot 8	1
42) Quad		county	Greene	↓
43) Other survey	8)	category		2/3)
		(site, structure,		<u> </u>
		building, object)	Building	
44) History	9)	significance	Contributing	1
	10)	date	1915-1916	1
Built 1915-1916 by Harry Ll Bissett (old family)		style		1
Teller McDonald Nat. Bank		architect	Catalogue/Builder	i i
		builder		+
		original use		4
		_	Residence	4
		present use	Residence	<del> </del>
45) Additional description Under the low pitch eaves the rafter		number of stories	2	4
ends are exposed. All window openings have multi-paned	l	plan shape	Irregular	1
upper sash over one light lower sash. A smaller gabled	/	basement	Unknown	
wing projects from the front elevation leaving an angel	,	foundation	Concrete	
in the northeast corner of the house filled by a closed		wall construction	Stucco over frame	7
	21)	roof type -	Gable	7
porch with a flat roof with balustraded open porch at		material	Asphalt Shingle	1
the second story. The corners of this frame closed	22)	contact print	Aspina L Sitting is	5
porch have brick (?) corner supports. Inbetween are		35mm		
grouped windows with casement multi-paned sash.				
The windows at the first and second stories in the pro-				
jecting wing are tripled with the larger window in the				!
center of the flanking smaller window openings. The				
window openings have fixed shutters (which may be				
original) with clover leaf cutouts. Behind the				
house is an attached one-story stuccoed building used as 46) Description of environment/outbuildings	L			
	23)	site plan		9)
a garage. At the street is a vermiculated limestone	1			
stepping block with the date: 1893 on the face955 on				
either sideand the name BISSETT on the long side front-	4			
research indicated that the house 955 is east of National	1			
Street and no longer extant				
47) Information sources	24)	changes -		5
City Directory 1900-1933		additions/alter-		
orly birectory 1900-1933		ations/moved	None visible	
	25)	condition	Good	7
	26)	visible from road?		7
	'	) distance/frontage		┪
	1	accessible?		6
	1	) preservation	-	_
48) Location of negatives ROTT 2 #13	29,	•		
Roll 1 #44, 1-3 Roll 547-6 #7-8	200	underway?	No.	-
49) Prepared by DDD	l.	) endangered?	No.	4
	[31]	) on National	No	
50) Organization Missouri Heritage Trust		Register?	No	77
THISSOUTT HET TEAGE THUSE	32	) part of		
		established		
		historical district	No	
If additional space is needed, attached separate sheets	33	) name of historica		
· · · · · · · · · · · · · · · · · · ·		district	_	
	34	) is site eligible?	No	
	- 1	) district potential?		30
		) date	Jan. 26, 1984	
	l l	) revision	- MMII 6 CU 9 1 304	
	- 1			_



GR-AS-003-644



SAFETY FILM 5062

KODAK SAFETY F M 506



AFEIT FILM 5062

KUDAR SAFETT FILM




## Missouri Historic Architectural Inventory for CR A COLOR

•				
38) Ownership — private X	1)	inventory number	30	]=
— public	2)	name (cont)		]
39) Owners — name Ray Mitchell	3)	name - historial		
— address 1122 E. Walnut	4)	street address	1107 E. Walnut	
10) Local contact	l	town or vicinity	Springfield	
+1) Coordinates (UTM)	l	legal description	East side add. Lot 48	
42) Quad		county	Greene	
43) Other survey	8)	category		2/3)
		(site, structure,		<u>w</u>
		building, object)	Building	
44) History Built in 1906 as a speculative venture	l	significance	Contributing-Commerce	
by Charles McCann and sold to its first resident, David		date	1906	
Diffenderffer, the proprietor of the Diffenderffer Buggy	1	style	Catalogue/Builder with	
& Implement Co. 1101, 1107 and 1117 E. Walnut all built		architect	Classical details	ŝ
by same builder at about same time.	1 .	builder		
		original use	Residence	
AFX Addition		present use	Apartment	ļ
45) Additional description This house is very much similar to that		number of stories	2	4
next door at 1101 E. Walnut and at 1117 E. Walnut		plan shape	Irregular	
they must have been build by the same builder at roughly		basement	Full	
the same time. The brick work isdark red. There is a	,	foundation	Rough:faced.coursed	1
bellcast hipped dormer on the front elevation with butt		wall construction	Brick ashlar limes	ton
shingles covering the face and walls. Recessed window	21)	roof type -	Hip with gable wing	4
opening in dormer with one over one light sash. On the	221	material	<u>asphalt</u>	ļ
house itself there are projecting eaves with a narrow	22)	contact print	shingle	5
cornice. Beneath the cornice is a belt course of pro-		35mm	Siringre	
jecting brick stretchers delineating the brick frieze.				
The relieving arch lintles at the windows form a con-				
tinuous row with the belt course. The lintels are of				
buff colored brick headers. Rough limestone sills at				
window openings. A double header course separates				
the first from the second stories. At the corners of the 46) Description of environment/outbuildings	23)	site plan		و
To, Description of environment, outbandings		Site plan		
47) Information sources	24)	changes -		5
Sanborn 1910		additions/alter-		
City Directory 1905-1910		ations/moved	None visible	
Greene County Deed Record Book 198 page 46, and Book	25)	condition		7
238, page 613.	26)	visible from road?	Good	_
	27)	distance/frontage	_	
	28)	accessible?	_	6
48) Location of negatives	29)	preservation		٦
Roll 6 #34-35, 37, - ?		underway?	No	
49) Prepared by DDD	30)	endangered?	No	1
	31)	on National	No	
50) Organization Missouri Heritage Trust		Register?	110	
	32)	part of		_ت
		established		
		historical district	No	╛
If additional space is needed, attached separate sheets.	33)	name of historical		7
		district		
)		is site eligible?	Yes	
		district potential?		30
		date	Jan. 26, 1984	_
	37)	revision		_
	1		1	1

house are staggered projecting brick made to simulate quoins. The facade is two bay with one light sash. A one story hipped roof porch extends across the front and projects eastward, with a very simple cornice and entablature. Round wooden small columns support porch with Tuscan capitals. The porch floor and structure are of wood. The entry has a transom above it. On the east elevation is a landing oriel window with three sides clearly placed between the first and second floors at the landing in the stairhall. The roof is hipped and there is a single bracket beneath.

On the west elevation is a projecting wing with a pedimented gable set off with a continuous cornice beneath with chamtered corners and a window in each face. The face of the pediment is covered with butt shingles.

The cellar openings have triple coursed brick relieving arches with brick "keystones" as a decorative addition.




NT



Missouri Historic Architectural Inventory for GE, 2003-600 Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private X	1) inventory number 45	=
public	2) name (cont)	
39) Owners—name Ray Mitchell	3) name - historial	
— address 1122 E. Walnut	4) street address 1108 E. Walnut	
40) Local contact	5) town or vicinity Springfield	
41) Coordinates (UTM)	6) legal description Ad. E. Smith Add. Lot 7 7) county Greene	
42) Quad		N)
43) Other survey	(site, structure,	2/3)
	building, object) Building	
44) History	9) significance   Contributing-Social	
Built 1906-1907 by Wm. T. Carrington,	10) date 1906-1907	
President Springfield State Normal College	11) style Catalogue/Builder	
riestaent springriera state normal correge	12) architect	1
	13) builder	
	14) original use Residence	
	15) present use Apts.	
45) Additional description	16) number of stories 2	4
Hip dormers on the north and south root	17) plan shape Square	
faces. Projecting house roof eaves with simple cornice	18) basement Full	
and frieze board which doubles as the head to the window	Rough, raced, coursed	]
openings at the second story. Three bay facade with one over one window sash in all windows. The corner boards	Trailey astrait times co	he
on the house have a simple bead running the length. One	21) roof type lap siding	4
story hipped porch runs the entire length of the front	The it case hip aspiral c	(D
elevation. Over the entry in the first bay there is a	22) contact print shingle	5)
qabled pediment on the porch with a continuous cornice.	35mm	
The face of the pediment is covered with butt shingles.		
Narrow round wooden columns with tuscan capitals suppor		
the porch. The porch structure is of wood. Most of the		
Oorch has been filled in to add a room to the first		
story. The window originally opening onto the porch		
was moved to become the center window of this addition.  46) Description of environment/outbuildings	23) site plan	9
All window openings on the side and rear elevations hav		
a simple narrow moulding applied to the window heads.		
a symple harrow mountaing apprica to the window heads.		
On the rear is a one-story hipped roofed sun porch with		
multiple windows which appears to be original.		
47) Information sources	24) changes -	5)
City Directory 1905-1933	additions/alter-	
,	ations/moved Porch filled in	_
	25) condition Good	4
	26) visible from road?	4
	27) distance/frontage	<u></u>
	28) accessible?	ا ا
48) Location of negatives Roll 2 #11-12	29) preservation underway?	
	110	-
49) Prepared by DDD	30) endangered? NO	-
	Register?	-
50) Organization Missouri Heritage Trust	32) part of	_2
	established	
	historical district NO	
If additional space is needed, attached separate sheets.	33) name of historical	
a document oppose to treatment and the copy of the	district	
(	34) is site eligible? No	4.0
	35) district potential? Yes	30)
	36) date Jan. 26, 1984	
	37) revision	4
		1





GP-21-1111-11960



## Missouri Historic Architectural Inventory for Garage Court Division of Parks and Historic Preservation Department of Natural Resources

•		
38) Ownership — private X	1) inventory number 31	;
— public	2) name (cont)	
39) Owners—name William Ferguson	3) name - historial	
— address IIII E. Walnut	4) street address TTTT E. Walnut	
40) Local contact	5) town or vicinity Springfield	
41) Coordinates (UTM)	6) legal description East side add. Lot 99	
42) Quad	7) county Greene	
43) Other survey		— د
	8) category (site, structure,	3
	building, object) Building	
44) History	9) significance Architectural-Commerce	
Built 1902-1903 by Arthur C. Daily, loca		
Manager United Iron Works. In 1910 Daily moved to 1117	3, 3	
E. Walnut - next door - and rented out this house.	12) architect with vestiged queen	
	13) builder Anne details	
	14) original use Residence	
	15) presentuse Residence	
45) Additional description Front elevation - two bay facade with	16) number of stories 2	•
pedimented gable. There are two pediment areas in the	17) plan shape rectangle	
gable. The first is at the apex and is covered with	18) basement full	
fishscale shingles. The cornice overhangs the lower	19) foundation Rough, faced, coursed	
pediment area with grouped modillions or brackets. The	20) wall construction Frame/ ashlar limestone	
second pediment area is actually indented from the wall		
surface and is covered with shingles. A single light	material lap siding	
fixed sash window is centered in the second pediment	22) contact print Gable asphalt shingle	<u></u>
•	35mm	
area. The pediment itself is set off by a heavily		
moulded and dentiled cornice. At the corners of the		
gable are scrolled brackets. A board frieze acts as		
window head to the second_story windows which are one		
over one light sash. First story windows and all		
others have a narrow applied moulding on the window		
head. There is a full one story hipped roof porch with		
46) Description of environment/outbuildings	23) site plan	ز
	·	
47) Information sources	24) changes -	יינ
Caty Directory 1898-1933	additions/alter- Rear wing added	
Sanborn 1910	ations/moved	
	25) condition Good	
	26) visible from road?	
	27) distance/frontage	
		2)
AQ\ Location of pagatives	29) preservation	
48) Location of negatives Roll 6 #37-40		
40) B	120	
49) Prepared by DDD	30) endangered? No	
	31) on National	
50) Organization Missouri Heritage Trust	Register? No	7
	32) part of	
	established	
	historical district No	
If additional space is needed, attached separate sheets.	33) name of historical	
	district	
	34) is site eligible? Yes	_
· · ·	35) district potential? Yes	30)
	36) date Jan. 26, 1984	-
	37) revision	

a pedimented gable over the entry area. The dentiled cornice is continuous across the porch and pediment. The face of the pediment is plastered and has a foliate design applied to it.


A transom is above the entryway. The upper sash of the only first story window has diamond patterned leaded glass.

On the east elevation is a one-story oriel set at the first story with three faces. Underneath the oriel are three large brackets. The roof is hipped.

The gable dormers on the east, north, and west are gabled with butt shingled faces, and fixed light sash windows.

A one-story gabled wing to the rear has a random ashlar limestone foundation. A shed roofed addition in the north east corner is modern.

GR 25 103-1147



 $N \uparrow$ 

Re an somewhite



## Missouri Historic Architectural Inventory for GRAD CONTROL Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private X	1) inventory number	44	=
— public	2) name (cont)		_
39) Owners — name Ray Mitchell	3) name - historial		
	4) street address	1112 E. Walnut	ł
	5) town or vicinity	Springfield	1
40) Local contact	6) legal description		,
41) Coordinates (UTM)		Ad. E. Smith's Add. Lot	7
42) Quad	7) county	Greene	-
43) Other survey	8) category		2/3)
	(site, structure,	D :3.1:	_
	building, object)	Building	1
44) History	9) significance	Architectural-Contribut	ina
Built 1908-1909 by Elton Murray,	10) date	1908-1909	
salesman for Springfield Grocery Co.	11) style	Catalogue/builder with	
	12) architect	vestiged Queen A	nne
	13) builder	details	11110
	14) original use	Residence	1
	15) present use	Apts.	1
AS) Additional description -	16) number of stories	Apr.s.	4
45) Additional description Front elevation - a very simple narrow	17) plan shape	inno qui a r	┪
cornice moulding sets off the gable pediment in the	18) basement	irregular	1
front wing. In the pediment is a single double hung	19) foundation	full .	1
window with pilastered surround with a moulded entab-		Rough, faced, coursed	4
lature dand corner block bullseyes. All windows on the	20) wall construction	Frame/ ashlar limesto	<b>n</b> e
front and east elevations are one over one light sash	21) roof type	<u>lap siding</u>	4
with a simple narrow moulding applied to the window	material	Hip & Gable combination	
heads. On the inside of the window frame under the	22) contact print	asphalt	5
window head is a spindled entablature.	35mm	shingle	1
		Siringic	1
The front facade presents an L shape created by the pro-			
jecting wing and the bulk of the house. The entrance is			1
in the gable. Across the whole of the front is a one-			
story porch with hipped roof. Over the entry way is			1
a projecting gable on the porch with continuous			
cornice line. The pediment is covered with decorative 46) Description of environment/outbuildings	23) site plan		9
46) Description of environment/outbuildings	25) Site plan	•	
		• •	
			<b>,</b> n
47) Information sources	24) changes -		5)
City Directory 1907-1933	additions/alter-	Rear El additions +	
· ·	ations/moved	exterior stairway	
	25) condition	Good	
	26) visible from road?		
	27) distance/frontage		
	28) accessible?		6
AQ\ Location of pagatives	29) preservation	<del>-</del>	┪
48) Location of negatives Roll 2 #14-18	underway?	N'o	
	30) endangered?	No .	$\dashv$
49) Prepared by DDD	31) on National	No	4
	· ·		
50) Organization Missouri Heritage Trust	Register?	No	75
	32) part of		
	established		
	historical district		4
If additional space is needed, attached separate sheets	33) name of historica	it	Ì
	district		_
			- 1
	34) is site eligible?		
	<ul><li>34) is site eligible?</li><li>35) district potential</li></ul>	? Yes	30
	_	· <del>Yes</del>	30)
	35) district potential		30)

shingles. The cornice of the pediment and on the porch itself is moulded with an open spindled entablature beneath. Porch posts are square, wooden, and taper upward. The wood ballustrade on the porch and steps has turned balusters and a moulded handrail. The steps leading to the orch appear to be limestone.


On the west elevation is a wall dormer with attic window executed in similar manner to the front gable surround.

On the west elevation at the north east crner the second story projects slightly over the first with a moulded cornice. The single parlor window opening under the overhand has a recessed wooden panel above the window head. Originally the overhang above described ended midway in the east elevation at a hipped roof one story open porch which has been filled in recently.

At the rear is a projecting wing with filled in porches and a modern stair leading to an apartment. On the property line is a modern apartment building.

At the street as a concrete walkway with a large iron step set into the concrete in recent times which has the manufacturer's name: PHOENIX FOUNDRY SPRINGFIELD, MO.

GRAT CES L





GRANIBLE ...



Missouri Historic Architectural Inventory for

Division of Parks and Historic Preservation Department of Natural Resources No place to a x 11) inventory number 182

38) Ownership — private X		inventory number	<u> </u>	ןב
— public	2)	name (cont)		
39) Owners—name Congregation of the Mother Redemptrix	3)	name - historial		
<pre>— address 410 Landers Building</pre>		street address	1117 E. Walnut	
40) Local contact		town or vicinity	Springfield	
41) Coordinates (UTM)		legal description	East Side Add. Lot 50	
42) Quad	7)	county	Greene	
43) Other survey	8)	category		2/3)
		(site, structure,	_	=
		building, object)	Building	
44) History Lived in from 1913-1933+ Arthur Dailey, Local Mgr.		significance	Contributing	_
of United Iron Works Co.	10)	date	ca. 1905	4
1107, 1101, 1117 E. Walnut built by same builder.		style	Catalogue/builder with	_
1107; 1101; 1117 E. Harring Darre 25 35		architect	classical_detai	ls .
		builder		_
		original use	Residence	4
		present use	Apartments	4
45) Additional description Red brick used in the construction.		number of stories	2	_4_
Front elevation-two bay facade with gable entry. There		plan shape	irregular	_
is a small gabled dormer on the east elevation. Pediment	18)	basement	full	_
is a small gabled dormer on the east elevation. Pediment in the gable with cornice returns and recessed gable			Rough, faced, coursed	
cornice of simple mouldings. The face of the gable is	1	wall construction	ashlar limeston	e
covered with butt shingles curving inward to the re-	21)	roof type -	Brick/	_
cessed centered window opening of one over one light		material	Hip & Gable combinatio	n 5
sash. Under the cornice is (slightly projecting) a brick	22)	contact print	asphalt	55
belt course. Brick double course relieving arches at the		35mm	shingle	
window openings of rusticated brick headers. The windows			5,. <b></b>	
are one over one light sash. Rough faced limestone sills		-		
at all window openings. There is a double brick stretche				
course to delimit the first and second stories. There				
is a one story hipped roof porch across the front of				10
		site plan		9)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings		site plan		9)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame out-		site plan		9)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings		site plan		9)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame out-		site plan		9)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area	23)			
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame out-	23)	changes -	Exterior stair adde	5)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources	23)	changes - additions/alter-	Exterior stair adde	5)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources  City Directory 1910-1933	23)	changes - additions/alter- ations/moved	West el.	5)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources	24)	changes - additions/alter- ations/moved condition	West el.	5)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources  City Directory 1910-1933	23) 24) 25) 26)	changes - additions/alter- ations/moved condition visible from road	West el. Good	5)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources  City Directory 1910-1933	23) 24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road?	West el. Good	55 ed
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources  City Directory 1910-1933  Sanborn 1910	23) 24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage	West el. Good	5)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources  City Directory 1910-1933	23) 24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	West el. Good	55 ed
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources  City Directory 1910-1933  Sanborn 1910  48) Location of negatives  Roll 6 #42-44  Roll 547-6 #17	23) 24) 25) 26) 27) 28,	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	West el. Good No	55 ed
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources  City Directory 1910-1933  Sanborn 1910	23) 24) 25) 26) 27) 28) 29] 30]	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	West el. Good	55 ed
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources  City Directory 1910-1933  Sanborn 1910  48) Location of negatives  Roll 6 #42-44  Roll 547-6 #17	23) 24) 25) 26) 27) 28) 29] 30]	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	West el. Good No No	5) 6)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources  City Directory 1910-1933  Sanborn 1910  48) Location of negatives  Roll 6 #42-44  Roll 547-6 #17	23) 24) 25) 26) 27) 28) 29 30) 31	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	West el. Good No	55 ed
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources  City Directory 1910-1933  Sanborn 1910  48) Location of negatives  Roll 6 #42-44  Roll 547-6 #17  DDD	23) 24) 25) 26) 27) 28) 29 30) 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	West el. Good No No	5) 6)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources  City Directory 1910-1933  Sanborn 1910  48) Location of negatives  Roll 6 #42-44  Roll 547-6 #17  DDD	23) 24) 25) 26) 27) 28) 29 30) 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	West el. Good No No No	5) 6)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources  City Directory 1910-1933  Sanborn 1910  48) Location of negatives  Roll 6 #42-44  Roll 547-6 #17  DDD  50) Organization  Missouri Heritage Trust	23) 24) 25) 26) 27) 28, 29 30 31	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	West el. Good No No No No	5) 6)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources  City Directory 1910-1933  Sanborn 1910  48) Location of negatives  Roll 6 #42-44  Roll 547-6 #17  DDD	23) 24) 25) 26) 27) 28, 29 30 31	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	West el. Good No No No No	5) 6)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources  City Directory 1910-1933  Sanborn 1910  48) Location of negatives  Roll 6 #42-44  Roll 547-6 #17  DDD  50) Organization  Missouri Heritage Trust	23) 24) 25) 26) 27) 28) 30 31 32	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district oname of historical district	West el. Good No No No No No	5) 6)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources  City Directory 1910-1933 Sanborn 1910  48) Location of negatives Roll 6 #42-44 Roll 547-6 #17  49) Prepared by DDD  50) Organization  Missouri Heritage Trust	23) 24) 25) 26) 27) 28) 30) 31 32	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	West el.  Good  No No No No  No  Yes	5) 6) 7)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources  City Directory 1910-1933 Sanborn 1910  48) Location of negatives Roll 6 #42-44 Roll 547-6 #17  49) Prepared by DDD  50) Organization  Missouri Heritage Trust	23) 24) 25) 26) 27) 28) 30) 31 32 33 34 35	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible?	West el. Good  No No No No No Yes Yes Yes	5) 6)
is a one story hipped roof porch across the front of  46) Description of environment/outbuildings  Behind the house is a one-story shed roof frame outbuilding with a two bay garage and storage area  47) Information sources  City Directory 1910-1933 Sanborn 1910  48) Location of negatives Roll 6 #42-44 Roll 547-6 #17  49) Prepared by DDD  50) Organization  Missouri Heritage Trust	23) 24) 25) 26) 27) 28) 30 31 32 33 34 35 36)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	West el.  Good  No No No No  No  Yes	5) 6) 7)


the house projecting beyond the house to the eastward. The simple moulded cornice and enlature are supported by slender round wooden porch posts with Tuscan capitals. There is a wooden balustrade with turned balusters. The porch floor and structure are of wood. On the west elevation is a second story entrance to an apartment which may be an original oriel window much modified.

On the west roof is a hipped dormer.

On the east elevation is a projecting wing with pedimented gable.

Butt shingles cover the face of the pediment with a continuous cornice setting off the pediment. Brackets are placed at the corners of the gable. Beneath the cornice the corners of the wing are chamtered with a window in each face.

GR AS-Organ



## Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources


38) Ownership — private X			
	1) inventory number	43	Ξ
public	2) name (cont)		
39) Owners — name Ray Mitchell	3) name - historial		]
— address 1122 E. Walnut	4) street address	1122 E. Walnut	1
40) Local contact	5) town or vicinity	Springfield	
41) Coordinates (UTM)	6) legal description	Ad. E. Smith's Add. Lot	4
42) Quad	7) county	Greene	<b>-</b>
43) Other survey	8) category		2/3)
	(site, structure,	D :114:	
	building, object)  9) significance	Building	-
44) History	10) date	3000	-
	11) style	ca. 1890	4
	12) architect	Queen Anne	4
	13) builder		-
	14) original use	Donidonas	┪
	15) present use	Residence	-
45) Additional description –	16) number of stories	Residence	4
45) Additional description Front projecting wing with flat roofed	17) plan shape	Innogulan	٦
dormer one over one light sash with	18) basement	Irregular	-
dentiled entablature with moulding on	19) foundation	Unknown Paugh frank sourced	┨
slight projecting hood. This motif	20) wall construction	Rough, faced, coursed ashlar Limestone	-
carried around most of the house. Owner	21) roof type -	Frane ashlar Limestone	1
informed me that he duplicated much of this moulding.	material	(See description)	-
The Mansard roof has a new shake roof which may or may	22) contact print	(See description)	5
not be original to the nouse. Iripled window in the	35mm		
front wing with larger window in the center and fixed			
upper sash with stained glass in corner paned lights.	 		
Porch with flat roof and jig saw cut out entablature and			
elaborate though small brackets set with the posts. On			
( the east elevation is a 1-1/2 story bay window with			
three sides and window dormer in the Mansard above.	<u> </u> 		
On the west elevation is a three-sided bay of only one 46) Description of environment/outbuildings	23) site plan		9
story with hipped roof. This is a difficult house to			
story with hipped roof. This is a difficult house to			1
read accurately. There is some reason to question the			1
read accurately. There is some reason to question the			
read accurately. There is some reason to question the house and its history.			
· · · · · · · · · · · · · · · · · · ·			
· · · · · · · · · · · · · · · · · · ·	24) changes -		5)
house and its history.	24) changes - additions/alter-	(See Full discussion)	5)
house and its history.	additions/alter- ations/moved	,	5)
house and its history.	additions/alter- ations/moved 25) condition	Good	5)
house and its history.	additions/alter- ations/moved 25) condition 26) visible from road?	Good	5)
house and its history.	additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	Good	
house and its history.  47) Information sources	additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	Good	5) 6)
house and its history.  47) Information sources  48) Location of negatives	additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	Good	
47) Information sources  48) Location of negatives Roll 2 #19-22	additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	Good - - - - No	
house and its history.  47) Information sources  48) Location of negatives	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	Good No No	
47) Information sources  48) Location of negatives Roll 2 #19-22 49) Prepared by DDD	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	Good - - - - No	
47) Information sources  48) Location of negatives Roll 2 #19-22  49) Prepared by DDD  50) Organization Missouri Heritage Trust	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	Good No No	
47) Information sources  48) Location of negatives Roll 2 #19-22 49) Prepared by DDD	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	Good No No	6)
47) Information sources  48) Location of negatives Roll 2 #19-22  49) Prepared by DDD  50) Organization Missouri Heritage Trust	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	Good  No No No	6)
47) Information sources  48) Location of negatives Roll 2 #19-22 49) Prepared by DDD  50) Organization  Missouri Heritage Trust	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	Good  No No No No	6)
47) Information sources  48) Location of negatives Roll 2 #19-22  49) Prepared by DDD  50) Organization Missouri Heritage Trust	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	Good No No No No	6)
47) Information sources  48) Location of negatives Roll 2 #19-22 49) Prepared by DDD  50) Organization Missouri Heritage Trust  If additional space is needed attached separate sheets	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	Good	6)
47) Information sources  48) Location of negatives Roll 2 #19-22 49) Prepared by DDD  50) Organization  Missouri Heritage Trust	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	Good	6) 7)
47) Information sources  48) Location of negatives Roll 2 #19-22 49) Prepared by DDD  50) Organization Missouri Heritage Trust  If additional space is needed attached separate sheets	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	Good  No No No No No No Ves	6)
47) Information sources  48) Location of negatives Roll 2 #19-22 49) Prepared by DDD  50) Organization Missouri Heritage Trust  If additional space is needed attached separate sheets	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	Good	6) 7)



Missouri Historic Architectural Inventory for

Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private X	1)	inventory number	42	ニ
— public	2)	name (cont)		_
39) Owners — name Darrell Hall		name - historial		
—address 2327 E. Broadmoor		street address	1128 E. Walnut	
		town or vicinity	Springfield	
40) Local contact		=		
1) Coordinates (UTM)		legal description	Ad. E. Smith's Add. Lot	
42) Quad		county	Greene 3	
43) Other survey	8)	category	ar conc	2/3)
		(site, structure,		3)
		building, object)	Building	
44) History		significance	Contributing	
		date		
BUILT 1913-1914 by Wm. J. Orr. Lawver		style	1913-1914	
			Catalogue/Builder	
		architect		
		builder		
	14)	original use	Residence	
	15)	present use	Apts.	
45) Additional description	16)	number of stories	2	4
The facade presents an L shape with a		plan shape	Square with wing	
	l	basement		l
continuous. The enves are arrow and prefect. A nearly		foundation	Full	-
of and stony with hippod most fills the angle of the l			Rough, faced, coursed,	
chang Over the entry is a gabled nameh most with		wall construction	Frame/steel siding	l
	21)	roof type -	steel siding	
tinuous cornice. The porch column s are square wooden		material	Hip with gable wings	
and taper upward. The porch structure is concrete and	22)	contact print	asphalt	5)
more recent (?). The entry is in the angle of the face	]	35mm	-	
with sidelights of diamond leaded glass. A multipaned			shingle	
vestibule encases the entryway and probably is of later				
date. The single window at the first story level in the				
front wing has a leaded glass upper sash. On the west	-			
elevation is a fixed sash small window with leaded				
glass at what is probably a landing in the stairhall.				
On the east elevation the seond story of the projecting	23)	site plan		9)
wing overhangs the first story. All windows are one over	1		in the second se	1
			100	l
one light sash. A one story hipped roof open porch ran	1			
across the rear of the house with a rough faced coursed	1			
cast stone foundation it has since been filled in, and		4	· ·	
a modern addition is behind it.				
47) Information sources	24)	changes -		5)
		additions/alter-	Steel siding added	
0:4 D: 4 1010 1000		ations/moved	Concrete porch rear	
City Directory 1912-1933	25)	condition	being added	7
	Ϊ.	visible from road?	Good	-
	" '			$\dashv$
		distance/frontage		<del> </del>
<u> </u>		accessible?		]စ
48) Location of negatives Roll 2 #23	29)	preservation		
NOTE C #CJ		underway?	No No	
49) Prepared by	30)	endangered?		7
·		on National	No	1
DDD 500 Operation in the contract of the contr	1	Register?	No	
50) Organization	200	_		_3
Missouri Heritage Trust	32)	part of	No	
		established	No	
		historical district		_
If additional space is needec attached separate sheets	33	name of historica		
		district		
	34	) is site eligible?	Vos	7
		) district potential	, Yes	30
		) date		⊣ల
	1		Jan. 26, 1984	-
	37	) revision		4
	1		i	1



S

GR-26-000






Missouri Historic Architectural Inventory for

Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private $\chi$ .	1)	inventory number	33	]=
— public	2)	name (cont)		1
39) Owners — name Homer Wampler III	3)	name - historial		1
-address 1615 S. Glenstone	4)	street address	1129 E. Walnut	1
40) Local contact	5)	town or vicinity	Springfield	1
41) Coordinates (UTM)	6)	legal description	East Side add. Lot 51	1
42) Quad		county	Greene	i
43) Other survey		category	- Conc	N
43) Other survey	, 	(site, structure,		2/3)
		building, object)	Building .	1
	91	significance		3
44) History		date	Architectural-Contribut	ing
Built 1921-1922 by A. T. Quisenberry,			1921-1922	-
Trisurance broke:		style	Colonial Revival	_
		architect		_
		builder		1
		original use	Residence	
	15)	present use	Apartment	]
		number of stories	2	4
Three bay facade with multi-paned sash	17)	plan shape	Rectangle	1
in double hung frames at the window openings. The center	18)	basement	FuT1	1
bay on the second story level is comprised of a tripled	19)	foundation	Concrete	7
window with the larger in the center. There is a small	20)	wall construction		1
portico over the entry in the center bay. It has a flat	21)	roof type -	Gable	1
roof with a wrought iron balustrade on the roof. A broad	1	material	Asphalt shingle	4
entablature and cornice are supported by round wooden	22)		Aspirate sittigle	5
columns with Tuscan capitals. The entry has multi-paned		35mm		
sidelights. On the west elevation is a one-story flat		33/////		
roofed portico over a side entrance with sequare wooden	\			
columns tripled at the corners. On the east elevation				
·	}			
is an open sun porch with a wooden balustrade on a flat				
roof. Porch posts are square of wood and tripled at				-
the corners. Behind the house is a one-story gable				
46) Description of environment out buildings	23)	site plan		9
	1		A contract	
47) Information sources	24)	changes -		5
47) Information Journals		additions/alter-		
City Directory 1920-1933	-	ations/moved	None visible	Ì
	251	condition	Medium to Good	-
	-			4
	1	visible from road?		4
		distance/frontage	-	
		accessible?	-	၂၅
48) Location of negatives	29	) preservation		
Roll 4 #2, 44 Roll 547-7 #2-3		underway?	No	_
49) Prepared by DDD	30	endangered?	No	
עטט	31	on National	}	
50) Organization	1	Register?	No.	
Missouri Heritage Trust	32	) part of		
		established		
		historical district	No.	
If additional space is needed, attached separate sheets	33	) name of historica		7
The state of the s		district		
	34	) is site eligible?		
	(	) district potential	, <del>Yes</del>	30
		) date	Yes	75
		) revision	<del>Jan. 26, 1984</del>	7
	10,	,		

1



0 1 3 2 .06 2 ... 2 2



Missouri Historic Architectural Inventory for GRA - 053 - 053

Division of Parks and Historic Preservation Department of Natural Resources


•				
38) Ownership — private X	1)	inventory number	41	]=
public	2)	name (cont)		[
39) Owners — name Darrell Hall	3)	name - historial		1
-address 2327 E. Broadmoor	4)	street address	1132 E. Walnut	1
40) Local contact	5)	town or vicinity	Springfield	1
41) Coordinates (UTM)		legal description	Ad. E. Smith's Add. Lot	1
42) Quad		county		7
43) Other survey		category	Greene 3	- N
45) Other survey	U,	(site, structure,		2/3)
		building, object)		}
				4
844) History Built 1929-1930 probably by adjacent		significance	Contributing	4
(1100 F. Halmut) as impose producing		date	1929-1930	4
		style		4
		architect		4
	-	builder		1
		original use	Residence/Apt.	
	15)	present use	Residence/Apt.	]
45) Additional description	16)	number of stories	1	4
the windows are one over one light sash	17)	plan shape	Rectangle	7
and have simple narrow applied moulding at the window	18)	basement	None	7
heads. The gables have continuous cornices with simple	19)	foundation	Concrete	-
moulding. The front is covered with a porch with con-	20)	wall construction	Frame/Asbestos siding	7
- Admira in the C. I. C. Albertalbert albertalbert in Idable than A. M. IA. C. Albertalbert		roof type -	Gable	┥
lights in a rear sun porch on the building which apparent	-	material		4
ly doubled as the original kitchen wing.	221	contact print	Asphalt shingle	5
j	(22)	35mm		٦
	}	33mm		
46) Description of environment/outbuildings	23)	site plan		9)
47) Information sources	24)	changes -	Asbestos Siding - pord	5)
City Directory 1920-1933		additions/alter- ations/moved	altered	
	25)	) condition	Good	
	26	visible from road?		٦
	1	) distance/frontage		7
		) accessible?		6
	1 '	) preservation	-	⊣~
48) Location of negatives Roll 2 #24-25	23			
NOTE THE LI		underway?	No No	4
49) Prepared by DDD	1	) endangered?	No	-
	31	) on National		
50) Organization Missouri Heritage Trust		Register?	No	7
Journal of the standard of	32	) part of		
	-	established	No	
	}	historical district		
If additional space is needed, attached separate sheets.	33	) name of historica	1	1
·		district		
	34	) is site eligible?	No	
	35	) district potential		30)
	36	) date	Jan. 26, 1984	
	1	) revision		



Missouri Historic Architectural Inventory for GRAME COS-654

Division of Parks and Historic Preservation Department of Natural Resources

•				
38) Ownership — private X		inventory number	40	1)
public	2)	name (cont)		
39) Owners—name C. Arch Bay		name - historial		
<pre>—address Wilhort-Bay Building</pre>	•	street address	1138 E. Walnut	
( 40) Local contact		town or vicinity	Springfield	
41) Coordinates (UTM)		legal description	Ad. E. Smith's Add. Lot	
42) Quad		county	Greene 2	
43) Other survey	0)	category (site, structure,		2/3)
		building, object)	Building	)
44) History Ruilt 1905-1906 by John C. Keet, Grocer	91	significance	Contributing	
Built 1905-1906 by John C. Keet, Grocer		date	Contributing 1905-1906	
	/	style	Catalogue/Builder	Ì
	l	architect	Catalogue/Bullaci	
	l	builder		Ì
	14)	original use	Residence	1
	15)	present use	Apts.	Ì
45) Additional description		number of stories	2	4
Front elevation - the front projecting	17)	plan shape	Square with wing	]
wing has a pedimented gable with a continuous cornice	l '	basement	Full	}
with a small pent roof. The surface of the pediment is		foundation	Rough,,faced,coursed	}
covered with fishscale shingles. The frieze board under			Frame/lan siding	e
the cornice doubles as the window head to the second story windows. All first story windows have narrow	21)	roof type -	Tap Stuting	]
applied moulding to the window heads. All windows have	001	material	Hip & Gable combination	
one over one light sash. The projecting wing creates	[22)	contact print	asphalt	5)
an L shape with the bulk of the house. The angle create	,	35mm	shingle	Ì
is filled with a one-story porch with hipped roof. The	<b>u</b> .			Ì
cornice and entablature are simple and are supported by				
slim wooden round columns with Tuscan capitals. There				
is a wooden balustrade with moulded handrail and	ļ			Ì
turned balusters. The porch structure and floor are				
48 Description of the restinguishment of the description of the	23)	site plan		9
rear which since has been filled in.				Ì
real winter strice has been filled in.				1
	<u> </u>	· · · · · · · · · · · · · · · · · · ·	·	ļ
47) Information sources	24)	changes -		5)
City Directory 1905-1933		additions/alter-		
·		ations/moved	None visible	4
	1	condition	Good	4
	1	visible from road? distance/frontage		$\dashv$
	1	accessible?		6
40) Leasting of agenting	1	preservation	-	-
48) Location of negatives Roll 2 #26-28		underway?	N -	
49) Prepared by DDD	30	endangered?	No.	1
49) Prepared by DDD		on National		-
50) Organization Missouri Heritage Trust	}	Register?	No	\
50) Organization Missouri Heritage Trust	32	) part of		72
		established		
		historical district	No.	
If additional space is needed, attached separate sheets.	33	) name of historica		
		district		4
	1	) is site eligible?	Yes	1
	1	) district potential?		30)
		) date	Jan. 26, 1984	-
	1.57	) revision	İ	1



SA

CR-AS-003-1214



Missouri Historic Architectural Inventory for (2) -655


Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private $\chi$		inventory number	34	=
public	2)	name (cont)		•
39) Owners—name Eugene R. Smith	3)	name - historial		
-address 1139 E. Walnut	4)	street address	1139 E. Walnut	1
\40) Local contact	5)	town or vicinity	Springfield	1
41) Coordinates (UTM)	6)	legal description	East Side Add. Lot 53	1
42) Quad		county	Greene	1
43) Other survey		category	ui eeile	N
		(site, structure,		2/3)
		building, object)	Don't Talking	)
AAN HEALTH	91	significance	Building	}
44) History Built 1900-1901 by John Farmington - Attorney.		date	Architectural-Social	ł
			1900-1901	-
		style	Queen Anne	ł
		architect		1
	-	builder		
		original use	Residence	
		present use	Resident	
45) Additional description Front elevation - Gable dominates the	16)	number of stories	1	4
facade with staggered butt shingles in the face of the	17)	plan shape	Irregular	]
pediment. There are cornice returns with a narrow band	18)	basement	Full?	1
of moulding as compice setting off the golds national	19)	foundation	Rough Faced coursed.	1
of moulding as cornice setting off the gable pediment.	20)	wall construction	achlan Limestone	1
Over the doubled windows in the gable is found a window	21)	roof type -	Frane/Lap siding	1
nead with narrow applied moulding such as is found on all		material	Lau Stuttiu	1
window surrounds on the house. The gable is actually	22)	contact print	Gable asphalt shingle	5
a projecting wing from a rectangular nouse mass creating	,	35mm		
a T shape. A porch extends across the front of the		33		
gabled wing and extends around to the east elevation un-	}			1
til it meets with the main house mass. The porch has a				
hipped roof except over the entry area where there is a	l			
	ì			
\ able bediment with staggered butt shingles covering	ĺ			
gable pediment with staggered butt shingles covering the face. Beneath the simple cornice and entablature				
the face. Beneath the simple cornice and entablature				
	23)	site plan		9)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings	23)	site plan		9)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used	23)	site plan		9)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings	23)	site plan		9)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used	23)			9)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings				9)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.				9) 5)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings				
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.		changes -	None visible	
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.	24)	changes - additions/alter- ations/moved	None visible	
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.  47) Information sources  City Directory 1898-1910.	24)	changes - additions/alter- ations/moved condition	None visible	
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.  47) Information sources	24) 25) 26)	changes - additions/alter- ations/moved condition visible from road?	None visible Good	
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.  47) Information sources  City Directory 1898-1910.	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road?	None visible Good	5)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.  47) Information sources  City Directory 1898-1910.  Greene ounty Dead Record Book 180 Page 628	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage	None visible Good	
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.  47) Information sources  City Directory 1898-1910.	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	None visible  Good	5)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.  47) Information sources  City Directory 1898-1910. Greene ounty Dead Record Book 180 Page 628	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	None visible  Good  No	5)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.  47) Information sources  City Directory 1898-1910.  Greene ounty Dead Record Book 180 Page 628	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	None visible  Good	5)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.  47) Information sources  City Directory 1898-1910. Greene ounty Dead Record Book 180 Page 628	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	None visible  Good  No  No No	5)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.  47) Information sources  City Directory 1898-1910. Greene ounty Dead Record Book 180 Page 628	24) 25) 26) 27) 28) 30) 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	None visible  Good  No	5)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.  47) Information sources  City Directory 1898-1910. Greene ounty Dead Record Book 180 Page 628  48) Location of negatives  49) Prepared by DDD	24) 25) 26) 27) 28) 30) 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	None visible  Good  No  No No	5) 6)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.  47) Information sources  City Directory 1898-1910. Greene ounty Dead Record Book 180 Page 628  48) Location of negatives  49) Prepared by DDD	24) 25) 26) 27) 28) 30) 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	None visible  Good  No  No  No	5) 6)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.  47) Information sources  City Directory 1898-1910. Greene ounty Dead Record Book 180 Page 628  48) Location of negatives  49) Prepared by DDD	24) 25) 26) 27) 28) 29) 30) 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	None visible  Good  No  No  No  No	5) 6)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.  47) Information sources  City Directory 1898-1910. Greene ounty Dead Record Book 180 Page 628  48) Location of negatives  49) Prepared by DDD	24) 25) 26) 27) 28) 29) 30) 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	None visible  Good  No  No  No  No	5) 6)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.  47) Information sources  City Directory 1898-1910. Greene ounty Dead Record Book 180 Page 628  48) Location of negatives  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	None visible  Good  No  No  No  No	5) 6)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.  47) Information sources  City Directory 1898-1910. Greene ounty Dead Record Book 180 Page 628  48) Location of negatives  49) Prepared by DDD  50) Organization Missouri Heritage Trust	25) 26) 27) 28) 30) 31 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica	None visible  Good  No  No  No  No	5) 6) 7)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.  47) Information sources  City Directory 1898-1910. Greene ounty Dead Record Book 180 Page 628  48) Location of negatives  49) Prepared by DDD  50) Organization Missouri Heritage Trust	25) 26) 27) 28) 300 31 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district of additional	None visible  Good  No  No  No  No  No  Yes	5) 6)
the face. Beneath the simple cornice and entablature are round wood porch columns with Tuscan capitals. The 46) Description of environment/outbuildings  Behind the house is a one-story frame outbuilding used as garage and as storage. The door and window openings have applied moulding.  47) Information sources  City Directory 1898-1910. Greene ounty Dead Record Book 180 Page 628  48) Location of negatives  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 30) 31 32 33 34 35	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible?	None visible  Good  No  No  No  No  No  Yes	5) 6) 7)

porch floor and structure are of wood. 'A wooden balustrade surrounds the porch with turned valusters. The first story window is what must be the entry hall has an elaborately stained glass upper sash done to imitate a spider's wed.

on the west elevation there is a corner cut out in the southwest corner of the main house mass. The area is cut at 90 degree angels instead of the usual 45 degrees creating two new faces recessed. There is an entryway with a small shed roofed porch in the angle of the wing and the main house mass. There are two hipped dormers on the east elevation with staggered butt shingled walls.

12-05-603-605



COLOGINALL



## Missouri Historic Architectural Inventory for Grade Constant Division of Parks and Historic Preservation Department of Natural Resources

•				
38) Ownership—private $\chi$		inventory number	39	ב
— public	-	name (cont)		ı
39) Owners—name Richard Taylor		name - historial		
-address Rt. Box 397	•	street address town or vicinity	1144 F. Walnut	l
40) Local contact 41) Coordinates (UTM)		legal description	Springfield	
42) Quad		county	Ad E Smith's Add Lot	
43) Other survey		category	Greene ]	N
(S) Stills survey	-,	(site, structure,		2/3)
		building, object)	Building	
44) History	9)	significance	Architectural-Commerce	
Built 1903-1904 by Ellis Munger, SecTreas. Dunckel	10)	date	1803-1904	
Box & Lumber Co.	11)	style	Catalogue/Builder with	
	12)	architect	Classical detai	
		builder		
		original use	Residence	
		present use	Apts.	
45) Additional description Front elevationHipped dormer with broad		number of stories	2	4)
		pian snape basement	Irregular	
		foundation	Full	
		wall construction	Rough faced coursed,	
		roof type -	Frame/ ashlar Limeston	e
fact that the front wing has corner chamters under the	,	material		1
	22)	contact print	Hip & gable combination	5)
with bed moulding at the cornice. The frieze board be-		35mm	asphalt shingle	
comes the window heads to all of the second story windows				
on the house. The second story wall surface on the house				Ì
is lap sided with a narrow moulded skirt separating it				
from the first story. The first story has ship lap				
siding which, where joined, forms horizontal wide				
beads. The pediment in the front gable wing is set off by	_			
46) Description of environment/outbuildings	23)	site plan		9
At the rear of the property is a two bay garage of brick		4		
which appears to be later than the house though visible				
on the Sanborn map of 1933.				
47) Information sources	24)	changes -	Rear wing additions	5
City Directory 1903-1933		additions/alter-	l and wing addresses.	
city birectory 1903-1933		ations/moved		
	25)	condition	Good	
	26)	visible from road?	-	
	1	distance/frontage		<b>_</b>
	1	accessible?	-	6
48) Location of negatives	29)	preservation		
Roll 2 #29-34	201	underway?	No.	-
49) Prepared by DDD		endangered?	<u>No</u>	-
	31)	on National Register?	*1	
50) Organization Missouri Heritage Trust	32	part of	No	7
		established		
		historical district	No	
If additional space is needed, attached separate sheets.	33	) name of historical		7
		district	_	
(	34	) is site eligible?	Yes	
		) district potential?	Yes	30)
	l	) date	Jan. 27, 1984	4
	37	) revision		4

a continuous cornice. The pediment itself is deeply recessed as it is flush with the wall surfaces behind the wide projecting eaves and cornice (photo). There is a double hung one over one light sash in the pediment and the face of the area is covered with butt shingles.


.e first story windows have heavily moulded window heads with moulded corner blocks.

The front gabled wing creates an L shaped space with the primary mass of the house. A porch of one story with hipped roof fills the angle and extends around the east elevation until it meets with the east projecting wing.

The porch has a moulded cornice with dentil detailing and a fairly broad board entablature. Squat wooden round columns support the porch roof with Ionic plaster cast capitals. The columns rest on red brick piers with limestone caps. There is a wooden balustrade with moulded handrail and turned balusters. The porch floor and structure are of wood. The steps leading to the porch are of wood as well. The doorway is topped with a transom. The entry to the house is at the angle of the walls. Over the entry on the porch roof is a pedimented gable. The cornice is continuous and the face of the pediment is covered with staggered butt shipngles. At the corners of the gable under the eaves on the cornice are scroll brackets. At the rear elevation is a two-story shed roofed porch which has been filled in recently as well as a smaller one story open porch in the southeast corner. Added to the rear of the rear hipped gabled wing is a one-story modern addition.

In the ground near the southeast corner and next to the rear drive is a limestone hitching post with an iron ring in the top. The post is carved so as to appear like a tree trunk.

no a real lotter



21



## Missouri Historic Architectural Inventory for GRANGE COST Division of Parks and Historic Preservation Department of Natural Resources

	X	1)	inventory number	35	=
— public	•	2)	name (cont)	Mosher House	1~
39) Owners — name	James Riley	3)	name - historial	Mostlet House	ł
— address	1147 E. Walnut	4)	street address	1147 Ø Walmut	1
/ 40) Local contact	1147 L. Mainut	1	town or vicinity	1147 8. Walnut	1
41) Coordinates (UTI	<b>A</b> '	1	legal description	Springfield	1
42) Quad	···	1	county	Fast side Add. Lot 54	1
43) Other survey		1	category	Greene	<del> </del>
45) Other survey		ı	(site, structure,		2/3)
	Historic Site Board Springfield Historic	7			
AAV US-A	Site	1	building, object) significance	Building	1
44) History	Built 1892-1893 by Edward Mosher,		-	Architectural-Commerce	1
	Owner of United Iron Works		date	ca. 1892-1893	1
		1	style	Queen Anne	1
		1	architect		4
			builder		
			original use	Residence	
		1	present use	Residence	<u> </u>
45) Additional description		16)	number of stories	2	4
	West elevation - Wall gable dormer with	17)	plan shape	Irregular	7
	v and wall surfaces covered with butt ship	<b>193</b> )	e <b>S</b> asement	Full	1
	otical eyebrow window to the right of the	19)	foundation	Rough, faced, coursed	1
•	Projecting eaves with simple cornice	20)	wall construction	Limostono	1
though wide frie	eze board double service as window head	21)	roof type -	Frame/ Limescone	1
to the window of	penings of the second story. The second	1	material	Lap Siding	1
story wall surfa	aces are dovered with fishscale shingles.	22)	contact print	Hip Gable combination	5
Where it meets	the first story there is a slight moulded	[	35mm	asphalt shingle	
	ard frieze which doubles as the window	-		·	
head to the fir	st story windows and doors. The north-	}			ì
	the house mass has a gently curving	1			1
	ntinues upward as part of the illusory	1			
	of engaged corner round tower with an				
	roof capped with a metal finial. The roo	f			
-	· · · · · · · · · · · · · · · · · · ·		-9		10
46) Description of enviro	iment/outbuildings	23)	site plan		9
In the rear of t	he property is a one-story outbuilding	}			
of frame constru	ction with a gable garage entrance.		·		
or trame constru	ction with a gable garage entrance.	1			
47) Information sources		24)	changes -		5)
47) Information sources	Historic Site Board File	24)	changes - additions/alter	Sun parlor is added	5)
47) Information sources	Historic Site Board File "The Mosher House" Crystal Wood	24)	_	ca. 1930 (?)	5)
47) Information sources	Historic Site Board File		additions/alter-		5)
47) Information sources	Historic Site Board File "The Mosher House" Crystal Wood	25)	additions/alter- ations/moved	ca. 1930 (?)	5)
47) Information sources	Historic Site Board File "The Mosher House" Crystal Wood	25) 26)	additions/alter- ations/moved condition	ca. 1930 (?)	5)
47) Information sources	Historic Site Board File "The Mosher House" Crystal Wood	25) 26) 27)	additions/alter- ations/moved condition visible from road?	ca. 1930 (?) Good	5) 6)
	Historic Site Board File "The Mosher House" Crystal Wood Cherie McCullah 1981	25) 26) 27) 28)	additions/alter- ations/moved condition visible from road? distance/frontage	ca. 1930 (?)	
47) Information sources  48) Location of negatives	Historic Site Board File "The Mosher House" Crystal Wood Cherie McCullah 1981	25) 26) 27) 28)	additions/alter- ations/moved condition visible from road? distance/frontage accessible?	ca. 1930 (?) Good	
48) Location of negatives	Historic Site Board File "The Mosher House" Crystal Wood Cherie McCullah 1981  Roll 6 #7-13	25) 26) 27) 28)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	ca. 1930 (?) Good	
48) Location of negatives 49) Prepared by	Historic Site Board File "The Mosher House" Crystal Wood Cherie McCullah 1981	25) 26) 27) 28) 29)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	ca. 1930 (?) Good	
48) Location of negatives 49) Prepared by DDD	Historic Site Board File "The Mosher House" Crystal Wood Cherie McCullah 1981  Roll 6 #7-13	25) 26) 27) 28) 29)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	ca. 1930 (?) Good	6)
48) Location of negatives 49) Prepared by	Historic Site Board File "The Mosher House" Crystal Wood Cherie McCullah 1981  Roll 6 #7-13 Roll 547-7 #12	25) 26) 27) 28) 29) 30) 31)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	ca. 1930 (?) Good	
48) Location of negatives 49) Prepared by DDD	Historic Site Board File "The Mosher House" Crystal Wood Cherie McCullah 1981  Roll 6 #7-13	25) 26) 27) 28) 29) 30) 31)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	ca. 1930 (?) Good	6)
48) Location of negatives 49) Prepared by DDD	Historic Site Board File "The Mosher House" Crystal Wood Cherie McCullah 1981  Roll 6 #7-13 Roll 547-7 #12	25) 26) 27) 28) 29) 30) 31)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	ca. 1930 (?) Good	6)
48) Location of negatives 49) Prepared by DDD 50) Organization	Historic Site Board File "The Mosher House" Crystal Wood Cherie McCullah 1981  Roll 6 #7-13 Roll 547-7 #12  Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	ca. 1930 (?) Good	6)
48) Location of negatives 49) Prepared by DDD 50) Organization	Historic Site Board File "The Mosher House" Crystal Wood Cherie McCullah 1981  Roll 6 #7-13 Roll 547-7 #12	25) 26) 27) 28) 29) 30) 31)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	ca. 1930 (?) Good	6)
48) Location of negatives 49) Prepared by DDD 50) Organization	Historic Site Board File "The Mosher House" Crystal Wood Cherie McCullah 1981  Roll 6 #7-13 Roll 547-7 #12  Missouri Heritage Trust	25) 26) 27) 28) 30) 31) 32	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district district	ca. 1930 (?) Good	6)
48) Location of negatives 49) Prepared by DDD 50) Organization	Historic Site Board File "The Mosher House" Crystal Wood Cherie McCullah 1981  Roll 6 #7-13 Roll 547-7 #12  Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31) 32, 33	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	ca. 1930 (?) Good	6) 7)
48) Location of negatives 49) Prepared by DDD 50) Organization	Historic Site Board File "The Mosher House" Crystal Wood Cherie McCullah 1981  Roll 6 #7-13 Roll 547-7 #12  Missouri Heritage Trust	25) 26) 27) 28) 29) 30, 31) 32	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	ca. 1930 (?) Good	6)
48) Location of negatives 49) Prepared by DDD 50) Organization	Historic Site Board File "The Mosher House" Crystal Wood Cherie McCullah 1981  Roll 6 #7-13 Roll 547-7 #12  Missouri Heritage Trust	25) 26) 27) 28) 30) 31) 32 33 34 35 36	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	ca. 1930 (?) Good	6) 7)

the tower maintains the house cornice and frieze and projects from the roof of the house mass, but actually the tower itself is indistinguishable from the mass of the house - the curved surface gives the illusion of there being a distinct tower.

On the first story level the northwest corner is "cut"out" at 45 degree angle to create a face with a window opening.

On the west elevation and on the front elevation placed close to the curved corner surface are two identical window openings. They are large half round openings divided into three distinct areas. The center area is souble hung with one over one light sash. The flanking openings have floreate leaded glass fixed sash. The first story level below the skirt separating it from the second story is covered with lap siding. The main entry is on the front facade with a leaded glass window light set in the upper half.

The two window openings at either first and second story level have laded glass upper sashes over one light.


There is a porch of one story which wraps around the northwest corner giving further visual evidence of the curved wall surface above it. The porch roof is of one pitch except over the entry area on the facade where there is a half elliptical barrel vaulted pediment. The face of the pediment has a plastered design. The house number seems to be of wooden numerals and is a much later addition to the pediment. The cornice is continuous on the porch itself and under the pediment with simple mouldings and narrow entablature.

There are, at intervals, round wooden porch posts with Tuscan capitals resting on a parapet of wood which surrounds the porch. The exterior surface of the parapet is covered with shocale shingles. The porch floor and structure are of wood.


To the rear on the east elevation is a one-story hipped roof sun parlor with multipaned windows and wall surfaces covered with butt shingles. This may be a later addition.

There is a simple limestone buggy stoop at the street. The steps at the sidewalk and at the porch are of limestone as is the slab walkway leading to the house.

Proceedings to the State




C1100-107-157




MOSHER HOME 1147 EAST WALNUT SCALE: 1/8"=1' THIRD FLOOR

0 0 0



MOSHER HOME 1147 EAST WALNUT SCALE: 1/8"=1" FIRST FLOOR


Only and and of



MOSHER HOME 1147 EAST WALNUT SCALE: 1/8"=1' SECOND FLOOR



· · · · · · · · · · · · · · · · · · ·			
38) Ownership — private X	1) inventory number	38	]=
— public  39) Owners — name Δη Ιρες	name (cont)     name - historial		_
Mirech 0633	4) street address	1750 E. Walnut	4
— address 1150 E. Walnut  40) Local contact	5) town or vicinity	Springfield	-
41) Coordinates (UTM)	6) legal description	Ireg. Survey Lot a	-
42) Quad	7) county	Greene	1
43) Other survey	8) category	3. 66.116	N
	(site, structure,		2/3)
	building, object)	Building	-
44) History	9) significance	Architectural-Contribu	iting
Burlt 1925-1926 by Frank C. Mann, Lawyer	10) date	1925-1926	] `
	11) style	Spanish Mission Reviva	1]
	12) architect		
	13) builder		
	14) original use	Residence	_
	15) present use	Residence	4
45) Additional description Front elevation - gabled wing projecting	16) number of stories	2	<b>4</b>
on a hipped roof house. The eaves are narrow with mini-	<ul><li>17) plan shape</li><li>18) basement</li></ul>	L-shape	4
mal overhang. The walls are covered with pink colored	19) foundation	Full ?	4
textured stucco over frame. The windows have six over	20) wall construction	Concrete	4
six light sash. In the gable wing the window openings	21) roof type -	Stucco/frame Hip & gable combination	_
have elliptical heads. The entry is in the angle created	material	asphalt shingle	711
by the projecting wing and the mass of the house. The	22) contact print	asphart siringle	IJ
soor surround is done in colored white formed concrete	35mm		
(?) to appear as if it is ashlar stonework. On the west			
elevation is a one-story entry porch and vestibule with a hipped roof. On the west side of the property is a			
brick drive which does not appear to be of the same vin-			
tage as the house. It is possible that the limestone			
hitching post (visible in the photo) is associated			1
with this property rather than 1144 F. Walnut.			
46) Description of environment/outbuildings	23) site plan		9
At the rear of the property is a one and one half story			
frame outbuilding with jerkinheads on a gabled roof. The			
walls are of board and batten. A large modern garage			i
opening obscures the facade. The outbuilding was ob-			
visously intended as a stable predating the present house 47) Information sources	24) changes -	1	5
by some years.	additions/alter-		
City Directory 1917-1933	ations/moved	None visible	
	25) condition	Good	-
	26) visible from road?		7
	27) distance/frontage	-	$\neg$
	28) accessible?		6
48) Location of negatives Roll 2 #36-38	29) preservation		
100 00	underway?	No	
49) Prepared by DDD	30) endangered?	-	
	31) on National	-	
50) Organization Missouri Heritage Trust	Register?		_ <del>_</del>
-	32) part of		
	established	No	
W. Aller	historical district		-
If additional space is needed, attached separate sheets.	33) name of historical district	_	1
	34) is site eligible?		$\dashv$
	35) district potential?	Yes	30
	36) date	168	۳
	37) revision	Jan. 27, 1984	7
			$\neg$






•				
38) Ownership — private X	1)	inventory number	36	]=
— public	2)	name (cont)		1
39) Owners—name Lauren Davidson	3)	name - historial		1
—address 1159 E. Walnut	4)	street address	1159 E. Walnut	7
(40) Local contact	5)	town or vicinity	Springfield	7
41) Coordinates (UTM)	6)	legal description	East Side Add. Lot 56	
42) Quad	7)	county	Greene	
43) Other survey	8)	category		2/3)
Historic Site Board Springfield Historic		(site, structure,	Deci 1 di una	3
Site		building, object)	Building	1
44) History Built 1893 by George Anderson, former	9)	significance	Architectural-Commerce	.]
lumber baron from Ozarks. Bought Home Lumber Co. in	10)	date	1893	1
1890. Sold 1898 to Edgar Drake a buyer for Heers De-	11)	style	Queen Anne	1
partment Store. Lived here until 1943.	12)	architect		1
pur tillette Score. Elved here diter 1545.	13)	builder	C.J.Burnell	1
	14)	original use	Residence	1
	15)	present use	Residence	7
45) Additional description Front elevation - pedimented gable in	16)	number of stories	1	4
the projecting wing. The apex of the gable has a plaste	17)	plan shape	Irregular	7
	18)	basement	Full	7
work panel with a floreat design above doubled windows used as attic vents with louvers. The surrounds have	19)	foundation	Rough, faced, coursed,	7
	20)	wall construction	achlan Limocto	um e
fluted pilasters and corner bullseyes with a moulded	21)	roof type -	Frame/lap siding	7
window head. The face of the pediment is filled with	1	material	Hip with gable wings	┥
shingles. A narrow moulded cornice sets off the pedi-	22)		asphalt shingle	5
ment. Below the cornice the corners of the wing are characters.	m	35mm	asphart siringle	1
fered with large_brackets with pendants framing the	Ì			1
angled corner. There is a wide frieze which carries				1
around the entire east and front elevations under the	-			
eaves which has applied wooden strips laid in a vertical	1			
repattern (see photo). The frieze just described be-				
comes the window head to all of the openings below.				
The front wing creates an L shape with the house mass on	221	site plan		و
46) Description of environment/outbuildings	23,	site plan		
Behind the house is a two-bay garage which is later than				
the house.	1			
the house.	}			
	-			
	0.4			5
47) Information sources "A Journey into the Past" 1976 - Phylli	S 24	cnanges -		-
Woolsey		additions/alter-	Porch on east el. remo	ved
Historic Site Board File		ations/moved		_
City Directory 1898-1933	- 1	) condition	Good	4
·	[	visible from road?		_
		) distance/frontage		
		) accessible?		_
48) Location of negatives Roll 6 #14-15	29	) preservation		)
	}	underway?	No -	_
49) Prepared by DDD	30	) endangered?	Ne	_
	31	) on National	1	
50) Organization Missouri Heritage Trust		Register?	No.	
- in 330ur i her rouge in use	32	) part of		
		established	No	
		historical district	110	
If additional space is needed, attached separate sheets	33	) name of historical		
		district		
	34	) is site eligible?	Yes	
	35	) district potential?	Yes	30)
	36	) date	Jan. 27, 1984	
	37	') revision	udii. 2/, 1904	

## 1159 E. Walnut

In the north west corner. The entrance, with transom above, is in the angle of the two suse sections. A porch fills the space in the angle and continues around the west side of the house till it meets with a projecting wing on the west elevation.

The porch has a hipped roof with dentiled cornice. The supports are round wooden columns with Tuscan capitals. The porch floor and structure are of wood.

On the east gable projecting wing there are scroll brackets at the corners of the gable roof. The single window opening has a stained and leaded glass upper sash over one light. All other windows are one over one light sash in the house.




NA

CR-ASSOCIATION



38) Ownership — private X		inventory number	37	]=
— public		name (cont)		] -
39) Owners—name Laverta Reisner		name - historial		]
-address 1160 E. Walnut		street address	1160 E. Walnut	1
41) Coordinates (UTM)		town or vicinity legal description	Springfield	-
42) Quad		county	Ireg. Survey 166 Lot b	-
43) Other survey		category	Greene	<del> </del>
43) Other Survey	0,	(site, structure,		2/3)
		building, object)	D: 1 dim ~	
44) History	9)	significance	Building	1
Build 1919-1920 by John J. Angersbach,		date	Contributing 1919-1920	-
Retired	11)	style	Four Square	7
THE OTT CO	12)	architect		
	13)	builder		
	14)	original use	Residence	}
	_	present use	_Apartment	]
45) Additional description	16)	number of stories	2	4
Bellcast hipped dormers on all roof faces			Square	
with extremely wide projecting eaves. There are doubled windows which appear to be doble hung with single light	- 1	basement	Full	
sash in the opening.	1	foundation	Rough,faced,coursed	]
The pronounced wide projecting eaves is carried on to the	20)	wall construction	Frame/ ashlar cast sto	he
house itself. The facade is three bay with one over one	21)	roof type - material	steel sluing	4
light sash in all windows. There is a one story hipped	321	contact print	Bell cast hip asphalt	5
roof porch on the facade with wooden round columns sup-	(22)	35mm	shingle	5
ports with Tuscan capitals in turn supported on rough		33111111		
faced cast stone piers. The porch structure is of wood	İ			
with wooden floor though the balustrade is of modern				
wrought ironwork.				Ì
On the west elevation is a oriel window at the second				}
story level with three scrolled brackets under the oriel.				
The roof is tucked under the eaves. On the east elevation of environment/outbuildings	23)	site plan		9
is a one-story bay window with a bell cast hipped roof.				1
Originally there was a one-story porch on the rear				
supported on cast stone piers, but the porch has been				
filled and a second story added to the porch. At the				
rear is a detached modern apartment complex.	0.43			\ (T)
47) Information sources	24)	changes - additions/alter-	Steel siding added 2nd	ع اد
City Directory 3918-1933.	}	ations/moved	S on rear porch.	1
	251	condition	Modern porch posts	-
	1 '	visible from road?	Good	4
	1	distance/frontage		_
	1 '	accessible?	-	9
48) Location of negatives	1 .	preservation	_	┥¯
Roll 2 #39-40		underway?	No	
49) Prepared by	30	endangered?	No	٦
DDD	31	on National	1,0	7
50) Organization Missouri Heritage Trust		Register?	No	
777330ut Title Fouge Trade	32	) part of		$\neg$
		established		
		historical district	No.	_
If additional space is needed, attached separate sheets.	33	) name of historical		
		district		-
	1	) is site eligible?	No No	w
		) district potential? ) date		30)
	1	) revision	Jan. 27, 1984	$\dashv$
	17,	,		-



5



· · · · · · · · · · · · · · · · · · ·	•				
38) Ownership — private	X .	1)	inventory number	84	]=
public		2)	name (cont)	Hahn House	]
	John Hahn et al	\ `	name - historial		
	c/o John Hulston P. O. Box 1591	1 '	street address	1200 E. Walnut	4
40) Local contact		1	town or vicinity	Springfield	4
41) Coordinates (UTN	1)	1	legal description	O.H.Mitchell's Add.	4
42) Quad	···	<u> </u>	county	Greene Lot 4	<del>                                      </del>
43) Other survey		8)	category		2/3)
			(site, structure, building, object)	Puilding	
AA\ Listory		9/	significance	Building Architectural-Commerce	_
44) History	Build 1921-1922 by John H. Hahn, Pres.	l	date	1921-1922	=
	zark Land & Lumber Co. Unil her death	1	style	Four Square - Catalogi	
in 1982, daughte	r (?) lived there.	ì	architect	Builder	7
		13)	builder	34.1.46.	7
		14)	original use	Residence	7
			present use	Residence	7
45) Additional description		16)	number of stories	2	4
	On the front and west elevations are	17)	plan shape	Square	7
	wide projecting eaves and cornice re-	18)	basement	Füll	
	e on the dormers still projects notice-	19)	foundation	Rough, faced, coursed	7
	complete pediment. The window openings	20)	wall construction	Brick Vanash LImes	tone
	ten over one light sash and pilastered	21)	roof type -	Veneer Veneer	
surrounds with but	tt shingled wall surfaces. On the main		material	Hip red clay ceramic t	
nouse mass are with	de projecting eaves with a moulded cornic ers under the eaves are brackets on each	22)			5
	r. The wide frieze board is the window		35mm		
	nd story window openings. The second				
	e smooth limestone sills and twelve over	}			
	The facade is three bay with doubled				
	ngs at the first and second bays on the				
	level with a center bay comprised of a				
very small opening	though still with 12 over one light sas	h			9
467 Description of enviror	ment/outbuildings	23)	site pian		٦
Behind the house	is a one-story brick veneered gable				
	a red clay roof which appears to be				
original.	•				
-					
47) Information sources		24)	changes -		5
4// Information sources	Guardian of Estate Mr. Frazier		additions/alter-		
	City Directory 1915-1933		ations/moved	None visible	
		25)	condition	Good	
		26)	visible from road?		
		27)	distance/frontage	_	
		28)	accessible?	-	0
48) Location of negatives	Roll 4 #14-17	29	preservation		
-	Roll 547-8 #1-2		underway?	No	
49) Prepared by DDD	KUTT 547-0 #T-Z	30	endangered?	No	
טטט		31	on National		
50) Organization	Missouri Hamitago Trust		Register?	No	
-	Missouri Heritage Trust	32	) part of		
			established		
			historical district	110	
If additional space is need	ed_attached separate sheets.	33	) name of historica	'	
			district		_
(		- (	) is site eligible?	Yes	ω
			) district potential?		30)
		- 1	) date ) revision	Jan. 27, 1984	$\dashv$
		3/	, 164131011		—


The entry is in the first bay with a more recent vestibule build around the entry way with large multipaned window areas. The entry itself has a large limestone smooth dressed lintel. T re are sidelights flanking the entry with panels below and a four light sash fixed in the  $u_{\rm tr}$ er portion of the sidelight opening.

The windows are single at the first story with large smooth dressed limestone lintels.

There is a one-story porch across the front elevation and around almost all of the west elevation as well. The roof is covered with red clay tile and has a hipped roof plan with pedimented gables over the front and side entrances to the porch. The pediments have wide projecting gable eaves and cornice returns while the full cornice in the pediment projects noticeably. The face of the pediment is covered with shingles. The porch roof has wide projecting eaves with moulded cornice and wide entablature supported by square brick columns with square limestone capitals. The porch itself has a brick parapet with smooth limestone coping. The limestone water table is carried around the porch and there are limestone steps leading to the porch. Below the watertable the foundation of the porch is rough faced coursed ashlar limestone.

On the rear elevation is a one story sun porch with a flat roof. On the east elevation is an oriel window at the first story level with a gabled red tile roof and triple window. Under the oriel are tripled scrolled brackets.

Co rossini



S 1

(22 mg/2 1906



	Division of Parks and mistoric Preservation Dep	artn	ient of Matura		
38) Ownership — privat	•	1	inventory number	59	]=
— public		1	name (cont)		
39) Owners — name	Alpha Sigma Alpha Sorority 1201 E. Walnut	1	name - historial		_
address 40) Local contact	1201 E. Walliut	1 '	street address town or vicinity	1201 E. Walnut	4
41) Coordinates (U	TM)		legal description	Springfield	-{
42) Quad	1117	1	county	Hawthorne add. Lot 10	-
43) Other survey	· · · · · · · · · · · · · · · · · · ·		category	Greene	-
10, 21,10, 22,10,		-,	(site, structure,		2/3)
			building, object)	Building	
44) History		9)	significance	Architectural-Contribu	ut i r
•	Build 1914-1915 by James P. Nixon,	1	date	1914-1915	<del>-</del> ' '
	Attorney	11)	style	Catalogue/Builder with	่า่
	•	12)	architect	Classical det	
		13)	builder		٦.,
		14)	original use	Residence	7
		15)	present use	Sorority House	
45) Additional descript	on Walls of buff colored brick and there is	16)	number of stories	2	4
a wide smooth	dress limestone water table. Pedimented	17)	plan shape	Irregular	
	the front facade. Broad projecting eave	<b>:</b>	basement	Full	
•	th returns in the pediment. The pediment	[19)	foundation	Rough,faced,coursed	
	n a recessed continusous cornice of wide	1	wall construction	Brick/ ashlar Limesto	one
	e walls of the dormer are slightly splayed	21)	roof type -	veneer cor	1¢rε
	th butt shingles. There are two window		material	Hip asphalt shingles	
	e dormer with eight over one light sash.	22)	contact print		5)
	three bays wide. The eaves of the main		35mm		
house mass are	widely projecting with simple board				
modillions and	a narrow wood frieze board. The second				
	penings are doubled with one over one				
	except in the center bay which has eight				
over one l	ight sash. The lintels and sills appear				
to be smooth 1:	imestone. A porch begins midway on the comment/outbuildings	23)	site plan		9
70, 2000 pt.0 01 c		1-0,	one prant		
Behind the hou	se is <mark>a two bay frame gable garage.</mark>				
Danina one mod	or to a two bay frame gable garage.		*		1
47) Information source		24)	changes -		5
	City Directory 1910-1933		additions/alter-	Sun parlor 2 S added	-
	57 57 12 10 15 15 15 15 15 15 15 15 15 15 15 15 15		ations/moved	ca. 1925 on west el	
		25)	condition	Good	
		26)	visible from road?	-	
		1 .	distance/frontage	-	
			accessible?	-	6
48) Location of negativ	es Roll 547-8 #3-4	29)	preservation	No	
			underway?		
49) Prepared by DDD		- 1	endangered?	No	4
EO) O	Miccouni Honitago Truct	(31)	on National	No	
50) Organization	Missouri Heritage Trust	32	Register? part of	<u>No</u>	<del>-</del> 3
		32	established	1	
			historical district	No.	
If additional snare is nee	ded, attached separate sheets	33	name of historical	No	$\dashv$
addona. space is free			district	_	-
		34	) is site eligible?		$\dashv$
			) district potential?	Yes	30)
			) date	Yes 27 1094	
		37	) revision	<del>Jan. 27, 1984</del>	


facade and continues around to the west elevation. Over the center bay it is covered with a flat reportion. There is a balustrade of wood on the roof of the porch with moulded handrail and turned balusters.

The porch has a moulded cornice with braod entablature. Round wooden columns tripled at the corners and with Tuscan capitals are at the porch corners. Steps leading to the porch are of smooth limestone. Sidelights flank the center bay entryway.

The porch is open at the northwest corner of the house with a buff brick foundation and concrete porch floor. Piers of brick with limestone coping are set at intervals with a wooden balustrade with moulded handrail and turned balusters.

On the west elevation there is a hipped dormer on the roof face. A two story sun parlor has been added onto the open porch taking in one side of a three sided bay window of two stories at the first story level. The roof of the bay is tucked under the broad eaves. The sun porch has multiple light sash windows and the wooden balustrade on the originally open porch are incorporated into the first story level.

On the east elevation is an angle created by the house mass and a projecting east wing. At one time there was an open two story porch under the gabled roof line of the rear of the house which has since been filled in (see drawing).




NA

Courselle




100

1) inventory number 83 38) Ownership - private ۳ 2) name (cont) --- public 3) name - historial 39) Owners --- name S. E. Dobbs 4) street address - address 1208 F. Walnut 1208 E. Walnut 5) town or vicinity 40) Local contact Sprinafield 41) Coordinates (UTM) 6) legal description O.H.Mitchell's Add 7) county 42) Quad Greene 8) category 43) Other survey (site, structure, building, object) Building 9) significance 44) History Contributing Built 1932-1933 by Clifford French 10) date 1932-1933 11) style Colonial Revival 12) architect 13) huilder 14) original use Residence 15) present use Residence 16) number of stories 45) Additional description Narrow moulded cornice at anarrow eave 17) plan shape L-shape line on the three bay front elevation. Full pediment on 18) basement Full. a gabled portico roof with a heavily moulded continuous 19) foundation Concrete cornice. Thin round wooden columns with Tuscan capitals 20) wall construction Brick Veneer support the porch with tripled columns at the corners. 21) roof type -Gable The first and third bays have tripled openings with the center opening with eight over one light sash and the side material [22] contact print asphalt shingles 5 flanking smaller openings with four over one light sash. 35mm The entry has The lintels are flat arch brick headers. a fan-shape transom light in a rectangular opening. On the east elevation is a gabled sun parlor with eight over eight light sash at the window openings. The gable has a round window opening in the attic story and there are cornice returns. On the rear wing west face are two boston dormers
46) Description of environment/outbuildings و 23) site plan Behind the house is a one-story brick veneer two bay garage matching the details found on the house with gable cornice returns and circular window centered in the west gable wall. 5 24) changes -47) Information sources additions/alter-City Directory 1930-1933 ations/moved None visible 25) condition Good 26) visible from road? 27) distance/frontage 6 28) accessible? \_ 29) preservation 48) Location of negatives Roll 547-8 #5-6 underway? No 30) endangered? No DDD 49) Prepared by 31) on National Missouri Heritage Trust Register? No 50) Organization 32) part of established historical district No 33) name of historical If additional space is needed, attached separate sheets district 34) is site eligible? Yes 30 35) district potential? Yes 36) date 27, 1984 Jan. 37) revision





	1 4	<del>-, , </del>		
38) Ownership — private X		inventory number	60	ا ت ا
— public	1	name (cont)		4
39) Owners — name Jack Brown	1	name - historial		_
—address 1213 E. Walnut	1 1	street address	1213 E. Walnut	
40) Local contact	1	town or vicinity	Springfield	4
41) Coordinates (UTM)	1	legal description	Hawthorne Add. Lot 11	4
42) Quad	L	county	Greene	
43) Other survey	8)	category		2/3)
		(site, structure,		=
		building, object)	Building	_
44) History  Duil+ 1006 1007 by Dr. Thomas King -	l	significance	Contributing	
Built 1906-1907 by Dr. Thomas King -		date	1906-1907	
0s teopath		style	Catalogue/Builder with	1
		architect	classical deta	_ <b>j</b> ] s
	1 '	builder		
	1	original use	Residence	
	1	present use	Residence	
45) Additional description Front elevation - hipped dormer with		number of stories	2	4
latticed muntin sash over one light window. The eaves of	17)	plan shape	Irregular	7
the house are moderately projecting with narrow cornice.	18)	basement	Full	7
Two bay facade with eight over eight window lights in	19)	foundation	Rough, faced, coursed	
openings which may be modernized. The entry is on the	20)	wall construction	achlar limocto	ne
right and most certainly has been altered. The entry	21)	roof type -	Frame/Lap siding	7
has a portico with gabled pediment and round wooden		material	Hip Asphalt Shingles	
columns with Tuscan capitals supporting it. This is a	22)	contact print		5
		35mm		
remnant of a much larger porch which probably extended				
across the entire facade. The porch structure and floor				
is brick veneered concrete. On the east face is an open				
porch with hipped roof and square tapering columns sup-				
porting the roof. On the west is a two story bay				
μοjection with five sided hipped roof and wall surface.				
The three west facing sides have eight over eight light 46) Description of environment/outbuildings window sash at both stori	23)	site plan		و
4b) Description of environment/odtbuildings window sash at both stori	es	•		
47) Information sources	24)	changes -		5
., momentum sector ( )	- '	additions/alter-	Most of porch has beer	
		ations/moved	removed-window opening	g <b>\$</b>
	25)	condition	on facade altered	$\dashv$
	1	visible from road?	Good	$\dashv$
		distance/frontage	-	_
		accessible?		6
AQ\ Location of pagatives	,	preservation		ات ا
48) Location of negatives Roll 547-8 #7-8	29)	underway?	NI -	
49) Prepared by DDD	30	endangered?	No No	$\dashv$
49) Prepared by UDD		on National	No	-
50) Organization Missouri Heritage Trust	31)			
50) Organization MRSSOUP1 Heritage Trust	30	Register?	No	_\\\
	32	part of established		ĺ
		historical district		
	22	nistorical district name of historical	No No	4
		i vame oi nistorical	I .	
If additional space is needed, attached separate sheets.	33			
If additional space is needed, attached separate sheets.		district		_
If additional space is needed: attached separate sheets.	34	district is site eligible?	No No	ω
If additional space is needed: attached separate sheets.	34 35	district ) is site eligible? ) district potential?	Yes	30)
If additional space is needed, attached separate sheets.	34 35 36	district is site eligible?		30)



Pr. 002 100




Division of Parks and Historic Preservation Depa	artment of Natura	I Resources	
38) Ownership — private X	1) inventory number	61	]=
— public	2) name (cont)		7
39) Owners — name Jane Ulman	3) name - historial		
— address 1221 E. Walnut	4) street address	1221 E. Walnut	
40) Local contact	5) town or vicinity	Springfield	
41) Coordinates (UTM):	6) legal description	<u>Hawthorne Add. Lot 12</u>	
42) Quad	7) county	Greene	_
43) Other survey	8) category		2/3)
	(site, structure,	Building	
44) History	building, object)  9) significance	Contributing-Social	4
Built 1905-1906 by Lee Ulman,	10) date	1905-1906	4
Treas. of Ulmar Trust Co.	11) style	Catalogue/Builder	4
	12) architect	Four Square	$\dashv$
	13) builder	Tour Square	$\dashv$
	14) original use	Residence	_
	15) present use	Residence	
45) Additional description Hipped dormer on the front facade with	16) number of stories	2	4
fixed multi paged each and walls severed with shingles	17) plan shape	Rectangle	-
fixed multi-paned sash and walls covered with shingles. The eaves project noticeably and the cornice is obscured	18) basement	Full	_
by the modern siding. Three bay facade with multipaned	19) foundation	Rough, faced, coursed	1
sash over one light double hung windows in the first	20) wall construction	ashlar Limestone	2
and third bays of the second story. The center bay of	21) roof type -	Frame/steel siding	
the second story has a multi-paned transom above two	material	Hip Asphalt shingles	
small double hung windows with one over one light sash.	22) contact print		5)
All window surrounds have applied narrow moulding to the	35mm		
window heads. On the first story there are sidelights			
to each of the first and third bays with multi-paned			
lights with geometric design muntins (photo). The			
double hung window itself has one over one light			
sash. Multipaned and paneled sidelights flank the entry itself with fluted surrounds on the doorway. A			
entry itself with fluted surrounds on the doorway. A  46) Description of environment/outbuildings	23) site plan		و
40) Description of environment/outsumantgs	25) Site plan		٦
Behind the house is a one bay garage with hipped roof			
of frame construction with lap siding.			
or traine construction with rap starting.			
47) Information sources	24) changes -		5)
City Directory 1900-1910	additions/alter-		1
1918-1933	ations/moved	Steel siding added	_
Greene County Deed Record Book 226, page 139	25) condition	Good	_
dicence country beed nector a book 220, page 105	26) visible from road?	_	_
	27) distance/frontage	-	
AO) Location of possible	28) accessible?	-	6)
48) Location of negatives Roll 547-8 #10-11	29) preservation underway?	N -	
	30) endangered?	No	_
49) Prepared by DDD	31) on National	No	
50) Organization	Register?	No	
Missouri Heritage Trust	32) part of	NO	<b>–</b> 3
	established		
	historical district	No	
If additional space is needed attached separate sheets	33) name of historical		7
	district	_	
	34) is site eligible?	Yes	
	35) district potential?		30
	36) date	Jan. 27, 1984	
	37) revision		_

full porch across the entire facade though it is roofed only over the first and second bays.

porch roof is flat (?) with simple cornice and entablature with fluted round columns and Tuscan capitals. The plinth is of cast stone resting on a parapet and foundation of rough faced coursed ashlar cast stone.

On the east elevation there are multipaned fixed sash windows in what must be a front parlor.


12 25 002 /31



NY



38) Ownership — private	X *	1)	inventory number	82	]=
— public	ŕ	2)	name (cont)		7
39) Owners — name	Union National Bank of Springfield	3)	name - historial		7
address	as Trustee of Lucy Arnold	4)	street address	1230 E. Walnut	7
~ 40) Local contact	P. 0. Box 1157	5)	town or vicinity	Springfield	1
41) Coordinates (UT	M)	6)	legal description	O.H. Mitchell's Add.	7
42) Quad		7)	county	Greene Lot 10	
43) Other survey		8)	category		2/3)
			(site, structure,	D. 11.1.	ω
			building, object)	Building	
44) History	Duild 1000 1000 by Man M. Manufaca	9)	significance	Architectural-Contribu	utin
	Build 1932-1933 by Mrs. M. Morrison	10)	date	1932-1933	7
		11)	style	Tudor Revival	7
		12)	architect		
		13)	builder		
		14)	original use	Residence	
		1	present use	Residence	
45) Additional description	Extremely high pitch roof with three	16)	number of stories	1-1/2	4
hinned dormors	on the west roof face. There is a five-	17)	plan shape	Irregular	
	of dormer on the front elevation posi-	18)	basement	Full	
	e recessed entry way below. There are	19)	foundation	Concrete	
	s with latticed leaded sash. Each gable	1	wall construction	Brick & Frame	
	s flush eaves with a face of half-timber	21)	roof type -	Hip gable asphalt	
	The right hand gable face has a half		material	shingles	
	window with multiple light sash and fan	22)	contact print		5)
	in the half round portion. Below in the		35mm		
	ck portion of the gable is a casement				
	enter fixed sash all with multi-paned				
	e lintel is exaggerated rough sawn wood.				
	hand gable is an engaged chimney rising to				
	gable. The chimney is of brick covered				
with stucco work	k except in the lower left corner where —				
46) Description of enviro	k_except in the lower left corner where nment/outbuildings	23)	site plan		9)
	empted to create the illusion of missing				
•	g a broken joint with a brick portion of				
	e (see photo). On the west televation is				
	parlor with large window areas. The entry	/			
	in a recessed area created by the two				
	There is a slightly projecting surround	24)	changes -		5)
·	crete made to imitate ashlar stonework.		additions/alter-	None visible	
	is slightly elliptical. The exterior door	1	ations/moved		_
is multi-paned	and probably original.	1	) condition	Good	_
	C:   D:   1000		visible from road?		_
	City Directory 1933	1 .	) distance/frontage		
		1	) accessible?	-	6
48) Location of negatives	Roll 547-8 #12-13	29	) preservation		
	ROTT 347-0 #12-13		underway?	No	
49) Prepared by	DDD		) endangered?	No	_
		31	) on National		
50) Organization	Missouri Heritage Trust		Register?	No No	<b>⊣</b> ∃
		32	) part of		
			established	No	
ar are	and the short of a second of the short	22	historical district ) name of historical		$\dashv$
If additional space is need	ed_attached separate sheets.	33	district	-	
		24	) is site eligible?	Vas	$\dashv$
		- 1	) district potential?	Yes	ļω
		- 1	) date		30)
			) revision	Jan. 27, 1984	-
		'	,		$\dashv$



GRAGOUR-HOUSE




Division of Parks and historic Preservation Department	irtinent of Natural Re	sources
38) Ownership — privatex *	· -	2 =
— public	2) name (cont)	
39) Owners—name Justin Baker	3) name - historial	
address 1231 E. Walnut		T E. Walnut
40) Local contact		ingfield
41) Coordinates (UTM)		thorne Add. Lot 13
42) Quad 43) Other survey	7) county Gre 8) category	
43) Other survey	(site, structure,	2/3)
	1 ' ' 1	lding
44) History	I I	hitectural-Contributing
· · / · · · · · · · · · · · · · · · · ·		1895
		en Anne
	12) architect	5 /c
	13) builder	
	14) original use Res	idence
	15) present use Res	idence
45) Additional description	16) number of stories	2 🕭
Front elevation - at the southeast	17) plan shape Trr	egular
corner is a gable taken from the corner of the hipped	18) basement Full	· · · · · · · · · · · · · · · · · · ·
roof plan. There are modillions under the gable eaves.	19) foundation Rou	gh,faced,coursed
The wall surfaces are obscured by the modern siding.	20) wall construction Fra	me/ ashlar Limestone
Window heads on the house project slightly with light	217 1001 type	steer stuffig
moulding. All window lights are one over one sash.		with gable wing
The entryway has sidelights and transom. The porch ex-	22) contact print	asphalt shinglesಅ
tends across most of the facade and continues around to	35mm	
the west side elevation. The porch has a hipped roof		
with a dentiled and moulded cornice supported by square wooden tapering porch posts which are tripled at the		
r mers and doubled at intervals between. The columns		
in turn are supported by brick piers. The foundation		
is of brick with a cast stone water table and coping on		
46) Description of environment/outbuildings	23) site plan	9
	,	
47) Information sources		orch below roof alter#d
	1	teel siding added
	ations/moved	
	25) condition Go	bod
	27) distance/frontage	
	28) accessible?	6
49) Location of pagatives	29) preservation	
48) Location of negatives Roll 547-8 #14-15	1	No
49) Prepared by DDD	I ———	No
43) Trepared by SBD	31) on National	
50) Organization Missouri Heritage Trust	Register?	No
oo, organization Prissour File Flage Trust	32) part of	
	established	
	historical district	No
If additional space is needed, attached separate sheets.	33) name of historical	
	district	
	34) is site eligible?	Yes w
	35) district potential?	Yes
	36) date	Jan. 27, 1984
	37) revision	

around the porch with square balusters. There are smooth limestone steps leading to the porch, a limestone (with vermiculated treatment) buggy stoop is at the street and a limestone slab walkway.

It is likely that the porch roof and cornice are original to the house but that the columns and porch structure are later alterations. In the southeast corner of the house is a corner bay at thefirst story with five sides at the first story level. A hipped roof covers the bay with only three faces so that the appearance is that the bay has chamfered corners (see drawing). Each face has a one over one light sash window.

A small gabled dormer is positioned on the roof hip on the front facade. To the left and at the southwest corner is a flat roof tower projection above the roof level of the house mass. There are eight sides to the tower above the roof level. The eaves and cornice of the house are continuous around the corner though they match the second story level with the corner chamfered. The angled face has a one over one light sash window at the second story level. Below at the first story level the depth of the corner cut out is much greater than at the second story level (see drawing).

RP-AS-CC - 667



1. x . 95 66 2 107




38) Ownership — private $\chi$	1) inventory number	81	
— public	2) name (cont)		7
39) Owners — name Elizabeth Farthing	3) name - historial		
— address 1234 E. Walnut	4) street address	1234 E. Walnut	
40) Local contact	5) town or vicinity	Springfield	
41) Coordinates (U <sup>T</sup> M)	6) legal description	Ireg. Survey 34 Lot A	
42) Quad	7) county	Greene	
43) Other survey	8) category		2/3)
	(site, structure,		50
	building, object)	Building	
44) History Built 1911-1912 by Ewing Y. Mitchell, a	9) significance	Architectural-Commerce	ع ا
prominent lawyer	10) date	1911-1912	
	11) style	Calonial Revival	
	12) architect		
	13) builder		
	14) original use	Residence	
	15) present use	Residence	
45) Additional description  Post example of its type. Three podi	16) number of stories	2	4
Best example of its type. Three pedi-	17) plan shape	Rectangle	7
mented gable dormers positioned above the three bay	18) basement	Full T	
facade. Continuous cornice on the dormer pediments with	19) foundation	Concrete	
six over six light sash double hung windows in the dor-	20) wall construction	Frame/Steel siding	
mer. The walls and face of the dormers are covered with	21) roof type -	Gable	
modern cedar shale shingles.	material	asphalt shingles	
There are wide projecting eaves with moulded cornice.	22) contact print		5
The frieze board is the head to the window openings of	35mm		
the second story. The first and third bays at the			
second story are eight over eight light sash. The center			
bay and the first and third bays of the first story are			
identical with tripled window openings. The center open-	•		
ing is larger with six over six light in the second			
story window openings while the flanking openings have	2		
46) Description of environment/outbuildings	23) site plan		9
	·	•	İ
47) Information sources	24) changes -		5
City Directory 1910-1933	additions/alter-	Steel siding + cedar	
57 57 5 17 CC CO. y 1310 1300	ations/moved	shingle added	
	25) condition	Good	
	26) visible from road?	-	
	27) distance/frontage	-	
	28) accessible?		9
48) Location of negatives Roll 4 #13	29) preservation		_
Roll 547-8 #16-17	underway?	No	
49) Prepared by DDD	30) endangered?	No	
טטט	31) on National		$\dashv$
50) Organization Missouri Heritage Trust	Register?	No	<u></u>
- missouri nericage rrusc	32) part of		- 2
	established		
	historical district	No	
If additional space is needed attached separate sheets	33) name of historical	110	-
•	district	_	
	34) is site eligible?	Yes	
	35) district potential?		30)
	36) date	Jan. 27, 1984	⊣≝
	37) revision	<u>Vall+ 2/3 1504</u>	-

fr ~ light sash. First story tripled window openings have eight over eight light sash in the concer window.

There is a portico over the center bay entrance with an open elliptical roof with a dentiled cornice under the gable eaves and with cornice returns. Under the returns are scrolled brackets. The porch is supported on round wood columns with Tuscan capitals. At the entryway there are sidelights which are set off by pilasters matching the porch columns.

On the east elevation is a one-story hipped roof sun parlor with square coffered pilasters. The window openings have multi-paned lights. The steel siding obscures other details. Wide pilastered corner boards are found on the front corners of the house. In the gables the face is covered with modern butt shingle work with pronounced cornice returns.

S



11. 1 NO 115 1. 116 18




CR - 003-1069 Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources 1) inventory number 38) Ownership - private 63 2) name (cont) - public 3) name - historial 39) Owners - name Gene Farthing 4) street address 1235 E. Walnut - address 1235 E. Walnut 5) town or vicinity Springfield \*0) Local contact 6) legal description 41) Coordinates (UTM Ireg. Survey 30-A Lot C 7) county Greene 8) category 2/3 43) Other survey (site, structure, Building building, object) 9) significance Contributing-Commerce 44) History Built 1916-1917 by Charles F. Hatten 10) date 1916-1917 Pres. I. E. Hatten Lumber Co. & Supply 11) style Catalogue/Builder with 12) architect classical detalils 13) builder 14) original use Residence 15) present use Residence 16) number of stories 4) 2 45) Additional description Shed roofed dormer on the front eleva-17) plan shape Rectangle tion with tripled window openings with one over one 18) basement Full light sash. The wall surfaces are covered with butt shingles. Very simple cornice. Flat arch lintels to sed ond wall construction Concrete ? Brick Veneer story window openings. No lintle at all at the first 21) roof type -Gable story. The sills of all windows appear to be limestone. material Asphalt shingled Windows have six over one light sash. 5 22) contact print Pedimented gable roof over the entry in the first bay 35mm of a four bay facade. Very narrow cornice is continuous across the porch. Porch supports are square brick columns. The coping and capitals as well as the steps are of smoothed limestone. The porch continues around the west side of the house with a hipped roof to become continuous with a porte cochere. On the east elevation is an open porch with hipped roof.
46) Description of environment/outbuildings 9 23) site plan 5 24) changes -47) Information sources None visible City Directory 1915-1933 additions/alterations/moved 25) condition Good 26) visible from road? 27) distance/frontage 6 28) accessible? \_ 29) preservation 48) Location of negatives Roll 547-8 #18-19 underway? No 30) endangered? No 49) Prepared by DDD 31) on National Register? No 50) Organization Missouri Heritage Trust 32) part of established historical district No 33) name of historical If additional space is needed, attached separate sheets district 34) is site eligible? Yes 30 35) district potential? Yes 36) date 27, 1984 Jan.

37) revision

42) Quad

NA





CDUNG OF THE



## Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources


— public 2) name (cont)  39) Owners — name   Edward Corbett 3) name - historial	
39) Owners — name Edward Corbett 3) name - historial	
address 1244 E. Walnut 4) street address 1244 E. Walnut	nut
40) Local contact 5) town or vicinity Springfield	
41) Coordinates (UTM)  6) legal description Ireg. Surve	
42) Quad 7) county Greene	34 LUL B
43) Other survey 8) category	
(site, structure,	2/3)
building, object) Building	
bulleting, object/	
Arethicecuri	al-Commerce
Adams-Mosier Mortgage Co. 10) date 1913-1914	
11) style Bungaloid	
12) architect	
13) builder	
14) original use Residence	
15) present use Residence	
45) Additional description 16) number of stories 1_1/2	4
rront elevation - across the front is an   17) plan shape   Death mel-	
engaged wall dormer with a sned root which extends across <sub>[18]</sub> basement	
most of the roof face. Inree bay facade with single 19) foundation Concrete	
window openings at the first and third bay and doubled 20) wall construction Reick over	tilo
at the center in the dormer. The window sash are eight  21) roof type.	CITE
over eight light. The face of the dormer is rough toy	shingle
tured stucco slightly darker than the brick at the 22) contact print	, sningte o
first story. The rafter ends are exposed in the dormer 35mm	3
and at the eaves of the main house mass. Separating the	
wall dormer from the brick faced first story is a thin	
· · · · · · · · · · · · · · · · · · ·	
nrojecting hand of smooth concrete blocks - Brick header	
projecting band of smooth concrete blocks. Brick header	
flat arch lintels on the first story window openings which	
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-	
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side- lights flanking the doorway with paneled inset and small	
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-	9
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side- lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  23) site plan	9)
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side- lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable	9)
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side- lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  23) site plan	9)
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side- lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable	9)
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side- lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable	9)
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side- lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.	9)
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  23) site plan  47) Information sources	5)
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  23) site plan  47) Information sources	5)
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  23) site plan  47) Information sources  City Directory 1910-1933  24) changes-additions/alterations/moved  None visible	5)
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  23) site plan  47) Information sources  City Directory 1910-1933  City Directory 1910-1933  Annual State of S	5)
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  23) site plan  47) Information sources  City Directory 1910-1933  24) changes-additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage	5)
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side—lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  23) site plan  47) Information sources  City Directory 1910-1933  City Directory 1910-1933  Applications/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	e e
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  23) site plan  47) Information sources  City Directory 1910-1933  City Directory 1910-1933  Additions/alterations/moved  25) condition  City Directory 1910-1939  City Directory 1910-1939  Additions/alterations/moved  25) condition  City Directory 1910-1939  City Directory 1910-1939  City Directory 1910-1939  City Directory 1910-1939  City Directory 1910-1939  City Directory 1910-1939  City Directory 1910-1939	5)
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  23) site plan  23) site plan  24) changes-additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  29) preservation  Roll 547-8 #20-21	e e
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side—lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  24) changes—additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  48) Location of negatives  Roll 547-8 #20-21  Roll 547-8 #20-21  Roll 547-8 #20-21	e e
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  47) Information sources  City Directory 1910-1933  City Directory 1910-1933  City Directory 1910-1933  Anditions/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?  No  No  No  No  No  No  No  No  No  N	e e
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  24) changes-additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	e e
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  23) site plan  23) site plan  24) changes-additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  28) accessible?  48) Location of negatives  Roll 547-8 #20-21  49) Prepared by  DDD  30) endangered? 31) on National	e
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  24) changes-additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	e e
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  24) changes-additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  29) preservation underway? 30) endangered? 31) on National Register? No No No No No No No No No No No No No	e
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side—lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  47) Information sources  City Directory 1910–1933  City Directory 1910–1933  And the house is a one-story brick garage with gable single bay entrance.  Value of the house is a one-story brick garage with gable single bay entrance.  And the house is a one-story brick garage with gable single bay entrance.  And the house is a one-story brick garage with gable single bay entrance.  And the house is a one-story brick garage with gable single bay entrance.  And the house is a one-story brick garage with gable single paneled in set and small single paneled in set and smal	e
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  24) changes-additions/laterations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  48) Location of negatives  Roll 547-8 #20-21  49) Prepared by  DDD  30) endangered? 31) on National  Register? 32) part of established  No.	e
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  24) changes-additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 29) preservation 20) endangered? 30) endangered? 31) on National 32) Part of established historical district No	e
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  47) Information sources  City Directory 1910-1933  City Directory 1910-1933  Another ations/moved 25 condition 26 visible from road? 27 distance/frontage 28 accessible?  48) Location of negatives  Roll 547-8 #20-21  49) Prepared by DDD  The properties of the pro	e
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  24) changes-additions/alterations/moved  25) condition 26) visible from road? 27) distance/frontage 28) accessible?  48) Location of negatives  Roll 547-8 #20-21  49) Prepared by  DDD  30) endangered? 31) on National Register? 32) part of established historical district If additional space is needed, attached separate sheets  If additional space is needed, attached separate sheets	Θ (7)
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  24) changes-additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  48) Location of negatives  Roll 547-8 #20-21  49) Prepared by  DDD  30) Organization  Missouri Heritage Trust  Register? 31) and National Register? 32) part of established historical district 34) is site eligible? 35) district potential?  Yes	e (5) (5) (7) (30)
flat arch lintels on the first story window openings which have eight over twelve light sash. There are side-lights flanking the doorway with paneled inset and small  46) Description of environment/outbuildings  Behind the house is a one-story brick garage with gable single bay entrance.  24) changes-additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  48) Location of negatives  Roll 547-8 #20-21  49) Prepared by DDD  30) endangered? 31) on National Register? 32) part of established historical district 11 additional space is needed. attached separate sheets  14 additional space is needed. attached separate sheets  34 is site eligible? 35 district potential?  Yes	e (5) (5) (7) (30)

window sash at the top. There is a full porch across the entire facade though roofed only over the entry area. The porch has a brick parapet and foundation with a concrete floor.

-cast concrete copying covers the brick work. The porch is shed roofed with open structure work beneath used as a decorative element with heavy exposed joists and plates. The porch columns are square and are of brickwork.

The gables of the house have projecting eaves with stuccoed face and corner brackets under the eaves. There are multi-paned parlor windows visible at the first story level in the west elevation.

C-0.00-000-10-10






GR 4 603-671

## Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	χ ,	1)	inventory number		שׁב
— public		2)	name (cont)		7
39) Owners — name		3)	name - historial		
- address	Charles Mariner	4)	street address	1249 E. Walnut	
40) Local contact	1249 E. Walnut	5)	town or vicinity	Springfield	
41) Coordinates (UT	M)	6)	legal description	L.C.Hubbell's Add. Lo	+
42) Quad		7)	county	Greene 1	۲
43) Other survey			category	dicenc	N
45) Other survey		'	(site, structure,		2/3)
			building, object)	Building	
42		-	significance		
44) Built 1932-3	3 by non-resident owner.		date	Contributing	
			style	1932-1933	4
		1 '	,	Tudor Revival	_
		1 .	architect		4
			builder		4
		- 1	original use	Residence	_
			present use	Residence	<u> </u>
45) Additional description	Front elevation - projecting entry gabl	C	number of stories	1-1/2	
with the first	gable projection of random ashlar stone	17)	plan shape	Rectangle	
walls with a si	ngle centered window opening with multi-	18)	basement	Full	
	sh and stone lintel. There is a small	19)	foundation	Concrete	
latticed window	fixed sash in the gable pediment perhaps	20)	wall construction	Brick 1st Frame 1/2 S	torv
	and then another gabled projection rising	21)	roof type -	High gable	7
	is seen with stucco wall surface and hal		material	asphalt shingle	
	ed to the surface. The roof line extends	[	contact print		5)
	feet of the ground (see photo) and it is		35mm		
	t the entrance to the house is found. Th				
		ا ح			
	irst story brick wall of the house mass				
	ne light sash with a rough wooden lintel.				
	r at the facade has a doubled window open				
•	the rear roof face is an almost full she	1			
dormer. On the	west gable wall is a one-story sun parlo	r	V -341		9
46) Description of environment	onment/outbuildings with large window area. On	23	site plan		۳
the east is a g	abled garage which is attched to the hous	e.			
_					
					ì
47) Information sources					
47) IIIIOIIIIation sources		24	) changes -		5)
47) Information sources	City Directory 1930-1933	24	) changes - additions/alter-		5)
47) Information sources		24	_	None visible	5)
47) mormation sources			additions/alter-	None visible	5)
47) mormation sources		25	additions/alter- ations/moved	None visible Good	5)
47) mormation sources		25 26	additions/alter- ations/moved ) condition		5)
47) mormation sources		25 26 27	additions/alter- ations/moved ) condition ) visible from road?		5)
	City Directory 1930-1933	25 26 27 28	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible?		
48) Location of negative	City Directory 1930-1933	25 26 27 28	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation	Good - - -	
48) Location of negative	City Directory 1930-1933  s Rcll 547-9 #1-2	25 26 27 28 29	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway?	Good	
	City Directory 1930-1933	25 26 27 28 29	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered?	Good - - -	
48) Location of negative 49) Prepared by	City Directory 1930-1933  * Roll 547-9 #1-2  DDD	25 26 27 28 29	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National	Good No No	
48) Location of negative	City Directory 1930-1933  s Rcll 547-9 #1-2	25 26 27 28 29 30 31	additions/alterations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register?	Good	
48) Location of negative 49) Prepared by	City Directory 1930-1933  * Roll 547-9 #1-2  DDD	25 26 27 28 29 30 31	additions/alterations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? endangered?	Good No No	6)
48) Location of negative 49) Prepared by	City Directory 1930-1933  * Roll 547-9 #1-2  DDD	25 26 27 28 29 30 31	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ?) part of established	Good No No No	6)
48) Location of negative 49) Prepared by	City Directory 1930-1933  * Roll 547-9 #1-2  DDD	25 26 27 28 29 30 31	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? Part of established historical district	Good	6)
48) Location of negative 49) Prepared by 50) Organization	City Directory 1930-1933  * Roll 547-9 #1-2  DDD	25 26 27 28 29 30 31	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? part of established historical district so name of historical	Good	6)
48) Location of negative 49) Prepared by 50) Organization  If additional space is nee	City Directory 1930-1933  * Roll 547-9 #1-2  DDD  Missouri Heritage Trust	25 26 27 28 29 30 31 32	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ?) part of established historical district so mame of historical district	Good	6)
48) Location of negative 49) Prepared by 50) Organization	City Directory 1930-1933  * Roll 547-9 #1-2  DDD  Missouri Heritage Trust	25 26 27 28 29 30 31 32	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? !) part of established historical district name of historical district i) is site eligible?	Good	6) 7)
48) Location of negative 49) Prepared by 50) Organization  If additional space is nee	City Directory 1930-1933  * Roll 547-9 #1-2  DDD  Missouri Heritage Trust	255 266 277 288 299 300 311 322 333 344 355	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? !) part of established historical district name of historical district i) is site eligible? 50 district potential?	Good	6)
48) Location of negative 49) Prepared by 50) Organization  If additional space is nee	City Directory 1930-1933  * Roll 547-9 #1-2  DDD  Missouri Heritage Trust	25 26 27 28 29 30 31 32 33 34 35 36	additions/alterations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? part of established historical district name of historical district is site eligible? district potential?	Good No No No No Yes	6) 7)
48) Location of negative 49) Prepared by 50) Organization  If additional space is nee	City Directory 1930-1933  * Roll 547-9 #1-2  DDD  Missouri Heritage Trust	25 26 27 28 29 30 31 32 33 34 35 36	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? !) part of established historical district name of historical district i) is site eligible? 50 district potential?	Good No No No No Yes Yes	6) 7)



En 25-1003-1-71



GR-1-1-003-672

Missouri Historic Architectural Inventory for
Division of Parks and Historic Preservation Department of Natural Resources

— public 2) name (cont) Dickey House	Division of Parks and Historic Preservation Depa	rtment of Natura		
- public 39) Owners — man 40) Locationate 41) Coordinates (LITM) 42) Good 43) Gober survey 44) Coordinates (LITM) 43) Coordinates (LITM) 43) Coordinates (LITM) 43) Coordinates (LITM) 43) Coordinates (LITM) 43) Coordinates (LITM) 43) Coordinates (LITM) 43) Coordinates (LITM) 43) Coordinates (LITM) 44) History 54) History 64) History 64) History 65) Build History 66) Locationates (LITM) 67) Locationates (LITM) 68) When exterior/interior remodeled. 69) Significance 60) date 61) Significance 61) date 62) Significance 61) date 63) Significance 64) Significance 64) Significance 61) Significance 61) Significance 61) Significance 61) date 62) Significance 63) Significance 64) Significance 64) Significance 64) Significance 64) Significance 65) Significance 66) Significance 67) Significance 67) Significance 68) Significance 68) Significance 68) Significance 69) Significance 61) Significance 61) Significance 61) Significance 61) Significance 61) Signi	38) Ownership — private X	1) inventory number	79	=
49) tocal compact 40) tocal compact 41) Coordinates (UTM) 42) Count 43) Control Site Board Springfield Historic Site 43) Thistory Built 1869-1870 by Waldo Booth, Hardware store owners. Sold to Edward Stonebraker in 1898 when exterior/interior remodeled. 45) Additional description Five bay facade with a slightly project- ing wall dormer with pedimented gable. The cornice projects from the cornice of the main house mass. The wide projecting eaves in the gable have modificant word projecting eaves in the gable have modificant made ca. 1890. The cornice of the main house mass. The which projecting eaves and a wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped h	•	2) name (cont)	Dickey House	
49) tocal compact 40) tocal compact 41) Coordinates (UTM) 42) Count 43) Control Site Board Springfield Historic Site 43) Thistory Built 1869-1870 by Waldo Booth, Hardware store owners. Sold to Edward Stonebraker in 1898 when exterior/interior remodeled. 45) Additional description Five bay facade with a slightly project- ing wall dormer with pedimented gable. The cornice projects from the cornice of the main house mass. The wide projecting eaves in the gable have modificant word projecting eaves in the gable have modificant made ca. 1890. The cornice of the main house mass. The which projecting eaves and a wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied wopenings have triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped heads with applied word triangular shaped h	39) Owners—name Francis Tucker	3) name - historial		1
40) Local commact 41) Courdinas (UTM) 42) Quard 42) Courdinas (UTM) 43) Consequency Historic Site Board Springfield Historic Site 44) History Built 1869-1870 by Waldo Booth, Hardware store owner. Sold to Edward Stonebraker in 1898 when exterior/interior remodeled. 45) Additional description Five bay facade with a slightly project. 160 presentuse Projects from the cornice of the main house mass. The wide projecting eaves in the gable have modifilions became the frace of the pediment. In the center of the pediment is a palladian window. It is very likely that the entire gable downer is an addition made ca. 1890. The cornice of the main house mass on the facade is moulded with wide projecting eaves and a wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied moulding. The openings have two over two lights ash. There is a small port at the center bay first story entrance with a flat roof and dentiled cornice. The 200 to the flat of the same o	·	4) street address	1260 F. Walnut	1
43) Coordinates (UTM) 43) Contens survey Historic Site Board Springfield Historic Site  43) Whistory Built 1869-1870 by Waldo Booth, Hardware store owners. Sold to Edward Stonebraker in 1898 when exterior/interior remodeled.  45) Additional description Five bay facade with a slightly projecting wall dormer with pedimented gable. The cornice projects from the cornice of the main house mass. The wide projecting eaves in the gable have modificant and wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied awide frieze board. The window surrounds on all window openings have triangular shaped heads with applied wolding. The openings have two over two light sash There is a small porch at the center bay first story entrance with a flat roof and dentiled connice. The  47) Information sources  Historic Site Board File  47) Information sources  Historic Site Board File  47) Information sources  Historic Site Board File  47) Information sources  Historic Site Board File  47) Information sources  Historic Site Board File  47) Information sources  Historic Site Board File  47) Information sources  Historic Site Board File  48) Decaring Missouri Heritage Trust  49) Prepared by Prepared By Prepared By Prepared By Rep		5) town or vicinity		1
437 Output with the periment of the main house mass. The wind with wife periodic ting eaves and a wide frieze board. The window surrounds on all window openings have triangular shaped heads with a piled moulding. The openings have two over two light sash. There is a small porth at the center bay first story entrance with a flat roof and dentiled cornice. The 287 Outs Malada allio-mending square wooden joinery with  47) Information sources.  48) Location of negatives Roll 4 #10-12  48) Location of negatives Roll 4 #10-12  48) Location of negatives Roll 4 #10-12  48) Location of negatives Roll 4 #10-12  49) Prepared body  50) Organization  Missouri Heritage Trust  7) county (obtes structure, building, objecting building, objecting eaves and a wide frieze board. The window surrounds on all window openings have two over two light sash. There is a small porth at the center bay first story entrance with a flat roof and dentiled cornice. The 287 Outs Malada allio-mendical statics. Mal	•	- 1		1
## Historic Site Board Springfield Historic Site ## Historic Site Board Springfield Historic Site ## Historic Site Board Springfield Historic Site ## Historic Site Board Springfield Historic Site ## Historic Site Board Springfield Historic Site ## Historic Site Board Springfield Historic Site ## Historic Site Board Springfield Historic Site ## Historic Site Board Springfield Historic Site ## Historic Site Board File ## Historic Site Board File ## Historic Site Board File ## Historic Site Board File ## Historical district #		_		1
## Historic Site Board Springfield Historic Site  ### History  ### Built 1869-1870 by Waldo Booth, Hardware store owner. Sold to Edward Stonebraker in 1898 when exterior/interior remodeled.  ### Historic Site Board Five bay facade with a slightly project- ing wall dormer with pedimented gable. The cornice of projecting eaves in the gable have modillions be- neath with a shingled face in the pediment. In the  center of the pediment is a palladian window. It is  very likely that the entire gable dormer is an addition  made ca. 1890. The cornice of the main house mass on  the facade is moulded with wide projecting eaves and  wide frieze board. The window surrounds on all window  openings have traingular shaped heads with applied  moulding. The openings have two very two light sash.  There is a small porch at the center bay first story  entrance with a filat roof and dentiled cornice. The  ####################################			di eene	- N
### Additional space is needed attached separate sheets  ### Additional space is needed attached separate sheets  ### Additional space is needed attached separate sheets  ### Additional space is needed attached separate sheets  ### Additional space is needed attached separate sheets  ### Additional space is needed attached separate sheets  ### Additional space is needed attached separate sheets  ### Additional space is needed attached separate sheets  ### Additional space is needed attached separate sheets  ### Additional space is needed attached separate sheets  ### Additional space is needed attached separate sheets  #### Additional space is needed attached separate sheets  #### Additional space is needed attached separate sheets  ##### Additional space is needed attached separate sheets  ##################################				3
## Built 1869-1870 by Waldo Booth, Hardware store owner. Sold to Edward Stonebraker in 1898 when exterior/interior remodeled.  ### Additional description Five bay facade with a slightly project- ing wall dormer with pedimented gable. The cornice projects from the cornice of the main house mass on the facade is moulded with wide projecting eaves and a wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied moulding. The openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The ### Built 1869-1870 by Waldo Booth,  ### Built 1869-1870 by Waldo Booth, 10 pain size of 1869-1870  ### Built 1869-1870 by Waldo Booth, 11 pain store 12 painter 13 builder 13 painter 140 orgenatuse Residence 1870 painter 1870 builders 1870 builders 1870 builders 1870 builders 1870 basement 1970 builders 1870 basement 1970 builders 1970 builders 1870 builders 1970 builders 1870	Historic Site Board Springfield Historic Site		5 . 7	
Hardware store owner. Sold to Edward Stonebraker in 1898 when exterior/interior remodeled.  45) Additional description Five bay facade with a slightly projecting wall dormer with pedimented gable. The cornice projects from the cornice of the main house mass. The wide projecting eaves in the gable have modifilions beneath with a shingled face in the pediment. In the center of the pediment is a palladian window. It is very likely that the entire gable dormer is an addition made ca. 1890. The cornice of the main house mass on the facade is moulded with wide projecting eaves and a wide frieze board. The window surrounds on all window penings have triangular shaped heads with applied moulding. The openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The 1897 Colon Missi				4
Hardware store owner. Sold to Edward Stonebraker in 1898 when exterior/interior remodeled.  1898 when exterior/interior remodeled.  1898 when exterior/interior remodeled.  1898 when exterior/interior remodeled.  1898 when exterior/interior remodeled.  1890 when exterior/interior with a slightly project. In which was a significant with a slightly project. In which was mass on the facade is moulded with wide projecting eaves and a will extend with a sall and window openings have triangular shaped heads with applied moulding. The openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The additional which was a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The additional was a small proper with a story was a small proper with a sall was a small proper with a sall was a small proper with a sall was a small proper with a sall was a small proper with a sall was a small proper with a sall was a small proper with		_		2
120 architect   130 builder   130 builder   130 builder   140 original use   150 present use   150 p			1869-1870	_
45) Additional description Five bay facade with a slightly projecting will dormer with pedimented gable. The cornice projects from the cornice of the main house mass. The wide projecting eaves in the gable have modifilions beneath with a shingled face in the pediment. In the center of the pediment is a palladian window. It is very likely that the entire gable dormer is an addition made ca. 1890. The cornice of the main house mass on the facade is moulded with wide projecting eaves and a wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied moulding. The openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The window appearance with a flat roof and dentiled cornice. The window appearance with a flat roof and dentiled cornice. The window appearance with a flat roof and dentiled cornice. The window appearance with a flat roof and made ca. 1890. The opening have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The window appearance with a flat roof and dentiled cornice. The window appearance with a flat roof and dentiled cornice. The window appearance with a flat roof and dentiled cornice. The window appearance with a flat roof and dentiled cornice. The window appearance wooden joinery with appearance with a flat roof and dentiled cornice. The window appearance wooden joinery with appearance wooden joinery with appearance wooden joinery with appearance wooden joinery with appearance wooden joinery with appearance wooden joinery with appearance wooden joinery with appearance wooden joinery with appearance wooden joinery with appearance wooden joinery with appearance wooden joinery with appearance wooden joinery with appearance wooden joinery with appearance wooden joinery with appearance wooden joinery with appearance wooden joinery with appearance wooden joinery with appearance wooden joinery with appear	Hardware store owner. Sold to Edward Stonebraker in	11) style	<u> Italjanate</u>	
45) Additional description   Five bay facade with a slightly projecting wall dormer with pedimented gable. The cornice projects from the cornice of the main house mass. The wide projecting eaves in the gable have modifilions between the triangle of the pediment is a palladian window. It is very likely that the entire gable dormer is an addition made ca. 1890. The cornice of the main house mass on the facade is moulded with wide projecting eaves and a wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied moulding. The openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentified cornice. The 189 TSAL-MBSH a RNTG-MBARE_HEADINA_ESQUARE Wooden   23) site plan  47) Information sources  Historic Site Board File  48) Location of negatives  Roll 4 #10-12  49) Prepared by DD  50) Organization  Missouri Heritage Trust  45) Additional Space is neeced attached separate sheets  16) Innome of stories   2   2   2   2   2   2   2   2   2	1898 when exterior/interior remodeled.	12) architect		
15) present use   Residence   Partial   Part		13) builder		
45) Additional description Five bay facade with a slightly projecting wall dormer with pedimented gable. The cornice projects from the cornice of the main house mass. The wide projecting eaves in the gable have modifilions beneath with a shingled face in the pediment. In the center of the pediment is a palladian window. It is very likely that the entire gable dormer is an addition made ca. 1890. The cornice of the main house mass on the facade is moulded with wide projecting eaves and a wide frieze board. The window surrounds on all window openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The  47) Information sources  Historic Site Board File  47) Information ources  Historic Site Board File  47) Information ources  Historic Site Board File  47) Information or negatives  Roll 4 #10-12  48) Location of negatives  Roll 4 #10-12  49) Prepared by DD  50) Organization  Missouri Heritage Trust  And ditional space is needed attached separate sheets  Madditional space is needed attached separate sheets  Hadditional space is needed attached separate sheets		14) original use	Residence	
45) Additional description Five bay facade with a slightly projecting wall dormer with pedimented gable. The cornice projects from the cornice of the main house mass. The wide projecting eaves in the gable have modifilions beneath with a shingled face in the pediment. In the center of the pediment is a palladian window. It is very likely that the entire gable dormer is an addition made ca. 1890. The cornice of the main house mass on the facade is moulded with wide projecting eaves and a wide frieze board. The window surrounds on all window openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The  47) Information sources  Historic Site Board File  47) Information ources  Historic Site Board File  47) Information ources  Historic Site Board File  47) Information or negatives  Roll 4 #10-12  48) Location of negatives  Roll 4 #10-12  49) Prepared by DD  50) Organization  Missouri Heritage Trust  And ditional space is needed attached separate sheets  Madditional space is needed attached separate sheets  Hadditional space is needed attached separate sheets		_		1
Partial?  Position the cornice of the main house mass. The wide projecting eaves in the gable have modifilions beneath with a shingled face in the pediment. In the center of the pediment is a palladian window. It is very likely that the entire gable dormer is an addition made ca. 1890. The cornice of the main house mass on the facade is moulded with wide projecting eaves and a wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied moulding. The openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The 489 Teletripolar and the cornice of the main house mass on the facade is moulded with wide projecting eaves and a wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied moulding. The openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The 489 Teletripolar and the center bay first story entrance with a flat roof and dentiled cornice. The 23) site plan  47) Information source.  Historic Site Board File  47) Information source.  Roll 4 #10-12  48) Location of negatives  Roll 4 #10-12  49) Prepared by DD  50) Organization  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Monaditional space is needed attached separate sheets  Mit additional space is needed attached separate sheets  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Mis	45) Additional description			4
Partial?  Position the cornice of the main house mass. The wide projecting eaves in the gable have modifilions beneath with a shingled face in the pediment. In the center of the pediment is a palladian window. It is very likely that the entire gable dormer is an addition made ca. 1890. The cornice of the main house mass on the facade is moulded with wide projecting eaves and a wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied moulding. The openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The 489 Teletripolar and the cornice of the main house mass on the facade is moulded with wide projecting eaves and a wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied moulding. The openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The 489 Teletripolar and the center bay first story entrance with a flat roof and dentiled cornice. The 23) site plan  47) Information source.  Historic Site Board File  47) Information source.  Roll 4 #10-12  48) Location of negatives  Roll 4 #10-12  49) Prepared by DD  50) Organization  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Monaditional space is needed attached separate sheets  Mit additional space is needed attached separate sheets  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Mis	Five bay facade with a slightly project-	•		$\dashv$
projects from the cornice of the main house mass. The wide projecting eaves in the gable have modifilions beneath with a shingled face in the pediment. In the center of the pediment is a palladian window. It is very likely that the entire gable dormer is an addition made ca. 1890. The cornice of the main house mass on the facade is moulded with wide projecting eaves and a wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied moulding. The openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The 1870 the penings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The 1870 the penings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The 1870 the penings have two over two light sash.  There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The 23) site plan  47) Information sources  Historic Site Board File  48) Location of negatives  Roll 547-9 #3-4  Roll 4 #10-12  48) Location of negatives  Roll 547-9 #3-4  Roll 4 #10-12  49) Prepared by ODD  50) Organization  Missouri Heritage Trust  44) Individual space is needed attached separate sheets  45) district potential? 36 date  46) date  47) is site eligible? 35 district potential? 36 date  47) is site eligible? 35 district potential? 36 date  48) Location of negatives  Roll 24) changes additions/alterations/moved 25 condition 26) visible from road? 27 destance/frontage 28) accessible?  47) prepared by Opposition of negatives and additions/alterations/moved 28) and 27, 1984	ing wall dormer with pedimented gable. The cornice			$\dashv$
wide projecting eaves in the gable have modillions beneath with a shingled face in the pediment. In the center of the pediment is a palladian window. It is very likely that the entire gable dormer is an addition made ca. 1890. The cornice of the main house mass on the facade is moulded with wide projecting eaves and a wide frieze board. The window surrounds on all window penings have triangular shaped heads with applied moulding. The openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The 1870-1816-1816-1816-1816-1816-1816-1816-181		1		-
neath with a shingled face in the pediment. In the center of the pediment is a palladian window. It is very likely that the entire gable dormer is an addition made ca. 1890. The cornice of the main house mass on the facade is moulded with wide projecting eaves and a wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied moulding. The openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and dentiled cornice. The 1890 the first story entrance with a flat roof and denti	• =	1 '	T 1 1 1 .	_
very likely that the entire gable dormer is an addition made ca. 1890. The cornice of the main house mass on the facade is moulded with wide projecting eaves and a wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied moulding. The openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The 1876-1876-1876-1876-1876-1876-1876-1876-		I = - ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '	Frame/ asniar Limesto	one
very likely that the entire gable dormer is an addition made ca. 1890. The cornice of the main house mass on the facade is moulded with wide projecting eaves and a wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied moulding. The openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The 1876-1876-1876-1876-1876-1876-1876-1876-	· · · · · · · · · · · · · · · · · · ·		Steel Siding	4
made ca. 1890. The cornice of the main house mass on the facade is moulded with wide projecting eaves and a wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied moulding. The openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The description of the control of the contro		1	Hip Asphalt shingle	
the facade is moulded with wide projecting eaves and a wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied moulding. The openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The  47) Information sources  Historic Site Board File  47) Information sources  Historic Site Board File  48) Location of negatives  Roll 547-9 #3-4  Roll 4 #10-12  49) Prepared by DD  50) Organization  Missouri Heritage Trust  Mis		22) contact print		5
wide frieze board. The window surrounds on all window openings have triangular shaped heads with applied moulding. The openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The 487 Destribution and the center bay first story entrance with a flat roof and dentiled cornice. The 487 Destribution and the center bay first story entrance with a flat roof and dentiled cornice. The 487 Destribution and the center bay first story entrance with a flat roof and dentiled cornice. The 487 Destribution and the center bay first story entrance with a flat roof and dentiled cornice. The 487 Destribution and the center bay first story entrance with a plat roof and dentiled cornice. The 487 Destribution and the center bay first story entrance with a plate with applied cornice. The 487 Destribution and the center bay first story entrance with a plate with applied cornice. The 487 Destribution and the center bay first story entrance with a plate with applied cornice. The 487 Destribution and the center bay first story entrance with a plate with applied cornice. The 487 Destribution and the center bay first story entrance with a plate with applied cornice. The 487 Destribution and the center bay first story entrance with a plate with applied cornice. The 487 Destribution and the center bay first story entrance with a plate with applied cornice. The 487 Destribution and the center bay first story entrance with a flat roof and dentiled cornice. The 487 Destribution additional and the center bay first story entrance with a flat roof and dentiled cornice. The 487 Destribution additional and the center bay first story entrance with a flat roof and dentiled cornice. The 487 Destribution additional and storic and stor		35mm		
openings have triangular shaped heads with applied moulding. The openings have two over two light sash.  There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The  487 Test. 1913 for a Nife manufacutton and gesquare wooden joinery with  479 Information sources  Historic Site Board File  481 Location of negatives  Roll 547-9 #3-4 Roll 4 #10-12  489 Prepared by DD  50) Organization  Missouri Heritage Trust  18 additional space is needed attached separate sheets  18 accessible?  18 additional space is needed attached separate sheets  18 accessible?  18 additional space is needed attached separate sheets  424) changes-additions/alter-a	· · · · · · · · · · · · · · · · · · ·			
moulding. The openings have two over two light sash. There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The 489 Description environments with a flat roof and dentiled cornice. The 489 Description environments with a flat roof and dentiled cornice. The 489 Description environments with a flat roof and dentiled cornice. The 489 Description environments with a flat roof and dentiled cornice. The 489 Description environments with a flat roof and dentiled cornice additions/alterations/moved 255 inclinations/moved 255 inclin	wide frieze board. The window surrounds on all window			
There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The  489 Test-1913 for eNtiron Meritaution and ges square wooden joinery with  47) Information sources  Historic Site Board File  48) Location of negatives Roll 547-9 #3-4 Roll 4 #10-12  48) Location of negatives Roll 547-9 #3-4 Roll 4 #10-12  49) Prepared by DDD  50) Organization  Missouri Heritage Trust  49 Information sources  24) changes additions/alterations/moved 25) condition 26) visible from road? 27) distancefrontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 34) is site eligible? 35) district potential? 36) date  49 Yes Jan. 27, 1984	openings have triangular shaped heads with applied			
There is a small porch at the center bay first story entrance with a flat roof and dentiled cornice. The  489 Test-1913 for eNtiron Meritaution and ges square wooden joinery with  47) Information sources  Historic Site Board File  48) Location of negatives Roll 547-9 #3-4 Roll 4 #10-12  48) Location of negatives Roll 547-9 #3-4 Roll 4 #10-12  49) Prepared by DDD  50) Organization  Missouri Heritage Trust  49 Information sources  24) changes additions/alterations/moved 25) condition 26) visible from road? 27) distancefrontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 34) is site eligible? 35) district potential? 36) date  49 Yes Jan. 27, 1984	moulding. The openings have two over two light sash.			
entrance with a flat roof and dentiled cornice. The  47) Information sources  Historic Site Board File  24) changes additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  48) Location of negatives  Roll 547-9 #3-4 Roll 4 #10-12  49) Prepared by DDD  50) Organization  Missouri Heritage Trust  If additional space is needed attached separate sheets  Missouri Heritage Trust  Application of negatives attached separate sheets  Application of negatives added attached separate sheets  Application of negatives added attached separate sheets  Application of negatives added attached separate sheets  Application of negatives added attached separate sheets  Application of negatives added attached separate sheets  Application of negatives added attached separate sheets  Application of negatives added attached separate sheets  Application of negatives added attached separate sheets  Application of negatives added attached separate sheets  Application of negatives added attached separate sheets  Application of negatives added attached separate sheets  Application of negatives added ad				
47) Information sources Historic Site Board File  48) Location of negatives Roll 4 #10-12  49) Prepared by DDD  48) Prepared by DDD  Missouri Heritage Trust  11 additional space is needed attached separate sheets  42) changes-additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district district 34) is site eligible? 33) name of historical district 34) is site eligible? 34) district potential? 36) date  47) Information sources  Rear wing either altered or added-gable drower later-steel sit added added-gable drower later-steel sit added added-gable drower later-steel sit added added-gable drower later-steel sit added add				
47) Information sources Historic Site Board File  24) changes additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  48) Location of negatives Roll 547-9 #3-4 Roll 4 #10-12  49) Prepared by ODD  50) Organization  Missouri Heritage Trust  16 additional space is needed attached separate sheets  24) changes additions/alter- ations/moved 25) condition 26 visible from road? 27) distance/frontage 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 34) is site eligible? 35) district 34) is site eligible? 36) date  24) Changes 48 additions/alter- ations/moved 25 condition 26 48 Added 39 preservation underway? No No No No No No No No No No No No No		22) site plan		9
Historic Site Board File  additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  Roll 547-9 #3-4 Roll 4 #10-12  49) Prepared by ODD  50) Organization  Missouri Heritage Trust  If additional space is needed attached separate sheets  Additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  Additions/alterations/moved 27) distance/frontage 400 deviner later-steel sid of the condition of the	46) Description of environment/outballoings quality is the second of the	25) Site plan		
Historic Site Board File  additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  Roll 547-9 #3-4 Roll 4 #10-12  49) Prepared by ODD  50) Organization  Missouri Heritage Trust  If additional space is needed attached separate sheets  Additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  Additions/alterations/moved 27) distance/frontage 400 deviner later-steel sid of the condition of the				
Historic Site Board File  additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  Roll 547-9 #3-4 Roll 4 #10-12  49) Prepared by ODD  50) Organization  Missouri Heritage Trust  If additional space is needed attached separate sheets  Additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  Additions/alterations/moved 27) distance/frontage 400 deviner later-steel sid of the condition of the				
Historic Site Board File  additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  Roll 547-9 #3-4 Roll 4 #10-12  49) Prepared by ODD  50) Organization  Missouri Heritage Trust  If additional space is needed attached separate sheets  Additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  Additions/alterations/moved 27) distance/frontage 400 deviner later-steel sid of the condition of the				
Historic Site Board File  additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  Roll 547-9 #3-4 Roll 4 #10-12  49) Prepared by ODD  50) Organization  Missouri Heritage Trust  If additional space is needed attached separate sheets  Additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  Additions/alterations/moved 27) distance/frontage 400 deviner later-steel sid of the condition of the				
Historic Site Board File  additions/alterations/moved 25 condition 26 visible from road? 27 distance/frontage 28 accessible? - 29 preservation underway? No 20 endangered? 31 on National Register? No 32) part of established historical district 31 name of historical district 34) is site eligible? 35 district potential? 36 date 4 name of historical 36 date 4 name of historical 36 date 4 name of historical 36 date 4 name of historical 36 date 4 name of historical 36 date 4 name of historical 36 date 4 name of historical 36 date 4 name of historical 37 date 37 1984	47) Information sources	24) changes -	D	5
## A substantial actions with the control of the co		additions/alter-		
25) condition 26) visible from road? 27) distance/frontage 28) accessible? - 29) preservation underway? 49) Prepared by DDD  50) Organization  Missouri Heritage Trust  If additional space is needed attached separate sheets  25) condition 26) visible from road? 27) distance/frontage 28) accessible? - 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 32) part of 48) Location of negatives 33) name of historical district 34) is site eligible? 35) district potential? 36) date  37) district potential? 38) district potential? 39  10  11  12  13  14  15  15  15  15  15  15  16  17  17  18  18  18  18  18  18  18  18	Historic Site Board File	ations/moved		ĺ
26) visible from road? 27) distance/frontage 28) accessible?				<del>d i</del> ng
27) distance/frontage 28) accessible? - ©  48) Location of negatives Roll 547-9 #3-4 29) preservation underway? 49) Prepared by DDD  50) Organization Missouri Heritage Trust  If additional space is needed attached separate sheets  130) endangered? No 30) endangered? No 31) on National Register? No 32) part of established historical district No 33) name of historical district 34) is site eligible? 35) district potential? Yes 36) date  27) distance/frontage - ©  29) preservation underway? No 30) endangered? No 30) endangered? No 31) on National Register? No 32) part of established historical district 32) part of established historical district 33) name of historical district 34) is site eligible? Yes 35) district potential? Yes 36) date		1= - '	Good added	$\dashv$
48) Location of negatives Roll 547-9 #3-4		· ·		-
48) Location of negatives Roll 547-9 #3-4 Roll 4 #10-12 Roll 4 #10-12 Roll 4 #10-12 Roll 4 #10-12 Roll 4 #10-12 Roll 4 #10-12 Register? Roll 4 #10-12			-	
Roll 547-9 #3-4 Roll 4 #10-12  49) Prepared by DDD  50) Organization  Missouri Heritage Trust  If additional space is needed attached separate sheets  No  Wissouri Heritage Trust  If additional space is needed attached separate sheets  No  No  No  No  No  Standard Missouri Heritage Trust  No  Stan			-	$\dashv_{\mathfrak{S}}$
49) Prepared by DDD  Missouri Heritage Trust  Missouri Heritage Trust  If additional space is needed attached separate sheets.  Missouri Heritage Trust  If additional space is needed attached separate sheets.  Wo  30) endangered?  No  32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  Jan. 27, 1984	48) Location of negatives Doll 547 0 42 4	1 ' '	No	
49) Prepared by DDD  50) Organization Missouri Heritage Trust  Missouri Heritage Trust  32) part of established historical district  33) name of historical district  34) is site eligible?  35) district potential?  36) date	ROTT 547-9 #3-4	underway?	HU	
50) Organization  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  32) part of established historical district  33) name of historical district  34) is site eligible? 35) district potential? Yes Yes Jan. 27, 1984	49) Prepared by 55	30) endangered?	No	
Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  Register? NO  NO  Ves Yes Jan. 27, 1984	DDD	31) on National		
Missouri Heritage Trust  32) part of established historical district  33) name of historical district 34) is site eligible? 35) district potential? 36) date  37. 1984	EO) Organization	1 '	No	<u></u>
established historical district  33) name of historical district  34) is site eligible? 35) district potential? 36) date  NO  NO	Missouri Heritage Trust	_	110	7
historical district  33) name of historical district  34) is site eligible?  35) district potential?  36) date  NO  Yes  Jan. 27, 1984		' '		
If additional space is needed attached separate sheets  33) name of historical district  34) is site eligible?  35) district potential?  36) date  37, 1984		1	No	
district  34) is site eligible? 35) district potential?  36) date  37. 1984				$\dashv$
34) is site eligible? 35) district potential? 36) date  37. 1984	If additional space is needed attached separate sheets	·	1	
35) district potential? Yes 36) date Jan. 27, 1984				$\dashv$
35) district potential? Yes 36) date Jan. 27, 1984		34) is site eligible?	Yes	$\perp$
36) date Jan. 27, 1984		35) district potential?	) [· · · · · · · · · · · · · · · · · · ·	30
37) revision		36) date	. ••	
		37) revision	VUII	

\_\_mall recessed panels at the base of these composite posts (see photo). The porch structure and floor are of wood.

There is a recessed entry with rope turned applied moulding at all outside and inside corners. The side walls have recessed panels. The entry itself is flanked by sidelights and has a transom above filled with modern stained glass work. There is a recessed wooden panel above the transom.


The rear wing may not be original though the foundation seems to be continuous and of the same finish on the stone work. The window openings have simple board head at the second story and the first story window and door heads have simple applied narrow moulding. The projecint eaves have modillions beneath on the rear wing. There are one over one light sash at window openings. The east elevation of the main house mass has the same window treatment (to confuse matters).

In the southwest corner angle created by the house mass and the rear wing is a small flat roofed porch filling part of the angle with a dentiled cornice and heavy turned posts supporting the roof. The porch floor and structure are of wood.

On the southeast angle created by the house mass and the rear wing is a long single pitch roofed porch filling the angle. A modern porch extending from the original obscures the details of the former.

At the rear of the property is a large outbuilding. Wood frame construction with a gabled roof plan and basic rectangle plan shape. It is two story with a centered roofcupola vent noto). There are four over four light sash in the second story with moulded window heads. The gable ends have shingled faces. The foundation is rough faced coursed ashlar limestone. The wooden horse stalls are intact on the interior with decorative iron bars at the windows in the stall and on the wooden partitions. At the rear is a one-story open area used formerly to house carriages.

CELECTIVE 21 97



Commented to the



Missouri Historic Architectural Inventory for Grand Gr

38) Ownership — private	X .	l l	nventory number	78	٥
— public	_	1	name (cont)		] -
39) Owners — name	James Frost	1 1	name - historial		
address	1300 E. Walnut	1	street address	1300 E. Walnut	
40) Local contact 41) Coordinates (U1	**A	1	town or vicinity legal description	Springfield	-
42) Quad	W! )	1	county	Ireg. Survey 34 Lot D	-
43) Other survey			category	Greene	<del> </del>
43) Other survey		1	(site, structure,		2/3)
		J	building, object)	Building	
44) History	Built 1921-1922 by Louis W. Reps,		significance	Architectural-Commerce	4
SecTreas. Rep		10)		1921-1922	1
, , , , , , , , , , , , , , , , , , ,		11) 9	style	Colonial Revival	1
		12) a	architect		7
		13) 1	builder		1
		14)	original use	Residence	
			present use	Residence	<u></u>
45) Additional description	of Five bay facade at both stories. Heavily	1 '	number of stories	2	4
moulded cornice	with projecing eaves with modillions	' '	plan shape	Rectangle	_
	rick of the facade is laid in Flemish	'	basement	Full	
, ,	t structural) with flat arch lintels at	1/	foundation	Concrete	
the window head	s. The sills appear to be smooth pre-	( '	wall construction	Brick over tile	_
cast concrete a	nd the <mark>openings have six over six light s</mark> a	a <b>∮11</b> ! '	root type -	Gable	4
There are worki	ng shutters at each window opening.	l '	material	asphalt shingle	5
The center bay	of the second story has a palladian window	V 22)	35mm		9
	ction opens onto a flat roofed portico	1	33111111		
	ay entrance on the first story. Wrought i	1			
	the portico above moulded and dentiled	1			
	ablature. Portico is supported by round place at the corners) of wood fluted with				
	if capitals. The entryway has a fan				1
	with sidelights sporting leaded glass fla	ankir	ים מים		
46) Description of environment	onment/outbuildings	23)	site plan		<u>o</u>
		1			
		}			
					ļ
			<del>,                                      </del>		(D
47) Information sources			changes		5)
	City Directory 1919-1933	- 1	additions/alter-	None visible	
			ations/moved condition		-
			visible from road?	Good	$\dashv$
			distance/frontage	-	$\dashv$
		( *	accessible?	-	6
48) Location of negative	S D 11 4 47 0 D-11 547 0 45 6		preservation		7
.5/ Lood Con Or Hogari Ve	s Roll 4 #7-9 Roll 547-9 #5-6	( '	underway?	No.	
49) Prepared by	DDD	30)	endangered?	No.	
,	טטט	31)	on National	110	
50) Organization	Missouri Heritage Trust		Register?	No.	
	mosouri nerroage mase	32)	part of		
			established	No	
		200	historical district	No	-
If additional space is nee	ded, attached separate sheets.	33)	name of historical		
		24)	district is site eligible?		-
		1	district potential?	Yes	30
		1	date	——————————————————————————————————————	નુ <sup>છ</sup>
		1 - 1	revision	Jan. 27, 1984	7
				T. Control of the Con	


1 1300 E. Walnut

the window openings at the first story have a recessed arched "niche" into which the window is placed.

On the east elevation in the gable end is a two-story flat roofed porch with a moulded cornice. There are doubled wood fluted pilasters separating the two bays and at the corners of the sun parlor with casement windows with multipaned sash in each bay opening. Below the window openings are recessed panels with centered rosettes of plaster (?). Below the second story is an open loggia or porch with tripled columns duplicating those found on the porticoed entry at the corners and doubled at intervals between the corners. Between the columns are arched moulded entablatures in each bay (photo).

On the west elevation there is an attached gable roofed garage with a single bay and a fan lighted transom above the garage door.

GO 4-003-673





## Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private X	1)	inventory number	65	=
— public	2)	name (cont)		
39) Owners — name Denton Smith	3)	name - historial		
— address 1303 E. Walnut		street address	1303 E. Walnut	
40) Local contact		town or vicinity	Springfield	
41) Coordinates (UTM)		legal description	Whitehead's Add. Lot 1	
42) Quad		county	Greene	
43) Other survey		category		2/3)
		(site, structure, building, object)		
44) History Ruilt 1010-1011 by Clifford Jarrett		significance	Building Architectural-Commerce	
batte 1910-1911, by official darrects	10)		1910-1911	
a paving contractor.		style	Rennaisance Revival	
		architect	Remarsance Revivar	
	13)	builder		
	14)	original use	Residence	
	15)	present use	Residence	
45) Additional description Wide projecting eave with dentiled	16)	number of stories	2	4
	17)	plan shape	Rectangle with wing	
	18)	basement	Full	
ashlar stonework. On all but the facade the window	19)	foundation	Rough,faced,coursed	
Surrounds are or wide smoothed rimestone with rimestone	/	wall construction	ashlar Limeston	e
lintels with carved keystones (see photo). The windows		roof type -	Smooth, faced, coursed,	
are six over six ligyt sash on the side and rear ele-	L	material	Hip ashlar Limeston	W
vations. Hipped dormers placed on the roof at various	22)	contact print	Red clay ceramic til	5) <sub>a</sub>
locations with casement windows with pilastered sur-	}	35mm	ner stag set ampe str	
rounds. The front facade is five bay with center bay	ļ			
entrance. At the second story all but the center bay				1
have double door openings with multi-paned lights giving	ļ			
onto small but functional stonework balconies with				
elaborate carved balustrades also of stone. The sur-				
rounds are smooth stone with a stonework lintel with  46) Description of environment/outbuildings	23)	site plan		9
	1	Site plan		
There is a large outbuilding one-story stone identical in				
detail to the main house except that the roof is press				
metal instead of being genuine clay tile. There are				İ
hipped dormers on the south east and west faces of the				
roof. There are two garage bays and a storage area in the 47) Information sources outbuilding. There is a swimming pool	24)	changes -		5)
and changing building adjacent built of stone which date		additions/alter-		
post 1933.		ations/moved	None visible	j
City Directory 1881-1933	25)	condition	Good	
Greene County Deed Record Book 282 page 134.	1	visible from road?	-	
puge 134.		distance/frontage		
		accessible?		6)
48) Location of negatives Roll 4 #42-44, 1 & 2, Roll 547-9 #7-8	29)	preservation		
	İ	underway?	No	Á
49) Prepared by DDD		endangered?	No	4
The state of the s	31)	on National	No	
50) Organization Missouri Heritage Trust	337	Register?	No	-[3]
	321	established		
		historical district	No	
If additional space is needed, attached separate sheets	33)	name of historical		1
in additional space is needed, attoened separate should	'	district	_	Ì
	34)	is site eligible?	Yes	
	35)	district potential?		30
	36)	date		
	37)	revision	Jan. 30, 1984	4
			l	1

keystone. The center bay has flanking fixed multi-paned light openings with surrounds like those described. Clearly these and the center bay give into a large entryhall and provide light. The center bay has a large fixed sash window of multi-panes with a carved stone arround in a Greek Key motif with flanking carved stone flourishes (see Photo). A belt course of smooth limestone separates the first from the second stories on the house. The first story copies the second except that the double doors give onto the open porch. Above the entry is an elliptical broken pediment done in stone work with heavy carved moulding and dentilpattern found under the gable pediment and at the cornice.


The pediment is supported by round stone columns with Tuscan capitals. A low open porch surrounds the front and east elevations of the house with a rough faced coursed ashlar foundation and red quarry tile floor. There are piers at intervals of rough stone with smooth limestone caps. The balustrade is of carved stone work with turned stone balusters. On the east elevation is a two story sun porch entry. The second story has a flat roof with a dentiled moulded, and coffered cornice. The corners are given over to square wooden pilasters between which are arched entablatures with wooden keystones, anddoubled window areas with multipaned sash.


Below the windows are recessed (?) panels between the engaged plinths to the above described pilasters.

The first story begins with a moulded and dentiled cornice supported by round stone columns with Tuscan capitals doubled at the corners. The porch doubles as a side entrance from a drive which comes in a straight line from the street.

On the rear elevation is a one-story open porch with a flat roof with square coffered columns and wide window areas.

the east and west property lines there are low stone walls of rough faced ashlar limestone with smooth coping stonework.








Missouri Historic Architectural Inventory for

Division of Parks and Historic Preservation Department of Natural Resources

	DIVISION OF PAIKS AND HISCORIC FRESERVACION DEPO		iciit oi natulai	n Nesources	
38) Ownership — private	•		inventory number	77	=
— public	-1		name (cont)		
39) Owners — name	Enla Mae Curtis	1 .	name - historial		ļ
— address	7.50 N. Jefferson	1 ′	street address	1314 E. Walnut	-
40) Local contact		1	town or vicinity	Springfield	1
41) Coordinates (UTI	<b>v</b> ),	1	legal description	Ireg. Survey 34 Lot E	┧
42) Quad			county	Greene	-
43) Other survey		8)	category		2/3)
			(site, structure,	Puilding	
		100	building, object) significance	Building Commons	-
44) History	Built ca. 1925 by George H. McCann, Pres	100	date	Contributing-Commerce ca. 1925 Social	1
New Phoenix Fou	ndry Co. (owned property back to at least		style	ca. 1925 Social Colonial Revival	1
	amily built along E. Walnut.)		architect	Colonial Revival	-
	<b>,</b> , , , , , , , , , , , , , , , , , ,	1 '	builder		-
			original use	Dosidonas	+
			present use	Residence Residence	1
AE\ Additional description		1	number of stories	1-1/2	4
45) Additional descriptio	Three bay facade - all window openings		plan shape		
but the center	bay on the shed dormer half story have	1	basement	Rectangle	-
six over six li	ght sash. The center has doubled window		foundation	Full	-
openings with n	arrow six over six light sash. At the		wall construction	Concrete Brick over tile	-
first story the	first and third bay have tripled window	1	roof type -		-
openings with e	ight over eight light sash in the center		material	Gambrel Asphalt	1
window opening	and six over six in the flanking open-	22	contact print		5
ings. There is	a small portico gable pediment over the		35mm		
center entrance	bay with continuous cornice and wide				
entablature. T	ripled square wooden columns support the				
	. The entry way has multi-paned side-				
	bled multi-paned ante-chamber door.				
	elevation is a large wing tucked into the				
gable and wh	ich echoes the facade of the main house				
46) Description of enviro	nment/outbuildings	23	) site plan		9)
			•		ŀ
		$\perp$			4
47) Information sources	City Directory 1890 - 1933.	24	) changes -		5)
	67 ty Birectory 1030 1333.		additions/alter-	None visible	
			ations/moved		4
			) condition	Good	4
		1 -	) visible from road?	-	4
		-	) distance/frontage		-6
			) accessible?		<u> </u>
48) Location of negative	<sup>5</sup> Roll 547-9 #9-10	129	) preservation underway?	NI -	
		20	) endangered?	No	_
49) Prepared by	DDD		) on National	No	$\dashv$
<b>50.0</b> ( ):		31	Register?	No	
50) Organization	Missouri Heritage Trust	32	Register:	No	-2
	-	32	established		
			historical district	No	
If additional chack in page	ded atrached separate sheets	33	3) name of historica	110	7
n additional space is need	ned, ambanica superiore ambata	-	district	_	
		34	is site eligible?	Yes	$\neg$
		35	b) district potential?		
		36	6) date	Jan. 30, 1984	
		3	7) revision		






## Missouri Historic Architectural Inventory for GRADING CONTROL FOR Division of Parks and Historic Preservation Department of Natural Resources

1) inventory number 38) Ownership - private 76 \_ - public 2) name (cont) 39) Owners - name Bishop of Springfield C G Diocese 3) name - historial 1714 E. Meadowmere 1320 E. Walnut 4) street address -- address 5) town or vicinity 40) Local contact Springfield 6) legal description Ireg. Survey 34 Lot F 41) Coordinates (UTM 42) Quad 7) county Greene 8) category 43) Other survey 2/3 (site, structure, building, object) Building 9) significance 44) History Architectural-Contributing Built 1926-1927 by Dr. Eugene Roseberry, 10) date 1926-1927 Physician 11) style Bungaloid 12) architect 13) builder 14) original use Residence 15) present use Multi-occupancy /office 16) number of stories 45) Additional description Gabled dormer on the front elevation 17) plan shape with a pendant hanging from the apex of the verge board. Square 18) basement The face of the gable is half-timber and stucco. The Full. 19) foundation plates project at the corners of the gable. The rafter Concrete 20) wall construction Brick Veneer ends are exposed along the roof eaves on the dormer. 21) roof type -Gable Asphalt There are tripled window openings in the dormer with six material over one light sash. There are copper gutters at the 22) contact print 5 roof eaves of the house mass. The eaves are overhanging 35mm and have exposed rafter ends. The house is three bay. At the second story there are doubled windows at the first and third bays wity concrete lintels and sills in imitation of stone, and six over one window light sash. The center bay has small tripled window openings. At the first story there are four windows grouped together with a continuous banded concrete surround 9 46) Description of environment/outbuildings 23) site plan Behind the house is a one-story outbuilding used as a garage and storage. 24) changes -47) Information sources additions/alter-City Directory 1925-1933 Part of porch filled in ations/moved 25) condition Good 26) visible from road? 27) distance/frontage 6 28) accessible? 48) Location of negatives 29) preservation Roll 4 #4 underway? No Roll 547-9 #11-12 30) endangered? 49) Prepared by No 31) on National DDD Register? Missouri Heritage Trust 50) Organization No 32) part of established historical district No 33) name of historical If additional space is needed, attached separate sheets district 34) is site eligible? Yes 35) district potential? Yes 36) date Jan. 30, 1984 37) revision

noto). Across the front elevation is a porch which is open on the east and covered over the entry area and around to the west elevation. The open porch has a brick parapet and foundation with concrete floor and brick piers at intervals. There is a pre-cast concrete balustrade with square handrail and balusters. The piers are topped with pre-cast concrete caps.

The porch has a hipped roof except over the entry where there is a gable pediment which projects slightly from the rest of the porch roof and cornice. The face of the pediment is half-timbered and stuccoed. There is a pendant at the apex of the vergeboard. The roof plates project from the gable corners supporting the projecting eaves of the porch gable. The supports of the porch entrance gable are basically square though splayed brick columns (photo). The porch has been filled recently with brick walls though keeping the outline of the original porch. The gable ends of the house are stucco and half-timbered with large supporting brackets at wide projecting gable eaves. There is a pendant at the apex of the verge board.

CR. As no sell to






Missouri Historic Architectural Inventory for

Division of Parks and Historic Preservation Department of Natural Resources

1) inventory number 75 38) Ownership — private x - public 2) name (cont) 39) Owners - name 3) name - historial Boatman's Union Nat. Bank B.A. Hoover 4) street address - address Trust 1330 E. Walnut Box 1157 40) Local contact 5) town or vicinity <u>Springfield</u> 6) legal description 41) Coordinates (UTM) Ireq. Survey 34 Lot G 7) county 42) Quad Greene 43) Other survey 8) category (site, structure, Building building, object) 9) significance 44) History Contributing-Commerce-Built 1909-1910 by George McCann, 10) date Social 1909-1910 Secy. Treas. - New Phoenix Foundry 11) style Foursquare Catalogue & Machine Co. 12) architect Builder 13) builder 14) original use Residence 15) present use Residence 16) number of stories 4) 45) Additional description 2 Hipped dormers on all faces of the roof 17) plan shape Square except the south elevation. Wide projecting with 18) basement Full narrow cornice. Three bay facade with off center en-19) foundation Concrete trance. The window openings have simple narrow applied 20) wall construction Frame/Lap siding moulding to the window heads and have one over one win-21) roof type -Bell cast hip asphalt dow light sash. One story porch with hipped roof. Very material shinale simple moulded cornice and entablature supported by round22) contact print 5 wooden columns with Tuscan capitals. A wooden balustrade 35mm surrounds the porch with moulded handrail and turned balusters. The porch floor, steps, and structure are of wood. 9 23) site plan 46) Description of environment/outbuildings Behind the house is a one-story hipped roof frame garage of one bay. 24) changes -47) Information sources additions/alter-City Directory 1908-1933 ations/moved None visible 25) condition Good 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation 48) Location of negatives Roll 4 #5 underway? No 30) endangered? 49) Prepared by No DDD 31) on National Register? 50) Organization No Missouri Heritage Trust 32) part of established No historical district 33) name of historical If additional space is needed, attached separate sheets district 34) is site eligible? Yes 35) district potential? Yes 36) date Jan. 27, 1984 37) revision



COASTON 1000



Missouri Historic Architectural Inventory for Company Company Company Division of Parks and Historic Preservation Department of Natural Resources

	Division of Parks and Historic Preservation Def	Jaitii	ieni vi Matura	Resources	
38) Ownership — priva	•		inventory number	66	5
— publ			name (cont)		_
39) Owners — name — address	Howard Reed		name - historial		4
40) Local contact	1333 E. Walnut		street address town or vicinity	1333 E. Walnut	-
41) Coordinates (	!TM		legal description	<u>Springfield</u>	4
42) Quad	2114.		county	Whitehead's Add. Lots	-
43) Other survey			category	Greene 5-6	
, , , , , , , , , , , , , , , , , , ,		"	(site, structure,		2/3)
			building, object)	Building	
44) History		9)	significance	Architectural-Commerce	-
Build 1912	by Charles H. Dalrymple, owner of		date	1912	4
Dalrymple	Drug Store. Widow living in house	11)	style	Catalogue/Builder with	7
1933.	- sy cook of myself in the use	12)	architect	<u>Classical detai</u>	
		13)	builder	0.430 1041 40041	
		14)	original use	Residence	7
		15)	present use	Residence	7
45) Additional descrip	Hipped dormers on the south east and	16)	number of stories	2	4
west elevation	ns with butt shingled walls and face. The		plan shape	Square	
	nas tripled windows with latticed muntin	18)	basement	Full	
	sash over one light sash. Very broad pro-	1 .	foundation	Smooth, faced, coursed	
	on the house (and the dormers). Five bay		wall construction	ashlar Cast S	$\overline{t}$ on $\epsilon$
	ne over one light window sash. The walls	21)	roof type -	Cast Stone coursed,ash	]]ar
	shlar smooth faced cast stone. Larger	001	material	Hip smoth, faced	<del></del> -
	ed as lintels at the window surrounds. At	[22)	contact print	Red Clay Ceramic Tile	5
	f the house rough faced cast stone work is		35mm		
	S. A one story porch with hipped roof				
	s the facade and wraps around the west				
	to become a porte cochere. The porch roof				
	vered with red clay tile. The porch is				
	rough faced ashlar square cast stone pilla	r\$			
46) Description of envi	ronment/outbuildings	23)	site plan		9
•			•		
47) Information source	SS S	24)	changes -		5)
	City Directory 1911-1933.		additions/alter-	Part of porch on east	
		-	ations/moved	elevation filled in	_
		1	condition	Good	
			visible from road?	_	_
		1	distance/frontage		4_
			accessible?	-	၂၅
48) Location of negative	<sup>res</sup> Roll 547-9 #15-16	[29]	preservation		
40) B		30	underway?	No No	4
49) Prepared by	DDD	!	endangered?	-	4
50) 0		31	on National Register?	-	
50) Organization	Missouri Historical Trust	32	) part of		73
		32	established	_	
			historical district		
If additional space is no	eded_attached_separate_sheets	33	) name of historical		-
n auditional space is he	edeo attached separate sheets		district		
		34	) is site eligible?	V	$\dashv$
			) district potential?	Yes Yes	30
			) date	Jan. 30, 1983	75
		37	) revision	Uaii. 30, 1303	1


with smoothed cast stone capitals and with a rough faced cast stone parapet wall also with smooth faced cast stone coping.

There is a pediment gable above the entryway area on the porch roof with continuous cornice. The pediment area is covered with a plaster work decoration. There are scrolled brackets beneath the cornice under the corners of the pedimented gable (photo).

The doorway is flanked by small window openings or sidelights.

On the east elevation there is a sun parlor filled in at the southeast corner of the house. Also there is a flat roofed porch area filled in at the same time to make a large room of the addition.

( D NO - NO 10 4 8




120 33 33 33 68



## Missouri Historic Architectural Inventory for GR 4 - CO GR

38) Ownership — private	*	1)	inventory number	74	]=
— public	•	2)	name (cont)		
39) Owners — name	Jacqueline Harmon	3)	name - historial		1
— address	1336 E. Walnut	4)	street address	1336 E. Walnut	
40) Local contact		5)	town or vicinity	Springfield	
41) Coordinates (UT	<b>(♥</b> )	6)	legal description	Chamberlain's Add. Lot	:
42) Quad		7)	county	Greene	
43) Other survey		8)	category	- ar eche	2/3)
			(site, structure,		199
			building, object)	Building	
44) History			significance	Contributing	
	Build 1926-1927 by Charles C. Skeels.	1 '	<b>da</b> te	1926-1927	
		11)	style	Cottage Revival	_
			architect		_
		1 '	builder		_
		1	original use	Residence	_
			present use	Residence	-
45) Additional description	In theconton of the front feeded is a	1	number of stories	1-1/2	4
ned brick chims	In thecenter of the front facade is a	ì	plan shape	Square	4
	ney engaged to the wall which rises to the of. The entire facade is the gable of the		basement	Full	_}
	roof line. The eaves are flush in the		foundation	Concrete	_
. •	ndow openings have casement sash with	1 '	wall construction		_
	both stories. The entrance is to the right		roof type	High gable	_
•	with a separate narrow gabled entry wing		material	asphalt shingle	(T)
	feet or so depth. There is an arched	[22)	contact print	,	5)
	e doors in the entry. There are gabled		35mm		
	ner of the east-west roof faces with				
	openings. There is a one-story sun parlo				
	evation with a continuous roof line. There				
	indow areas with casement windows with	=			
	sash. On the facade is an exterior en-				
trance with arc	thed opening and doubled doors with multi-	221	aita alaa		وو
46) Description of envir	paned lights.	(23)	site plan		-
	p 3				
		241	changes -		5
47) Information sources	City Directory 1919-1933	24)	additions/alter		
	City directory 1919-1933		ations/moved	_	
		25)	condition	None visible	-
		/	visible from road?	Good	$\dashv$
		,	distance/frontage		$\dashv$
		1 .	accessible?		6
	D.11 E47 D #17 10		preservation	*	$\dashv$
48) Location of negative	es Roll 547-9 #17-18	23,	underway?		
40) 5	DOD	30)	endangered?	No.	-
49) Prepared by	DDD	1	on National	No.	-
	Minaguni Hamitago Trust	31,	Register?	\ ,	
50) Organization	Missouri Heritage Trust	321	part of	No.	- 2
		02,	established	No	
			historical district		
(f and district a second second	and attached cenerate sheets	331	name of historical		$\dashv$
it additional space is nee	eded, attached separate sheets.		district	_	
*** <u>*</u>		34	) is site eligible?	Yes	$\neg$
		1 '	) district potential?		30)
			) date	Jan. 27, 1984	7=
		1	) revision		7
					$\neg$



51

GP - Alexander 1996



Missouri Historic Architectural Inventory for G ( )

Division of Parks and Historic Preservation Department of Natural Resources

	- 122.00 m / 128.00 m	T			
38) Ownership — privat	•		inventory number	67	E
— public		ı	name (cont)		
39) Owners — name	Harold Richardson		name - historial		
— address	1351 E. Walnut	1	street address	1351 E. Walnut	
40) Local contact			town or vicinity	Springfield	
41) Coordinates (U	<b>"M</b> :		legal description	Whitehead's Add. Lot 8	1
42) Quad			county	Greene	<u> </u>
43) Other survey		8)	category		2/3)
			(site, structure,		٥
			building, object)	Building	
44) History			significance		1
			date	ca. 1915	
			style	Catalogue/Builder	
		1	architect		
		13)	builder		
		14)	original use	Residence	
		1	present use	Residence	
45) Additional descript	<sup>on</sup> Partial hipped porch roof may be origina	16)	number of stories	1	4
but the pects	have been replaced with wassabt then work		plan shape	Square	
	have been replaced with wrought iron work.	18)	basement	Full	1
	ight window sash. There is a pent roof	19)	foundation	Unknown	1
	etting off a pediment with a simple attic	20)	wall construction	Frame/plywood covering	ī
	ith louvers. On the east elevation is a	21)	roof type -	Hip asphalt shingle	í
modern garage	with shed roof added recently.		material		1
		22)	contact print		5)
			35mm		
					İ
,					
46) Description of envi	an an antiquithuildings	231	site plan		9
46) Description of envi	onment/outpariamigs	20,	site plan		
47\  -4		241	changes -	Plywood covers walls-	<u>5</u>
47) Information source		124)	additions/alter-		
	City Directory 1919-1933	į	ations/moved	porch posts removed	
		125	) condition	garage added on east el	_
				Good	4
		1 .	<ul><li>visible from road?</li><li>distance/frontage</li></ul>	-	-
				-	<del>-</del>
			accessible?		6
48) Location of negative	es Roll 547-10 #1-2	29	) preservation	No	
		120	underway?		4
49) Prepared by	DDD	- 1	endangered?	No	_
		31	on National		
50) Organization	Missouri Heritage Trust		Register?	No	72
	-	32	) part of		
		İ	established		
			historical district	No	4
If additional space is ne	eded, attached separate sheets	33	) name of historical		
~			district		4
)	·	- 1	) is site eligible?	<u>No</u>	105
			) district potential?		30)
		ì	) date	Jan. 27, 1984	4
		37	) revision		_


1131611



Missouri Historic Architectural Inventory for

Division of Parks and Historic Preservation Department of Natural Resources

	Division of Parks and Historic Preservation Depa	rtn	nent of Natura	Resources	
38) Ownership — private	*	1)	inventory number	68	Ξ
— public		2)	name (cont)		]
39) Owners — name	Helen Smith	'	name - historial		
— address	1363 E. Walnut	1 .	street address	<u> 1363 E. Walnut</u>	
40) Local contact	145		town or vicinity	Springfield	
41) Coordinates (UT	M)		legal description	Whitehead's Add. Lots	4
42) Quad 43) Other survey		1	county	Greene 9-10	
43) Other survey		0)	(site, structure,		2/3)
			building, object)		
44) History	House build ca. 1890-1900 and then moved	9)	significance	Contributing	1
	al location on NE corner Kickapoo &		date	ca. 1890-1900	1
Walnut St. in 1	910 to its present location by Percy	11)	style	Italinate	1
	r of First Ward Grocery. He lived there	12)	architect	1 ca i i ii a c	1
at least throug		13)	builder		1
J		14)	original use	Residence	
		15)	present use	Residence	
45) Additional description	Notably tall window openings with applied	16)	number of stories	2	4
moulding at the	window heads with one over one light			Irregular	
	ndow opening. There is a one-story flat	1	basement	Partial	
	n which extends across most of the front		foundation	Rough,faced,coursed	
	ontinues around on the west side. Very	1 .	wall construction	Frame/ ashlar Limesto	ne
simple moulded	cornice and entablature supported by round	1	roof type - material	Frame/vinyl siding	4
wooden columns	with Tuscan capitals. The porch floor and	221	contact print	_ <u>H1P</u>	5)
structure are w	ood. There is a two-story gabled addition	22,	35mm	Asphalt	2
	angle created by the house mass and an		3311111		
-	n the rear elevation. On one face of the				
	small gabled dormer. Below it on the wa	1			
	square by with applied moulding to the				
	The owner stated that the house had				
	rom the lot occupied by 1303 E. Walnut.				
46) Description of enviro	nment/outbuildings	23)	site plan		9
					İ
47) Information sources		24)	changes -		(D
47) Information Sources	0wner	24)	additions/alter-	House moved from NE co	rne
	City Directory 1909-1933	İ	ations/moved	Kickapoo & Walnut-viny	1
		25)	condition	siding-wing on rear ad	ded
		26)	visible from road?	Good	-
		27)	distance/frontage		7
		28)	accessible?		6)
48) Location of negative	D 17 4 44	29)	preservation		7
	Roll 4 #4		underway?	No.	ļ
49) Prepared by	Roll 547-10 #3-4	30	endangered?	No	
DDD	Missouri Hamitago Truct	31	on National		
50) Organization	Missouri Heritage Trust		Register?	No	77
		32	) part of		
			established		
the data and	(id asked against charte	22	historical district name of historical	No	+
it additional space is need	led. attached separate sheets	33	district		
		34	) is site eligible?	Voc	$\dashv$
		1	) district potential?	Yes Yes	30
			) date	Jan. 30, 1984	۳
		37	) revision	0411. 30, 1304	7



NA


(D. C. CO)



Missouri Historic Architectural Inventory for Communication of Parks and Historic Preservation Department of Natural Resources

_	JIVISIUII UI PAIKS AIIU MISTUME PTESEIVATION DEPA		iciit oi itataia		
38) Ownership — private	X .		inventory number	73	=
public			name (cont)		-
39) Owners — name	W. E. Lemery		name - historial		
— address	1430 E. Walnut		street address town or vicinity	1430 E. Walnut	Ì
40) Local contact			legal description	Springfield	
41) Coordinates (UTA	A ;		county	Irreg. Survey 33 Lot	}
42) Quad 43) Other survey			category	Greene	N
43) Other Survey		0,	(site, structure,		2/3)
		Ì	building, object)	Building	-
44) History		9)	significance	Commerce	1
44) Instory	Ruil+ 1021 1022 by lames A MacDonell	1	date	Contributing Commerce	1
	Built 1921-1922 by James A. MacDonell, Supt. Springfield Table Mfg. Co.	11)	style	Bungalow	1
	Super Springife a labre mg. co.	12)	architect	54.754.701	1
		13)	builder		]
		14)	original use	Residence	
		1	present use	Residence	
45) Additional description	Three bay facade with a hipped dormer on	1 1	number of stories	1-1/2	4-
the facade roof	face with exposed rafter ends and lap	i	plan shape	Rectangle	
	ndow opening has one over one light sash.	1	basement	Full	4
There is a contr	inuous roof line over the porch with over-	19)	foundation	Concade	
hanging roof ear	ves and exposed rafter ends. The porch			Frame/lap siding	4
	e wooden and taper upward resting on red	21)	roof type	Gable	4
•	There is a full porch balustrade with	00	material	asphalt shingle	5
•	and square wooden balusters. The porch	22)	contact print 35mm		9
	ture are of wood. The steps leading to		30mm		
	oncrete with flanking walls of red brick.				
	the facade are one over one light sash				
	alding to the window heads which also is				
	ne door way. The galbes have wide pro-				
jecting eaves	s with four simple knee braces under the				1
46) Description of environment	nment/outbuildings	23	) site plan		9
,					1
	ge of wood with a jerkinhead on the front	Ì			
	with a two bay facade. The location and				
	respond with that found on the Sanborn				
	f 1933 though the present building cannot				
be much later. 47) Information sources	0 00 1000	24	) changes -		5)
	City Directory 1919-1933		additions/alter-	None visible	į
		1	ations/moved	None visible	-
		1	) condition	Good	4
		1	) visible from road?		-
		- 1	') distance/frontage		6)
			3) accessible?	-	<b>⊣</b> =
48) Location of negative	Ro11 4 #23	29	) preservation underway?		
	Roll 547-10 #13-14	30	)) endangered?	No	$\dashv$
49) Prepared by DD		1	) on National	No No	$\dashv$
		3,	Register?	N -	<u> </u>
50) Organization	Missouri Heritage Trust	32	2) part of	No	72
			established		
			historical district	No.	
If additional snace is need	ed attached separate sheets	33	3) name of historica		
in additional space is need	*** **********************************		district		
(		34	4) is site eligible?	Yes	
		3	<ol><li>district potential</li></ol>		30)
			6) date	Jan. 30, 1984	Ц
		3	7) revision		_

5







Missouri Historic Architectural Inventory for Galactic Control

301 0	X - X	T 2:			
38) Ownership — private	•	1	inventory number	69	]=
— public 39) Owners — name	C N	1 '	name (cont) name - historial		_
— address	Guy Mace	1	street address	1435 E. Walnut	_
40) Local contact	1435 E. Walnut	1 .	town or vicinity		4
41) Coordinates (UT	Mi		legal description	Springfield	_
42) Quad	v.;		county	Ireg. Survey 31-B	
43) Other survey			category	Greene	-
43) Other survey	City of Springfield Historic Site	0)	(site, structure,		2/3)
	3		building, object)	Duilding	
44) History		0)	significance	Building	_
44) History	George Sease bought land in 1886 and	1	date	Architectural - Commerce	
is listed in Ci	ty Directory of 1890-91 on property.		style	Ca. 1886-1890 Socia	<u> </u>
George Sease wa			architect	Queen Anne	4
J		1 '	builder	George Sease?	_
		1 .		D	4
			original use	Residence	
AE \ Addis.			present use	Residence	4
45) Additional descriptio	Front elevation - the apex of the verge	1 .	number of stories	2	4
board in the fr	ont gable wing has a raised "M" exe-	1 '	plan shape	Irregular	_
	dings. The apex of the gable pediment is	1 '	basement	Full	
	acts as the head to the window opening	1 '	foundation	Rough, faced, coursed	
	e are doubled window openings with single		wall construction	Frame/ ashlar Limestone	9
	e face of the pediment is covered with	(21)	roof type	Steel siding?	
	w the windows is a narrow moulded cornice	200	material	Multi-gable asphalt	
	a narrow band of coffering used as a	22)	contact print	shingle	5
	ojecting gable wing on the right and the		35mm		
	create an L shape to the street. In the				
	cond story level is a shed roofed porch	İ			
	ce. On the open side of the porch roof				
	racket with a pendant. Around the porch				
	ade with simple wooden balusters. At the				
southwest corne	r of the house is an eight sided tower	<u> </u>			
46) Description of enviro	iment outbuildings	23)	site plan		9)
47) Information sources	Historic Site Board File	24)	changes -		5)
	"The Sease House" Caryn Johnson &		additions/alter-		
		1	ations/moved	steel siding added	
	Frank Baugh 1981		) condition	go0d	_i
		1 '	) visible from road?	500	_
		1	) distance/frontage	_	
			accessible?		
48) Location of negatives	Roll 4 #18-22	29	) preservation		
	Roll 547-10 #11-12		underway?	Yes	
49) Prepared by DDD			endangered?	No	
		31	) on National		
50) Organization	Missouri Heritage Trust		Register?	No.	
		32	) part of		7~
			established		
			historical district	No	
If additional space is need	ed attached separate sheets	33	) name of historical		
			district	_	
/		34	) is site eligible?	Yes	
		35	) district potential?	Yes	30
		- 1	) date	Jan. 30, 1984	
		37	) revision	WALL MAN LINE	
				1.0 1/4	

ich rises a full story above the roof eave level with an eight sided asphalt shingled roof.

The roof eaves project with a heavily moulded cornice beneath. There are window openings on the third story on six faces with double hung window sash with upper sash composed of multipaned stained glass surrounding a center pane of clear glass. There is a pent roof at the separation of third and second story on the tower still above the eave line of the house. Under the eave is a dentiled cornice and coffered frieze. The six window openings have one over one light sash. The first story level of the corner tower also has six window openings with eight paned transom above one over one light sash.

Above the entry is an eight light sash transom as well. There is a one-story hipped roof porch around the entire front elevation extending around partially on the east elevation and continuing around the tower on the west with angled roof line and porch outline matching the facets of the tower itself. Over the entry area on the facade is a pedimented gable with a slightly projecting continuous cornice in the pediment. The face of the pediment has a carved wooden inset. The cornice is moulded with a turned spindle entablature beheath. Each of the turned wooden porch posts has scrolled braces beneath the entablature. The wooden balustrade has arcaded jigsaw cut out panels. The porch floor and porch structure are of wood. East elevation – at the apex of the vergeboard is a panel with a sunburst design in the gabled wing. In the apex of the pediment in the gable is an area treated with vertical boards applied used as a decorative motif. This acts as window head to the gable window openings. The face of the gable is covered with fish scale shingles. The frieze board below the narrow moulded cornice is composed of narrow vertical boards applied to the frieze board to create a motif like that in the gable apex.


There is an angle created by the east wing and the front projecting wing. In the angle is a first two story porch with a shed roof. The entablature under the porch eaves has a round jigsaw cut out design. The porch posts and balustrade match that found below on the first story porch.

West elevation - the west projecting wing has a sunflower motif carved into the vergeboard panel otherwise the pediment is identical to the east gable wing. Beneath the cornice the corners of the gable wing are chamfered with brackets on either face under the corner of the gable eaves. There are window openings in the three faces of the gable wing. The verticle applied board motif is used as a band to separate the first from the second stories on the gable wing.

There are stained glass fixed sash in windows positioned at what are probably the landings in a stair hall on the west elevation. At the rear of the house is a two-story portion which has a gabled continuous roof line with the main house though it apparently was once at least partially open on the first and second stories and used as porch areas. In the northwest corner large bays are framed in wood with arched entablatures and engaged wooden balustrades (photo).

At the street there are two tapering concrete columns which were used as hitching posts with iron rings set into the top.

GR. 2 10 - 6683



NA


Co 25 2800 1

SEASE HOUSE FLOOR PLAN 1/8° - 1'

61 -7

-






SEASE HOUSE 2 No. FLOOR I/8"-I'





Missouri Historic Architectural Inventory for GR Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	× .	1)	inventory number	72	]=
— public		2)	name (cont)		
39) Owners — name	C. M. Nenno	3)	name - historial		7
- address	1440 E. Walnut	4)	street address	1440 E. Walnut	7
<ul> <li>40) Local contact</li> </ul>		5)	town or vicinity	Springfield	٦
41) Coordinates (UT	M)	6)	legal description	Ireg. Survey 33 Lot E	3
42) Quad		7)	county	Greene	7
43) Other survey	one given supposed the supposed to the suppose	8)	category		2/3)
			(site, structure,		$ \omega $
			building, object)	Building	
44) History	5 13 300 300 5	9)	significance	Contributing-Social	7
	Built 1921-1922 by Fred H. McCann while	10)	date	1921-1922	7
	an for Standard Motor Co. Four years	11)	style	Bungalow	7
	lvanced to Dept. Mgr. and built 1460	12)	architect		
E. Walnut.		13)	builder		7
		14)	original use	Residence	
		15)	present use	Residence	7
45) Additional description	n _	16)	number of stories	1-1/2	4
	West elevation - simple knee braces unde	<b>†</b> 17)	plan shape	Rectangle	7
	. All windows have vertical muntins in	18)	basement	Full	7
the upper sash.	There is applied moulding on all win-	19)	foundation	Concrete	
dow heads. On	the front elevation is a gabled dormer	20)	wall construction	Frame/lap siding	1
with exposed ra	fter ends on the eaves with knee braces.	21)	roof type -	Gable	_
Dormer windows	appear to be modern replacements. The		material	asphalt shingle	-
roof line of th	e house is continuous over the porch. Th	(22)	contact print		5
rafter ends are	exposed. Supporting the porch are		35mm		1
square wooden t	apering columns resting on brick pillars.	1			
There is a wood	en parapet on the porch covered with lap	[			
siding. The fa	cade is three bay.				
(					
46) Description of enviro	nment/outbuildings	23)	site plan		9
		-			
					!
Behind the hous	e is a one-story gable entrance single ba	y			1
garage.					
					1
47) Information sources		24	changes -	doman windows alter-	5
			additions/alter-	dormer windows altere	a.
	Caty Directory 1920-1933	1	ations moved	Porch screened in	!
		25	) condition	Good	
		26	visible from road?	-	
		27	) distance/frontage	-	
		28	accessible?	-	6)
48) Location of negative	s Roll 4 #24	29	) preservation		
	Roll 547-10 #15-16		underway?	No	_
49) Prepared by DDD	ROTT 347-10 #13-16	30	endangered?	No	
טטט		31	) on National		
50) Organization	Missouri Haritago Trust		Register?	No	7
	Missouri Heritage Trust	32	) part of		
			established		
			historical district	No	
If additional space is need	ded. attached separate sheets	33	) name of historical		į
, <del></del>			district	-	_
			) is site eligible?	V	
		- 1	) district potential?	Yes	30)
		- 1	) date	Jan. 30, 1984	_
		37	) revision	Julii 50, 1504	-





Missouri Historic Architectural Inventory for GRANGE CONTROL C

29) Ourseship private Y	1\ inventor	70	
38) Ownership — private X	1) inventory number	70	<b>↓</b> =
— public	2) name (cont)		]
39) Owners—name Gladys Ray	3) name - historial		
address 1442 E. Cairo	4) street address	1451 E. Walnut	1
40) Local contact	5) town or vicinity	Springfield	1
─ 41) Coordinates (UTM)	6) legal description	Pickwick Terrace, Bloc	1
42) Quad	7) county	Greene 7 Lot 2	1
43) Other survey	8) category	dreene 7 Luc 2	+
43) Other survey	(site, structure,		2/3)
		D .3.1.	
	building, object)	Building	4
44) History	9) significance	Contributing	_
	10) date	ca. 1915	_]
	11) style	Bungalow	
	12) architect		
	13) builder		7
	14) original use	Residence	7
	15) present use	Residence	7
45) Additional description	16) number of stories	1-1/2	4
	17) plan shape	Rectangle	- `
centered shed roofed dormer covered with steel siding	18) basement		4
	,	Full	4
on the wall surfaces and face. The rafter ends are ex-	19) foundation	Rough, faced, coursed	
posed under the dormer eaves. There is a tripled win-	20) wall construction	Frame/ ashlar Cast S	tone
The specific state of the state	21) roof type -	Lap Siding	
The facade is two bay with the entrance on the left.	material	Gable Asphalt shingle	
	22) contact print	dante Aspilate Sittigle	5)
ginal sidelights removed. The door head extended over	35mm		
entry and sidelights and is still in place with simple			-
applied moulding. On the right is a tripled window open-			
ing with eight over one light sash. Under the over-			
hanging eaves of the main house mass the frieze is mad			
up of two courses of butt shingles with a thin applied			}
moulding above a second frieze area consisting of a narro			1
46) Description of environment/outbuildings	23) site plan		9
	*	•	
The garage appears to be a modern addition though the	•		1
1933 sanborn indicates its presence.			
			1
47) Information sources	24) changes -		5
47) Inditination sources	additions/alter-		
	ations/moved	Entire porch removed	
			-
	25) condition	Good	_
	26) visible from road?		4
	27) distance/frontage	_	
	28) accessible?		
48) Location of negatives Roll 547-10 #17-18	29) preservation		
1.3.1 017 10 117 10	underway?	No	
49) Prepared by DDD	30) endangered?	No	$\neg$
υυυ υυυ	31) on National	HO	7
EO) Organization Missaura Harabbara Traval	Register?	No	
50) Organization Missouri Heritage Trust	32) part of	No	-[7]
	1 '		
	established		
	historical district		_
If additional space is needed, attached separate sheets.	33) name of historica	<sup>1</sup> [	
		1	
	district		_
	district 34) is site eligible?	Yes	
			30
	34) is site eligible?	Yes	30)
	34) is site eligible? 35) district potential?		30)

ulard. The entire porch shown in the 1933 Sanborn is missing. On the east elevation in the gable is an oriel window with a shed roof and exposed rafter ends. The window has twelve over one light sash. The gable face is covered with butt shingles, with a tripled window opening with applied moulding to the window head.

 $\alpha_{p_0}$ 

and the second of the second o 


N



Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private					
- b.10	χ ,	1)	inventory number	71	]=
public		2)	name (cont)		7
39) Owners — name	Herschel Chudemelha	3)	name - historial		
address	Rt. 2, Box 48 Ozark, MO.	4)	street address	1460 E. Walnut	٦
\40) Local contact	(Kar 2, par 10 - 025) Ky 110	5)	town or vicinity	Springfield	7
41) Coordinates (UTM	1)	6)	legal description	Ireg. Survey 33, Lot	Ē
42) Quad		7)	county	Greene	7
43) Other survey		8)	category	di cene	N
.,		1	(site, structure,		2/3)
		}	building, object)	Building	}
44) History		9)	significance	Contributing-Social	-
++/ Thotory	Built 1925-1926 Fred H. McCann. Dept.	1	date	1925-1926	1
	Manager, Standard Motor Co.	11)	style	Bungalow	
		1	architect	bunga row	-
			builder		-
		1	original use	Danidana	-
		1	present use	Residence	-
AC) Additional Jacobias		1	number of stories	Residence	4
45) Additional description	The porch dominated the facade with its	1	plan shape	Do atomo?	<b>ا</b> ٔ
gabled face to	the street. The surface of the pediment	1	basement	Rectangle	4
	with stucco. In the center of the	1 '	foundation	<u>Full</u>	_
	ixed sash window with corner muntin sash.	/	wall construction	Concrete	4
	ings have upper sash fitting the above	1		Stucco over Frame	_
	h applied moulding at the window heads.	21)	roof type -	Gable	4
	eaves have exposed rafter ends visible.	100	material	Asphalt shingle	+
	hree bay with tripled windows at the	(22)	contact print		5)
first and thind	hav aparings. The contan window of the	l	35mm		
	bay openings. The center window of the				}
	than those flanking it. Below on the				
	ows is a red brick veneer on the wall	1			
surface. The p	orch is supported by square brick pillars				
and has a co	ncrete porch surface and steps.	-			1
46) Description of enviro					<del> </del>
	nment/outbuildings	23)	site plan		99
	nment/outbuildings	23)	site plan		9)
<b>0 b</b> • · · · · b		}	site plan		9)
Behind the hous	e is a one bay gable entrance wood garage	}	site plan		9)
Behind the hous		}	site plan		9)
Behind the hous					
Behind the hous			site plan		9) 5)
	e is a one bay gable entrance wood garage		changes -	None visible	
		24)	changes - additions/alter-	None visible Good	
	e is a one bay gable entrance wood garage	24)	changes - additions/alter- ations/moved		
	e is a one bay gable entrance wood garage	24) 25) 26)	changes - additions/alter- ations/moved condition	Good	5)
	e is a one bay gable entrance wood garage	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road?	Good	
47) Information sources	e is a one bay gable entrance wood garage  City Directory 1924-1933.	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road?	Good	5)
	e is a one bay gable entrance wood garage  City Directory 1924-1933.  Roll 547-10 #19-20	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	Good	5)
47) Information sources  48) Location of negatives	e is a one bay gable entrance wood garage  City Directory 1924-1933.	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	Good	5)
47) Information sources	e is a one bay gable entrance wood garage  City Directory 1924-1933.  Roll 547-10 #19-20	25) 26) 27) 28) 29	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	Good	5)
47) Information sources  48) Location of negatives  49) Prepared by DDD	e is a one bay gable entrance wood garage  City Directory 1924-1933.  Roll 547-10 #19-20  Roll 4 #25	25) 26) 27) 28) 29	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	Good No No	5) 6)
47) Information sources  48) Location of negatives	e is a one bay gable entrance wood garage  City Directory 1924-1933.  Roll 547-10 #19-20	24) 25) 26) 27) 28) 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	Good	5)
47) Information sources  48) Location of negatives  49) Prepared by DDD	e is a one bay gable entrance wood garage  City Directory 1924-1933.  Roll 547-10 #19-20  Roll 4 #25	24) 25) 26) 27) 28) 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	Good No No	5) 6)
47) Information sources  48) Location of negatives  49) Prepared by DDD	e is a one bay gable entrance wood garage  City Directory 1924-1933.  Roll 547-10 #19-20  Roll 4 #25	24) 25) 26) 27) 28) 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	Good No No	5) 6)
48) Location of negatives 49) Prepared by DDD 50) Organization	e is a one bay gable entrance wood garage  City Directory 1924-1933.  Roll 547-10 #19-20 Roll 4 #25  Missouri Heritage Trust	24) 25) 26) 27) 28) 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	Good	5) 6)
48) Location of negatives 49) Prepared by DDD 50) Organization	e is a one bay gable entrance wood garage  City Directory 1924-1933.  Roll 547-10 #19-20  Roll 4 #25	24) 25) 26) 27) 28) 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	Good	5) 6)
48) Location of negatives 49) Prepared by DDD 50) Organization	e is a one bay gable entrance wood garage  City Directory 1924-1933.  Roll 547-10 #19-20 Roll 4 #25  Missouri Heritage Trust	24) 25) 26) 27) 28) 30 31 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	Good	5) 6)
48) Location of negatives 49) Prepared by DDD 50) Organization	e is a one bay gable entrance wood garage  City Directory 1924-1933.  Roll 547-10 #19-20 Roll 4 #25  Missouri Heritage Trust	24) 25) 26) 27) 28 29 30 31 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	Good No No No No Yes	5) 6) 7)
48) Location of negatives 49) Prepared by DDD 50) Organization	e is a one bay gable entrance wood garage  City Directory 1924-1933.  Roll 547-10 #19-20 Roll 4 #25  Missouri Heritage Trust	24) 25) 26) 27) 28) 30 31 32 33 34 35	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	Good No No No No Yes	5) 6)








Missouri Historic Architectural Inventory for GRAA 063 - 663

•	Division of Parks and Historic Preservation Dep	artn	nent of Natura	Resources	
38) Ownership — privat	e X . *	1)	inventory number	85	٥
— public			name (cont)		]
39) Owners — name	Ella Woomer	1 '	name - historial		
address	1461 E. Walnut	1 '	street address	1461 E. Walnut	ļ
40) Local contact			town or vicinity	Springfield	
41) Coordinates (U	TM)	1	legal description	Erisco Heights Add. Lot	
42) Quad			county	Greene 12 Block 8	<u> </u>
43) Other survey		8)	category		2/3)
		1	(site, structure,	Building	
44) History		100	building, object) significance		₹.
44) History	Built 1925-1926 for unknown non-resident		date	Architectural-Contribut	ing
	owner.	1	style	1925-1926	1
		1	architect	Colonial Revival	1
		1 '	builder		┥
		1 '	original use	Residence	┪
		1	present use	Residence	1
45) Additional descripti	on In the west gable are six over one ligh	16)	number of stories	1-1/2	4
	The face of the gable is stuccoed at the	417)	plan shape	Rectangle	1
half story leve		18)	basement	Full	1
•	rieze. At the gable ends are cornice re-	19)	foundation	Concrete	1
	brick stretchers is a horizontal band as	20)	wall construction	Brick Veneer-1st Frame	1
	the front elevation is a wide shed dor-		roof type -	Gambrel 1/2 story	1
	er one window sash and a stucco face. On		material	Asphalt shingle	
	level the window sash is twelve over one.	22)	contact print		5)
There is a cent	ral entrance with sidelights flanking the	Ì	35mm		
entry way. Abo	ve the entry is a portico with a half				}
	supported by simple corner brackets. On	1			
	ion is a one-story sun porch which has				
	illed in. There are square brick pillars				1
with cast co	ncrete square capitals. On the rear of				
the house is a	one-story modern addition.	231	site plan		و
		20,	Site plan		
	e is a one-bay wooden gable entrance	1		· ·	
garage with lap	siding.	1			
		1			
				and the second s	
47) Information source	s	24	) changes -		5
	City Directory 1924-1933.		additions/alter-		
		ł	ations/moved	None visible	
		25	) condition	Good	
		- 1	) visible from road?		4
			) distance/frontage		
			) accessible?	<u> </u>	6
48) Location of negative	es Roll <b>547-11</b> #1-2	29	) preservation		
	Roll 4 #26	120	underway?	_No	4
49) Prepared by D	<b>D</b> D		) endangered? ) on National	No	4
		31	Register?		
50) Organization	Missouri Heritage Trust	32	) part of	No.	7
		٦٤	established		
		-	historical district	No	
If additional space is nee	eded, attached separate sheets.	33	) name of historical		7
- accidental opace to the			district	-	
		34	) is site eligible?	Yes	
		35	) district potential?		30)
			) date	Jan. 30, 1984	4
		37	') revision		

N



0 00 00



Missouri Historic Architectural Inventory for Control

38) Ownership — private	x . *	1)	inventory number	86	
— public		2)	name (cont)		
39) Owners — name	James Muchmore	3)	name - historial		
- address	1465 E. Walnut	4)	street address	1465 E. Walnut	
40) Local contact		5)	town or vicinity	Springfield	
41) Coordinates (UTA	A)	6)	legal description	Frisco Heights Add.	
42) Quad		7)	county	Greene Block 8 Lot	11
43) Other survey		8)	category		2/3)
			(site, structure,		(9)
		Ì	building, object)	Building	
44) History		9)	significance	Architectural-Contri	butin
	Built 1912-1913 by Wm. B. Raymond,	10)	date	1912-1913	
	traveling salesman	11)	style	Bungalow	
	<b>3</b>	12)	architect		
		13)	builder		
		14)	original use	Residence	
		15)	present use	Residence	
45) Additional description	On the front elevation is a gable dorme	<b>u</b>	number of stories	1-1/2	4
contared on the	e long side of the gabled roof. The	17)	plan shape	Rectangle	
	ormer overhang with exposed rafter ends.	18)	basement	Full Turner	
The nahla ic no	orings over hand with exposed ratter ends.	19)	foundation	Concrete	
ic a narrow mo	edimented with a butt shingled face. The ulded cornice with the frieze as window			Frame/lap siding	
	ipled gable window with six over one ligh	121)	roof type -	Gable	
	is of the dormer are butt shingled.	٩	material	Asphalt shingle	
	ntinuous over the front porch but with a	22)	contact print		5)
	carry over beginning above the exterior	Ì	35mm		
	ne facade is three bay with doubled windo				
	e over one light sash with applied mould-	W S			
	dow heads. The entry bay is slightly re-				1
cassad from	the wall surface and has sidelights with				
	s lights flanking the entrance. Above				1
the door is a	transom with a moulded door head covering				
46) Description of enviro	transom with a moulded door head covering	23)	site plan		9
					-
Behind the hous	e is a one-story wood frame garage with	'		en en en en en en en en en en en en en e	*
a gabled roof a					-
· ·					1
47) Information sources		24)	changes -		5
			additions/alter-		
	City Directory 1911-1933		ations/moved		
	·		condition	Good	
			visible from road?		
		- 1	) distance/frontage		
			accessible?	-	6
48) Location of negatives	Roll 4 #27-29	29	) preservation		
	ROT1 4 #27-29 ROT1 547-11 #3-4		underway?	No	
49) Prepared by DDD	KU11 547-11 #5-4		endangered?	No	
		31	on National		
50) Organization	Missouri Heritage Trust	l	Register?	No	<u>––</u> ∃
		32	) part of		
		-	established	No	
			historical district	No	
If additional space is need	ed, attached separate sheets.	33	) name of historical	1	
			district	- Voc	
		- 1	) is site eligible?	Yes	- ω
			) district potential?		30)
		- 1	) date	Jan. 30, 1984	-
		3/	') revision	l	

1465 E. Walnut

usor and sidelights.

There are overhanging eaves on the porch roof with tapering square wooden column supports and moulded wooden plinths. Beneath the columns are square red brick pillars with limestone caps. The balustrade has a moulded hand rail and square wooden balusters. The porch floor and structure are wood with concrete steps leading to it and brick flanking walls with limestone copings.

The east elevation - the gable is butt shingle faced in the pediment with a doubled window opening. The first story is lap sided. The pediment frieze acts as window head to the first story window openings. There is a first story oriel window with a shed roof with exposed rafter ends. The oriel is three sided with a large center window opening with a multi-paned upper sash.

On the rear roof face is a shed dormer.

C-0, De, DO: 10 66

 $\sqrt{}$ 



Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources 38) Ownership - private 1) inventory number 87 - public 2) name (cont) 39) Owners - name 3) name - historial Billie Ellingsworth - address 4) street address 1471 E. Walnut <u> 1471 E. Walnut</u> 40) Local contact 5) town or vicinity Springfield 6) legal description 41) Coordinates (UTM) Frisco Heights Add 42) Quad 7) county Greene Block 8 Lot 10 8) category 43) Other survey (site, structure, Building building, object) 9) significance 44) History Architectural-Contributin 10) date ca. 1910 11) style Catalogue/Builder 12) architect with classical detai 13) builder 14) original use Residence 15) present use Residence 16) number of stories 4 45) Additional description West elevation - broad projecting eaves in the gables and under the long side eaves. The face of 17) plan shape Square 18) basement the gable is covered with butt shingles. In the gable Full 19) foundation there are pronounced cornice returns. The pediment is Concrete 20) wall construction Frame/Lap Siding set off with a moulded cornice and frieze which serves 21) roof type as the window heads to the second story windows. All Gable material Asphalt shingle window openings have one over one light sash. The ex-22) contact print 5 ception is the upper sash in what is probably the entry 35mm hall window which has an ornate stained glass sash. All first floor window openings have applied moulding to the window heads. On the front elevation is a gabled dormer with slightly splayed walls covered with butt shingles. There are pronounced cornice returns with a wide cornice and frieze setting off the gable pediment area. There are two window openings with one over one light sash 23) site plan 46) Description of environment/outbuildings Behind the house is a two bay frame garage which appears to be modern. 5 24) changes -47) Information sources additions/alterations/moved None visible 25) condition Good 26) visible from road? 27) distance/frontage 28) accessible? 9 29) preservation 48) Location of negatives Roll 5 #3-5 underway? No Roll 547-11 #5-6 30) endangered? No 49) Prepared by DDD 31) on National Missouri Heritage Trust Register? No 50) Organization 32) part of established historical district No 33) name of historical If additional space is needed, attached separate sheets. district 34) is site eligible? Yes 35) district potential? Yes 36) date Jan. 30, 1984

37) revision

1471 E. Walnut

The porch has a hipped roof with a centered gabled pediment over the entry area. The face of the pediment is covered with butt shingles. The porch cornice has a dentil pattern with porch supports of square wooden posts. There is a very simple square wooden balustrade above a stone parapet of rough faced ashlar limestone construction topped with smooth limestone coping. A belt or water table extends around the porch also of smoothed stonework.

Around the entry way is a transom and flanking sidelights with multipaned lights. On the rear of the shouse is a two-story porch area which has since been filled in.

(10 A

2 Story closed porch


NA



Division of Lancounter Cooking and Doba				
38) Ownership — private X	1)	inventory number	88	۳
— public	2)	name (cont)		
39) Owners — name Donald Stratton	3)	name - historial		1
-address 1477 E. Walnut	4)	street address	1477 E. Walnut	
40) Local contact	5)	town or vicinity	Springfield	1
41) Coordinates (UTM)	6)	legal description	Frisco Heights Add.	1
42) Quad	7)	county	Greene Block 8 Lot 9	1
43) Other survey	8)	category		2/3)
		(site, structure,		ω
		building, object)	Building	
44) History	9)	significance	Architectural-Commerce	1
	10)	date	1911-1912	1
Manager of Lucas-Horner Belt Co.	11)	style	Colonial Revival	1
	12)	architect		7
	13)	builder		1
	14)	original use	Residence	}
	15)	present use	Residence	1
45) Additional description  The eaves project over the walls with	16)	number of stories	2	4
ine eaves project over the walls with	17)	plan shape	Square	1
modifications beneath. The irreze board acts as the window	18)	basement	Fu11	1
head to the second story windows which have eight over	19)	foundation	Concrete	1
one light sash and limestone sills. The facade is two	20)	wall construction	Brick	1
bay with the first bay as a tripled window with the	21)	roof type -	Gable Asphalt shingle	1
center opening larger than those flanking. The entry		material		1
has sidelights with leaded glass lights. Both window	22)	contact print		5)
and door openings have smooth dressed limestone lintels.	ı	35mm		
The porch has hipped roof covered only above the entry				
area with fluted columns with Tuscan capitals tripled				-
at the corners. The porch structure is of brick and con-				1
tinued across the entire facade as an open porch before				1
the first bay. Across both the open and closed porch	}			1
areas is a wooden balustrade with turned balusters.	Ì			
46) Description of environment/outbuildings	23)	site plan		9
	}			
Debied 4b. be a few and street 47b. manage and office				
Behind the house is a one-story tile garage outbuilding	ĺ			
with a gable roof.				
47) Information sources	24)	changes -		5)
City Directory 1910-1933	Ì	additions/alter-		
		ations/moved	None visible	
	25)	condition	Good	
	261	visible from road?	_	
	20,	VISIDIE II OIII TOBU.		
		distance/frontage		
	27)		-	9
48) Location of negatives Doll E47 11 #7_9	27) 28)	distance/frontage	-	6)
48) Location of negatives Roll 547-11 #7-8	27) 28)	distance/frontage accessible?	-	6)
	27) 28) 29)	distance/frontage accessible? preservation	No.	6)
48) Location of negatives Roll 547-11 #7-8  49) Prepared by DDD	27) 28) 29) 30)	distance/frontage accessible? preservation underway?	-	6)
49) Prepared by DDD	27) 28) 29) 30)	distance/frontage accessible? preservation underway? endangered?	No No	
	27) 28) 29) 30) 31)	distance/frontage accessible? preservation underway? endangered? on National	No.	6) 7)
49) Prepared by DDD	27) 28) 29) 30) 31)	distance/frontage accessible? preservation underway? endangered? on National Register?	No No	
49) Prepared by DDD	27) 28) 29) 30) 31)	distance/frontage accessible? preservation underway? endangered? on National Register? part of	No No	
49) Prepared by DDD  50) Organization Missouri Heritage Trust	27) 28) 29) 30) 31) 32)	distance/frontage accessible? preservation underway? endangered? on National Register? part of established	No No No	
49) Prepared by DDD	27) 28) 29) 30) 31) 32)	distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	No No No	
49) Prepared by DDD  50) Organization Missouri Heritage Trust	27) 28) 29) 30) 31) 32)	distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	No No No	
49) Prepared by DDD  50) Organization Missouri Heritage Trust	27) 28) 29) 30) 31) 32) 33)	distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	No No No Yes	7)
49) Prepared by DDD  50) Organization Missouri Heritage Trust	27) 28) 29) 30) 31) 32) 33) 34) 35)	distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	No No No Yes	

ist elevation - There are cornice returns in the gable with the gable pediment set off with a heavy moulded slightly projecting cornice and frieze as window head to the second story windows. The pediment area is covered with stucco. There are doubled windows in the gable with six over one light sash.

141 Bushall C



N


Ca



## Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership - private	*	1 1)	inventory number	89	Ι
— public	•	1	name (cont)		=
39) Owners — name	Robert Killian et al		name - historial		
	1481 E. Walnut	1			
— address	1401 E. Walliut	1	street address	<u> 1481 E. Walnut</u>	
40) Local contact			town or vicinity	<u>Springfield</u>	
41) Coordinates (UTA	<b>/</b> )		legal description	Frisco Heights Add.	
42) Quad		7)	county	Greene Block 8 Lot	8
43) Other survey		8)	category		
			(site, structure,		2/3)
			building, object)	Building	
44) History	Desile 1026 1027 for Mary Marris	9)	significance	Contributing	1
	Built 1926-1927 for Mrs. Mary Morriss	J	date		ł
		1	style	1926-1927	ł
		ì	architect	Colonial Revival	
		1			-
		1 .	builder		
		1	original use	Residence	
			present use	Residence	
45) Additional description	Fact Gable - simple moulded compice	1	number of stories	2	4
notunne in the	East Gable - simple moulded cornice	17)	plan shape	Rectangle	]
	gable. A belt course of vertical	18)	basement	Full	1
	off the pediment area in the gable,	19)	foundation	Concrete	1
	window head to the second story window	20)	wall construction	Brick Veneer	1
	window openings flank the end chimney		roof type -	Gable	1
centered in the	gable. False shutters are at each win-				1
dow opening. A	1 windows are composed of steel multipane	<b>d</b> 21	contact print	Asphalt shingle	5
sash in a caseme	ent window. There is a flat roofed open	22)	35mm		<u> </u>
	st side of the house with square wooden	ì	Somm		
	ing it. On the facade there are three				
	ze under the eaves acts as window head				
· ·	tory window openings. Between the first				
		4			į
	cories is a belt course of vertical placed	J			
	nich serves as the window head to the				
46) Description of environ	nings. Over the entry way is a half ——	23)	site plan		9
·	-		•		
Pohind the house	s is a one hay brick outbuilding with a				
	e is a one-bay brick outbuilding with a				İ
gabled roof.					
47) Information courses		24)	<u></u>		(n
47) Information sources		24)	changes -		5)
	City Directory 1925-1933		additions/alter-		
	<b>.</b> ▼		ations/moved	None	1
		/	condition	Good	
		26)	visible from road?		
		27)	distance/frontage	_	
		28)	accessible?	_	6)
48) Location of negatives	D-11 F #6	29)	preservation		1
	Roll 5 #6	1	underway?	No.	
49) Prenared by	Roll 547-11 #9-10	301	endangered?	No	+
49) Prepared by DDD		1	-	No	-
50\ 0		211	on National		i
50) Organization		31)	on National	No.	
oo, organization	Missouri Heritage Trust		Register?	No	7
oo, organization	Missouri Heritage Trust		Register? part of	No	7
oo, organization	Missouri Heritage Trust		Register? part of established		7)
oo, o gamzatto.	Missouri Heritage Trust	32)	Register? part of established historical district	No No	7)
-	Missouri Heritage Trust  d. attached separate sheets	32)	Register? part of established historical district name of historical		7)
-		32)	Register? part of established historical district		7)
-		32)	Register? part of established historical district name of historical	No	7)
-		32) 33) 34)	Register? part of established historical district name of historical district	No Yes	
-		32) 33) 34) 35)	Register? part of established historical district name of historical district is site eligible?	No Yes Yes	7) 30)
-		32) 33) 34) 35) 36)	Register? part of established historical district name of historical district is site eligible? district potential?	No Yes	

N






### Missouri Historic Architectural Inventory for Company Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — privare X	1) inventory number	90	J=
— pub <sup>4</sup> :	2) name (cont)		7
39) Owners—name Michael Sapp	3) name - historial		7
— address 1985 E. Walnut	4) street address	1485 E. Walnut	7
40) Local contact	5) town or vicinity	Springfield	7
41) Coordinates (UTM)	6) legal description	Frisco Heights Add. Bl	dck
42) Quad	7) county	Greene 8 Lot 7	٠ ا
43) Other survey	8) category	di cerie s 200 /	N
	(site, structure,		2/3)
	building, object)	Building	
44) History D = 1 1 1000 1007 L 0 D	9) significance	Contributing	+
Build 1926-1927 by Guy Reed, a grocer	10) date		-
by trade.	11) style	1926-1927	4
	12) architect	<u>Colonial Revival</u>	-
	13) builder		4
	14) original use	Residence	4
	15) present use	Residence	4
AEV Additional design	1	Residence	<del> </del>
45) Additional description The eaves project on the gabled roof	16) number of stories	D. F. S. S. T.	4
house with a moulded cornice. There are jerkinheads on	17) plan shape	Rectangle	_
each of the gables. At the gable corners are notable	18) basement	Full	_
cornice returns. The face of the gable is covered with	19) foundation	Concrete	
stucco. The facade is three bay with flat arch lintels	20) wall construction	Brick Veneer	
at the openings The windows are six over six light sash	21) roof type -	Gable	
doubled at each bay. Centered over the entrance is a	material	Asphlat shingle	
covered portico on an otherwise open porch. The porch	22) contact print		5
roof is gabled with a jerkinhead roof at the apex. The	35mm		
face of the ped ment is stucco. The entablature is			
notably broad with round wooden columns with Tusdan			
· · · · · · · · · · · · · · · · · · ·			
capitals supporting it. The porch itself is of brick.			
Alamana di Alamana di Alamana di Alamana di Alamana di Alamana di Alamana di Alamana di Alamana di Alamana di A			1
Around the house is a watertable of vertically placed			
Naround the house is a watertable of vertically placed stretcher brick.			
	23) site plan		9)
stretcher brick.	23) site plan		9)
stretcher brick.	23) site plan		9)
stretcher brick.	23) site plan		9)
stretcher brick.	23) site plan		9)
stretcher brick.	23) site plan		9)
Stretcher brick.  46) Description of environment/outbuildings			
stretcher brick.	24) changes		9) 5)
Stretcher brick.  46) Description of environment/outbuildings	24) changes - additions/alter-	None	
Stretcher brick.  46) Description of environment/outbuildings	24) changes - additions/alter- ations/moved	None	
Stretcher brick.  46) Description of environment/outbuildings	24) changes - additions/alter- ations/moved 25) condition	Good	
Stretcher brick.  46) Description of environment/outbuildings	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	Good	
Stretcher brick.  46) Description of environment/outbuildings	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	Good	5)
Stretcher brick.  46) Description of environment/outbuildings  47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	Good	
Stretcher brick.  46) Description of environment/outbuildings	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	Good - - -	5)
46) Description of environment/outbuildings  47) Information sources  Roll 547-11 #11-12	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	Good No	5)
46) Description of environment/outbuildings  47) Information sources	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	Good - - -	5)
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives Roll 547-11 #11-12  49) Prepared by DDD	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	Good No No	5)
48) Location of negatives Roll 547-11 #11-12	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	Good No	5)
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives Roll 547-11 #11-12  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	Good No No	5) [6]
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives Roll 547-11 #11-12  49) Prepared by DDD	<ul> <li>24) changes - additions/alterations/moved</li> <li>25) condition</li> <li>26) visible from road?</li> <li>27) distance/frontage</li> <li>28) accessible?</li> <li>29) preservation underway?</li> <li>30) endangered?</li> <li>31) on National Register?</li> <li>32) part of established</li> </ul>	Good No No	5) [6]
48) Location of negatives Roll 547-11 #11-12  49) Prepared by DCD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	Good No No No	5) [6]
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives Roll 547-11 #11-12  49) Prepared by DDD	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	Good No No No	5) [6]
48) Location of negatives Roll 547-11 #11-12  49) Prepared by DCD  50) Organization Missouri Heritage Trust	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	Good No No No No	5) [6]
48) Location of negatives Roll 547-11 #11-12  49) Prepared by DCD  50) Organization Missouri Heritage Trust	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	Good No No No No - Yes	5) [6) 7)
48) Location of negatives Roll 547-11 #11-12  49) Prepared by DCD  50) Organization Missouri Heritage Trust	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	Good	5) [6]
48) Location of negatives Roll 547-11 #11-12  49) Prepared by DCD  50) Organization Missouri Heritage Trust	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	Good No No No No - Yes	5) [6) 7)







# Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources \* 1) inventory number | 91

38) Ownership — private X	1) inventory number	91	تا
public	2) name (cont)		}
39) Owners—name Sara Rice	3) name - historial		1
—address 1501 E. Walnut	4) street address	1501 E. Walnut	1
	5) town or vicinity		1
40) Local contact		Springfield	-
41) Coordinates (UTM)	6) legal description	Frisco Heights Add.	ļ
42) Quad	7) county	Greene Block 9 Lot 14	
43) Other survey	8) category		2
	(site, structure,		2/3)
	building, object)	Dud I di na	ĺ
	<del>-</del> -	Building	1
44) History	9) significance	Contributing	1
	10) date	ca. 1910	Ì
	11) style	Catalogue/Builder with	}
	12) architect	colonial details	1
	13) builder	Colonial decaris	1
		<del></del>	-
	14) original use	Residence	ļ
	15) present use	Residence	
45) Additional description	16) number of stories	2	4
West gable - at the gable corners are	17) plan shape	Square	1
cornice returns with modillions under the returns and	18) basement		
under the gable eaves. The window openings are six over	,	Full	_
· · · · · · · · · · · · · · · · · · ·	19) foundation	Concrete	
six light sash. The facade is three bay. The frieze	20) wall construction	Frame/Steel siging	7
under the cornice acts as the window head to the second	21) roof type -	Gable	1
story window openings. There is a flat roofed porch with	material	Asphalt shingle	4
a wooden balustrade around the edge. Under the eave of	22) contact print	Aspliant sinnight	5
	1		
the porch are moddillions. Supporting the porch are	35mm		
tripled round wooden columns with tuscan capitals. The			
porch floor is of concrete.	İ		1
On the rear of the house is a two story sun porch with			
multiple window openings which appears to remain			Ì
relatively unaltered.			
t relatively unaltered			
refuelt very una recrea.	1		1
refuervery unartered.			
·	23) site plan		9
46) Description of environment/outbuildings	23) site plan		99
·	23) site plan		9)
46) Description of environment/outbuildings	23) site plan		9)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with	23) site plan		9)
46) Description of environment/outbuildings	23) site plan		9)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with	23) site plan		9)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.	at.	· · · · · · · · · · · · · · · · · · ·	
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with	24) changes -		9) 5)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.	24) changes - additions/alter-	Steel siding added	
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.	24) changes -	Steel siding added	
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.	24) changes - additions/alter-		
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.	24) changes - additions/alter- ations/moved 25) condition	Good	
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	Good	
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	Good	5)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	Good	
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.  47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	Good	5)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.  47) Information sources  Roll 5 #7	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	Good	5)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.  47) Information sources  Roll 5 #7  Poll 547-11 #13-14	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	Good	5)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.  47) Information sources  Roll 5 #7  Roll 547-11 #13-14	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	Good	5)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.  47) Information sources  Roll 5 #7  Poll 547-11 #13-14	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	Good No No	5)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.  47) Information sources  Roll 5 #7  49) Prepared by DDD  50) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	Good	5)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.  47) Information sources  48) Location of negatives Roll 5 #7 Roll 547-11 #13-14	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	Good No No	5) 6)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.  47) Information sources  Roll 5 #7  49) Prepared by DDD  50) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	Good No No	5) 6)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.  47) Information sources  Roll 5 #7  49) Prepared by DDD  50) Organization	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	Good No No No	5) 6)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.  47) Information sources  48) Location of negatives Roll 5 #7 Roll 547-11 #13-14 DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	Good No No No	5) 6)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.  47) Information sources  Roll 5 #7  49) Prepared by DDD  50) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica	Good No No No	5) 6)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.  47) Information sources  48) Location of negatives Roll 5 #7 Roll 547-11 #13-14 DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district	Good  No No No No	5) 6)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.  47) Information sources  48) Location of negatives Roll 5 #7 Roll 547-11 #13-14 DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible?	Good  No No No No Yes	5) 6) 7)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.  47) Information sources  48) Location of negatives Roll 5 #7 Roll 547-11 #13-14 DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district	Good  No No No No Yes	5) 6)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.  47) Information sources  48) Location of negatives Roll 5 #7 Roll 547-11 #13-14 DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible?	Good  No No No No  No  Yes Yes Yes	5) 6) 7)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.  47) Information sources  48) Location of negatives Roll 5 #7 Roll 547-11 #13-14 DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential: 36) date	Good  No No No No Yes	5) 6) 7)
46) Description of environment/outbuildings  Behind the house is a one-story single bay garage with gable entrance.  47) Information sources  Roll 5 #7 Roll 547-11 #13-14 DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential:	Good  No No No No  No  Yes Yes Yes	5) 6) 7)

The Story Sun Porch NA

Acres Andrews




Missouri Historic Architectural Inventory for Gazana Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership private		11	inventory number	92	
38) Ownership — private	× . *		inventory number name (cont)	<u> </u>	<u>ا</u> ت
public	was Vandauhilt	1 -	name (cont)		_
	orge Vanderbilt			3,000 00 11 3	4
	05 E. Walnut	l '	street address	1505 E. Walnut	_
)40) Local contact			town or vicinity	Springfield	
41) Coordinates (UTM)			legal description	Frisco Heights Add.	4
42) Quad			county	Greene Block 9 Lot 13	
43) Other survey			category		2/3)
			(site, structure,		=
			building, object)	Building	
44) History	1t 1928-1929 by Perry Ragan		significance	<u> Architectural-Contrib</u>	<u>u</u> tin
	ner of Ragan's Dept. Store		date	1928-1929	
OWI	iei oi kagan 3 bept. 3tore		style	Four Square Catalogue	_
		1 1	architect	Builder	
			builder		
			original use	Residence	
		L	present use	Residence	
45) Additional description	t side elevation there is a hipped	1	number of stories	2	4
	st side elevation - there is a hipped	1	plan shape	Square	
	one story with a brick veneer parapet	18)	basement	Full	
	ick columns supporting the roof.	19)	foundation	Concrete	_
	v openings have upper sash with	20)	wall construction	Stucco over frame	
corner muntins (see		21)	roof type -	Hip Asphalt shingle	_
	ashes are like that described above.		material	1119 7.39114 10 311113 10	7
	ojecting eaves on the house with a	22)	contact print		5
	g as window head to the second story		35mm		
, ,	The corners of the house at the facade	1			1
	which splay outward as they come to				
	acade is three bay with double window				
	ne windows on the first story is a	1			1
brick veneer on	the wall surface which extends around				
the entire struc	the wall surface which extends around cture. At the second story level there	e	site plan		9)
	the wall surface which extends around cture. At the second story level there	e	site plan		9)
the entire structure 46) Description of environment	the wall surface which extends around cture. At the second story level there to the total distribution to the total distribution of the total distri	e	site plan		9)
the entire structure 46) Description of environment Behind the house is	the wall surface which extends around cture. At the second story level there to the control of t	e	site plan		9)
the entire structure 46) Description of environment	the wall surface which extends around cture. At the second story level there to the control of t	e	site plan		9)
the entire structure 46) Description of environment Behind the house is	the wall surface which extends around cture. At the second story level there to the control of t	e	site plan		9)
the entire struct  46) Description of environment  Behind the house is hip roof and one back  47) Information sources	the wall surface which extends around cture. At the second story level there would be a considered to the second story level the second s	23)			
the entire struct  46) Description of environment  Behind the house is hip roof and one back  47) Information sources	the wall surface which extends around cture. At the second story level there to the control of t	23)	changes -	Steel roof porch is a	5)
the entire struct  46) Description of environment  Behind the house is hip roof and one back  47) Information sources	the wall surface which extends around cture. At the second story level there would be a considered to the second story level the second s	23)	changes - additions/alter-	Steel roof porch is a	5)
the entire struct  46) Description of environment  Behind the house is hip roof and one back  47) Information sources	the wall surface which extends around cture. At the second story level there would be a considered to the second story level the second s	23)	changes - additions/alter- ations/moved	later addition	5)
the entire struct  46) Description of environment  Behind the house is hip roof and one back  47) Information sources	the wall surface which extends around cture. At the second story level there would be a considered to the second story level the second s	24)	changes - additions/alter- ations/moved condition		5)
the entire struct  46) Description of environment  Behind the house is hip roof and one back  47) Information sources	the wall surface which extends around cture. At the second story level there would be a considered to the second story level the second s	24) 25) 26)	changes - additions/alter- ations/moved condition visible from road?	later addition	5)
the entire struct  46) Description of environment  Behind the house is hip roof and one back  47) Information sources	the wall surface which extends around cture. At the second story level there would be a considered to the second story level the second s	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road? distance/frontage	later addition	5)
the entire struct  46) Description of environment  Behind the house is hip roof and one back  47) Information sources  Ci	the wall surface which extends around cture. At the second story level there would be a second story level there with a second story level there with a second story frame garage with a second story level there with a second story level there with a second story level there with a second story level there will be a second story level the second story level there will be a second story level the second story level there will be a second story level the second story leve	23) 23) 24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	later addition	5)
the entire struct  46) Description of environment  Behind the house is hip roof and one both  47) Information sources  Ci	the wall surface which extends around cture. At the second story level there would be a second story level there would be a second story level there would be a second story level there were second story level the second	23) 23) 24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	later addition  Good	5)
46) Description of environment Behind the house is hip roof and one ba	the wall surface which extends around cture. At the second story level there would be a second story level there with a second story level there with a second story frame garage with a second story level there with a second story level there with a second story level there with a second story level there will be a second story level the second story level there will be a second story level the second story level there will be a second story level the second story leve	24) 224) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	later addition  Good  No	5)
the entire struct  46) Description of environment  Behind the house is hip roof and one both  47) Information sources  Ci	the wall surface which extends around cture. At the second story level there would be a second story level there would be a second story level there would be a second story level there were second story level the second	24) 224) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	later addition  Good	5)
46) Description of environment Behind the house is hip roof and one back  47) Information sources Ci  48) Location of negatives Ro Ro 49) Prepared by DDD	the wall surface which extends around cture. At the second story level there would be a considered by the second story level the second s	24) 224) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	later addition  Good  No	5)
46) Description of environment Behind the house is hip roof and one back  47) Information sources Ci  48) Location of negatives Ro Ro 49) Prepared by DDD	the wall surface which extends around cture. At the second story level there would be a second story level there would be a second story level there would be a second story level there were second story level the second	23) 24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	later addition  Good  No	5)
46) Description of environment Behind the house is hip roof and one back  47) Information sources Ci  48) Location of negatives Ro Ro 49) Prepared by DDD	the wall surface which extends around cture. At the second story level there would be a considered by the second story level the second s	23) 24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	later addition  Good  No	5) 6)
46) Description of environment Behind the house is hip roof and one back  47) Information sources Ci  48) Location of negatives Ro Ro 49) Prepared by DDD	the wall surface which extends around cture. At the second story level there would be a considered by the second story level the second s	23) 24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	later addition  Good  NoNoNo	5) 6)
the entire struct  46) Description of environment  Behind the house is hip roof and one back  47) Information sources  Ci  48) Location of negatives Ro Ro  Ro  49) Prepared by DDD  50) Organization Mi	the wall surface which extends around cture. At the second story level there would be to the second story level there with a lay.  The second story level the se	24) 224) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	later addition  Good  No No No	5) 6)
46) Description of environment Behind the house is hip roof and one back  47) Information sources Ci  48) Location of negatives Ro Ro 49) Prepared by DDD	the wall surface which extends around cture. At the second story level there would be to the second story level there with a lay.  The second story level the se	24) 224) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	later addition  Good  No No No	5) 6)
the entire struct  46) Description of environment  Behind the house is hip roof and one back  47) Information sources  Ci  48) Location of negatives Ro Ro  Ro  49) Prepared by DDD  50) Organization Mi	the wall surface which extends around cture. At the second story level there would be to the second story level there with a lay.  The second story level the se	24) 224) 25) 26) 27) 28) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	later addition  Good  No No No No	5) 6)
the entire struct  46) Description of environment  Behind the house is hip roof and one back  47) Information sources  Ci  48) Location of negatives Ro Ro  Ro  49) Prepared by DDD  50) Organization Mi	the wall surface which extends around cture. At the second story level there would be to the second story level there with a lay.  The second story level the se	23) 24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	later addition  Good  No No No No Yes	5) 6) 7)
the entire struct  46) Description of environment  Behind the house is hip roof and one back  47) Information sources  Ci  48) Location of negatives Ro Ro  Ro  49) Prepared by DDD  50) Organization Mi	the wall surface which extends around cture. At the second story level there would be to the second story level there with a lay.  The second story level the se	23) 24) 25) 26) 27) 28) 29) 30) 31) 32) 34) 35)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	later addition  Good  No No No No Yes	5) 6)

are raised diamond lozenges on the wall surfaces done in plaster (?).

( ginally there was an entry vestibule with a flat roof and an iron crest railing on the projecting roof. A modern shed roofed porch has been added across the facade. The door opening is arched with a brick faced surround. There is a brick parapet wall on the porch with smooth dressed limestone coping.

N



Upper Sash

0 - - - - - - 6 - 4




Missouri Historic Architectural Inventory for GR.

Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	• •		inventory number	115	اء
— public			name (cont)		4
39) Owners — name	Harley Mortensen		name - historial	1510 5 11-1	_
— address	634 E. Morningside		street address	1510 E. Walnut	4
. 40) Local contact	TMV		town or vicinity legal description	Springfield Arlington Heights Add.	_
41) Coordinates (U	IM)		county	Greene Lot D	
42) Quad 43) Other survey			category	Greene Lot D	+
43) Other Survey		6,	(site, structure,		2/3)
			building, object)	Building	
44) History		9)	significance	Contributing	+
44) History	Built 1924-1925 by George M. Thompson,	l	date	1924-1925	1
	Pres. Thompson Tire Co.	l	style	Colonial Revival	1
		I	architect	00101110111011101	1
		13)	builder		1
		14)	original use	Residence	7
		15)	present use	Residence	7
45) Additional descripti	Facade is three bay with six over six	16)	number of stories	2	4
7	Facade is three bay with six over six	17)	plan shape	Rectangle	7
TIGHT Sash Will	JOWS. There is a mounded cornice with the	18)	basement	Full	
	ow head to the second story windows. Under	19)	foundation	Concrete	
	y windows is a brick veneer around the en-	20)	wall construction	Stucco over Frame	
	n the east elevation is a one-story sun	21)	roof type -	Gable	
	eel siding. Over the entryway is a half defined by the supporting scroll brackets.		material	Asohalt shingle	<u> </u>
erriptical noor	a with supporting scroll brackets.	22)	contact print		5)
			35mm		
i					
46) Description of envir	ronment/outbuildings	23)	site plan		9)
	se is a one-story frame garage with one bay				
47) Information source	s	24)	changes -		5)
	City Directory 1923-1933		additions/alter-	steel siding on sun	
	aray bir ecooly 1320 1000		ations/moved		4
			condition	Good	4
		1 '	visible from road?	-	$\dashv$
			) distance/frontage ) accessible?		- 6
40)	D 11 FAZ 11 #10 20		) preservation	-	٦
48) Location of negative	es Roll 547-11 #19-20 -	23	underway?	M -	
40) Proposed by DDF		30	) endangered?	No.	7
49) Prepared by DD[	J	1	) on National		
50) Organization	Missouri Heritage Trust		Register?	No	
50) Organization	MISSOURI Heritage Trust	32	) part of		
			established		
			historical district	No	
If additional space is nee	eded, attached separate sheets.	33	) name of historical		
			district		
(		34	) is site eligible?	Yes	
		35	) district potential?		30)
			) date	Jan. 30, 1984	_
		37	') revision	1	

I Black to want




51

10.05.05



Division of Parks and Historic Preservation Department of Natural Resources 1) inventory number 38) Ownership - private X 2) name (cont) - public 39) Owners --- name Emma & Mary McDaniel 3) name - historial 1513 E. Walnut 4) street address 1513 E. Walnut --- address 5) town or vicinity Springfield 40) Local contact Frisco Heights Add. 6) legal description 41) Coordinates (UTM) Block 9 Lot 7) county Greene 42) Quad 8) category 43) Other survey 2/3 (site, structure, building, object) Building 9) significance 44) History Contributing Built 1916-1917 by Charles Ferguson 10) date 1916-1917 Secy. & Treas. State Savings Trust Co. 11) style Four Square Catalogue/ 12) architect Builder 13) builder 14) original use Residence 15) present use Residence 16) number of stories 45) Additional description 2 Overhanging eaves on the house with ex-17) plan shape Square posed rafter ends. There are corner board pilasters 18) basement Full. with applied moulding in vertical strips. The facade 19) foundation Concrete is two bay with one over one window light sash and 20) wall construction Frame/asbestos siding applied moulding to the window heads. The hipped roof 21) roof type -Hip porch has square tapering wood porch posts with a wood material Asphalt shingle balustrade and square balusters. The porch floor and 22) contact print 5 structure are of wood. On the east elevation is a 35mm one-story flat roofed sun parlor with multiple window openings with multi-paned window sash. There is a balustrade around the flat roof. On the rear is a two-story open porch with a hip roof. 9 23) site plan 46) Description of environment/outbuildings Behind the house is a one-story one bay garage with a hip roof of wood construction. 24) changes -47) Information sources Addition on east side additions/alter-Asbestos siding ations/moved 25) condition Good 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation 48) Location of negatives Roll 547-11 #17-18 underway? No 30) endangered? No 49) Prepared by DDD 31) on National Register? No 50) Organization 7 Missouri Heritage Trust 32) part of established No historical district 33) name of historical If additional space is needed, attached separate sheets district 34) is site eligible? Yes 30) 35) district potential? Yes 36) date Jan. 30, 1984

37) revision



NA




#### Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources

381 8	. V	140	in.,antan.,h 1	11/	_
38) Ownership — private		ı	inventory number	114	تا
— public			name (cont)		,
39) Owners — name	George Harriman	1 ~ ′	name - historial	1520 E. Walnut	-
— address	721 S. Holland	1 1	street address town or vicinity	Springfield	-
40) Local contact	T.A.\		legal description	Arlington Heights Add.	-
41) Coordinates (U	1M)	1		<del></del>	-
42) Quad			county	Greene Lot C.	<b>.</b>
43) Other survey		8)	category		2/3)
			(site, structure,	D +1 1	
			building, object)	Building	┧.
44) History	Della 1016 1017 by Famil Widney Dros	1	significance	Architectural-Contribu	
	Built 1916-1917 by Earl Widner, Pres.		date	1916-1917 Commerc	<b>e</b>
	North American Securities Co.	1	style	Bungalow	4
		1 '	architect		-
			builder		4
		1	original use	Residence	1
		1	present use	Residence	<del> </del>
45) Additional descripti	Front elevation - gabled dormer on long	1 1	number of stories	1-1/2	4
side roof face	with wide eaves with exposed rafter ends.		plan shape	Rectangle	1
	gable is covered with butt shingles and	1 '	basement	Full	
	ids are corner braces. The porch roof is	,	foundation	Concrete	
	ne with the roof of the house mass.	1 .	wall construction	Frame/Lap Siding	
	three bay with doubled windows and a center	(21)	roof type -	Gable	
ontranco The	door head is triangular. The porch posts	1	material	Asphalt shingle	<u> </u>
	den and taper. The corner posts are	22)	contact print		5)
	ch face. There are pillars supporting the	Ì	35mm		}
	ve stucco covering. The porch structure is				
•	wooden balustrade is a recent alteration.	`			
	vations of the porch area the entablature				1
	West gable- the window openings at the				
	have latticed sash in what is probably the				
parlor. The fa	ice of the gable is covered with stucco. A comment/outbuildings	i it			ļ
46) Description of envir	onment/outbuildings	23)	site plan		9
Pohind the hour	se is a one-story hipped roof garage frame	,			
	se is a one-scory implea root garage traine				
and one bay.					
					1
47) Information source		24)	changes -		5)
	City Directory 1915-1933		additions/alter-	_	1
			ations/moved	Porch is altered	
			) condition	Good	_
			visible from road?	_	_
			) distance/frontage		
			accessible?	<u> </u>	၂၅
48) Location of negative	es Roll 5 #11-13	29	) preservation		
	Roll 547-12 #1-2		underway?	No	_
49) Prepared by DDD	NOTE 11 2		endangered?		
000		31	) on National		
50) Organization	Missouri Heritage Trust		Register?	No	
	Pils sour Fried Fouge Trust	32	) part of		
			established		
			historical district	<u>No</u>	4
If additional space is nee	eded. attached separate sheets.	33	) name of historical		
			district		4
			) is site eligible?	<u>Yes</u>	1
		1	) district potential?	Yes	30)
		- 1	) date	Jan. 30, 1984	-
		37	) revision	Wall. 30, 1304	

une gable ends are corner knee braces. The gable is set off with a narrow band of moulding with lap siding below at the first story level.

00.28




51



### Missouri Historic Architectural Inventory for 🕒 🖟 Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private X	1) inventory number	94	J=
public	2) name (cont)		
39) Owners — name Matilda Hentschel	3) name - historial		7
—address 1523 E. Walnut	4) street address	1523 E. Walnut	7
40) Local contact	5) town or vicinity	Springfield	7
41) Coordinates (UTM)	6) legal description	Frisco Heights Add.	7
42) Quad	7) county	Greene Block 9 Lot	Τþ
43) Other survey	8) category		N
40) Other survey	(site, structure,		2/3)
	building, object)	Building	
MA IRAA	9) significance	Architectural-Contrib	utin
44) History Built 1925-1926 by unknown owner.	_	T925-1926	40111
•	10) date		4
	11) style	Colonial Revival	
	12) architect		_
	13) builder		_
	14) original use	Residence	_]
	15) present use	Residence	
45) Additional description	16) number of stories	1-1/2	4
On the front elevation is a shed dormer	17) plan shape	rectangle	
with cornice returns in the side wall gable of the dor-	18) basement	Full	7
mer. The walls are of stucco and there are three windows	19) foundation	Concrete	┪
with eight over one eight sash. The facade is three	20) wall construction		_
	21) roof type -	Brick Veneer	$\dashv$
with six over one light sash. The openings have flat	material	Gable	
arch lintels and limestone sills. There is a projecting		Asphalt Shingle	U)
center entrance bay with a gabled roof and moulded	· ·		۳
cornice. The entry is "palladian" with the arched center	35mm		
bay with a fanlight above and six over one light side			
windows flanking. West gablethere are half-hemi			
window openings flanking the centered gable chimney.			
There are cornice returns at the gable ends. On the			
east side is a one-story sun room with a flat roof			
east side is a one-story sun room with a flat roof	23) site plan		9
	23) site plan		9)
east side is a one-story sun room with a flat roof	23) site plan		9)
east side is a one-story sun room with a flat roof	23) site plan	· · · · · · · · · · · · · · · · · · ·	9)
east side is a one-story sun room with a flat roof  **********************************			9)
east side is a one-story sun room with a flat roof			9)
east side is a one-story sun room with a flat roof  ***Robert Activation of the property.  There is a gable roof garage at the rear of the property.			
east side is a one-story sun room with a flat roof  **The strate of the mode and the strate of the property.  **There is a gable roof garage at the rear of the property.  **The strate of the property.**	24) changes -		9) 5)
east side is a one-story sun room with a flat roof  ***Robert Activation of the property.  There is a gable roof garage at the rear of the property.	24) changes - additions/alter-		
east side is a one-story sun room with a flat roof  **The strate of the mode and the strate of the property.  **There is a gable roof garage at the rear of the property.  **The strate of the property.**	24) changes - additions/alter- ations/moved	None	
east side is a one-story sun room with a flat roof  **The strate of the mode and the strate of the property.  **There is a gable roof garage at the rear of the property.  **The strate of the property.**	24) changes - additions/alter-		
east side is a one-story sun room with a flat roof  **The strate of the mode and the strate of the property.  **There is a gable roof garage at the rear of the property.  **The strate of the property.**	24) changes - additions/alter- ations/moved	Good	
east side is a one-story sun room with a flat roof  **The strate of the mode and the strate of the property.  **There is a gable roof garage at the rear of the property.  **The strate of the property.**	24) changes - additions/alter- ations/moved 25) condition	Good	5)
east side is a one-story sun room with a flat roof  **The strate of the mode and the strate of the property.  **There is a gable roof garage at the rear of the property.  **The strate of the property.**	24) changes - additions/alter- ations/moved 25) condition 26) visible from road	Good	
east side is a one-story sun room with a flat roof  ***Problem of the multi-  paned casement sash.  There is a gable roof garage at the rear of the property.  47) Information sources  City Directory 1925-1926	24) changes - additions/alter-ations/moved 25) condition 26) visible from road 27) distance/frontage	Good	5)
east side is a one-story sun room with a flat roof  **The strate of the mode and the strate of the property.  **There is a gable roof garage at the rear of the property.  **The strate of the property.**	24) changes - additions/alter-ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation	Good	5)
east side is a one-story sun room with a flat roof  **Robestription of particular window openings have multi- paned casement sash.  There is a gable roof garage at the rear of the property.  47) Information sources  City Directory 1925-1926  **Roll 5 #9  Participation of negatives  Roll 5 #9  Participation of negatives  Roll 5 #9  Participation of negatives  Roll 5 #9	24) changes - additions/alterations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway?	Good	5)
east side is a one-story sun room with a flat roof  ***Robestription reministration window openings have multi- paned casement sash.  There is a gable roof garage at the rear of the property.  47) Information sources  City Directory 1925-1926  48) Location of negatives  Roll 5 #9  Roll 5 #9  Roll 547-12 #6-7	24) changes - additions/alter-ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	Good	5)
east side is a one-story sun room with a flat roof  ***Problem of the minds window openings have multipaned casement sash.  There is a gable roof garage at the rear of the property.  47) Information sources  City Directory 1925-1926  48) Location of negatives  Roll 5 #9  49) Prepared by  Roll 547-12 #6-7  DDD	24) changes - additions/alter-ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National		5) 6)
east side is a one-story sun room with a flat roof  window openings have multipaned casement sash.  There is a gable roof garage at the rear of the property.  City Directory 1925-1926  Roll 5 #9  49) Prepared by  Roll 547-12 #6-7  DDD  So) Organization	24) changes - additions/alterations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	Good	5)
east side is a one-story sun room with a flat roof  ***Problem of the minds window openings have multipaned casement sash.  There is a gable roof garage at the rear of the property.  47) Information sources  City Directory 1925-1926  48) Location of negatives  Roll 5 #9  49) Prepared by  Roll 547-12 #6-7  DDD	24) changes - additions/alterations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of		5) 6)
east side is a one-story sun room with a flat roof  window openings have multipaned casement sash.  There is a gable roof garage at the rear of the property.  City Directory 1925-1926  Roll 5 #9  49) Prepared by  Roll 547-12 #6-7  DDD  So) Organization	24) changes - additions/alterations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	Good	5) 6)
east side is a one-story sun room with a flat roof  48) best-priority window openings have multipaned casement sash.  There is a gable roof garage at the rear of the property.  47) Information sources  City Directory 1925-1926  48) Location of negatives  Roll 5 #9  Roll 5 #7  DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alterations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district		5) 6)
east side is a one-story sun room with a flat roof  window openings have multipaned casement sash.  There is a gable roof garage at the rear of the property.  City Directory 1925-1926  Roll 5 #9  49) Prepared by  Roll 547-12 #6-7  DDD  So) Organization	24) changes additions/alterations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical		5) 6)
east side is a one-story sun room with a flat roof  48) best-priority window openings have multipaned casement sash.  There is a gable roof garage at the rear of the property.  47) Information sources  City Directory 1925-1926  48) Location of negatives  Roll 5 #9  Roll 5 #7  DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter-ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district		5) 6)
east side is a one-story sun room with a flat roof  48) best-priority window openings have multipaned casement sash.  There is a gable roof garage at the rear of the property.  47) Information sources  City Directory 1925-1926  48) Location of negatives  Roll 5 #9  Roll 5 #7  DDD  50) Organization  Missouri Heritage Trust	24) changes additions/alterations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	Good	5) 6) 7)
east side is a one-story sun room with a flat roof  48) best-priority window openings have multipaned casement sash.  There is a gable roof garage at the rear of the property.  47) Information sources  City Directory 1925-1926  48) Location of negatives  Roll 5 #9  Roll 5 #7  DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter-ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	Sood	5) 6)
east side is a one-story sun room with a flat roof  48) best-priority window openings have multipaned casement sash.  There is a gable roof garage at the rear of the property.  47) Information sources  City Directory 1925-1926  48) Location of negatives  Roll 5 #9  Roll 5 #7  DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter-ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible?	Good  No No No No	5) 6) 7)
east side is a one-story sun room with a flat roof  48) best-priority window openings have multipaned casement sash.  There is a gable roof garage at the rear of the property.  47) Information sources  City Directory 1925-1926  48) Location of negatives  Roll 5 #9  Roll 5 #7  DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter-ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential	Sood	5) 6) 7)



NV


C. P. A. - M.



# Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private X	1)	inventory number	113	]=
— public	2)	name (cont)		7
39) Owners—name T. G. Frost	3)	name - historial		1
—address 1526 E. Walnut	4)	street address	1526 E. Walnut	1
40) Local contact	1 '	town or vicinity	Sprinfield	┨
41) Coordinates (UTM)	1	legal description		4
,	1		Arlington Heights Add.	4
42) Quad		county	Greene Lot B	
43) Other survey	8)	category		2/3)
		(site, structure,		٥
		building, object)	Building	
44) History	9)	significance	Architectural-Commerce	
Built 1912-1913 by Lewis Potter, Asst.	10)	date	1912-1913	7
Manager of the Springfield Wagon Co.	11)	style	Bungalow	1
	12)	architect	Dungarow	1
	1 .	builder		-
	'		D	-
	ĺ	original use	Residence	4
	1 .	present use	Residence	
45) Additional description	16)	number of stories	1-1/2	<u>4</u>
Gabled dormer on the front elevation with	17)	plan shape	Rectangle	
accented projecting purlins and rafters with broad eave	18)	basement	Full	
overhang. Continuous roof over the porch. Three bay	19)	foundation	Concrete	
facade with multi-paned casement window sash. The third	20)	wall construction	Frame/Asbestos Siding	4
bay projects from the facade. Porch posts are tapering	21)	roof type -	Gable	
square and of wood with brackets at the corners. The	,	material		-
posts rest on limestone plinths with square pillars of	22)	contact print	Asphalt shingle	5
rough fieldstone (red limestone). The porch parapet is	22)	·		15
of the fieldstone as are the flanking walls of the steps		35mm		1
	Ì			
leading to the porch and the chimney base on the west				
elevation. The parapet wall has limestone coping.				
On the west elevation are two oriel resting on pro-	1			
jecting joists with shed roofs and exposed rafter ends	<b>s</b>  .			
jecting joists with shed roofs and exposed rafter ends. The gable has stucco face and exposed projecting purlins.	<b>.</b>			
The gable has stucco face and exposed projecting purlins.		site nlan		9
jecting joists with shed roofs and exposed rafter ends The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings		site plan		9)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings		site plan		9)
The gable has stucco face and exposed projecting purlins.		site plan		9)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings		site plan		9)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings		site plan		9)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings		site plan		
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings	23)	site plan		9) 5)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources	23)	· · · · · · · · · · · · · · · · · · ·		
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.	23)	changes -	Ashestos sidina	
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources	23)	changes - additions/alter- ations/moved	Asbestos siding	
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources	24)	changes - additions/alter- ations/moved condition	Good	
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources	23) 24) 25) 26)	changes - additions/alter- ations/moved condition visible from road?	Good -	
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road? distance/frontage	Good	5)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources  City Directory 1911-1933.	23) 24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	Good -	
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources  City Directory 1911-1933.	23) 24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	Good - - -	5)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources  City Directory 1911-1933.	23) 24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	Good - - - - Yes	5)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources  City Directory 1911-1933.	23) 24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	Good - - -	5)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources  City Directory 1911-1933.	23) 24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	Good - - - - Yes	5)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources  City Directory 1911-1933.  48) Location of negatives Roll 547-12 #4-5  49) Prepared by DDD	23) 24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	Good Yes No	5) 6)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources  City Directory 1911-1933.	23) 24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	Good - - - - Yes	5)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources  City Directory 1911-1933.  48) Location of negatives Roll 547-12 #4-5  49) Prepared by DDD	23) 24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	Good Yes No	5) 6)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources  City Directory 1911-1933.  48) Location of negatives Roll 547-12 #4-5  49) Prepared by DDD	23) 24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	Good Yes No	5) 6)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources  City Directory 1911-1933.  48) Location of negatives Roll 547-12 #4-5  49) Prepared by DDD  50) Organization Missouri Heritage Trust	23) 24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	Good Yes No No	5) 6)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources  City Directory 1911-1933.  48) Location of negatives Roll 547-12 #4-5  49) Prepared by DDD	23) 24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	Good Yes No No	5) 6)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources  City Directory 1911-1933.  48) Location of negatives Roll 547-12 #4-5  49) Prepared by DDD  50) Organization Missouri Heritage Trust	23) 24) 25) 26) 27) 28) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	Good  Yes No No No	5) 6)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources  City Directory 1911-1933.  48) Location of negatives Roll 547-12 #4-5  49) Prepared by DDD  50) Organization Missouri Heritage Trust	23) 24) 25) 26) 27) 28) 29) 30) 31) 32) 34,	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	Good	5) 6) 7)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources  City Directory 1911-1933.  48) Location of negatives Roll 547-12 #4-5  49) Prepared by DDD  50) Organization Missouri Heritage Trust	23) 24) 25) 26) 27) 28) 29) 30) 31) 32) 34, 35,	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	Good	5) 6)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources  City Directory 1911-1933.  48) Location of negatives Roll 547-12 #4-5  49) Prepared by DDD  50) Organization Missouri Heritage Trust	23) 24) 25) 26) 27) 28) 29) 31) 32) 33, 34, 35, 36,	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	Good	5) 6) 7)
The gable has stucco face and exposed projecting purlins.  46) Description of environment/outbuildings  Behind the house is a one bay gable garage.  47) Information sources  City Directory 1911-1933.  48) Location of negatives Roll 547-12 #4-5  49) Prepared by DDD  50) Organization Missouri Heritage Trust	23) 24) 25) 26) 27) 28) 29) 31) 32) 33, 34, 35, 36,	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	Good	5) 6) 7)

31




Go energy A



Missouri Historic Architectural Inventory for GRAD 057-69

	Division of Parks and Historic Preservation Dep.	artment of Natura	al Resources
38) Ownership — private		1) inventory number	
— public		2) name (cont)	
39) Owners — name	Eleanor M. O'Day	3) name historial	E
address	531 E. Walnut	4) street address	1531 \$. Walnut
40) Local contact		5) town or vicinity	Springfield
41) Coordinates (UT	M1:	6) legal description	Frisco Heights Add. Blo
42) Quad		7) county	Greene 9 Lot 9
43) Other survey		8) category	dreene 9 Lot 9
		(site, structure,	Puilding
		building, object)	Building
44) History	The state of the second control of the secon	9) significance	Anabitastus 1 Cantaibut
•		10) date	Architectural-Contribut
		11) style	ca. 1920
		12) architect	Bunga low
		13) builder	
		14) original use	Marie 1960 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
		15) present use	Residence
45) Additional description	TO THE THE PROPERTY OF THE PRO	16) number of stories	Residence
49) Additional description		1	1
المستامة فيامانية	As best example of its type. There is	17) plan shape	Square
-	on the porch gable roof. The face of the	1	Full
	ured stucco with a centered window with a		Concrete
***	ith corner muntins. All window openings	20) wall construction	Brick Veneer
	sh like that described above. There are	21) roof type -	Gable
	ns in the gable with a wide entablature	material	Asphalt Shingle
	square tapering wooden columns which are	22) contact print	
	at. There are limestone plinths resting	35mm	
on square bri	ck pillars. On the right of the facade		
is an open po	rch area with a parapet which is contin-		
uous on the w	hole porch with limestone coping. The		
<pre>     steps are cor</pre>	crete with brick flanking walls and lime-		
stone coping.	The facade is three bay with sidelights		
flanking the	entry. The door and sidelight surround i	S	
	nment/outbuildings in finished oak woodwork.	23) site plan	
On the east a	nd west elevations are small boston hippe	d	
dormers.			
	use is a one bay frame garage which may		
be original.			
00 01 1 g 1 1 to 1			1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
47) Information sources		24) changes	
		additions/alter-	Al
		ations/moved	None
		25) condition	
		26) visible from road?	Good
		27) distance/frontage	
		28) accessible?	
AQ) Location of access		29) preservation	
48) Location of negative	Roll 5 #10	· •	
40) Barrer (1)		underway?	No.
49) Prepared by	DED	30) endangered?	No.
	<del></del>	31) on National	No
50) Organization	Missouri Heritage Trust.	Register?	iVo.
	in sood i het rouge it uso.	32) part of	
		established	Mo
		historical district	
If additional space is need	led artsched separate sheets	33) name of historical	1
		district	Vac
		34) is site eligible?	Yes
		35) district potential?	
		36) date	Feb. 7, 1984
		37) revision	
			1



NA

Ch no was by



### Missouri Historic Architectural Inventory for Grand Control of Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private x	1) i	nventory number	112	Ξ
public	2) r	name (cont)		1
39) Owners — name H. W. Stoneman	3) r	name - historial	F	1
— address 1538 E. Walnut	4) 9	street address	1538 %. Walnut	
40) Local contact	5) t	own or vicinity	Springfield	1
41) Coordinates (UTM)	6) 1	egal description	Arlington Heights Add.	1
42) Quad	1	county	Greene Lot A	1
43) Other survey		category	dreeneLOUA	N
43) Other survey	ı	site, structure,		2/3)
	ı	ouilding, object)	Double and the second	
AN DE-L-		significance	Building	-
44) History	10)	- [	Architectural	-
			Post 1933 ca. 1938	4
	11) 9	,	<u>Colonial Revival</u>	_
	1	architect		-
		builder		_
		original use	Residence	
		present use	<u>Residence</u>	
45) Additional description The compiles frainze acts as window heads	1	number of stories	2	<b>4</b>
The cornice frieze acts as window heads	1 '	plan shape	Rectangle	
to the second story window openings in the three bay	18)	basement	Full	
facade. The windows have eight over one window sash.	19) 1	foundation	Concrete	1
At the first and third bays on the second story level	20)	wall construction	Brick Veneer	1
there are small wrought iron projecting porches. The	21)	roof type -	Gable/Asphalt Shingle	1
center bay has a door with flanking window openings		material		1
giving onto the flat roof of the porch which has a	22)	contact print		5
wrought iron railing. The porch has a moulded cornice		35mm		
on an elliptical shape with round wood columns with				
Tuscan capitals. The entryway has an elliptical transom				
and there are sidelights with leaded glass flanking the	ļ			
doorway. The window openings at the first story level				
are tripled with flat arch lintles with keystone.				
On the west elevation tripled square pillars support				
an open borch. On the east elevation is a port cochere 46) Description of environment/outbuildings	221	site plan		وا
46) Description of environment/outbuildings	23)	Site plan		
B 1 2 1 2 1 1 2 1 2 1 2 1 2 1 2 1 2 1 2	l l			
Behind the house is a two-story outbuilding with brick				
veneer two bay garage with quarters above. The second				
story of the wing is an open porch area under the roof.				
47) Information sources	1	<del></del>		150
• • • • • • • • • • • • • • • • • • • •		changes -		5
		additions/alter-		5
City Directory 1933		_	none visible	5)
		additions/alter-		5)
	25)	additions/alter- ations/moved	none visible good	5)
	25) 26)	additions/alter- ations/moved condition	good	5)
	25) 26) 27)	additions/alter- ations/moved condition visible from road?	good -	5) 6)
City Directory 1933	25) 26) 27) 28)	additions/alter- ations/moved condition visible from road? distance/frontage	good -	
	25) 26) 27) 28)	additions/alter- ations/moved condition visible from road? distance/frontage accessible?	good - - -	
City Directory 1933  48) Location of negatives  Roll 547-12 #10-11	25) 26) 27) 28) 29)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	good    No	
City Directory 1933  48) Location of negatives	25) 26) 27) 28) 29)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	good - - -	
City Directory 1933  48) Location of negatives Roll 547-12 #10-11  49) Prepared by DDD	25) 26) 27) 28) 29)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National		6)
City Directory 1933  48) Location of negatives  Roll 547-12 #10-11	25) 26) 27) 28) 29) 30) 31)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	good    No	
City Directory 1933  48) Location of negatives Roll 547-12 #10-11  49) Prepared by DDD	25) 26) 27) 28) 29) 30) 31)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of		6)
City Directory 1933  48) Location of negatives Roll 547-12 #10-11  49) Prepared by DDD	25) 26) 27) 28) 29) 30) 31)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established		6)
City Directory 1933  48) Location of negatives Roll 547-12 #10-11  49) Prepared by DDD  50) Organization Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31) 32)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	good	6)
City Directory 1933  48) Location of negatives Roll 547-12 #10-11  49) Prepared by DDD	25) 26) 27) 28) 29) 30) 31) 32)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	good	6)
City Directory 1933  48) Location of negatives Roll 547-12 #10-11  49) Prepared by DDD  50) Organization Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31) 32)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	good	6)
City Directory 1933  48) Location of negatives Roll 547-12 #10-11  49) Prepared by DDD  50) Organization Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31) 32) 33)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	good No No No No Yes	6) 7)
City Directory 1933  48) Location of negatives Roll 547-12 #10-11  49) Prepared by DDD  50) Organization Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	good No No No No Ves Yes	6)
City Directory 1933  48) Location of negatives Roll 547-12 #10-11  49) Prepared by DDD  50) Organization Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35) 36)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	good No No No No Yes	6) 7)
City Directory 1933  48) Location of negatives Roll 547-12 #10-11  49) Prepared by DDD  50) Organization Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35) 36)	additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	good No No No No Ves Yes	6) 7)


1538 E. Walnut


with a pedimented gable with a stucco face in which is decorative plaster work. Triple square brick pilasters support the roof.

East gable - heavy cornice returns with hemispherical window fan light in the gable attic story.

GRAGE NOR 711

 $S \uparrow \uparrow$ 






CO & W.Z. 711



#### Missouri Historic Architectural Inventory for Galactic Preservation Department of Natural Resources

	_			
38) Ownership — private $\chi$	1) inventory n	umber	96	]=
public	2) name (cont)	) [		
39) Owners — name Francis Ferguson	3) name - histo	orial 🗍		]
address 1603 E. Walnut	4) street addre	ess	1603 E. Walnut	
40) Local contact	5) town or vici	inity 🗍	Springfield	]
41) Coordinates (UTM)	6) legal descri	iption 🗌	Bigbee's Add. Lot 16	1
42) Quad	7) county		Greene	1
43) Other survey	8) category		UI EEIIC	2/3)
	(site, struct	ture,		3)
	building, ob	oject)	Building	
44) History Built by E. P. Mann, Attorney 1916-1917	9) significance		Architectural-Contribu	1
	10) date	<u> </u>	1916-1917	LIN
	11) style	H	Bungalow	1
	12) architect	<u> </u>	Bungarow	1
	13) builder	-		1
	14) original use	e h	Residence	1
	15) present use		Residence	┪
45) Additional description _	16)	-4:	1	4
Front elevation- shed roof dormer on the	17) plan shape	-	Rectangle	┤
roof face with low pitch and broad overhanging eaves with	18) basement	-	Full	-
acomes bases. In the face of the desman is a window	19) foundation		Concrete	┨
light with fixed sash (see drawing).	20) wall constr		Frame/Steel Siding	4
All windows on the house have upper sash like that above.	21) roof type -	-		┥
The facade is three bay. The porch is continuous roof	material	-	Gable Asphalt shingle	4
line with the main house mass supported by square taper-	22) contact pri	nt	Asphalt shingle	5
ing wooden posts resting on red brick pillars. The porch	35mm	***		
has a simple wooden balustrade with square balusters.	3311111			
The porch floor and structure are of wood. The gables				
have five knee braces under the eaves.				1
				l l
	23) site plan			9
46) Description of environment/outbuildings	23) site plan			9)
	23) site plan	· .		9)
Behind the house is a two-story frame garage with resi-	23) site plan	- - - -		9)
Behind the house is a two-story frame garage with residence above which is all original with the same upper	23) site plan	:		9)
Behind the house is a two-story frame garage with resi-	23) site plan			9)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.				
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources	24) changes -			5)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.	24) changes - additions/a		Addition to east eleva	5)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources	24) changes - additions/a ations/mov		Addition to east eleva tion. Steel Siding	5)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources	24) changes - additions/a ations/mov 25) condition	ved	Addition to east eleva	5)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources	24) changes - additions/a ations/mov 25) condition 26) visible from	ved m road?	Addition to east eleva tion. Steel Siding	5)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources	24) changes - additions/a ations/mov 25) condition 26) visible from 27) distance/fr	wed m road? rontage	Addition to east eleva tion. Steel Siding	5)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources	24) changes - additions/a ations/mov 25) condition 26) visible from 27) distance/from 28) accessible	m road? rontage	Addition to east eleva tion. Steel Siding Good	5)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources  City Directory 1915-1933	24) changes - additions/a ations/mov 25) condition 26) visible from 27) distance/from 28) accessible 29) preservation	m road? rontage e? on	Addition to east eleva tion. Steel Siding Good	5)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources  City Directory 1915-1933	24) changes - additions/a ations/mov 25) condition 26) visible from 27) distance/fr 28) accessible 29) preservation underway?	m road? rontage e? on	Addition to east eleva tion. Steel Siding Good 	5)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources  City Directory 1915-1933	24) changes - additions/a ations/mov 25) condition 26) visible from 27) distance/from 28) accessible 29) preservation underway? 30) endangere	m road? rontage e? on ?	Addition to east eleva tion. Steel Siding Good	5)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources  City Directory 1915-1933  48) Location of negatives Roll 5 #17 Roll 547-12 #12-13	24) changes - additions/a ations/move 25) condition 26) visible from 27) distance/from 28) accessible 29) preservation underway? 30) endangere 31) on National	m road? rontage e? on ?	Addition to east eleva tion. Steel Siding Good 	5)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources  City Directory 1915-1933  48) Location of negatives Roll 5 #17 Roll 547-12 #12-13	24) changes - additions/a ations/mov 25) condition 26) visible from 27) distance/fr 28) accessible 29) preservation underway? 30) endangere 31) on National Register?	m road? rontage e? on ?	Addition to east eleva tion. Steel Siding Good 	5)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources  City Directory 1915-1933  48) Location of negatives Roll 5 #17 Roll 547-12 #12-13 DDD	24) changes - additions/a ations/mov 25) condition 26) visible fror 27) distance/fr 28) accessible 29) preservation underway? 30) endangere 31) on Nationa Register? 32) part of	m road? rontage e? on ? ed?	Addition to east eleva tion. Steel Siding Good 	5)   6)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources  City Directory 1915-1933  48) Location of negatives Roll 5 #17 Roll 547-12 #12-13 DDD	24) changes - additions/a ations/mov 25) condition 26) visible from 27) distance/fr 28) accessible 29) preservation underway? 30) endangere 31) on National Register? 32) part of establishe	m road? rontage e? on ? ed? al	Addition to east eleva tion. Steel Siding Good	5)   6)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources  City Directory 1915-1933  48) Location of negatives Roll 5 #17 Roll 547-12 #12-13 DDD	24) changes - additions/a ations/mov 25) condition 26) visible from 27) distance/fr 28) accessible 29) preservation underway? 30) endangere 31) on National Register? 32) part of established historical	m road? rontage e? on ? ed? al	Addition to east eleva tion. Steel Siding Good 	5)   6)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources  City Directory 1915-1933  48) Location of negatives Roll 5 #17 Roll 547-12 #12-13 DDD	24) changes - additions/a ations/mov 25) condition 26) visible from 27) distance/from 28) accessible 29) preservation underway? 30) endangere 31) on National Register? 32) part of established historical 33) name of his	m road? rontage e? on ? ed? al	Addition to east eleva tion. Steel Siding Good	5)   6)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources  City Directory 1915-1933  All 5 #17  Roll 5 #17  Roll 547-12 #12-13  DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/s ations/mov 25) condition 26) visible from 27) distance/fr 28) accessible 29) preservation underway? 30) endangere 31) on National Register? 32) part of established historical 33) name of his district	m road? rontage e? on ? ed? al ed district istorical	Addition to east eleva tion. Steel Siding Good	5)   6)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources  City Directory 1915-1933  All 5 #17  Roll 5 #17  Roll 547-12 #12-13  DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/a ations/move 25) condition 26) visible from 27) distance/from 28) accessible 29) preservation underway? 30) endangere 31) on National Register? 32) part of established historical 33) name of his district 34) is site elig	m road? rontage e? on ? ed? al district istorical	Addition to east eleva tion. Steel Siding Good	5) 6) 7)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources  City Directory 1915-1933  All 5 #17  Roll 5 #17  Roll 547-12 #12-13  DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/a ations/mov 25) condition 26) visible fror 27) distance/fr 28) accessible 29) preservation underway? 30) endangere 31) on Nationa Register? 32) part of establishe historical 33) name of hid district 34) is site elig 35) district po	m road? rontage e? on ? ed? al district istorical	Addition to east eleva tion. Steel Siding Good	5)   6)
Behind the house is a two-story frame garage with residence above which is all original with the same upper sash as in house. There is only one garage bay with storage space.  47) Information sources  City Directory 1915-1933  All 5 #17  Roll 5 #17  Roll 547-12 #12-13  DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/a ations/move 25) condition 26) visible from 27) distance/from 28) accessible 29) preservation underway? 30) endangere 31) on National Register? 32) part of established historical 33) name of his district 34) is site elig	m road? rontage e? on ? ed? al district istorical	Addition to east eleva tion. Steel Siding Good	5) 6) 7)






CB 18 22 101



### Missouri Historic Architectural Inventory for Company Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private X	1) inventory	1 31	] <u>=</u>
public	2) name (con	t)	_]
39) Owners—name Francis Gentry	3) name - his	torial	
— address 1611 E. Walnut	4) street add	TOTTE - Waltiut	
~ 40) Local contact	5) town or vid	cinity Springfield	
41) Coordinates (UTM)	6) legal desc		
42) Quad	7) county	Greene	
43) Other survey	8) category		2/3)
	(site, struc	cture,	3)
	building, o		
44) History	9) significan	ce Contributing	
Built by F. C. Mann - Attorney -	10) date	1916-1917	
1916-1917	11) style	Catalogue/Builder wit	- h
	12) architect	classical det	
	13) builder	C18331CW1 WC1	ш 13
	14) original us	se Residence	7
	15) present us	Residence	_
45) Additional description _	16) number of	stories 2	4
45) Additional description Front elevation - hipped roof dormer	17) plan shape	<del> </del>	
with sprayed warrs two window openings with multi-paned	18) basement	l Necturite	$\neg$
light sash. The eaves project and the cornice frieze	19) foundatio		
is the window head to the second story window openings	20) wall const	ruction Frame/Steel Siding	-
which have twelve over one light sash. The first story	21) roof type	I raille/Steel Stallia	$\dashv$
window openings have applied moulding on the window	material	Asphalt shingle	-
heads and have 18 over 18 window light sash. The porch	22) contact pr	rint	5
extends across the entire facade and has a hipped roof.	35mm		
The porch is supported by tapering square wooden columns			Ì
The balustrade is of wood with square baluster. The	}		
porch floor and structure are of wood. On the west	(		
elevation there is a one-story bay window with a hipped			}
roof.	1		
46) Description of environment/outbuildings	23) site plan		9
TO Description of entironmental authorities	[		
	1		-
Behind the house is a one-story hipped roof outbuilding			
with a one bay garage opening.	}		
		e e	
47) Information sources	24) changes -		<del></del>
• • • • • • • • • • • • • • • • • • • •	additions	l l	-
City Directory 1916-1919	ations/mo	C+col Cidina	
	25) condition		
	26) visible from	'	$\overline{}$
	27) distance/		
	28) accessib		
40) L	29) preservat		
48) Location of negatives Roll 547-12 #14-15	underwa	J NI =	
40) 0	30) endanger		_
49) Prepared by DDD	31) on Nation	NU	$\rightarrow$
	Register		
50) Organization Missouri Heritage Trust	32) part of	NO	
	establish	ned	
	_	I district NO	
,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,,	33) name of		-
If additional space is needed, attached separate sheets.	Haine Ut		
	district		1
	district	igible?	
	34) is site el		<u>ω</u>
	34) is site el	ootential? Yes	30)
	34) is site el		30)




NA

Λ



## Missouri Historic Architectural Inventory for Colored To To Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private X	1) inventory number	98	]=
— public	2) name (cont)		
39) Owners — name , Mace	3) name - historial		
— address	4) street address	1619 E. Walnut	
40) Local contact	5) town or vicinity	Springfield	4
41) Coordinates (UTM)	6) legal description	Bigbee's Add. Lot 18	4
42) Quad	7) county	Greene	4
43) Other survey	8) category		2/3)
	(site, structure,	Building	
	building, object)		4
44) History	9) significance 10) date	Contributing	4
		ca. 1910	4
	11) style 12) architect	Catalogue/Builder with	
	13) builder	classical deta	ali Is
	· ·		4
	<ul><li>14) original use</li><li>15) present use</li></ul>	Residence	-
AFX ALLIES AND AND AND AND AND AND AND AND AND AND	16) number of stories	Residence	4
45) Additional description Three bay facade with vertical divided	17) plan shape	2	<b>=</b> ا
muntil upper sash. The porch covers the facade and has	18) basement	Rectangle	_
a gable roof. The roof is supported by square wood	19) foundation	<u>Full</u>	4
tapering posts. The pillars and parapet on the porch	20) wall construction	Concrete	_
are plastered brick with limestone coping. Side ele-	21) roof type -	Frame/Steel siding	4
vations - cornice returns in the gables. On the east	material	Gable	-
side is a two story sun parlor with gable roof and cor-	22) contact print	Asphalt shingle	5
nice returns.	35mm		
46) Description of environment/outbuildings	23) site plan		9)
46) Description of environment/outbuildings	23) site plan		9)
46) Description of environment/outbuildings	23) site plan		
46) Description of environment/outbuildings	23) site plan		
46) Description of environment/outbuildings  47) Information sources	23) site plan  24) changes	the second secon	
		the second secon	
	24) changes - additions/alter-	Steel siding added	
	24) changes - additions/alter- ations/moved		
	24) changes - additions/alter-ations/moved 25) condition	Steel siding added	5)
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	Steel siding added	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	Steel siding added	5)
47) Information sources  48) Location of negatives  Roll 547-12 #16-17	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	Steel siding added	5)
47) Information sources  48) Location of negatives  Roll 547-12 #16-17	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	Steel siding added Good	5)
47) Information sources  48) Location of negatives Roll 547-12 #16-17  49) Prepared by DDD	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	Steel siding added Good	5)
47) Information sources  48) Location of negatives Roll 547-12 #16-17  49) Prepared by DDD  50) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	Steel siding added Good	5)
47) Information sources  48) Location of negatives Roll 547-12 #16-17  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	Steel siding added Good	5) 6)
47) Information sources  48) Location of negatives Roll 547-12 #16-17  49) Prepared by DDD  50) Organization	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	Steel siding added  Good  No No	5) 6)
47) Information sources  48) Location of negatives Roll 547-12 #16-17  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	Steel siding added Good No No	5) 6)
47) Information sources  48) Location of negatives Roll 547-12 #16-17  49) Prepared by DDD  50) Organization	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	Steel siding added Good No No	5) 6)
47) Information sources  48) Location of negatives Roll 547-12 #16-17  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	Steel siding added  Good  No No No	5) 6)
47) Information sources  48) Location of negatives Roll 547-12 #16-17  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	Steel siding added  Good  No No No No Yes	5) 6) 7)
47) Information sources  48) Location of negatives Roll 547-12 #16-17  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	Steel siding added  Good  No No No No Yes	5) 6)




GR-45.00= 703



# Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources

	7, .			
38) Ownership — private X		nventory number		E
— public		name (cont)		
39) Owners — name Paul Mueller	3) 1	name - historial		
— address 1622 E. Walnut	4) 9	street address	1622 E. Walnut	
40) Local contact	5) 1	town or vicinity	Springfield	l
41) Coordinates (UTM)	6) i	egal description	East Elm St. Add. Lots	l
42) Quad	7) (	county	Greene A-D	1
43) Other survey	8) (	category		N
	(	(site, structure,		2/3)
	1	building, object)	Building	1
44) History Ruilt 1026-1027 by Dr. Gustavus Moyon		significance	Architectural-Commerce	
but it 1920-1927 by bi. dustavus neger,	10)	- L	1926-1927	l
PNVS1C1an		style		1
		· .	Catalogue/Builder with	
,	-	architect	bungalow and Tudor Re-	Ĭ
		builder	vival elements	1
		original use	Residence	1
	-	present use	Residence	
45) Additional description Front gable - three brackets are set	16)	number of stories	1-1/2	4
under the eaves of the gable which appear as projecting	17)	plan shape	Irregular	
purlins. The face of the gable is covered with stucco	18)	basement	Full	
material and half timbering. There are few ground	19)	foundation	Concrete	1
material and half timbering. There are four grouped	20)	wall construction	Brick Veneer	1
windows with six over one light sash. The first story	21)	roof type -	Gable	1
is three bay with the first and third bays tripled with		material		1
six over one center opening and four over one flanking	22)	contact print	Red Clay Ceramic Tile	5
opening window sash. The openings have flat arch lin-		35mm		
tels and limestone sills. The porch extends across most				
of the facade with a hipped roof plan. The porch is				
supported on brick columns with limestone capitals. The				
corner columns have a splayed shape. There is a low				1
parapet wall on the porch with limestone coping. The				1
east and west gables each have one story projecting				
				ļ
Wings within the gable which in turn have gable roofs.  46) Description of environment/outbuildings	23)	site plan	ej i sa	9
			and the second of the second of	ļ
Behind the house is a one-story two bay garage brick over				
tile with gable roof matching the main house.				
			garanta da seria da seria de la competita de la competita de la competita de la competita de la competita de l La competita de la competita de la competita de la competita de la competita de la competita de la competita d	
47) Information sources	24)	changes -		5
City Directory 1925-1933		additions/alter-		
31 dy 21 de 2001 y 1320 1300		ations/moved		
	25)	condition	None	1
		visible from road?	-Good	-
	'			-
	1 1	distance/frontage	-	0
	,	accessible?		اعت
48) Location of negatives Roll 547-12 #18-19	29)	preservation		
Roll 5 & 18	1	underway?	No	_
49) Prepared by DDD	30)	endangered?	No	_
	31)	on National		
50) Organization Missouri Heritage Trust		Register?	No No	7
- missouri neritage itust			110	
	32)	part of		1
	32)	established		
	32)	•	No	
If additional space is needed, attached separate sheets.		established		-
If additional space is needed, attached separate sheets.		established historical district		
If additional space is needed, attached separate sheets.	33)	established historical district name of historical	-	_
If additional space is needed, attached separate sheets.	33)	established historical district name of historical district is site eligible?	Yes	30
If additional space is needed, attached separate sheets.	33) 34) 35)	established historical district name of historical district	Yes Yes	30)
If additional space is needed, attached separate sheets.	33) 34) 35) 36)	established historical district name of historical district is site eligible? district potential?	Yes	30)



S



### Missouri Historic Architectural Inventory for Glace Color Co

38) Ownership — private X	I '	inventory number name (cont)	99	۳
— public  39) Owners — name — Dr. Urban Rusiek	l i			
DI. UIDAN BUSIEK	1	name - historial street address	1605 F 161m 4	
—address 1635 E. Walnut  (40) Local contact		town or vicinity	1635 E. Walnut	
41) Coordinates (UTM)	1	legal description	Springfield Bigbee's Add. Lot 18	
42) Quad	1	county	Greene	ì
43) Other survey		category	di eelle	N
(a) Called Gallets,	-′	(site, structure,	  Building	2/3)
	l	building, object)	barraring	
44) History	9)	significance	Architectural-Social	1
Built 1909-1910 by Edward Tucker, Pres.		date	1909-1910	1
of Tucker-Ferguson Warehouse Co. Purchased in late 1920s	11)	style	Four Square Catalogue/	1
by Dr. Urban Busiek who still lives in house.	12)	architect	Builder	1
	13)	builder	<u> </u>	1
	14)	original use	Residence	
	15)	present use	Residence	1
45) Additional description Front elevation-Boston dormer with bell	16)	number of stories	2	4
cast hip roof. Triple window with center opening larger	17)	plan shape	Square	
than those flanking and one over one sash. The window	18)	basement	Full	
surround is pilastered. The eaves on the main house mass	19)	foundation	Cast Stone Rough, faced	1
project broadly and the cornice frieze acts as window	1 '	wall construction	coursed,ashlar	
head to the second story window openings. There is one	21)	roof type -	Frame/lap siding	
over one sash through out the house. Three bay facade		material	Bell cast hip asphalt	
with center door entrance with flanking windows on the	22)	contact print	shingle	5)
second story. Above the entry area on the hipped roof		35mm		
porch is a flat roof area with a wooden balustrade. On				
the first story window and door openings there is applied				
moulding to the heads. The entry has sidelights and tran-	+			
som with leaded glass. The porch is supported by				
round wooden columns with Tuscan capitals. The porch				
pillars supporting the columns are square cast stone roug 46) Description of environment/outbuildings	)   	site plan		9
	23)	Site plan		۳
To the rear of the property is a one-story multi-bay				
garage with shed roof and cast stone ashlar laid walls.				
There is a square building with a bell cast roof and lap				
siding with splayed walls which may have been original to the house and used as a well house covering (?).			and the second of the second o	
47) Information sources	24)	changes -		5
City Directory 1908-1933		additions/alter-		
		ations/moved	None	1
	25)	condition	Good	†
	26)	visible from road?	_	1
	27)	distance/frontage		1
	28)	accessible?	_	9
48) Location of negatives Roll 5 #14-16	29)	preservation		1
Roll 547-12 #20-21		underway?	No	
49) Prepared by DDD	30)	endangered?	No	
	(31)	on National		7
50) Organization Missouri Heritage Trust		Register?	No	7
11,000 and 11,000 and				-
	32)	part of		
	32)	establish <b>ed</b>		
		established historical district	No	
If additional space is needed, attached separate sheets.		established historical district name of historical	Nσ	
If additional space is needed, attached separate sheets.	33)	established historical district name of historical district	-	
If additional space is needed, attached separate sheets.	33)	established historical district name of historical district is site eligible?	Yes	3
If additional space is needed, attached separate sheets.	33) 34) 35)	established historical district name of historical district is site eligible? district potential?	Yes Yes	30)
If additional space is needed, attached separate sheets.	33) 34) 35) 36)	established historical district name of historical district is site eligible?	Yes	30)


faced ashlar. The balustrade has a moulded handrail and turned balusters.

meporch foundation is of random ashlar cast stone and the porch floor and structure are of wood.

On the west elevation is a port cochere continuous with the porch with a pedimented gable with stucco face with a plaster design motif applied. The cornice is continuous. On the east elevation is a two story sun parlor with second story openings with twelve over one sash on the first story. This could be a later addition.

0 2 00 6 -2 -235


1630 a Walnut



C-R-AS-003-765



1) inventory number 110 38) Ownership - private ۳ 2) name (cont) — public Marie Coulter 3) name - historial 39) Owners - name 1638 E. Walnut 1638 E. Walnut 4) street address --- address 5) town or vicinity Springfield 40) Local contact East Elm St. Add. Lot D 6) legal description 41) Coordinates (UTM) 7) county Pt. E Greene 42) Quad 8) category 43) Other survey 2/3 (site, structure, building, object) Building 9) significance 44) History Architectural-Commerce Built 1923-1924 by J. F. Legan, Sec.-10) date 1923=1924 Treas, of Williams Lumber Co. 11) style Spanish Mission Revival 12) architect 13) builder 14) original use Residence 15) present use Residence 16) number of stories 45) Additional description A low parapet wall surrounds the roof 17) plan shape Square with concrete coping. The facade is three bay with pent 18) basement Unknown roofs above the window openings. The roofs are of green 19 foundation Unknown clay tile and have modillions under the eaves of the pent20) wall construction Stucco over tile (?) roof. The window openings are tripled with fixed sash 21) roof type -Flat transoms and vertically divided muntins in the upper material The center opening is larger than those flanking. 22 contact print <u>U</u> The entryway has sidelights flanking it with multipaned 35mm lights. There is a round portico with a flat roof and a wooden balustrade above with turned balsters. There are modillions under the porch eaves. The porch is supported by round wooden columns with fluted shafts and Tuscan capitals. On the east elevation is a porte cochere which was originally open with exposed joists since 46) Description of environment/outbuildings support columns which mate23) site plan those on the porch. Behind the house is a two bay garage with stucco walls dand a flat roof. 5 24) changes -47) Information sources Port Cochere altered additions/alter-City Directory 1922-1923. ations/moved 25) condition Good 26) visible from road? 27) distance/frontage 6 28) accessible? 29) preservation 48) Location of negatives Roll 547-13 #1-2 N'2 underway? 30) endangered? 49) Prepared by DD Νο 31) on National Register? 50) Organization No Missouri Heritage Trust 32) part of established historical district Nο 33) name of historical If additional space is needed, attached separate sheets district Yes 34) is site eligible? 30 35) district potential? Yes 36) date Jan. 30, 1984 37) revision



51

Conscionate L




#### Missouri Historic Architectural Inventory for ( )

38) Ownership — private X	1) inventory number   100	:
— public	2) name (cont)	
39) Owners — name lowell Millon	3) name - historial	
Lowert Miller	4) street address 1647 E. Walnut	
— address 1647 E. Walnut	5) town or vicinity Springfield	
41) Coordinates (UTM)	6) legal description Bigbee's Add. Lot 20	
42) Quad	7) county Greene	
43) Other survey	8) category	2/3)
	(site, structure, Building	ع ا
	building, object)	
44) History	9) significance Contributing	
•	10) date 1916-1917	
Built 1916-1917 by J. R. Ferguson Jr.,		
Mgr. of J. R. Ferguson Furniture Co.	11) style Four Square 12) architect	
	13) builder	
	14) original use Residence	
	15) presentuse Residence	
45) Additional description Projecting eaves with cornice frieze	16) number of stories 2	4
projecting eaves with cornice trieze	17) plan shape Square	
as window nead to the second story window openings. Two	18) basement Full	
bay facade with eight over eight window light sash. On	19) foundation Concrete?	$\neg$
the side elevations the window lights are one over one.	20) wall construction Frame/lap siding	
The hipped roof porch covers the entire facade and is		
supported with fluted square tapering wood columns. The	.   <u> </u>	
balustrade is of wood with wood floor, structure, and	asphart shingle	5
the steps to the porch.	22) contact print 35mm	۳
·	Somm	
46) Description of environment/outbuildings	23) site plan	9
46) Description of environment/outbuildings	23) site plan	9
46) Description of environment/outbuildings	23) site plan	9)
46) Description of environment/outbuildings	23) site plan	9)
46) Description of environment/outbuildings		9)
46) Description of environment/outbuildings	23) site plan	9)
46) Description of environment/outbuildings  47) Information sources City Directory 1915-1933.	24) changes -	9) 5)
	24) changes - additions/alter-	
	24) changes - additions/alter- ations/moved	
	24) changes - additions/alter-	
	24) changes - additions/alter- ations/moved	
	24) changes - additions/alter- ations/moved 25) condition  Good	
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	
47) Information sources City Directory 1915-1933.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	5)
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	5)
47) Information sources City Directory 1915-1933.  48) Location of negatives Roll 547-13 #3-4	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? No	5)
47) Information sources City Directory 1915-1933.	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? No	5)
47) Information sources City Directory 1915-1933.  48) Location of negatives Roll 547-13 #3-4  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	5)
47) Information sources City Directory 1915-1933.  48) Location of negatives Roll 547-13 #3-4	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No	5)
47) Information sources City Directory 1915-1933.  48) Location of negatives Roll 547-13 #3-4  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of	5)
47) Information sources City Directory 1915-1933.  48) Location of negatives Roll 547-13 #3-4  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established No	5)
47) Information sources City Directory 1915-1933.  48) Location of negatives Roll 547-13 #3-4  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	5)
47) Information sources City Directory 1915-1933.  48) Location of negatives Roll 547-13 #3-4  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established No	5)
47) Information sources City Directory 1915-1933.  48) Location of negatives Roll 547-13 #3-4  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	5)
47) Information sources City Directory 1915-1933.  48) Location of negatives Roll 547-13 #3-4  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is sit at light 2	5) 6) 7)
47) Information sources City Directory 1915-1933.  48) Location of negatives Roll 547-13 #3-4  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	5)
47) Information sources City Directory 1915-1933.  48) Location of negatives Roll 547-13 #3-4  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	5) 6) 7)
47) Information sources City Directory 1915-1933.  48) Location of negatives Roll 547-13 #3-4  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?  Yes	5) 6) 7)

1647 E ( raturet

.






### Missouri Historic Architectural Inventory for Communication of Parks and Historic Preservation Department of Natural Resources

· · · · · · · · · · · · · · · · · · ·	\ ^′	inventory number	<u> </u>	]=
— public	2)	name (cont)		]
39) Owners — name Larry Dixon	3)	name - historial	<del></del>	1
address 1648 E. Walnut	1 4)	street address	1648 E. Walnut	1
40) Local contact	1 .	town or vicinity		1
	1	, i	Springfield	-
41) Coordinates (U™M)	1	legal description	East Elm St. Add. Lots	
42) Quad		county	Greene F & G	
43) Other survey	8)	category		2/3)
		(site, structure,	Building	۳ ا
		building, object)	3	[
44) History	9)	significance	Architectural-Contribu	tin
77, 110001	1	date		10 111
		style	ca. 1905	-
	1	•	Catalogue/Builder	4
	1	architect		_
	1	builder		
	14)	original use	Residence	
	15)	present use	Residence	
45) Additional description	16)	number of stories	2	4
Front elevation - Hip dormer on the	17)	plan shape	Square	┪ ̄
front roof face with broad projecting eaves and a stucco		basement	Full	-
face. Projecting eaves on the main house mass. Three		foundation		-
bay facade with one over one light window sash. Each			Concrete	1
window opening has limestone lintel and sill. On the	1 .	wall construction	Brick	
	21)	roof type -	Hip	
west elevation is a port cochere as part of the front		material	Red Clay Ceramic Tile	
porch which covers the facade. The porch is supported	22)	contact print		5
by square brick columns with limestone capitals. There	1	35mm		
is a band of smooth limestone around the house as a				
water table which is also the plinth to the porch columns	s.			
Around the porch is a brick parapet with limestone cop-				
ing. The porch is filled in with modern screening and				
glass enclosure. Below the water table the house is				
covered with rough textured stucco. Above the pro-				
covered with rough textured stucco. Above the pro-	23)	site plan	3 - 1	9)
	23)	site plan		9)
covered with rough textured stucco. Above the pro-	23)	site plan		9)
covered with rough textured stucco. Above the pro-	23)	site plan		9)
covered with rough textured stucco. Above the pro- <u>jecting port cochere is a sun parlor of wood. At the</u> 46) Description of environment/outbuildings	23)	site plan		9)
covered with rough textured stucco. Above the pro- icting port cochere is a sun parlor of wood. At the  46) Description of environment/Soutbuildings  Behind the house is an original (?) one story brick	23)	site plan		9)
covered with rough textured stucco. Above the pro- <u>jecting port cochere is a sun parlor of wood. At the</u> 46) Description of environment/outbuildings				
covered with rough textured stucco. Above the pro- icting port cochere is a sun parlor of wood. At the  46) Description of environment/Soutbuildings  Behind the house is an original (?) one story brick		site plan	and the second of the second	9) 5)
covered with rough textured stucco. Above the pro- iecting port cochere is a parlor of wood. At the 46) Description of environment/outbuildings un parlor of wood. At the Behind the house is an original (?) one story brick garage with two bays.			Porch screened in	
covered with rough textured stucco. Above the pro- iecting port cochere is a parlor of wood. At the 46) Description of environment/outbuildings un parlor of wood. At the Behind the house is an original (?) one story brick garage with two bays.		changes -	and the second of the second	
covered with rough textured stucco. Above the pro- iecting port cochere is a parlor of wood. At the 46) Description of environment/outbuildings un parlor of wood. At the Behind the house is an original (?) one story brick garage with two bays.	24)	changes - additions/alter- ations/moved	Porch screened in	
covered with rough textured stucco. Above the pro- iecting port cochere is a parlor of wood. At the 46) Description of environment/outbuildings un parlor of wood. At the Behind the house is an original (?) one story brick garage with two bays.	24)	changes - additions/alter- ations/moved condition	Porch screened in	
covered with rough textured stucco. Above the pro- iecting port cochere is a parlor of wood. At the 46) Description of environment/outbuildings un parlor of wood. At the Behind the house is an original (?) one story brick garage with two bays.	24) 25) 26)	changes - additions/alter- ations/moved condition visible from road?	Porch screened in  Good	
covered with rough textured stucco. Above the pro- iecting port cochere is a parlor of wood. At the 46) Description of environment/outbuildings un parlor of wood. At the Behind the house is an original (?) one story brick garage with two bays.	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road?	Porch screened in	5)
covered with rough textured stucco. Above the projecting port cochere is a sun parlor of wood. At the 46) Description of environment/outbuildings  Behind the house is an original (?) one story brick garage with two bays.  47) Information sources	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	Porch screened in  Good	
covered with rough textured stucco. Above the projecting port cochere is a sun parlor of wood. At the 46) Description of environment/outbuildings  Behind the house is an original (?) one story brick garage with two bays.  47) Information sources	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road?	Porch screened in  Good	5)
covered with rough textured stucco. Above the projecting part cochere is a sun parlor of wood. At the 46) Description of environment/outbuildings  Behind the house is an original (?) one story brick garage with two bays.  47) Information sources	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	Porch screened in  Good	5)
covered with rough textured stucco. Above the projecting part cochere is a sun parlor of wood. At the  Behind the house is an original (?) one story brick garage with two bays.  47) Information sources  48) Location of negatives Roll 5 #19-20 Roll 547-13 #6-7	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	Porch screened in  Good	5)
covered with rough textured stucco. Above the projecting part cochere is a sun parlor of wood. At the 46) Description of environment/outbuildings  Behind the house is an original (?) one story brick garage with two bays.  47) Information sources	24) 25) 26) 27) 28) 29, 30,	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	Porch screened in  Good No	5)
Covered with rough textured stucco. Above the pro- icting port cochere is a sun parlor of wood. At the  Behind the house is an original (?) one story brick garage with two bays.  47) Information sources  48) Location of negatives Roll 5 #19-20 Roll 547-13 #6-7  49) Prepared by DDD	24) 25) 26) 27) 28) 29, 30,	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	Porch screened in  Good	5) 6)
covered with rough textured stucco. Above the projecting part cochere is a sun parlor of wood. At the  Behind the house is an original (?) one story brick garage with two bays.  47) Information sources  48) Location of negatives Roll 5 #19-20 Roll 547-13 #6-7	24) 25) 26) 27) 28) 29, 30) 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	Porch screened in  Good No	5)
Covered with rough textured stucco. Above the pro- icting port cochere is a sun parlor of wood. At the  Behind the house is an original (?) one story brick garage with two bays.  47) Information sources  48) Location of negatives Roll 5 #19-20 Roll 547-13 #6-7  49) Prepared by DDD	24) 25) 26) 27) 28) 29, 30) 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	Porch screened in  Good	5) 6)
Covered with rough textured stucco. Above the pro- icting port cochere is a sun parlor of wood. At the  Behind the house is an original (?) one story brick garage with two bays.  47) Information sources  48) Location of negatives Roll 5 #19-20 Roll 547-13 #6-7  49) Prepared by DDD	24) 25) 26) 27) 28) 29, 30) 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	Porch screened in  Good  No No No	5) 6)
Covered with rough textured stucco. Above the pro- icting port cochere is a sun parlor of wood. At the  Behind the house is an original (?) one story brick garage with two bays.  47) Information sources  48) Location of negatives Roll 5 #19-20 Roll 547-13 #6-7  49) Prepared by DDD	24) 25) 26) 27) 28) 29, 30, 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	Porch screened in  Good No No No	5) 6)
Covered with rough textured stucco. Above the pro- icting port cochere is a sun parlor of wood. At the  Behind the house is an original (?) one story brick garage with two bays.  47) Information sources  48) Location of negatives Roll 5 #19-20 Roll 547-13 #6-7  49) Prepared by DDD	24) 25) 26) 27) 28) 29, 30, 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	Porch screened in  Good No No No	5) 6)
Covered with rough textured stucco. Above the pro- icting port cocher is a sun parlor of wood. At the  Behind the house is an original (?) one story brick garage with two bays.  47) Information sources  48) Location of negatives Roll 5 #19-20 Roll 547-13 #6-7  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29, 30, 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	Porch screened in  Good No No No	5) 6)
covered with rough textured stucco. Above the pro- icting part cochere is a sun parlor of wood. At the  Behind the house is an original (?) one story brick garage with two bays.  47) Information sources  48) Location of negatives Roll 5 #19-20 Roll 547-13 #6-7  49) Prepared by DDD  50) Organization Missouri Heritage Trust  If additional space is needed, attached separate sheets.	24) 25) 26) 27) 28) 29] 30) 31] 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	Porch screened in  Good  No No No	5) 6) 7)
Covered with rough textured stucco. Above the pro- icting port cocher is a sun parlor of wood. At the  Behind the house is an original (?) one story brick garage with two bays.  47) Information sources  48) Location of negatives Roll 5 #19-20 Roll 547-13 #6-7  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 30 31 32 33	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	Porch screened in  Good No No No No Yes	5) 6) 7)
covered with rough textured stucco. Above the pro- icting part cochere is a sun parlor of wood. At the  Behind the house is an original (?) one story brick garage with two bays.  47) Information sources  48) Location of negatives Roll 5 #19-20 Roll 547-13 #6-7  49) Prepared by DDD  50) Organization Missouri Heritage Trust  If additional space is needed, attached separate sheets.	24) 25) 26) 27) 28) 30, 31, 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	Porch screened in  Good No No No No Yes Yes	5) 6)
covered with rough textured stucco. Above the pro- icting part cochere is a sun parlor of wood. At the  Behind the house is an original (?) one story brick garage with two bays.  47) Information sources  48) Location of negatives Roll 5 #19-20 Roll 547-13 #6-7  49) Prepared by DDD  50) Organization Missouri Heritage Trust  If additional space is needed, attached separate sheets.	24) 25) 26) 27) 28) 29] 30, 31 32 33 34 35 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	Porch screened in  Good No No No No Yes	5) 6) 7)

c.  $_{i}$ ers are doubled wooden pilasters. The window bay has tripled window openings with fifteen over one light sash.




Commence of the second



## Missouri Historic Architectural Inventory for ( ) A Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private *	1) inventory number	101	
— public	2) name (cont)		1
39) Owners—name Leeson-Cook Meador	3) name - historial		1
	4) street address	1655 E. Walnut	
— address 1655 E. Walnut	5) town or vicinity	Springfield	1
41) Coordinates (UTM)	6) legal description		-
	1 - 1	Bigbee's Add. Lot 21	4
42) Quad	7) county	Greene	<b>_</b>
43) Other survey Historic Site Board City Historic Site	8) category		2/3)
7113 501 10 51 50 50 10 51 50 11 51 51 51 51 51 51 51 51 51 51 51 51	(site, structure,		=
	building, object)	Building	
44) History Duilt for Louis Mondon Professor at	9) significance	Contributing-Social	
Built for Lewis Meador, Professor at	10) date	1923	
Drury College in 1923 incorporating part of an earlier	11) style	Spanish Mission Reviva	1
home on the site.	12) architect	Spantsh Mission Reviva	┦
	13) builder		4
			4
	14) original use	Residence	
	15) present use	Residence	
45) Additional description	16) number of stories	One	4)
The notable feature of this house is the	17) plan shape	Irregular	1
arched open loggia porch at the entry area. There is a	18) basement	Unknown	1
gabled projecting wing with multipaned light sash which	19) foundation	Unknown	┨
appears to be double hung. Opening onto the loggia are	20) wall construction		4.2
French double doors with multi-paned lights. There are		Stucco over frame? Bri	CK!
casement windows with multi-pane lights on the east	21) roof type -	Gable	_
portion of the house on the facade.	material	Red Clay Ceramic Tile	<del></del>
portion of the house on the racade.	22) contact print		5)
	35mm		1
46) Description of environment/outbuildings	23) site plan		9)
46) Description of environment/outbuildings	23) site plan		9)
	23) site plan		9)
46) Description of environment/outbuildings  Behind the house is a one-story garage with stucco over	23) site plan		9)
Behind the house is a one-story garage with stucco over	23) site plan		9)
	23) site plan		9)
Behind the house is a one-story garage with stucco over wood and one bay garage opening.			
Behind the house is a one-story garage with stucco over	24) changes -		9) 5)
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources	24) changes - additions/alter-		
Behind the house is a one-story garage with stucco over wood and one bay garage opening.	24) changes - additions/alter- ations/moved		
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources	24) changes - additions/alter- ations/moved 25) condition	Good	
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?		
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage		5)
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	-	
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources Historic Site Board File	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	-	5)
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	-	5)
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources Historic Site Board File  48) Location of negatives Roll 547-13 #7-8	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	- - No	5)
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources Historic Site Board File	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	-	5)
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources Historic Site Board File  48) Location of negatives Roll 547-13 #7-8  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	- - - No No	5) 6)
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources Historic Site Board File  48) Location of negatives Roll 547-13 #7-8  49) Prepared by DDD  50) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	- - No	5)
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources Historic Site Board File  48) Location of negatives Roll 547-13 #7-8  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	No No No	5) 6)
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources Historic Site Board File  48) Location of negatives Roll 547-13 #7-8  49) Prepared by DDD  50) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	No No No	5) 6)
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources Historic Site Board File  48) Location of negatives Roll 547-13 #7-8  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	- - - No No No	5) 6)
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources Historic Site Board File  48) Location of negatives Roll 547-13 #7-8  49) Prepared by DDD  50) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	- - - No No No	5) 6)
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources Historic Site Board File  48) Location of negatives Roll 547-13 #7-8  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	- - - No No No	5) 6)
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources Historic Site Board File  48) Location of negatives Roll 547-13 #7-8  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	No No No No	5) 6) 7)
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources Historic Site Board File  48) Location of negatives Roll 547-13 #7-8  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	No No No No No Yes	5) 6)
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources Historic Site Board File  48) Location of negatives Roll 547-13 #7-8  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	No No No No Yes Yes	5) 6) 7)
Behind the house is a one-story garage with stucco over wood and one bay garage opening.  47) Information sources Historic Site Board File  48) Location of negatives Roll 547-13 #7-8  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	No No No No No Yes	5) 6) 7)



NA


er er er

- · · · · · ·



#### Missouri Historic Architectural Inventory for G Natural Resources

38) Ownership — private X	1)	inventory number	108	]=
— public	2)	name (cont)		
39) Owners—name Union Natl. Bank Trust	3)	name - historial		1
- address	4)	street address	1656 E. Walnut	1
40) Local contact		town or vicinity	Springfield	-
41) Coordinates (UTM)	- /	legal description	East Elm St. Add. Lot	1
				-
42) Quad		county	Greene H	-
43) Other survey		category	5 13 11	2/3)
		(site, structure,	Building	
		building, object)		_
44) History	9)	significance	Architectural	
	10)	date	Post 1933 ca. 1938	
	11)	style	Cottage Revival	7
	ı	architect		1
	1 .	builder		1
		original use	Residence	4
	1	present use		-
		<u> </u>	Residence	_
45) Additional description The front wng and the east wing are	l '	number of stories	2	_4_
of brick (veneer?) and the back portion of the house	1	plan shape	Irregular	1
is stucce ever (2). The equation the house	l	basement	Full?	
is stucco over (?). The eaves on the house are more	19)	foundation	Concrete	
or less flush with the wall. The front gable has butt	20)	wall construction	Brick Veneer	7
shingles at the apex in a secondary pediment overhanging	<b>2</b> 1)	roof type -	Gable	7
tripled windows with the center opening with eight over		material	Asphalt shingle	7
eight sash and the flanking openings having four over	22)	contact print		5
four light sash. The pediment cornice has brackets and	/	35mm		
acts as the window head to the above described gable	ľ	3311111		
windows. There is a limestone sill on the window open-				
ing . Each face of the roof of the front gable has a	1			
small gable dormer. There are corbelled cornices on				
the gable. To one side of the gable is a massive				
chimney base with accented angular brick chimney				
chimney base with accented angular brick chimney  sections. There are ceramic chimney pots caping the  46) Description of environment/outbuildings	23)	site plan		9)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings	23)	site plan	· ·	9)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with	23)	site plan	· · · · · · · · · · · · · · · · · · ·	9)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a	23)	site plan		9)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with	23)	site plan		9)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a	23)	site plan		9)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.				
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a		changes -		9) 5)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.		changes - additions/alter-	None visible	
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.	24)	changes - additions/alter- ations/moved	None visible	
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.	24)	changes - additions/alter-		
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.	24)	changes - additions/alter- ations/moved	None visible	
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.	24) 25) 26)	changes - additions/alter- ations/moved condition		
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road?		
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.  47) Information sources	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?		5)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	Good - -	5)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.  47) Information sources  48) Location of negatives Roll 547-13 #9-10	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	Good - - - No	5)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.  47) Information sources	25) 26) 27) 28) 29) 30)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	Good - -	5)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.  47) Information sources  48) Location of negatives Roll 547-13 #9-10	25) 26) 27) 28) 29) 30)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	Good - - - No	5)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.  47) Information sources  48) Location of negatives Roll 547-13 #9-10  49) Prepared by DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	Good - - - No	5)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.  47) Information sources  48) Location of negatives Roll 547-13 #9-10  49) Prepared by DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	- No No	5) 6)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.  47) Information sources  48) Location of negatives Roll 547-13 #9-10  49) Prepared by DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	- No No No	5) 6)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.  47) Information sources  48) Location of negatives Roll 547-13 #9-10  49) Prepared by DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	- No No	5) 6)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.  47) Information sources  48) Location of negatives Roll 547-13 #9-10  49) Prepared by DDD  50) Organization Missouri Heritage Trust	25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	- No No No	5) 6)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.  47) Information sources  48) Location of negatives Roll 547-13 #9-10  49) Prepared by DDD	25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	- No No No	5) 6)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.  47) Information sources  48) Location of negatives Roll 547-13 #9-10  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	No No No	5) 6)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.  47) Information sources  48) Location of negatives Roll 547-13 #9-10  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district ) is site eligible?	No No No Yes	5) 6) 7)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.  47) Information sources  48) Location of negatives Roll 547-13 #9-10  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32) 34, 35,	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district ) is site eligible? ) district potential?	Cood  No No No No  No  Yes Yes	5) 6)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.  47) Information sources  48) Location of negatives Roll 547-13 #9-10  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 31) 32) 33, 34, 35, 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	No No No Yes	5) 6) 7)
chimney base with accented angular brick chimney sections. There are ceramic chimney pots caping the 46) Description of environment/outbuildings chimney. The face of the chimney is covered with "exposed" random ashlar limestone sections used as a decorative motif.  47) Information sources  48) Location of negatives Roll 547-13 #9-10  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 31) 32) 33, 34, 35, 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district ) is site eligible? ) district potential?	Cood  No No No No  No  Yes Yes	5) 6) 7)



71



# Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources

•				
38) Ownership — private <sub>X</sub> *		inventory number	102	٥
public	1	name (cont)		
39) Owners — name Donald Deeds	1.	name - historial		
—address 1673 E. Walnut		street address	1673 E. Walnut	4
40) Local contact 41) Coordinates (UTM)		town or vicinity legal description	Springfield	-
42) Quad		county	Kennedy Heights Add.	
43) Other survey		category	Greene Lot 22	
437 Other survey		(site, structure,	Building	2/3)
	Į.	building, object)	building	
44) History		significance	Contributing	1
	10)	date	ca. 1938	1
	11)	style	Cottage REvival	
	12)	architect		
		builder		
		original use	Residence	
		present use	Residence	ļ
45) Additional description In Southwest corner there is a Field-		number of stories	1-1/2	_ <b>4</b> _
stone buttress. There is a small gable on a gable with	1	plan shape	Irregular	4
Fieldstone rubble walls and a centered chimney with	1	basement foundation	Unknown	4
ceramic chimney pots. All of the window openings appear	1 '	wall construction	Concrete	-
to have been altered recently.		roof type -	Brick &Frame	_
	'	material	Gable Cedar Shale	+
	22)	contact print	Cedar Share	5
		35mm		
46) Description of environment/outbuildings	23)	site plan	* *	9
		· · · · · · · · · · · · · · · · · · ·		
		e e e e e e e e e e e e e e e e e e e		
47) Information sources	24)	changes -		5
		additions/alter-	New Windows	
		ations/moved		
	1 .	condition	Good	_
		visible from road?		4
		distance/frontage		6)
	1 '	accessible?	<del>-</del>	اعت
48) Location of negatives  Roll 547-13 #11-12	29)	underway?		
	30)	endangered?	No	$\dashv$
49) Prepared by DDD	- 1	on National	No	
50.0		Register?	No	
Missouri Heritage Trust	32)	part of	No	72
		established	No.	
		historical district		
If additional space is needed, attached separate sheets.	33)	name of historical		
		district		4
	1	is site eligible?	No	(0)
	- 1	district potential?	163	30)
	(30)	date	Jan. 30, 1984	
	371	revision		

### 1673 E Walnut

GR +1-052-71




#### Missouri Historic Architectural Inventory for State Company Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private X		
	* 1) inventory number 107	==
— public	2) name (cont)	
39) Owners — name H. A. Lowe, Jr.	3) name - historial	
— address 1700 E. Walnut	4) street address 1700 E. Walnut	
(40) Local contact	5) town or vicinity Springfield	
41) Coordinates (UTM)	6) legal description Ireq. Survey 32-B Lo	F A
42) Quad	7) county Greene	~~~
43) Other survey	8) category	N
is, outsi savis,	(site structure	2/3)
	building, object) Building	
44) History		
·	Contributing	
Built 1916-1917 by Jefferson Hansell,	1310 1317	
a conductor for the Frisco RR. In	11) style Catalogue/Builder 12) architect	
1920 D. Arch Lowe purchased house	,	
his son lived there today.	13) builder	
	14) original use Residence	
	15) present use Residence	
45) Additional description	16) number of stories 2	4
Overhanging roof eaves with exposed	17) plan shape Rectangle	
rafter ends. Three bay facade with narrow flanking	18) basement Full	
windows around the center second story window and the	19) foundation Concrete	
doorway at the first story. The hip roof porch is a	20) wall construction Brick	
modern addition.	21) roof type - Hip	
Multi-pane window sash.	material Asphalt shingle	
	22) contact print	5
	35mm	
	02) eite-de-	9
46) Description of environment/outbuildings	23) site plan	9)
46) Description of environment/outbuildings	23) site plan	9)
46) Description of environment/outbuildings	23) site plan	9)
46) Description of environment/outbuildings	23) site plan	9)
46) Description of environment/outbuildings		9)
46) Description of environment/outbuildings		
46) Description of environment/outbuildings  47) Information sources	24) changes -	9) 5)
47) Information sources	24) changes -	
47) Information sources Owner	24) changes - additions/alter Front porch added	
47) Information sources Owner	24) changes - additions/alter- ations/moved  Pront porch added	
47) Information sources Owner	24) changes - additions/alter- ations/moved 25) condition  Good	5)
47) Information sources Owner	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?  -	
47) Information sources  Owner  City Directory 1915-1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	5)
Owner City Directory 1915-1933  48) Location of negatives Roll 547-13 #15-16	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	5)
Owner City Directory 1915-1933  48) Location of negatives Roll 547-13 #15-16	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? No	5)
47) Information sources  Owner  City Directory 1915-1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? No	5)
47) Information sources  Owner City Directory 1915-1933  48) Location of negatives Roll 547-13 #15-16  49) Prepared by DDD  50) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	5) 6)
Owner City Directory 1915-1933  48) Location of negatives Roll 547-13 #15-16	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	5)
47) Information sources  Owner City Directory 1915-1933  48) Location of negatives Roll 547-13 #15-16  49) Prepared by DDD  50) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? - 29) preservation underway? 30) endangered? 31) on National Register? No	5) 6)
47) Information sources  Owner City Directory 1915-1933  48) Location of negatives Roll 547-13 #15-16  49) Prepared by DDD  50) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	5) 6)
Owner City Directory 1915-1933  48) Location of negatives Roll 547-13 #15-16  49) Prepared by DDD  50) Organization  Missouri Historic Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	5) 6)
47) Information sources  Owner City Directory 1915-1933  48) Location of negatives Roll 547-13 #15-16  49) Prepared by DDD  50) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	5) 6)
Owner City Directory 1915-1933  48) Location of negatives Roll 547-13 #15-16  49) Prepared by DDD  50) Organization  Missouri Historic Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district  Front porch added  Rood  No  No  No  No  No  No  No  No  No	5) 6)
Owner City Directory 1915-1933  48) Location of negatives Roll 547-13 #15-16  49) Prepared by DDD  50) Organization  Missouri Historic Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?  Front porch added  Rood  No  No  No  No  No  No  No  No  No	5) 6) 7)
Owner City Directory 1915-1933  48) Location of negatives Roll 547-13 #15-16  49) Prepared by DDD  50) Organization  Missouri Historic Trust	24) changes - additions/alter- ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National Register?  32) part of established historical district  33) name of historical district  34) is site eligible? 35) district potential?  Front porch added  No  No  No  No  No  No  No  No  No  N	5) 6)
Owner City Directory 1915-1933  48) Location of negatives Roll 547-13 #15-16  49) Prepared by DDD  50) Organization  Missouri Historic Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?  Front porch added  Rood  No  No  No  No  No  No  No  No  No	5) 6) 7)



### Missouri Historic Architectural Inventory for Control Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private X	1) inventory number	103	Ξ
— public	2) name (cont)		4
39) Owners — name Calvin Weese et al	3) name - historial	1701 5 1/ 1	_
— address 1701 E. Walnut	4) street address	1701 E. Walnut	4
40) Local contact	5) town or vicinity	Springfield 07	4
41) Coordinates (UTM:	6) legal description	Kennedy Heights Lot 27	_
42) Quad	7) county	Greene	+
43) Other survey	8) category		2/3)
	(site, structure,	2	
	building, object)	Building	
8uilt 1927-1928 by James A. Sherrow,	9) significance 10) date	Architectural-Contribu	<u>t</u> ing
a restaurant owner	,	1927-1928	4
a restaurante owner	11) style	Tudor Revival	4
	12) architect		4
	13) builder		4
	14) original use	Residence	4
	15) present use	Residence	-
45) Additional description	16) number of stories	1-1/2	4
Hip dormer on the west roof face with	17) plan shape	Irregular	4
stucco wall surfaces. The eaves in the gables are	18) basement	Full	_
nearly flush and the face of the gables are stucco and	19) foundation	Concrete	_
half timber. Centered in the gable and below at the	20) wall construction	Brick Veneer	
first floor lever are latticed casement windows. The	21) roof type	<u>Combination</u>	
entrance is in the southwest corner of the house which	material	asphalt shingle	<u> </u>
has its corner cut out to create a porch under the roof			5)
line of the house. The porch has arched bays.	35mm		}
1			
			- 10
46) Description of environment/outbuildings	23) site plan		9)
46) Description of environment/outbuildings	23) site plan		9)
46) Description of environment/outbuildings	23) site plan		9)
46) Description of environment/outbuildings	23) site plan		9)
46) Description of environment/outbuildings	23) site plan		9)
47) Information sources	24) changes		9) 5)
	24) changes - additions/alter-		
47) Information sources	24) changes - additions/alter- ations/moved	None	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition	None Good	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	None Good	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	None Good	5)
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	None Good	
47) Information sources  City Directories 1927-1933  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	None Good	5)
47) Information sources  City Directories 1927-1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	None Good	5)
47) Information sources  City Directories 1927-1933  48) Location of negatives  Roll 547-13 #13-14  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	None Good	5)
47) Information sources  City Directories 1927-1933  48) Location of negatives  Roll 547-13 #13-14	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	None Good	5)
47) Information sources  City Directories 1927-1933  48) Location of negatives  Roll 547-13 #13-14  49) Prepared by DDD  50) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	None Good	5) 6)
47) Information sources  City Directories 1927-1933  48) Location of negatives  Roll 547-13 #13-14  49) Prepared by  DDD	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	None Good	5)
47) Information sources  City Directories 1927-1933  48) Location of negatives  Roll 547-13 #13-14  49) Prepared by DDD  50) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	None Good	5) 6)
47) Information sources  City Directories 1927-1933  48) Location of negatives  Roll 547-13 #13-14  49) Prepared by DDD  50) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	None Good	5) 6)
47) Information sources  City Directories 1927-1933  48) Location of negatives  Roll 547-13 #13-14  49) Prepared by DDD  50) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	None Good  No No No No	5) 6)
47) Information sources  City Directories 1927-1933  48) Location of negatives Roll 547-13 #13-14  49) Prepared by DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	None Good  No No No No	5) 6)
47) Information sources  City Directories 1927-1933  48) Location of negatives Roll 547-13 #13-14  49) Prepared by DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	None Good  No No No No	5) 6) 7)
47) Information sources  City Directories 1927-1933  48) Location of negatives Roll 547-13 #13-14  49) Prepared by DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	None Good	5) 6) 7)
47) Information sources  City Directories 1927-1933  48) Location of negatives Roll 547-13 #13-14  49) Prepared by DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	None Good  No No No No No Yes Yes	5) 6)
47) Information sources  City Directories 1927-1933  48) Location of negatives Roll 547-13 #13-14  49) Prepared by DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	None Good	5) 6) 7)



NA


(-0 AS-00-712



#### Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private X	1) inventory number	106	1
— public	2) name (cont)	100	⊐=
'			
39) Owners—name John A. Helbig	3) name - historial	1704 E. Walnut	1
— address 1704 E. Walnut	4) street address	1704 E. Warnac	7
( 40) Local contact	5) town or vicinity	Springfield	
41) Coordinates (UTM)	6) legal description	East Elm St. Add. Lot	.1
42) Quad	7) county	Greene	<del>-</del>
43) Other survey	8) category	dieene	<del>                                     </del>
45) Office Survey			2/3)
	(site, structure,		٦
	building, object)	Building	
44) History	9) significance	Contributing	
Built 1924-1925 by non-resident owner.	10) date	1925	1
	11) style	Colonial Revival	4
	12) architect	00.00.100.1100.1	┥
	13) builder		4
	,		_
	14) original use	Residence	_
	15) present use	Residence	
45) Additional description	16) number of stories	2	4
Two bay facade. Window openings have	17) plan shape	Rectangle	7
flat arch lintels and limestone sills with eight over	18) basement	Full	7
eight light sash. Pediment gable portico with cornice	19) foundation	Concrete	+
returns supported by round wood columns with Tuscan	20) wall construction	Brick Veneer	_
capitals. The gables have cornice returns. In the	21) roof type -		
east gable is a two-story sun parlor.	- ·	Gable	
cust gubic is a two story sun parior.	material	Asphalt Shingle	
	22) contact print		5
	35mm		l l
			ļ
46) Description of environment/outbuildings	23) site plan		9)
	23) site plan		9)
Behind the house is a one-story single bay garage with	23) site plan		9)
	23) site plan		9)
Behind the house is a one-story single bay garage with	23) site plan		9)
Behind the house is a one-story single bay garage with	23) site plan		9)
Behind the house is a one-story single bay garage with			
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources	24) changes -		9) 5)
Behind the house is a one-story single bay garage with gable roof and matching brick walls.	24) changes - additions/alter-		
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources	24) changes - additions/alter- ations/moved	None	
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources	24) changes - additions/alter- ations/moved 25) condition		
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	None Good	
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	None	5)
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources  City Directory 1920-1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	None Good	
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources  City Directory 1920-1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	None Good	5)
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources  City Directory 1920-1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	None Good	5)
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources  City Directory 1920-1933  48) Location of negatives Roll 547-13 #18-19	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	None Good - - - No	5)
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources  City Directory 1920-1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	None Good - - -	5)
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources  City Directory 1920-1933  48) Location of negatives Roll 547-13 #18-19  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	None Good - - - - No	5) 6)
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources  City Directory 1920-1933  48) Location of negatives Roll 547-13 #18-19	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	None Good - - - No	5)
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources  City Directory 1920-1933  48) Location of negatives Roll 547-13 #18-19  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	None Good - - - No No	5) 6)
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources  City Directory 1920-1933  48) Location of negatives Roll 547-13 #18-19  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	None Good No No No	5) 6)
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources  City Directory 1920-1933  48) Location of negatives Roll 547-13 #18-19  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	None Good - - - No No	5) 6)
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources  City Directory 1920-1933  48) Location of negatives Roll 547-13 #18-19  49) Prepared by DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	None Good No No No	5) 6)
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources  City Directory 1920-1933  48) Location of negatives Roll 547-13 #18-19  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	None Good No No No	5) 6)
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources  City Directory 1920-1933  48) Location of negatives Roll 547-13 #18-19  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	None Good No No No	5) 6) 7)
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources  City Directory 1920-1933  48) Location of negatives Roll 547-13 #18-19  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	None Good No No No No Ves	5) 6) 7)
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources  City Directory 1920-1933  48) Location of negatives Roll 547-13 #18-19  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	None Good  No No No No  No  Yes Yes	5) 6)
Behind the house is a one-story single bay garage with gable roof and matching brick walls.  47) Information sources  City Directory 1920-1933  48) Location of negatives Roll 547-13 #18-19  49) Prepared by DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	None Good No No No No Ves	5) 6) 7)

51





#### Missouri Historic Architectural Inventory for ( )

38) Ownership — priva	te Y	* 1) inventory number	105	
— publi	•	2) name (cont)	103	<u>=</u>
39) Owners — name	Larry Reed	3) name - historial		
— address	_	4) street address	1700 F Walnut	
	1700 E. Walligt	5) town or vicinity	1708 E. Walnut	
40) Local contact	(73.4)		Springfield East Elm St. Add. Lo	
(41) Coordinates (U	J [ M] !	6) legal description	l .	
42) Quad		7) county	Greene	Κ
43) Other survey		8) category		2/3)
		(site, structure,		۳
		building, object)	Building	
44) History		9) significance	Contributing	
		10) date	ca. 1940	
		11) style		
		12) architect		
		13) builder		
		14) original use	Residence	_
		15) present use	Residence	_
45) Additional descript	tion	16) number of stories		4
43) Additional descript	(to)	17) plan shape	1-1/2	— <del> </del> ~
			Irregular	
		18) basement	Full	
		19) foundation	Concrete	
		20) wall construction	Frame/Lap Siding	
		21) roof type -	Gable	
		material	Asphalt Shingle	
		22) contact print		5)
		35mm		
_				
,				
,				
A6) Description of any	in a mont fourth vildings	23) site plan		9
46) Description of env	ironment/outbuildings	23) site plan		9)
46) Description of env	ironment/outbuildings	23) site plan		9)
46) Description of env	ironment/outbuildings	23) site plan		9)
46) Description of env	ironment/outbuildings	23) site plan		9)
46) Description of env	ironment/outbuildings	23) site plan		9)
46) Description of env	es	24) changes -		
		24) changes - additions/alter-		
	es	24) changes - additions/alter- ations/moved	None visible	
	es	24) changes - additions/alter- ations/moved 25) condition	None visible	
	es	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	None visible	
	es	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	None visible	5)
	es	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	None visible Good	
	es City Directory 1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	None visible Good	5)
47) Information source	es City Directory 1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	None visible Good	5)
47) Information source 48) Location of negation	es City Directory 1933 ves Roll 547-13 #19-20	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	None visible  Good No	5)
47) Information source	es City Directory 1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	None visible Good	5)
47) Information source 48) Location of negati 49) Prepared by	City Directory 1933  Ves Roll 547-13 #19-20  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	None visible  Good No No	5) 6)
47) Information source 48) Location of negati	es City Directory 1933 ves Roll 547-13 #19-20	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	None visible  Good No	5)
47) Information source 48) Location of negati 49) Prepared by	City Directory 1933  Ves Roll 547-13 #19-20  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	None visible  Good No No	5) 6)
47) Information source 48) Location of negati 49) Prepared by	City Directory 1933  Ves Roll 547-13 #19-20  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	None visible  Good No No No	5) 6)
47) Information source 48) Location of negation 49) Prepared by 50) Organization	City Directory 1933  Ves Roll 547-13 #19-20  DDD  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	None visible  Good No No No	5) 6)
47) Information source 48) Location of negation 49) Prepared by 50) Organization	City Directory 1933  Ves Roll 547-13 #19-20  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica	None visible  Good No No No	5) 6)
47) Information source 48) Location of negation 49) Prepared by 50) Organization	City Directory 1933  Ves Roll 547-13 #19-20  DDD  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district	None visible  Good No No No No	5) 6)
47) Information source 48) Location of negation 49) Prepared by 50) Organization	City Directory 1933  Ves Roll 547-13 #19-20  DDD  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible?	None visible  Good No No No No No	5) 6) 7)
47) Information source 48) Location of negation 49) Prepared by 50) Organization	City Directory 1933  Ves Roll 547-13 #19-20  DDD  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential?	None visible  Good No No No No No	5) 6)
47) Information source 48) Location of negation 49) Prepared by 50) Organization	City Directory 1933  Ves Roll 547-13 #19-20  DDD  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential? 36) date	None visible  Good No No No No No No Yes	5) 6) 7)
48) Location of negation 49) Prepared by 50) Organization	City Directory 1933  Ves Roll 547-13 #19-20  DDD  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential?	None visible  Good No No No No No	5) 6) 7)



Missouri Historic Architectural Inventory for

Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private X		Ι 11	immandam, mb.a		
	*	1	inventory number	104	שב
— public		2)	name (cont)		
39) Owners — name Rio	chard Donnell	3)	name - historial		7
	19 E. Walnut	4)	street address	1714 5 11 7	-
40) Local contact	19 E. Walliut		town or vicinity	1714 E. Walnut	4
		1	•	Springfield	_
41) Coordinates (UTM)		1	legal description	Ireg. Survey 32 Lot A	_
42) Quad		7)	county	Greene	7
43) Other survey		8)	category	01 66116	100
•		-	(site, structure,		2/3)
				Building	
			building, object)	_	
44) History		9)	significance	Contributing	7
Bur	ild ca. 1925-1926. In 1926 the house	10)	date		┥
sat	t vacant. By 1933 L. J. Lippman, a	1	style	ca. 1925-1926	4
nri	inter for Lippman Printing Co. owned	1	•	Bungaloid	4
5.1	d littled in the barrar	1	architect		
anc	d lived in the house.	13)	builder		7
		14)	original use	Doordon	┥
		1	present use	Residence	<del>-</del> i
	<del></del>			Residence	1
45) Additional description		1	number of stories	]	4
0∨€	erhanging eaves with exposed rafter	17)	plan shape	Rectangle	7
ends on the side el	evations. Facade entrance with three	1	basement		4
have The center b	evacions: Tacade entrance with three	1 '		Full	4
bays. The center b	pay entrance has sidelights and a tran-	13)	iounuation	Concrete	
som. Flat roof on	porch with wooden balustrade. The	1 -	wall construction	Frame/Vinyl Siding	7
porch posts are mod	dern replacements. All windows are six	(21)	roof type -	Gable	7
over six light sash	)	1	material		7
over six right sush	•	221	contact print	Asphalt shingle	5
		22)			9
			35mm		ŀ
					1
					1
		1			
;					
46) Description of environment	t/outbuildings	23)	site plan		9)
	t/outbuildings	23)	site plan		9)
46) Description of environment	-	23)	site plan		9)
46) Description of environment Behind the house is	a one and one half story wood out-	23)	site plan		9)
46) Description of environment  Behind the house is building with a one	-	23)			9)
46) Description of environment Behind the house is	a one and one half story wood out-			·	9)
46) Description of environment  Behind the house is building with a one	a one and one half story wood out-				9)
46) Description of environment Behind the house is building with a one gable roof.	a one and one half story wood out-	- N		· · · · · · · · · · · · · · · · · · ·	
46) Description of environment Behind the house is building with a one gable roof.	a one and one half story wood out- bay garage and a storage area with	- N	changes -	Porch posts replaced	9) 5)
46) Description of environment Behind the house is building with a one gable roof.	a one and one half story wood out-	- N	changes - additions/alter-	Porch posts replaced	
46) Description of environment Behind the house is building with a one gable roof.	a one and one half story wood out- bay garage and a storage area with	24)	changes - additions/alter- ations/moved	Porch posts replaced vinyl siding	
46) Description of environment Behind the house is building with a one gable roof.	a one and one half story wood out- bay garage and a storage area with	24)	changes - additions/alter-	vinyl siding	
46) Description of environment Behind the house is building with a one gable roof.	a one and one half story wood out- bay garage and a storage area with	24)	changes - additions/alter- ations/moved condition	vinyl siding Good	
46) Description of environment Behind the house is building with a one gable roof.	a one and one half story wood out- bay garage and a storage area with	24) 25) 26)	changes - additions/alter- ations/moved condition visible from road?	vinyl siding	
46) Description of environment Behind the house is building with a one gable roof.	a one and one half story wood out- bay garage and a storage area with	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road? distance/frontage	vinyl siding Good	5)
46) Description of environment Behind the house is building with a one gable roof.	a one and one half story wood out- bay garage and a storage area with	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road?	vinyl siding Good	
46) Description of environment Behind the house is building with a one gable roof.  47) Information sources  Cit	a one and one half story wood outbay garage and a storage area with  y Directories 1925-1933	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage	vinyl siding Good	5)
46) Description of environment Behind the house is building with a one gable roof.  47) Information sources Cit	a one and one half story wood outbay garage and a storage area with  y Directories 1925-1933	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	vinyl siding Good	5)
46) Description of environment Behind the house is building with a one gable roof.  47) Information sources Cit	a one and one half story wood outbay garage and a storage area with  y Directories 1925-1933	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	vinyl siding Good No	5)
46) Description of environment Behind the house is building with a one gable roof.  47) Information sources  Cit  48) Location of negatives Ro Ro	a one and one half story wood outbay garage and a storage area with  y Directories 1925-1933	25) 26) 27) 28) 29) 30)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	vinyl siding Good	5)
46) Description of environment Behind the house is building with a one gable roof.  47) Information sources Cit	a one and one half story wood outbay garage and a storage area with  y Directories 1925-1933	25) 26) 27) 28) 29) 30)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	vinyl siding Good No	5)
46) Description of environment Behind the house is building with a one gable roof.  47) Information sources Cit  48) Location of negatives Ro Ro DDD  50) Organization	a one and one half story wood outbay garage and a storage area with  y Directories 1925-1933	25) 26) 27) 28) 29) 30)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	vinyl siding Good No No	5) 6)
46) Description of environment Behind the house is building with a one gable roof.  47) Information sources Cit  48) Location of negatives Ro Ro DDD  50) Organization	a one and one half story wood outbay garage and a storage area with  y Directories 1925-1933	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	vinyl siding Good No	5)
46) Description of environment Behind the house is building with a one gable roof.  47) Information sources Cit  48) Location of negatives Ro Ro DDD  50) Organization	a one and one half story wood outbay garage and a storage area with  y Directories 1925-1933	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	vinyl siding Good No No	5) 6)
46) Description of environment Behind the house is building with a one gable roof.  47) Information sources Cit  48) Location of negatives Ro Ro DDD  50) Organization	a one and one half story wood outbay garage and a storage area with  y Directories 1925-1933	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	vinyl siding  Good  No No No	5) 6)
46) Description of environment Behind the house is building with a one gable roof.  47) Information sources Cit  48) Location of negatives Ro Ro DDD  50) Organization	a one and one half story wood outbay garage and a storage area with  y Directories 1925-1933	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	vinyl siding  Good  No No No No	5) 6)
46) Description of environment Behind the house is building with a one gable roof.  47) Information sources Cit  48) Location of negatives Ro Ro DDD  50) Organization	a one and one half story wood outbay garage and a storage area with  y Directories 1925-1933  11 547-14 #1-2 11 5 #21  ssouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	vinyl siding  Good  No No No No	5) 6)
46) Description of environment Behind the house is building with a one gable roof.  47) Information sources Cit  48) Location of negatives Ro Ro Prepared by DDD  50) Organization Mi	a one and one half story wood outbay garage and a storage area with  y Directories 1925-1933  11 547-14 #1-2 11 5 #21  ssouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	vinyl siding  Good  No No No No	5) 6)
46) Description of environment Behind the house is building with a one gable roof.  47) Information sources Cit  48) Location of negatives Ro Ro Prepared by DDD  50) Organization Mi	a one and one half story wood outbay garage and a storage area with  y Directories 1925-1933  11 547-14 #1-2 11 5 #21  ssouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	vinyl siding  Good  No No No No	5) 6)
46) Description of environment Behind the house is building with a one gable roof.  47) Information sources Cit  48) Location of negatives Ro Ro Prepared by DDD  50) Organization Mi	a one and one half story wood outbay garage and a storage area with  y Directories 1925-1933  11 547-14 #1-2 11 5 #21  ssouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	vinyl siding  Good  No No No No Ves	5) 6) 7)
46) Description of environment Behind the house is building with a one gable roof.  47) Information sources Cit  48) Location of negatives Ro Ro Prepared by DDD  50) Organization Mi	a one and one half story wood outbay garage and a storage area with  y Directories 1925-1933  11 547-14 #1-2 11 5 #21  ssouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	vinyl siding  Good  No No No No	5) 6)
46) Description of environment Behind the house is building with a one gable roof.  47) Information sources Cit  48) Location of negatives Ro Ro Prepared by DDD  50) Organization Mi	a one and one half story wood outbay garage and a storage area with  y Directories 1925-1933  11 547-14 #1-2 11 5 #21  ssouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	vinyl siding  Good  No No No No Yes Yes	5) 6) 7)
46) Description of environment Behind the house is building with a one gable roof.  47) Information sources Cit  48) Location of negatives Ro Ro Prepared by DDD  50) Organization Mi	a one and one half story wood outbay garage and a storage area with  y Directories 1925-1933  11 547-14 #1-2 11 5 #21  ssouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35) 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	vinyl siding  Good  No No No No Ves	5) 6) 7)

5 **↑** 





#### 

* 1) inventory number P=1503
2) name (cont)
3) name - historial
5) town or vicinity Springfield
6) legal description
7) county Greene
8) category (site, structure,
(Site, Structure,
9) significance
10) date
11) style bungalow
12) architect
1
13) builder
14) originaluse residence
15) presentuse
16) number of stories 1
· · · · · · · · · · · · · · · · · · ·
17) plan shape rectangle
18) basement no
19) foundation concrete
20) wall construction frame/modern siding
21) roof type- gable
material asphalt shingle
22) contact print
35mm
23) site plan
24) changes -
additions/alter-
ations/moved
25) condition
( '
26) visible from road?
27) distance/frontage
28) accessible?
29) preservation
· · · · · · · · · · · · · · · · · · ·
underway?
30) endangered?
30) endangered? 31) on National
30) endangered? 31) on National Register? No
30) endangered? 31) on National Register? NO 32) part of
30) endangered? 31) on National Register? NO 32) part of established
30) endangered? 31) on National Register? NO 32) part of established historical district NO
30) endangered? 31) on National Register? NO 32) part of established
30) endangered? 31) on National Register? NO 32) part of established historical district NO
30) endangered? 31) on National Register? NO 32) part of established historical district NO 33) name of historical district
30) endangered? 31) on National Register? NO 32) part of established historical district NO 33) name of historical district 34) is site eligible?
30) endangered? 31) on National Register? NO 32) part of established historical district NO 33) name of historical district 34) is site eligible? 35) district potential?
30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  No No No No No No No No No No No No No
30) endangered? 31) on National Register? NO 32) part of established historical district NO 33) name of historical district 34) is site eligible? 35) district potential?
30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  No No No No No No No No No No No No No
30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  No No No No No No No No No No No No No



Missouri Historic Architectural Inventory for GR - OCS - TITE

Division of Parks and Historic Preservation Department of Natural Resources

2010	
38) Ownership — private — public	* 1) inventory number P=1279
39) Owners — name	2) name (cont)
— address	3) name · historial
40) Local contact	4) street addressW.Walnut st.
	5) town or vicinity Springfield
41) Coordinates (UTM)	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
	(site, structure,
	building, object) Building
44) History	9) significance
	10) date
	11) style late catbuilder
	12) architect
	13) builder
	14) original use residence
	15) present use same
45) Additional description	16) number of stories   2
	17) plan shape square
	18) basement full
	19) foundation stone
	20) wall construction frame/lap siding
	21) roof type-
	material asphalt shingle
•	22) contact print
$\bigcirc$	
46) Description of environment/outbuildings	23) site plan
- Lescription of environment/outbulldings	23) site plan
47) Information sources	24) changes -
47) Information sources	additions/alter-
	ations/moved
	25) condition
	26) visible from road?
	27) distance/frontage
	28) accessible?
49) Location of pogotives	29) preservation
48) Location of negatives  Roll 143 #25	underway?
49) Prepared by	30) endangered?
DDD	31) on National
FOX Opposite ties	
50) Organization Missouri Heritage Trust	Register? No 32) part of
The real state of the second s	established
	historical district NO
If additional space is needed, a	33) name of historical
The state of the s	district
	34) is site eligible? NO
	35) district potential? Ye
	36) date $\frac{5/3}{84}$
and the second second	37) revision
* # 1 <u> </u>	
HISTORIC INVENTORY FORM	
MISSOURI HERITAGE TRUST	1



Missouri Historic Architectural Inventory for GR. 10-63-718

Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number 1.–215	<del></del>
public	2) name (cont)	
39) Owners — name	3) name - historial	
— address		
	4) street address	
40) Local contact	5) town or vicinity Springfield	
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county Greene	
43) Other survey	8) category	
, , , , , , , , , , , , , , , , , , ,	(site, structure,	
	]	1
44) History	9) significance contributing	
	10) date	
	\\	<del></del> -
	Car it Cau	<u>.lder</u>
	12) architect	
	13) builder	
	14) original use residence	
	15) 7777771	
AE) Addistructions	Same	
45) Additional description	• 16) number of stories 1 1	
	17) plan shape irregular	
	10) foundation	
	Score	
	20) wall construction   frame/modern s	sidin
	21) roof type- gable-hip comb	
•	material asphalt shing	Le
	35mm	
		I
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings		
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings		
46) Description of environment/outbuildings  47) Information sources	24) changes -	
	24) changes - additions/alter-	
	24) changes - additions/alter- ations/moved	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	
47) Information sources  48) Location of negatives  Roll 133 #29-30	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	
47) Information sources  48) Location of negatives  RoII 133 #29-30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	
47) Information sources  48) Location of negatives  RoII 133 #29-30  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
47) Information sources  48) Location of negatives  ROII 133 #29-30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No	
47) Information sources  48) Location of negatives  RoII 133 #29-30  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of	
47) Information sources  48) Location of negatives  RoII 133 #29-30  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established	
47) Information sources  48) Location of negatives  RoII 133 #29-30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of	
47) Information sources  48) Location of negatives  RoII 133 #29-30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established	
47) Information sources  48) Location of negatives  RoII 133 #29-30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No	
47) Information sources  48) Location of negatives  RoII 133 #29-30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No 33) name of historical district	
48) Location of negatives  ROII 133 #29-30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible?	
48) Location of negatives  ROII 133 #29-30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? Ye.	
48) Location of negatives  ROII 133 #29-30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? Ye.	
48) Location of negatives  ROII 133 #29-30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 34) is site eligible? 35) district potential? 36) date  24) changes - additions/alter- ations/moved No No No No No No No No No No No No No	
47) Information sources  48) Location of negatives  Roll 133 #29-30  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? Ye.	
47) Information sources  48) Location of negatives  RoII 133 #29-30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 34) is site eligible? 35) district potential? 36) date  24) changes - additions/alter- ations/moved No No No No No No No No No No No No No	



### Missouri Historic Architectural Inventory for GR-93-63-719 Division of Parks and Historic Preservation Department of Natural Resources

Take A second se	<del></del>	
38) Ownership — private		<u></u>
— public	2) name (cont)	
39) Owners — nam€	3) name - historial	
— address	4) street address	705 11 11 1
40) Local contact	5) town or vicinity	305 W. Walnut st.
41) Coordinates (UTM)	6) legal description	Springfield
42) Quad		
·	7) county	Greene
43) Other survey	8) category	
	(site, structure,	2004.7
	building, object)	building
44) History	9) significance	
Built in 1926 according to the	10) date	1926
Sanborn ins. co. map	I L	1)/20
•	11) style	
	12) architect	
	13) builder	
	14) original use	commercial
	15) present use	comercial
45) Additional description The entire facade is sheathed .		1
the entire tacade is sherthed	17) plan shape	
in architectural terra cotta of an offwhite		rectangle
color with contrast provided by various colour	e (D) basement	-
bands and other lecorative devices The	19) lodildation	
primary storefront faces Walnut and has a	20) wall construction	brick
corner catrance above which on either face	21) roof type -	flet
•	material	
(north anleast) there is a terra-cotta	, 22) contact print	
panel with the name "The John Williams Building	35mm	
also in terra-cotta. On the east side are	3311111	
several store fronts with clear luxor glass		
transons above the storefronts.	1	
	1	
	1	
46) Description of environment/outhuildings	(23) site plant to the	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
47) Information sources	24) changes -	
	24) changes - additions/alter-	
47) Information sources Sanborn 1933	24) changes - additions/alterations/moved	
47) Information sources	24) changes - additions/alterations/moved 25) condition	
47) Information sources Sanborn 1933	24) changes - additions/alterations/moved	
47) Information sources Sanborn 1933	24) changes - additions/alterations/moved 25) condition	
47) Information sources Sanborn 1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	
47) Information sources  Sanborn 1933	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #26	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	
47) Information sources  Sanborn: 1933  48) Location of negatives  roll 1 #26  roll 117 #14-15-17	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	
47) Information sources  Sanborn: 1933  48) Location of negatives  roll 1 #26  roll 117 #14-15,17	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	
47) Information sources  Sanborn: 1933  48) Location of negatives  roll 1 #26 roll 117 #14-17,17 DDD	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #26 roll 117 #14-15,17  DDD  50) Organization	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	no
47) Information sources  Sanborn 1933  48) Location of negatives  roll 1 #26  roll 117 #14-15,17  DDD	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	no
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #26 roll 117 #14-15,17  DDD  50) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #26 roll 117 #14-15,17  DDD  50) Organization	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	no
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #26 roll 117 #14-15,17 DDD  50) Organization	24) changes- additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #26 roll 117 #14-15,17 DDD  50) Organization  If additions are sees to see the sees to	24) changes- additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	
47) Information sources  Sanborn: 1933  48) Location of negatives roll 1 #26 roll 117 #14-15,17 DDD  50) Organization	24) changes- additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	no
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #26 roll 117 #14-15,17 DDD  50) Organization  If additions are sees to see the sees to	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district ) is site eligible?	
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #26 roll 117 #14-15,17 DDD  50) Organization	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district ) is site eligible? ) district potential?	no yes yes
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #26 roll 117 #14-15,17 DDD  50) Organization	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district ) is site eligible?	no yes
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #26 roll 117 #14-15,17 DDD  50) Organization	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district ) is site eligible? ) district potential?	no yes yes
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #26 roll 117 #14-15,17 DDD  50) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district ) is site eligible? ) district potential? ) date	no yes yes
47) Information sources  Sanborn 1933  48) Location of negatives roll 1 #26 roll 117 #14-15,17 DDD  50) Organization	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district ) is site eligible? ) district potential? ) date	no yes yes



#### Missouri Historic Architectural Inventory for (72-45-003-760)Division of Parks and Historic Preservation Department of Natural Resources

Division of rarks and mistoric reservation Deba		
38) Ownership — private *	1) inventory number	
— public	2) name (cont)	
39) Owners — name	3) name - historial	
— address	4) street address	313 W. Walnut st.
40) Local contact	5) town or vicinity	Springfield
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county	Greene
43) Other survey	8) category	Greene
	(site, structure,	
	building, object)	building
44) History	9) significance	
•	10) date	ca. 1930
	11) style	
	12) architect	
	13) builder	
	1	<del></del>
	14) original use	co mercial
45) Additional description	15) present use	domercial
45) Additional description  Flat parapet with stone coping.	16) number of stories	1
Very simple geometric motif decoration in stone	17) plan shape	rectangle
	18) basement	-
at the parapet and on the pilasters seperating	19) foundation	-
the store bays.	20) wall construction	brick
	21) roof type -	flat
	material	-
	22) contact print	
	35mm	
	1	
$\cup$		
_	}	
46) Description of environment/outbuildings	23) site plan	
To be description of environment/outburnuings		<del>┈╎╎╎╎╎┼┝</del> ┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼
· ·		
- Description of characteristings		
To bescription of chimomical journalings		
40/ Description of chimomically output langs		
47) Information sources	24) changes -	storefronts have
	24) changes - additions/alter-	storefronts have minor alterations
47) Information sources	24) changes -	
47) Information sources	24) changes - additions/alter-	
47) Information sources	24) changes - additions/alter-ations/moved	minor alterations
47) Information sources	24) changes - additions/alter- ations/moved 25) condition	minor alterations
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	minor alterations
47) Information sources  Sanborn 1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	minor alterations
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	minor alterations
47) Information sources  Sanborn 1933,  48) Location of negatives roll 101 ,/25	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	minor alterations
47) Information sources  Sanborn 1933	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	minor alterations
47) Information sources  Sanborn 1933  48) Location of negatives roll 101 #25  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	minor alterations
47) Information sources  Sanborn 1933,  48) Location of negatives roll 101 , 25	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	minor alterations
47) Information sources  Sanborn 1933  48) Location of negatives roll 101 #25  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	minor alterations
47) Information sources  Sanborn 1933  48) Location of negatives roll 101 #25  49) Prepared by  DUD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	minor alterations
47) Information sources  Sanborn 1933  48) Location of negatives roll 101 #25  49) Prepared by DDD  50) Organization I IIT	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	no no
47) Information sources  Sanborn 1933  48) Location of negatives roll 101 #25  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	no no
47) Information sources  Sanborn 1933  48) Location of negatives roll 101 #25  49) Prepared by DDD  50) Organization I III	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	no no
47) Information sources  Sanborn 1933  48) Location of negatives roll 101 #25  49) Prepared by DDD  50) Organization I III	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	no no
47) Information sources  Sanborn 1933  48) Location of negatives roll 101 #25  49) Prepared by DDD  50) Organization I III	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	no no no yes
47) Information sources  Sanborn 1933  48) Location of negatives roll 101 #25  49) Prepared by DDD  50) Organization I III	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	no no
47) Information sources  Sanborn 1933  48) Location of negatives roll 101 #25  49) Prepared by DDD  50) Organization I III	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	no no no yes
48) Location of negatives roll 101 #25  49) Prepared by DUD  50) Organization 1 HTT	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	no no no yes
48) Location of negatives roll 101 #25  49) Prepared by DUD  50) Organization 1 HTT	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	no no no yes



#### Missouri Historic Architectural Inventory for $G_{R-A5-003}$ - 731 Division of Parks and Historic Preservation Department of Natural Resources

201 Awarchin private	1) inventory number	7.300	
38) Ownership — private — public	2) name (cont)	P-1257	1=
39) Owners — name	3) name - historial		_
address	4) street address	(00) 11 11 2	_
40) Local contact	5) town or vicinity	608 W. Walnut st.	-
41) Coordinates (UTM)	6) legal description	Springfield	-
42) Quad	7) county	0	-
43) Other survey	8) category	Greene	-
To, Other Survey	(site, structure,		2/3)
	building, object)	Building	- }
44) History	9) significance		-
44, 1113(d) j	10) date	1011	$\dashv$
	11) style	1911	$\dashv$
	12) architect		-
	13) builder		$\neg$
	14) original use	anont mont a	-
	15) present use	apartments	$\dashv$
45) Additional description	* 16) number of stories	Same 2	4
stone panel below the parapet	17) plan shape		$\dashv^{\Xi}$
with the following carved on it:"J.F.King	18) basement	rectangle	-
1911"	19) foundation	full	$\dashv$
•	20) wall construction	concrete	-
•	21) roof type -	brick	_
	material	flat	-
	22) contact print	L <del>-</del>	<u> </u>
	35mm		
46) Description of environment/outbuildings	23) site plan		9)
47) Information sources	24) changes -	porch removed	19
	additions/alter-	por en remoied	
	ations/moved		
	25) condition		
	26) visible from road?		
	27) distance/frontage		
	28) accessible?		- (
48) Location of negatives	29) preservation		$\neg$
Roll 120 #2	underway?	•	
49) Prepared by	30) endangered?		
DDD	31) on National		
50) Organization Missouri Heritage Trust	Register?	No	
missouri heritage irust	32) part of		7
and the second of the second o	established		
	historical district	110	
If additional space is needed, at	33) name of historica	'	
	district		
	34) is site eligible?	1.0	
	35) district potential?		
	36) date	4/30/84	—
	37) revision		
"To grant of the			
HISTORIC INVENTORY FORM	}		ĺ
MISSOURI HERITAGE TRUST		l .	



## Missouri Historic Architectural Inventory for CR- Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number 11,203	
public	2) name (cont)	
39) Owners — name	3) name - historial	
— address	4) street address 600 No. Walnut st.	<del></del> ,
		<b>⊣</b> i
40) Local contact	5) town or vicinity Springfield	
41) Coordinates UTM)	6) legal description	
42) Quad	7) county Greene	
43) Other survey	8) category	-
	(site, structure,	ت
•	building, object) Building	
AA\ Uistory	9) significance	$\dashv$
44) History	10) date	
	11) style <u>late Italianate</u>	
	12) architect	
	13) builder	!
	14) original use residence	
	15) presentuse apts.	$\neg$
45) Additional description	2,700	<u>4</u>
(a) the state of t		$\dashv$
	16CGail: 1C	$\dashv$
	19) foundation stone	
	20) wall construction frame/modern sid	lid
	21) roof type- truncated him	
	material asphalt shingle	
•	22) contact print	12
	35mm	
		!
		ì
		1
		1
$\bigcirc$		ı
		İ
46) Description of environment/outbuildings	23) site plan	(9
46) Description of environment/outbuildings	23) site plan	9)
46) Description of environment/outbuildings	The state of the s	9)
46) Description of environment/outbuildings	The state of the s	9)
46) Description of environment/outbuildings		9)
46) Description of environment/outbuildings	The state of the s	9)
46) Description of environment/outbuildings  47) Information sources	24) changes -	9) 5)
	24) changes -	
47) Information sources	24) changes - additions/alter- ations/moved	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	5)
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	5)
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	5)
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	5)
47) Information sources  48) Location of negatives  Roll 133 #12	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	5)
47) Information sources  48) Location of negatives  Roll 133 #12  49) Prepared by	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	5)
47) Information sources  48) Location of negatives  Roll 133 #12	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No	5)
47) Information sources  48) Location of negatives  Roll 133 #12  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of	5)
47) Information sources  48) Location of negatives  Roll 133 #12  49) Prepared by	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established	5)
48) Location of negatives  Roll 133 #12  49) Prepared by  50) Organization Missouri Heritage Trust	24) changes additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No	5)
47) Information sources  48) Location of negatives  Roll 133 #12  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district NO	5)
48) Location of negatives  Roll 133 #12  49) Prepared by  50) Organization Missouri Heritage Trust	24) changes additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No	5)
48) Location of negatives  Roll 133 #12  49) Prepared by  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible?	5)
48) Location of negatives  Roll 133 #12  49) Prepared by  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 34) is site eligible?	5)
48) Location of negatives  Roll 133 #12  49) Prepared by  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	5) 6)
48) Location of negatives  Roll 133 #12  49) Prepared by  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 34) is site eligible? 35) district potential? 36) date  5/9/84	5) 6)
48) Location of negatives  Roll 133 #12  49) Prepared by  50) Organization Missouri Heritage Trust  If additional space is no	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	5) 6)
48) Location of negatives  Roll 133 #12  49) Prepared by  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 34) is site eligible? 35) district potential? 36) date  5/9/84	5) 6)



## Missouri Historic Architectural Inventory for GRAS-003-703 Division of Parks and Historic Preservation Department of Natural Resources

70\0	• 1 1) invariant to 405d
38) Ownership — private	* 1) inventory number P_1258
— public	2) name (cont)
39) Owners — name	3) name - historial
addres -	4) street address 614 W. Walnut st.
40) Local contact	5) town or vicinity   Springfield
41) Coordinates (UTM)	6) legal description
42) Quad	7) county Greene
43) Other survey	
	8) category (site, structure,
	building, object) Building
	9) significance
44) History	
	10) date ca. 1910
	11) style
	12) architect
	13) builder
	14) original use apartments
	15) present use Same
AEV Additional description	16) number of stories 2 with attic ±
45) Additional description	
	17) plan shape rectangle
	18) basement full
	19) foundation concrete
	20) wall construction brick
	21) roof type - gable
	material ashhalt shingle
	22) contact print
	35mm
( )	
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	The same and the s
46) Description of environment/outbuildings	The same and the s
46) Description of environment/outbuildings	The same and the s
46) Description of environment/outbuildings	
46) Description of environment/outbuildings	
46) Description of environment/outbuildings  47) Information sources	
	24) changes - additions/alter-
	24) changes - additions/alter- ations/moved
	24) changes - additions/alter- ations/moved 25) condition
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  29) preservation
47) Information sources  48) Location of negatives  Roll 120 #3	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
47) Information sources  48) Location of negatives  Roll 120 #3  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
47) Information sources  48) Location of negatives  Roll 120 #3  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 120 #3  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO
47) Information sources  48) Location of negatives  Roll 120 #3  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO
47) Information sources  48) Location of negatives  Roll 120 #3  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established
47) Information sources  48) Location of negatives  Roll 120 #3  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district NO
47) Information sources  48) Location of negatives  Roll 120 #3  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established
48) Location of negatives  Roll 120 #3  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district NO
48) Location of negatives  Roll 120 #3  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible?
48) Location of negatives  Roll 120 #3  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible?
48) Location of negatives  Roll 120 #3  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
48) Location of negatives  Roll 120 #3  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date
48) Location of negatives  Roll 120 #3  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
48) Location of negatives  Roll 120 #3  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date
48) Location of negatives  Roll 120 #3  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date



# Missouri Historic Architectural Inventory for Ge-G - 734 Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number P-1259
— pub ic	2) name (cont)
39) Owners — name	3) name - historial
— address	4) street address 620 W.Walnut st.
40) Local contact	
41) Coordinates (UTM)	5) town or vicinity Springfield 6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
	(site, structure,
	building, object) Building
44) History	9) significance
THE THIS COLUMN TO THE THE THE THE THE THE THE THE THE THE	
	33,7 27,13
	11) style bungalow
	12) architect
	13) builder
	14) original use residence
	1001401100
45) Additional description	
	- d
	17) plan shape rectangle
	18) basement full
	19) foundation stone
	20) wall construction lap siding
	TOO STOTIES
	material asphalt siding
·	22) contact print
	35mm
46) Description of environment/outbuildings	23) site plan
47) Information sources	24) changes -
	additions/alter-
	ations/moved
	25) condition
	25) condition
	26) visible from road?
	26) visible from road? 27) distance/frontage
	26) visible from road? 27) distance/frontage 28) accessible?
48) Location of negatives	26) visible from road? 27) distance/frontage
48) Location of negatives	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
Roll 120 #4	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
Roll 120 #4	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
Roll 120 #4  49) Prepared by  DDD	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
Roll 120 #4  49) Prepared by  DDD	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO
Roll 120 #4  49) Prepared by  DDD	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
Roll 120 #4  49) Prepared by  DDD	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO
Roll 120 #4  49) Prepared by  DDD	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of
Roll 120 #4  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district NO
Roll 120 #4  49) Prepared by  DDD	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical
Roll 120 #4  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	26) visible from road? 27) distance/frontage 28) accessible?  29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district
Roll 120 #4  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible?
Roll 120 #4  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district NO 33) name of historical district 34) is site eligible? 35) district potential?
Roll 120 #4  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible?
Roll 120 #4  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district NO 33) name of historical district 34) is site eligible? 35) district potential?
Roll 120 #4  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  NO
Roll 120 #4  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  NO



#### Missouri Historic Architectural Inventory for GR-A-O63-705Division of Parks and Historic Preservation Department of Natural Resources

	<del></del>	7: 6:
38) Ownership private	* 1) inventory number	11-204
public	2) name (cont)	
39) Owners — name	3) name - historial	
address	4) street address	623 W. Walnut st.
		<del></del>
40) Local contact	5) town or vicinity	Springfield
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county	Chann
		Greene
43) Other survey	8) category	
	(site, structure,	5
	building, object)	Building
7/\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	9) significance	
44) History		
	10) date	ca. 1890
	11) style	late Italianate
	12) architect	2300 200 22 200 200
	13) builder	
	14) original use	residence
	15) present use	funearal parlor
45) Additional description	16) number of stories	2
	17) plan shape	rectangle
	18) basement	
	1	
	19) foundation	_
	20) wall construction	frame/modern sidir
	21) roof type -	
	· ·	truncated hip
	material	asphalt shingle
•	22) contact print	9
	35mm	
		•
$\circ$		
0		
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings		
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings		
46) Description of environment/outbuildings		
46) Description of environment/outbuildings		
46) Description of environment/outbuildings  47) Information sources	24) changes -	
		modern additions
	24) changes - additions/alter-	
	24) changes - additions/alter-ations/moved	modern additions
	24) changes - additions/alter- ations/moved 25) condition	modern additions across the facade
	24) changes - additions/alter-ations/moved	modern additions across the facade
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	modern additions across the facade
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	modern additions across the facade
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	modern additions across the facade
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	modern additions across the facade
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	modern additions across the facade
47) Information sources  48) Location of negatives  Roll 133 #13	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	modern additions across the facade
47) Information sources  48) Location of negatives  Roll 133 #13  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	modern additions across the facade
47) Information sources  48) Location of negatives  Roll 133 #13	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	modern additions across the facade
47) Information sources  48) Location of negatives  Roll 133 #13  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	modern additions across the facade
47) Information sources  48) Location of negatives  Roll 133 #13  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	modern additions across the facade
47) Information sources  48) Location of negatives  Roll 133 #13  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	modern additions across the facade
47) Information sources  48) Location of negatives  Roll 133 #13  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	modern additions across the facade
47) Information sources  48) Location of negatives  Roll 133 #13  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	modern additions across the facade
48) Location of negatives  Roll 133 #13  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	modern additions across the facade
48) Location of negatives  Roll 133 #13  49) Prepared by  DDD  50) Organization Missouri Heritage Trust  If additional space is needed, attache	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica	modern additions across the facade
47) Information sources  48) Location of negatives  Roll 133 #13  49) Prepared by  DDD  50) Organization Missouri Heritage Trust  If additional space is needed, attache	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district	modern additions across the facade  No  No
48) Location of negatives  Roll 133 #13  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible?	modern additions across the facade  No  No
47) Information sources  48) Location of negatives  Roll 133 #13  49) Prepared by  DDD  50) Organization Missouri Heritage Trust  If additional space is needed, attache	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district	modern additions across the facade  No  No
47) Information sources  48) Location of negatives  Roll 133 #13  49) Prepared by  DDD  50) Organization Missouri Heritage Trust  If additional space is needed, attache	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential?	modern additions across the facade  No  No  No
47) Information sources  48) Location of negatives  Roll 133 #13  49) Prepared by  DDD  50) Organization Missouri Heritage Trust  If additional space is needed, attache	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential? 36) date	modern additions across the facade  No  No
47) Information sources  48) Location of negatives  Roll 133 #13  49) Prepared by  DDD  50) Organization Missouri Heritage Trust  If additional space is needed, attache	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential?	modern additions across the facade  No  No  No
48) Location of negatives  Roll 133 #13  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential? 36) date	modern additions across the facade  No  No  No
48) Location of negatives  Roll 133 #13  49) Prepared by  DDD  50) Organization Missouri Heritage Trust  If additional space is needed. attacho	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential? 36) date	modern additions across the facade  No  No  No



#### Missouri Historic Architectural Inventory for GRADIOS - 7060 Division of Parks and Historic Preservation Department of Natural Resources

Division of Farks and Historic Frescribition	
38) Ownership — private	• 1) inventory number 11–205
— pubac	2) name (cont)
39) Owners — name	3) name - historial
— address	4) street address 629 W. Walnut st.
40) Local contact	5) town or vicinity   Springfield
41) Coordinates (UTM)	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
	(site, structure,
	building, object) Building
44) History	9) significance architectural
	10) date ca. 1895-1900
	111
	12) architect
	13) builder
	15) magazitus
45) Additional description	
- Additional description	
	<u> </u>
	partrai
	19) foundation stone
	20) wall construction frame/lap siding
	21) roof type hip with gable v
	material asphalt shingle
·	22) contact print 35mm
46) Description of environment/outhwildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings  47) Information sources	
	24) changes -
47) Information sources	24) changes - additions/alter-
47) Information sources	24) changes - additions/alterations/moved
47) Information sources	24) changes - additions/alter- ations/moved 25) condition
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources  48) Location of negatives  Roll 133 #14-15	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
47) Information sources  48) Location of negatives  Roll 133 #14-15  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
47) Information sources  48) Location of negatives  Roll 133 #14-15  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 133 #14-15  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No
47) Information sources  48) Location of negatives  Roll 133 #14-15  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 133 #14-15  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established
47) Information sources  48) Location of negatives  Roll 133 #14-15  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established
47) Information sources  48) Location of negatives  Roll 133 #14-15  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical
47) Information sources  48) Location of negatives  Roll 133 #14-15  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No 33) name of historical district
47) Information sources  48) Location of negatives  Roll 133 #14-15  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible?
47) Information sources  48) Location of negatives  Roll 133 #14-15  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
47) Information sources  48) Location of negatives  Roll 133 #14-15  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible?



Missouri Historic Architectural Inventory for GR-185-003-737

Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private *	1)	inventory number	P-1260	JE
public	2)	name (cont)		- -
39) Owners — name	31	name - historial		-
— address	1			4
	1 '	street address	632 W.Walnut st.	
40) Local contact	5)	town or vicinity	Springfield	
41) Coordinates (JTM)	6)	legal description		
42) Quad	7)	county	Change	┪
43) Other survey		category	Greene	-
40) Other Survey	37			2/3)
	Ì	(site, structure,	D. 21 12 .	3
		building, object)	Building	
44) History	9)	significance		_
		date	7.04.0	$\dashv$
			ca.1910	
		style		_
	12)	architect		
	13)	builder		$\neg$
	141	original use		-
			<u>apartments</u>	-
		present use	şame	
45) Additional description The steps leading to the build	31 ·	number of stories	<u> </u>	4
	17)	plan shape	rectangle	$\neg$
-ing entrance are stone. The porch and			full	$\dashv$
second story porch access have been altered	34°C	foundation		-
Flat arch brick lintels on the facade with			stone	
segmental arch window lintels on the side		wall construction	brick	
	21)	roof type -	flat	
and rear elevations. The flat parapet has		material		_
brick corbelling.	22)	contact print		<del>-</del> -
g	221			5)
		35mm		
	1.		•	
_				
46) Description of environment/outbuildings	23)	site plan		9
46) Description of environment/outbuildings	23)	site plan		9)
46) Description of environment/outbuildings	23)	site plan		9)
46) Description of environment/outbuildings	23)	site plan		9)
46) Description of environment/outbuildings	23)	site plan		9)
46) Description of environment/outbuildings	23)			9)
46) Description of environment/outbuildings				9)
46) Description of environment/outbuildings  47) Information sources		changes -		9) 5)
		changes - additions/alter-		
	24)	changes - additions/alter- ations/moved		
	24)	changes - additions/alter- ations/moved		
	24)	changes - additions/alter- ations/moved condition visible from road?		
	24)	changes - additions/alter- ations/moved		
	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road? distance/frontage		5)
47) Information sources	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?		
47) Information sources  48) Location of negatives	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?		5)
47) Information sources  48) Location of negatives  Roll 120 #5-6	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?		5)
47) Information sources  48) Location of negatives	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?		5)
47) Information sources  48) Location of negatives  Roll 120 #5-6  49) Prepared by	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?		5)
47) Information sources  48) Location of negatives  Roll 120 #5-6  49) Prepared by  DDD	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National		5)
47) Information sources  48) Location of negatives  Roll 120 #5-6  49) Prepared by  DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?		5)
47) Information sources  48) Location of negatives  Roll 120 #5-6  49) Prepared by	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of		5) 6)
47) Information sources  48) Location of negatives  Roll 120 #5-6  49) Prepared by  DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?		5) 6)
47) Information sources  48) Location of negatives  Roll 120 #5-6  49) Prepared by  DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	No	5) 6)
47) Information sources  48) Location of negatives  Roll 120 #5-6  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	No	5) 6)
47) Information sources  48) Location of negatives  Roll 120 #5-6  49) Prepared by  DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	No	5) 6)
47) Information sources  48) Location of negatives  Roll 120 #5-6  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	No	5) 6)
47) Information sources  48) Location of negatives  Roll 120 #5-6  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	No No	5) 6) 7)
47) Information sources  48) Location of negatives  Roll 120 #5-6  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	No No	5) 6) 7)
47) Information sources  48) Location of negatives  Roll 120 #5-6  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	No No No	5) 6) 7)
47) Information sources  48) Location of negatives  Roll 120 #5-6  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	No No	5) 6)
47) Information sources  48) Location of negatives  Roll 120 #5-6  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	No No No	5) 6) 7)
47) Information sources  48) Location of negatives  Roll 120 #5-6  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	No No No	5) 6) 7)
47) Information sources  48) Location of negatives  Roll 120 #5-6  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	No No No	5) 6) 7)



#### Missouri Historic Architectural Inventory for G-12-13-3-73% Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number 1.–206	F
— public	2) name (cont)	
39) Owners — name	3) name - historial	
address	4) street address 633 W.Walnu	ut et
40) Local contact		ut sta
41) Coordinates (UTM)	5) town or vicinity Springfield 6) legal description	
42) Quad		
43) Other survey	8) category	tio)
	(site, structure, building object) Building	٤
	3, 12,131,	
44) History	9) significance architectu	ral
	10) date ca. 1900	
	11) style early cat.	-builder
	12) architect	, ,
	13) builder	
	14) original use residence	
45) Additional description		<del></del>
Top Additional description		= =====================================
	17) plan shape irregular	
	18) basement partial	
	19) foundation stone	
	20) wall construction frame/lap	siding
	21) roof type - hip with g	
	material asphalt sh	
•	22) contact print	ز
	35mm	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	· · · · · · · · · · · · · · · · · · ·
46) Description of environment/outbuildings		
46) Description of environment/outbuildings		
46) Description of environment/outbuildings		
46) Description of environment/outbuildings		
46) Description of environment/outbuildings  47) Information sources	24) changes -	
	24) changes - additions/alter-	
	24) changes - additions/alter- ations/moved	
	24) changes - additions/alter-	
	24) changes - additions/alter- ations/moved	
	24) changes - additions/alter- ations/moved 25) condition	
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	
48) Location of negatives  Roll 133 #16.18	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	
47) Information sources  48) Location of negatives  Roll 133 #16,18  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	
47) Information sources  48) Location of negatives  Roll 133 #16,18  49) Prepared by  DID	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
47) Information sources  48) Location of negatives  Roll 133 #16,18  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No	
47) Information sources  48) Location of negatives  Roll 133 #16,18  49) Prepared by  DID	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of	
47) Information sources  48) Location of negatives  Roll 133 #16,18  49) Prepared by  DID	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established	
47) Information sources  48) Location of negatives  Roll 133 #16,18  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No	
47) Information sources  48) Location of negatives  Roll 133 #16,18  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No 33) name of historical	
48) Location of negatives  Roll 133 #16,18  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district	
48) Location of negatives  Roll 133 #16,18  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible?	
47) Information sources  48) Location of negatives  Roll 133 #16,18  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	
47) Information sources  48) Location of negatives  Roll 133 #16,18  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5 / 9 / 8 /L	
48) Location of negatives  Roll 133 #16,18  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	
47) Information sources  48) Location of negatives  Roll 133 #16,18  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5 / 9 / 8 /L	
48) Location of negatives  Roll 133 #16,18  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5 / 9 / 8 /L	



#### Missouri Historic Architectural Inventory for G12 (45043-729) Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number 1207
— pub ic	2) name (cont)
39) Owners — name	3) name - historial
address	4) street address 639 W.Walnut st.
40) Local contact	5) town or vicinity Springfield
41) Coordinates (UTM)	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category (site structure
	Des 3 12 may
·	building, object) Building
44) History	9) significance
	10) date ca. 1935
	11) style Spanish Mission
	12) architect
·	13) builder
	14) original use filling station
	15) present use same
45) Additional description	16) number of stories
	17) plan shape rectangle
	18) basement no
	19) foundation concrete
	20) wall construction frame/stucco cover
	21) roof type-
	material asphalt shingle
·	22) contact print
	35mm
	· I
	1
46) Description of environment/outbuildings	23) site plan
40) Description of environment/outburndings	
47) Information sources	24) changes -
Try mormation sources	additions/alter-
<b>1</b>	ations/moved
	25) condition
	25) condition 26) visible from road?
	26) visible from road?
	26) visible from road? 27) distance/frontage
48) Location of negatives	26) visible from road? 27) distance/frontage 28) accessible?
48) Location of negatives	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
Roll 133 #17	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
Roll 133 #17	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
Roll 133 #17 49) Prepared by  DDD	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
Roll 133 $\#17$	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No
Roll 133 #17 49) Prepared by  DDD	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
Roll 133 #17 49) Prepared by  DDD	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO
Roll 133 #17 49) Prepared by  DDD	26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established
Roll 133 #17  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	26) visible from road? 27) distance/frontage 28) accessible?  29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No
Roll 133 #17  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	26) visible from road? 27) distance/frontage 28) accessible?  29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible?
Roll 133 #17  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	26) visible from road? 27) distance/frontage 28) accessible?  29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible?
Roll 133 #17  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	26) visible from road? 27) distance/frontage 28) accessible?  29) preservation underway? 30) endangered? 31) on National Register? NO  32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
Roll 133 #17  49) Prepared by  50) Organization Missouri Heritage Trust  If additional space is needed, attached	26) visible from road? 27) distance/frontage 28) accessible?  29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
Roll 133 #17  49) Prepared by  50) Organization Missouri Heritage Trust  If additional space is needed, attached	26) visible from road? 27) distance/frontage 28) accessible?  29) preservation underway? 30) endangered? 31) on National Register? No  32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  28) visible from road? No  No  No  No  No  No  No  No  No  No
Roll 133 #17  49) Prepared by  50) Organization Missouri Heritage Trust  If additional space is needed, attached	26) visible from road? 27) distance/frontage 28) accessible?  29) preservation underway? 30) endangered? 31) on National Register? No  32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  28) visible from road? No  No  No  No  No  No  No  No  No  No



#### Missouri Historic Architectural Inventory for GR - AS - CGS - 730Division of Parks and Historic Preservation Department of Natural Resources

	·	
38) Ownership — private	* 1) inventory number	P-1261
— public	2) name (cont)	
39) Owners — name	3) name - historial	
— address	4) street address	710 W.Walnut st.
40) Local contact	5) town or vicinity	Springfield
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county	Greene
43) Other survey	8) category	
	(site, structure,	Building
	building, object)	Building
44) History	9) significance	
	10) date	
	11) style	<u>late catbuilder</u>
	12) architect	
	13) builder	
	14) original use	residence
	15) present use	same
45) Additional description	* 16) number of stories	_2
	17) plan shape	square
	18) basement	füll
	19) foundation	stone
	20) wall construction	frame/lap siding
	21) roof type -	hip
	material	asphalt shingle
·	22) contact print	
	35mm	
	•	
_		
46) Description of environment/outbuildings	23) site plan	
,		
		<del>╎┙┊┞┊┞┞┆┊╃┞┪┆╏╏╬</del>
47) Information sources	24) changes -	<del>╎╛┊┞┋╄╏┆┊╄┡┪╏╏╏</del> ╊ ┰
47) Information sources		<del>┊╛┊╏╏╂╏┆┊╄┡╉╏╏╏╏</del> ┃
47) Information sources	24) changes -	
47) Information sources	24) changes - additions/alter-	
47) Information sources	24) changes - additions/alter- ations/moved	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	
48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	
48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	
48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	
48) Location of negatives  Roll 142 #20  49) Prepared by Roll 117 #1  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	
48) Location of negatives  Roll 142 #20  49) Prepared by Roll 117 #1	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
48) Location of negatives  Roll 142 #20  49) Prepared by  Roll 117 #1  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	
48) Location of negatives  Roll 142 #20  49) Prepared by  Roll 117 #1  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	No
Roll 142 #20  49) Prepared by Roll 117 #1  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	No
Roll 142 #20 49) Prepared by Roll 117 #1 DDD 50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	No
Roll 142 #20 49) Prepared by Roll 117 #1 DDD 50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica	No No
Roll 142 #20 49) Prepared by Roll 117 #1 DDD 50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	No No Yeu
Roll 142 #20 49) Prepared by Roll 117 #1 DDD 50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible?	No No Ye. Ye.
Roll 142 #20 49) Prepared by Roll 117 #1 DDD 50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential	No No Yeu
Roll 142 #20 49) Prepared by Roll 117 #1 DDD 50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential	No No Ye. Ye.
Roll 142 #20  49) Prepared by Roll 117 #1  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential	No No Ye. Ye.



#### Missouri Historic Architectural Inventory for GR-AS-CCS-731 Division of Parks and Historic Preservation Department of Natural Resources

Division of Fairs and Historic Preservation Dep		
38) Ownership — private •	1) inventory number	P-1262
— public	2) name (cont)	
39) Owners — name	3) name - historial	
— address	4) street address	716 W.Walnut st.
40) Local contact	5) town or vicinity	Springfield
41) Coordinates (JTM) 42) Quad	6) legal description	
42) Quad 43) Other survey	7) county	Greene
45) Onle Survey	8) category	
	(site, structure, building, object)	Building
44) History	9) significance	
17) HOW J	10) date	
	11) style	penly ant huilden
	12) architect	early catbuilder
	13) builder	
	14) original use	residence
	15) present use	same
45) Additional description	* 16) number of stories	2
	17) plan shape	irregular
	18) basement	partial?
	19) foundation	stone
	20) wall construction	frame/lap siding
	21) roof type -	gable
	material	asphalt shingle
•	22) contact print	apinaro pirmere
	35mm	
		ı
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings		
46) Description of environment/outbuildings		
46) Description of environment/outbuildings		
46) Description of environment/outbuildings 47) Information sources	24) changes -	
	24) changes - additions/alter-	
	24) changes - additions/alterations/moved	
	24) changes - additions/alter- ations/moved 25) condition	
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road	
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway?	
48) Location of negatives  Roll 142 #21-22  49) Prepared by Roll 117 #44	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	
47) Information sources  48) Location of negatives  Roll 142 #21-22  49) Prepared by  Roll 117 #44  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
48) Location of negatives  Roll 142 #21-22  49) Prepared by Roll 117 #44	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	
47) Information sources  48) Location of negatives  Roll 142 #21-22  49) Prepared by  Roll 117 #44  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
47) Information sources  48) Location of negatives  Roll 142 #21-22  49) Prepared by  Roll 117 #44  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	No
47) Information sources  48) Location of negatives  Roll 142 #21-22  49) Prepared by  Roll 117 #44  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	No
47) Information sources  48) Location of negatives  Roll 142 #21-22  49) Prepared by Roll 117 #44  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	No
47) Information sources  48) Location of negatives  Roll 142 #21-22  49) Prepared by Roll 117 #44  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district name of historica	No
47) Information sources  48) Location of negatives  Roll 142 #21-22  49) Prepared by Roll 117 #44  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district name of historical district	No No
47) Information sources  48) Location of negatives  Roll 142 #21-22  49) Prepared by Roll 117 #44  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district name of historical district is site eligible?	No No
47) Information sources  48) Location of negatives  Roll 142 #21-22  49) Prepared by Roll 117 #44  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district name of historical district is site eligible?	No No No No No Ne No Ne Ne Ne Ne Ne Ne Ne Ne Ne Ne Ne Ne Ne
47) Information sources  48) Location of negatives  Roll 142 #21-22  49) Prepared by Roll 117 #44  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district name of historical district is site eligible? district potential	No No No No No Ne No Ne Ne Ne Ne Ne Ne Ne Ne Ne Ne Ne Ne Ne



#### Missouri Historic Architectural Inventory for G R = A + B + B + B + BDivision of Parks and Historic Preservation Department of Natural Resources

39) Owners = name		partitiont of italaiai		
2   name (cant)   39) Owners - mane   30   name - habital   40   40   Location stands   50   50   60   60   60   60   60   60	38) Ownership — private	* 1) inventory number	-208	T.
33 name historias	— public	2) name (cont)		7`
40  Locationate   41  Street address   727   Missinut St.	39) Owners name			-
4-00		\ '	MARI II II II II II II II II II II II II I	
42) Location of negatives  43) Characteristics  44) Description of environmenticulturilings  46) Description of environmenticulturilings  47) Information sources  48) Location of negatives  48) Location of negatives  48) Location of negatives  48) Location of negatives  48) Location of negatives  48) Location of negatives  48) Location of negatives  48) Location of negatives  48) Location of negatives  48) Location of negatives  48) Location of negatives  48) Location of negatives  49) Prepared by  50) Organization  Missouri Heritage Trust  40) Additional specific or the properties of the properties			/2/ 11. Wainut St.	_
42) Docardinates (LTM) 43) Other survey  44) History  44) History  45) Additional description  45) Additional description  45) Additional description  46) Description of environmentourbuildings  47) Information sources  48) Location of negatives  48) Location of negatives  48) Location of negatives  48) Location of negatives  48) Location of negatives  48) Location of megatives  48) Location of megatives  48) Location of megatives  48) Location of megatives  48) Location of megatives  48) Location of megatives  48) Location of megatives  48) Location of megatives  49) Prepared by  50) Organization  Missouri Heritage Trust  40) Hardinonal spain  41) Information sources  42) DDD  50) Organization  Missouri Heritage Trust  45) Additional spain  46) Location of megatives  47) Information sources  48) Location of megatives  49) Prepared by  49) Prepared by  50) Organization  Missouri Heritage Trust  40) Missouri Heritage Trust  41) Missouri Heritage Trust  42) DDD  53) Organization  44) Missouri Heritage Trust  45) Additional spain  46) Location of megatives  47) Information sources  48) Location of megatives  49) Prepared by  50) Organization  60) Missouri Heritage Trust  41) Missouri Heritage Trust  42) Missing eligible?  43) Instruction of megatives  44) Missouri Heritage Trust  45) Additional spain  46) Location of megatives  47) Information membranes  48) Location of megatives  49) Prepared by  50) Organization  60) Missouri Heritage Trust  61) Missouri Heritage Trust  63) district presential Missouri Missou	40) Local contact	5) town or vicinity	Sprinafield	
42) Quad  43) Other survey  8) category (site structure, building, object)  44) History  9) significance of the survey of the structure of the survey of the structure of the survey of the structure of the survey	41) Coordinates (UTM)	6) legal description		٦
43) Cheer survey  8) Category Safe Structure, building, object)  44) History  9) Significance 10 date 111 style 122 architect 133 builder 112 architect 133 builder 112 architect 135 builder 112 architect 135 builder 112 architect 135 builder 112 architect 135 builder 112 architect 135 builder 112 architect 135 builder 112 architect 135 builder 112 architect 135 busement 195 foundation 125 persent use 115 presen	42) Quad		Ciacana	┪
(alte structure, building, object)  ### Duilding object)  ### Spidenicance    100 date			<u> </u>	_
### Partition of Environment Nourbuildings  ### Additional description  #### Additional description  #### Additional description  #### Additional description  #### Additional description  #### Additional description  ##### Additional description  ##### Additional description  ##### Additional description  ######### Additional description  ###################################	43) Other survey			1,
44) History  9 Significance 100 date 111 style 122 architect 133 builder 143 original use 153 present use 154 present use 154 present use 155		(site, structure,		1
45) Additional description  45) Additional description  45) Additional description  45) Additional description  45) Additional description  46) Description of environment/outbuildings  46) Description of environment/outbuildings  47) Information sources  48) Location of negatives  48) Location of negatives  48) Location of megatives  48) Location of megatives  48) Location of megatives  48) Location of megatives  48) Location of megatives  48) Location of megatives  48) Location of megatives  48) Location of megatives  48) Location of megatives  48) Location of megatives  48) Location of megatives  48) Location of megatives  48) Location of megatives  48) Location of megatives  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust  10) Missouri Heritage Trust  11) Madditional specific potential solution of megatives and meaning the meaning of meaning the meani		building, object)	Building	
10 date   11 style   12 architect   13 builder   14 Cat. = Initider   15 present use   15	44) History			-
111 style   22 architect   13 builder   140 original use   150 present use   150 p	44) History	l L.	contributing	4
12  architect   13  builder   14  original use   15  present use   15  present use   15  present use   15  present use   15  present use   16  present use   17  plan shape   18  basement   19  foundation   20  wall construction   21  prof type   materia   22  contact print   25  materia   25  contact print   25  contact pr		1		
45) Additional description  45) Additional description  45) Additional description  46) Description of environmentioutbuildings  46) Description of environmentioutbuildings  47) Information sources  48) Location of negatives  Roll 133 #19-20  49) Prepared by  DDD  50) Organization  Missouri Herritage Trust  Madditional sp  Missouri Herritage Trust  Missouri Herritage Trust  Missouri Herritage Trust  Missouri Herritage Trust  Missouri Herritage Trust  Missouria district 331 name of historical district 341 is site eligible? 350 date 377 revision		11) style	late cat -builder	
45) Additional description  10) Information sources  46) Description of environment outbuildings  47) Information sources  48) Location of negatives  Roll 133 //19-20  49) Prepared by  DDD  Sol Organization  Missouri Heritage Trust  13) builder 140 prepared by  DDD  Missouri Heritage Trust  14) prepared by  DDD  Missouri Heritage Trust  14) Additional sp.  15) present use  16) busines of stories  17) plan happee 18  18) basement 19  19) foundation 20) wall construction 21) ror type- material  22) confact print 35mm  23) site plan  24) changes- additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  30) engagere? 31) on National Register? 30) engagere? 31) on National Register? 32) purt of established No No No No No No No No No No No No No		12) architect		_
45) Additional description  10) Additional description  11) present use  12) present use  13) present use  14) fundation  20) wall construction  21) roof type- material  22) contact print  35mm  23) site plan  46) Description of environmentioutbuildings  24) changes- additions/alter- atlons/moved  25) condition  26) visible from road?  27) distancesfrontage  28) accessible?  48) Location of negatives  AB) Location of negatives  AB) Location of negatives  AB) Location of megatives  Roll 133 #19-20  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust  Madditional sp  Missouri Heritage Trust		1		-
15) present use   Va.Camt   2   17) plan shape   18) basement   19) foundation   20) will construction   21) root type-material   22) contact print   35mm				
15  present use		14) original use	residence	
45) Additional description  16) number of stories 2 irregular 17) pin shape 18 basement 19 foundation 20) wall construction 21) roof type-material 22) contact print 35mm  46) Description of environmentioutbuildings  47) Information sources  48) Location of negatives Roll 133 #19-20  49) Prepared by DDD  50) Organization Missouri Heritage Trust  11		15) present use		7
17) plan shape 18) basement 19 foundation 20) wall construction 21) roof type- material 22) contact print 35mm  46) Description of environment outbuildings  23) site plan  47) Information sources  48) Location of negatives Roll 133 #19-20 49) Prepared by DDD  50) Organization Missouri Heritage Trust  18 description of negatives Roll 133 #19-20 19 preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 35 is site eligible? 36) date 37) revision	45) Additional description			+:
18) basement 19) foundation 20) wall construction 21) roof type   hip material 22) contact print 35mm   Sprint shingle 3   hip material 22) contact print 35mm   Sprint shingle 3   hip material 23   hip material 24   changes   hip material 25   hip material 26   hip material 27   hip material 27   hip material 28   hip material 28   hip material 28   hip material 28   hip material 29   hi	45) Additional description			վ՝
18) basement 19 foundation 20) wall construction 20) wall construction 21) roof type material 22) contact print 35mm  46) Description of environment/outbuildings  23) site plan 24) changes additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 28) accessible? 31) on National Register? 32) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 34) is site eligible? 35) district potential? 36) date 37) revision			irregular	_].
19) foundation   20) well construction   21) roof type   material   22) contact print   35mm   35m		1	์ กาา	.
20) wall construction 21) roof type material remarked process and the process		19) foundation		_
21)   roof type material				$\dashv$
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives  48) Location of negatives  Roll 133 #19-20  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust  ### Additional sp  ### Additional s			frame/modern_sidi	<u> </u>
### Additional sp  #### Additional sp  #### Additional sp  #### Additional sp  #### Additional sp  #### Additional sp  ###################################		21) roof type -		
46) Description of environment/outbuildings  23) site plan  47) Information sources  24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  48) Location of negatives  Roll 133 #19-20  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust  11 Additional sp.  12 Additional sp.  13 Additional sp.  14 Additional sp.  15 Additional sp.  16 Additional sp.  17 Additional sp.  18 Additional sp.  18 Additional sp.  19 Additional sp.  29 preservation underway? 30 endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date 37) revision		material		٦
46) Description of environment/outbuildings  23) site plan  47) Information sources  24) changes- additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 88 accessible?  48) Location of negatives  Roll 133 #19-20  49) Prepared by  DDD  50) Organization Missouri Heritage Trust  Madditional sp  Madditi	•	22) contact print	ASTURT PHTUSTS	- U
46) Description of environment/outbuildings  23) site plan  24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage  48) Location of negatives  Roll 133 #19–20  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust  11 additional sp  11 additional sp  11 additional sp  11 additional sp  12 yes reservation underway? 31) on National Register? 32 part of established historical district 33) name of historical district 33) name of historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date 37) revision		35mm		
47) Information sources  24) changes - additions/alter ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  48) Location of negatives  Roll 133 #19-20  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust  18 Additional sp  19 Additional sp  10 Additional sp  10 Additional sp  10 Additional sp  10 Additional sp  11 Additional sp  12 Additional sp  13 Additional sp  14 Additional sp  15 Additional sp  16 Additional sp  17 Additional sp  18 Additional sp  19 Additional sp  19 Additional sp  20 Additional sp  21 Additional sp  22 Additional sp  23 Dark of established historical district 33 Dark of established historical district 34) is site eligible? 35 district potential? 36 date 37) revision				
47) Information sources  24) changes - additions/alter ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  48) Location of negatives  Roll 133 #19-20  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust  18 Additional sp  19 Additional sp  10 Additional sp  10 Additional sp  10 Additional sp  10 Additional sp  11 Additional sp  12 Additional sp  13 Additional sp  14 Additional sp  15 Additional sp  16 Additional sp  17 Additional sp  18 Additional sp  19 Additional sp  19 Additional sp  20 Additional sp  21 Additional sp  22 Additional sp  23 Dark of established historical district 33 Dark of established historical district 34) is site eligible? 35 district potential? 36 date 37) revision	46) Description of environment/outbuildings	23) site plan		1 4
47) Information sources  24) changes- additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  48) Location of negatives  Roll 133 #19-20  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust  If additional sp.  If additional sp.  If additional sp.  All STARRICHMY MANY SORD  All STARRICHMY MANY	To Second the control of the control			i"
47) Information sources  24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  48) Location of negatives  Roll 133 #19-20  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust  If additional sp.  If additional sp.  If additional sp.  All Strict additions additions additions additional sp.  All Strict additions				
47) Information sources  24) changes-additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) date 37) revision				-
47) Information sources  24) changes-additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) date 37) revision	·			<del> </del>
47) Information sources  24) changes-additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) date 37) revision			<del></del>	$\vdash$
47) Information sources  24) changes—				-
additions/alterations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  48) Location of negatives  Roll 133 #19-20  49) Prepared by  DDD  30) endangered?  31) on National Register? Register? No  32) part of established historical district 34) is site eligible? 35) district potential? 36) date 37) revision  Also part of established historical district 34) is site eligible? 35) district potential? 36) date 37) revision				و
ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?  48) Location of negatives  Roll 133 #19-20  49) Prepared by  DDD  30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date 37) revision	47) Information sources	_		٦
25) condition 26) visible from road? 27) distance/frontage 28) accessible?  48) Location of negatives  Roll 133 #19-20  49) Prepared by  DDD  31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date 37) revision	s .	additions/alter-		
48) Location of negatives  Roll 133 #19-20  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust  If additional spanning and the standard district  31) in Alaman of historical district  33) name of historical district  34) is site eligible?  35) district potential?  36) date  37) revision	·	ations/moved	·	- 1
48) Location of negatives  Roll 133 #19-20  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust  If additional spanning and the standard district  31) in Alaman of historical district  33) name of historical district  34) is site eligible?  35) district potential?  36) date  37) revision		· · · · ·		$\dashv$
48) Location of negatives  Roll 133 #19-20  49) Prepared by  DDD  50) Organization Missouri Heritage Trust  If additional sps  If additional sps  All 133 #19-20  All 133 #19-20  30) endangered?  31) on National Register?  32) part of established historical district  33) name of historical district  34) is site eligible?  35) district potential?  36) date  37) revision		1		-
48) Location of negatives  Roll 133 #19-20  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust  If additional sp.  If additional sp.  Application of negatives  Roll 133 #19-20  30) endangered?  31) on National Register?  No  32) part of established historical district  33) name of historical district  34) is site eligible?  35) district potential?  36) date  37) revision  Application of negatives  No  No  130 on National Register?  No  331 on National Register?  No  332 of the properties of the pro		1 *		-
Roll 133 if 19-20  49) Prepared by  DDD  50) Organization  If additional sp  If additional sp  All 133 if 19-20  DDD  Missouri Heritage Trust  If additional sp  All 133 if 19-20  29) preservation underway?  30) endangered?  31) on National Register?  No  32) part of established historical district  33) name of historical district  34) is site eligible?  35) district potential?  36) date  37) revision		27) distance/frontage		
Roll 133 #19-20  49) Prepared by  DDD  50) Organization  If additional sp.  If additional sp.  All 133 #19-20  DDD  Missouri Heritage Trust  10		28) accessible?		5
Roll 133 #19-20  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust  If additional spi  If additional spi  All 133 #19-20  underway?  30) endangered?  31) on National Register? No  32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date 37) revision	40) 1			_
49) Prepared by  DDD  50) Organization  Missouri Heritage Trust  Missouri Heritage Trust  11 additional spanning and the properties of the				1
DDD  So) Organization Missouri Heritage Trust  Missouri Heritage Trust  Missouri Heritage Trust  Mo  State Additional specific and interest and inte	ROII 133 #19-20			_
50) Organization  Missouri Heritage Trust  Missouri Heritage Trust  Mo  Missouri Heritage Trust  Mo  Missouri Heritage Trust  Mo  Missouri Heritage Trust  Mo  Missouri Heritage Trust  Mo  Missouri Heritage Trust  Mo  Mo  Missouri Heritage Trust  Mo  Mo  Missouri Heritage Trust  Mo  Mo  Missouri Heritage Trust  Mo  Mo  Missouri Heritage Trust  Mo  Mo  Missouri Heritage Trust  Mo  Mo  Missouri Heritage Trust  Mo  Mo  Missouri Heritage Trust  Mo  Mo  Missouri Heritage Trust  Mo  Mo  Missouri Heritage Trust  Mo  Mo  Missouri Heritage Trust  Mo  Missouri Heritage Trust  Mo  Missouri Heritage Trust  Mo  Mo  Missouri Heritage Trust  Mo  Mo  Missouri Heritage Trust  Mo  Mo  Missouri Heritage Trust  Mo  Missouri	49) Prepared by	30) endangered?		
Register?  No  If additional specification  If additional specification  No  Register?  No  No  No  No  No  No  No  No  No  N		_		$\neg$
If additional sp.  If additional	EON Commitmention	1	l No	L
If additional space   No   Strict   No   Strict   No   Strict   St	Missouri Heritage Trust	- I	NO	\
historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date 37) revision	······································			
If additional sp.  33) name of historical district  34) is site eligible?  35) district potential?  36) date  37) revision		established		
33) name of historical district 34) is site eligible? 35) district potential? 36) date 37) revision	MARIAN MARKET	historical district	No	
district 34) is site eligible? 35) district potential? 36) date 37) revision  HISTORIC INVENTORIC INVENTORIC INC.	If additional sp.	33) name of historical		
34) is site eligible? 35) district potential? Ye 36) date 37) revision	in additional specific property of the specifi	·	l .	
35) district potential? Ye 36) date 5/9/85 37) revision		1		$\dashv$
36) date 5/9/85 37) revision				-
36) date 5/9/85 37) revision			Yes.	
HISTORIC INVENTORY FORM		35) district potential?		
HISTORIC INVENTORY FORM				
HISTORIC INVENTORY FORM		36) date		$\dashv$
HISTORIC INVENTORY FORM		36) date		
	——————————————————————————————————————	36) date		





## Missouri Historic Architectural Inventory for GRO - CC - 735 Division of Parks and Historic Preservation Department of Natural Resources

Division of Parks and Historic Preservation De	<u> </u>	
38) Ownership — private — public	* 1) inventory number 1'=1263 2) name (cont)	
39) Owners — name	3) name - historial	
addres	4) street address 730 W.Walnut st.	
40) Local contact	5) town or vicinity Springfield	
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county Greene	
43) Other survey	8) category	
	(site, structure,	
	building, object) Building	
44) History	9) significance	
	10) date	
	11) style <u>early catbuild</u>	der
	12) architect	
	13) builder	
	14) original use residence	
	15) present use Same	
45) Additional description	16) number of stories $2\frac{1}{2}$	
	17) plan shape irregular	[#.
	18) basement full	
	19) foundation stone 20) wall construction frame/lan siding	
	II ame I an oralli	<u> </u>
	1,4016	
	material asphalt shingle 22) contact print	
	35mm	
	,	
	<u> </u>	
46) Description of environment/outbuildings	23) site plan	1
•	<del>╶</del>	_
		П
		<del> - - </del>
	24) above	
47) Information sources	24) changes - additions/alter-	
	additions/aiter- ations/moved	
	25) condition	
	26) visible from road?	
C.T.S.E.T.W. FIL	M 5062 ontage	
	?	
48) Location of negatives	bn bn	
Roll 117 #L3		
Roll 117 #43 49) Prepared by Roll 142 #23-26	d?	
DDD		
50) O was institut	No	
. Missouri Heritage Trusc		
ECHAK SAF, TO A PARAMETER AND A STATE OF THE SAFE	Terrana d	
If additio		
	/84	
The second secon		
HISTORIC INVENTORY FORM MISSOURI HERITAGE TRUST	•	_

rother Dr 180 coeff: Cownge A. Callon Julia House

100 Stability 730 W. Walnut

ESSSARSED bY: Hayward Barnett

OWNER APPROVAL RECEIVED:

HSB AP ROVAL GRANTED: 12/12/82

BUILT BY: George A. McLaughlin

DARE SULT: ca. 1905

PR NEWT OWNERS: J. Harper

McClure Addition established in 1871. It is believed that an older house proviously occupied this lot dating from co. 1878 to the construction of the present house ca. 1905. The former dwelling carried the house number 608 according to the 1878 City Directory until the number was changed in 1889 to 730. In 1878 the house at this address was occupied by Mrs. Nottie Pacse Fox and her husband. Mrs. Fox was the leader of the popular Spiritualist movement in Springfield in 1877 which attracted the interest of a number of prominent citizens, and was active over a four year period. She was also the editor of the popular Spiritual over a four year period. She was also the editor of the popular works. Tradition holds that the present house was built by George 4. McLaughlin about 1905, and occupied by this family until ca. 1910. Mr. McLaughlin was an attorney and dealt in real estate.

The space of this two storey house is formed by two intersecting gables. The do input gable with flared caves which shapes the left side of the front or north elevation has an inset rectangular window and is covered with fish scale shingles. It is poised atop a projected three-planed bay which rises from the masonry foundation through the second storey to the gable pent. This pent is supported by paired knee braces at each side of the bay. A similarity formed bay projects from the ground storey of the east elevation. The east and west flared gable ends are marked by gable returns. A small, pedimented attic dormer with rectangular base balances the composition of the front elevation.

A raised, balustrated porch with tapered posts supported by ashlar pedestals extends the full width of the front of the house and part of the east elevation. With the exception of the shingled gable ends, the structure is covered with clapboard.

The near of the house features twp gabled attic dormers with recommendate bases and a projected two-storey mass with a salther roof. A further one-storey projection appears to have been a later addition to this turn-of-the century house.



## Missouri Historic Architectural Inventory for GRANGES - 734 Division of Parks and Historic Preservation Department of Natural Resources

20) Ownership Private	* 1) inventory number	<del></del>
38) Ownership — private	1) inventory number 1 = 209	5
pub ic	2) name (cont)	
39) Owners — name	3) name - historial	
addres :	4) street address 733 W. Walnut st.	,]
40) Local contact	5) town or vicinity Springfield	
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county Greene	
43) Other survey	8) category	<del></del> ,
	(site, structure,	į
	building, object) Building	}
44) History	9) significance	
447 (11300)		
	Ca 1900	
	L CALLY CAU DOMESTI	<u>ier</u>
	12) architect	
	13) builder	
	14) original use residence	
	15) present use	
45) Additional description	* 16) number of stories	
	17) plan shape irregular	
	10) becomes	
	10) foundation	
	St.one	
	truma/lan gidin	g
	acabalt shingle	
	22) contact print	:
1	35mm	
46) Description of environment/outbuildings	23) site plan	1_:
47) Information sources	24) changes -	
• a p	additions/alter-	
	ations/moved	
	25) condition	
	26) visible from road?	
	27) distance/frontage	
	28) accessible?	
48) Location of negatives	29) preservation	
Roll 133 #21	underway?	1
	30) endangered?	
49) Prepared by		
DDD	31) on National	
50) Organization Missouri Heritage Trust	Register? No	
	32) part of	
Market Market Control of the Control	established	
TO THE STATE OF TH	historical district No	
If additional space is needed, attached sepa	33) name of historical	
	district	
	34) is site eligible?	
	35) district potential? Ye -	
	35) district potential? $\frac{\gamma_e}{5/8/8\mu}$	
	35) district potential? Ye -	
MICTORIO INVENTORY CORV	35) district potential? $\frac{\gamma_e}{5/8/8\mu}$	
HISTORIC INVENTORY FORM MISSOURI HERITAGE TRUST	35) district potential? $\frac{\gamma_e}{5/8/8\mu}$	-



Missouri Historic Architectural Inventory for Garages Company 5 Division of Parks and Historic Preservation Department of Natural Resources

Division of Parks and historic Preservation		
38) Ownership — private	* 1) inventory number	P-1264
public	2) name (cont)	
39) Owners name	3) name - historial	
address	4) street address	736 W.Walnut st.
40) Local contact	5) town or vicinity	Springfield
41) Coordinates (UTM)	6) legal description	Spi Iligi le id
42) Quad	7) county	Greene
43) Other survey	8) category	
	(site, structure,	
	building, object)	Building
44) History	9) significance	
•	10) date	
	11) style	early catbuilder
	12) architect	early catbulluer
	13) builder	
	14) original use	ļ
	_	residence
45) Additional description	15) present use	apts.
45) Additional description	* 16) number of stories	~
	17) plan shape	irregular
•	18) basement	full?
	19) foundation	stone
	20) wall construction	frame/modern siding
	21) roof type -	galle-hip combo.
	material	asphalt shingle
·	22) contact print	
	35mm	
		•
· <u>·</u>		
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings  47) Information sources	24) changes -	
	24) changes -	
	24) changes - additions/alter-	
	24) changes - additions/alter-ations/moved	
	24) changes - additions/alter- ations/moved 25) condition	
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road	
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible?	
47) Information sources  48) Location of negatives  Roll142 #27-29  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation	
47) Information sources  48) Location of negatives  Roll1142 #27-29	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway?	
47) Information sources  48) Location of negatives  Roll142 #27-29  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	
47) Information sources  48) Location of negatives  Roll142 #27-29  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
47) Information sources  48) Location of negatives  Roll142 #27-29  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	
47) Information sources  48) Location of negatives  Roll142 #27-29  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	No
47) Information sources  48) Location of negatives  Roll142 #27-29  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of tablished	No
47) Information sources  48) Location of negatives  Roll142 #27-29  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of tablished storical district	No
47) Information sources  48) Location of negatives  Roll142 #27-29  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of tablished storical district	No No
48) Location of negatives  Roll142 #27-29  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of tablished storical district time of historical strict	No No
47) Information sources  48) Location of negatives  Roll142 #27-29  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of tablished storical district ime of historical strict site eligible? strict potential ate	No No No No No No No
47) Information sources  48) Location of negatives  Roll142 #27-29  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of tablished storical district ime of historical strict site eligible? strict potential	No No
47) Information sources  48) Location of negatives  Roll142 #27-29  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of tablished storical district ime of historical strict site eligible? strict potential ate	No No No No No No No
47) Information sources  48) Location of negatives  Roll142 #27-29  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of tablished storical district ime of historical strict site eligible? strict potential ate	No No No No No No No





# Missouri Historic Architectural Inventory for Color Co

38) Ownership — private *	1) inventory number	I211	Τ.
- public	2) name (cont)	11-211	۲
39) Owners — name	3) name - historial		┦
address	4) street address	727	-
40) Local contac:	5) town or vicinity	737 W.Walnut st.	1
41) Coordinates UTM)	6) legal description	<u>Springfield</u>	1
42) Quad	7) county		1
43) Other survey		Greene	-
43) Other Survey	8) category		(13)
	(site, structure,	Building	_
	building, object)		<u> </u>
44) History	9) significance	contributing	1
	10) date		]
	11) style	<u>late catbuilder</u>	]
	12) architect		
	13) builder		]
	14) original use	residence	
	15) present use	apts.	
45) Additional description	* 16) number of stories	2	£
	17) plan shape	rectangle	1.
	18) basement	_full	1
	19) foundation	concrete with stor	16-
	20) wall construction	frame/ yeneer	1
	21) roof type -	lap siding	-
	material	gable with asphali	
•	22) contact print		2
	35mm	shingle	
			1
			1
			1
			ı
46) Description of environment/outhuildings	23) site plan		9
46) Description of environment/outbuildings	23) site plan		9)
46) Description of environment/outbuildings			9)
46) Description of environment/outbuildings			9)
46) Description of environment/outbuildings			9)
46) Description of environment/outbuildings			9)
46) Description of environment/outbuildings  47) Information sources	24) changes -		9) 5)
	24) changes - additions/alter-		
	24) changes - additions/alter- ations/moved		
47) Information sources	24) changes - additions/alter- ations/moved 25) condition		
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?		
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage		5)
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?		
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation		5)
47) Information sources  48) Location of negatives  Roll 133 #22	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?		5)
47) Information sources  48) Location of negatives  Roll 133 #22  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?		5)
47) Information sources  48) Location of negatives  Roll 133 #22  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National		5)
47) Information sources  48) Location of negatives  Roll 133 #22  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?		5)   6)
47) Information sources  48) Location of negatives  Roll 133 #22  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National		5)
47) Information sources  48) Location of negatives  Roll 133 #22  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	No	5)   6)
47) Information sources  48) Location of negatives  Roll 133 #22  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	No	5)   6)
47) Information sources  48) Location of negatives  Roll 133 #22  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	No	5)   6)
47) Information sources  48) Location of negatives  Roll 133 #22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	No	5)   6)
47) Information sources  48) Location of negatives  Roll 133 #22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	No No	5) (6) (7)
47) Information sources  48) Location of negatives  Roll 133 #22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	No No No I.c. Ye.	5)   6)
47) Information sources  48) Location of negatives  Roll 133 #22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	No No	5) (6) (7)
47) Information sources  48) Location of negatives  Roll 133 #22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	No No No I.c. Ye.	5) (6) (7)
47) Information sources  48) Location of negatives  Roll 133 #22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	No No No I.c. Ye.	5) (6) (7)
47) Information sources  48) Location of negatives  Roll 133 #22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	No No No I.c. Ye.	5) (6) (7)



Missouri Historic Architectural Inventory for GRA =

Division of Parks and Historic Preservation Dep	·
38) Ownership — private	* 1) inventory number 7.—212
— public	2) name (cont)
39) Owners name	3) name - historial
address	4) street address 739 W. Walnut st.
40) Local contact	5) town or vicinity   Springfield
41) Coordinates (UTM)	6) legal description
42) Quad 43) Other survey	7) county Greene
43) Onici Survey	8) category
	(site, structure, building Building
44) History	
TT/ 1114(4) /	9) significance architectural-cor
	11) style late catbuilder
	12) architect
	13) builder
	14) original use residence
	1001401100
45) Additional description	16) number of stories 2
	~~~
	17) plan shape 18) basement  L-shape partial
	Partural
	Scotte
	20) wall construction frame/lap siding 21) roof type - gable gable
	material asphalt shingle
	22) contact print
	35mm
	i e
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings  47) Information sources	24) changes -
	24) changes - additions/alter-
	24) changes - additions/alter- ations/moved
	24) changes - additions/alter- ations/moved 25) condition
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources  48) Location of negatives  Roll 133 #23-24	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
48) Location of negatives  Roll 133 #23-24  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
48) Location of negatives  Roll 133 #23-24  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
47) Information sources  48) Location of negatives  Roll 133 #23-24  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
48) Location of negatives  Roll 133 #23-24  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No
48) Location of negatives  Roll 133 #23-24  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of
48) Location of negatives  Roll 133 #23-24  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical
47) Information sources  48) Location of negatives  Roll 133 #23-24  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district
47) Information sources  48) Location of negatives  Roll 133 #23-24  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible?
47) Information sources  48) Location of negatives  Roll 133 #23-24  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
47) Information sources  48) Location of negatives  Roll 133 #23-24  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5/9/84
47) Information sources  48) Location of negatives  Roll 133 #23-24  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
47) Information sources  48) Location of negatives  Roll 133 #23-24  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5/9/84



Missouri Historic Architectural Inventory for G(c-a) = cc + 738Division of Parks and Historic Preservation Department of Natural Resources

Division of Fairs and Historic Fleservation De	<u> </u>
38) Ownership — private	* 1) inventory number P=1265
pub.+c	2) name (cont)
39) Owners — name	3) name - historial
— address	4) street address 800 W. Walnut st.
40) Local contact	5) town or vicinity   Sprinafield
41) Coordinates (UTM)	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
	(site, structure,
	building, object) Building
44) History	9) significance
	10) date
	11) style late catbuilder
	12) architect
	13) builder
	14) original use residence
	15) present use same
45) Additional description	* 16) number of stories 2
	17) plan shape irregular
	18) basement full
	1 44.4
	Concrete (Scored
	11 ame/ model ii bras
	10010
•	
	22) contact print 35mm
	3311111
	· ·
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	, a company and a company and a company and a company and a company and a company and a company and a company
46) Description of environment/outbuildings	, a company and a company and a company and a company and a company and a company and a company and a company
46) Description of environment/outbuildings	, a company and a company and a company and a company and a company and a company and a company and a company
46) Description of environment/outbuildings  47) Information sources	
	24) changes -
	24) changes - additions/alter-
	24) changes - additions/alter- ations/moved
	24) changes - additions/alter- ations/moved 25) condition
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
47) Information sources  48) Location of negatives  Roll 142 #31  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources  48) Location of negatives  Roll 142 #31	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
47) Information sources  48) Location of negatives  Roll 142 #31  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 142 #31  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 142 #31  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO
47) Information sources  48) Location of negatives  Roll 142 #31  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established
47) Information sources  48) Location of negatives  Roll 142 #31  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established
47) Information sources  48) Location of negatives  Roll 142 #31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district NO
47) Information sources  48) Location of negatives  Roll 142 #31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district
47) Information sources  48) Location of negatives  Roll 142 #31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible?
48) Location of negatives  Roll 142 #31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
47) Information sources  48) Location of negatives  Roll 142 #31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  100  100  100  100  100  100  100  1
48) Location of negatives  Roll 142 #31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
48) Location of negatives  Roll 142 #31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  100  100  100  100  100  100  100  1



Missouri Historic Architectural Inventory for ( ) Division of Parks and Historic Preservation Department of Natural Resources

30) (			
38) Ownership — private	* 1) inventory number	<u> </u>	_ =
public	2) name (cont)		
39) Owners — name	3) name - historial		
address	4) street address	801 W.Walnut st.	
40) Local contact	5) town or vicinity	Springfield	
41) Coordinates (JTM)	6) legal description		7
42) Quad	7) county	Greene	-
43) Other survey	8) category	<u> dreene</u>	-
	(site, structure,		2/3)
		Building	
	building, object)		_
44) History	9) significance	contributing	
	10) date		
	11) style	early cat.builder	•
	12) architect		
	13) builder		7
	14) original use	residence	_
	15) present use		$\dashv$
45) Additional description	16) number of stories	same	4
*			ᆜᄞ
	17) plan shape	irregular	_
	18) basement	partial	
	19) foundation	stone	
	20) wall construction	frame/modern sid	<b>,</b>
	21) roof type -	zable-hip combo.	<u> </u>
	material	asphalt shingle	$\dashv$
	22) contact print	asphalt shingle	<u>U</u>
	35mm		- 1
46) Description of environment/outbuildings	23) site plan		9)
46) Description of environment/outbuildings  47) Information sources	24) changes -		+
	24) changes - additions/alter-		+
47) Information sources	24) changes - additions/alter-ations/moved		+
	24) changes - additions/alter- ations/moved 25) condition		+
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?		+
47) Information sources	24) changes - additions/alter- ations/moved 25) condition		5)
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?		+
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage		5)
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?		5)
47) Information sources  48) Location of negatives  Roll 133 #25,35	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?		5)
47) Information sources  48) Location of negatives  Roll 133 #25,35  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?		5)
48) Location of negatives  Roll 133 #25,35  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National		0)
48) Location of negatives  Roll 133 #25,35  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?		5)
48) Location of negatives  Roll 133 #25,35  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of		0)
48) Location of negatives  Roll 133 #25,35  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	No	0)
48) Location of negatives  Roll 133 #25,35  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district		0)
48) Location of negatives  Roll 133 #25,35  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	No	0)
48) Location of negatives  Roll 133 #25,35  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	No	5)
48) Location of negatives  Roll 133 #25,35  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	No No	5)
48) Location of negatives  Roll 133 #25,35  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	No No lvc	5)
48) Location of negatives  Roll 133 #25,35  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	No No	0)
48) Location of negatives  Roll 133 #25,35  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	No No lvc	5)
47) Information sources  48) Location of negatives  Roll 133 #25,35  49) Prepared by  DDD  50) Organization Missouri Heritage Trust  If additional space is ne	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	No No lvc	5)
48) Location of negatives  Roll 133 #25,35  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	No No lvc	5)



### Missouri Historic Architectural Inventory for GRADOS-740 Division of Parks and Historic Preservation Department of Natural Resources

AMI (humorchia privato	
38) Ownership — private	* 1) inventory number 11–214
— pub(-c	2) name (cont)
39) Owners — name	3) name - historial
— address	4) street address 807 W.Walnut st.
40) Local contact	5) town or vicinity Springfield
41) Coordinates (UTM)	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
	(site, structure,
	building, object) Building
44) History	9) significance architecural-con
	10) date
	11) style early catbuild
	12) architect
	13) builder
	14) original use residence
	15) presentuse ants.
45) Additional description	• 16) number of stories $2^{\frac{1}{2}}$
	17) plan shape irregular
	18) basement partial
	19) foundation stone_
	20) wall construction frame/modern si
	21) roof type-  gable-hip combo
	material asphalt shingle
	22) contact print
46) Description of environment/outbuildings	23) site plan
47) Information sources	24) changes -
47) Information sources	24) changes - additions/alter-
47) Information sources	24) changes -
47) Information sources	24) changes - additions/alter- ations/moved 25) condition
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
48) Location of negatives  ROII 133 #26-28	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
48) Location of negatives  Roll 133 #26-28  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
48) Location of negatives  Roll 133 #26-28  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
48) Location of negatives  Roll 133 #26-28  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO
48) Location of negatives  Roll 133 #26-28  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of
48) Location of negatives  Roll 133 #26-28  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established
48) Location of negatives  Roll 133 #26-28  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district NO
48) Location of negatives  Roll 133 #26-28  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district NO
48) Location of negatives  Roll 133 #26-28  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district No No No No No No No No No No No No No
Roll 133 #26-28  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district name of historical district ) is site eligible?
Roll 133 #26-28  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district name of historical district ) is site eligible?  Ye
Roll 133 #26-28  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district name of historical district ) is site eligible? ) district potential?  ye 5/9/84
Roll 133 #26-28  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district name of historical district ) is site eligible?  Ye
A8) Location of negatives  Roll 133 #26-28  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district name of historical district ) is site eligible? ) district potential?  ye 5/9/84



Division of Parks and Historic Preservation Dep	artment of Natura	l Resources	
38) Ownership — private *	1) inventory number	P-1266	
— public	2) name (cont)		1
39) Owners — name	3) name - historial		1
address	4) street address	810 W.Walnut st.	
40) Local contact	5) town or vicinity	Springfield	]
41) Coordinates (UTM)	6) legal description		
42) Quad	7) county	Greene	
43) Other survey	8) category		2/3)
	(site, structure,	Building	٦
44) History	building, object)	Darrang	4
44) history	9) significance 10) date		4
	11) style	o what had how	4
	12) architect	early catbuilder	4
	13) builder		4
	14) original use		┨
	15) present use	residence	+
45) Additional description	16) number of stories	same	£
	17) plan shape	irregular	┧~
	18) basement	partial	1
	19) foundation	stone	1
	20) wall construction	frame/modern sidir	-
	21) roof type -	gable-hip combo.	دك
	material	asphalt shingle	1
•	22) contact print		ű
	35mm		
		•	
46) Description of environment/outbuildings	22) aita alam		+.
46) Description of environment/outbuildings	23) site plan		-   3
			-
		<del>┊</del> ┊┊┊┊	-
			_
			-
47) Information sources	24) changes -		15
	additions/alter-		
	ations/moved		
	25) condition		٦
	26) visible from road?		
	27) distance/frontage		
	28) accessible?		_ 9
48) Location of negatives	29) preservation		
Roll 142 #32-33	underway?		4
49) Prepared by	30) endangered?		4
DDD	31) on National		
50) Organization Missouri Heritage Trust	Register?	No	1
	32) part of established		
	historical district	No	
If additional spaces	33) name of historica		$\dashv$
	district		
	34) is site eligible?	lvo	7
	35) district potential		18
	36) date	4/30/84	
the second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second secon	37) revision		
23.16 -			
HISTORIC INVENTORY FORM			

MISSOURI HERITAGE TRUST



# Missouri Historic Architectural Inventory for GRAGA CONTRACTOR Division of Parks and Historic Preservation Department of Natural Resources

DIVISION OF PAIRS AND DISCONDE PRESERVACION	· · · ·
38) Ownership — priva e	* 1) inventory number P=1267
— public  39) Owners — name	2) name (cont)
— address	3) name - historial 4) street address 816 J. Wallnut. 8t.
40) Local contact	O TO WANTED
41) Coordinates (UTM)	5) town or vicinity Springfield 6) legal description
42) Quad	
43) Other survey	7) county Greene 8) category
	(site, structure,
	building, object) Building
44) History	9) significance
	10) date
	11) style early catbuilder
	12) architect
• .	13) builder
· ·	14) original use residence 15) present use same
45) Additional description	15) present use same
Ady Maditional accomption	<u></u>
	17) plan shape irregular partial
	19) foundation stone
	20) wall construction frame/modern sidin
	21) roof type- hip with gable win
	material asphalt shingle
•	22) contact print
	35mm
	•
46) Description of environment/outbuildings	23) site plan : : : : : : : : : : : : : : : : : : :
+ a) Description of environment/outbuildings	23) Site plan
47) Information sources	24) changes -
	additions/alter-
	ations/moved
	25) condition .
	26) visible from road?
	27) distance/frontage
	28) accessible?
48) Location of negatives	29) preservation
Roll 142 #34-36	underway?
	30) endangered?
49) Prepared by	21)
49) Prepared by DDD	31) on National
49) Prepared by	Register? No
49) Prepared by  DDD	Register? No 32) part of
49) Prepared by  DDD	Register? No 32) part of shed
49) Prepared by  DDD  50) Organization Missouri Heritage Trust	Register? No 32) part of
49) Prepared by  DDD	Register? NO 32) part of shed call district NO
49) Prepared by  DDD  50) Organization Missouri Heritage Trust	Register?  32) part of shed cal district f historical
49) Prepared by  DDD  50) Organization Missouri Heritage Trust	Register? NO  32) part of shed cal district f historical
49) Prepared by  DDD  50) Organization Missouri Heritage Trust	Register? NO  32) part of  shed cal district NO f historical
49) Prepared by  DDD  50) Organization Missouri Heritage Trust	Register? NO  32) part of  shed cal district NO f historical eligible? potential? Yec
49) Prepared by  DDD  50) Organization Missouri Heritage Trust	Register? NO  32) part of  shed cal district NO f historical eligible? potential? Yec



## Missouri Historic Architectural Inventory for (5 (2 ), a section of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number	M-216
— public	2) name (cont)	
39) Owners — name	3) name - historial	
— address	4) street address	danin
(40) Local contact	5) town or vicinity	817 W. Walnut st.
1 1	1	Springfield
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county	Greene
43) Other survey	8) category	
	(site, structure,	
	building, object)	Building
44) History	The state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the s	
44) History	9) significance	contributing-arch
	10) date	
	11) style	bungalow
	12) architect	
	13) builder	
	14) original use	residence
	15) present use	same
45) Additional description	16) number of stories	15
	17) plan shape	
	18) basement	rectangle
		full?
	19) foundation	concrete
	20) wall construction	frame/lap siding
	21) roof type -	nable
	material	
		as; halt shingle
	22) contact print 35mm	
·		
$\cup$	·	
	·	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings		
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings		
46) Description of environment/outbuildings		
	24) changes -	
47) Information sources	24) changes - additions/alter-	
	24) changes - additions/alter-ations/moved	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition	
47) Information sources	24) changes - additions/alter-ations/moved	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	
47) Information sources  48) Location of negatives  Roll 133 #31-32  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	
47) Information sources  48) Location of negatives  Roll 133 #31-32  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
47) Information sources  48) Location of negatives  ROII 133 #31-32  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	No
48) Location of negatives  Roll 133 #31-32  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	
47) Information sources  48) Location of negatives  Roll 133 # 31-32  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	No
47) Information sources  48) Location of negatives  Roll 133 #31-32  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	
47) Information sources  48) Location of negatives  Roll 133 # 31-32  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	No
48) Location of negatives  Roll 133 #31-32  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	No
48) Location of negatives  Roll 133 #31-32  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	No No
48) Location of negatives  Roll 133 #31-32  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	No No
48) Location of negatives  Roll 133 #31-32  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	No No YG. Yes
48) Location of negatives  Roll 133 #31-32  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	No No
48) Location of negatives  Roll 133 #31-32  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	No No YG. Yes
48) Location of negatives  Roll 133 #31-32  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	No No YG. Yes
48) Location of negatives  Roll 133 #31-32  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	No No YG. Yes



#### Missouri Historic Architectural Inventory for Grand Color 3-749 Division of Parks and Historic Preservation Department of Natural Resources

	<del></del>	
38) Ownership — private	1) inventory number	F-1268
— publ €	2) name (cont)	
39) Owners — name	3) name - historial	
— address	4) street address	822 W.Walnut st.
40) Local contact	5) town or vicinity	Springfield
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county	Greene
43) Other survey	8) category	
	(site, structure,	
	building, object)	Building
44) History	9) significance	
	10) date	
	11) style	early catbuilder
	12) architect	33127 000 000
	13) builder	
	14) original use	residence
	15) present use	
45) Additional description		same
45) Additional description		2
	17) plan shape	irregular
	18) basement	pa <b>rtial</b>
	19) foundation	stone
	20) wall construction	frame/modern sidin
	21) roof type -	gable-hip combo.
	material	asphalt shingle
•	22) contact print	
AC) Description of any analysis building	02) - 1 1-	
46) Description of environment/outbuildings	23) site plan	
	The state of the state of the state of	
17) Information courses	T	
47) Information sources	24) changes -	
47) Information Sources	additions/alter-	
47) Information Sources	additions/alter- ations/moved	
47) Information Sources	additions/alter-	
47) Information Sources	additions/alter- ations/moved 25) condition 26) visible from road?	
47) Information Sources	additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	
47) Information Sources	additions/alter- ations/moved 25) condition 26) visible from road?	
48) Location of negatives	additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	
	additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	
48) Location of negatives  Roll 136 #5-6 Roll131 #15  49) Prepared by	additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	
48) Location of negatives  Roll 136 #5-6 Roll131 #15	additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	
48) Location of negatives  Roll 136 #5-6 Roll131 #15  49) Prepared by  DDD	additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	
48) Location of negatives  Roll 136 #5-6 Roll131 #15  49) Prepared by  DDD	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	No
48) Location of negatives  Roll 136 #5-6 Roll131 #15  49) Prepared by  DDD	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	
48) Location of negatives  Roll 136 #5-6 Roll131 #15  49) Prepared by  DDD	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	
48) Location of negatives  Roll 136 #5-6 Roll131 #15  49) Prepared by  DDD	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	No No
48) Location of negatives  Roll 136 #5-6 Roll131 #15  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	No No
48) Location of negatives  Roll 136 #5-6 Roll131 #15  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district name of historica	No
48) Location of negatives  Roll 136 #5-6 Roll131 #15  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district name of historica	No No
48) Location of negatives  Roll 136 #5-6 Roll131 #15  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district name of historica district is site eligible?	No No Yeu
48) Location of negatives  Roll 136 #5-6 Roll131 #15  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district name of historica district is site eligible? district potential?	No No
Roll 136 #5-6 Roll131 #15  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district name of historica district is site eligible? district potential?	No No Yeu
Roll 136 #5-6 Roll131 #15  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district name of historica district is site eligible? district potential?	No No Yeu





# Missouri Historic Architectural Inventory for GAS OCCATICE Division of Parks and Historic Preservation Department of Natural Resources

201 A		
38) Ownership — private — public	* 1) inventory number 2) name (cont)	1217
put iic 39) Owners name	3) name (cont)	
address	4) street address	823 W.Walnut st.
40) Local contact	5) town or vicinity	
41) Coordinates (UTM)	6) legal description	Springfield
(2) Quad	7) county	Greene
3) Other survey	8) category	di ecile
	(site, structure,	
	building, object)	Building
14) History	9) significance	architectural-con
	10) date	
	11) style	bungalow
	12) architect	
	13) builder	
	14) original use	residence
AEV Additional description	15) present use	same
45) Additional description	• 16) number of stories	1
	17) plan shape 18) basement	rectangle full?
	19) foundation	concrete
	20) wall construction	frame/lap siding
	21) roof type -	gable gable
	material	asphalt shingle
	22) contact print	applicate purificate
47) Information sources	24) changes -	
•	additions/alter-	
	ations/moved 25) condition	
	26) visible from road?	
	27) distance/frontage	
	28) accessible?	
48) Location of negatives	29) preservation	
Roll 133 #33,34,36	underway?	
49) Prepared by	30) endangered?	
DAD	31) on National	
50) Organization Missouri Heritage Trust	Register?	No
	32) part of	
And the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of t	established	No
If addit	historical district name of historical	No
n addit		
	district	
	district is site eligible?	Vc.
	is site eligible?	Ye.
	,	Ye.
	is site eligible? district potential?	
	is site eligible? district potential? date	Ye



# Missouri Historic Architectural Inventory for GR-A3-003-746 Division of Parks and Historic Preservation Department of Natural Resources

	cpartification tratainal resources
38) Ownership — private	* 1) inventory number P=1269
— public	2) name (cont)
39) Owners — name	3) name - historial
— address	4) street address 826 W.Walnut st.
40) Local contact	5) town or vicinity Springfield
41) Coordinates (UTM)	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
	(site, structure,
	building, object) Building
44) History	9) significance
	10) date ca. 1940
	11) style <u>bungalow</u>
	12) architect
	13) builder
	14) original use residence
	15) present use same
45) Additional description	16) number of stories
	17) plan shape rectangle
- pref	18) basement
	19) foundation   concrete
	20) wall construction frame/modern sidin
	21) roof type-
	material asphalt, shingle
•	22) contact print
	35mm
46) Description of environment/outbuildings	23) site plan
47) Information control	
47) Information sources	24) changes -
	additions/alter-
	ations/moved 25) condition
	26) visible from road? 27) distance/frontage
(0) 14	28) accessible?
48) Location of negatives	29) preservation underway?
	ı underway:
Roll 136 #2-3	
Roll 136 $\#2-3$	30) endangered?
Roll 136 $\#2-3$ 49) Prepared by  DDD	30) endangered? 31) on National
Roll 136 $\#2-3$	30) endangered? 31) on National Register? NO
Roll 136 #2-3  49) Prepared by  DDD	30) endangered? 31) on National Register? NO 32) part of
Roll 136 #2-3  49) Prepared by  DDD	30) endangered? 31) on National Register? NO 32) part of established
Roll 136 #2-3  49) Prepared by  DDD  Missouri Heritage Trust	30) endangered? 31) on National Register? NO 32) part of established historical district NO
Roll 136 $\#2-3$ 49) Prepared by  DDD	30) endangered? 31) on National Register? NO 32) part of established historical district NO 33) name of historical
Roll 136 #2-3  49) Prepared by  DDD  Missouri Heritage Trust	30) endangered? 31) on National Register? NO 32) part of established historical district NO 33) name of historical district
Roll 136 #2-3  49) Prepared by  DDD  Missouri Heritage Trust	30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible?
Roll 136 #2-3  49) Prepared by  DDD  Missouri Heritage Trust	30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
Roll 136 #2-3  49) Prepared by  DDD  Missouri Heritage Trust	30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  NO  NO  NO  NO  NO  NO  NO  NO  NO  N
Roll 136 #2-3  49) Prepared by  DDD  Missouri Heritage Trust	30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
Roll 136 #2-3  49) Prepared by  DDD  Missouri Heritage Trust	30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  NO  NO  NO  NO  NO  NO  NO  NO  NO  N



Missouri Historic Architectural Inventory for  $G_{K^2-i+1}$ ,  $-\epsilon \circ 3 - 7 \circ 7$ Division of Parks and Historic Preservation Department of Natural Resources

DIVISION OF PARKS and Historic Preservati	
38) Ownership — private — public	* 1) inventory number P = 1270
39) Owners — name	2) name (cont) 3) name - historial
address	,
40) Local contact	
41) Coordinates (UTM)	5) town or vicinity   Springfield
2) Quad	
3) Other survey	- GI CEILE
o, other survey	8) category (site, structure,
	building, object) Building
4) History	9) significance
7, 1113Co. y	10) date
	11) style early catbuilder 12) architect
	13) builder
	165 Tueste
5) Additional description	Same
ar riaditional accomplish	
	10) to
	10) foundation
	scone
	rame/modern sidin
	Eau e-in D Combo
	material asphalt shingle  22) contact print
	35mm
(C) Danishin of anti-many and anti-many	033 - 14
16) Description of environment/outbuildings	23) site plan
	<del>┍╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒╒</del>
7) Information sources	24) changes -
, , , , , , , , , , , , , , , , , , , ,	additions/alter-
	ations/moved
	25) condition
	26) visible from road?
	27) distance/frontage
	28) accessible?
8) Location of negatives	29) preservation
Ro11 136 #1	underway?
9) Prepared by	30) endangered?
DDD	31) on National
	Register? NO
Missouri Heritage Trust	32) part of
	established
	historical district No
If additional space is needed, atta-	33) name of historical
	district
	34) is site eligible? NO
	35) district potential? Ye
	36) date 5/4/84
	37) revision
Marie Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlotte Carlot	
HISTORIC INVENTORY FORM	
MISSOURI HERITAGE TRUST	



Missouri Historic Architectural Inventory for GR-A-003-748

Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	1) inventory number	1218	]=
public	2) name (cont)		1
39) Owners — name	3) name - historial		-
— address	4) street address	CORNETTO	-{
	· ·	837 W.Walnut st.	4
40) Local contact	5) town or vicinity	Springfield	_}
41) Coordinates (UTM)	6) legal description		
42) Quad	7) county	Greene	
43) Other survey	8) category		2/3)
	(site, structure,		$ \omega $
	building, object)	Building	
44) History	9) significance	contributing	7
· · · · · · · · · · · · · · · · · · ·	10) date	conditionaling	┥
	11) style	vernacular I-hous	-
	12) architect	vernacular 1-110us	25
	1		4
	13) builder		_]
	14) original use	resdience	_
	15) present use	_same	-
45) Additional description	16) number of stories	2	4
	17) plan shape	L-shape	7
	18) basement	partial	4
	19) foundation		⊣
	20) wall construction	stone	<u>.</u>
	21) roof type -	frame/modern sid:	<u>-</u>
		<u>gable</u>	
	material	asphalt shingle	4
·	22) contact print		5)
	35mm		i
		•	ļ
			- (
			- 1
(C) Occasion to a standard control of the library	22) cita plan		9
46) Description of environment/outbuildings	23) site plan	· 	9)
46) Description of environment/outbuildings	23) site plan :		9)
46) Description of environment/outbuildings	23) site plan		9)
46) Description of environment/outbuildings	23) site plan		9)
46) Description of environment/outbuildings	23) site plan		9)
46) Description of environment/outbuildings			
46) Description of environment/outbuildings  47) Information sources			
	24) changes - additions/alter-		
	24) changes - additions/alterations/moved		
47) Information sources	24) changes - additions/alter- ations/moved 25) condition		
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?		
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage		5)
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?		
47) Information sources , . 48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation		5)
47) Information sources , . 48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?		5)
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation		5)
47) Information sources  48) Location of negatives  Roll 133 #37  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?		5)
47) Information sources  48) Location of negatives  Roll 133 #37  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National		5) 6)
47) Information sources  48) Location of negatives  Roll 133 #37  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?		5)
47) Information sources  48) Location of negatives  Roll 133 #37  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of		5) 6)
47) Information sources  48) Location of negatives  Roll 133 #37  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	No	5) 6)
47) Information sources  48) Location of negatives  Roll 133 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	No	5) 6)
47) Information sources  48) Location of negatives  Roll 133 #37  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	No	5) 6)
47) Information sources  48) Location of negatives  Roll 133 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	No No	5) 6)
47) Information sources  48) Location of negatives  Roll 133 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	No No	5) (6) (7)
47) Information sources  48) Location of negatives  Roll 133 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	No No	5) 6)
47) Information sources  48) Location of negatives  Roll 133 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	No No	5) (6) (7)
47) Information sources  48) Location of negatives  Roll 133 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	No No	5) (6) (7)
47) Information sources  48) Location of negatives  Roll 133 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	No No	5) (6) (7)



# Missouri Historic Architectural Inventory for 612-11-05-749 Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	t 1) inventory number   0 107/1
— pulnic	1) inventory number $P=12.71$
	2) name (cont)
39) Owners — name	3) name-historial
— address	4) street address 838 W.Walnut st.
40) Local contact	5) town or vicinity Springfield
41) Coordinates (JTM)	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
	(site, structure,
	building, object) Building
AAN HIIAAA	
44) History	9) significance
	10) date
	11) style early catbuilder
	12) architect
	13) builder
	14) original use residence
	15)
45) Additional description	an I Danie
70) Additional description	
	17) plan shape rectangle with add
	18) basement partial
	19) foundation stone
	20) wall construction frame/modern sidin
	21) roof type-
	material asimalt shingle
	22) contact print
46) Description of environment/outbuildings	23) site plan
47) Information sources	24) changes -
	additions/alter-
	ations/moved
	ations/moved 25) condition
	ations/moved 25) condition 26) visible from road?
	ations/moved 25) condition 26) visible from road? 27) distance/frontage
	ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
48) Location of negatives	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation
Roll 136 #42	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?
Roll 136 $\#42$	ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
Roll 136 #42	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?
Roll 136 #42  49) Prepared by  DDD	ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
Roll 136 #42  49) Prepared by  DDD	ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
Roll 136 #42  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National Register?  No
Roll 136 #42  49) Prepared by  DDD	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National Register?  NO  32) part of established
Roll 136 #42  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation     underway?  30) endangered?  31) on National     Register?  NO  32) part of     established     historical district  NO
Roll 136 #42  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation     underway?  30) endangered?  31) on National     Register?  NO  32) part of     established     historical district  33) name of historical
Roll 136 #42  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation     underway?  30) endangered?  31) on National     Register?  NO  32) part of     established     historical district  33) name of historical     district
Roll 136 #42  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation     underway?  30) endangered?  31) on National     Register?  No  32) part of     established     historical district  33) name of historical     district  34) is site eligible?  Ye_
Roll 136 #42  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation     underway?  30) endangered?  31) on National     Register?  No  32) part of     established     historical district  33) name of historical     district  34) is site eligible?  35) district potential?
Roll 136 #42  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation     underway?  30) endangered?  31) on National     Register?  No  32) part of     established     historical district  34) is site eligible?  35) district potential?  36) date
Roll 136 #42  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation     underway?  30) endangered?  31) on National     Register?  No  32) part of     established     historical district  33) name of historical     district  34) is site eligible?  35) district potential?
Roll 136 #42  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation     underway?  30) endangered?  31) on National     Register?  No  32) part of     established     historical district  34) is site eligible?  35) district potential?  36) date



### Missouri Historic Architectural Inventory for & Resources Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number $\tilde{r}_1$ -219
— public	2) name (cont)
39) Owners — name	3) name - historial
— address	4) street address 901 W.Walnut st.
40) Local contact	
41) Coordinates (UTM)	6) legal description Springfield
42) Quad	
43) Other survey	8) category Greene
	(site, structure, building, object) Building
44) History	9) significance architectural-co
	10) date
	11) style late Italianate
	12) architect
	13) builder
	14) original use residence
	15) present use same
45) Additional description	• 16) number of stories 2
	17) plan shape irregular
	18) basement partial
	P. 6.1 0 2 6 2 .
	300116
	20) wall construction frame/modern sid
	21) roof type- truncated hip
	material asphalt shingle
•	22) contact print 35mm
46) Description of environment/outbuildings	23) site plan
47) Information sources	24) changes -
_	and distinguished
	additions/alter-
	adottions/aiter-
	ations/moved
	ations/moved 25) condition
	ations/moved 25) condition 26) visible from road?
, , , , , , , , , , , , , , , , , , ,	ations/moved 25) condition 26) visible from road? 27) distance/frontage
```	ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
48) Location of negatives	ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
48) Location of negatives Roll 117 ポ42	ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
48) Location of negatives	ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
48) Location of negatives Roll 117 #42	ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
48) Location of negatives  Roll 117 #42  49) Prepared by	ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
48) Location of negatives  ROII 117 #42  49) Prepared by	ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
48) Location of negatives  Roll 117 #42  49) Prepared by	ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO
48) Location of negatives  ROII 117 #42  49) Prepared by	ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of
Roll 117 #42  49) Prepared by  50) Organization Missouri Heritage Trust	ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established
48) Location of negatives  ROII 117 #42  49) Prepared by	ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district NO
Roll 117 #42  49) Prepared by  50) Organization Missouri Heritage Trust	ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district NO 33) name of historical district
Roll 117 #42  49) Prepared by  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation     underway?  30) endangered?  31) on National     Register?  NO  32) part of     established     historical district  33) name of historical     district  34) is site eligible?
Roll 117 #42  49) Prepared by  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation     underway?  30) endangered?  31) on National     Register?  NO  32) part of     established     historical district  33) name of historical     district  34) is site eligible?  35) district potential?
Roll 117 #42  49) Prepared by  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation     underway?  30) endangered?  31) on National     Register?  NO  32) part of     established     historical district  33) name of historical     district  34) is site eligible?  35) district potential?  36) date  5 / 9 / 8 / 4
Roll 117 #42  49) Prepared by  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation     underway?  30) endangered?  31) on National     Register?  NO  32) part of     established     historical district  33) name of historical     district  34) is site eligible?  35) district potential?
Roll 117 #42  49) Prepared by  50) Organization Missouri Heritage Trust  If additional space is need	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation     underway?  30) endangered?  31) on National     Register?  NO  32) part of     established     historical district  33) name of historical     district  34) is site eligible?  35) district potential?  36) date  5 / 9 / 8 / 4
Roll 117 #42  49) Prepared by  50) Organization Missouri Heritage Trust  If additional space is need	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation     underway?  30) endangered?  31) on National     Register?  NO  32) part of     established     historical district  33) name of historical     district  34) is site eligible?  35) district potential?  36) date  5 / 9 / 8 / 4



***			
38) Ownership — private	1) inventory number	₽-1272	_ =
— public	2) name (cont)		_
39) Owners — name	3) name - historial		4
— address	4) street address	902 W.Walnut st.	_
40) Local contact	5) town or vicinity	Springfield	_
41) Coordinates (UTM)	6) legal description		_
42) Quad	7) county	Greene	
43) Other survey	8) category		2/3)
	(site, structure,	Duilding	\ <del>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</del>
	building, object)	Building	
44) History	9) significance		
	10) date		7
	11) style	late catbuilder	7
	12) architect		٦
	13) builder		٦
	14) original use	residence	٦
	15) present use	same	7
45) Additional description	* 16) number of stories	1	4
	17) plan shape	irregular	7
	18) basement	partial	٦
	19) foundation	stone	٦
	20) wall construction	frame/modern sidi	
	21) roof type -	gable-hip combo.	155
	material	asphalt shingle	7
	22) contact print	gabuare autuare	5
	35mm		
			-
46) Description of environment/outbuildings	23) site plan		9
46) Description of environment/outbuildings	25) site plan		~ <b> </b> ~
			-
47) Information sources	24) changes -		<u> </u>
4/) Information Sources	additions/alter-		
	ations/moved		
		<u></u>	-\
	25) condition		$\dashv$
	26) visible from road?		$\dashv$
	27) distance/frontage		<del></del>
	28) accessible?		(6)
48) Location of negatives	29) preservation		
Roll 136 #41	underway?		-
49) Prepared by	30) endangered?		_
DDD	31) on National		
50) Organization Missouri Heritage Trust	Register?	No	<u> </u>
		1	
the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the s	32) part of		1
	established		
	established historical district		
If additional space is needed, atta	established historical district 33) name of historica		_
If additional space is needed, atta	established historical district 33) name of historica district		
If additional space is needed, atta	established historical district 33) name of historica district 34) is site eligible?	No	
If additional space is needed, atta	established historical district 33) name of historica district 34) is site eligible? 35) district potential?	No Ye.	30)
If additional space is needed, atta	established historical district 33) name of historica district 34) is site eligible? 35) district potential? 36) date	No	30)
If additional space is needed, atta	established historical district 33) name of historica district 34) is site eligible? 35) district potential?	No Ye.	30)
If additional space is needed, atta	established historical district 33) name of historica district 34) is site eligible? 35) district potential? 36) date	No Ye.	30)
HISTORIC INVENTORY FORM	established historical district 33) name of historica district 34) is site eligible? 35) district potential? 36) date	No Ye.	30)



### Missouri Historic Architectural Inventory for Grand Control of Parks and Historic Preservation Department of Natural Resources

	<del></del>		
38) Ownership — private *	1) inventory number	12.20	
public	2) name (cont)		
, , , , , , , , , , , , , , , , , , ,	· L		
39) Owners — name	3) name - historial		
— address	4) street address	907 W.Walnut st.	
(40) Local contact	5) town or vicinity		
	1 1	Springfield	
41) Coordinates (UTM)	6) legal description		
42) Quad	7) county	C	
· · · · · · · · · · · · · · · · · · ·		Greene	
43) Other survey	8) category	Ī	
	(site, structure,	\3	:
	1	Building	
	building, object)	burraring	
44) History	9) significance	architectural	
	10) date	ar chirocodarar	
	l l		
	11) style	late catbuilder	
	12) architect		
	1		
•	13) builder		
	14) original use	residence	
	15) present use		
		apts.	
45) Additional description	16) number of stories	2	1
	17) plan shape	~	
		irregular	
	18) basement	full?	
	19) foundation	stone and cast sto	١
	20) wall construction		
		frame/modern sidin	
	21) roof type -	hip and gablet wit	
	material		
		gable wing	<del>-</del> .
`	22) contact print	asphalt shingle	C
	35mm	αορ	
	}		
		<b>I</b>	
	1		
			<del></del>
46) Description of environment/outbuildings	23) site plan		ردا
46) Description of environment/outbuildings	23) site plan		(6)
46) Description of environment/outbuildings			(6)
46) Description of environment/outbuildings			(د ا
46) Description of environment/outbuildings			(6)
46) Description of environment/outbuildings			(6)
46) Description of environment/outbuildings			ופן
46) Description of environment/outbuildings			(6)
46) Description of environment/outbuildings  47) Information sources	24) changes -		(c)
47) Information sources			
	24) changes -		
47) Information sources	24) changes - additions/alterations/moved		
47) Information sources	24) changes - additions/alter- ations/moved 25) condition		
47) Information sources	24) changes - additions/alterations/moved		
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?		
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage		(5)
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?		
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage		(5)
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation		(5)
47) Information sources  48) Location of negatives  Roll 117 #40-41	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?		(5)
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation		(5)
47) Information sources  48) Location of negatives  Roll 117 #40-41  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?		(5)
47) Information sources  48) Location of negatives  Roll 117 #40-41  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National		(5)
47) Information sources  48) Location of negatives  Roll 117 #40-41  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?		(5)
47) Information sources  48) Location of negatives  Roll 117 #40-41  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?		(5)
47) Information sources  48) Location of negatives  Roll 117 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of		(5)
47) Information sources  48) Location of negatives  Roll 117 #40-41  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	No	(5)
47) Information sources  48) Location of negatives  Roll 117 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	No	(5)
48) Location of negatives  ROII 117 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	No	(5)
47) Information sources  48) Location of negatives  Roll 117 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	No	(5)
48) Location of negatives  ROII 117 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	No	(5)
48) Location of negatives  ROII 117 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	No	(5)
48) Location of negatives  ROII 117 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	No No	(5)
48) Location of negatives  ROII 117 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	No No No	(5)
48) Location of negatives  ROII 117 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	No No	(5)
48) Location of negatives  ROII 117 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	No No No	(5)
48) Location of negatives  Roll 117 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	No No No	(5)
48) Location of negatives  ROII 117 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	No No No	(b) (b) (7)





# Missouri Historic Architectural Inventory for GRAS COS-753 Division of Parks and Historic Preservation Department of Natural Resources

	<u> </u>	
38) Ownership — provate	* 1) inventory number	P-1273
— public	2) name (cont)	
39) Owners — name	3) name - historial	
— address		
	4) street address	908 W.Walnut st.
40) Local contact	5) town or vicinity	Springfield
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county	Greene
43) Other survey	8) category	
	(site, structure,	
	1 1	Building
	building, object)	Darrang
44) History	9) significance	
	10) date	
	11) style	ormly act hailden
	12) architect	early catbuilder
	13) builder	
	14) original use	residence
	15) present use	same
45) Additional description	16) number of stories	I. I.
	17) plan shape	irregular or L
	18) basement	partial
	19) foundation	stone
		1
	20) wall construction	frame/modern siding
	11 Was pice	1 / A C C
	material	asphalt shingle
•	22) contact print	Tablification of tablification
	35mm	
	00	
		·
AC) Provide the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the	02)	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings		
46) Description of environment/outbuildings		
46) Description of environment/outbuildings  47) Information sources		
	24) changes -	
	24) changes - additions/alter-ations/moved	
	24) changes - additions/alter- ations/moved 25) condition	
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	
47) Information sources  48) Location of negatives  Roll 136 if 40	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	
47) Information sources  48) Location of negatives  Roll 136 #40  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	
47) Information sources  48) Location of negatives  Roll 136 if 40  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
47) Information sources  48) Location of negatives  Roll 136 if 40  49) Prepared by  DI)D	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	
47) Information sources  48) Location of negatives  Roll 136 if 40  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
47) Information sources  48) Location of negatives  Roll 136 if 40  49) Prepared by  DID	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	
47) Information sources  48) Location of negatives  Roll 136 if 40  49) Prepared by  DI)D	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	No
48) Location of negatives  Roll 136 #40  49) Prepared by  DID  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	No
47) Information sources  48) Location of negatives  Roll 136 if 40  49) Prepared by  DI)D	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	No
48) Location of negatives  Roll 136 #40  49) Prepared by  DI)D  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	No
48) Location of negatives  Roll 136 #40  49) Prepared by  DI)D  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	No No
48) Location of negatives  Roll 136 #40  49) Prepared by  DI)D  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	No No No Ye_
48) Location of negatives  Roll 136 #40  49) Prepared by  DI)D  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	No No No Ye_
48) Location of negatives  Roll 136 #40  49) Prepared by  DI)D  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	No No
48) Location of negatives  Roll 136 #40  49) Prepared by  DI)D  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	No No No Ye_
48) Location of negatives  Roll 136 #40  49) Prepared by  DID  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date	No No No Ye_



## Missouri Historic Architectural Inventory for 627003-754 Division of Parks and Historic Preservation Department of Natural Resources

		1 1001
38) Ownership — pr vate	* 1) inventory number	P-1274
public	2) name (cont)	
39) Owners — name	3) name - historial	
	· ·	
address	4) street address	914 W.Walnut st.
40) Local contact	5) town or vicinity	
		Springfield
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county	Greene
	8) category	- di eene
43) Other survey		
	(site, structure,	I I
	building, object)	Building
	9) significance	
44) History	*	
	10) date	
	11) style	Queen Anne
	-	- Gacon mino
	12) architect	
	13) builder	1
	14) original use	residence
	l l	
	15) present use	apts.
45) Additional description	16) number of stories	1 2
	17) plan shape	irregular
	18) basement	partial
	19) foundation	stone
	20) wall construction	frame/modern sidin
	1	
	21) roof type -	gable
	material	asphalt shingle
	22) contact print	
	35mm	
	)	
	}	
( )		
. $\bigcirc$		
46) Description of environment/outbuildings	23) site plan	·
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings		
46) Description of environment/outbuildings  47) Information sources	24) changes -	
	24) changes - additions/alter-	
	24) changes -	
	24) changes - additions/alter-	
	24) changes - additions/alter- ations/moved 25) condition	
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road	
	24) changes - additions/alter- ations/moved 25) condition	
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road: 27) distance/frontage 28) accessible? 29) preservation	
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	
47) Information sources  48) Location of negatives  Roll 136 #38-39	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	
47) Information sources  48) Location of negatives  Roll 136 #38-39  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	
47) Information sources  48) Location of negatives  Roll 136 #38-39  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
48) Location of negatives  Roll 136 #38-39  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	
47) Information sources  48) Location of negatives  Roll 136 #38-39  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	
48) Location of negatives  Roll 136 #38-39  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	
48) Location of negatives  Roll 136 #38-39  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	No
48) Location of negatives  Roll 136 #38-39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	No No
48) Location of negatives  Roll 136 #38-39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	No No
48) Location of negatives  Roll 136 #38-39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	No No
48) Location of negatives  Roll 136 #38-39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road: 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	No No
48) Location of negatives  Roll 136 #38-39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	No No
48) Location of negatives  Roll 136 #38-39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road: 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	No No No No No No No No No No No No No N
48) Location of negatives  Roll 136 #38-39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential	No No No No No No No No No No No No No N
48) Location of negatives  Roll 136 #38-39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential 36) date	No No
48) Location of negatives  Roll 136 #38-39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential	No No No No No No No No No No No No No N
48) Location of negatives  Roll 136 #38-39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential 36) date	No No No No No No No No No No No No No N
48) Location of negatives  Roll 136 #38-39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential 36) date	No No No No No No No No No No No No No N





· ·		·		
38) Ownership — private	1	inventory number	K-221	_
public	1 2	name (cont)		
— public	4	name (cont)		
39) Owners — name	1 3	name - historial		
address	1 4		605 31 11 3	
— address	4.	street address	925 W.Walnut st.	
40) Local contact	5	town or vicinity		
		•	Springfield	
41) Coordinates (UTM)	6	legal description	1	
42) Quad	7	county	Cucana	
			Greene	_
43) Other survey	8	category	1	1
	1	(site, structure,		(
	1		Building	
	- 1	building, object)	Duriding	
44) History	1 9	significance	architectural	
44, (110,03)			architecoural	
	10	) date	1	
	111	) style	7 to The Talente	
	1		late Italianate	
	12	) architect		
	113	) builder		
	ſ			
	14	) original use	residence	
	115	) present use		
	. l		same	L
45) Additional description	16	) number of stories	2	£
	117	) plan shape		
			irregular	
	18	) basement	partial	
	110	) foundation	1 (	
	- 1		stone	
	20	) wall construction	frane/lan siding	1
	21	) roof type -	Trans/ rain profite	
	121		gable-hip combo.	
	1	material	asphalt shingle	
	22	) contact print	1 912 DUGTO SUTURTA	1
	22			-
	ı	35mm		ļ
	1		_	
	- }			
	- I		'	ì
	l l			\
				!
	1			Į
	1			
				1
46) Description of anyironment/outhwildings	23	l) site plan		1
46) Description of environment/outbuildings	23	s) site plan		1
46) Description of environment/outbuildings	23	site plan		1
46) Description of environment/outbuildings	23	site plan		1/2/
46) Description of environment/outbuildings	23	site plan		1
46) Description of environment/outbuildings	23			1
46) Description of environment/outbuildings				
46) Description of environment/outbuildings				1
46) Description of environment/outbuildings				
46) Description of environment/outbuildings  47) Information sources		l) changes -		(1)
47) Information sources		l) changes - additions/alter-		2)
		l) changes - additions/alter-		()
47) Information sources	24	changes - additions/alter- ations/moved		
47) Information sources	24	l) changes - additions/alter-		
47) Information sources	24	changes - additions/alter- ations/moved condition		
47) Information sources	24	l) changes - additions/alter- ations/moved b) condition c) visible from road	7	
47) Information sources	24	changes - additions/alter- ations/moved condition visible from road distance/frontage	7	
47) Information sources	24	changes - additions/alter- ations/moved condition visible from road distance/frontage	7	
47) Information sources	25 25 25 25 25 25 25 25 25 25 25 25 25 2	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible?	7	
47) Information sources	25 25 25 25 25 25 25 25 25 25 25 25 25 2	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible?	7	
47) Information sources	25 25 25 25 25 25 25 25 25 25 25 25 25 2	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible?	7	
47) Information sources  48) Location of negatives  Roll 117 #37,39 Roll 133 #38	24 29 20 21 21 21 21 21 21 21 21 21 21 21 21 21	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway?	7	
47) Information sources  48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by	24 25 26 27 28 27 30	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway? endangered?	7	
47) Information sources  48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by	24 25 26 27 28 27 30	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway?	7	
47) Information sources  48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by  DDD	24 25 26 27 28 27 30	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway? endangered? on National		
47) Information sources  48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by  DDD	222 22 23 33 3	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway? endangered? on National Register?	7	
47) Information sources  48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by	222 22 23 33 3	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway? endangered? on National		
47) Information sources  48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by  DDD	222 22 23 33 3	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway? endangered? on National Register? part of		
47) Information sources  48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	222 22 23 33 3	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway? endangered? on National Register? part of established	No	
47) Information sources  48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 33 3	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical districe	No No	
47) Information sources  48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 33 3	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway? endangered? on National Register? part of established	No No	
47) Information sources  48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 33 3	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical distric name of historical	No No	
47) Information sources  48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 33 3	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway? on National Register? part of established historical district district	No No	
47) Information sources  48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 33 3	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical distric name of historical	No No	
47) Information sources  48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 33 3	l) changes - additions/alter- ations/moved b) condition visible from road visible from road distance/frontage accessible? preservation underway? on endangered? on National Register? part of established historical district district district district district	No No	
47) Information sources  48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 33 3	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district district is site eligible? district potential	No No No Ye. Ye.	
47) Information sources  48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 33 3	l) changes - additions/alter- ations/moved b) condition visible from road visible from road distance/frontage accessible? preservation underway? on endangered? on National Register? part of established historical district district district district district	No No	
47) Information sources  48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 33 3	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district district is site eligible? district potential of date	No No No Ye. Ye.	
48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 33 3	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district district is site eligible? district potential	No No No Ye. Ye.	
48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by  50) Organization Missouri Heritage Trust	24 25 26 27 28 33 3	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district district is site eligible? district potential of date	No No No Ye. Ye.	
48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 33 3	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district district is site eligible? district potential of date	No No No Ye. Ye.	
48) Location of negatives  Roll 117 #37,39 Roll 133 #38  49) Prepared by  50) Organization Missouri Heritage Trust	24 25 26 27 28 33 3	changes - additions/alter- ations/moved condition visible from road distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district district is site eligible? district potential of date	No No No Ye. Ye.	



## 

38) Ownership — private	* 1) inventory number P=1275
— public	2) name (cont)
39) Owners — name	3) name - historial
— address	4) street address 930 W.WaInut st.
40) Local contact	
41) Coordinates (UTM)	5) town or vicinity 6) legal description
42) Quad	
43) Other survey	8) category (site structure.
	building, object) Building
44) History	9) significance
	10) date
	11) styleate_catbuilder
	12) architect
	13) builder
	14) original use apts.
	15) present use same
45) Additional description	16) number of stories 2
	17) plan shape rectangle
	1000
	1.4.1.1
	19) foundation stone
	20) wall construction frame/modern sidin
	21) roof type - hip
	material asphalt shingle
•	22) contact print
	35mm
	}
$\cap$	
$\cup$	
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	
46) Description of environment/outbuildings	
46) Description of environment/outbuildings	
46) Description of environment/outbuildings 47) Information sources	
	24) changes - additions/alter-
	24) changes - additions/alter- ations/moved
	24) changes - additions/alter- ations/moved 25) condition
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
	24) changes - additions/alter- ations/moved 25) condition
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources  48) Location of negatives  Roll 136 #37	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
47) Information sources  48) Location of negatives  Roll 136 #37  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
47) Information sources  48) Location of negatives  Roll 136 #37  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 136 #37  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No
47) Information sources  48) Location of negatives  Roll 136 #37  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 136 #37  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No
47) Information sources  48) Location of negatives  Roll 136 #37  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of
47) Information sources  48) Location of negatives  Roll 136 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established
47) Information sources  48) Location of negatives  Roll 136 #37  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No 33) name of historical
47) Information sources  48) Location of negatives  Roll 136 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district
47) Information sources  48) Location of negatives  Roll 136 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible?
47) Information sources  48) Location of negatives  Roll 136 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
47) Information sources  48) Location of negatives  Roll 136 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5 / L / 8 L
47) Information sources  48) Location of negatives  Roll 136 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
47) Information sources  48) Location of negatives  Roll 136 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5 / L / 8 L
47) Information sources  48) Location of negatives  Roll 136 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5 / L / 8 L



Missouri Historic Architectural Inventory for GR-AS-003-757

Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	1)	inventory number	Jv. <b>−</b> 222
— public	2)	name (cont)	
39) Owners — name	3)	name - historial	
address	]	street address	022 11 11 2
		· ·	933 W.Walnut st.
40) Local contact		town or vicinity	Springfield
41) Coordinates (UTM)	(6)	legal description	
42) Quad	7)	county	Greene
43) Other survey		category	
45) Other survey	",	· · · · · · · · · · · · · · · · · · ·	(6/2
	1	(site, structure,	
	1	building, object)	Building
44) History	9)	significance	architectural
·		date	
			1,100
	J	style	Queen Anne
		architect	_
	13)	builder	
	14)	original use	residence
		present use	
ACN ADDICE TO THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF THE PROPERTY OF	1	•	Same
45) Additional description	}	number of stories	1 2
	17)	plan shape	irregular
	18)	basement	partial
•		foundation	
			stone
		wall construction	frame/lap siding
	21)	roof type -	hip with gablet and
		material	gable wing
•	221	) contact print	
	122		asphalt shingle
	Ì	35mm	
5	}		•
	1		,
	1		
	1		
46) Description of environment/outhuildings	23	) site plan	
46) Description of environment/outbuildings	23	) site plan	
46) Description of environment/outbuildings	23	) site plan	<u> </u>
46) Description of environment/outbuildings	23	) site plan	
	23	) site plan	
46) Description of environment/outbuildings			
•			
		) changes -	<u> </u>
•			<u></u>
47) Information sources		) changes -	
•	24	) changes - additions/alter- ations/moved	
47) Information sources	24	) changes - additions/alter- ations/moved	Ę.
47) Information sources	24 25 26	changes - additions/alter- ations/moved condition visible from road?	Ę.
47) Information sources	24 25 26 27	) changes - additions/alter- ations/moved ) condition ) visible from road? () distance/frontage	C
47) Information sources	24 25 26 27	changes - additions/alter- ations/moved condition visible from road?	Ę.
47) Information sources	24 25 26 27 28	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	C
47) Information sources  48) Location of negatives	24 25 26 27 28	changes - additions/alter-ations/moved condition visible from road? distance/frontage accessible?	C
47) Information sources  48) Location of negatives  Roll 117 #35,36,38	24 25 26 27 28 29	changes - additions/alter-ations/moved condition visible from road? distance/frontage accessible? preservation underway?	C
48) Location of negatives  Roll 117 #35,36,38  49) Prepared by	24 25 26 27 28 29 30	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	C
48) Location of negatives  Roll 117 #35,36,38  49) Prepared by	24 25 26 27 28 29 30	changes - additions/alter-ations/moved condition visible from road? distance/frontage accessible? preservation underway?	C
48) Location of negatives  Roll 117 #35,36,38  49) Prepared by	24 25 26 27 28 29 30	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	<u>c</u>
48) Location of negatives  Roll 117 #35,36,38  49) Prepared by	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	C
47) Information sources  48) Location of negatives  Roll 117 #35,36,38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	<u>c</u>
48) Location of negatives  Roll 117 #35,36,38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	No
47) Information sources  48) Location of negatives  Roll 117 #35,36,38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	No S
47) Information sources  48) Location of negatives  Roll 117 #35,36,38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	No S
48) Location of negatives  Roll 117 #35,36,38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica	No S
48) Location of negatives  Roll 117 #35,36,38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district hame of historical district	No S
48) Location of negatives  Roll 117 #35,36,38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district hame of historical district s site eligible?	No Ye
48) Location of negatives  Roll 117 #35,36,38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district hame of historical district s site eligible? district potential	No S
48) Location of negatives  Roll 117 #35,36,38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district hame of historical district s site eligible?	No Ye
48) Location of negatives  Roll 117 #35,36,38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district hame of historical district s site eligible? district potential	No S
47) Information sources  Roll 117 #35,36,38  49) Prepared by  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of stablished historical district hame of historical district s site eligible? district potential date revision	No S
48) Location of negatives  Roll 117 #35,36,38  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of stablished historical district hame of historical district s site eligible? district potential date revision	No S



### Missouri Historic Architectural Inventory for ( 2 3 1 5 2 Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number 1276
— public	2) name (cont)
39) Owners — name	3) name - historial
address	
	4) street address 936 W.Walnut st.
40) Local contact	5) town or vicinity Springfield
41) Coordinates (UTM)	6) legal description
42) Quad	7), county Greene
43) Other survey	8) category
70, 0(10.00.10)	(site, structure,
	)   D • 7 1 •
44) History	9) significance
	10) date
	11) style
	12) architect
	13) builder
	14) original use <u>commercial</u>
	SOLUTION OF STATE
	501110
45) Additional description	. 16) number of stories 2
	17) plan shape irregular
	18) basement partial
	Daittai
	Scorie
	20) wall construction brick
	21) roof type-
	material
•	22) contact print
	35mm
46) Description of environment/outbuildings	23) site plan
•	
47) Information sources	24) changes -
	additions/alter-
	ations/moved
	25) condition
	26) visible from road?
	27) distance/frontage
	28) accessible?
100 1	
48) Location of negatives	29) preservation
Roll <sub>123</sub> #20	underway?
49) Prepared by DDD	30) endangered?
	31) on National
50) Organization Missouri Honitago Trust	Register? No
Missouri Heritage Trust	
	32) part of
the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of the common of th	established
	historical district No
If additional space is need	33) name of historical
	district
	34) is site eligible?
	25) 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	35) district potential? Ye.
	35) district potential? $\gamma_{\Theta}$ 36) date $\frac{7}{5}$
	36) date $\frac{5/3/84}{}$
	36) date $\frac{5/3/84}{}$
HISTORIC INVENTORY FORM MISSOURI HERITAGE TRUST	36) date $\frac{5/3/84}{}$



### Missouri Historic Architectural Inventory for Company Division of Parks and Historic Preservation Department of Natural Resources

	•
38) Ownership — private	* 1) inventory number P-1277
put lic	2) name (cont)
39) Owners — name	3) name - historial
address	
(40) Local contact	1000 W.Walliuc BC.
41) Coordinates (UTM)	6) legal description Springfield
42) Quad	
	7) county Greene
43) Other survey	8) category
	(site, structure,
	building, object) Building
44) History	9) significance
	10) date
	11) style early catbuilder
	12) architect
	13) builder
	14) original use residence
45) Additional description	
45) Additional description	
	17) plan shape irregular
	18) basement partial
	19) foundation stone
	20) wall construction frame/lap siding
	21) roof type- gable-hip combo.
	material asphalt shingle
•	22) contact print
	35mm
ACV Describing of an in-	02) - 't
46) Description of environment/outbuildings	23) site plan
47) Information sources	24) changes -
	1
	additions/alter-
	additions/alter- ations/moved
	ations/moved
	ations/moved 25) condition
	ations/moved 25) condition 26) visible from road?
	ations/moved  25) condition  26) visible from road?  27) distance/frontage
AS) Lacation of propings	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?
48) Location of negatives	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation
Roll 143 #20-22	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?
Roll 143 $\#20$ –22	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation     underway?  30) endangered?
Roll 143 #20-22 49) Prepared by DDD	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National
Roll 143 #20-22  49) Prepared by  DDD	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National Register?  NO
Roll 143 #20-22 49) Prepared by DDD	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National
Roll 143 #20-22  49) Prepared by  DDD	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National Register?  NO
Roll 143 #20-22  49) Prepared by  DDD	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National Register? No  32) part of
Roll 143 #20-22  49) Prepared by  DDD	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National Register? No  32) part of  tablished
Roll 143 #20-22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation     underway?  30) endangered?  31) on National     Register?  NO  32) part of  tablished  storical district  NO
Roll 143 #20-22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation     underway?  30) endangered?  31) on National     Register?     No  32) part of  tablished     storical district     me of historical     Itrict
Roll 143 #20-22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National Register? No  32) part of  tablished storical district ne of historical trict site eligible?  16
Roll 143 #20-22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National Register? No  32) part of  tablished storical district ne of historical trict tite eligible? crict potential?  Ye
Roll 143 #20-22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National Register? No  32) part of tablished storical district ne of historical ltrict ite eligible? crict potential?  Ye.  5/3/84
Roll 143 #20-22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National Register? No  32) part of  tablished storical district ne of historical trict tite eligible? crict potential?  Ye
Roll 143 #20-22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	ations/moved  25) condition  26) visible from road?  27) distance/frontage  28) accessible?  29) preservation underway?  30) endangered?  31) on National Register? No  32) part of tablished storical district ne of historical ltrict ite eligible? crict potential?  Ye.  5/3/84





#### Missouri Historic Architectural Inventory for $G_{\mathcal{C}}$ (4. 6.3 - 760) Division of Parks and Historic Preservation Department of Natural Resources

20) 6	
38) Ownership — private	inventory number [N=223]
— public	2) name (cont)
39) Owners — name	3) name - historial
— address	4) street address 1003 W salmut et
40) Local contact	100) W. Halliac Sc.
41) Coordinates (UTM)	1 2011011610
	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
	(site, structure,
	building, object) Building
44) History	9) significance contributing
	10) date
	11) style
	12) architect
	13) builder
	14) original use residence
	15) presentuse Same
45) Additional description	· 16) number of stories 2
	17) plan shape rectangle
	18) basement partial?
	19) foundation concrete
	20) wall construction frame/modern siding
	21) roof type-
	material asphalt shingle
•	22) contact print
	35mm
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	
46) Description of environment/outbuildings	
46) Description of environment/outbuildings	
46) Description of environment/outbuildings  47) Information sources	
	24) changes -
	24) changes - additions/alter-
	24) changes - additions/alter- ations/moved
	24) changes - additions/alter- ations/moved 25) condition
	24) changes - additions/alter- ations/moved
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources  48) Location of negatives  Roll 133 #39	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
48) Location of negatives  Roll 133 #39  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
47) Information sources  48) Location of negatives  Roll 133 #39  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 133 #39  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No
47) Information sources  48) Location of negatives  Roll 133 #39  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of
47) Information sources  48) Location of negatives  Roll 133 #39  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established
47) Information sources  48) Location of negatives  Roll 133 #39  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of
47) Information sources  48) Location of negatives  Roll 133 #39  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established
47) Information sources  48) Location of negatives  Roll 133 #39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical
47) Information sources  48) Location of negatives  Roll 133 #39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district NO 33) name of historical district
47) Information sources  48) Location of negatives  Roll 133 #39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible?
48) Location of negatives  Roll 133 #39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site oligible?
48) Location of negatives  Roll 133 #39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
48) Location of negatives  Roll 133 #39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5/9/84
48) Location of negatives  Roll 133 #39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
48) Location of negatives  Roll 133 #39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust  If additional space is nee	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5/9/84
47) Information sources  48) Location of negatives  Roll 133 #39  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5/9/84



# 

·	т	<del></del>		
38) Ownership — private	1	inventory number	P-1278	=
— public	2)	name (cont)		
39) Owners — name	3)	name - historial		
— address		street address	1006 W Walnut at	
	(		1006 W.Walnut st.	
40) Local contact		town or vicinity	Springfield	
41) Coordinates (UTM)	1	legal description		
42) Quad	7)	county	Greene	
43) Other survey	8)	category	91.00110	2
40) Other surrey	) `	(site, structure,		2/3)
	Ì		Building	_
		building, object)	541141119	
44) History	9)	significance		
	10)	date		
	111	style	early catbuilder	
		architect	carry cars-barracr	}
	1	builder	L	}
	14)	original use	residence	
	15)	present use	same	1
45) Additional description		number of stories	7	4
nuuliiviiai uesoripiivii	- 1	plan shape		1
	- 1		irregular	1
	1 '	basement	partial	]
	[19]	foundation	stone	
	20)	wall construction	frame/lapsiding	1
	211	roof type -	gable-hip combo	1
	/	material	asphalt shingle	1
			asphatt shingle	122
·	(22)	contact print		5)
		35mm		
	- {			1
	- {			
	- (			
				1
46) Description of environment/outbuildings	23	) site plan		9
,				.}
				.
		<u> </u>		- (
·				-
	1-	<del></del>		- [
				-
47) Information sources	24	) changes -		5
47) Information Sources	- '	additions/alter-		1
	- {			1
•		ations/moved		_
	25	) condition		-
	26	) visible from road?	?	
	1			٦ .
	127	\ dictance/frontage		
	1	) distance/frontage		- m
	28	accessible?		6)
48) Location of negatives	28	_		6)
48) Location of negatives  Roll 143 #23-24	28	accessible?  preservation		6)
Roll 143 #23-24	28 29	) accessible? ) preservation underway?		6)
Roll 143 #23-24 49) Prepared by	28 29 30	accessible?  preservation underway?  endangered?		6)
Roll 143 #23-24  49) Prepared by  DDD	28 29 30	a) accessible? b) preservation underway? c) endangered? d) on National		6)
Roll 143 #23-24  49) Prepared by  DDD	28 29 30 31	accessible? b) preservation underway? c) endangered? d) on National Register?	No	6) 7)
Roll 143 #23-24  49) Prepared by  DDD	28 29 30 31	a) accessible? b) preservation underway? c) endangered? d) on National		
Roll 143 #23-24  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	28 29 30 31	accessible? b) preservation underway? c) endangered? d) on National Register?		
Roll 143 #23-24  49) Prepared by  DDD	28 29 30 31	a) accessible? b) preservation underway? c) endangered? c) on National Register? c) part of	No	
Roll 143 #23-24  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	28 29 30 31 32	accessible? b) preservation underway? c) endangered? d) on National Register? part of established historical district	No No	
Roll 143 #23-24  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	28 29 30 31 32	accessible? b) preservation underway? c) endangered? c) on National Register? c) part of established historical districts name of historical	No No	
Roll 143 #23-24  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	28 29 30 31 32	accessible? b) preservation underway? c) endangered? c) on National Register? c) part of established historical district district	No t No	
Roll 143 #23-24  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	28 29 30 31 32 33	accessible? b) preservation underway? c) endangered? d) on National Register? part of established historical district district district is site eligible?	No No No	7)
Roll 143 #23-24  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	28 29 30 31 32 33 34 31	accessible? b) preservation underway? c) endangered? d) on National Register? part of established historical district district district d) is site eligible? district potential	No No No No No No No No No No No No No N	
Roll 143 #23-24  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	28 29 30 31 32 33 34 31	accessible? b) preservation underway? c) endangered? d) on National Register? part of established historical district district district is site eligible?	No No No No No No No No No No No No No N	7)
Roll 143 #23-24  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	28 29 30 31 32 33 34 39 30	accessible? b) preservation underway? c) endangered? d) on National Register? part of established historical district district district d) is site eligible? district potential	No No No	7)
Roll 143 #23-24  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust	28 29 30 31 32 33 34 39 30	accessible? b) preservation underway? c) endangered? c) on National Register? c) part of established historical district district district district district potential district potential	No No No No No No No No No No No No No N	7)
Roll 143 #23-24  49) Prepared by  DDD  50) Organization Missouri Heritage Trust  If additional space i	28 29 30 31 32 33 34 39 30	accessible? b) preservation underway? c) endangered? c) on National Register? c) part of established historical district district district district district potential district potential	No No No No No No No No No No No No No N	7)
Roll 143 #23-24  49) Prepared by  DDD  50) Organization Missouri Heritage Trust  If additional space i	28 29 30 31 32 33 34 39 30	accessible? b) preservation underway? c) endangered? c) on National Register? c) part of established historical district district district district district potential district potential	No No No No No No No No No No No No No N	7)



# Missouri Historic Architectural Inventory for GQ - 146 - 003 - 760\* Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	1) inventory number	- 8 - 1919 <b>J</b> .
— public	2) name (cont)	1224
39) Owners — name	3) name - historial	
	4) street address	4044 57 17-7
— address	l '	1011 W.Walnut st.
40) Local contact	5) town or vicinity	Springfield
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county	Greene
43) Other survey	8) category	
	(site, structure,	
	building, object)	Building
44) History	9) significance	contributing
· · · · · · · · · · · · · · · · · · ·	10) date	Contributing
	11) style	late catbuilder
	12) architect	Lace Cat - Durider
	13) builder	
	γ	
	14) original use	residence
	15) present use	same
45) Additional description	16) number of stories	2
	17) plan shape	rectangle
	18) basement	partial?
	19) foundation	stone
	20) wall construction	frame/modern sidin
	21) roof type -	
		hip
	material	asphalt shingle
•	22) contact print 35mm	
46) Description of environment/outbuildings	23) site plan	
	0.41	
47) Information sources	24) changes -	
47) Information sources	additions/alter-	
	_	
	additions/alter-	
	additions/alter- ations/moved	
	additions/alter- ations/moved 25) condition 26) visible from road	,
	additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage	,
• ,	additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible?	,
48) Location of negatives	additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation	,
48) Location of negatives  Roll 133 #40-41	additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway?	,
48) Location of negatives  Roll 133 #40-41  49) Prepared by	additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	,
48) Location of negatives  Roll 133 #40-41	additions/alterations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
Roll 133 #40-41  49) Prepared by	additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	,
48) Location of negatives  Roll 133 #40-41  49) Prepared by	additions/alterations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
Roll 133 #40-41  49) Prepared by	additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	
Roll 133 #40-41  49) Prepared by	additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	No
Roll 133 #40-41  49) Prepared by  I)DD  50) Organization Missouri Heritage Trust	additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	No .
Roll 133 #40-41  49) Prepared by	additions/alterations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	No .
Roll 133 #40-41  49) Prepared by  I)DD  50) Organization Missouri Heritage Trust	additions/alterations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	No No
Roll 133 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	additions/alterations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	No No
Roll 133 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	additions/alterations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential	No No No No No Ye
Roll 133 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	additions/alterations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential	No No
Roll 133 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	additions/alterations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential	No No No No No Ye



# Missouri Historic Architectural Inventory for GR 14 003-703 Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	1) inventory number 14–225
— public	2) name (cont)
39) Owners — name	3) name - historial
address	4) street address 1015 W. Walnut st.
(40) Local contact	5) town or vicinity Springfield
41) Coordinates (UTM)	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
	(site, structure,
	building, object) Building
44) History	9) significance
	10) date
	11) style early catbuilder
	12) architect
	13) builder
	14) original use residence
	15) present use Same
45) Additional description	16) number of stories 1
	17) plan shape irregular
	10) foundation
	<u> Shone</u>
	20) wall construction frame/modern sidin
	21) roof type-
	material gable-hip combo.
	Schnalt Schnole
	22) contact print
	35mm
	·
	{
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	
46) Description of environment/outbuildings  47) Information sources	24) changes -
	24) changes - additions/alter-
	24) changes -
	24) changes - additions/alter-
	24) changes - additions/alter- ations/moved 25) condition
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources  48) Location of negatives  Roll 157 #17	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
47) Information sources  48) Location of negatives  Roll 157 #17  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
47) Information sources  48) Location of negatives  Roll 157 #17	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
47) Information sources  48) Location of negatives  Roll 157 #17  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 157 #17  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO
47) Information sources  48) Location of negatives  Roll 157 #17  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of
47) Information sources  48) Location of negatives  Roll 157 #17  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established
47) Information sources  48) Location of negatives  Roll 157 #17  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of
47) Information sources  48) Location of negatives  Roll 157 #17  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established
47) Information sources  48) Location of negatives  Roll 157 #17  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical
47) Information sources  48) Location of negatives  Roll 157 #17  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district
47) Information sources  48) Location of negatives  Roll 157 #17  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible?
47) Information sources  48) Location of negatives  Roll 157 #17  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? Yes.
47) Information sources  48) Location of negatives  Roll 157 #17  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? Yes.
47) Information sources  48) Location of negatives  Roll 157 #17  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? Ye
47) Information sources  48) Location of negatives  Roll 157 #17  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  27) changes - Additions/alter- Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/mo
47) Information sources  48) Location of negatives  Roll 157 #17  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  27) changes - Additions/alter- Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/moved Additions/mo



Missouri Historic Architectural Inventory for G 1-12-003-704 Division of Parks and Historic Preservation Department of Natural Resources

	•
38) Ownership — private	* 1) inventory number 17-226
— public	2) name (cont)
39) Owners — name	3) name - historial
— address	4) street address 1021 W.Walnut st.
40) Local contact	5) town or vicinity Springfield
41) Coordinates (UTM)	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
	(site, structure,
	building, object) Building
Ad) History	3, 1, 1, 1
44) History	9) significance
	10) date <u>ca. 1870</u>
	11) style vern, center hall
	12) architect
	13) builder
	14) original use residence
	15) present use same
45) Additional description	16) number of stories 1
	19) becoment
	20) wall construction frame/lap siding
	21) roof type-
	material asphalt shingle
•	22) contact print
	35mm
	,
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	
46) Description of environment/outbuildings  47) Information sources	
	24) changes -
	24) changes - additions/alter-
47) Information sources	24) changes - additions/alter- ations/moved
	24) changes - additions/alter- ations/moved 25) condition
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources  48) Location of negatives  Roll 157 #18-19  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
47) Information sources  48) Location of negatives  Roll 157 #18-19  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 157 #18-19  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No
47) Information sources  48) Location of negatives  Roll 157 #18-19  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of
47) Information sources  48) Location of negatives  Roll 157 #18-19  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established
47) Information sources  48) Location of negatives  Roll 157 #18-19  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No
47) Information sources  48) Location of negatives  Roll 157 #18-19  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No
47) Information sources  48) Location of negatives  Roll 157 #18-19  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district
47) Information sources  48) Location of negatives  Roll 157 #18-19  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible?  Ye.
47) Information sources  48) Location of negatives  Roll 157 #18-19  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? Ye. 35) district potential?
47) Information sources  48) Location of negatives  Roll 157 #18-19  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  24) changes - Additions/alter- ations/moved  No No No No No No No No No No No No No
47) Information sources  48) Location of negatives  Roll 157 #18-19  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? Ye. 35) district potential?
47) Information sources  48) Location of negatives  Roll 157 #18-19  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  24) changes - Additions/alter- ations/moved  No No No No No No No No No No No No No



Missouri Historic Architectural Inventory for GRADA COSTORIOS Division of Parks and Historic Preservation Department of Natural Resources

Division of Parks and Historic Preservation De	partment of Natura	l Resources
38) Ownership — private	* 1) inventory number	M -227
public	2) name (cont)	
39) Owners — name	3) name - historial	
address	4) street address	1027 W.Walnut st.
40) Local contact	5) town or vicinity	Springfield Sur
41) Coordinates (UTM)	6) legal description	Spr nigi re id
42) Quad	7) county	Greene
43) Other survey	8) category	
	(site, structure,	(3)
	building, object)	Building
44) History	9) significance	
	10) date	
	11) style	late catbuilder
	12) architect	Tabe Cae Bullidel
	13) builder	
•	14) original use	residence _
	15) present use	
45) Additional description	16) number of stories	apts.
	17) plan shape	2 2
	18) basement	rectangle
	19) foundation	partial
		stone
	20) wall construction	frame/modern siding
	21) roof type -	hip
	material	asphalt shingle
	22) contact print	
	35mm	
		•
$\cdot$ $\bigcup$		
46) Description of environment/outbuildings	23) site plan	9
47) Information sources	24) changes -	
	additions/alter-	
( × 14	ations/moved	
1 1 3	25) condition	
	26) visible from road?	
	27) distance/frontage	
	28) accessible?	
48) Location of negatives	29) preservation	<del></del>
	underway?	
Roll 157 $\#20$	30) endangered?	
	31) on National	
DDD	·	No
50) Organization Missouri Heritage Trust	Register?	No
•	32) part of	
KODAK Sagara en Artena	established	l Na
	historical district	No
If additional space is needed, attached sen	33) name of historical	1
	district	
	34) is site eligible?	No
	35) district potential?	
	36) date	5/6/84
and the second second	37) revision	



Division of Parks and Historic Preservation Dep	artment of Natural Resources
38) Ownership — private	1) inventory number 1,-228
public	2) name(cont)
39) Owners — name	3) name - historial
address	4) street address 1031 W.Walnut st.
40) Local contact	5) town or vicinity Springfield
41) Coordinates (UTM)	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
	(site, structure,
	building, object) Building
44) History	9) significance
	10) date
	11) style early catbuilder
	12) architect
	13) builder
	14) original use residence
	15) present use same
45) Additional description	* 16) number of stories 2
	17) plan shape irregular
•	18) basement partial
	19) foundation stone
	20) wall construction frame/modern sidin
	21) roof type-
	material apphalt shingle_
•	22) contact print
	35mm
•	•
46) Description of environment/outbuildings	23) site plan
	<del>╶╎╌╎╌╎╌┼╌┼┈┼┈╎┈╎┈╎┈╎┈┼┈┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼┼</del>
47) Information sources	24) changes -
	additions/alter-
1	ations/moved
	25) condition
	26) visible from road?
	27) distance/frontage
	28) accessible?
48) Location of negatives	29) preservation
Roll 157 #21-22	underway?
49) Prepared by	30) endangered?
DDD	31) on National
50) Organization Missouri Heritage Trust	Register? No
ilissour i her reage it use	32) part of
	established
	historical district No
If additional space is needed,	33) name of historical
	district
	34) is site eligible? NO
7.67 (0.022)	35) district potential? Ye.
	36) date $\frac{5/6/84}{}$
and the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of t	37) revision

MISSOURI HERITAGE TRUST



## Missouri Historic Architectural Inventory for G-12-16-3-76-7 Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number 1.–229
— public	2) name (cont)
39) Owners — name	3) name - historial
address	4) street address 1035-7 W.Walnut
40) Local contact	10))=/ Wawalluc
	J Springred
41) Coordinates (UTM)	6) legal description
42) Quad	7) county Greene
43) Other survey	
45) Other survey	8) category
	(site, structure,
	building, object) Building
44) History	9) significance
	10) date ca. 1925
	11) style bungalow
	12) architect
	13) builder
	14) original use duplex
	15) present use same
45) Additional description	16) number of stories
	17) plan shape rectangle
	18) basement full
	2. 0.2.2
	00110100
	20) wall construction brick veneer
	50010
	material asphalt shingle
•	22) contact print
	35mm
	3311111
	·
	•
/ \	
. ( )	
46) Description of environment/outbuildings	23) site plan : : : : : : : : : ! ! ! ! ! ! ! ! ! !
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	
46) Description of environment/outbuildings  47) Information sources	24) changes -
	24) changes - additions/alter-
	24) changes -
	24) changes - additions/alter- ations/moved
	24) changes - additions/alter- ations/moved 25) condition
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
	24) changes - additions/alter- ations/moved 25) condition
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources  48) Location of negatives  Roll 173 #8	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
47) Information sources  48) Location of negatives  Roll 173 #8	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
47) Information sources  48) Location of negatives  Roll 173 #8  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 173 #8  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No
47) Information sources  48) Location of negatives  Roll 173 #8  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 173 #8  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No
47) Information sources  48) Location of negatives  Roll 173 #8  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established
47) Information sources  48) Location of negatives  Roll 173 #8  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No
47) Information sources  48) Location of negatives  Roll 173 #8  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established
47) Information sources  48) Location of negatives  Roll 173 #8  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No
47) Information sources  48) Location of negatives  Roll 173 #8  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No 33) name of historical district
47) Information sources  48) Location of negatives  Roll 173 #8  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district No 33) name of historical district 34) is site eligible?
47) Information sources  48) Location of negatives  Roll 173 #8  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district No 33) name of historical district 34) is site eligible?
47) Information sources  48) Location of negatives  Roll 173 #8  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 34) is site eligible? 35) district potential?
47) Information sources  48) Location of negatives  Roll 173 #8  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 34) is site eligible? 35) district potential? 36) date  5/6/84
47) Information sources  48) Location of negatives  Roll 173 #8  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 34) is site eligible? 35) district potential?
47) Information sources  48) Location of negatives  Roll 173 #8  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 34) is site eligible? 35) district potential? 36) date  5/6/84
47) Information sources  48) Location of negatives  Roll 173 #8  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 34) is site eligible? 35) district potential? 36) date  5/6/84



### Missouri Historic Architectural Inventory for GP-A-003-763 Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number N=230
— public	2) name (cont)
39) Owners — name	3) name - historial
address	4) street address 1041 W. Walnut st.
40) Local contact	5) town or vicinity Springfield
41) Coordinates (UTM)	6) legal description
42) Quad	
	_
43) Other survey	8) category
	(site, structure,
	building, object) Building
44) History	9) significance
117 1113(01)	
	10) date
	11) style   late Italianate
	12) architect
	13) builder
	h
	15) presentuse apts.
45) Additional description	16) number of stories 2
	17) plan shape irregular
	211 000201
	18) basement partial
	19) foundation stone
	20) wall construction frame/modern sidi
	21) roof type - hip
	112.17
	aspliate sitting e
•	22) contact print
	35mm
46) Description of environment/outbuildings	23) site plan
47) Information courses	24) changes -
47) Information sources	_
•	additions/alter-
	ations/moved
in the second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second se	25) condition
	26) visible from road?
	27) distance/frontage
	28) accessible?
48) Location of negatives	29) preservation
Roll 157 #23-24	underway?
49) Prepared by	30) endangered?
רוב און דעדע To די די די די די די די די די די די די די	GG/ CHAGHEOLOG.
111111	
DDD	31) on National
EO. Ourseinstein	31) on National Register? NO
	31) on National
EO. Ourorisation	31) on National Register? NO
EM Commission	31) on National Register? NO 32) part of established
50) Organization Missouri Heritage Trust	31) on National Register? NO 32) part of established historical district NO
EO. Ourseinstein	31) on National Register? NO 32) part of established historical district NO 33) name of historical
50) Organization Missouri Heritage Trust	31) on National Register? NO 32) part of established historical district NO 33) name of historical district
50) Organization Missouri Heritage Trust	31) on National Register? NO 32) part of established historical district NO 33) name of historical district 34) is site eligible?
50) Organization Missouri Heritage Trust	31) on National Register? NO 32) part of established historical district NO 33) name of historical district A) is site eligible?
50) Organization Missouri Heritage Trust	31) on National Register? NO 32) part of established historical district NO 33) name of historical district 34) is site eligible? NO NO NO NO NO NO NO NO NO NO NO NO NO
50) Organization Missouri Heritage Trust	31) on National Register? NO  32) part of established historical district NO  33) name of historical district 34) is site eligible? 35) district potential?
50) Organization Missouri Heritage Trust	31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date No No No No No No No No No No No No No
Missouri Heritage Trust  If additional space is nee	31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date No No No No No No No No No No No No No
50) Organization Missouri Heritage Trust	31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date No No No No No No No No No No No No No



Missouri Historic Architectural Inventory for GR Access To a Division of Parks and Historic Preservation Department of Natural Resources

	,	
38) Ownership — private	1) inventory number	P-1280
— public	2) name (cont)	
39) Owners — name	3) name - historial	
— address	4) street address	
		1044 W.Walnut st.
40) Local contact	5) town or vicinity	Springfield
41) Coordinates (UTM)	<ol><li>6) legal description</li></ol>	
42) Quad	7) county	Greene
43) Other survey	8) category	
	(site, structure,	Duri Talian
	building, object)	Building
44) History	9) significance	
	10) date	
	11) style	late catbuilder
		race catburiter
	12) architect	
	13) builder	
	14) original use	residence
	15) present use	
45) Additional description	16) number of stories	apts.
	17) plan shape	irregular
	18) basement	partial
	19) foundation	stone
	20) wall construction	
		frame/modern sidin
	21) roof type -	hip
	material	asphatl shingle
•	22) contact print	<del></del>
	35mm	
	3	
46) Description of equironment/outhwildings	22) cita plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings		
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings  47) Information sources		
	24) changes - additions/alter-	
	24) changes - additions/alterations/moved	
	24) changes - additions/alter- ations/moved 25) condition	
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	
	24) changes - additions/alter- ations/moved 25) condition	
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	
47) Information sources  48) Location of negatives  Roll 143 #26	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	
47) Information sources  48) Location of negatives  Roll 143 #26  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	
47) Information sources  48) Location of negatives  Roll 143 #26	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	
47) Information sources  48) Location of negatives  Roll 143 #26  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
47) Information sources  48) Location of negatives  Roll 143 #26  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	
47) Information sources  48) Location of negatives  Roll 143 #26  49) Prepared by  DDD  59) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	
47) Information sources  48) Location of negatives  Roll 143 #26  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	No
48) Location of negatives  Roll 143 #26  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	No
47) Information sources  48) Location of negatives  Roll 143 #26  49) Prepared by  DDD  59) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	No
48) Location of negatives  Roll 143 #26  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	No
48) Location of negatives  Roll 143 #26  49) Prepared by  DDD  59) Organization Missouri Heritage Trust  If additional space is needed, attached separate shee	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district	No
48) Location of negatives  Roll 143 #26  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible?	No No
48) Location of negatives  Roll 143 #26  49) Prepared by  DDD  50) Organization Missouri Heritage Trust  If additional space is needed, attached separate shee	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential?	No No No Ye.
48) Location of negatives  Roll 143 #26  49) Prepared by  DDD  59) Organization Missouri Heritage Trust  If additional space is needed, attached separate shee	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential? 36) date	No No
48) Location of negatives  Roll 143 #26  49) Prepared by  DDD  59) Organization Missouri Heritage Trust  If additional space is needed, attached separate shee	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential?	No No No Ye.
48) Location of negatives  Roll 143 #26  49) Prepared by  DDD  50) Organization Missouri Heritage Trust  If additional space is needed, attached separate shee	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential? 36) date	No No No Ye.



#### Missouri Historic Architectural Inventory for Grand Company - 770 Division of Parks and Historic Preservation Department of Natural Resources

Division of Parks and Historic Preservation Dep		
38) Ownership — private	1) inventory number [1,-231	
— public	2) name (cont)	
39) Owners — name	3) name - historial	
address	4) street address 1045 W.Walr	ut st.
40) Local contact	5) town or vicinity Springfield	
41) Coordinates (UTM)	6) legal description	
42) Quad		<del></del>
43) Other survey	8) category Greene	
•	(site, structure,	
	building, object) Building	
44) History	9) significance	<del></del>
44, 110001	10) date	
	Queen minic	
	12) architect	
	13) builder	
	14) original use residence	
	15) present use same	
45) Additional description	16) number of stories	
	17) plan shape irregular	
	18) basement partial	
	(10) foundation	
	20) wall construction stone	an a d d d
	<u> </u>	en sidir
	- Agote-Hill	compo.
	22) contact print asphalt sh	ingle
	35mm	
	3311111	
,		
. 🔾		
46) Description of environment/outbuildings	23) site plan	
	23) site plan	
	23) site plan	
46) Description of environment/outbuildings		
	24) changes -	
46) Description of environment/outbuildings	24) changes - additions/alter-	
46) Description of environment/outbuildings	24) changes - additions/alter- ations/moved	
46) Description of environment/outbuildings	24) changes - additions/alter- ations/moved 25) condition	
46) Description of environment/outbuildings  47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	
46) Description of environment/outbuildings  47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	
46) Description of environment/outbuildings  47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives  Roll 157 #25-28	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives  Roll 157 #25-28  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives  Roll 157 #25-28	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives  Roll 157 #25-28  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	
46) Description of environment/outbuildings  47) Information sources  Roll 157 #25-28  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives  Roll 157 #25-28  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No	
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives  Roll 157 #25-28  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of	
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives  Roll 157 #25-28  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No	
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives  Roll 157 #25-28  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of	
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives  Roll 157 #25-28  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO NO	
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives  Roll 157 #25-28  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of  No	
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives  Roll 157 #25-28  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of  No  Ye: Ye: Ye:	
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives  Roll 157 #25-28  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of  No	
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives  Roll 157 #25-28  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of  No  Ye: Ye: Ye:	
46) Description of environment/outbuildings  47) Information sources  48) Location of negatives  Roll 157 #25-28  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of  No  Ye: Ye: Ye:	

MISSOURI HERITAGE TRUST



### 

nventory number	P-1281
name (cont)	
name - historial	
	1052 W Walnut at
	1052 W.Walnut st.
town or vicinity	Springfield
legal description	
county	Greene
category	30220.2
(site, structure,	Į.
building, object)	Building
significance	
date	
style	early catbuilder
architect	
builder	
original use	
_	residence
present use	apts.
number of stories	2
plan shape	irregular
basement	
foundation	partial
	stone
wall construction	frame/lap siding
roof type -	hip with gable wal
material	dormer
contact print	asphalt shingle
35mm	aspirate sittingto
site plan	
changes -	
additions/alter-	
ations/moved	
condition	
visible from road?	
distance/frontage	
- J.	
accessible?	
preservation	
underway?	
endangered?	
on National	
Register?	No
_	110
part of	
established	
historical district	No
name of historical	
district	
is site eligible?	No
district potential?	
	Ye.
date	5/3/84
	I .
revision	
revision	
revis	



### Missouri Historic Architectural Inventory for Galage (1972) Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number P=1282
publ €	2) name (cont)
39) Owners — name	3) name - historial
address	
40) Local contact	1000 W. Walluc St.
41) Coordinates (UTM)	, i Spiritui leta
	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
	(site, structure,
	building, object) Building
44) History	9) significance
·	10) date
	11) style late catbuilder
	12) architect
	13) builder
	14) original use residence
	15) presentuse same
45) Additional description	16) number of stories 2
	17) plan shape rectangle
	18) basement partial?
	19) foundation concrete
	20) wall construction frame/modern siding
	Treame/ model in Order
	112 5
	22) contact print
	35mm
	·
4b) Description of environment/outbuildings	123) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	
46) Description of environment/outbuildings	
46) Uescription of environment/outbuildings	
46) Description of environment/outbuildings	
46) Description of environment/outbuildings	
46) Description of environment/outbuildings  47) Information sources	
	24) changes - additions/alter-
	24) changes - additions/alter- ations/moved
	24) changes - additions/alter- ations/moved 25) condition
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources  48) Location of negatives  Roll 143 #29-30	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
48) Location of negatives  Roll 143 #29-30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources  48) Location of negatives  Roll 143 #29-30	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
47) Information sources  48) Location of negatives  Roll 143 #29–30  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 143 #29-30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No
47) Information sources  48) Location of negatives  Roll 143 #29–30  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of
47) Information sources  48) Location of negatives  Roll 143 #29–30  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established
47) Information sources  48) Location of negatives  Roll 143 #29-30  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No
47) Information sources  48) Location of negatives  Roll 143 #29–30  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical
47) Information sources  48) Location of negatives  Roll 143 #29-30  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district
47) Information sources  48) Location of negatives  Roll 143 #29-30  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible?
47) Information sources  48) Location of negatives  Roll 143 #29-30  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
47) Information sources  48) Location of negatives  Roll 143 #29-30  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  24) changes - Additions/alter- ations/moved 25) NO NO NO NO NO NO NO NO NO NO NO NO NO
47) Information sources  48) Location of negatives  Roll 143 #29-30  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
47) Information sources  48) Location of negatives  Roll 143 #29-30  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  24) changes - Additions/alter- ations/moved 25) NO NO NO NO NO NO NO NO NO NO NO NO NO
47) Information sources  48) Location of negatives  Roll 143 #29-30  49) Prepared by  DDD  50) Organization  Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  24) changes - Additions/alter- ations/moved 25) NO NO NO NO NO NO NO NO NO NO NO NO NO



# Missouri Historic Architectural Inventory for GRAC-DGB-TTDB Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private *	1)	inventory number	N-232	Œ
public	2)	name (cont)		
39) Owners — name	3)	name - historial		7
address	4)	street address	1101 W.Walnut st.	7
40) Local contact	1	town or vicinity	Springfield	
41) Coordinates (UTM)	1	legal description		]
42) Quad	l	county	Greene	
43) Other survey	8)	category		2/3)
		(site, structure,	Building	<u> </u>
		building, object)		4
44) History		significance		_
		date	ca. 1920	_
		style	bungalow	_
	- (	architect builder		4
		original use		4
		present use	residence	
45) Additional description	- 1	number of stories	same	+
45) Additional description .		plan shape	noat anglo	= ا
		basement	rectangle full	4
	1	foundation	concrete	-
	1	wall construction	frame/lap siding	-
		roof type -	gable	+
		material	asphalt shingle	$\dashv$
	22)	contact print	asphato shingle	5
		35mm		
				Ì
				)
	}			Ì
_				- i
	1			
46) Description of environment/outbuildings	23)	site plan	·	(6
46) Description of environment/outbuildings	23)	site plan		(6
46) Description of environment/outbuildings	23)	site plan		(6)
46) Description of environment/outbuildings	23)	) site plan		(6
46) Description of environment/outbuildings	23)			9)
46) Description of environment/outbuildings  47) Information sources		) changes -		9) (5)
		changes - additions/alter-		
47) Information sources	24	changes - additions/alter- ations/moved		
47) Information sources	24	changes - additions/alter- ations/moved		
47) Information sources	24	changes - additions/alter- ations/moved ) condition ) visible from road?		
47) Information sources	24 25 26 27	changes - additions/alter- ations/moved condition visible from road?		5)
47) Information sources	24 25 26 27 28	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?		
47) Information sources  48) Location of negatives	24 25 26 27 28	changes - additions/alter- ations/moved condition visible from road?		5)
47) Information sources  48) Location of negatives  RO11 117 #33	24 25 26 27 28 29	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?		5)
48) Location of negatives  Roll 117 #33  49) Prepared by	24 25 26 27 28 29	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?		5)
48) Location of negatives  Roll 117 #33  49) Prepared by  DDD	24 25 26 27 28 29	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?		5)
48) Location of negatives  Roll 117 #33  49) Prepared by	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of		5)
48) Location of negatives  Roll 117 #33  49) Prepared by  DDD	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	No	5)
48) Location of negatives  Roll 117 #33  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? !) part of established historical district	No No	5)
48) Location of negatives  Roll 117 #33  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	No No	5)
48) Location of negatives  Roll 117 #33  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	No	5)
48) Location of negatives  Roll 117 #33  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31 32	changes - additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? !) part of established historical district so name of historical district is site eligible?	No No	(5)
48) Location of negatives  Roll 117 #33  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31 32 34 35	changes - additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? !) part of established historical district so name of historical district is site eligible? district potential?	No No No Inc	5)
48) Location of negatives  Roll 117 #33  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31 32 33 34 35 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	No No	(5)
48) Location of negatives  Roll 117 #33  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24 25 26 27 28 29 30 31 32 33 34 35 36	changes - additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? !) part of established historical district so name of historical district is site eligible? district potential?	No No No Inc	(5)



# Missouri Historic Architectural Inventory for Garage 2003-774 Division of Parks and Historic Preservation Department of Natural Resources

* 1) inventory number P-1283	
2) name (cont)	
3) name - historial	
1 OH WAIHUU	St.
- 1 JDI 11191 1 <u>E1u</u>	
7) county Greene	
8) category	
(site. structure.	
L D	
1	
11) style early catbui	lder
12) architect	
13) builder	
• 16) number of stories	
17) plan shape   irregular	
1,	
102020	
300110	<del></del>
11 ame/ medel 11	
21) roof type- hip with gable	wir
35mm	
23) site plan	
24) changes - additions/alters	
24) changes - additions/alter-	
24) changes - additions/alter- ations/moved	
24) changes - additions/alter-	
24) changes - additions/alter- ations/moved	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district NO	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district NO 33) name of historical district	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district NO 33) name of historical district 34) is site eligible?	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 34) is site eligible? 35) district potential?	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 34) is site eligible? 35) district potential? 36) date  100  100  100  100  100  100  100  1	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 34) is site eligible? 35) district potential?	
24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 34) is site eligible? 35) district potential? 36) date  100  100  100  100  100  100  100  1	
	2) name (cont) 3) name - historial 4) street address 5) town or vicinity 6) legal description 7) county  8) category (site, structure, building, object)  9) significance 10) date 11) style 12) architect 13) builder 14) original use 15) present use  16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print 35mm   23) site plan



Missouri Historic Architectural Inventory for GR-F-0003-775 Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number 1233
— puolic	2) name (cont)
39) Owners — name	
	3) name - historial
— address	4) street address 1107 W.Walnut st.
40) Local contact	
41) Coordinates (UTM)	, Solitidi teta
	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
·, · · · · · · · · · · · · · · · · · ·	_ :
	(site, structure,
	building, object) Building
44) History	9) significance
, , , , , , , , , , , , , , , , , , ,	
	10) date ca. 1920
	11) style bungalow
	12) architect
	)
•	13) builder
	14) original use residence
	15) precentuse
AEN Additional desired	1 3450
45) Additional description	16) number of stories -
	17) plan shape
	18) because
	1 11
	19) foundation concrete
	iname/lap siding
	1.91.010
	achhalt shingle
·	22) contact print
	35mm
	·
	[
46) Description of environment/outbuildings	23) site plan : : : : : : : : : : : : : : : : : : :
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	
46) Description of environment/outbuildings	
46) Description of environment/outbuildings  47) Information sources	
	24) changes -
	24) changes - additions/alter-
47) Information sources	24) changes - additions/alter- ations/moved
	24) changes - additions/alter-
47) Information sources	24) changes - additions/alter- ations/moved 25) condition
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources  48) Location of negatives  Roll 157 #30	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources  48) Location of negatives  Roll 157 排30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
47) Information sources  48) Location of negatives  Roll 157 #30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 157 #30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No
47) Information sources  48) Location of negatives  Roll 157 #30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 157 #30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of
47) Information sources  48) Location of negatives  Roll 157 #30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established
48) Location of negatives Roll 157 排30 49) Prepared by DDD 50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No
48) Location of negatives Roll 157 排30 49) Prepared by DDD 50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established
47) Information sources  48) Location of negatives  Roll 157 #30  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No 33) name of historical
48) Location of negatives Roll 157 排30 49) Prepared by DDD 50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district
48) Location of negatives Roll 157 排30 49) Prepared by DDD 50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? Ivo
48) Location of negatives Roll 157 排30 49) Prepared by DDD 50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? Ivo
47) Information sources  48) Location of negatives  Roll 157 排30  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? Ye.
47) Information sources  48) Location of negatives  Roll 157 排30  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5/6/84
48) Location of negatives Roll 157 排30 49) Prepared by DDD 50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? Ye.
47) Information sources  48) Location of negatives  Roll 157 排30  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5/6/84
47) Information sources  48) Location of negatives  Roll 157 #30  49) Prepared by  50) Organization Missouri Heritage Trust  If additional space is needed, attached	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date 37) revision
48) Location of negatives Roll 157 排30 49) Prepared by DDD 50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date 37) revision



### Missouri Historic Architectural Inventory for $G \approx 7.003 - 7.76$ Division of Parks and Historic Preservation Department of Natural Resources

		•	
38) Ownership — private		* 1) inventory number	P-1284
— public  39) Owners — name		2) name (cont)	
		3) name - historial	
— address		4) street address	1110 W.Walnut st.
40) Local contact		5) town or vicinity	Springfield
41) Coordinates (UTM)		6) legal description	
42) Quad		7) county	Greene
43) Other survey		8) category	
		(site, structure,	Puilding
		building, object)	Building
44) History		9) significance	
		10) date	
		11) style	early catbuilder
		12) architect	
		13) builder	
	•	14) original use	residence
<u> </u>		15) present use	same
45) Additional description	•	<ul> <li>16) number of stories</li> </ul>	<u> </u>
		17) plan shape	irregular
		18) basement	partial
		19) foundation	stone
		20) wall construction	frame/lap siding
		21) roof type -	hip with gable win
		material	asphalt shingle
•		22) contact print 35mm	
46) Description of environment,	/outbuildings	23) site plan	
47) Information sources		24) changes -	
		additions/alter-	
		ations/moved	
		25) condition	
		26) visible from road?	
·		27) distance/frontage	
		28) accessible?	
		29) preservation	
· La Comment	Roll 134 #16-17	underway?	
	ia il 🛊	30) endangered?	
E	DDD 143 #P	31) on National	
	uri Heritage Trust	Register?	No
.00	ii i nei itage ii ust	32) part of	
		established	
		historical district	110
If additional spac		33) name of historica	1
		district	
		34) is site eligible?	No
		35) district potential	? Yes
		36) date	5/4/84
		37) revision	
711.2	1111		
HISTORIC INVENTORY FORM			
		I	i .



# Missouri Historic Architectural Inventory for GRAGOUS-777 Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number K-234
public	2) name (cont)
39) Owners — name	3) name - historial
— address	4) street address 1111 W. Walnut st.
40) Local contact	
41) Coordinates (UTM)	701 HQL1514
	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
	(site, structure,
	building, object) Building
44) History	9) significance
	10) date ca. 1915
	0411/3421011
	12) architect
•	13) builder
	14) original use residence
	, 15) present use same
45) Additional description	16) number of stories 1 2
	17) plan shape rectangle
	1000011620
	1411
	19) foundation concrete
	20) wall construction frame/modern sidin
	21) rooftype- gable
	material asphalt shingle
•	22) contact print
	35mm
4 J	
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	
46) Description of environment/outbuildings	
46) Description of environment/outbuildings  47) Information sources	24) changes -
	24) changes - additions/alter-
	24) changes - additions/alter- ations/moved
	24) changes - additions/alter- ations/moved 25) condition
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
	24) changes - additions/alter- ations/moved 25) condition
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources  48) Location of negatives  Roll 157 #31	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
47) Information sources  48) Location of negatives  Roll 157 #31  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
47) Information sources  48) Location of negatives  Roll 157 #31  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
48) Location of negatives  Roll 157 #31  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?
47) Information sources  48) Location of negatives  Roll 157 #31  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
48) Location of negatives  Roll 157 #31  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?
48) Location of negatives  Roll 157 #31  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established
48) Location of negatives  Roll 157 #31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No
48) Location of negatives  Roll 157 #31  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No 33) name of historical
48) Location of negatives  Roll 157 #31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district
48) Location of negatives  Roll 157 #31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible?
48) Location of negatives  Roll 157 #31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
48) Location of negatives  Roll 157 #31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5 /6/8/4
48) Location of negatives  Roll 157 #31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
48) Location of negatives  Roll 157 #31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5 /6/8/4
47) Information sources  48) Location of negatives  Roll 157 #31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5 /6/8/4



## Missouri Historic Architectural Inventory for $(2k)_{F}$ $(2k)_{F}$ $(3k)_{F}$ Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number 11-235
— public	2) name (cont)
39) Owners — name	3) name - historial
— address	4) street address 1113 W.Walnut st.
40) Local contact	5) town or vicinity Springfield
41) Coordinates (UTM)	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
	(site, structure,
	building, object) Building
44) History	9) significance
	10) date ca. 1910
	11) style late catbuilder
	12) architect
	13) builder
	14) original use residence
	15) present use Same
45) Additional description	16) number of stories 2
	17) plan shape irregular
	18) basement partial
	19) foundation stone
	20) wall construction frame/modern sidi
	21) roof type- hip with gable win
	material asphalt shingle
•	22) contact print
	35mm
$\bigcirc$	
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings  47) Information sources	24) changes -
	24) changes - additions/alter-
47) Information sources	24) changes - additions/alter- ations/moved
	24) changes - additions/alter- ations/moved 25) condition
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources  48) Location of negatives  Roll 157 #32	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
47) Information sources  48) Location of negatives  Roll 157 #32  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
47) Information sources  48) Location of negatives  Roll 157 #32  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 157 #32  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No
47) Information sources  48) Location of negatives  Roll 157 #32  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of
47) Information sources  48) Location of negatives  Roll 157 #32  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established
47) Information sources  48) Location of negatives  Roll 157 #32  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No
47) Information sources  48) Location of negatives  Roll 157 #32  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No
47) Information sources  48) Location of negatives  Roll 157 #32  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No 33) name of historical district
47) Information sources  48) Location of negatives  Roll 157 #32  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible?
47) Information sources  48) Location of negatives  Roll 157 #32  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 34) is site eligible? 35) district potential?  Very
47) Information sources  48) Location of negatives  Roll 157 #32  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No 33) name of historical district 34) is site eligible? 35) district potential? 36) date  24) changes - additions/alter- ations/moved No No No No No No No No No No No No No
47) Information sources  48) Location of negatives  Roll 157 #32  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 34) is site eligible? 35) district potential?  Very
47) Information sources  48) Location of negatives  Roll 157 #32  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No 33) name of historical district 34) is site eligible? 35) district potential? 36) date  24) changes - additions/alter- ations/moved No No No No No No No No No No No No No



### Missouri Historic Architectural Inventory for CR-C-COS-779Division of Parks and Historic Preservation Department of Natural Resources

70.0	
38) Ownership — private	• 1) inventory number P-1285
— putic	2) name (cont)
39) Owners — name	3) name - historial
— address	4) street address 1114 W.Walnut st.
40) Local contac	5) town or vicinity   Springfield
41) Coordinates UTM)	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
·	(site, structure,
	building, object) Building
44) History	9) significance
44) Mistory	10) date
	11) style early catbuilder
	12) architect
	13) builder
	14) original use residence
	15) present use same
45) Additional description	16) number of stories 7
	10) foundation
	SLOTE
	Trame/modern sluin
	21) roof type- hip with gable win
	material asphalt shingle
•	22) contact print
46) Description of environment/outbuildings	23) site plan
47) Information sources	24) changes -
	additions/alter-
	ations/moved
	25) condition
	26) visible from road?
	27) distance/frontage
	28) accessible?
48) Location of negatives	29) preservation
Roll 134 #18-20	underway?
49) Prepared by	30) endangered?
DDD	31) on National
50) Organization Missouri Honitago Thust	Register? No
Missouri Heritage Trust	32) part of
	- actablished
	al district No
If additional spac	f historical
in additional space	
	ligible? No
Company of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the s	potential? Ye.
	5/4/84
	14 A 14 A 14 A 14 A 14 A 14 A 14 A 14 A





### Missouri Historic Architectural Inventory for GR-H-GS-780Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	1) inventory number P-1286
— public	2) name (cont)
39) Owners — name	3) name - historial
— address	4) street address 1122 W. Walnut st
40) Local contact	5) town or vicinity   Sprinafield
41) Coordinates (UTM)	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
	(site, structure,
	building, object) Building
44) History	9) significance
	10) date
	11) style early catbuild
	12) architect
	13) builder
	14) original use <u>fesidence</u>
	15) present use Same
45) Additional description	* 16) number of stories 1 1
	17) plan shape irregular
	10)
	<u>scone</u>
	<u> </u>
	22) contact print
	35mm
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	
•	
•	
•	
•	
	24) changes -
	24) changes - additions/alterations/moved
	24) changes - additions/alter- ations/moved 25) condition
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
	24) changes - additions/alter- ations/moved 25) condition
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources  48) Location of negatives  Roll 134 #21-22	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
47) Information sources  48) Location of negatives  Roll 134 #21-22  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
47) Information sources  48) Location of negatives  Roll 134 #21–22  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 134 #21-22  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No
47) Information sources  48) Location of negatives  Roll 134 #21-22  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 134 #21-22  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established
48) Location of negatives  Roll 134 #21-22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district NO
47) Information sources  48) Location of negatives  Roll 134 #21-22  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical
47) Information sources  48) Location of negatives  Roll 134 #21-22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district
47) Information sources  48) Location of negatives  Roll 134 #21-22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible?
47) Information sources  48) Location of negatives  Roll 134 #21-22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
47) Information sources  48) Location of negatives  Roll 134 #21-22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  24) changes - additions/alter- ations/moved  No No No No No No No No No No No No No
47) Information sources  48) Location of negatives  Roll 134 #21-22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
47) Information sources  48) Location of negatives  Roll 134 #21-22  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  24) changes - additions/alter- ations/moved  No No No No No No No No No No No No No



	inventory number	31 036	_
38) Ownership — private	2) name (cont)	м-236	ן:
— public	l L		4
39) Owners — name	3) name - historial		]
— address	4) street address	1125 W.Walnut st.	1
40) Local contact	5) town or vicinity	Springfield	]
41) Coordinates (UTM)	6) legal description	· · · · · · · · · · · · · · · · · · ·	_
42) Quad	7) county	Greene	<u> </u>
43) Other survey	8) category		2/3)
	(site, structure,	D :1:	ω
	building, object)	Building	}
44) History	9) significance		1
	10) date	ca. 1900	1
	11) style	early catbuilder	<del>i</del>
	12) architect	Cally Cab - Barrao	7
	13) builder		4
	14) original use		┪
	15) present use	<u>residence</u>	4
	16) number of stories	same	_
45) Additional description	1		4
	17) plan shape	<u>irregular</u>	4
	18) basement	partial	4
	19) foundation	stone	_
	20) wall construction	<u>frame/</u> lap <u>sidi</u>	$1_{P_{i}}$
	21) roof type -	gable and hip com	
	material	asphalt shingle	- [
•	22) contact print		5
	35mm		
46) Description of environment/outbuildings	23) site plan	131 331 431 141 141 14	9
			-
47) Information sources	24) changes -		5
47) miormation sources	additions/alter-		-
	ations/moved		
) <u>,</u>	25) condition		$\dashv$
			-
	26) visible from road?		-
	27) distance/frontage		- 6
	28) accessible?		۳
48) Location of negatives	29) preservation	1	- }
Roll 157 #33-34	underway?		_
49) Prepared by	30) endangered?		_
DDD	31) on National		
50) Organization Missouri Heritage Trust	Register?	No	ᆫ
Missoul i Heritage ir ust	32) part of		-
The state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the s	established		
	historical district	No	
If additional space is negative.	33) name of historica		-
	district		
	34) is site eligible?	No	
	35) district potential	Yeə	30
	36) date	5/6/84	
	27)		1
	37) revision		_
· ·	37) revision		



### Missouri Historic Architectural Inventory for 67-47-603-782Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number P=1287	
— public	2) name (cont)	
39) Owners — name	3) name - historial	
— address		
	4) street address 1200 W.Walnut st	•
40) Local contact	5) town or vicinity Springfield	
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county Greene	
43) Other survey	8) category	
	(site, structure,	
	D	
44) History	9) significance	
	10) date	
	11) ctulo	
	12) architect	
	13) builder	
	14) original use residence	
	115) presentuse	
45) Additional description	* 16) number of stories Same	
· · · · · · · · · · · · · · · · · · ·		
	111_00 4141	
	18) basement partial	
	19) foundation stone	
	20) wall construction brick	
	21) roof type- truncated hip W	1 t. h
		1011
	50010 1121160	
	22) contact print as phalt shingle	
	<u></u>	
46) Description of environment/outbuildings	23) site plan	
		441
		++
47) Information sources		
47) Information sources	24) changes -	
47) Information sources	24) changes - additions/alter-	
47) Information sources	24) changes - additions/alter- ations/moved	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	
48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	
48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation	
48) Location of negatives Roll 134 #23-25	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	
48) Location of negatives  Roll 134 #23-25  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	
48) Location of negatives  Roll 134 #23-25  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
48) Location of negatives  Roll 134 #23-25  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	
48) Location of negatives  Roll 134 #23-25  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
Roll 134 #23-25  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of	
Roll 134 #23-25  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established	
48) Location of negatives  Roll 134 #23-25  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district NO	
Roll 134 #23-25  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district name of historical	
48) Location of negatives  Roll 134 #23-25  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district name of historical district NO	
48) Location of negatives  Roll 134 #23-25  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district name of historical district is site eligible?  Yes	
48) Location of negatives  Roll 134 #23-25  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district name of historical district is site eligible? Yes	
48) Location of negatives  Roll 134 #23-25  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district name of historical district is site eligible? district potential?	
48) Location of negatives  Roll 134 #23-25  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district name of historical district is site eligible? district potential?	
48) Location of negatives  Roll 134 #23-25  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district name of historical district is site eligible? date revision  24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation Underway? 30) endangered? 31) on National Register? No No No No No No No No No No No No No	
48) Location of negatives  Roll 134 #23-25  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district name of historical district is site eligible? district potential? date  5 / 4 / 8 4	



## Missouri Historic Architectural Inventory for GROUP 693-783 Division of Parks and Historic Preservation Department of Natural Resources

		_
38) Ownership — private	1) inventory number 14-237	
— public	2) name (cont)	
39) Owners — name	3) name - historial	
— address	4) street address 1201 W. Walnut s	st.
40) Local contact	5) town or vicinity Springfield	
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county Greene	
43) Other survey	7) county Greene 8) category	
	(site, structure, building Building	
	_	
44) History	9) significance	
	10) date ca. 1905	
	11) style late catbuild	don
	12) architect	uer
	13) builder	
	14) original use residence	
•	15) present use same	
45) Additional description	• 16) number of stories	
	<u> </u>	
	18) basement partial	
·	19) foundation stone	
	20) wall construction frame/modern s	idir
	21) roof type- hip and gable	
	hill and gathe	
•	material asphalt shingl  [22] contact print	<u>e                                     </u>
	35mm	
46) Description of environment/outbuildings	23) site plan	<u> </u>
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	a comparation of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of t	
46) Description of environment/outbuildings	a comparation of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of t	
46) Description of environment/outbuildings	a comparation of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of the party of t	
46) Description of environment/outbuildings		
46) Description of environment/outbuildings  47) Information sources		
	24) changes -	
	24) changes - additions/alter- ations/moved	
	24) changes - additions/alter- ations/moved 25) condition	
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?	
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage	
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?	
47) Information sources  48) Location of negatives  Roll 157 #35-36	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?	
47) Information sources  48) Location of negatives  Roll 157 #35-36  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	
47) Information sources  48) Location of negatives  Roll 157 #35-36  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
47) Information sources  48) Location of negatives  Roll 157 #35-36  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No	
47) Information sources  48) Location of negatives  Roll 157 #35-36  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO	
47) Information sources  48) Location of negatives  Roll 157 #35-36  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No	
48) Location of negatives  Roll 157 #35-36  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of	
48) Location of negatives  Roll 157 #35-36  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established	
47) Information sources  48) Location of negatives  Roll 157 #35-36  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No	
48) Location of negatives  Roll 157 #35-36  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district	
48) Location of negatives  Roll 157 #35-36  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? No	
48) Location of negatives  Roll 157 #35-36  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	
48) Location of negatives  Roll 157 #35-36  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5 /6 /8 4	
47) Information sources  48) Location of negatives  Roll 157 #35-36  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?	
48) Location of negatives  Roll 157 #35-36  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5 /6 /8 4	
48) Location of negatives  Roll 157 #35-36  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  5 /6 /8 4	



## Missouri Historic Architectural Inventory for GRA-16-3-784 Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number 12-238
— public	2) name (cont)
39) Owners — name	3) name - historial
— address	4) street address 1205 W.Walnut st.
40) Local contact	5) town or vicinity Springfield
41) Coordinates (UTM)	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
,	(site, structure,
	building, object) Building
44) History	9) significance
44) History	
	10) date <u>ca. 1910</u>
	11) style late catbuilder
	12) architect
	13) builder
	14) original use residence
	15) present use same
45) Additional description	16) number of stories 12
	17) plan shape irregular
	18) basement partial?
	19) foundation stone
	500110
	II mac/ Hap braring
	1,00±0
	material asphalt shingle
·	22) contact print
	35mm
	·
. $\bigcup$	
46) Description of environment/outbuildings	23) site plan : : : : : : : : : : : : : : : : : : :
47) Information sources	24) changes -
47) Information sources	24) changes - additions/alter-
47) Information sources	24) changes - additions/alter- ations/moved
47) Information sources	24) changes - additions/alter- ations/moved 25) condition
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
47) Information sources	24) changes - additions/alter- ations/moved 25) condition
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage
48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?
48) Location of negatives  Roll 157 #37  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
48) Location of negatives  Roll 157 #37  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
48) Location of negatives Roll 157 $\#37$ 49) Prepared by	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO
48) Location of negatives  Roll 157 #37  49) Prepared by  DDD	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of
48) Location of negatives  Roll 157 #37  49) Prepared by  DDD	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established
Roll 157 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No
48) Location of negatives  Roll 157 #37  49) Prepared by  DDD	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical
Roll 157 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district NO 33) name of historical district
Roll 157 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible?
Roll 157 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
Roll 157 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible?
Roll 157 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?
Roll 157 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  24) changes And And And And And And And And And And
Roll 157 #37  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter-ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  24) changes And And And And And And And And And And



Missouri Historic Architectural Inventory for GRA - OCS - 785Division of Parks and Historic Preservation Department of Natural Resources

	ation Department of Natural Resources
38) Ownership — private	* 1) inventory number P=1288
— public	2) name (cont)
39) Owners — name — address	3) name - historial 4) street address 1210 W. Walnut, st.
40) Local contact	THE TO ME HAZZINGO DO
41) Coordinates (UTM)	5) town or vicinity Springfield 6) legal description
42) Quad	
43) Other survey	
•	(site, structure,
	building, object) Building
44) History	9) significance
	10) date
	11) style <u>late catbuilder</u>
	12) architect
	13) builder
•	14) original use residence
	15) presentuse a.pts
45) Additional description	16) number of stories 2
	17) plan shape irregular
	18) basement partial
	19) foundation
	20) wall construction frame/modern sidin
	21) roof type hip
	material asphalt ahingle  22) contact print
	22) contact print 35mm
	33/1111
46) Description of environment/outbuildings	23) site plan
·	
•	
47) Information sources	24) changes -
	additions/alter-
	ations/moved
	25) condition
	26) visible from road?
	27) distance/frontage 28) accessible?
48) Location of negatives	29) preservation
Roll 134 #26	underway?
49) Prepared by	30) endangered?
DDD	31) on National
EO) Organization	Register? No
Missouri Heritage Trust	32) part of
A CHITATE THE THE TANK A	established
	historical district No
If additional space is needed, atta	33) name of historical
	district
	34) is site eligible?
	35) district potential? You
	36) date 5/4/84
	37) revision
HISTORIC INVENTORY FORM	
MISSOURI HERITAGE TRUST	l l



## Missouri Historic Architectural Inventory for G ( 200 200 786). Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number M-239
— public	2) name (cont)
39) Owners — name	3) name - historial
address	4) street address 1211 W.Walnut st.
40) Local contact	5) town or vicinity Springfield
41) Coordinates (UTM)	6) legal description
42) Quad	7) county Greene
43) Other survey	8) category
	(site, structure,
	building, object,
44) History	9) significance
	10) date ca. 1910 11) style late catbuilder
	12) architect
	13) builder
	14) original use residence
	15) present use Same
AGN ALBINING CONTRACTOR	
45) Additional description	1
	17) plan shape irregular 18) basement partial
	19) foundation stone
	20) wall construction frame/modern siding
	21) roof type- gable asphalt shingle
	22) contact print
	35mm
46) Description of environment/outbuildings	23) site plan
40) Description of environment/outbuildings	
47) Information sources	24) changes -
47) monación sources	additions/alter-
	ations/moved
	25) condition
	26) visible from road?
	27) distance/frontage
	28) accessible?
AQV Location of negatives	29) preservation
48) Location of negatives  Roll 157 #38	underway?
	30) endangered?
49) Prepared by	31) on National
DDD DDD	Register? No
50) Organization Missouri Heritage Trust	32) part of
	established
•	historical district NO
If additional space is needed, at	33) name of historical
ii additional space is needed, all the	district
	34) is site eligible? Ivo
	35) district potential? Yes
	36) date 5/6/84
	37) revision
The state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the s	37) revision
HISTORIC INVENTORY FORM	37) revision



## Missouri Historic Architectural Inventory for GR-RS-003-787 Division of Parks and Historic Preservation Department of Natural Resources

* 1) inventory number
2) name(cont) 3) name-historial 4) street address 5) town or vicinity 6) legal description 7) county  8) category (site, structure, building, object)  9) significance 10) date 11) style 12) architect 13) builder 14) original use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print  1215 W.Walnut st. Springfield  Cae 1215 W.Walnut st. Springfield  Cae 1215 W.Walnut st. Springfield  Cae 1215 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1217 W.Walnut st. Springfield  Cae 1218 W.Walnut st. Springfield  Cae 1219 W.Walnut st. Springfield  Cae 1219 W.Walnut st. Springfield  Cae 1215 W.Walnut st. Springfield  Cae 1215 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1215 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1217 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield  Cae 1216 W.Walnut st. Springfield
3) name-historial 4) street address 5) town or vicinity 6) legal description 7) county  8) category (site, structure, building, object)  9) significance 10) date 11) style 12) architect 13) builder 14) original use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print  1215 W.Walnut st. Springfield  Cae  1215 W.Walnut st. Springfield  Cae  1216 W.Walnut st. Springfield  Cae  1217 W.Walnut st. Springfield  1218 W.Walnut st. Springfield  1218 W.Walnut st. Springfield  1219 W.Walnut st. Springfield  1219 W.Walnut st. Springfield  1219 W.Walnut st. Springfield  1219 W.Walnut st. Springfield  1219 W.Walnut st. Springfield  1215 W.Walnut st. Springfield  1215 W.Walnut st. Springfield  1215 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1216 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfield  1221 W.Walnut st. Springfie
4) street address 5) town or vicinity 6) legal description 7) county  8) category (site, structure, building, object)  9) significance 10) date 11) style 12) architect 13) builder 14) original use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print  1215 W.Walnut st. Springfield  Squeene  Building  Building  Ca. 1910  Late catbuilder  residence same  irregular partial stone frame/modern siding gable-hip combo. asphalt shingle
5) town or vicinity 6) legal description 7) county 8) category (site, structure, building, object) 9) significance 10) date 11) style 12) architect 13) builder 14) original use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print  Springfield  Square Square  Building  Building  Ca. 1910  Late catbuilder  residence same  irregular partial stone frame/modern side gable-hip combo. asphalt shingle
6) legal description 7) county  8) category (site, structure, building, object)  9) significance 10) date 11) style 12) architect 13) builder 14) original use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print  8 basement Greene  8 uilding  8 uilding  1ate catbuilder  residence same 1 irregular partial partial stone frame/modern siding gable-hip combo. asphalt shingle
6) legal description 7) county  8) category (site, structure, building, object)  9) significance 10) date 11) style 12) architect 13) builder 14) original use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print  Greene  Building  Ca. 1910  Late catbuilder  residence  residence  irregular  partial stone frame/modern siding gable-hip combo. asphalt shingle
8) category (site, structure, building, object)  9) significance 10) date 11) style 12) architect 13) builder 14) original use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print  Building  Building  Building  Fate catbuilder  residence  residence  same  irregular  partial  stone  gable-hip combo. asphalt shingle
8) category (site, structure, building, object)  9) significance 10) date 11) style 12) architect 13) builder 14) original use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print  Building  Building  Building  Fate catbuilder  residence  residence  same  irregular  partial  stone  gable-hip combo. asphalt shingle
(site, structure, building, object)  9) significance 10) date 11) style 12) architect 13) builder 14) original use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print  Building  Ca. 1910  Late catbuilder  residence  residence  residence  same  irregular  partial  stone gable-hip combo. asphalt shingle
building, object)  9) significance 10) date 11) style 12) architect 13) builder 14) original use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print  Building  Ca. 1910  Iate catbuilder  residence  residence  irregular  partial  partial  stone  frame/modern side  gable-hip combo- asphalt shingle
9) significance 10) date
10) date 11) style 12) architect 13) builder 14) original use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print  ca. 1910  late catbuilder  residence  same  irregular  partial  stone  frame/modern siding  gable-hip combo- asphalt shingle
10) date 11) style 12) architect 13) builder 14) original use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print  ca. 1910 late catbuilder residence same  residence same  residence same  fragular partial stone frame/modern sidence gable-hip combo- asphalt shingle
11) style 12) architect 13) builder 14) original use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print  late catbuilder residence same liregular partial stone partial stone gable-hip combo. asphalt shingle
12) architect 13) builder 14) original use residence 15) present use same 16) number of stories l 17) plan shape irregular 18) basement partial 19) foundation stone 20) wall construction frame/modern side 21) roof type-material asphalt shingle 22) contact print
13) builder 14) original use residence 15) present use same  16) number of stories l 17) plan shape irregular 18) basement partial 19) foundation stone 20) wall construction frame/modern side 21) roof type-material asphalt shingle 22) contact print
14) original use 15) present use 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print  residence  residence  residence  same  irregular  partial  stone frame/modern siding gable-hip combo. asphalt shingle
15) present use same  16) number of stories l 17) plan shape irregular 18) basement partial 19) foundation stone 20) wall construction 21) roof type-material asphalt shingle 22) contact print
15) present use same  16) number of stories l 17) plan shape irregular 18) basement partial 19) foundation stone 20) wall construction 21) roof type-material asphalt shingle 22) contact print
. 16) number of stories 17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print  irregular partial stone frame/modern side gable-hip combo. asphalt shingle
17) plan shape 18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print  irregular partial stone frame/modern side gable-hip combo- asphalt shingle
18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print  partial stone frame/modern sidingle gable-hip combo. asphalt shingle
18) basement 19) foundation 20) wall construction 21) roof type- material 22) contact print  partial stone frame/modern sidingle gable-hip combo. asphalt shingle
19) foundation stone 20) wall construction frame/modern side 21) roof type- material gable-hip combo. asphalt shingle 22) contact print
20) wall construction frame/modern side 21) roof type- gable-hip combo. material asphalt shingle 22) contact print
21) roof type- material  22) contact print  21) roof type- gable-hip combo- asphalt shingle
21) roof type- material  22) contact print  21) roof type- gable-hip combo- asphalt shingle
material asphalt shingle  22) contact print
22) contact print
35mm
23) site plan
25) Site Plan
24) changes -
additions/alter-
ations/moved
25) condition
26) visible from road?
27) distance/frontage
28) accessible?
29) preservation
underway?
30) endangered?
31) on National
Register? No
32) part of
1
established
historical district No
33) name of historical
district
34) is site eligible? NO
35) district potential?
36) date $5/6/84$
37) revision
_



## Missouri Historic Architectural Inventory for GPA5-003-788 Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number P=1289
— public	2) name (cont)
39) Owners — name	3) name - historial
— address	4) street address 1216 W. Walnut st.
40) Local contact	1210 W. Wallido So.
41) Coordinates (UTM)	5) town or vicinity Springfield 6) legal description
42) Quad	
	YI COIL
43) Other survey	8) category (site. structure.
	Duri Talan
	building, object) Building
44) History	9) significance
	10) date ca. 1915
	11) style late catbuilder
	12) architect
	13) builder
	14) original use residence
	15) present use same
45) Additional description	* 16) number of stories $\frac{1}{2}$
	17) plan shape rectangle
	18) basement full
	at Chapter at
	000110
	II ame/ model II Brazil
	21) roof type-garbrel
	material asphalt shingle
•	22) contact print
46) Description of environment/outbuildings	23) site plan
46) Description of environment/outbuildings	23) site plan
	23) site plan
	23) site plan
	24) changes - additions/alter-
	24) changes - additions/alter- ations/moved
	24) changes - additions/alter- ations/moved 25) condition
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road?
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?
47) Information sources  48) Location of negatives  Roll 134 #27	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation
47) Information sources  48) Location of negatives  Roll 134 #27  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?
47) Information sources  48) Location of negatives  Roll 134 #27  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National
47) Information sources  48) Location of negatives  Roll 134 #27  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No
48) Location of negatives  Roll 134 #27  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of
47) Information sources  48) Location of negatives  Roll 134 #27  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established
47) Information sources  48) Location of negatives  Roll 134 #27  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No
47) Information sources  48) Location of negatives  Roll 134 #27  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No 33) name of historical
47) Information sources  48) Location of negatives  Roll 134 #27  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No
47) Information sources  48) Location of negatives  Roll 134 #27  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district
47) Information sources  48) Location of negatives  Roll 134 #27  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district No 33) name of historical district 34) is site eligible?
47) Information sources  48) Location of negatives  Roll 134 #27  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?  No
47) Information sources  48) Location of negatives  Roll 134 #27  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  24) changes - Additions/alter- ations/moved 25) NO  NO  NO  NO  NO  NO  NO  NO  NO  NO
47) Information sources  48) Location of negatives  Roll 134 #27  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? No 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential?  No
47) Information sources  48) Location of negatives  Roll 134 #27  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? NO 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential? 36) date  24) changes - Additions/alter- ations/moved 25) NO  NO  NO  NO  NO  NO  NO  NO  NO  NO



Missouri Historic Architectural Inventory for GRAS-003-759
Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	* 1) inventory number P-1290	
— public	2) name (cont)	
39) Owners — name	3) name - historial	
address	4) street address 1220 W. Walnut s	t.
40) Local contact	5) town or vicinity Springfield	
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county Greene	
43) Other survey	8) category	
	(site, structure,	1
	building, object) Building	ļ
44) History	9) significance	
44) History		
	132	
	11) style bungal ow	
	12) architect	
	13) builder	
	14) original use residence	
	15) present use	
45) Additional description	16) number of stories	
	17) plan shape rectangle	$\overline{}$
	18) basement full	
	10) foundation	
	concrete	
	<u>L trame/modern_Sid</u>	m
	<u> </u>	
	agnhalt shingle	
	22) contact print 35mm	
46) Description of environment/outbuildings	23) site plan	
		++-
47) Information sources	24) changes -	<del></del>
47) Information Sources	additions/alter-	
	ations/moved	
•	25) condition	
	26) visible from road?	
	27) distance/frontage	
	28) accessible?	
48) Location of negatives	29) preservation	
Roll 134 # 28	underway?	
49) Prepared by	30) endangered?	
	31) on National	
DDD DDD	Register? No	
50) Organization Missouri Heritage Trust		
	32) part of	
ETA FIEM STORES	established	
	historical district No	
If additional space is needed, attached se	33) name of historical	
	district	
	34) is site eligible? NO	
	35) district potential? $1_{\Theta}$	
The state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the s	36) date $5/4/84$	
and the second second second	37) revision	
>1 ( \		
	l l	
HISTORIC INVENTORY FORM		



Missouri Historic Architectural Inventory for ( R-15-60 - 1960)

Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private *	1) inventory number	M-241
— public	2) name (cont)	11-241
39) Owners — name	3) name - historial	
	1	
address	4) street address	1221 W.Walnut st.
40) Local contact	5) town or vicinity	Springfield
41). Coordinates (UTM)	<ol><li>6) legal description</li></ol>	
42) Quad	7) county	Greene
43) Other survey	8) category	9,99119
	(site, structure,	( )
	building, object)	Building
44) History	9) significance	
44) History		ca. 1900
	10) date	
	11) style	early catbuilder
	12) architect	
	13) builder	
	14) original use	residence
	15) present use	same
45) Additional description	16) number of stories	1
· · · · · · · · · · · · · · · · · · ·	17) plan shape	irregular
	18) basement	
		partial
	19) foundation	stone
	20) wall construction	frame/modern siding
	21) roof type -	gable-hip combo.
	material	asphalt shingle
•	22) contact print	
	35mm	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings	23) site plan	
46) Description of environment/outbuildings		
46) Description of environment/outbuildings  47) Information sources	24) changes -	<u>S</u>
	24) changes - additions/alter-	
	24) changes - additions/alterations/moved	<u> </u>
	24) changes - additions/alterations/moved 25) condition	<u> </u>
	24) changes - additions/alterations/moved	<u> </u>
	24) changes - additions/alterations/moved 25) condition	<u>c</u>
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road	<u>c</u>
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage	<u>c</u>
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road: 27) distance/frontage 28) accessible? 29) preservation	<u>c</u>
47) Information sources  48) Location of negatives  Roll 157 #40-41	24) changes - additions/alter- ations/moved 25) condition 26) visible from road: 27) distance/frontage 28) accessible? 29) preservation underway?	<u>c</u>
47) Information sources  48) Location of negatives  Roll 157 #40-41  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?	<u>c</u>
47) Information sources  48) Location of negatives  Roll 157 #40-41  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National	
47) Information sources  48) Location of negatives  Roll 157 #40-41  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?	<u>c</u>
47) Information sources  48) Location of negatives  Roll 157 #40-41  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road: 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of	
47) Information sources  48) Location of negatives  Roll 157 #40-41  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road: 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	No
47) Information sources  48) Location of negatives  Roll 157 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road: 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	No
47) Information sources  48) Location of negatives  Roll 157 #40-41  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road; 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	No
47) Information sources  48) Location of negatives  Roll 157 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	No
47) Information sources  48) Location of negatives  Roll 157 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road; 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical	No No
47) Information sources  48) Location of negatives  Roll 157 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district	No No
47) Information sources  48) Location of negatives  Roll 157 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible?	No No St. No No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No
47) Information sources  48) Location of negatives  Roll 157 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road: 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential 36) date	No No
47) Information sources  48) Location of negatives  Roll 157 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential	No No St. No No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No
47) Information sources  48) Location of negatives  Roll 157 #40-41  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road: 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historical district 34) is site eligible? 35) district potential 36) date	No No St. No No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No St. No



## Missouri Historic Architectural Inventory for ( 10 1 - 003 - 791) Division of Parks and Historic Preservation Department of Natural Resources

30) Ownership and sta		
38) Ownership — private — public	* 1) inventory number P=1291	_==
39) Owners — name	2) name (cont)	
address	3) name - historial 4) street address 1224, W. Walnut, st.	
40) Local contact	1,357 11,012,120 20	
41) Coordinates UTM)	5) town or vicinity Springfield 6) legal description	
42) Quad		$\dashv$
43) Other survey	7) county Greene 8) category	
	(site, structure,	2/3)
	building, object) Building	
44) History	9) significance	
•	10) date ca. 1925	$\neg$
	11) style bungalow	_
	12) architect	-
	13) builder	-
	14) original use residence	-
	15) present use same	_
45) Additional description	* 16) number of stories 2	4
	17) plan shape rectangle	_
	18) basement full	$\neg$
	19) foundation concrete	$\neg$
	20) wall construction frame/modern sid	ino
	21) roof type - gable	سعندي
	material asymple asymple	
•	22) contact print	5
	35mm	
	•	
		ļ
		ļ
		-
$\circ$		
46) Description of environment/outbuildings	23) site plan	- L S
		1
		+
47) Information sources	24) changes -	<del>-   </del> 5
47) Information sources	additions/alter-	
•	ations/moved	
	25) condition	
	26) visible from road?	
	27) distance/frontage	-
	28) accessible?	- 6
48) Location of negatives	29) preservation	
Roll 134 #29	underway?	
49) Prepared by	30) endangered?	$\neg$
DDD	31) on National	-
EO) OiAion	Register? NO	
Missouri Heritage Trust	32) part of	
	established	
TENTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL TOTAL	historical district No	
	33) name of historical	
If additional space is needed, attacl	33) Hame of materical	
If additional space is needed, attact	district	
If additional space is needed, attacl		
If additional space is needed, attach	district 34) is site eligible? 35) district potential?  Ye	30)
If additional space is needed, attach	district  34) is site eligible?  35) district potential?  36) date $\frac{L_0}{\sqrt{2}}$	30
If additional space is needed, attach	district 34) is site eligible? 35) district potential?  Ye	30
If additional space is needed, attach	district  34) is site eligible?  35) district potential?  36) date $\frac{L_0}{\sqrt{2}}$	30
HISTORIC INVENTORY FORM MISSOURI HERITAGE TRUST	district  34) is site eligible?  35) district potential?  36) date $\frac{L_0}{\sqrt{2}}$	30)



### Missouri Historic Architectural Inventory for GRAJ-003-793 Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	1)	inventory number	M-242	]=
— public	2)	name (cont)		1
39) Owners — name	3)	name - historial		1
— address	4)	street address	1225 W.Walnut st.	7
40) Local contact	5)	town or vicinity	Springfield	7
41) Coordinates (UTM)		legal description		
42) Quad		county	Greene	
43) Other survey		category		2/3)
		(site, structure,	Building	=
	I .	building, object)		4
44) History		significance		_
		date	ca. 1895	_
		style architect	early catbuilder	2
,		builder		4
		original use		$\dashv$
		present use	residence	
45) Additional description		number of stories	same 2	4
		plan shape	irregular	<b>-</b>
		basement	partial	$\exists$
	19)	foundation	stone	
	l l	wall construction	frame/modern sidi	ng
	21)	roof type -	hip with gable wi	
		material	asphalt shingle	
·	22)	contact print		5)
		35mm		
			•	
	ŀ			
46) Description of environment/outbuildings	23)	site plan		(9
46) Description of environment/outbuildings	23)	site plan		(9
46) Description of environment/outbuildings	23)	site plan		9)
46) Description of environment/outbuildings	23)	site plan		9)
46) Description of environment/outbuildings	23)	site plan		9)
46) Description of environment/outbuildings	23)	site plan		
46) Description of environment/outbuildings  47) Information sources		changes -		9) 5)
		changes - additions/alter-		
	24)	changes - additions/alter- ations/moved		
	24)	changes - additions/alter- ations/moved condition		
	24)	changes - additions/alter- ations/moved condition visible from road?		
	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road? distance/frontage		5)
47) Information sources	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?		
47) Information sources  48) Location of negatives	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation		5)
47) Information sources  48) Location of negatives  Roll 157 #42-43	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?		5)
47) Information sources  48) Location of negatives  Roll 157 #42-43  49) Prepared by	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?		5)
48) Location of negatives  Roll 157 #42-43  49) Prepared by  DDD	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National		5) 6)
47) Information sources  48) Location of negatives  Roll 157 #42-43  49) Prepared by	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?		5)
48) Location of negatives  Roll 157 #42-43  49) Prepared by  DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National		5) 6)
48) Location of negatives  Roll 157 #42-43  49) Prepared by  DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	No	5) 6)
48) Location of negatives  Roll 157 #42-43  49) Prepared by  DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica	No	5) 6)
47) Information sources  48) Location of negatives  Roll 157 #42-43  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32,	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district	No	5) 6)
47) Information sources  48) Location of negatives  Roll 157 #42-43  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 30) 31) 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible?	No No	(5)
47) Information sources  48) Location of negatives  Roll 157 #42-43  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 29) 30) 31) 32, 33 34, 35	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible? ) district potential?	No No No No No	5) (6)
47) Information sources  48) Location of negatives  Roll 157 #42-43  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 30) 31) 32, 33 34 35 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential? date	No No	(5)
47) Information sources  48) Location of negatives  Roll 157 #42-43  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 30) 31) 32, 33 34 35 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district ) is site eligible? ) district potential?	No No No No No	(5)
47) Information sources  48) Location of negatives  Roll 157 #42-43  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) 25) 26) 27) 28) 30) 31) 32, 33 34 35 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential? date	No No No No No	(5)



Missouri Historic Architectural Inventory for Garage Constant of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	inventory number	P-1292	_ =
public	2) name (cont)		
39) Owners — name	3) name - historial		
address	4) street address	1200 H Holmut at	-
(40) Local contact	5) town or vicinity	1300 W.Walnut st.	-
	· ·	Springfield	4
41) Coordinates (UTM)	6) legal description		_
42) Quad	7) county	Greene	
43) Other survey	8) category		2/3)
	(site, structure,		$ \omega $
	building, object)	Building	
44) History	9) significance		-
44) History	_	7.00%	_
•	10) date	ca. 1895	
	11) style	early catbuilde	r
•	12) architect		
:C	13) builder		
	14) original use	residence	
	15) present use	same	-
45) Additional description	◆ 16) number of stories		4
Top reactional accompliant		22	
	17) plan shape	irregular	
	18) basement	partial	
	19) foundation	stone	
	20) wall construction	frame/modern sidi	ng
	21) roof type -	gable	-10
	material	oanhilt ahimmla	-
•	22) contact print	asphalt shingle	<u>5</u>
	35mm		3
	3311111		
		•	l
			Ì
ACA Description of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second of the second	22) eito plan		100
46) Description of environment/outbuildings	23) site plan		9)
46) Description of environment/outbuildings	23) site plan		9)
46) Description of environment/outbuildings	23) site plan		9)
46) Description of environment/outbuildings	23) site plan		9)
46) Description of environment/outbuildings			9)
46) Description of environment/outbuildings			9)
46) Description of environment/outbuildings  47) Information sources	24) changes -		9) 5)
	24) changes - additions/alter-		
	24) changes - additions/alter- ations/moved		
	24) changes - additions/alter- ations/moved 25) condition		
	24) changes - additions/alter- ations/moved		
	24) changes - additions/alter- ations/moved 25) condition		
	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage		5)
47) Information sources	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible?		
47) Information sources  48) Location of negatives	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation		5)
48) Location of negatives  Roll 134 #30-31	24) changes - additions/alterations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway?		5)
47) Information sources  48) Location of negatives  Roll 134 #30-31  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?		5)
48) Location of negatives  Roll 134 #30-31	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National		5)
48) Location of negatives  Roll 134 #30-31  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered?		5) 6)
48) Location of negatives  Roll 134 #30-31  49) Prepared by	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National		5)
48) Location of negatives  Roll 134 #30-31  49) Prepared by  DDD	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register?		5) 6)
48) Location of negatives  Roll 134 #30-31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established	No	5) 6)
48) Location of negatives  Roll 134 #30-31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district	No	5) 6)
48) Location of negatives  Roll 134 #30-31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica	No	5) 6)
48) Location of negatives  Roll 134 #30-31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district	No	5) 6)
48) Location of negatives  Roll 134 #30-31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible?	No No	5) 6) 7)
48) Location of negatives  Roll 134 #30-31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential?	No No Ye.	5) 6)
48) Location of negatives  Roll 134 #30-31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential? 36) date	No No	5) 6) 7)
48) Location of negatives  Roll 134 #30-31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential?	No No Ye.	5) 6) 7)
48) Location of negatives  Roll 134 #30-31  49) Prepared by  DDD  50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential? 36) date	No No Ye.	5) 6) 7)
47) Information sources  48) Location of negatives Roll 134 #30-31 49) Prepared by DDD 50) Organization Missouri Heritage Trust	24) changes - additions/alter- ations/moved 25) condition 26) visible from road? 27) distance/frontage 28) accessible? 29) preservation underway? 30) endangered? 31) on National Register? 32) part of established historical district 33) name of historica district 34) is site eligible? 35) district potential? 36) date	No No Ye.	5) 6) 7)





Missouri Historic Architectural Inventory for GR-25-603-794

Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private *	* 1) inventory number	_ :
— public	2) name (cont)	
39) Owners — name	3) name - historial	
— address	4) street address 609 N. Washington s	770
40) Local contact	5) town or vicinity Springfield	<b>-2</b> 43
41) Coordinates (UTM)	6) legal description	-
42) Quad	7) county Greene	$\dashv$
43) Other survey	8) category	+
45) Other survey	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2/3)
	building, object)	_
44) History	9) significance	
	10) date ca. 1915	}
	11) style late catalogue-	٦
	12) architect builder	7
	13) builder	┪
	14) original use residence	-
	2 3 3 4 67.10 0	$\dashv$
45) Additional description	1302001100	+-
45) Additional description		4
	17) plan shape irregular	
	18) basement no	_
	19) foundation stone	$\neg$
	20) wall construction frame/modern siding	$\dashv$
	21) roof type- <u>lle-hip combinat</u> :	4
	TACTILITY CONTOLLING	-911
	material as shalt shingle  22) contact print	5
	•	15
	35mm	1
		- }
	·	- {
		ļ
		-
•		ŀ
		- 1.6
46) Description of environment/outbuildings	23) site plan	199
•		<u>†</u>
		$\perp$
	<del>▕▗┋╃┢╎╁╏</del> ┋╇╁╀ <del>┋</del> ┾┞┿╀╃	+
	<del>▕</del>	÷Ι
47) Information sources	24) changesodern siding adde	2 0
47) Information sources		۲
	additions/alter-	- {
	ations/moved	_
	25) condition	
	26) visible from road?	
	27) distance/frontage	
	28) accessible?	0
48) Location of negatives	29) preservation	`
roll 86 #1	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	1
	underway?	_
49) Prepared by	30) endangered?	
DDD	31) on National	- }
50) Organization	Register?	
A C. C. C. C. C. C. C. C. C. C. C. C. C.	32) part of	7
SUT	1 '	1
14HT	i established	- 1
	established no	- }
	historical district NO	4
If additional space is needed, attache	historical district  33) name of historical	$\dashv$
	historical district  33) name of historical district	
	historical district  33) name of historical district  34) is site eligible?	
	historical district  33) name of historical district  34) is site eligible?  35) district potential?	
	historical district  33) name of historical district  34) is site eligible?	
	historical district  33) name of historical district  34) is site eligible?  35) district potential?	
	historical district  33) name of historical district  34) is site eligible?  35) district potential?  36) date  no  4/18/84	



GR- AS-003-795

## Missouri Historic Architectural Inventory for Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private	1)	inventory number	N-164	T_
public		name (cont)	1/-1.0+	<b> </b> =
39) Owners — name		name - historial		╣
-address				4
		street address	623 H. Washington av	<u>.</u>
40) Local contact		town or vicinity	Springfield	╛
41) Coordinates (UTM)	1	legal description		
42) Quad	7)	county	Greene	Ì
43) Other survey	8)	category		2/3)
		(site, structure,		L.
		building, object)	building	
44) History		significance	nut Iding	1
• • • • • • • • • • • • • • • • • • • •		date	ca. 1915	┥
•	1	style	late catalogue-	4
		architect		4
			builder	4
	1	builder		4
	1	original use	residence	
	15)	present use	residence	
45) Additional description The upper sash of the first story	16)	number of stories	1/2	2
window in the front wing has vertical muntins.	17)	plan shape	L-s.ape	1
The wood shingle siding may be original?	1	basement	full	7
	1	foundation	concrete?	$\dashv$
There are exposed rafter ends on the overhanging	1 .	wall construction		┨
eaves of the house.		roof type -	frame/wood shingle	4
	211	• •		_
		material	ashpalt shingle	
	22)	contact print		5
		35mm		
	1			-
	1			
	1			İ
				ļ
ACV Description of the April 1911	221	aita alaa ( ) ( ) ( )		146
46) Description of environment/outbuildings	23)	site plan		<u> </u>
46) Description of environment/outbuildings	23)	site plan		9
46) Description of environment/outbuildings	23)	site plan		9
46) Description of environment/outbuildings	23)	site plan		9)
46) Description of environment/outbuildings	23)	site plan		9)
46) Description of environment/outbuildings		site plan		9)
46) Description of environment/outbuildings  47) Information sources			there is a modern	9) 5)
			· ·	-
		changes - additions/alter-	there is a modern rear addition	-
	24)	changes - additions/alterations/moved	rear addition	-
	24)	changes - additions/alter- ations/moved condition	· ·	-
	24)	changes - additions/alter- ations/moved condition visible from road?	rear addition	-
	24) 25) 26) 27)	changes - additions/alter- ations/moved condition visible from road? distance/frontage	rear addition	5)
47) Information sources	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	rear addition	-
	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	rear addition	5)
47) Information sources	24) 25) 26) 27) 28)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	rear addition	5)
47) Information sources	24) 25) 26) 27) 28) 29)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation	rear addition	5)
47) Information sources  48) Location of negatives roll 5 #19	24) 25) 26) 27) 28) 29) 30)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway?	rear addition	5)
47) Information sources  48) Location of negatives roll 5 #19  49) Prepared by DDD	24) 25) 26) 27) 28) 29) 30)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	rear addition	5) 6)
47) Information sources  48) Location of negatives roll 5 #19	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	rear addition	5)
47) Information sources  48) Location of negatives roll 5 #19  49) Prepared by DDD	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of	rear addition	5) 6)
47) Information sources  48) Location of negatives roll 5 #19  49) Prepared by DDD  50) Organization 111. T	24) 25) 26) 27) 28) 29) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established	rear addition  good  no	5) 6)
48) Location of negatives roll 5 #19  49) Prepared by DDD  50) Organization 111 T	24) 25) 26) 27) 28) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district	rear addition  good  no	5) 6)
47) Information sources  48) Location of negatives roll 5 #19  49) Prepared by DDD  50) Organization 111. T	24) 25) 26) 27) 28) 30) 31)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical	rear addition  good  no	5) 6)
48) Location of negatives roll 5 #19  49) Prepared by DDD  50) Organization 111 T	24) 25) 26) 27) 28) 29) 30) 31) 32)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district	rear addition  good  no	5) 6)
48) Location of negatives roll 5 #19  49) Prepared by DDD  50) Organization 111 T	24) 25) 26) 27) 28) 29) 30) 31) 32) 33)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible?	rear addition  good  no  no	5) 6) 7)
48) Location of negatives roll 5 #19  49) Prepared by DDD  50) Organization 11. T	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	no no	5) 6)
48) Location of negatives roll 5 #19  49) Prepared by DDD  50) Organization 11. T	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35) 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	rear addition  good  no  no	5) 6) 7)
48) Location of negatives roll 5 #19  49) Prepared by DDD  50) Organization 11. T	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35) 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential?	no no	5) 6) 7)
48) Location of negatives roll 5 #19  49) Prepared by DDD  50) Organization 111 T	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35) 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	no no	5) 6) 7)
47) Information sources  48) Location of negatives roll 5 #19  49) Prepared by DDD  50) Organization III T	24) 25) 26) 27) 28) 29) 30) 31) 32) 33) 34) 35) 36)	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historical district is site eligible? district potential? date	no no	5) 6) 7)



## Missouri Historic Architectural Inventory for GR-AS-063-796 Division of Parks and Historic Preservation Department of Natural Resources


38) Ownership — private	1 11	inventory symbol		<del></del>
	1	inventory number	<u> F-65</u>	<b>∃</b> ະ
— public	2)	name (cont)	_ <del>-</del>	
39) Owners — name	3)	name - historial	Harry Cooper Supply	<b>.</b>
address	4)	street address	223 E. Water st.	<b>T</b> O,
40) Local contact	5)	town or vicinity		1
41) Coordinates (UTM)	1	legal description	Springfield	4
42) Quad	1	county		-
			Creene	
43) Other survey	8)	category		2/3)
	1	(site, structure,	building	=
		building, object)		
44) History tailt in 1913 by Harry Cooper a	9)	significance		1
	10)	date	1913	1
plumbing supply contractor		style		1
	1	architect		-
	1 .			4
	1 .	builder		_
	1	original use	commercial	
	15)	present use	storage	
45) Additional description .	16)	number of stories	3	£
In the southeast corner of the	17)	plan shape	rectangle	7
building is a stone with the following carved	18)	basement	full	┥
"Harry Cooler 1913" There are bands of smooth	1 '	foundation		-
stone below each window bay and at the parapet.	1	wall construction	concrete	_
stone below each window bay and at the prince.			steel frame-brick	_
The glass storefront appears to be totally unalter-	214		flot veneer	
Very simple entablature at the parapet with stone		material		
banding and stone dentil pattern.	22)	contact print		5
•		35mm		
$\circ$	-			
46) Description of environment/outbuildings	23)	site plan		_ 9
•	1-	++++++++	<del>╶┤┊┊┊┋┋┋</del>	-
	1-+-	<del>┤╎┤┞</del> ┼┼┼┼	<del>╶╁╎╁╎┧╏╏</del> ┼ <del>╏╏╏</del>	-
	1			Ī.
				<b>⊢</b>
	1-1-	<del>                                     </del>	<del>╒┋┋┋┋┋┋┋┋</del>	-
	- 24			5
47) Information sources Sanborn 1933	24.	changes -		
		additions/alter-		1
				- 1
		ations/moved		
	25		good	
		ations/moved	Lood	
•	26	ations/moved ) condition ) visible from road?		
· · · · · · · · · · · · · · · · · · ·	26 27	ations/moved ) condition		- 6
AP) Location of paratives	26 27 28	ations/moved ) condition ) visible from road? ) distance/frontage ) accessible?		
48) Location of negatives	26 27 28	ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation		
roll 1 %C-1	26 27 28 29	ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway?		6)
roll 1 #0-1	26 27 28 29	ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered?		6)
roll 1 %C-1	26 27 28 29	ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National		6)
roll 1 %0-1 49) Prepared by DDD	26 27 28 29	ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered?		
roll 1 %0-1 49) Prepared by  DDD	26 27 28 29 30 31	ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National		6) 7)
roll 1 %0-1 49) Prepared by DDD	26 27 28 29 30 31	ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register?	no	
roll 1 %0-1 49) Prepared by DDD	26 27 28 29 30 31	ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register?	no	
roll 1 #0-1 49) Prepared by DDD 50) Organization NHT	26 27 28 29 30 31	ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? !) part of established historical district	no	
roll 1 %0-1 49) Prepared by DDD 50) Organization NHT	26 27 28 29 30 31	ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established historical district ) name of historica	no	
roll 1 %0-1 49) Prepared by DDD 50) Organization NHT	26 27 28 29 30 31 32	ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established historical district of the storical district of conditions and the storical district	no no	
roll 1 #0-1 49) Prepared by DDD 50) Organization NHT	26 27 28 29 30 31 32	ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established historical district (i) name of historica district (i) is site eligible?	no no	7)
roll 1 %0-1 49) Prepared by DDD 50) Organization NHT	26 27 28 29 30 31 32 33 34 35	ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established historical district () name of historica district () is site eligible? () district potential?	no no No	
roll 1 #0-1 49) Prepared by DDD 50) Organization NHT	26 27 28 29 30 31 32 33 34 35 36	ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established historical district (i) name of historica district (i) is site eligible? (i) district potential? (i) date	no no	7)
roll 1 #0-1 49) Prepared by DDD 50) Organization NHT	26 27 28 29 30 31 32 33 34 35 36	ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established historical district () name of historica district () is site eligible? () district potential?	no no No	7)
roll 1 %C-1 49) Prepared by DDD 50) Organization NHT	26 27 28 29 30 31 32 33 34 35 36	ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established historical district (i) name of historica district (i) is site eligible? (i) district potential? (i) date	no no No	7)
roll 1 #0-1 49) Prepared by DDD 50) Organization NHT	26 27 28 29 30 31 32 33 34 35 36	ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established historical district (i) name of historica district (i) is site eligible? (i) district potential? (i) date	no no No	7)





Missouri Historic Architectural Inventory for Grand Table Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private				
	1)	inventory number	1:-63	
public	2)	name (cont)		<b>⊣</b> ~
39) Owners — name	1	name - historial		-
address	1 -			4
40) Local contact	1 '	street address	315 E. Water st.	_
1 1		town or vicinity	S_rincfield	
41) Coordinates (UTM)	6)	legal description	3	
42) Quad	7)	county	Grane	7
43) Other survey	8)	category	Griene	-
	"			2/3)
		(site, structure,	building	
		building, object)		
44) History	9)	significance		
built in 1929	10)	date	1929	7
socording to the Sandorn Ins. co map.	11)	style		┥
		architect		4
	1 .			_
		builder		
	14)	original use	commercial	
	15)	present use	storage	
45) Additional description	16)	number of stories	5	4
Very simple six bay building		plan shape		_ ⊢
with restrained Art Deco geometric detailing		•	rectanile	4
		basement	full	
seen be t at the parapet, and in the geometric		foundation	concrete	1
emphasis of each of the pilasters seperating th	€ 20)	wall construction	steel Frame-brick	7
bays.	21)	roof type -		-
		material		-
	22)	contact print	<del>-</del>	<del> </del> -
	221			5)
		35mm		
			-	
				Ì
				ļ
•				
46) Description of environment/outbuildings	23)	site plan	11111111111	9
•	1.			_
·	1			_
	_ <del> </del> _			_
	1 1	<del></del>	<del>╶┤┊</del> ╅┽╄╃┊╫╬╃╂╅╅╅╅	-
	1-1-		<del>╒┋╶┊╏┪╏┋┋</del>	_ l
	Ŧ	<del>┞╶┞┈┞┈┞</del> ╌┞		- 1
	Ŧ			-
47) Information sources Canadama 1077	24)	changes -	<del>                                      </del>	- 5
47) Information sources Sanborn 1933	24)	changes -	<del>                                     </del>	- 55
47) Information sources Sanborn 1933	24)	additions/alter-		5)
47) Information sources Sanborn 1933		additions/alter- ations/moved		5)
47) Information sources Sanborn 1933		additions/alter-		5)
47) Information sources Sanborn 1933	25)	additions/alter- ations/moved		5)
47) Information sources Sanborn 1933	25) 26)	additions/alter- ations/moved condition visible from road?		5)
47) Information sources Sanborn 1933	25) 26) 27)	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage		
Sanoorn Tyyy	25) 26) 27) 28)	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible?		5) 6)
Sanoorn Tyyy	25) 26) 27) 28)	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation		
Sanoora 1999	25) 26) 27) 28)	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible?		
48) Location of negatives roll 1 74	25) 26) 27) 28)	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation		
48) Location of negatives roll 1 44	25) 26) 27) 28) 29)	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered?		
48) Location of negatives roll 1 74  49) Prepared by DDD	25) 26) 27) 28) 29)	additions/alterations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National	no	6)
48) Location of negatives roll 1 74	25) 26) 27; 28; 29; 30; 31;	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register?	no	
48) Location of negatives roll 1 74  49) Prepared by DDD	25) 26) 27; 28; 29; 30; 31;	additions/alterations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of		6)
48) Location of negatives roll 1 74  49) Prepared by DDD	25) 26) 27; 28; 29; 30; 31;	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register?	no	6)
48) Location of negatives roll 1 74  49) Prepared by DDD	25) 26) 27; 28; 29; 30; 31;	additions/alterations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of		6)
48) Location of negatives roll 1 74  49) Prepared by DDD	25) 26) 27) 28) 29) 30) 31)	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established	no	6)
48) Location of negatives roll 1 44  49) Prepared by DDD  50) Organization NITT	25) 26) 27) 28) 29) 30) 31)	additions/alterations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica	no	6)
48) Location of negatives roll 1 44  49) Prepared by DDD  50) Organization NITT	25; 26; 27; 28 29; 30 31 32	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established historical district ) name of historica district	no	6)
48) Location of negatives roll 1 44  49) Prepared by DDD  50) Organization NITT	255, 266, 277, 288, 299, 300, 311, 322, 334, 344	additions/alter- ations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established historical district ) name of historica district ) is site eligible?	no	6) 7)
48) Location of negatives roll 1 74  49) Prepared by DDD  50) Organization NHT	255, 266, 277, 288, 299, 300, 311, 322, 33, 344, 35, 35	additions/alterations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established historical district ) name of historica district ) is site eligible? ) district potential?	no no yes	6)
48) Location of negatives roll 1 44  49) Prepared by DDD  50) Organization NITT	25) 26) 27) 28) 29) 30) 31) 32 33 34) 35) 36)	additions/alterations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established historical district ) name of historical district ) is site eligible? ) district potential? ) date	no	6) 7)
48) Location of negatives roll 1 74  49) Prepared by DDD  50) Organization NHT	25) 26) 27) 28) 29) 30) 31) 32 33 34) 35) 36)	additions/alterations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established historical district ) name of historica district ) is site eligible? ) district potential?	no no yes	6) 7)
48) Location of negatives roll 1 74  49) Prepared by DDD  50) Organization NHT	25) 26) 27) 28) 29) 30) 31) 32 33 34) 35) 36)	additions/alterations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established historical district ) name of historical district ) is site eligible? ) district potential? ) date	no no yes	6) 7)
48) Location of negatives roll 1 74  49) Prepared by DDD  50) Organization NHT	25) 26) 27) 28) 29) 30) 31) 32 33 34) 35) 36)	additions/alterations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established historical district ) name of historical district ) is site eligible? ) district potential? ) date	no no yes	6) 7)
48) Location of negatives roll 1 74  49) Prepared by DDD  50) Organization NITT	25) 26) 27) 28) 29) 30) 31) 32 33 34) 35) 36)	additions/alterations/moved ) condition ) visible from road? ) distance/frontage ) accessible? ) preservation underway? ) endangered? ) on National Register? ) part of established historical district ) name of historical district ) is site eligible? ) district potential? ) date	no no yes	6) 7)



## Missouri Historic Architectural Inventory for GR-145-003-798 Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership — private *	1)	inventory number	N-64	]=
public	2)	name (cont)	Mulholland furn.co.	1
39) Owners — name	3)	name - historial		1
address	4)	street address	331 E. Water st.	1
40) Local contact	5)	town or vicinity	Saringfield	1
41) Coordinates (UTM)	6)	legal description	()	1
42) Quad	7)	county	Cr.one	1
43) Other survey	8)	category		2/3,
		(site, structure,	huildina	ω
		building, object)	building	
44) History	9)	significance		1
Built in 1891. Statement found on the		date	1891.	7
Sanborn insurance map"Peing built for the	11)	style		7
Headle: Grocery Co."	12)	architect		7
	13)	builder		
	14)	original use	conmercial	
	15)	present use	co mercial	1
45) Additional description Brick banding and corbelling is used	16)	number of stories	3	4)
as a decorative pattern on the parapet entablature.	17)	plan shape	rectangle	1
The center two bays on the thrid story facade	18)	basement	full	1
have arched window openings. All other window	19)	foundation	stone	7
openings to we see ental anched openings with	1 .	wall construction	brick	7
wood panels filling the arch with decorative cut-or	(21)	roof type -	flat	]
patterns in the woodwork. The first story store-		material		1
front has c st iron pilasters framing the bays.	22)	contact print		5
Tions had a so first harmany the say of		35mm		
$\bigcup$				
	- 1			- 1
	1			l
46) Description of environment/outbuildings	23	) site plan		9
46) Description of environment/outbuildings	23	) site plan		- (9
46) Description of environment/outbuildings	23	) site plan		9)
46) Description of environment/outbuildings	23	) site plan		9)
46) Description of environment/outbuildings	23	) site plan		9)
46) Description of environment/outbuildings		) site plan		-
46) Description of environment/outbuildings  47) Information sources				9) 5)
		) changes - additions/alter-	all winds: openings	-
47) Information sources		) changes -	all winds: openings	-
47) Information sources	24	) changes - additions/alter-	1	-
47) Information sources	24	) changes - additions/alter- ations/moved	Live been closed	-
47) Information sources	24	) changes - additions/alter- ations/moved	Leve been closed	5)
47) Information sources	24 25 26 27 28	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible?	Leve been closed	-
47) Information sources	24 25 26 27 28	changes - additions/alter- ations/moved condition visible from road? distance/frontage	Leve been closed	5)
47) Information sources	24 25 26 27 28 29	changes - additions/alter-ations/moved condition visible from road? distance/frontage accessible? preservation underway?	Leve been closed	5)
47) Information sources	24 25 26 27 28 29 30	changes - additions/alter-ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered?	Leve been closed	5)
48) Location of negatives roll 1 #2-3  49) Prepared by DDD	24 25 26 27 28 29 30	changes - additions/alter- ations/moved condition visible from road? distance/frontage cessible? preservation underway? endangered? on National	Live been closed	5)
47) Information sources  Source 2022  48) Location of negatives roll 1 #2-3	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register?	Leve been closed	5)
48) Location of negatives roll 1 #2-3  49) Prepared by DDD	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage cacessible? preservation underway? endangered? on National Register? part of	Live been closed	5) 6)
48) Location of negatives roll 1 #2-3  49) Prepared by DDD  50) Organization NHT	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? non National Register? part of established	no	5) 6)
48) Location of negatives roll 1 #2-3  49) Prepared by DDD  50) Organization MHT	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage cocessible? preservation underway? endangered? on National Register? part of established historical district	no	5) 6)
48) Location of negatives roll 1 #2-3  49) Prepared by DDD  50) Organization NHT	24 25 26 27 28 29 30 31	changes - additions/alter- ations/moved condition visible from road? distance/frontage cocessible? preservation underway? endangered? on National Register? part of established historical district name of historica	no	5) 6)
48) Location of negatives roll 1 #2-3  49) Prepared by DDD  50) Organization MHT	24 25 26 27 28 29 30 31 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage cocessible? preservation underway? endangered? on National Register? part of established historical district name of historica district	no	5) 6)
48) Location of negatives roll 1 #2-3  49) Prepared by DDD  50) Organization MHT	24 25 26 27 28 29 30 31 32	changes - additions/alter- ations/moved condition visible from road? distance/frontage cocessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible?	no no yes	5) 6) 7)
48) Location of negatives roll 1 #2-3  49) Prepared by DDD  50) Organization NHT	24 25 26 27 28 29 30 31 32 33 34 35	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential	no no yes yes	5) 6)
48) Location of negatives roll 1 #2-3  49) Prepared by DDD  50) Organization NHT	24 25 26 27 28 29 30 31 32 33 34 35 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential: date	no no yes	5) 6) 7)
48) Location of negatives roll 1 #2-3  49) Prepared by DDD  50) Organization NHT	24 25 26 27 28 29 30 31 32 33 34 35 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential	no no yes yes	5) 6) 7)
48) Location of negatives roll 1 #2-3  49) Prepared by DDD  50) Organization NHT	24 25 26 27 28 29 30 31 32 33 34 35 36	changes - additions/alter- ations/moved condition visible from road? distance/frontage accessible? preservation underway? endangered? on National Register? part of established historical district name of historica district is site eligible? district potential: date	no no yes yes	5) 6) 7)



Missouri Historic Architectural Inventory for \$12-05-05-199

38) Ownership private	* 1) inventory number	N-60	$\neg$
public	<del>-</del>	1. 00	<b>⊣</b> =
	2) name (cont)		
39) Owners — name	3) name - historial		
address	4) street address	d. Water st.	7
40) Local contact	5) town or vicinity	Springfield	7
41) Coordinates (UTM)	6) legal description		٦
42) Quad	7) county	Greene	
43) Other survey	8) category	Greene	<del>- </del> -
45) Other survey			2/3)
	(site, structure,	building	
	building, object)		
44) History In 1933 the building was used by the	9) significance		
	10) date	ca. 1.920	$\neg$
Certified Flour and Feed Co.	11) style	Cat • 1.920	$\dashv$
	<del>-</del>		
	12) architect		
	13) builder		
	14) original use	dommercial	
·	15) present use	I ·	
45) Additional description	16) number of stories	com ercial	4
40) Additional description	4	3	
	17) plan shape	rectangle	
	18) basement		
	19) foundation		
	20) wall construction	concrete	
	1	brick	_
	21) roof type -	<u>flat</u>	
	material		
	22) contact print		5
	35mm		
•	ì		
			- (
			1
46) Description of environment/outbuildings	23) site plan		1 9
To be be be be the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the control of the co	in the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of the plant of th	<del>!                                    </del>	<del> -</del>
·			
			$\mathbb{L}$
		<del>┢╺┋╸┋╶┋╶┋</del> ╶ <del>┇</del>	4-
	<del></del>	<del>╽┈╎┈┆┈┆┈┆┈╏┈╏┈╏┈╏╸╏╸╏╸╏╸╏╸╏╸╏╸╏╸╏╸</del>	<del>-</del>
	\ <del>-\-\-\-\-\-\-\-\-</del>	<del>┞╶┊┩┼╏┋</del> ┼┼┲╂╗╃╒	+1
47) Information sources	24) changes -	T	5
Sauborn 1933	additions/alter-		
	· · · · · · · · · · · · · · · · · · ·	}	
	ations/moved		
	25) condition		
	26) visible from road?		
	27) distance/frontage		
	_		6
	28) accessible?		—  <sup>-</sup>
48) Location of negatives roll 101 #41-42	29) preservation		1
TOIL TOI WAILAR	underway?		
49) Prepared by	30) endangered?		
DDD	31) on National		_
50) Organization NIH中	Register?	no	L
50) Organization MiT		110	
	32) part of		[
	established	1	
	historical district	no	
	33) name of historica	l Table	
	district	Į.	}
	34) is site eligible?	10.0	_
		no	<del>-  </del> w
	35) district potential		30)
	36) date	4/11/84	
the second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second second secon	37) revision		
· ·			
HISTORIG INVENTORY FORM			
MICCOLIDI LIEDITA CE TRIICT			
MISSOURI HERITAGE TROST	•	÷	





Missouri Historic Architectural Inventory for C-12-145-003-800 Division of Parks and Historic Preservation Department of Natural Resources

38) Ownership private	* 1) inventory number 1-61	
public	2) name (cont)	
39) Owners — name	3) name - historial	
address	4) street address W. Water st.	
40) Local contact	5) town or vicinity	
41) Coordinates (UTM)	6) legal description	
42) Quad	7) county Greene	
43) Other survey	8) category	
•	(site, structure,	2/3)
	building, object) building	
44) History	9) significance	
	10) date ca. 1930	
	11) style	
	12) architect	
	13) builder	
45) Additional description	15) present use garage 16) number of stories ≥	4
Toy Additional description	· (	
	// VIGI	
	00.101666	
	· 5 veer : concret	e/brich
	21) roof type - flat ve	neer
	22) contact print 35mm	0
	35mm ·	
•		
$\cap$		
$\cup$		
46) Description of environment/outbuildings	23) site plan	4++++
		+++++
		++++
47) Information sources Sanborn 1933	24) changes -	9
Samorn 1999	additions/alter-	
	ations/moved	
$\mathcal{E} = \mathbf{x} \cdot \mathbf{y}$	25) condition	
	26) visible from road?	
	27) distance/frontage	
	28) accessible?	0
48) Location of negatives roll 101 #43	29) preservation	
	underway?	
49) Prepared by DDD	30) endangered?	
	31) on National	
50) Organization NHT	Register?	
•	32) part of	
	established no	ļ
	historical district	
If ac hed separate sheets.	33) name of historical	
	district	
	34) is site eligible?	
	35) district potential? yes	
L a	36) date $\frac{4}{11/84}$	
and the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of the state of t	37) revision	
The same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the same of the sa		
HIST		
MISSOURI HERITAGE TRUST		

